

August 29, 2000

Ro 349

Closed

Mr. Barney Chan
Alameda County Health Care Services Agency
1131 Harbor Bay Parkway, 2nd Floor
Alameda, California 94502

**RE: Notice of Case Closure Request Submittal to ACHCSA for
Former Shell Service Station – 7915 E. 14th Street, Oakland, CA**

In accordance with section 25297.15(a) of Chapter 6.7 of the Health and Safety Code, Equiva Services LLC (Equiva) certifies that, with this correspondence, current record fee title owners have been notified of the following:

- Case closure was requested in Cambria's August 1, 2000 RBCA analysis for the referenced site. A copy of Cambria's August 1, 2000 *Risk Based Corrective Action Report* is enclosed with the current record fee title owner's copy of this letter.
- The Alameda County Health Care Services Agency (ACHCSA) intends to make a determination that no further action is required or to issue case closure letter for the referenced site.

Please do not hesitate to contact me with any questions or comments regarding this matter.

Sincerely,



Karen Petryna
Equiva Services LLC
Science & Engineering, West Coast
(559) 645-9306
(559) 645-5643 fax
Email kepetryna@equiva.com

cc Van F. & Wendy Q. Gee, 3604 Redwood Rd., Oakland, CA 94619 (with enclosure)
Troy Buggle, Cambria Environmental Technology, Inc. (w/o enclosure)

CAMBRIA

ENVIRONMENTAL PROTECTION

#10,0 R0349

February 28, 2000

00 MAR -3 AM 9:15

Barney Chan
Alameda County Health Care Services Agency
1131 Harbor Bay Parkway, Suite 250
Alameda, California 94502

Consider adding Soils to MW2

Re: **Fourth Quarter 1999 Monitoring Report**
Former Shell Service Station
7915 East 14th Street
Oakland, California
Incident #97093401
Cambria Project #242-0936-002



Dear Mr. Chan:

On behalf of Equiva Services LLC (Equiva), Cambria Environmental Technology, Inc. (Cambria) is submitting this ground water monitoring report in accordance with the reporting requirements of 23 CCR 2652d.

FOURTH QUARTER 1999 ACTIVITIES

Ground Water Monitoring: Blaine Tech Services, Inc. (Blaine) of San Jose, California gauged water levels, measured dissolved oxygen (DO) concentrations, and sampled the wells. Blaine calculated ground water elevations and compiled the analytical data. Cambria prepared a ground water elevation contour map (Figure 1). The Blaine report, presenting the laboratory report and including supporting field documents, is included as Attachment A.

ANTICIPATED FIRST QUARTER 2000 ACTIVITIES

Oakland, CA
Sonoma CA
Portland OR
Seattle WA

Ground Water Monitoring: Blaine will gauge water levels and measure DO concentrations in all site wells, sample well MW-2, and tabulate the data. Cambria will prepare a monitoring report

Cambria
Environmental
Technology, Inc

Soil and Ground Water Investigation: As required in the Alameda County Health Care Services Agency letter to Equiva dated August 27, 1999, Cambria submitted its *Subsurface Investigation Report* on September 30, 1999. A revised risk assessment will be provided in a forthcoming report

44 6th Street
Suite 3
Oakland CA 94608
Tel (510) 420-0700
Fax (510) 420-9170

ALAMEDA COUNTY
HEALTH CARE SERVICES

AGENCY

DAVID J. KEARS, Agency Director



October 22, 1996
StID # 1070

20349

Mr. Jeff Granberry
Shell Oil Products Company
P.O. Box 4023
Concord CA 94524

ENVIRONMENTAL HEALTH SERVICES
ENVIRONMENTAL PROTECTION (LOP)
1131 Harbor Bay Parkway, Suite 250
Alameda, CA 94502-6577
(510) 567-6700
FAX (510) 337-9335

Re: Former Shell Service Station, 7915 E. 14th St., Oakland 94621

Dear Mr. Granberry:

This letter responds to the October 15, 1996 Cambria letter attached to the third quarter 1996 groundwater monitoring report for the above site. Based on historical monitoring data, Cambria requests that quarterly monitoring for wells be changed to annual monitoring during the second quarter of each year. Please be advised, you may change the monitoring frequency of wells MW-1, MW-3 and MW-4 to an annual basis as long as monitoring occurs during the first quarter of each year. Monitoring of MW-2 should continue on a **quarterly basis** due to the consistent elevated TPHg and BTEX concentrations found in this well and the uncertainty of the source of this contamination. Please also continue to take groundwater elevation measurements on all wells quarterly so a groundwater contour map can continue to be prepared.

In addition, our office has previously spoken with Mr. Paul Waite of Cambria who stated that a work plan was forthcoming for: the investigation of the former underground storage tank complex, performing a phase I investigation of the neighboring auto body and paint shop and the collection of site specific data for a RBCA Tier 2 evaluation.

Please submit this work plan within 30 days or by November 22, 1996.

You may contact me at (510) 567-6765 if you have any questions.

Sincerely,

Barney M. Chan
Hazardous Materials Specialist

c: B. Chan, files
Mr. Scott MacLeod, Cambria Env., 1144 65th St., Suite B,
Oakland CA 94608

2wp7915

Ro 349

SHELL OIL CORPORATION

QUARTERLY REPORT TO

THE CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD

Date of Report: October 29, 1993

Service Station WIC Number:	<u>204-5508-2402</u>
Site Address (Number, Street):	<u>7915 East 14th Street</u>
City:	<u>Oakland</u>
County:	<u>Alameda</u>

Actions in the past three months:

Submitted quarterly status report.
Submitted investigation work plan.

Actions planned for next three months:

Submit quarterly status report.
Conduct subsurface investigation.

Soil Contamination defined? Y\N	<u> N </u>
Soil Clean-up in progress? Y\N	<u> N </u>
Free-product plume defined? Y\N	<u> NA </u>
Free-product cleanup in progress? Y\N	<u> NA </u>
Dissolved constituent plume defined? Y\N	<u> N </u>
Dissolved constituent cleanup in progress? Y\N	<u> NA </u>

Contractor: Weiss Associates, Emeryville, California.



TRANSMITTAL LETTER

FROM: J. Michael Asport

DATE: June 26, 1992

TO: Barney Chan
Alameda County Health Department
Hazardous Materials Department
80 Swan Way, Room 200
Oakland, California 94621

VIA: First Class Mail
 Fax ___ pages
 UPS (Surface)
 Federal Express
 Courier

SUBJECT: CALWATER reports for Shell Oil Company.

JOB: Shell sites

AS: ___ We discussed on the telephone on _____
___ You requested _____
___ We believe you may be interested
 Is required

WE ARE SENDING: Enclosed
___ Under Separate Cover Via _____

Copies of 2nd quarter CALWATER reports that were sent to the RWQCB for Shell sites in your jurisdiction.

FOR: Your information
___ Your use
___ Your review & comments
___ Return to you

PLEASE: Keep this material
___ Return within 2
___ Acknowledge receipt

cc: Kurt Miller
Shell Oil Company
P.O. Box 4023
Concord, CA 94524

closed R0349

SHELL OIL CORPORATION

QUARTERLY REPORT TO

THE CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD

Date of Report: June 25, 1992

Service Station WIC Number:	<u>204-5508-2402</u>
Site Address (Number, Street):	<u>7915 East 14th Street</u>
City:	<u>Oakland</u>
County:	<u>Alameda</u>

Actions in the past three months:

Submitted quarterly status report.

Actions planned for next three months:

Submit quarterly status report.

Soil Contamination defined? Y\N	<u>N</u>
Soil Clean-up in progress? Y\N	<u>N</u>
Free-product plume defined? Y\N	<u>NA</u>
Free-product cleanup in progress? Y\N	<u>NA</u>
Dissolved constituent plume defined? Y\N	<u>NA</u>
Dissolved constituent cleanup in progress? Y\N	<u>NA</u>

Contractor: Weiss Associates, Emeryville, California.

SHELL OIL CORPORATION

QUARTERLY REPORT TO

THE CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD

Date of Report: April 17, 1992

Service Station WIC Number:	<u>204-5508-2402</u>
Site Address (Number, Street):	<u>7915 East 14th Street</u>
City:	<u>Oakland</u>
County:	<u>Alameda</u>

Actions in the past three months:

Submitted quarterly status report.
 Drilled soil borings to assess whether HCs are in the soil or groundwater beneath the site prior to removing the underground gasoline storage tanks.

Actions planned for next three months:

Submit quarterly status report.

Soil Contamination defined? Y\N	<u> N </u>
Soil Clean-up in progress? Y\N	<u> NA </u>
Free-product plume defined? Y\N	<u> NA </u>
Free-product cleanup in progress? Y\N	<u> NA </u>
Dissolved constituent plume defined? Y\N	<u> NA </u>
Dissolved constituent cleanup in progress? Y\N	<u> NA </u>

Contractor: Weiss Associates, Emeryville, California