

Chevron U.S.A. Inc.

2410 Camino Ramon, San Ramon, California • Phone (510) 842-9500 Mail Address: PO. Box 5004, San Ramon, CA 94583-0804

CHARLES CENTRE AND

Marketing Department

January 2, 1992

QUALITY CONTROL BOARD

Station to be demos had

Ms. Susan Hugo

Alameda County Health Care Services

80 Swan Way, Room 200

Qakland, CA 94621

600 p= 14.51

·1/2012

Re: Former Chevron Service Station #9-8864 \$101 Telegraph Avenue, Oakland

Dear Ms. Hugo:

Enclosed we are forwarding the results of the quarterly ground water sampling dated December 23, 1991, prepared by our consultant Siefra Environmental Services for the above referenced site. As indicated in the report, ground water samples collected were analyzed for total petroleum hydrocarbons as gasoline and BTEX. Benzene was detected in all monitor wells at concentrations ranging from 6.5 to 120 ppb. Depth to ground water was measured at approximately 14.5 to 16.8-feet below grade, and the direction of flow is to the southwest.

Our consultant, Pacific Environmental Group, Inc. has been instructed to conduct an investigation to assess the existence of potential off-site sources. This is surmised based on historical elevated concentrations being detected in upgradient monitor well C-1 and significantly higher concentrations being detected in monitor wells C-2 and C-3 during the last two (2) sampling events. In addition, a review of our files indicated no tank failures or product losses of the former tank system. Upon completion of this investigation, all data will be evaluated and appropriate next actions recommended in regards to additional assessment work and possible remediation.

Chevron will continue to monitor this site and report findings on a quarterly basis.

If you have any questions or comments, please do not hesitate to contact me at (510) 842-9581.

Very truly yours, GHEVRON U.S.

Nancy Vukelich

Environmental Engineer

cc: Mr. Eddy So, RWQCB-Bay Area Mr. W.T. Scudder File (9-3864Q1)

Mr. Paul Eveloff 80 E. Sir Francis Drake Blvd. Wood Island, Suite 3A Larkspur, CA 94939



December 23, 1991

Nancy Vukelich Chevron USA P.O. Box 5004 San Ramon, CA 94583

Former Chevron Service Station #9-3864 Re:

5101 Telegraph Avenue Oakland, California SES Project #1-203-04

Dear Ms. Vukelich:

This report presents the results of the quarterly water sampling at Former Chevron Service Station #9-3864, located at 5101 Telegraph Avenue in Oakland, California (Figure 1, Appendix A). Ground water samples from four wells, C-1 through C-4, were collected (Figure 2, Appendix A).

On December 4, 1991, SES personnel visited the site. Free phase hydrocarbons were not present in any of the site wells. Water level data is shown in Table 1 (Appendix B) and a ground water elevation contour map is included as Figure 2 (Appendix A).

The water samples were collected on December 4, 1991 in accordance with SES Standard Operating Procedure - Ground Water Sampling (Appendix C). All analyses were performed by Superior Precision Analytical, Inc. of Martinez, California. Analytic results for ground water are presented in Table 2 (Appendix B). The chain of custody document and analytic reports are included in Appendix D. SES is not responsible for laboratory omissions or errors.

Thank you for allowing us to provide services to Chevron. Please call if you have any questions.

Sincerely,

Sierra Environmental Services

Argy Mena

Environmental Technician

Registered Geologist #003011

AM/RG/ly 20304QM.DE1

Appendices

A - Figures

B - Tables

C - SES Standard Operating Procedure

D - Chain of Custody Document and Laboratory Analytic Reports

ERED OF

R. W. GREENSFELDER

Na. 003011




Figure 1. Site Location Map - Former Chevron Service Station #9-3864, 5101 Telegraph Avenue, Oakland, California




Figure 2. Monitoring Well Location and Ground Water Contour Map - December 4, 1991 - Former Chevron Service Station #9-3864, 5101 Telegraph Avenue, Oakland, California



Table 1. Water Level Data and Well Construction Details - Chevron Service Station #9-3864, 5101 Telegraph Avenue, Oakland, California

Well ID	Date Measured	DTW (ft)	TOC (ft)	GWE (msl)	Product Thickness* (ft)	Screen Interval <	Sand Pack Interval <i>feet below grade</i> -	Bentonite/Grout Interval >
C-1	12/6/90	15.34	117.45	102.11	0	10 - 29.5	8 - 30	0 - 8
	6/6/91	14.62		102.83	0			
	12/4/91	14.48		102.97	0			
C-2	12/6/90	15.34	116.16	100.82	o	10 - 29.5	8 - 30	0 - 8
	6/6/91	14.62		101.54	0			
	12/4/91	15.43		100.73	0			
C-3	12/6/90	16.86	115.70	98.84	0	10 - 29.5	8 - 30	0 - 8
	6/6/91	15.69		100.01	0			
	12/4/91	15.38		100.32	0			
C-4	12/6/90	17.68	116.10	98.42	0	10 - 29.5	8 - 30	0 - 8
	6/6/91	16.49		99.61	0			
	12/4/91	16.82		99.28	0			

EXPLANATION:

DTW = Depth to water

TOC = Top of casing elevation

GWE = Ground water elevation

msl = Measurements referenced relative to mean sea level

NOTES:

Depth to water measurements and top of casing elevations prior to June 6, 1991 were compiled from the January 17, 1991 Site Update Report prepared for this service station by GeoStrategies, Inc. of Hayward, California.

Well construction details were compiled from November 14 and 15, 1990 boring logs by GeoStrategies, Inc.

 Product thickness was measured by GeoStrategies, Inc. on December 6, 1990 with an electronic oil-water interface probe. SES product thickness measurements after 12/6/90 were made with an MMC flexi-dip interface probe.



Table 2. Analytic Results for Ground Water - Chevron Service Station #9-3864, 5101 Telegraph Avenue, Oakland, California

Well ID	Date Sampled	Analytic Lab	Analytic Method	TPPH(G)	В	T ppb	E	X >
C-1	12/6/90	SAL	8015/8020	1,900	17	11	3	21
- "	6/6/91	SAL	8015/8020	3,400	21	15	11	18
	12/4/91	SPA	8015/8020	2,700	22	16	13	23
C-2	12/6/90	SAL	8015/8020	210	140	9	2	11
	6/6/91	SAL	8015/8020	4,800	340	23	19	23
	12/4/91	SPA	8015/8020	3,900	85	15	9.1	15
C-3	12/6/90	SAL	8015/8020	210	2	<0.5	<0.5	1
	$12/6/90^{1}$	SAL	8015/8020	220	2	0.6	< 0.5	2
	6/6/91	SAL	8015/8020	6,400	310	21	16	21
	12/4/91	SPA	8015/8020	5,100	120	18	17	. 20
C-4	12/6/90	SAL	8015/8020	<50	<0.5	<0.5	<0.5	<0.5
	$12/18/90^2$	SAL	8015/8020	<50	<0.5	<0.5	< 0.5	<0.5
	6/6/91	SAL	8015/8020	<50	1.0	1.0	<0.5	0.7
	12/4/91	SPA	8015/8020	70	6.5	9.8	1.7	8.6
Trip Blank	12/6/90	SAL	8015/8020	<50	<0.5	<0.5	<0.5	<0.5
•	$12/18/90^3$	SAL	8015/8020	<50	< 0.5	<0.5	<0.5	<0.5
(AA)	6/6/91	SAL	8015/8020	<50	<0.5	<0.5	<0.5	<0.5
` 7	12/4/91	SPA	8015/8020	<50	<0.5	<0.5	<0.5	<0.5
Bailer Blan	ık 6/6/91	SAL	8015/8020	<50	<0.5	<0.5	<0.5	<0.5
(BB)	12/4/91	SPA	8015/8020	<50	<0.5	<0.5	<0.5	<0.5



Table 2. Analytic Results for Ground Water - Chevron Service Station #9-3864, 5101 Telegraph Avenue, Oakland, California (continued)

EXPLANATION:

TPPH(G) = Total Purgeable Petroleum Hydrocarbons as Gasoline

B = Benzene

T = Toluene

E = Ethylbenzene

X = Xylenes

ppb = Parts per billion

--- = Not analyzed/not applicable

ANALYTIC METHODS:

8015 = EPA Method 8015 for TPPH(G) 8020 = EPA Method 8020 for BTEX

ANALYTIC LABORATORIES:

SAL = Superior Analytical Laboratory of Martinez and San Francisco, California

SPA = Superior Precision Analytical, Inc. of Martinez, California

NOTES:

Ground water analytic data from December 6 and 18, 1990 was compiled from the January 17, 1991 Site Update Reports prepared for this service station by GeoStrategies, Inc. of Hayward, California.

Duplicate sample.

- ² C-4 was also analyzed for halogenated volatile organic compounds (HVOCs) by EPA Method 8010, and metals (Cd, Cr, Pb, Ni and Zn) by EPA-approved methods. Two ppb chloroform, 0.18 ppm chromium, 0.25 ppm nickel and 0.23 ppm zinc were detected. Other HVOCs, Cd and Pb were not detected.
- The trip blank was also analyzed for HVOCs. HVOCs were not detected.

20304T.GW



APPENDIX C SIERRA ENVIRONMENTAL SERVICES STANDARD OPERATING PROCEDURES



SES STANDARD OPERATING PROCEDURE GROUND WATER SAMPLING

The following describes sampling procedures used by SES field personnel to collect and handle ground water samples. Before samples are collected, careful consideration is given to the type of analysis to be performed so that precautions are taken to prevent loss of volatile components or contamination of the sample, and to preserve the sample for subsequent analysis. Wells will be sampled no less than 24 hours after well development. Collection methods specific to ground water sampling are presented below.

Prior to sampling, each well is checked for the presence of free-phase hydrocarbons using an MMC flexi-dip interface probe. Product thickness (measured to the nearest 0.01 foot) is noted on the sampling form. Water level measurements are also made using either a water level meter or the interface probe. The water level measurements are also noted on the sampling form.

Prior to sampling, each well is purged of a minimum of four well casing volumes of water using a steam-cleaned PVC bailer, or a pre-cleaned pump. Temperature, pH and electrical conductivity are measured at least three times during purging. Purging is continued until these parameters have stabilized (i.e., changes in temperature, pH or conductivity do not exceed ± 0.5 °F, 0.1 or 5%, respectively).

The purge water is stored temporarily on-site in 55-gallon Department of Transportation-approved drums pending analytic results. The drums are labeled with the date, contents, the SES field personnel initials and SES phone number.

Ground water samples are collected from the wells with steam-cleaned Teflon bailers. The water samples are decanted into the appropriate container for the analysis to be performed. Prepreserved sample containers may be used or the analytic laboratory may add preservative to the sample upon arrival. Duplicate samples are collected from each well as a back-up sample and/or to provide quality control. The samples are labeled to include the project number, sample ID, date, preservative, and the field person's initials. The samples are placed in polyethylene bags and in an ice chest (maintained at 4°C with blue ice or ice) for transport under chain-of-custody to the laboratory.



The chain-of-custody form includes the project number, analysis requested, sample ID, date analysis and the SES field person's name. The form is signed and dated (with the transfer time) by each person who yields or receives the samples beginning with the field personnel and ending with the laboratory personnel.

A trip blank and bailer blank accompanies each sampling set, or 5% trip blanks and 5% bailer blanks are included for sets of greater than 20 samples. The bailer blank is prepared by pouring previously boiled water into a steam-cleaned Teflon bailer prior to sampling a well. The trip and bailer blanks are analyzed for some or all of the same compounds as the ground water samples.

GWTRSAMP.SOP



APPENDIX D
CHAIN OF CUSTODY DOCUMENT AND
LABORATORY ANALYTIC REPORTS



Superior Precision Analytical, Inc.

825 Arnold Drive, Suite 114 • Martinez, California 94553 • (510) 229-1512 / fax (510) 229-1526

CERTIFICATE OF ANALYSIS

LABORATORY NO.: 84540

DATE RECEIVED: 12/04/91

CLIENT: Sierra Environmental

DATE REPORTED: 12/11/91

CLIENT JOB NO.: 1-203-04

Lab Number	Customer	Sample Id	Page 1 of 2 le Identification			Date Sampled	
84540- 1 84540- 2 84540- 3 84540- 4 84540- 5 84540- 6	MW-AA MW-BB C-4 C-1 C-2 C-3				12/0 12/0	-	
Laboratory I	Number:	84540	8 4 540 2	84540 3	84540 4		 540 5
ANALYTE LIS	T	Amounts/	'Quantitati	on Limits	(ug/L)		
OIL AND GREASE: TPH/GASOLINE RANGE: TPH/DIESEL RANGE: BENZENE:		NA ND<50 NA ND<0.5	NA ND<50 NA ND<0.5	NA 70 NA 6.5	NA 2700 NA 22	NA 390 NA 85	00

OIL AND GREASE: TPH/GASOLINE RANGE: TPH/DIESEL RANGE: BENZENE: TOLUENE: ETHYL BENZENE:	NA ND<50 NA ND<0.5 ND<0.5	NA ND<50 NA ND<0.5 ND<0.5	NA 70 NA 6.5 9.8	NA 2700 NA 22 16 13	NA 3900 NA 85 15
XYLENES:	ND<0.5	ND<0.5	8.6	23	15

Laboratory Number:

84540

6

ANALYTE LIST

Amounts/Quantitation Limits (ug/L)

OIL AND GREASE: NA: TPH/GASOLINE RANGE: 5100 TPH/DIESEL RANGE: NA **BENZENE:** 120 TOLUENE: 18 ETHYL BENZENE: 17 XYLENES: 20

825 Arnold Drive, Suite 114 • Martinez, California 94553 • (510) 229-1512 / fax (510) 229-1526

CERTIFICATE OF ANALYSIS

ANALYSIS FOR TOTAL PETROLEUM HYDROCARBONS

Page 2 of 2 QA/QC INFORMATION SET: 84540

NA = ANALYSIS NOT REQUESTED

ND = ANALYSIS NOT DETECTED ABOVE QUANTITATION LIMIT

ug/L = part per billion (ppb)

OIL AND GREASE ANALYSIS By Standard Methods Method 5520F:
Minimum Detection Limit in Water: 5000ug/L

Modified EPA-SW846 Method 8015 for Extractable Hydrocarbons:
Minimum Quantitation Limit for Diesel in Water: 50ug/L
Standard Reference: NA

EPA-SW846 Method 8015/5030 Total Purgable Petroleum Hydrocarbons:
Minimum Quantitation Limit for Gasoline in Water: 50ug/L
Standard Reference: 10/04/91

SW-846 Method 8020/BTXE

Minimum Quantitation Limit in Water: 0.5ug/L

Standard Reference: 10/11/91

ANALYTE	REFERENCE	SPIKE LEVEL	MS/MSD RECOVERY	RPD	CONTROL LIMIT
Oil & Grease Diesel Gasoline Benzene Toluene Ethyl Benzene Total Xylene	NA NA 10/04/91 12/02/91 12/02/91 12/02/91 12/02/91	NA NA 200 ng 200 ng 200 ng 200 ng 200 ng	NA NA 85/97 88/101 87/98 85/95 92/104	NA NA 14 14 12 11	NA NA 70-130 70-130 70-130 70-130

Richard Srna, Ph.D.

Laboratory Director

Certified Laboratories

Fax copy of Lab Report and COC to Chevron Contact: 12 No \$4590 Chain-of-Custody-Record #9-3864 NANCY VURGLICH Chevron Facility Number ... Chevron Contact (Name) _ Facility Address SIDI TELEGRAPH AVE, DAKLAND (510) 842-9581 Chevron U.S.A. inc. Consultant Project Number 1-203-04 Laboratory Name SUPERIOR PRECISION ANALYTICAL P.O. BOX 5004 Consultant Name SIETRA ENVIRONMENTAL SERVICES 4056670 Laboratory Release Number San Ramon, CA 94583 Address P.O. BOX 2546 MARTINEZ ARGY MENA Samples Collected by (Name)..... FAX (415)842-9591 4 Dec 91 Project Contact (Name) JEANNE WAHLER Collection Date. (Phone) (510) 370-1280 (Fax Number) (510) 370-7959 Signature ____ Air Charcool Analyses To Be Performed Grab Composite Discrete Purgeable Halocarbons (8010) Containera Purgeable Aromatics (8020) BIEX + TPH GAS (8020 + 8015) # # **∀** ♡ TPH Diesel (8015) U 7 8 000 Remorks AMALYZE IN 12:34 HeL MW-AA MW . BB 12:4/ orden 12:45 C-1 12:55 Please in train. / Samples Stored in ice. 13:10 C-2 13:15 C-3 VOA's william had of Cammer --Relinguished By (Signature) Organization Date/Time /5:74 Received By (Signature) Organization Date/Time Turn Around Time (Circle Cholce) 525 4Dec 50, 24 Hrs. 48 Hre. Relinquished By (Signature) Organization Date/Time Received By (Signature) Organization Date/Time 5 Daye 10 Days Date/Time 15名 Relinquished By (Signoture) Date/Time Reclaved For Laboratory By (Signature) Organization As Contracted 12/4/91