Ultramar

Telecopy: 209-584-6113 Credit & Wholesale 209-583-3330 Administrative 209-583-3302 Information Services 209-583-3358 Accounting

January 8, 1993

Hanford, CA 93232-0466 (209) 582-0241

Ultramar Inc.

525 W. Third Street

P.O. Box 466

Mr. Scott O. Seery, CHMM Senior Hazardous Materials Specialist Alameda County Health Care Services 80 Swan Way, Room 200 Oakland, CA 94621

SUBJECT: FORMER BEACON STATION NO. 574, 22315 REDWOOD ROAD, CASTRO VALLEY,

CALIFORNIA

Dear Mr. Seery:

Enclosed is a copy of the Quarterly Monitoring Report Third Quarter 1992 for the above-referenced Ultramar facility prepared by Aegis Environmental Inc. Also included with the report is a copy of the Quarterly Status report describing the work performed this quarter and the work anticipated to be conducted in the next quarter.

Please do not hesitate to call if you have any questions about this project at (209) 583-5571.

Sincerely,

ULTRAMAR INC.

Kenneth R. Earnest

Environmental Specialist I

Marketing Environmental Department

Enclosure:

Quarterly Groundwater Monitoring, Third Quarter 1992

Quarterly Project Status Report

cc w/encl:

Mr. Rich Hiett, San Francisco Bay Region, RWQCB



Ultramar

Ultramar Inc.

P.O. Box 466 525 W. Third Street Hanford, CA 93232-0466 (209) 582-0241

Telecopy: 209-584-6113 Credit & Wholesale 209-583-3330 Administrative 209-583-3302 Information Services 209-583-3358 Accounting

ENVIRONMENTAL PROJECT QUARTERLY STATUS REPORT

DATE REPORT SUBMITTED: January 8, 1993 QUARTER ENDING: September 30, 1992

FORMER SERVICE STATION NO.: 574

ADDRESS: 22315 Redwood Road, Castro Valley, CA

COUNTY: Alameda

ULTRAMAR CONTACT: Kenneth R. Earnest

TEL. NO: 209-583-5571

BACKGROUND:

On May 5, 1987, five underground storage tanks (two gasoline, two diesel and one waste oil) were excavated and removed from Soil samples were collected from beneath the tanks the site. hydrocarbon constituents. Based on analyzed for preliminary analytical data related to the collected soil samples, it was determined that elevated levels of gasoline and diesel were present in the soil beneath the former fuel Soil was overexcavated from beneath the former fuel Soil samples were collected after the over-excavation tanks. and confirmed that the addition excavation was successful.

During March 1991, three ground-water monitoring wells were Laboratory analysis of soil samples installed on-site. the borings for the installation of the obtained from monitoring wells indicated that the soil near the soil/water interface exhibited gasoline range hydrocarbons.

Quarterly monitoring was initiated during the fourth quarter 1991.

SUMMARY OF THIS QUARTER'S ACTIVITIES:

Performed third quarter monitoring on September 23, 1992.

RESULT OF QUARTERLY MONITORING:

Results indicate that since the previous sampling event benzene and TPH-g concentrations in MW-1, MW-2 and MW-3 have increased.



PROPOSED ACTIVITY OR WORK FOR NEXT QUARTER:

<u>ACTIVITY</u>

ESTIMATED COMPLETION DATE

Fourth quarter monitoring

December 1992

Install five ground-water monitoring wells

February 1993



neviewed 1/20/93 505

AEGIS ENVIRONMENTAL, INC.

1050 Metody Lane, Suite 160, Roseville, CA 95678

916 • 782-2110 / 916 • 969-2110 / FAX 916 • 7\$6-7830

December 14, 1992

regulated capies of field sampling shocks

Mr. Kenneth Earnest Environmental Specialist I Ultramar Inc. 525 West Third Street Hanford, California 93232-0466

Subject:

Third Quarter Monitoring Letter Report, September 1992

Beacon Station #574

22315 Redwood Road, Castro Valley, California

Dear Mr. Earnest:

INTRODUCTION

Aegis Environmental, Inc. (Aegis), has been authorized by Ultramar Inc. (Ultramar), to conduct groundwater monitoring at the former Beacon service station site, #574, located at 22315 Redwood Road, Castro Valley, Alameda County, California (site). This letter report documents the third quarter groundwater monitoring conducted by Aegis on September 23, 1992, at this site (Figure 1). This letter report is based, in part, on information obtained by Aegis from Ultramar, and is subject to modification as newly acquired information may warrant.

SITE DESCRIPTION

The former Beacon site currently is a strip shopping center occupied by a 7-Eleven store, Lee's Donuts, Redwood Cleaners, Pizza Express, and Rob's Video. There are no longer underground storage tanks at the former Beacon site. Details of the former Beacon site facilities, including monitoring wells, are shown on Figure 2.

91-212D.QMR

GROUNDWATER MONITORING

Groundwater Measurements

On September 23, 1992, Aegis personnel collected measurements of the depth to groundwater in monitoring wells MW-1, MW-2, and MW-3 on the former Beacon site. Depth to water ranged from 22.45 to 24.07 feet below grade at the former Beacon site. On the basis of the September 23, 1992, measurements, groundwater is estimated to flow to the southwest (Figure 3) at an average gradient of approximately 1802 11/ft.

Current and previous groundwater levels are summarized in Table 1 for the former Beacon site. All groundwater elevation measurements at the former Beacon site were made from the referenced wellhead elevations, measured to the nearest 0.01 foot, and conducted according to the Aegis standard operating procedures (SOP) included in Attachment 1.

Groundwater Sampling and Analyses

On September 23, 1992, Aegis personnel collected groundwater samples from monitoring wells MW-1, MW-2, and MW-3. The samples were collected according to the Aegis SOP included as Attachment 1, and delivered under chain-of-custody to West Analytical Laboratory of Davis, California, a state-certified analytical laboratory. The samples were analyzed for concentrations of total (volatile) petroleum hydrocarbons (TPH), as gasoline, by modified EPA Method 8015/purge-and-trap, benzene, toluene, ethylbenzene, and total xylenes (BTEX) by EPA Method 602, and TPH, as diesel, by modified EPA Method 8015/extraction. The analytical results are summarized in Table 2. The analytical reports and chain-of-custody forms are included in Attachment 2. I not analyzed for TPH-15

RECOMMENDATIONS

It is recommended that copies of this letter report be forwarded to the following agencies:

Mr. Scott Seery Senior Hazardous Materials Specialist Alameda County Health Agency Division of Hazardous Materials Department of Environmental Health 80 Swan Way, Room 350 Oakland, California 94621

Mr. Rich Hiett San Francisco Bay Region Water Quality Control Board 2101 Webster Street, Suite 500 Oakland, California 94612

REMARKS/SIGNATURES

The interpretations and/or conclusions contained in this letter report represent our professional opinions. These opinions are based on currently available information and were developed in accordance with currently accepted geologic, hydrogeologic, and engineering practices at this time and for this specific site. Other than this, no warranty is implied or intended.

This letter report has been prepared solely for the use of Ultramar Inc. Any reliance on this letter report be third parties shall be at such parties' sole risk. The work described herein was performed under the direct supervision of the professional geologist, registered with the State of California, whose signature appears below.

Sincerely,

AEGIS ENVIRONMENTAL, INC.

Wright

John Giorgi Staff Geologist

Pat Wright

Registered Geologist

CRG No. 529


72-16-9<u>2</u> Date

JG/PW/law



FIGURES:	FIGURE 1 SITE LOCATION MAP
	FIGURE 2 SITE MAP
	FIGURE 3 POTENTIOMETRIC SURFACE MAP
	FIGURE 4 ISOCONCENTRATION MAP OF BENZENE IN GROUNDWATER
TABLES:	TABLE 1
	TABLE 2 ANALYTICAL RESULTS: GROUNDWATER
ATTACHMENTS:	ATTACHMENT 1 STANDARD OPERATING PROCEDURES
·	ATTACHMENT 2 ANALYTICAL LABORATORY REPORTS AND CHAIN-OF-CUSTODY FORM

-




AEGIS ENVIRONMENTAL, INC.		SITE LOCATION MAP	FIGURE
DRAWNBY: Ed Berand	DATE: April 13, 1992	Former Beacon Station # 574	1
REVISED BY:	DATE:	22315 Redwood Road	PROJECT NUMBER:
REVIEWED BY:	DATE:	Castro Valley, CA	10-91212

Approximate Scale


1" = 2000'


7.5 MINUTE TOPOGRAPHIC

HAYWARD, CALIF.



AECIS ENVIRONMENTAL, INC.		SITE MAP	FIGURE
DRAWNBY: Ed Bernard	DATE: April 8, 1992	Former Beacon Station # 574	
REVISED BY:	DATE:	22315 Redwood Road	PROJECT NUMBER:
REVIEWED BY:	DATE:	Castro Valley, CA	10-91212





(A)	AEGIS ENN	/ironmental, inc	ISOCONCENTRATION OF BENZENE IN GROUNDWATER September 23, 1992	FIGURE
DRAWN BY:	Ed Bernard	DATE: October 28, 1992	Former Beacon Station # 574	
PEVISED BY: Ed Bernard December 8, 1992			22315 Redwood Road	PROJECT NUMBER:
REVIEWED BY: DATE:		DATE:	Castro Valley, CA	10-91212

TABLE 1
WATER LEVEL DATA - FORMER BEACON STATION

FORMER BEACON STATION #574 22315 REDWOOD ROAD, CASTRO VALLEY, CALIFORNIA (Measurements in feet)

Monitoring Well	Date	Reference Elevation (top of casing) ¹	Depth to Groundwater ¹	Groundwater Elevation ²
MW-1	03/26/91 04/01/91 11/22/91 03/27/92 06/04/92 09/23/92	156.55	22.43 22.37 24.09 22.43 23.40 24.07	134.12 134.18 132.46 134.12 133.15 132.51
MW-2	03/26/91 04/01/91 11/22/91 03/27/92 06/04/92 09/23/92	155.17	20.91 20.82 22.54 20.82 21.81 22.45	134.26 134.35 132.63 134.35 133.36 132.72
MW-3	03/26/91 04/01/91 11/22/91 03/27/92 06/04/92 09/23/92	157.13	21.62 21.55 23.98 21.46 22.34 22.84	135.51 135.58 133.15 135.67 134.79 134.29

NOTES:

 Measurement and reference elevation taken from notch/mark on top north side of well casing.

Elevation referenced to mean sea level and obtained from previous consultant.

TABLE 2
ANALYTICAL RESULTS: GROUNDWATER

FORMER BEACON STATION #574 22315 REDWOOD ROAD, CASTRO VALLEY, CALIFORNIA (All results in parts-per-billion)

Sample ID	Date Collected	Total Petro	leum Hydr	ocarbons	Aromatic Volatile Organics						
		Gasoline	Diesel	Motor Oil	Benzene	Toluene	Ethyl- benzene	Total Xylenes			
MW-1	04/01/91	4,100	<100		340	570	76	460			
	11/22/91	5,300	<50	<50	4.9	1,600	370	2,300			
	03/27/92	5,600	<50	<50	760	900	230	1,100			
	06/04/92	2,600	<800		270	57	230	440			
	09/23/92	3,400			480	430	110	550			
MW-2	04/01/91	10,000	<100		650	640	150	960			
	11/22/91	11,000	<50	<50	51	1,900	770	3,200			
	03/27/92	18,000	<50	<50	2,400	2,300	870	3,300			
	06/04/92	14,000	<5,000		1,900	1,700	580	2,300			
	09/23/92	22,000			2,100	1,500	760	2,900			
MW-3	04/01/91	3,100	<100		41	91	37	420			
	11/22/91	470	<50	<50	10	6.3	11	36			
	03/27/92	160	<50	<50	9.2	4.8	10	23			
	06/04/92	120	<50		7.5	2.7	0.5	15			
	09/23/92	220 .			0.3	4.3	6.2	19			

NOTES: < = Below the indicated detection limits labeled in the analytical laboratory results report.

--- = Not analyzed.

ATTACHMENT 1 STANDARD OPERATING PROCEDURES

AEGIS ENVIRONMENTAL, INC. STANDARD OPERATING PROCEDURES

RE: SAMPLE IDENTIFICATION AND CHAIN-OF-CUSTODY PROCEDURES

SOP-4

Sample identification and chain-of-custody procedures ensure sample integrity, and document sample possession from the time of collection to its ultimate disposal. Each sample container submitted for analysis is labeled to identify the job number, date, time of sample collection, a sample number unique to the sample, any in-field measurements made, sampling methodology, name(s) of on-site personnel and any other pertinent field observations also recorded on the field excavation or boring log.

Chain-of-custody forms are used to record possession of the sample from time of collection to its arrival at the laboratory. During shipment, the person with custody of the samples will relinquish them to the next person by signing the chain-of-custody form(s) and noting the date and time. The sample-control officer at the laboratory will verify sample integrity, correct preservation, confirm collection in the proper container(s), and ensure adequate volume for analysis.

If these conditions are met, the samples will be assigned unique laboratory log numbers for identification throughout analysis and reporting. The log numbers will be recorded on the chain-of-custody forms and in the legally-required log book maintained in the laboratory. The sample description, date received, client's name, and any other relevant information will also be recorded.

AEGIS ENVIRONMENTAL, INC. STANDARD OPERATING PROCEDURES RE: LABORATORY ANALYTICAL QUALITY ASSURANCE AND CONTROL SOP-5

In addition to routine instrument calibration, replicates, spikes, blanks, spiked blanks, and certified reference materials are routinely analyzed at method-specific frequencies to monitor precision and bias. Additional components of the laboratory Quality Assurance/Quality Control program include:

- 1. Participation in state and federal laboratory accreditation/certification programs;
- 2. Participation in both U.S. EPA Performance Evaluation studies (WS and WP studies) and inter-laboratory performance evaluation programs;
- 3. Standard operating procedures describing routine and periodic instrument maintenance;
- 4. "Out-of-Control"/Corrective Action documentation procedures; and,
- 5. Multi-level review of raw data and client reports.

AEGIS ENVIRONMENTAL, INC. STANDARD OPERATING PROCEDURE RE: GROUNDWATER PURGING AND SAMPLING

SOP-7

Prior to water sampling, each well is purged by evacuating a minimum of three wetted well-casing volumes of groundwater. When required, purging will continue until either the discharge water temperature, conductivity, or pH stabilize, a maximum of ten well-bore volumes of groundwater have been recovered, or the well is bailed dry. When practical, the groundwater sample should be collected when the water level in the well recovers to at least 80 percent of its static level.

The sampling equipment consists of either a "Teflon" bailer, PVC bailer, or stainless steel bladder pump with a "Teflon" bladder. If the sampling system is dedicated to the well, then the bailer is usually "Teflon," but the bladder pump is PVC with a polypropylene bladder. In general and depending on the intended laboratory analysis, 40-milliliter glass, volatile organic analysis (VOA) vials, with "Teflon" septa, are used as sample containers.

The groundwater sample is decanted into each VOA vial in such a manner that there is no meniscus at the top of the vial. A cap is quickly secured to the top of the vial. The vial is then inverted and gently tapped to see if air bubbles are present. If none are present, the vial is labeled and refrigerated for delivery, under strict chain-of-custody, to the analytical laboratory. Label information should include a unique sample identification number, job identification number, date, time, type of analysis requested, and the sampler's name.

For quality control purposes, a duplicate water sample is collected from each well. This sample is put on hold at the laboratory. When required, a trip blank is prepared at the laboratory and placed in the transport cooler. It is labeled similar to the well samples, remains in the cooler during transport, and is analyzed by the laboratory along with the groundwater samples. In addition, a field blank may be prepared in the field when sampling equipment is not dedicated. The field blank is prepared after a pump or bailer has been either steam cleaned or properly washed, prior to use in the next well, and is analyzed along with the other samples. The field blank analysis demonstrates the effectiveness of the in-field cleaning procedures to prevent cross-contamination.

To minimize the potential for cross-contamination between wells, all well development and water sampling equipment not dedicated to a well is either steam cleaned or properly washed between use. As a second precautionary measure, wells are sampled in order of least to highest concentrations as established by available previous analytical data.

In the event the water samples cannot be submitted to the analytical laboratory on the same day they are collected (e.g., due to weekends or holidays), the samples are temporarily stored until the first opportunity for submittal either on ice in a cooler, such as when in the field, or in a refrigerator at Aegis' office.

AEGIS ENVIRONMENTAL, INC. STANDARD OPERATING PROCEDURE

RE: MEASURING LIQUID LEVELS USING WATER LEVEL OR INTERFACE PROBE SOP-12

Field equipment used for liquid-level gauging typically includes the measuring probe (water-level or interface), light filter(s), and product bailer(s). The field kit also includes cleaning supplies (buckets, TSP, spray bottles, and deionized water) to be used in cleaning the equipment between wells.

Prior to measurement, the probe tip is lowered into the well until it touches bottom. Using the previously established top-of-casing or top-of-box (i.e., wellhead vault) point, the probe cord (or halyard) is marked and a measuring tape (graduated in hundredths of a foot) is used to determine the distance between the probe end and the marking on the cord. This measurement is then recorded on the liquid-level data sheet as the "depth to water" (DTW).

When necessary in using the interface probe to measure liquid levels, the probe is first electrically grounded to either the metal stove pipe or another metal object nearby. When no ground is available, reproducible measurements can be obtained by clipping the ground lead to the handle of the interface probe case. After grounding the probe, the top of the well casing is fitted with a light filter to insure that sunlight does not interfere with the operation of the probe's optical mechanism.


The probe tip is then lowered into the well and submerged in the groundwater. An oscillating (beeping) tone indicates the probe is in water. The probe is slowly raised until either the oscillating tone ceases or becomes a steady tone. In either case, this is the depth-to-water indicator and the DTW measurement is made accordingly. The steady tone indicates floating hydrocarbons. In this case, the probe is slowly raised until the steady tone ceases. This is the depth-to-product (DTP) indicator and the DTP measurement is made accordingly.

The process of lowering and raising the probe must be repeated several times to ensure accurate measurements. The DTW and DTP measurements are recorded on the liquid-level data sheet. When floating product is indicated by the probe's response, a product bailer is lowered partially through the product-water interface to confirm the product on the water surface, and as further indication of product thickness, particularly in cases where the product layer is quite thin. This measurement is recorded on the data sheet as "product thickness."

In order to avoid cross-contamination of wells during the liquid-level measurement process, wells are measured in the order of "clean" to "dirty" (where such information is available). In addition, all measurement equipment is cleaned with TSP solution and thoroughly rinsed with deionized water before use, between measurements in respective wells, and at the completion of the day's use.

ATTACHMENT 2

ANALYTICAL LABORATORY REPORTS AND CHAIN-OF-CUSTODY FORM





John Giorgi Aegis Environmental Consultants, Inc. 1050 Melody Lane, Suite 160 Roseville, CA 95678 RECEIVED

OCT - 5 1992

Ansid CF/AJG

Subject: Analytical Results for 3 Water Samples

Identified as: Project # 91-212 (Beacon 574)

Received: 09/24/92

Dear Mr. Giorgi:

Analysis of the sample(s) referenced above has been completed. This report is written to confirm results communicated on October 2, 1992 and describes procedures used to analyze the samples.

Sample(s) were received in 40-milliliter glass vials sealed with TFE lined septae and plastic screw-caps. Each sample was transported and received under documented chain of custody and stored at 4 degrees C until analysis was performed.


Sample(s) were analyzed using the following method(s):

"BTEX" (EPA Method 602/Purge-and-Trap)
"TPH as Gasoline" (Modified EPA Method 8015/Purge-and-Trap)

Please refer to the following table(s) for summarized analytical results and contact us at 916-757-4650 if you have questions regarding procedures or results. The chain-of-custody document is enclosed.

Approved by:

Joel Kiff





Sample: MW-1

From : Project # 91-212 (Beacon 574)


Sampled: 09/23/92

Dilution: 1:5


QC Batch: 4056E

Matrix : Water

Parameter	(MDL) ug/L	Measured Value ug/L
_		400
Benzene	(2.5)	480
Toluene	(2.5)	430
Ethylbenzene	(2.5)	110
Total Xylenes	(2.5)	550
TPH as Gasoline	(250)	3400



Western Environmental Science & Technology • 45133 County Road 32B • Davis, CA 95616 • 916 753-9500 • FAX: 916 757-4652






Sample: MW-2


From : Project # 91-212 (Beacon 574)
Sampled : 09/23/92
Dilution : 1:10 QC Batch QC Batch: 4056E

Matrix : Water

Parameter	(MDL) ug/L	Measured Value ug/L
Benzene	(5.0)	2100
Toluene	(5.0)	1500
Ethylbenzene	(5.0)	760
Total Xylenes	(5.0)	2900
TPH as Gasoline	(500)	22000



Date Analyzed: 09-29-92 Column: 0.53mm ID X 30m DBHAX (J&H Scientific)





Sample: MW-3


From : Project # 91-212 (Beacon 574)

Sampled: 09/23/92

Dilution: 1:1 QC Batch: 4056G

Matrix : Water

Parameter	(MDL) ug/L	Measured Value ug/L
Benzene	(.50)	8.3
Toluene	(.50)	4.3
Ethylbenzene	(.50)	6.2
Total Xylenes	(.50)	19
TPH as Gasoline	(50)	220



Date Analyzed: 09-30-92 Column: 0.53mm ID X 30m DBHAX (J&H Scientific)

Western Environmental Science & Technology - 45133 County Road 32B - Davis, CA 95616 - 916 753-9500 - FAX: 916 757-4652



Ultramar Inc.CHAIN OF CUSTODY REPORT

Beacon Station No.	Sampler (Print I	11								9-73-92	Form No	
574	BRNW HENDERSON					ANA	ALYSES	<u> </u>	-			
Project No.	Sampler (Signature)								,,	Toh	1651	
91-21Z	bre	Dea		╛┟	ē				Containers	753.	TST	\supset
Project Location Z C 3 15 Rep Louise Ra	I 6				悥	sed			onta	ZWK	THE	
CASTRO VAILET GA	36817 Z	EC-	+	_×	g	ğ			Š		(/ ()	
Sample No./Identification	Date	Tin	e Lab No.	BTEX	TPH (gasoline)				S	REMARI	KS	
MW-1	9-23-92	3:0	5	Y	V							
	9-23-92	3:11	ا ر	<i>y</i>	×							
MU-Z MU-3	9-2392			×	×							·
							- 	7	1	-		
									_			 -
					-						-	
Relinguished by: (Signature/Affiliation)	Date	Time	Received by: (Signatu	ле/А	ffili	atio	<u></u> i n)	<u></u>		<u> </u>	Date	Time
(Morrished	1/24/2	4:05										
Relinquished by: (Signature/Affiliation)	Date	Time	Received by: (Signatu	re/A	ffili	atio	n)				Date	Time
Relinquished by: (Signature/Affiliation)	Date	Time	Received by: (Signati	ıre/A	ffili	atio	n)				Date .	Time
Troining and by the control of the c			Juy & J Bill to: ULTRAMA								9/24/92	16:05
Report To: John G101261	· · · · · · · · · · · · · · · · · · ·		Bill to: ULTRAMA 525 West								7	-
1050 MELODY LH. HIGO			Hanford, C	A 93		Λ	4			ct-NI.	ایس	
Rosewite Ca 95678			Attention:			N	AN!	44	L	STEPHEN	50N	
WHITE: Return to Client with Report	YELLOW: Labo	ratory C	opy PINK: Orig	inato	r C	ору	· · · · · · · · · · · · · · · · · · ·			PL 1	553	003 1/90