Nowell, Keith, Env. Health

From: Nowell, Keith, Env. Health

Sent: Friday, August 04, 2017 11:40 AM

To: 'Jeff Friedman'

Cc: Ed.C.Ralston@p66.com; 'lewis.mosconi@P66.com'; Roe, Dilan, Env. Health; Khatri,

Paresh, Env. Health

Subject: BP #11117, RO356 and GeoTracker Global ID T0600100201, 7210 Bancroft Avenue,

Oakland

Jeff,

In response to your email -

The document entitled *Dual Phase Extraction Pilot Test Report* dated August 9 2002 is named IR_R_2002-08-08 on our FTP site;

The document entitled *Remediation System Installation* dated September 26, 2008 is named IR_R_2008-09-26 on our FTP site.

Re list for information/ document submittal, our agency did not specify a response date(s). Please note that items not responded to will need to be addressed prior to closure consideration:

- 1. The Ph I ESA, dated September 21, 2015 appears to have been received by our office on July 12, 2016;
- 2. Contaminant Modeling DVD- not located in case file;
- 3. Re WOTs and hoists information request- no additional information submitted to FTP;
- 4. SG Investigation: No formal WP submitted to ACDEH, FTP file WP_R_2016-12-22 contains a revised figure.
- 5. Re DPE effectiveness- no additional information submitted to FTP;
- 6. Re Bail Down Test no additional information submitted to FTP;
- 7. Re residual contamination in soil- no additional information submitted to FTP;
- 8. Re residual contamination in groundwater- no additional information submitted to FTP;
- Re hydrographs- no additional information submitted to FTP;
- 10. Re hydrograph data presentation- no additional information submitted to FTP;
- 11. Re depth to water data review- no additional information submitted to FTP;
- 12. Re sensitive receptors- no additional information submitted to FTP;
- 13. Re LTCP Direct Contact- no additional information submitted to FTP.

Please include the ACDEH case file number in the subject line for future correspondences with our agency.

Regards,

Keith Nowell

Keith Nowell PG, CHG Hazardous Materials Specialist Alameda County Department of Environmental Health 1131 Harbor Bay Parkway Alameda , CA 94502-6540 phone: 510 / 567 - 6764 fax: 510 / 337 - 9335 email: keith.nowell@acgov.org

From: Jeff Friedman [mailto:Jeff.Friedman@anteagroup.com]

Sent: Thursday, August 03, 2017 10:35 AM

To: Nowell, Keith, Env. Health <Keith.Nowell@acgov.org>

Subject: RE: 2611117 7210 Bancroft Avenue in Oakland - Request for Information

FYI, Hi Keith, the letter referring to the two documents I cannot seem to find is attached.

Jeffrey Friedman | Senior Project Manager | USA Antea® Group

3229 East Spring Street, Suite 100, Long Beach CA 90806 Direct +1 562 206 2551 | Mobile +1 626 408 4534 Fax +1 562 424 3800 | USA Toll Free 800 477 7411 jeff.friedman@anteagroup.com| www.anteagroup.com



Member of Inogen® | www.inogenet.com

From: Jeff Friedman

Sent: Thursday, August 03, 2017 9:01 AM

To: 'Nowell, Keith, Env. Health'

Subject: 2611117 7210 Bancroft Avenue in Oakland - Request for Information

Good Morning Keith, I am in the process of preparing an updated site history and determining the status of where we are in providing information to you in response to the attached July 7, 2016 letter. First, the following two references were mentioned in a past letter, and I have been unable to locate them for inclusion into the site history. Could you either point me to the correct document on your FTP site or email me copies of the documents.

- Cambria Environmental Technology, Inc. (Cambria), <u>Dual Phase Extraction Pilot Test</u>
 <u>Report</u>, Former BP Oil Site No. 11117, 7210 Bancroft Avenue, Oakland California, August

 9.
- STRATUS Environmental, Inc. (STRATUS), 2008b, Remediation System Installation,
 Former BP Service Station #11117, 7210 Bancroft Avenue, Oakland, California,
 September 26.

Could you review the list of items below that were included in the attached letter and let me know which items have been addressed. For documentation purposes, it would be helpful for me to know what was provided, when we provided it, and how it was transmitted. My goal is to include this information in the site background I am preparing. I know that the Phase 1 and the soil gas investigation work plan (along with the revision) have been uploaded in Geotracker, but there is no documentation acknowledging receipt of the other requested items.

Based on the meeting discussion, ACDEH requested the following iter

- Phase 1 Environmental Site Assessment (ESA) provide / site for new property owner, 7200 Bancroft Avenue LLC. Plea as an electronic mail attachment, Attention Keith Nowell.
- Contaminant Modeling Antea will provide ACDEH a copy c contamination. The 3-D model will be provided to ACDEH on
- Waste Oil Tanks and Hydraulic Hoists
 — Perform records revunderground storage tanks (USTs) and hydraulic hoists. Evaluation for these structures if waste oil USTs and/or hydraulic hoists a
- 4. Soil Gas Investigation Work Plan Please prepare a work prepares to assess the vapor intrusion pathway. Based on the requests that, at a minimum, soil gas samples are to be recovered surface (bgs). Please analyze samples for TPH as gasoline (susing EPA test method TO-15, and the fixed gases oxygen, care D1946. Additionally, ACDEH requests the analysis for the proper appropriate analysis test method. Please collect the samples Gas Investigations prepared by California Environmental Prote Control (Cal EPA / DTSC), and the Regional Water Quality Control (SFRWQCB) regions. ACDEH requests the control samples be corroborated using the EPA TO-17 analysis.
- Dual Phase Extraction Test Discuss the effectiveness of the 2011.

- Free Phase Product Bail Down Test ACDEH requests a reviet testing was performed to assess the mobility of free phase product
- Residual Contamination In Soil Perform a case file review to cremoved. Discuss the distribution of light non-aqueous phase per petroleum hydrocarbons in soil.
- Residual Contamination In Groundwater Prepare contaminar benzene, and methyl tertiary butyl ether (MTBE) depicting the ext groundwater. Include the data from the SB soil bores from the 20 boxes on the plume maps, but only consider groundwater monitor
- Hydrographs Please prepare hydrographs for all wells associate the next meeting. Depict if the well screens were appropriate to d
- 10. Hydrograph Data Presentation Several hydrographs were rev regarding the hydrographs are applicable to the others. Please place graph when remediation, e.g. dual phase extraction, chemical injection, was performed at the site.
- 11. Depth to Water A review of the hydrographs indicate adjustment have occurred. ACDEH requests a review of the case file to evaluate a cause of the apparent changes in the dtw data. ACDEH addition ACDEH case file number RO0000274 and GeoTracker Global ID located across Bancroft Avenue, be reviewed for similar changes.
- 12. Sensitive Receptors Please conduct a case file review to dete Agency (ACPWA) files were reviewed for the well survey. If the A survey of vicinity wells to include the ACPWA database.
- 13. LTCP Direct Contact Criteria Please prepare a plan view figur foot and 5- to 10-foot intervals indicating the concentrations of TP ethylbenzene, and naphthalene for each soil bore. Include prepare of the zones depicting the distribution of contamination.

Jeffrey Friedman | Senior Project Manager | USA Antea® Group

3229 East Spring Street, Suite 100, Long Beach CA 90806 Direct +1 562 206 2551 | Mobile +1 626 408 4534 Fax +1 562 424 3800 | USA Toll Free 800 477 7411 jeff.friedman@anteagroup.com | www.anteagroup.com



Member of Inogen® | www.inogenet.com

This e-mail is personal. For our full disclaimer, please visit http://www.anteagroup.com/confidentiality.