

## **RECEIVED**

11:55 am, Sep 30, 2011 Alameda County Environmental Health Antea USA, Inc. 312 Piercy Road San Jose, California, 95138 USA www.anteagroup.com

September 29, 2011

Paresh Khatri Alameda County Health Care Services Agency 1131 Harbor Bay Parkway Alameda, California 94502-6577

Re:

**Technical Report – Extension Request** 

Remedial Action Investigation Work Plan 76 (Former BP) Service Station No. 2611117 7210 Bancroft Avenue Oakland, California

Dear Mr. Khatri,

I declare under penalty of perjury that, to the best of my knowledge, the information and/or recommendations contained in the attached report is/are true and correct.

If you have any questions or need additional information, please call me at (408) 826-1874.

Sincerely,

Douglas K. Umland, P.G.

Senior Project Manager

doug.umland@anteagroup.com

Antea Group

Enc: Antea Group, *Technical Report – Extension Request*, dated September 29, 2011.





Antea USA, Inc. 312 Piercy Road San Jose, California 95138 USA www.anteagroup.com

September 29, 2011

Paresh C. Khatri Alameda County Environmental Health Department 1131 Harbor Bay Parkway, Suite 250 Alameda, California 94502-6577

Subject: **Technical Report - Extension Request**Former BP Service Station No. 11117
7210 Bancroft Avenue, Oakland, California
Fuel Leak Case No. RO0000356
GeoTracker Global ID No. T0600100201

Dear Me. Khatri:

Antea Group®, Formerly Delta Consultants, has received Alameda County Environmental Health Department's (ACEH) September 1, 2011 agency letter responding to Antea Group's August 3, 2011 Remedial Action Investigation Work Plan. The ACEH's agency letter specified a due date of December 2, 2011 for the soil/water investigation and pilot testing report. Due to scheduling, pilot testing, and bench-scale testing durations, Antea Group is requesting an extension of the due date for report submittal.

As discussed in the *Remedial Action Investigation Work Plan* and ACEH's agency letter, Antea Group will perform bench-scale tests to evaluate several In-Situ Chemical Oxidation (ISCO) strategies. Bench scale testing requires up to 90 days for completion. Fieldwork to collect soil/water samples for use during the bench scale testing is set for the week of October 3, 2011. The required due date of December 2, 2011 will not allow Antea Group to complete these tests and evaluate the results in time to be reported by this due date. Therefore, **Antea Group is requesting the ACEH extend the technical report due date to February 3, 2012**. An extension of the due date will allow a complete evaluation of the ISCO bench-scale test results, soil and groundwater analytical results, and pilot testing results to develop a remedial path forward for the site.

If you have any questions regarding this extension request, reporting requirements, or need additional information, please do not hesite to contact me at (800) 477-7411.

- Climbers

Sincerely,

**Douglas K. Umland, P.G.** Senior Project Manager

doug.umland@anteagroup.com

Antea Group



Mr. Paresh C. Khatri Alameda County Environmental Health Department. September 29, 2011 Page 2

Cc: Diane Clark, Eastmont Town Center
Shannon Couch, ARCO
Bill Borgh, ConocoPhillips
Jim Givens, Argonaut Financial Services, Inc.