A Report Prepared for

Texaco Refining and Marketing Inc. 10 Universal City Plaza Universal City, California 91608

QUARTERLY TECHNICAL REPORT SECOND QUARTER OF 1990 FORMER TEXACO STATION 2225 TELEGRAPH AVENUE OAKLAND, CALIFORNIA

HLA Job No. 2251,125.03 September 7, 1990 1990 Report No. 2

by

Michael A. Sides Senior Engineer

Randolph Stone

Associate Hydrogeologist

NO. 1214
CERTIFIED
ENGINEERING
GEOLOGIST

OF CALIFORNIT

Harding Lawson Associates 1355 Willow Way, Suite 109 Concord, California 94520 415/687-9660

#### INTRODUCTION

This quarterly technical report (QTR) presents the results of site investigation and remediation activities conducted by Harding Lawson Associates (HLA) at a service station site formerly owned by Texaco Refining and Marketing Inc. The station, at 2225 Telegraph Avenue, Oakland, California (see Plate 1), is currently owned and operated by Exxon Company U.S.A. This QTR summarizes HLA's work at the site, ongoing since May 1988, and presents results of the recent quarter's work.

#### SITE DESCRIPTION

The site is on the southwest corner of the intersection of Telegraph and West Grand Avenues (Plate 2). The surrounding area contains commercial/retail businesses, including a Chevron service station immediately across Telegraph Avenue and a Beacon service station northeast of the site. Adjacent to the site on the south is the First Baptist Church of Oakland. There is an apartment building, currently occupied, immediately west of the site.

Surface elevation at the site is approximately 20 feet above mean sea level. The land surface slopes gently southeast, toward Lake Merritt and the Oakland/Alameda Inner Harbor, an area of tidal flats that has been filled. This area has been extensively developed, and surface runoff is mainly controlled by the municipal storm sewer system.

As shown on Plate 3, structures at the service station include a building, three fuel pump islands, one underground waste oil tank, and three underground fuel storage tanks. Leaded and unleaded gasoline are dispensed from these tanks; automotive repair services are also provided.

#### HYDROGEOLOGIC SETTING

The East Bay Plain has been divided into seven groundwater subareas, defined by the California Department of Water Resources (DWR) on the basis of areal differences (i.e., faults and other geologic conditions). This site lies within the Oakland Upland and Alluvial Plain subarea. Most groundwater used in the East Bay Plain is for irrigation or industrial, rather than domestic, purposes. The majority of domestic water is supplied by the East Bay Municipal Utility District (EBMUD) from surface sources.

The groundwater reservoir is made up of the Alameda and Temescal Formations, along with the Merritt Sand; these have an aggregate thickness of more than 1,100 feet. According to maps for the area, surface materials at the site are from the Temescal Formation, an alluvial fan deposit. Approximately 1,000 feet west of the site is an outcrop of the Merritt Sand. Direction of regional groundwater flow is west-southwest, toward San Francisco Bay.

Subsurface materials at the site, down to the maximum depth explored of 20 feet, generally consist of stiff, silty clay (CL),

underlain by a dense layer of silty sand that ranges from 3 to 8 feet in thickness. According to slug test results, the hydraulic conductivity of the shallow, saturated sand aquifer beneath the site ranges from 1.2 to 5.9 feet per day (Table 1).

Groundwater is currently encountered at approximately 13 feet below grade; well monitoring and survey data are presented in Table 2. The estimated direction of groundwater flow is to the southwest, with a gradient of 0.005 foot per foot, as shown on the Groundwater Surface Map, Plate 4.

### SUMMARY OF PREVIOUS WORK

### Previous Reports

Since May 1988, HLA has investigated soil and groundwater conditions at this site. To date, the investigation and proposed remediation plan have comprised four sequential phases; results and proposed work were presented in the following reports:

1.	Sensitive Receptor Study	May 24, 1988
2.	Subsurface Investigation	July 20, 1988
3.	Environmental Assessment	June 22, 1989
4.	Groundwater Remediation Plan	November 30, 1989

### Previous Field Operations

Boring locations are shown on Plate 3. Because of restricted subsurface access on Telegraph and West Grand Avenues, no off-site exploration was conducted north or east of the site. These restrictions were imposed by the City of Oakland and the

Bay Area Rapid Transit District (BART), whose tunnel is in this area (see Plate 2). The investigation process has included the following field operations:

- Conducted a soil-gas survey on site and in city streets near the site. Probe locations are shown on Plate 3 and soil-gas survey results are presented in Table 3
- Drilled and sampled seven shallow soil borings (B-1 through B-7); locations are shown on Plate 3
- Drilled, constructed, developed, and sampled six onsite monitoring wells (MW-6A through MW-6F) and three off-site wells (MW-6G through MW-6I); locations are shown on Plate 5
- Ordered chemical analyses on soil and water samples to determine concentrations of petroleum hydrocarbons; results of analyses are presented in Tables 4 and 5, respectively
- Conducted slug tests in MW-6D, MW-6E, and MW-6H to estimate hydraulic conductivity and transmissivity values for the shallow aquifer; slug test results are presented in Table 1.

#### SUMMARY OF PREVIOUS FINDINGS

### <u>Vadose-zone Soil Condition</u>

No significant concentrations of petroleum hydrocarbons have been found in vadose-zone soils. The fuel constituents benzene, toluene, ethylbenzene, and xylenes (BTEX) and total petroleum hydrocarbons (TPH) have been detected in concentrations exceeding 100 parts per million (ppm) exclusively in soils at 12 to 13.5 feet below the ground surface (Table 4); this depth is within the zone of fluctuation of the groundwater table.

### Groundwater Conditions

No free product has been observed in any of the monitoring wells. As shown on Plate 5, hydrocarbons dissolved in the groundwater are generally limited to the vicinity of the tanks and pump islands, extending southwest.

Water from five on-site wells near the tanks and pump islands contains detectable levels of TPH as gasoline. As of April 1990, the lateral limits of the plume are delineated by MW-6G, MW-6F, and MW-6I; samples from these wells show no detectable hydrocarbons (detection limit for TPH = <50 parts per billion [ppb]). Upgradient plume definition is incomplete because of restricted subsurface access imposed by the City of Oakland and \*\*
BART.

WORK PERFORMED DURING THE SECOND QUARTER OF 1990

HLA performed the following activities during the second quarter of 1990:

- 1. Purged and sampled all monitoring wells and chemically analyzed groundwater samples for BTEX and TPH as gasoline (see Table 5). The laboratory report is presented in the Appendix.
- Drilled and installed three recovery wells, RW-1, RW-2, and RW-3 (locations shown on Plate 3). Boring logs presented on Plates 6 through 8 and Construction Details are shown on Plates 9 through 11. RW-1 was constructed at the same location as Soil Boring B-3. Two-inch diameter Monitoring Wells MW-6D and MW-6C were drilled out and deepened to 25 feet to facilitate installation of four-inch diameter recovery wells RW-2 and RW-3.
- 3. Initiated fabrication of groundwater treatment system after reviewing and approving shop drawings.

#### **Harding Lawson Associates**

- 4. Prepared construction specifications for installation of the groundwater collection and treatment system including:
  - Health and safety requirements
  - Scope of Work
  - Earthwork
  - · Asphalt, concrete, and paving
  - Basic mechanical requirements
  - Pipes and pipe fittings
  - Basic electrical requirements.
- 5. Met with an Exxon representative on site to discuss proposed construction activities.

### LIST OF TABLES

Table	1	Slug Test Results
Table	2	Well Monitoring and Survey Data
Table	3	Results of Soil-gas Survey
Table	4	Results of Soil Chemical Analyses
Table	5	Results of Groundwater Chemical Analyses

### LIST OF ILLUSTRATIONS

Plate	1	Site Location Map
Plate	2	Vicinity Plan
Plate	3	Site Plan
Plate	4	Groundwater Surface Map
Plate	5	Distribution of Hydrocarbons in Groundwater
Plates through	6 8	Boring Logs of RW-1 through RW-3
Plates through	9 11	Well Completion Details for RW-1 through RW-3

Table 1. Slug Test Results

	Most Permeab	<u>le Stratum Adjacen</u>	t to Well Scr	een
Well <u>Number</u>	Lithology	Classification	Thickness <u>(feet)</u>	Estimated Hydraulic Conductivity (feet/day)
MW-6D	sand	confined	2	5.9
MW-6E	sand, fine-grained	confined	2.5	1.2
MW-6H	sand, medium-grained	unconfined	6	4.8

Table 2. Well Monitoring and Survey Data

Well No.	Date	Top of Casing Elevation <sup>1</sup> (feet)	Depth to Groundwater (feet)	Groundwater Surface Elevation <sup>2</sup> (feet)	Incremental Water Elevation Change <sup>3</sup> (feet)	Total Water Elevation Change Since 12/15/88* (feet)
MW-6A	12/15/88	98.99	13.77	85.22	••	
	10/03/89		13.40	85.59	-0.37	-0.37
	05/11/90		12.87	86.12	-0.53	-0.90
MW-6B	12/15/88	98.81	13.01	85.80		
	10/03/89		12.94	85.87	-0.07	-0.07
	04/30/90		12.53	86.28	-0.41	-0.48
MW-6C	12/15/88	99.89	14.41	85.48		
	10/03/89		14.10	85.79	-0.31	-0.31
	04/30/90		13.81	86.08	-0.29	-0.60
MW-6D	12/15/88	98.78	13.53·	85.25		
	10/03/89		13.44	85.34	-0.09	-0.09
	04/30/90		13.19	85.59	-0.25	-0.34
MW-6E	12/15/88	98.99	13.84	85.15		
	10/03/89		13.70	85.29	-0.14	-0.14
	04/30/90		13.43	85.56	-0.27	-0.41
MW-6F	12/15/88	99.91	14.73	85.18		
	10/03/89		14.48	85.43	-0.25	-0.25
	04/30/90		14.14	85.77	-0.34	-0.69
MW-6G	12/15/88	99.16	12.39	86.77		
	10/03/89		12.22	86.94	-0.17	-0.17
	04/30/90		11.73	87.43	-0.49	-0.66
MW-6H	12/15/88	97.93	12.39	85.54		
	10/03/89		12.36	85.57	-0.03	-0.03
	04/30/90		12.10	85.83	-0.29	-0.29
MW-6I	12/15/88	97.60	12.82	84.78		
	10/03/89		12.83	84.77	+0.01	+0.01
	04/30/90		12.66	84.94	-0.17	-0.16

#### Notes:

<sup>1</sup> Elevation relative to HLA temporary benchmark located at the western end of the dispenser island nearest West Grand Avenue, with an arbitrary elevation of 100.0 feet (see Plate 3).

<sup>2</sup> Groundwater surface elevation = top of casing elevation - depth to water.

<sup>3</sup> Incremental groundwater elevation change = groundwater elevation - previous groundwater elevation.

<sup>4</sup> Total groundwater elevation change = groundwater elevation - groundwater elevation on 12/15/88

Table 3. Results of Soil-gas Survey Conducted on September 19, 1988

### Concentrations in micrograms per liter $(\mu g/L)$

<u>Sample</u>	Depth (feet)	<u>Benzene</u>	Ethyl- <u>benzene</u>	<u>Toluene</u>	<u>Xylenes</u>	Total Petroleum <u>Hydrocarbons</u>
Air	N/A	<0.7	<0.8	<0.8	<0.8	<0.7
SG-01						<del></del>
SG-02	5.0	<0.7	<0.8	<0.8	<0.8	<0.7
SG-03	12.0	10	4	<0.8	2,800	6,100
SG-04	13.0	<0.7	<0.8	<0.8	140	780
WS-05*	12.0	<75	<76	<77	<77	<75
SG-06	13.0	<0.7	<0.8	<0.8	<0.8	<0.7
SG-07						
Air	N/A	<0.7	<0.8	<0.8	<0.8	<0.7

- Not able to obtain sample

N/A - Not applicable Air - Ambient air sample

\* - WS-05 was a sample of groundwater

Table 4. Results of Soil Chemical Analyses Concentrations in milligrams per kilogram (mg/kg)

Sample <u>Number</u>	Depth (feet)	1 <u>Benzene</u>	Ethyl- 2 benzene	3 <u>Toluene</u>	3 Xylenes	TPH as <sub>4</sub> Gasoline
B-1	8.0	0.05	ND	ND	ND	ND
B-1	13.0	ND (5)	10 (10)	16 (10)	41 (10)	2,000 (1,000)
B-2	7.0	ND	ND	ND	ND	ND
B-2	13.5	ND	ND	ND	ND	ND
B-3	7.0	0.06	ND	ND	ND	ND
B-3	13.5	40 (25)	84 (50)	390 (50)	370 (50)	11,000 (5,000)
B-4	13.5	ND	ND	ND	ND	ND
B-5	5.5	ND	ND	ND	ND	ND
B-5	9.5	ND	ND	ND	ND	ND
B-5	12.5	ND	ND	ND	ND	ND
B-6	6.0	ND	ND	ND	ND	ND
в-6	9.5	ND	ND	ND	ND	ND
B-6	12.0	40 (5)	40 (20)	110 (10)	450 (10)	3,000 (1,000)
B-7	6.0	0.64	0.4	0.9	3.4	24
B-7	9.5	0.5	ND	0.7	1.0	ND
B-7	12.0	20 (5)	20 (20)	72 (10)	190 (10)	1,400 (1,000)
MW-6E	13.0	ND	ND	ND	ND	ND
MW-6F	13.0	ND	ND	ND	ND	ND
MW-6G	13.5	ND	ND	ND	ND	5.2
MW-6H	13.5	11 (0.5)	8.8 (2)	3.2 (1)	19 (1)	1,000 (495)
MW-6I	13.5	ND	ND	ND	ND	ND

ND = Not detected.

Detection limit 0.05 mg/kg except as noted in parentheses.

Detection limit 0.2 mg/kg except as noted in parentheses.

<sup>3</sup> Detection limit 0.1 mg/kg except as noted in parentheses.

<sup>4</sup> Detection limit 10 mg/kg except as noted in parentheses.

Table 5. Results of Groundwater Chemical Analyses
Concentrations in micrograms per liter (µg/L)

### EPA TEST METHOD 602

Well <u>Number</u>	Date Sampled	1 	Ethylbenzene <sup>2</sup>	<u>Toluene</u> 3	3 Xylenes	TPH <sup>4</sup> (as gasoline)
MW-6A	06/24/88	ND	ND	ND	ND	-
	10/20/88	1	ND	ND	ND	
	09/07/89	2	ND	ND	ND	ND
	05/11/90	150	ND (0.25)	6.2	13	ND (500)
MW-6B	06/24/88	ND	ND	ND	5	-
	10/20/88	4	ND	3	ND	-
	09/07/89	70 (2.5)	60 (3)	8 (3)	160 (4)	2,700 (25)
	04/30/90	45 (5)	20 (5)	6 (5)	22 (5)	168 (50)
MW-6C	06/24/88	7,480	170	7	2,300	-
	10/20/88	<b>9,50</b> 0 (50)	170 (2)	65 (100)	850 (1)	-
	09/07/89	<b>7,90</b> 0 (25)	350 (25)	430 (25)	1,100 (38)	<b>18,000</b> (2,500)
	04/30/90	<b>6,100</b> (250)	1,000 (250)	1,500 (250)	2,700 (250)	<b>30,880</b> (25,000)
MW-6D	07/11/88	220 (5)	ND (20)	27 (10)	ND (10)	-
	10/20/88	710 (5)	22 (20)	74 (10)	110 (10)	-
	09/07/89	600 (12.5)	58 (13)	26 (13)	31 (19)	2,200 (1,250)
	04/30/90	<b>800 (</b> 50)	310 (50)	150 (50)	280 (50)	<b>3,600</b> (500)
MW-6E	10/20/88	1	ND	ND	3	
	09/07/89	3	ND	ND	ND	220
	04/30/90	57 (5)	ND (5)	ND (5)	53 (5)	250 (50)
MW-6F	10/25/88	ND	ND	ND	2	
	09/07/89	ND	ND	ND	ND	ND
	04/30/90	ND	ND	ND	ND	ND
MW-6G	12/07/88	ND	ND	ND	ND	-
	09/07/89	ND	DM	ND	ND	ND
	04/30/90	ND	ND	ND	ND	ND
MW-6H	12/07/88	1,200 (25)	110 (20)	320 (10)	220 (10)	-
	09/07/89	480 (10)	16 (10)	ND (10)	ND (15)	<b>660</b> (500)
	04/30/90	<b>700 (</b> 50)	31 (5)	39 (5)	50 (5)	<b>630 (</b> 500)
MW-61	12/07/88	ND	ND	ND	ND	-
	09/07/89	ND	ND	ND	ND	ND
	04/30/90	ND	ND	ND	ND	ND

ND = Not detected.

Detection limits given in parentheses, where applicable. If not:


<sup>1.</sup> Detection limit = 0.5.

<sup>2.</sup> Detection limit = 2

Detection limit = 1

<sup>4.</sup> Detection limit = 50







**Harding Lawson Associates** 

Engineers and Geoscientists

Site Location Map Former Texaco Service Station 2225 Telegraph Avenue Oakland, California PLATE

YC


JOB NUMBER 2251,111.03

APPROVED


DATE 2/89


REVISED


DATE




J












Engineers and Geoscientists

Log of Boring B-3 (Median 19 RM-1) Former Texaco Service Station 2225 Telegraph Avenue

Oakland, California

DRAWN JOB NUMBER APPROVED REVISED DATE ΥC 2251,123.03 12/88 6/90





**Harding Lawson Associates** 

Engineers, Geologists & Geophysicists


Log of Boring MW-6D (Modified to RW-2) Texaco Station - 62488000195

2225 Telegraph Avenue

Oakland, California

DATE

DRAWN JOB NUMBER REVISED RS 2251,123.03 2/89 6/90





**Harding Lawson Associates** 


Engineers, Geologists & Geophysicists

Log of Boring MW-6C (Modified to RW-3)

Texaco Station - 62488000195 2225 Telegraph Avenue

Oakland, California

DRAWN JOB NUMBER REVISED APPROVED DATE RS 2251,123.03 2/89 6/90




Harding Lawson Associates Engineers and Geoscientists Recovery Well Completion Detail RW-1
Former Texaco Service Station

2225 Telegraph Avenue
Oakland, California

9

YC 2251,123.03 PROVED DATE REVISEO DATE

NOT TO SCALE



Harding Lawson Associates Engineers and Geoscientists Recovery Well Completion Detail RW-2
Former Texaco Service Station


2225 Telegraph Avenue Oakland, California 10

PLATE

YC 2251,123.03 DATE REVISED DATE

YC 2251,123.03

NOT TO SCALE



Engineers and Geoscientists

Former Texaco Service Station 2225 Telegraph Avenue

Oakland, California DATE REVISED NWARG JOB NUMBER 6/90 2251,123.03 YC

APPENDIX
LABORATORY ANALYSES REPORT



May 15, 1990

Harding Lawson Associates 1355 Willow Way, Suite 109 Concord, CA 94520

Attention: Mr. Randy Stone

Subject: Report of Data - Case Number 5919

Dear Mr. Stone:

The technical staff at CHEMWEST is pleased to provide our report for the analyses you requested: Total Petroleum Hydrocarbons, purgeable (gasoline) - DHS Method, LUFT Field Manual; and BTEX - EPA Method 8020.

Eight water samples for Project Texaco #6, Project Number 2251.111.03 were received May 1, 1990 in good condition. Results of the analyses, along with the analytical methodology and appropriate reporting limits, are presented on the following pages.

Thank you for choosing CHEMWEST Laboratories. Should you have questions concerning this data report or the analytical methods employed, please do not hesitate to contact Debbie Pearce your Customer/Technical Service Representative. We hope that you will consider CHEMWEST Laboratories for your future analytical support and service requirements.

Sincerely,

Robert T. Hart

Data Control Manager

RTH:ba

cc: File

#### ANALYTICAL METHODOLOGY

BTEX (Benzene, Toluene, Ethyl Benzene, and Xylenes) by Purge & Trap and GC-PID

WATER - Method 602 or 8020

A 5 ml sample volume, or 5 ml of a suitable dilution, is purged on a suitable purge and trap system with helium. The purged sample is analyzed on a Gas Chromatograph equipped with a Photoionization Detector (PID). A packed column is used to separate the compounds.

SOIL - Method 8020

A 10 gram, or other appropriate aliquot of soil, is weighed into a clean VOA vial. Soils received in brass core tubes are sampled by discarding 2-5 centimeters of soil from each end of the tubes (this is done to reduce the possibility of analyzing a portion of soil that has been exposed to sampling technique contamination). Equal aliquots of soil are then removed from each end of the tube and combined in the VOA vial. Soil in jars or bags is aliquoted using a similar technique, which discards exposed sample surfaces. A 10 ml, or other appropriate volume of methanol, is added to the soil and the soil is shaken with the solvent. 100 ul of the extract, or a reduced aliquot or volume of a suitable dilution, is injected into 5 ml of laboratory blank water and analyzed by the same technique used for water samples.

#### ANALYTICAL METHODOLOGY

Total Petroleum Hydrocarbons by Purge & Trap and GC-FID

WATER - DHS Method - Luft Field Manual

A 5 ml sample volume, or 5 ml of a suitable dilution, is purged on a suitable purge and trap system with helium. The purged sample is analyzed on a Gas Chromatograph equipped with a Flame Ionization Detector (FID). A packed column is used to separate the compounds.

SOIL - DHS Method - Luft Field Manual

A 10 gram, or other appropriate aliquot of soil, is weighed into a clean VOA vial. Soils received in brass core tubes are sampled by discarding 2-5 centimeters of soil from each end of the tubes (this is done to reduce the possibility of analyzing a portion of soil that has been exposed to sampling technique contamination). Equal aliquots of soil are then removed from each end of the tube and combined in the VOA vial. Soil in jars or bags is aliquoted using a similar technique, which discards exposed sample surfaces. A 10 ml, or other appropriate volume of methanol, is added to the soil and the soil is shaken with the solvent. 100 ul of the extract, or a reduced aliquot or volume of a suitable dilution, is injected into 5 ml of laboratory blank water and analyzed by the same technique used for water samples.

Client I.D.: Method Blank
Date Analyzed: 05/12/90

CHEMWEST I.D.: 5919-MB
Matrix
Water

Compound	Amount Detected (ug/L)	RL (ug/L)
Benzene	BRL	Ø.5
Toluene	BRL	Ø.5
Ethyl Benzene	BRL	Ø <b>.</b> 5 .
Para-Xylene	BRL	Ø <b>.</b> 5
Meta-Xylene	BRL	Ø <b>.</b> 5
Ortho-Xylene	BRL	Ø <b>.</b> 5
Total-Xylenes (1)	BRL	NA
Total Petroleum Hydrocarbor (Purgeable)	n BRL	50

Surrogate	% Recovery	Acceptance Window
Bromofluorobenzene	64%	50-150%

BRL: Below Reporting Limit.

RL: Reporting Limit.

(1): Total of P-, M-, and O- Xylenes.

Approved by: \_\_\_\_\_\_\_\_\_\_

Client I.D.: MW-6B CHEMWEST I.D.: 5919-1 Date Analyzed: 05/12/90 Matrix : Water

Compound	Amount Detected (ug/L)	RL (ug/L)
Benzene	45	5.0
Toluene	6.0	5.0
Ethyl Benzene	20	5.0
Para-Xylene	9.4	5.0
Meta-Xylene	5.3	5.0
Ortho-Xylene	7.2	5.0
Total-Xylenes (1)	22	NA
Total Petroleum Hydrocarbon	<del>150-</del> 2168	<u>599050</u>
(Purgeable)	•	Revised 6/28/90 MAS

Surrogate	% Recovery	Acceptance Window
Bromofluorobenzene	71%	50-150%

BRL: Below Reporting Limit.

RL: Reporting Limit.

(1): Total of P-, M-, and O- Xylenes.

Client I.D.: MW-6C CHEMWE Date Analyzed: 05/12/90 Matrix

CHEMWEST I.D.: 5919-2
Matrix : Water

Compound	Amount Detected (ug/L)	RL (ug/L)
Benzene	. 6100	250
Toluene	1500	250
Ethyl Benzene	1000	250
Para-Xylene	76Ø	250
Meta-Xylene	1000	250
Ortho-Xylene	960	250
Total-Xylenes (1)	2700	NA
Total Petroleum Hydroc (Purgeable)	arbon 30000	25000

Surrogate	% Recovery	Acceptance Window
Bromofluorobenzene	69%	50-150%

BRL: Below Reporting Limit.

RL: Reporting Limit.

(1): Total of P-, M-, and O- Xylenes.

Client I.D.: MW-6D Date Analyzed: 05/12/90 CHEMWEST I.D.: 5919-3
Matrix : Water

Amount etected (ug/L)	RL (ug/L)
800	5Ø
15Ø	50
310	50
140	50
73	50
67	50
28Ø	NA
3600	500
	etected (ug/L) 

Surrogate	% Recovery	Acceptance Window
Bromofluorobenzene	74%	50-150%

BRL: Below Reporting Limit.

RL: Reporting Limit.

(1): Total of P-, M-, and O- Xylenes.

Approved by:

Client I.D.: MW-6E
Date Analyzed: 05/12/90

CHEMWEST I.D.: 5919-4
Matrix : Water

Compound	Amount Detected (ug/L)	RL (ug/L)
Benzene	57	5.0
Toluene	BRL	5.Ø
Ethyl Benzene	BRL	5.0
Para-Xylene	BRL	5.0
Meta-Xylene	53	5.0
Ortho-Xylene	BRL	5.0
Total-Xylenes (1)	53-	NA
Total Petroleum Hydrocarbon	BRL 9 250	<del>588</del> 25
(Purgeable)	Kerisad	6/28/90 MKS

Surrogate	% Recovery	Acceptance Window
Bromofluorobenzene	8 4 %	50-150%

BRL: Below Reporting Limit.

RL: Reporting Limit.

(1): Total of P-, M-, and O-Xylenes.

Client I.D.: MW-6F CHEMWEST I.D.: 5919-5
Date Analyzed: 05/12/90 Matrix : Water

Compound	Amount Detected (ug/L)	RL (ug/L)
Benzene	BRL	Ø.5
Toluene	BRL	Ø <b>.</b> 5
Ethyl Benzene	BRL	Ø.5
Para-Xylene	BRL	0.5
Meta-Xylene	BRL	Ø.5
Ortho-Xylene	BRL	g.5
Total-Xylenes (1)	BRL	NA
Total Petroleum Hydrocarbon (Purgeable)	BRL	50

Surrogate	% Recovery	Acceptance Window
Bromofluorobenzene	73%	50-150%

BRL: Below Reporting Limit.

RL: Reporting Limit.

(1): Total of P-, M-, and O- Xylenes.

Approved by:

Client I.D.: MW-6G Date Analyzed: Ø5/12/9Ø CHEMWEST I.D.: 5919-6
Matrix : Water

Compound	Amount Detected (ug/L)	RL (ug/L)
Benzene .	BRL	Ø.5
Toluene	BRL	Ø <b>.</b> 5
Ethyl Benzene	BRL	Ø.5
Para-Xylene	BRL	Ø.5
Meta-Xylene	BRL	Ø.5
Ortho-Xylene	BRL	Ø.5
Total-Xylenes (1)	BRL	NA
Total Petroleum Hydrocarbor (Purgeable)	n BRL	50

Surrogate	% Recovery	Acceptance Window
Bromofluorobenzene	68%	50-150%
Bromofluorobenzene		50-150%

BRL: Below Reporting Limit.

RL: Reporting Limit.

(1): Total of P-, M-, and O- Xylenes.

Client I.D.: MW-6H Date Analyzed: 05/12/90

CHEMWEST I.D.: 5919-7

Matrix : Water

Compound	Amount Detected (ug/L)	RL (ug/L)
Benzene	. 700	5ø
Toluene	39	5.0
Ethyl Benzene	31	5.Ø
Para-Xylene	18	5.0
Meta-Xylene	16	5.0
Ortho-Xylene	16	5.0
Total-Xylenes (1)	50	NA
Total Petroleum Hydroc (Purgeable)	earbon 630	500

Surrogate	% Recovery	Acceptance Window
Bromofluorobenzene	71%	50-150%

BRL: Below Reporting Limit.

RL: Reporting Limit.

(1): Total of P-, M-, and O- Xylenes.

Client I.D.: MW-6I CHEMWEST I.D.: 5919-8
Date Analyzed: 05/12/90 Matrix : Water

Compound	Amount Detected (ug/L)	RL (ug/L)
Benzene	BRL	Ø.5
Toluene	BRL	Ø.5
Ethyl Benzene	BRL	Ø <b>.</b> 5
Para-Xylene	BRL	Ø.5
Meta-Xylene	BRL	Ø.5
Ortho-Xylene	BRL	Ø.5
Total-Xylenes (1)	BRL	NA
Total Petroleum Hydrocarbon (Purgeable)	n BRL	50

Surrogate	% Recovery	Acceptance Window
Bromofluorobenzene	55%	50-150%

BRL: Below Reporting Limit.

RL: Reporting Limit.

(1): Total of P-, M-, and O- Xylenes.

Approved by: \_\_\_\_\_

CHEMWEST AN 600W North Market Sacramento, Californ (916) 923-0840 FA	Blvd. nia 95834	BORATORIE	SINC	Order No. Date Rec' Compl. Da Section	05919 1.5/1/90 17:45 te
40m/ No		Way x 94520 er semp	Property Pro	ject No. <u>225</u> NO	des Roaly Stor
5919-1 MI -2 MI -3 M -4 MI -5 M -6 M -7 M	W-6D W-6E	DATE A/30/90	BTEXIS	MATER	CONTAINERS 2-40mlyon via
GC Bn)s ELLUMGBENCE		El : hi	DE YAM SS		CHEM WEST COURIER

Harding Lawson Associates

1355 Willow Way, Suite 109 Concord, California 94520 415/687-9660 Telecopy: 415/687-9673

### **CHAIN OF CUSTODY FORM**

Lab: Chem West

	Telecopy: 415/			_	Samplers:	an Johnson Brand	ANALYSIS REQUESTED
Job	Number:_	225%	111	7,03	mike	Brand	
Nam	e/Locatio	n: Tex	ac	U TEG			
Proj	e/Location	ger: Mi	he	Silles	Recorder: <u>Æ</u>	Jan John Landon nazure Required)	
	MATRIX	#CONTAIN. & PRESER	ERS IV.	SAMPLE NUMBER		1.	
SOURCE CODE	Water Sediment Soil	Unpres. H <sub>2</sub> SO <sub>4</sub> HNO <sub>3</sub>		OR LAB NUMBER	DATE	STATION DESCRIPTION/ NOTES	EPA 601/8010 EPA 602/8020 EPA 624/8240 EPA 625/8270 ICP METALS EPA 8015M/TPH
ន្ទ	Oii Se	2 포로		Yr Wk Seq	Yr Mo Dy Time		
'、'3	11111	1113		MW-6 B	909090		
12.3	1111		11	1/7/14	700430		
1-(-)			- - -	$  \mathbf{I} \mathbf{I} \mathbf{I} \mathbf{I} \mathbf{P} \mathbf{I} $			
╏╌╢╌┨	+1++		44	$\mathcal{E}$			
<b>′</b>  _{_{_}	+11+1	1119					
╏╌┼┼╏	14-1-1-			11116			
<b>' -/</b> -	-11		11	11414			
141	<del>-11-1-1-</del>		+1				
<u> </u>				<del>                                     </del>			
للا							
		<del>,</del>					
	LAB	DEPTH C	COL	QA			

	 LA NUM				EP1	-	MI	Œ	_	QA ODE		MISCELLANEOUS	CHAIN OF CUSTODY RECORD	
ı	Wk	Se	q	'	FEE	•	C	"						
				П		T	$\Box$			Τ	П		RECINQUISHED BY: (Signature) RECIVED BY: (SignatuGARY BLASE DATE/TIME	
				П	7	$\top$	П		$\top$	1	П		Dan Junson Dary Brase 5-1-90 10:15	
ı				17	十	1	Ħ	-	┰	+	1-		RECEIVED BY: (Signature) RECEIVED BY: (Signature) DATE/TIME	
	 +	- -		H	+	┿	╂┤		╁	╂━	-		17:45 Sam Brase GARY BIASE 5-1-90 17:45	
	 	_   _		╀	4	4	Ш	_1	1	1	Ш		RELINQUISHED BY: (Signature) RECEIVED BY: (Signature) DATE/TIME	
١.			<u> </u>											
				П		T	П			1			RELINQUISHED BY: (Signature) RECEIVED BY: (Signature) DATE/TIME	
				П	T	T				1				
				П	T	T	П		T	1			D (SPATCHED BY: (Signature) DATE/TIME RECEIVED FOR LAB BY: DATE/TIME	
				П	7	T	$\sqcap$		1	1	П		Dill MEBENGE 9/917:45	
					丁				1				METHOD OF SHIPMENT CHEM WEST COURIER	
									ł	Labc	rato	ory Copy Project Office Copy Field or (	Office Copy 6533	



June 28, 1990

Harding Lawson Associates 1355 Willow Way, Suite 109 Concord, CA 94520

Attention: Mr. Randy Stone

Subject: Report of Amended Data - Case Number 5919

Dear Mr. Stone

Enclosed you will find amended data sheets for the re-analysis of the Total Petroleum Hydrocarbon (Purgeable) Analysis for sample numbers MW-6B & MW-6E (CW5919-1 & 4).

Project Number: 2251.111.03

The enclosed data sheets reflect the correct results for the above samples.

I hope that this has not caused you any inconvenience, should you have any further questions please do not hesitate to give Debbie Pearce, your Customer/Technical Service Representative, a call.

Sincerely,

Robert Hart

cc: File

### CHEMWEST ANALYTICAL LABORATORIES TOTAL PETROLEUM HYDROCARBONS

Client I.D.: Method Blank Date Analyzed: 05/22/90

CHEMWEST I.D.: 5919-MB

Matrix : Water

Amount

Detected (ug/L) Compound

RL(ug/L)

Total Petroleum Hydrocarbon BRL (Purgeable)

Surrogate Recovery Window

Acceptance

Bromofluorobenzene 11g% Bromofluorobenzene

BRL: Below Reporting Limit.

RL: Reporting Limit.

(1): Total of P-, M-, and O- Xylenes.

Approved by: Hy

### CHEMWEST ANALYTICAL LABORATORIES TOTAL PETROLEUM HYDROCARBONS

Client I.D.: MW-6B Date Analyzed: 05/22/90

CHEMWEST I.D.: 5919-1

Matrix : Water

	Amount Detected	RL
Compound	(ug/L)	(ug/L)
Total Petroleum Hydrocarbo (Purgeable)	n 168	50

Surrogate	% Recovery	Acceptance Window
Bromofluorobenzene	129%	50-150%
<del></del>		

BRL: Below Reporting Limit.

RL: Reporting Limit.

(1): Total of P-, M-, and O- Xylenes.

### CHEMWEST ANALYTICAL LABORATORIES TOTAL PETROLEUM HYDROCARBONS

Client I.D.: MW-6E Date Analyzed: Ø5/22/9Ø

CHEMWEST I.D.: 5919-4

Matrix : Water

Compound	Amount Detected (ug/L)	RL (ug/L)
Total Petroleum Hydrocarbon (Purgeable)	n 250	50

Surrogate	% Recovery	Acceptance Window
Bromofluorobenzene	97%	50-150%

BRL: Below Reporting Limit.

RL: Reporting Limit.

(1): Total of P-, M-, and O- Xylenes.

JUL 9 1990



July 14, 1990

Harding Lawson Associates 1355 Willow Way, Suite 109 Concord, CA 94520

Attention: Mr. Mike Sides

Subject: Report of Amended Data - Case Number 5997

Dear Mr. Sides

Enclosed you will find amended data sheets for the Total Petroleum Hydrocarbons (Purgeable) Analysis of sample number MW-6A (CW5997-1).

Project Number: 2251,123.03

The enclosed data sheets now reflect the amount detected in the Total Petroleum Hydrocarbons (Purgeable) analysis per your request.

I hope that this has not caused you any inconvenience, should you have any further questions please do not hesitate to give Debbie Pearce, your Customer/Technical Service Representative, a call.

Sincereb

Robert Hart

Production Manager

cc: File

Client I.D.: MW-6A

Date(s) Analyzed: Ø5/18/90

CHEMWEST I.D.: 5997-1

Matrix: Water

Compound	Amount Detected (ug/L)	RL (ug/L)
Benzene	150	5 .
Toluene	6.2	2.5
Ethyl Benzene	BRL	2.5
p-Xylene	6.5	2.5
m-Xylene	6.5	2.5
o-Xylene	BRL	2.5
Total-Xylenes (1)	13	NA
Total Petroleum Hydrocarbon (Purgeable)	100	50

Surrogate	% Recovery	Acceptance Window
Bromofluorobenzene	92%	50-150%

BRL: Below Reporting Limit.

RL: Reporting Limit.

(1): Total of P-, M-, and O- Xylenes.

Approved by: \( \frac{\mathcal{H}}{2} \)

#### DISTRIBUTION

3 copies: Texaco Refining and Marketing Inc.

10 Universal City Plaza

Universal City, California 91608 Attention: Mr. R. W. Conlon

1 copy: Texaco Refining and Marketing Inc.

100 Cutting Boulevard

Richmond, California 94804 Attention: Mr. R. R. Zielinski

MAS/RS/mlw 031714L/R38

QUALITY CONTROL REVIEWER

Stephen J. Osborne Principal Engineer