

ENDINE ASENTAL PROTECTION

99 DEC -7 PM 3: 20

P.O. BOX 4032 ● CONCORD, CA 94524-4032 MARKETING DEPARTMENT ● ENVIRONMENTAL ENGINEERING

DARIN L. ROUSE SENIOR ENGINEER

(925) 246-8768 (925) 246-8798 FAX

December 7, 1999

Mr. Scott Seery Alameda County Health Care Services Agency Department of Environmental Health 1131 Harbor Bay Parkway, Room 250 Alameda, California 94502-6577

RE: Exxon RAS #7-0235/2225 Telegraph Avenue, Oakland, California.

Dear Mr. Seery:

Attached for your review and comment is a letter report entitled *Quarterly Groundwater Monitoring Report, Fourth Quarter 1999*, dated November 30, 1999, for the above referenced site. The report was prepared by Environmental Resolutions, Inc. (ERI) of Novato, California, and details the results of the quarterly groundwater monitoring and sampling activities at the subject site.

If you have any questions or comments, please contact me at (925) 246-8768.

Sincerely,

Darin L. Rouse Senior Engineer

Attachment

ERI's Quarterly Groundwater Monitoring Report, Fourth Quarter 1999, dated

November 30, 1999.

cc:

w/ attachment

Mr. Stephen Hill - California Regional Water Quality Control Board-San Francisco Bay Region

w/o attachment

Mr. James F. Chappell - Environmental Resolutions, Inc.

Ms. Kathy Simonelli - Geologic Services Corporation





### ENVIRONMENTAL RESOLUTIONS, INC.

November 30, 1999 ERI 222913.R08

Mr. Darin L. Rouse Exxon Company, U.S.A. P.O. Box 4032 Concord, California 94524-4032

Subject:

Quarterly Groundwater Monitoring Report, Fourth Quarter 1999, Exxon Service Station

7-0235, 2225 Telegraph Avenue, Oakland, California.

Mr. Rouse:

At the request of Exxon Company, U.S.A. (Exxon), Environmental Resolutions, Inc. (ERI) is reporting the results of the fourth quarter 1999 groundwater monitoring and sampling event. The location of the site is shown on the Site Vicinity Map (Plate 1). The purpose of quarterly monitoring is to evaluate concentrations of dissolved hydrocarbons in groundwater and groundwater flow direction and gradient. Blaine Tech Services, Inc. (Blaine Tech) performed the site field activities at the request of Exxon.

### GROUNDWATER MONITORING AND SAMPLING

On October 25, 1999, Blaine Tech measured depth to water (DTW) and collected groundwater samples from select wells for laboratory analyses. Work was performed in accordance with Blaine Tech's groundwater sampling protocol provided in Attachment A. Field data sheets are presented in Attachment B.

Calculated groundwater gradient and flow direction are presented on Plate 2. Historical and recent monitoring data are summarized in Table 1.

### LABORATORY ANALYSES AND RESULTS

Groundwater samples were submitted to Southern Petroleum Laboratories, Inc. (SPL), a California state-certified laboratory, under Chain of Custody protocol. The samples were analyzed for benzene, toluene, ethylbenzene, and total xylenes (BTEX), methyl tertiary butyl ether (MTBE), and total purgeable petroleum hydrocarbons as gasoline (TPPHg) using the methods listed in the notes in Table 1. The laboratory analysis report and Chain of Custody record are provided in Attachment C. Cumulative results of laboratory analyses of groundwater samples are summarized in Table 1. The results of analyses of groundwater samples collected during the recent sampling event are shown on Plate 2.

CANEER

### LIMITATIONS

This report was prepared in accordance with generally accepted standards of environmental practice in California at the time this investigation was performed. This report has been prepared for Exxon Company, U.S.A., and any reliance on this report by third parties shall be at such party's sole risk.

ERI recommends forwarding copies of this report to:

Mr. Scott Seery Alameda County Health Care Services Agency Department of Environmental Health 1131 Harbor Bay Parkway, Room 250 Alameda, California 94502-6577

Mr. Stephen Hill California Regional Water Quality Control Board San Francisco Bay Region 1515 Clay Street, Suite 1400 Oakland, California 94612

If you have any questions or comments regarding this report, please call Mr. James F. Chappell at (415) 382-4323.

Sincerely,

Environmental Resolutions, Inc.

James F. Chappell Senior Staff Scientist

Mark S/Docklim

R.G. C.E.G. 1675

Attachments:

Table 1:

Cumulative Groundwater Monitoring and Sampling Data

Plate 1:

Site Vicinity Map

Plate 2:

Generalized Site Plan

Attachment A: Groundwater Sampling Protocol

Attachment B: Field Data Sheets

Attachment C: Laboratory Analysis Report and Chain of Custody Record

## TABLE 1 CUMULATIVE GROUNDWATER MONITORING AND SAMPLING DATA

Exxon Service Station 7-0235 2225 Telegraph Avenue Oakland, California (Page 1 of 4)

Well ID#	Sampling	SUBJ	DTW	Elev.	ТРРН	MTBE	В	r	E	Х
(TOC)	Date	<	feet							
MW6B	11/26/96	NLPH	12.26	5.22	< 50	< 30	< 0.5	<0.5	< 0.5	< 0.5
(17.48)	2/27/97	NLPH	11.73	5.75	< 50	< 30	< 0.5	< 0.5	< 0.5	0.80
	5/21/97	NLPH	12.70	4.78	< 50	< 30	< 0.5	< 0.5	< 0.5	< 0.5
	8/18/97	NLPH	12.89	4.59	380	< 30	4.3	< 0.5	1.2	1.5
	3/13/98	NLPH	11.15	6.33	360	< 6.2	93	4.9	4.1	12
	4/20/98	NLPH	11.49	5.99	110	5.5	19	1.3	1.5	3.9
(21.37)	7/21/98	NLPH	12.18	9.19	< 50	8.7	0.84	0.59	< 0.5	< 0.5
	10/6/98	NLPH	12.70	8.67	190	6.0	2.4	0.56	0.51	1.2
	1/11/99	NLPH	12.48	8.89	50	3.9	1.2	< 0.5	< 0.5	0.95
	4/8/99	NLPH	11.52	9.85	85	14.0	4.4	< 0.5	< 0.5	< 0.5
	7/19/99	NLPH	11.39	9.98	< 50	< 2.50	< 0.5	< 0.5	< 0.5	< 0.5
	7/27/99	NLPH	12.71	8.66						
	10/25/99	NLPH	12.49	8.88	260	<2	2.3	< 0.5	< 0.5	< 0.5
MW6E	11/26/96	NLPH	12.94	4.69	< 50	< 30	1.1	< 0.5	< 0.5	< 0.5
(17.63)	2/27/97	NLPH	12.28	5.35	< 50	< 30	< 0.5	< 0.5	< 0.5	< 0.5
	5/21/97	NLPH	13.60	4.03	160	< 5	10	1.4	5.5	4.8
	8/18/97	NLPH	13.75	3.88	66	< 30	< 0.5	< 0.5	< 0.5	< 0.5
	3/13/98	NLPH	11.36	6.27	< 50	< 2.5	< 0.5	< 0.5	< 0.5	< 0.5
	4/20/98	NLPH	11.88	5.75	< 50	<2.5	< 0.5	< 0.5	< 0.5	< 0.5
(21.58)	7/21/98	NLPH	13.10	8.48	1,200	< 10	81	3.1	28	77
,	10/6/98	NLPH	13.55	8.03	< 50	6.6	1.4	0.51	< 0.5	0.97
	1/11/99	NLPH	13.40	8.18	< 50	5.1	< 0.5	< 0.5	< 0.5	< 0.5
	4/8/99	NLPH	12.04	9.54	< 50	4.7	< 0.5	< 0.5	< 0.5	< 0.5
	7/19/99	NLPH	11.59	9.99						
	7/27/99	NLPH	13.65	7.93						
	10/25/99	NLPH	13.52	8.06	< 50	2.5	< 0.5	< 0.5	< 0.5	< 0.5
MW6F	11/26/96	NLPH	13.29	5.29	< 50	<30	< 0.5	< 0.5	< 0.5	< 0.5
(18.58)	2/27/97									
` ,	5/21/97	NLPH	14.18	4.40						
	8/18/97	NLPH	14.69	3.89						
	3/13/98	NLPH	10.93	7.65	< 50	< 2.5	< 0.5	< 0.5	< 0.5	< 0.5
	4/20/98	NLPH	11.77	6.81						
(22.51)	7/21/98	NLPH	13.62	8.89						
· ·- · /	10/6/98	NLPH	13.52	8.99						

# TABLE 1 CUMULATIVE GROUNDWATER MONITORING AND SAMPLING DATA

Exxon Service Station 7-0235 2225 Telegraph Avenue Oakland, California (Page 2 of 4)

Well ID#	Sampling	SUBJ	DTW	Elev.	TPPHg	MTRE	В	T	E	X
(TOC)	Date	< ,	feet		<		ug/L			
MW6F (cont.)	1/11/99	NLPH	14.06	8.45						
(22.51)	4/8/99	NLPH	11.86	10.65						
	7/19/99									
	7/27/99	Well Inaccess	ible							
	10/25/99	NLPH	12.63	9.88		***				
MW6G	11/26/96	NLPH	11.12	5.70	<50	< 30	< 0.5	< 0.5	< 0.5	<0.5
(16.82)	2/27/97									
	5/21/97	NLPH	11.76	5.06				*		
	8/18/97	NLPH	12.23	4.59						
	3/13/98	NLPH	9.13	7.69	< 50	4.4	< 0.5	< 0.5	< 0.5	<0.:
	4/20/98	NLPH	9.73	7.09						
(20.72)	7/21/98	NLPH	11.15	9.57						
	10/6/98	NLPH	11.91	8.81						
	1/11/99	NLPH	12.00	8.72						
	4/8/99	NLPH	10.04	10.68						•••
	7/19/99									
	7/27/99	NLPH	11.75	8.97						
	10/25/99	NLPH	11.76	8.96			•••			
ммен	11/26/96	NLPH	11.87	4.71	1,200	< 30	320	110	22	85
(16.58)	2/27/97	NLPH	11.58	5.00	1,800	< 200	760	31	8.4	44
	5/21/97	NLPH	12.23	4.35	1,100	81	640	18	5.4	45
	8/18/97	NLPH	12.29	4.29	870	26	200	3.6	2.4	7.4
	3/13/98	NLPH	11.44	5.14	5,300	< 125	1,900	720	100	470
	4/20/98	NLPH	11.58	5.00	6,000	2,700	1,500	600	91	440
(20.47)	7/21/98	NLPH	11.97	8.5	2,200	1,600	740	44	15	63
	10/6/98	NLPH	12.23	8.24	5,400	3,000	1,900	<25	< 25	76
	1/11/99	NLPH	12.17	8.30	2,600	4,300	1,200	< 12	< 12	20
	4/8/99	NLPH	11.56	8.91	13,000	13,000	3,400	1,300	260	1,20
	7/19/99	NLPH	11.71	8.76	< 2,000	6,920/8,520*	732	< 20	< 20	< 20
	7/27/99	NLPH	12.39	8.08						
	10/25/99	NLPH	12.16	8.31	700	4,000	360	1.1	0.68	2
MW6I	11/26/96	NLPH	12.45	3.81	< 50	<30	< 0.5	< 0.5	< 0.5	<0
(16.26)	2/27/97	NLPH	12.24	4.02	< 50	< 30	< 0.5	< 0.5	< 0.5	<0.
-	5/21/97	NLPH	12.82	3.44	< 50	<30	< 0.5	< 0.5	< 0.5	<0

TABLE 1
CUMULATIVE GROUNDWATER MONITORING AND SAMPLING DATA

Exxon Service Station 7-0235 2225 Telegraph Avenue Oakland, California (Page 3 of 4)

Well ID#	Sampling	SUBJ	DTW	Elev.	TPPHg	MTBE	В	T	3	X
(TOC)	Date	<	feet	>	<		ug/L	• • • • • • • • • • • • • • • • • • • •		
MW6I (cont.)	8/18/97	NLPH	12.81	3.45	< 50	< 30	< 0.5	< 0.5	< 0.5	< 0.5
(16.26)	3/13/98									***
	4/20/98	NLPH	12.14	4.12	< 50	< 2.5	< 0.5	< 0.5	< 0.5	< 0.5
(20.24)	7/21/98	NLPH	12.59	7.65	< 50	< 2.5	< 0.5	< 0.5	< 0.5	< 0.5
	10/6/98	NLPH	12.81	7.43						
	1/11/99	NLPH	12.74	7.50	< 50	<2.5	< 0.5	< 0.5	< 0.5	< 0.5
	4/8/99	NLPH	11.93	8.31						
	7/19/99	NLPH	11.75	8.49	281	17.6	35.4	9.1	7.4	30.7
	7/27/99	NLPH	12.95	7.29						•••
	10/25/99	NLPH	12.79	7.45					***	
RW1	Not Monitored	6/16/92 throu	igh 10/6/98.							
(20.24)	1/11/99	NLPH	12.37	7.87						
, ,	4/8/99	NLPH	10.41	9.83						
	7/19/99									
	7/27/99	NLPH	12.76	7.48						
	10/25/99	NLPH	12.50	7.74		***			****	
RW2	Not Monitored	6/16/92 throu	gh 4/20/98.							
(20.44)	7/21/98	NLPH	12.65	7.79	3,500	170	240	100	41	96
(=====,	10/6/98	NLPH	13.06	7.38	3,200	200	120	48	56	120
	1/11/99	NLPH	12.88	7.56	3,300	350	150	17	35	40
	4/8/99	sheen	11.76	8.68						
	7/19/99	NLPH	11.61	8.83	1,980	160/499*	44	4.16	22.3	11.6
	7/27/99	NLPH	13.26	7.18		****				
	10/25/99	NLPH	12.96	7.48	1,800	440	51	< 0.5	4.7	9.5
RW3A	Not Monitored	6/16/92 throu	oh 4/20/98							
(21.75)	7/21/98	NLPH	13.08	8.67	280	16	97	< 1.2	<1.2	<1.2
(21.70)	10/6/98	NLPH	13.72	8.03	78	26	26	0.89	< 0.5	< 0.5
	1/11/99	NLPH	12.00	9.75	1,000	230	490	5.0	< 5.0	7.4
	4/8/99	NLPH	11.90	9.85	130	11	70	< 1.0	<1.0	<1.0
	7/19/99	NLPH	11.75	10.00	989	16.4	393	6.40	5.70	15.0
	7/27/99	NLPH	13.68	8.07	***					
	10/25/99	NLPH	13.61	8.14	150	19	53	< 0.5	< 0.5	< 0.5


# TABLE 1 CUMULATIVE GROUNDWATER MONITORING AND SAMPLING DATA


### Exxon Service Station 7-0235

2225 Telegraph Avenue Oakland, California

(Page 4 of 4)

Notes:		
SUBJ	=	Results of subjective evaluation.
NLPH	=	No liquid-phase hydrocarbons present in well.
sheen	=	Liquid-phase hydrocarbon present as sheen.
TOC	=	Elevation of top of well casing; relative to mean sea level.
DTW	=	Depth to water.
Elev.	=	Elevation of groundwater surface; relative to mean sea level.
TPPHg	=	Total purgeable petroleum hydrocarbons as gasoline analyzed using EPA method 5030/8015 (modified).
MTBE	=	Methyl tertiary butyl ether analyzed using EPA method 5030/8020.
BTEX	=	Benzene, toluene, ethylbenzene, and total xylenes analyzed using EPA method 5030/8020.
<	=	Less than the indicated detection limit shown by the laboratory.
	=	Not measured or sampled.
*	=	Methyl tertiary butyl ether analyzed using EPA method 8260B.
ug/L	=	Micrograms per liter.
Sampling discontinu	ed for wells	MW6F, MW6G, and RW1 per Alameda County Health Services Agency letter dated June 1, 1998.






### SITE VICINITY MAP

EXXON SERVICE STATION 7-0235 2225 Telegraph Avenue Oakland, California

### PLATE

1



FN 22290002

### EXPLANATION

MWGH

Groundwater Monitoring Well

8.31 Groundwater elevation in feet

above mean sea level
i = Interpreted Groundwater Gradient

RWSA

Recovery Well

VV3

Vapor/Vadose Well



## GENERALIZED SITE PLAN

EXXON SERVICE STATION 7-0235 2225 Telegraph Avenue Oakland, California PROJECT NO.

2229

PLATE

2 November 17, 1999

# ATTACHMENT A GROUNDWATER SAMPLING PROTOCOL

# BLAINE TECH SERVICES, INC. METHODS AND PROCEDURES FOR THE ROUTINE MONITORING OF GROUNDWATER WELLS AT EXXON STATIONS

Blaine Tech Services, Inc. performs environmental sampling and documentation as an independent third party. We specialize in groundwater monitoring assignments and intentionally limit the scope of our services to those centered on the generation of objective information.

To avoid conflicts of interest, Blaine Tech Services, Inc. personnel do not evaluate or interpret the information we collect. As a state licensed contractor (C-57 well drilling –water – 746684) performing strictly technical services, we do not make any professional recommendations and perform no consulting of any kind.

### SAMPLING PROCEDURES OVERVIEW

### SAFETY

All groundwater monitoring assignments performed for Exxon comply with Exxon's safety guidelines, 29 CFR 1910.120 and SB-198 Injury and Illness Prevention Program (IIPP). All Field Technicians receive the full 40 hour 29CFR 1910.120 OSHA SARA HAZWOPER course, medical clearance and on-the-job training prior to commencing any work on any Exxon site.

### INSPECTION AND GAUGING

Wells are inspected prior to evacuation and sampling. The condition of the wellhead is checked and noted according to a wellhead inspection checklist.

Standard measurements include the depth to water (DTW) and the total well depth (TD) obtained with industry standard electronic sounders which are graduated in increments of hundredths of a foot.

The water in each well is inspected for the presence of Immiscibles or sheen and when free product is suspected, it is confirmed using an electronic interface probe (e.g. MMC). If sheen or product is found in a well, the Project Coordinator notifies the appropriate party (e.g. Exxon employee or consultant).

No samples are collected from a well containing sheen or product. EVACUATION

Depth to water measurements are collected by our personnel prior to purging and minimum purge volumes are calculated anew for each well based on the height of the water column and the diameter of the well. Expected purge volumes are never less than three case volumes and

are set at no less than four case volumes in some jurisdictions.

Well purging devices are selected on the basis of the well diameter and the total volume to be evacuated. In most cases the well will be purged using an electric submersible pump (i.e. Grundfos) suspended near (but not touching) the bottom of the well. Small volumes of purgewater are often removed by hand bailing with a disposable bailer.

### PARAMETER STABILIZATION

Well purging completion standards include minimum purge volumes, but additionally require stabilization of specific groundwater parameters prior to sample collection. Typical groundwater parameters used to measure stability are electrical conductivity, pH, and temperature. Instrument readings are obtained at regular intervals during the evacuation process (no less than once per case volume).

Stabilization standards for routine quarterly monitoring of fuel sites include the following: Temperature is considered to have stabilized when successive readings do not fluctuate more than +/- 1 degree Celsius. Electrical conductivity is considered stable when successive readings are within 10%. pH is considered to be stable when successive readings remain constant or vary no more than 0.2 of a pH unit.

### **DEWATERED WELLS**

Normal evacuation removes no less than three case volumes of water from the well. However, less water may be removed in cases where the well dewaters and does not recharge.

Wells known to dewater are evacuated as early as possible during each site visit in order to allow for the greatest amount of recovering. Any well that does not recharge to 80% of its original volume will be sampled prior to the departure of our personnel from the site in order to eliminate the need of a return visit.

In jurisdictions where a certain percentage of recovery is included in the local completion standard, our personnel follow the regulatory expectation.

#### PURGEWATER CONTAINMENT

All non-hazardous purgewater evacuated from each groundwater monitoring well is captured and contained in on-board storage tanks on the Sampling Vehicle and/or special water hauling trailers. Effluent from the decontamination of reusable apparatus (sounders, electric pumps and hoses etc.), consisting of groundwater combined with deionized water and non-phosphate soap, is also captured and pumped into effluent tanks.

Non hazardous purgewater is transported under standard Bill of Lading documentation to a Blaine Tech Services, Inc. facility before being transported to an Exxon approved disposal facility (e.g. Romic Environmental Technologies Corporation in East Palo Alto, California).

### SAMPLE COLLECTION DEVICES

All samples are collected using a disposable bailer.

### SAMPLE CONTAINERS

Sample material is decanted directly from the sampling bailer into sample containers provided by the laboratory which will analyze the samples. The transfer of sample material from the bailer to the sample container conforms to specifications contained in the USEPA T.E.G.D. The type of sample container, material of construction, method of closure and filling requirements are specific to the intended analysis. Chemicals needed to preserve the sample material are commonly placed inside the sample containers by the laboratory or glassware vendor prior to delivery of the bottle to our personnel. The laboratory sets the number of replicate containers.

#### TRIP BLANKS

A Trip Blank is carried to each site and is kept inside the cooler for the duration of the sampling event. It is turned over to the laboratory for analysis with the samples from that site.

### SAMPLE STORAGE

All sample containers are promptly placed in food grade ice chests for storage in the field and transport (direct or via our facility) to the analytical laboratory that will perform the intended analytical procedures. These ice chests contain quantities of restaurant grade ice as a refrigerant material. The samples are maintained in either an ice chest or a refrigerator until relinquished into the custody of the laboratory or laboratory courier.

### DOCUMENTATION CONVENTIONS

Each and every sample container has a label affixed to it. In most cases these labels are generated by our office personnel and are partially preprinted. Labels can also be hand written by our field personnel. The site is identified with the station number and site address, as is the particular groundwater well from which the sample is drawn (e.g. MW-1, MW-2, S-1 etc.). The time at which the sample was collected and the initials of the person collecting the sample are handwritten onto the label.

Chain of Custody records are created using client specific preprinted forms following USEPA specifications.

Bill of Lading records are contemporaneous records created in the field at the site where the non-hazardous purgewater is generated. Field Technicians use preprinted Bill of Lading forms.

### DECONTAMINATION

All equipment is brought to the site in clean and serviceable condition and is cleaned after use in each well and before subsequent use in any other well. Equipment is decontaminated before

leaving the site.

The primary decontamination device is a commercial steam cleaner. The steam cleaner is detuned to function as a hot pressure washer which is then operated with high quality deionized water which is produced at our facility and stored onboard our sampling vehicle. Cleaning is facilitated by the use of proprietary fixtures and devices included in the patented workstation (U.S. Patent 5,535,775) that is incorporated in each sampling vehicle. The steam cleaner is used to decon reels, pumps and bailers.

Any sensitive equipment or parts (i.e. Dissolved Oxygen sensor membrane, sounder etc.) that cannot be washed using the hot high pressure water, will be sprayed with a non-phosphate soap and deionized water solution and rinsed with deionized water.

EXAMPLE: The sounder is cleaned between wells using the non-phosphate soap and deionized water solution followed by deionized water rinses. The sounder is then washed with the steam cleaner between sites or as necessitated by use in a particularly contaminated well.

#### DISSOLVED OXYGEN READINGS

All Dissolved Oxygen readings are taken using YSI meters (e.g. YSI Model 58 or equivalent YSI meter). These meters are equipped with a YSI stirring device that enables them to collect accurate in-situ readings. The probe/stirring devices are modified to allow downhole measurements to be taken from wells as small as two-inch diameter.

The probe and reel is decontaminated between wells as described above. The meter is calibrated between wells as per the instructions in the operating manual. The probe and stirrer is lowered into the water column allowed to stabilize before use.

### OXYIDATON REDUCTION POTENTIAL READINGS

All readings are obtained with either Corning or Myron-L meters (e.g. Corning ORP-65 or a Myron-L Ultrameter GP). The meter is cleaned between wells as described above. The meter is calibrated at the start of each day according to the instruction manual. In use the probe is placed in a cup of freshly obtained monitoring well water and allowed to stabilize.

# ATTACHMENT B FIELD DATA SHEETS

	ces	_\ele	graph.	AW	- 0	libras , i	A		
Well ID	Well Size (in.);	Sheën/ Odoë		Thickness of Immiscible Liquid (ft)	Volume of Immiscibles Removed (ml)	・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・	Depth to well bottom (ts)		
. uwes	$\mathcal{V}$			fi T			4.52	10.40	
MW GE	4						1957	TOL	
<u>Negaé</u>	4	Man and the second	7 - 100 F	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	en e	<u>ILLE</u>	19.666	₩.	An a transfer
MAGG	A(z)		See Salesande			17.6	19,5]	104	
. MKALL	3代	<u> 274</u>	14 <b>8</b> 2 8			17:16	14:166-	*EUS-	
S KILLIOE				e Estado Caragado		izatû	1120	106	
<u>  [24]                                   </u>				e gar Esception		12:50.	Service and the service of	179/2	
8v/2 2(U2)		Land Ha				AND A STATE OF THE	734 <b>(</b> )	A MERCANDINA MA	3 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3
ZOJSE:				0 (14) (1) 40 (14)		34	71.09	TOC	
****	<b>*</b> 7 *****	<b>新州市区</b> 第一条	The state of the s						

3 <del>3 -</del> 1

Project #:	99102	5-K1		Store # 7	-0235		
Sampler:	MATT	- 		Date: 10	125/99		
Well I.D.:	MWG	13		Well Diamete	r: <b>②</b> 3 4	6 8	
Total Wel	l Depth:	18.32		Depth to Wate	er: 12.49		
Depth to l	Free Produ	ct:	,	Thickness of I	Free Product (fee	t):	
Reference	ed to:	PV	Grade	D.O. Meter (it	freq'd):	YSI	НАСН
	Well Diamete  2"  3"  4"	0	ultiplier <u>y</u> .16 .37 .65	5" 6"	<u>Multiplier</u> 1.02 1.47 ius <sup>2</sup> * 0.163		
Purge Metho	Ele	Bailer Disposable Bail Middleburg ectric Submersi Extraction Pum	ble	Sampling Method Other	Oisposable Bailey Extraction Port	_	
	1 Case Volu		x		Gals.		
Time	Temp (°F)	pН	Cơnd.	Gals. Removed	Observations		
903	68.8	6.96	1028	1	oco		
906	69.2	7.04	1016	2	6 dor		
908	69.5	7.07	1015	3			
Did well o	dewater?	Yes	60	Gallons actual	ly evacuated:	3.0	
Sampling	Time:	709		Sampling Date	: 10/25/99		
Sample I.	D.: MY	WUB		Laboratory:	Sequioia SPI—	Other_	
Analyzed	for: PH-	G ETEX 1	ТВЕ ТРН-D	Other:			
D.O. (if re	eq'd):		Pre-purge:	mg/I	Post-purge		mg/ <sub>L</sub> .
O.R.P. (if	req'd):		. Pre-purge:	mV	Post-purge	:	mV

Project #:	99102	5-K1		Store #	7-	0235		
Sampler:	Mr	+11		Date:	10/24	199	<u>.</u> .	
Well I.D.	M	WUE		Well Dia	meter:	2 3 4	6 8	
Total Wel	ll Depth:	19.5	51	Depth to	Water:	13.52	,	
Depth to	Free Produ	ct:		Thicknes	s of Fr	ee Product (feet	):	
Reference	ed to:	PVO	Grade	D.O. Met	ter (if r	eq'd):	YSI	НАСН
	Well Diamete 2" 3" 4"	0	ultiplier <u>y</u> ).16 ).37 ).65	Vell Diameter 5" 6" Other	1.0 1.4			
Purge Metho	ođ:	Bailer		Sampling M	lethod:	Bailer		
_		Disposable Bail	er			Disposable Bailer		
		* Middleburg	•		Out	Extraction Port		
		ectric Submers Extraction Pum			Other:		-	
	Other:		· <b>F</b>					
	4		x3	=		Gals.		
	1 Case Volu	ime (Gais.)	Specified Vo	lumes	Calcu	lated Volume		
Time	Temp (°F)	pН	Cond.	Gals. Ren	noved	Observations		
9,154	(AO/18)	17/191	1914	1 MAI	1			·
9.55	id #	17.64	HE BOHY	A LANGE	V			
9:56	٥.٥ي	6.69	803	way	4			
956	64.7	659	600	8		6.59		
957	64.1	6.58	599	12				
Did well	dewater?	Yes	<u>M</u>	Gallons a	ctually	evacuated: 17		
Sampling	Time:	gusta	1002	Sampling	Date:	10/25/99		
Sample I.	D.: M4	ME		Laborator	ry: S	<del>lequoia</del> SPL	Other	r
Analyzed	for: PH	В	<b>ТРН-</b> D	Other:				
D.O. (if re	eq'd):		Pre-purge:		mg/L	Post-purge:		mg/ <sub>L</sub>
O.R.P. (if	req'd):		Pre-purge:		mV	Post-purge:		mV

Project #:	99102	5-K		Job # 7.	-0235		
Sampler:	M	ATT		Date: (0)	25/19		
Well I.D.:	Mh	Lett		Well Diameter	r: 2 3 <u>4</u>	68	
Total Wel	l Depth:	۱٩.	90	Depth to Wate	er: 12.16		
Depth to I	Free Produ	ict:	•	Thickness of I	Free Product (fe	et):	
Reference	ed to:	(evc)	Grade	D.O. Meter (if	req'd):	YSI HAC	Н
	Well Diamete 2" 3" 4"		Multiplier 9 0.16 0.37 0.65	5" 6" Other rad	Multiplier 1.02 1.47 lius <sup>2</sup> * 0.163		
Purge Metho	Ø €Iē	Bailer  Sposoble Bailer  Middleburg  ctric Submers  xtraction Pum	ible	Sampling Method Other	Bailer  isposable Baile  Extraction Port		
·	1 Case Volu	ume (Gals.)	x Specified Vo	=	Gals.		
Time	Temp (°F)	pН	Cond.	Turbidity	Gals. Removed	Observati	ons
1039	67.3	6.83	1076		5		<u></u>
1040	68.8	Co,77	1071		10		
104(	69.8	6.77	(090		15		
10 ·	, i	· · · · · · · · · · · · · · · · · · ·					
Did well	dewater?	Yes	<b>6</b>	Gallons actual	ly evacuated:	15	
Sampling	Time:	1044		Sampling Date	: 10/25/	99	
Sample I.	D.: <b>W</b>	IW 6H		Laboratory:	Sequoia SPL	Other	
Analyzed	for: Ten-	G ETEX	MEE TPH-D	Other:			
D.O. (if re	eq'd):		Pre-purge:	mg <sub>/</sub>	Post-purge:	- No. of	mg/L
O.R.P. (if	req'd):		Pre-purge:	m\	Post-purge:	12.5	mV

Project #:	910	25-KI		Store #	1-0235	-
Sampler:	MA			Date: 10	125/99	
Well I.D.	: و	W-Z		Well Diameter	: 2 3 <b>(5</b> )	6 8
Total We	ll Depth:	23.40		Depth to Water	r: 12.96	
Depth to	Free Produ	ct:		Thickness of F	ree Product (feet)	):
Reference	ed to:	PVC	Grade	D.O. Meter (if	req'd):	YSI HACH
	Well Diamete 2" 3" 4"	<u>M</u> 0 0 0	ultipfier V 0.16 0.37 0.65	Vell Diameter M 5" 6" Other radiu	<u>Multiplier</u> 1.02 1.47 us <sup>2</sup> * 0.163	
Purge Metho	1 25	Bailer Disposable Bail Middleburg Stric Submers Extraction Pum	₹ble	Sampling Method: Other:	Disposable Batter Extraction Port	
	1 Case Volu		X Specified Vo		Gals.	
Time	Temp (°F)	pН	Cond.	Gals. Removed	Observations	
1018	63.5	6.71	₹38	7	blackwater	lodor
1019	64.2	6.74	840	14		
1020	64.4	6.80	842	21		
Did well	dewater?	Yes	<b>6</b>	Gallons actuall	y evacuated:	21
Sampling	Time:	1023		Sampling Date	: 10/25/	99
Sample I.	D.: R	22		Laboratory:	Sequeia SPL	Other
Analyzed	for: TH	TEX 1	TPH-D	Other:		
D.O. (if re	eq'd):		Pre-purge:	$^{ m mg}/_{ m L}$	Post-purge:	mg/L
O.R.P. (if	req'd):		Pre-purge:	mV	Post-purge:	mV

Project #:	9910	25-KI		Store# 7	0235	
Sampler:	me	+11		Date: 10	125/99	
Well I.D.	e e	13A		Well Diamete	er: 2 3 <b>4</b>	6 8
Total We	ll Depth:	21.0	7	Depth to Wat	er: \3.@	
Depth to	Free Produ	ct:	•	Thickness of	Free Product (feet)	):
Reference	ed to:	(PVC)	Grade	D.O. Meter (i	f req'd):	YSI HACH
Purge Metho		0 0 0 Bailer	.16 .37 .65	Vell Diameter 5* 6* Other rad Sampling Method		
	ভ	Disposable Baile Middleburg ectric Submersi Extraction Pum	bie>	Othe	Disposable Bailer Extraction Port	
	1 Case Volu		X 3	· =	Gals.	
Time	Temp (°F)	pН	Cond.	Gals. Removed	l Observations	
926	67.9	6.93	913	5	odor	
927	68.4	6.87	885	10		
928	68.5	6.84	929	15	V	
Did well	dewater?	Yes	No	Gallons actua	lly evacuated: (	5
Sampling	Time:	931		Sampling Dat	e: 10/25/9	5
Sample I.	D.: <b>K</b> ı	N 3A		Laboratory:	Sequoia SPL	Other
Analyzed	for: TH-		TPH-D	Other:		
D.O. (if re	eq'd):		Pre-purge:	mg <sub>/</sub>	L Post-purge:	<sup>mg</sup> / <sub>L</sub>
O.R.P. (if	req'd):		Pre-purge:	m\	V Post-purge:	mV

### ATTACHMENT C

# LABORATORY ANALYSIS REPORT AND CHAIN OF CUSTODY RECORD



HOUSTON LABORATORY 8880 INTERCHANGE DRIVE HOUSTON, TEXAS 77054 (713) 660-0901

# Case Narrative for: EXXON Company U.S.A.

### Certificate of Analysis Number:

### 99100531

Report To:

Project Name:

2229

Environmental Resolution, Inc.

73 Digital Drive Suite 100

Site:

7-0235,19900939

Jim Chappell

Site Address:

2225 Telegraph Avenue

Addicas.

Oakland

ÇA

Novato

California 94949State:

California

\_\_\_\_

PO Number:

1903

State Cert. No.:

ph: (415) 382-5996

fax: (415) 382-1856

Date Reported:

Any data flags or quality control exceptions associated with this report will be footnoted in the analytical result page(s) or the quality control summary page(s).

Please do not hesitate to contact us if you have any questions or comments pertaining to this data report. Please reference the above Certificate of Analysis Number.

SPL, Inc. is pleased to be of service to you. We anticipate working with you in fulfilling all your current and future analytical needs.

This report shall not be reproduced except in full, without the written approval of the laboratory. The reported results are only representative of the samples submitted for testing.

Wyatt, Meaundra
Project Manager

11/12/99

Date





### **EXXON Company U.S.A.**

### Certificate of Analysis Number:

### 99100531

port To:

**Environmental Resolution, Inc.** 

fax: (415) 382-1856

Jim Chappell

73 Digital Drive Suite 100

Novato

California

94949-

ph: (415) 382-5996

Project Name:

2229

Site:

7-0235,19900939

Site Address:

2225 Telegraph Avenue

**Qakland** 

CA

PO Number:

State:

California

1903

State Cert. No.:

Date Reported:

Client Sample II	Lab Sample ID	Matrix	Date Collected	Date Received	COC ID	HOLD
_						
<b>11/6</b> B	99100531-01	Water	10/25/99 9:09:00 AM	10/28/99 10:00:00 AM		
/6E	99100531-02	Water	10/25/99 10:02:00 AM	10/28/99 10:00:00 AM		
/W6H	99100531-03	Water	10/25/99 10:44:00 AM	10/28/99 10:00:00 AM		
<u>RW</u> 2	99100531-04	Water	10/25/99 10:23:00 AM	10/28/99 10:00:00 AM		
′3A	99100531-05	Water	10/25/99 9:31:00 AM	10/28/99 10:00:00 AM		
no Blank	99100531-06	Water	10/25/99	10/28/99 10:00:00 AM		

James Ufact

11/12/99

yatt, Neaundra oject Manager Date

Joel Grice Laboratory Director

Ted Yen Quality Assurance Officer



HOUSTON LABORATORY 8880 INTERCHANGE DRIVE HOUSTON, TEXAS 77054 (713) 660-0901

Client Sample ID MW6B Collected: 10/25/99 9:09:00 SPL Sample ID: 99100531-01

Site: 7-0235,19900939

		Oite.	7-0255,15500505			
Analyses/Method	Result	Rep.Limit	Dil. Factor Ql	JAL Date Analyzed	Analyst	Seq.#
GASOLINE RANGE ORGANICS			CA_GRO	Units: ug/	L L	
Gasoline Range Organics	260	50	1	11/02/99 22:47	CJ	88988
Surr: 1,4-Diffuorobenzene	110	62-144	1	11/02/99 22:47	CJ	88988
Surr: 4-Bromofluorobenzene	210	44-153	1 *	11/02/99 22:47	ch	88988
PURGEABLE AROMATICS			SW8021B	Units: ug/	L	
Benzene	2.3	0.5	1	11/02/99 22:47	CJ	88739
Ethylbenzene	ND	0.5	1	11/02/99 22:47	CJ	88739
Methyl tert-butyl ether	ND	2	1	11/02/99 22:47	CJ	88739
Toluene	ND	0.5	1	11/02/99 22:47	CJ	88739
m,p-Xylene	ND	0.5	1	11/02/99 22:47	ÇJ	88739
o-Xylene	ND	0.5	1	11/02/99 22:47	CJ	88739
Xylenes,Total	ND	0.5	1	11/02/99 22:47	CJ	88739
Surr: 1,4-Difluorobenzene	89	72-137	1	11/02/99 22:47	CJ	88739
Surr: 4-Bromofluorobenzene	150	48-156	1	11/02/99 22:47	CJ	88739

Wyatt, Neaundra
Project Manager

Qualifiers:

ND/U - Not Detected at the Reporting Limit

B - Analyte detected in the associated Method Blank

alfact

\* - Surrogate Recovery Outside Advisable QC Limits

J - Estimated Value between MDL and PQL

>MCL - Result Over Maximum Contamination Limit(MCL)





Client Sample ID MW6E

Collected: 10/25/99 10:02:0 SPL Sample ID: 99100531-02

Site: 7-0235,19900939

Analyses/Method	Result	Rep.Limit	Dil. Factor QUAL	Date Analyzed	Analyst	Seq. #	
GASOLINE RANGE ORGANICS			CA_GRO	Units: ug/	L		
Gasoline Range Organics	ND	50	1	11/04/99 4:35	D_R	90643	
Surr: 1,4-Difluorobenzene	93	62-144	1	11/04/99 4:35	D_R	90643	
Surr: 4-Bromofluorobenzene	110	44-153	1	11/04/99 4:35	D_R	90643	
PURGEABLE AROMATICS			SW8021B	Units: ug/L			
Benzene	ND	0.5	1	11/03/99 4:06	D_R	89952	
Ethylbenzene	ND	0.5	1	11/03/99 4:06	D_R	89952	
Methyl tert-butyl ether	2.5	2	1	11/03/99 4:06	D_R	89952	
Toluene	ND	0.5	1	11/03/99 4:06	D_R	89952	
m,p-Xylene	ND	0.5	1	11/03/99 4:06	D_R	89952	
o-Xylene	ND	0.5	1	11/03/99 4:06	D_R	89952	
Xylenes,Total	ND	0.5	1	11/03/99 4:06	D_R	89952	
Surr: 1,4-Difluorobenzene	95	72-137	1	11/03/99 4:06	D_R	89952	
Surr: 4-Bromofluorobenzene	120	48-156	1	11/03/99 4:06	D_R	89952	

Teame Ufact

Wyatt, Neaundra Project Manager

Qualifiers:

ND/U - Not Detected at the Reporting Limit

- B Analyte detected in the associated Method Blank
- \* Surrogate Recovery Outside Advisable QC Limits
- J Estimated Value between MDL and PQL

>MCL - Result Over Maximum Contamination Limit(MCL)

D - Surrogate Recovery Unreportable due to Dilution

99100531 Page 3 11/12/99 8:49:48 AM





Client Sample ID MW6H		Colfed	cted: 10/25/99 10:44:0	SPL Sample ID:	99100	531-03
		Site:	7-0235,19900939			
Analyses/Method	Result	Rep.Limit	Dil. Factor QUAL	Date Analyzed	Analyst	Seq.#
GASOLINE RANGE ORGANICS			CA_GRO	Units: ug/L		
Gasoline Range Organics	700	250	5	11/04/99 18:51	D_R	92264
Surr: 1,4-Difluorobenzene	100	62-144	5	11/04/99 18:51	D_R	92264
Surr: 4-Bromofluorobenzene	100	44-153	5	11/04/99 18:51	D_R	92264
PURGEABLE AROMATICS			SW8021B	Units: ug/L		
Benzene	360	0.5	1	11/03/99 5:01	D_R	89956
Ethylbenzene	0.68	0.5	1	11/03/99 5:01	D_R	89956
Methyl tert-butyl ether	4000	25	25	11/04/99 5:02	D_R	90913
Toluene	1.1	0.5	1	11/03/99 5:01	D_R	89956
m,p-Xylene	2	0.5	1	11/03/99 5:01	D_R	89956
o-Xylene	ND	0.5	1	11/03/99 5:01	D_R	89956
Xylenes,Total	2	0.5	1	11/03/99 5:01	D_R	89956
Surr: 1,4-Difluorobenzene	100	72-137	25	11/04/99 5:02	D_R	90913
Surr: 1,4-Difluorobenzene	120	72-137	1	11/03/99 5:01	D_R	89956
Surr: 4-Bromofluorobenzene	99	48-156	25	11/04/99 5:02	D_R	90913
Surr: 4-Bromofluorobenzene	130	48-156	1	11/03/99 5:01	D_R	89956

Wyatt, Neaundra Project Manager

Qualifiers:

ND/U - Not Detected at the Reporting Limit

B - Analyte detected in the associated Method Blank

\* - Surrogate Recovery Outside Advisable QC Limits

J - Estimated Value between MDL and PQL

>MCL - Result Over Maximum Contamination Limit(MCL)



HOUSTON LABORATORY 8880 INTERCHANGE DRIVE HOUSTON, TEXAS 77054 (713) 660-0901

Client Sample ID RW2 Collected: 10/25/99 10:23:0 SPL Sample ID: 99100531-04

Site: 7-0235,19900939

tesult	Rep.Limit	Dil. Factor QUAL	Date Analyzed	Amakini	O 4
			Date Allalyzeu	Analyst	Seq. #
	-	CA_GRO	Units: ug/	'L	
1800	50	1	11/04/99 5:30	D_R	90645
95	62-144	1	11/04/99 5:30	D_R	90645
120	44-153	1	11/04/99 5:30	D_R	90645
		SW8021B	Units: ug/		
51	0.5	1 ′	11/04/99 5:30	D_R	90914
4.7	0.5	1	11/04/99 5:30	D_R	90914
440	2	1	11/04/99 5:30	D_R	90914
ND	0.5	1	11/04/99 5:30	D_R	90914
7.2	0.5	1	11/04/99 5:30	D_R	90914
2.3	0.5	1	11/04/99 5:30	D_R	90914
9.5	0.5	1	11/04/99 5:30	D_R	90914
170	72-137	1 *	11/04/99 5:30	D_R	90914
130	48-156	1	11/04/99 5:30	D_R	90914
	95 120 51 4.7 440 ND 7.2 2.3 9.5 170	95 62-144 120 44-153 51 0.5 4.7 0.5 440 2 ND 0.5 7.2 0.5 2.3 0.5 9.5 0.5 170 72-137	1800 50 1 95 62-144 1 120 44-153 1  SW8021B  51 0.5 1 4.7 0.5 1 440 2 1 ND 0.5 1 7.2 0.5 1 2.3 0.5 1 9.5 0.5 1 170 72-137 1 *	1800         50         1         11/04/99 5:30           95         62-144         1         11/04/99 5:30           SW8021B         Units: ug/           51         0.5         1         11/04/99 5:30           4.7         0.5         1         11/04/99 5:30           440         2         1         11/04/99 5:30           ND         0.5         1         11/04/99 5:30           7.2         0.5         1         11/04/99 5:30           2.3         0.5         1         11/04/99 5:30           9.5         0.5         1         11/04/99 5:30           170         72-137         1         11/04/99 5:30	1800         50         1         11/04/99 5:30         D_R           95         62-144         1         11/04/99 5:30         D_R           120         44-153         1         11/04/99 5:30         D_R           SW8021B         Units: ug/L           51         0.5         1         11/04/99 5:30         D_R           4.7         0.5         1         11/04/99 5:30         D_R           440         2         1         11/04/99 5:30         D_R           ND         0.5         1         11/04/99 5:30         D_R           7.2         0.5         1         11/04/99 5:30         D_R           2.3         0.5         1         11/04/99 5:30         D_R           9.5         0.5         1         11/04/99 5:30         D_R           170         72-137         1         11/04/99 5:30         D_R

Wyatt, Neaundra
Project Manager

Qualifiers:

ND/U - Not Detected at the Reporting Limit

B - Analyte detected in the associated Method Blank

\* - Surrogate Recovery Outside Advisable QC Limits

J - Estimated Value between MDL and PQL

>MCL - Result Over Maximum Contamination Limit(MCL)





Client Sample ID RW3A Collected: 10/25/99 9:31:00 SPL Sample ID: 99100531-05

Site: 7-0235,19900939

		Site:	7-0235,19900939			
Analyses/Method	Result	Rep.Limit	Dil. Factor QUAL	Date Analyzed	Analyst	Seq. #
GASOLINE RANGE ORGANICS			CA_GRO	Units: ug/	L	
Gasoline Range Organics	150	. 50	1	11/04/99 5:57	D_R	90647
Surr: 1,4-Difluorobenzene	110	62-144	1	11/04/99 5:57	D_R	90647
Surr: 4-Bromofluorobenzene	120	44-153	1	11/04/99 5:57	D_R	90647
PURGEABLE AROMATICS			SW8021B	Units: ug/	L	
Benzene	53	0.5	1	11/03/99 4:33	D_R	89955
Ethylbenzene	ND	0.5	1	11/03/99 4:33	D_R	89955
Methyl tert-butyl ether	19	2	1	11/03/99 4:33	D_R	89955
Toluene	ND	0.5	1	11/03/99 4:33	D_R	89955
m,p-Xylene	ND	0.5	1	11/03/99 4:33	D_R	89955
o-Xylene	ND	0.5	1	11/03/99 4:33	D_R	89955
Xylenes,Total	ND	0.5	1	11/03/99 4:33	D_R	89955
Surr: 1,4-Difluorobenzene	86	72-137	1	11/03/99 4:33	D_R	89955
Surr: 4-Bromofluorobenzene	100	48-156	1	11/03/99 4:33	D_R	89955

The and Uffer

Wyatt, Neaundra Project Manager

Qualifiers:

ND/U - Not Detected at the Reporting Limit

B - Analyte detected in the associated Method Blank

\* - Surrogate Recovery Outside Advisable QC Limits

J - Estimated Value between MDL and PQL

>MCL - Result Over Maximum Contamination Limit(MCL)





 Client Sample ID Trip Blank
 Collected: 10/25/99
 SPL Sample ID: 99100531-06

 Site: 7-0235,19900939

		Oite				_
Analyses/Method	Result	Rep.Limit	Dil. Factor QUAL	Date Analyzed	Analyst	Seq.#
GASOLINE RANGE ORGANICS			CA_GRO	Units: ug/	ľL.	
Gasoline Range Organics	ND	50	1	11/04/99 3:13	D_R	90640
Surr: 1,4-Difluorobenzene	96	62-144	1	11/04/99 3:13	D_R	90640
Surr: 4-Bromofluorobenzene	110	44-153	1	11/04/99 3:13	D_R	90640
PURGEABLE AROMATICS			SW8021B	Units: ug/	L	
Benzene	ND	0.5	1	11/03/99 3:38	D_R	89951
Ethylbenzene	ND	0.5	1	11/03/99 3:38	D_R	89951
Methyl tert-butyl ether	ND	2	1	11/03/99 3:38	D_R	89951
Toluene	ND	0.5	1	11/03/99 3:38	D_R	89951
m,p-Xylene	ND	0.5	1	11/03/99 3:38	D_R	89951
o-Xylene	ND	0.5	1	11/03/99 3:38	D_R	89951
Xylenes,Total	ND	0.5	1	11/03/99 3:38	D_R	89951
Surr: 1,4-Difluorobenzene	88	72-137	1	11/03/99 3:38	D_R	89951
Surr: 4-Bromofluorobenzene	120	48-156	1	11/03/99 3:38	D_R	89951

James Uffred

Wyatt, Neaundra Project Manager

Qualifiers:

ND/U - Not Detected at the Reporting Limit

- B Analyte detected in the associated Method Blank
- \* Surrogate Recovery Outside Advisable QC Limits
- J Estimated Value between MDL and PQL

>MCL - Result Over Maximum Contamination Limit(MCL)

D - Surrogate Recovery Unreportable due to Dilution

99100531 Page 7 11/12/99 8:49:51 AM

# Quality Control Documentation





### **EXXON Company U.S.A.**

2229

Ānalysis: Method:

**Purgeable Aromatics** 

SW8021B

99100531

WorkOrder: Lab Batch ID:

R4225

Method Blank

Samples in Analytical Batch:

RunID:

HP\_R\_991102A-88733

Units: ug/L

CJ

Lab Sample ID

Client Sample ID

alysis Date:

11/02/1999 13:51

Analyst:

99100531-01A

MW6B

Analyte	Result	Rep Limit
Benzene	ND	0,50
Ethylbenzene	ND	0,50
Methyl tert-butyl ether	ND	2.0
Toluene	ND	0.50
m.p-Xylene	ND	0.50
o-Xylene	ND	0.50
Xylenes, Total	ND	0.50
Surr: 1,4-Difluorobenzene	86.1	72-137
Surr: 4-Bromofluorobenzene	97.5	48-156

### Laboratory Control Sample (LCS)

RunID:

HP\_R\_991102A-88732

Units:

ug/L

Analysis Date:

11/02/1999 12:59

Analyst: CJ

Analyte	Spike Added	Result	Percent Recovery	Lower Limit	Upper Limit
Benzene	50	53	107	61	119
Ethylbenzene	50	55	111	70	118
Methyl tert-butyl ether	50	54	109	72	128
Toluene	50	55	109	65.	125
m,p-Xylene	100	110	111	72	116
o-Xylene	50	55	110	72	117
Xylenes,Total	150	165	110	72	116

### Matrix Spike (MS) / Matrix Spike Duplicate (MSD)

Sample Spiked:

99100524-02

RunID:

HP\_R\_991102A-88735

Units:

ug/L

Analysis Date:

11/02/1999 19:48

Analyst: CJ

Analyte	Sample Result	MS Spike Added	MS Result	MS % Recovery	MSD Spike Added	MSD Result	MSD % Recovery	RPD	RPD Limit	Low Limit	High Limit
Penzene	ND	20	20	97.8	20	19	94.7	3.24	21	32	164

alifiers:

ND/U - Not Detected at the Reporting Limit

\* - Recovery Outside Advisable QC Limits

B - Analyte detected in the associated Method Blank

D - Surrogate Recovery Unreportable due to Dilution





### **EXXON Company U.S.A.**

2229

Analysis: Method: **Purgeable Aromatics** 

SW8021B

WorkOrder:

99100531

Lab Batch ID:

R4225

### Matrix Spike (MS) / Matrix Spike Duplicate (MSD)

Sample Spiked:

RunID:

99100524-02

HP\_R\_991102A-88735

Units:

ug/L

Analysis Date:

11/02/1999 19:48

Analyst:

: CJ

Analyte	Sample Result	MS Spike Added	MS Result	MS % Recovery	MSD Spike Added	MSD Result	MSD % Recovery	RPD	RPD Limit		High Limit
hylbenzene	ND	20	19	95.9	20	18	91.0	5.19	19	52	142
wethyl tert-butyl ether	ND	20	25	125	20	23	113	9.63	20	39	150
Foluene	ND	20	20	97.9	20	19	94.2	3.85	20	38	159
p-Xylene	ND	40	39	96.4	40	37	91.4	5.31	17	53	144
Xylene	ND	20	20	100	20	19	95.3	4.85	18	53	143
(ylenes,Total	ND	60	59	98.3	60	56	93.3	5.22	17	53	143

Qualifiers:

ND/U - Not Detected at the Reporting Limit

ank D

\* - Recovery Outside Advisable QC Limits

B - Analyte detected in the associated Method Blank

D - Surrogate Recovery Unreportable due to Dilution







### **EXXON Company U.S.A.**

2229

Analysis: Method:

Gasoline Range Organics

CA\_GRO

99100531

WorkOrder: Lab Batch ID:

R4232

Method Blank

Samples in Analytical Batch:

RunID: nalysis Date: HP\_R\_991102C-88969

11/02/1999 13:51

Units:

Analyst:

CJ

mg/L

Lab Sample ID

Client Sample ID

99100531-01A

MW6B

Analyte	Result	Rep Limit
Gasoline Range Organics	ND	0.050
Surr. 1,4-Diffuorobenzene	85.2	62-144
Surr. 4-Bromofluorobenzene	78.9	44-153

### Laboratory Control Sample (LCS)

RunID:

HP\_R\_991102C-88968

Units: mg/L

Analysis Date:

11/02/1999 13:25

CJ Analyst:

Analyte	Spike Added	Result	Percent Recovery	Lower Limit	Upper Limit
Gasoline Range Organics	1	0.99	99	64	131

### Matrix Spike (MS) / Matrix Spike Duplicate (MSD)

Sample Spiked:

99100524-03

RunID:

HP\_R\_991102C-88976

Units:

mg/L

Analysis Date:

11/02/1999 20:39

Analyst: CJ

Analyte	Sample Result	MS Spike Added	MS Result	MS % Recovery	MSD Spike Added	MSD Result	MSD % Recovery	RPD	RPD Limit	Low Limit	High Limit
Gasoline Range Organics	ND	0.9	0.75	83.1	0.9	0.75	82.9	0.174	36	36	160

ualifiers:

ND/U - Not Detected at the Reporting Limit

\* - Recovery Outside Advisable QC Limits

B - Analyte detected in the associated Method Blank

D - Surrogate Recovery Unreportable due to Dilution





### **EXXON Company U.S.A.**

2229

Analysis: Method:

RunID:

alysis Date:

**Purgeable Aromatics** 

SW8021B

WorkOrder:

Samples in Analytical Batch:

99100531

Lab Batch ID:

R4278

Method Blank

VARE\_991102E-89948

11/03/1999 0:53

Units: Analyst:

ug/L D\_R

Lab Sample ID

Client Sample ID

99100531-02A

MW6E

99100531-03A 99100531-05A MW6H RW3A

99100531-06A

Trip Blank

Analyte	Result	Rep Limit
Benzene	ND	0.50
Ethylbenzene	ND	0,50
Methyl tert-butyl ether	ND	2.0
Toluene	ND	0.50
m,p-Xylene	ND	0,50
o-Xylene	ND	0.50
Xylenes,Total	ND	0.50
Surr. 1,4-Difluorobenzene	96.4	72-137
Surr. 4-Bromofluorobenzene	126.1	48-156

### Laboratory Control Sample (LCS)

RunID:

VARE\_991102E-89947

Units:

ug/L

Analysis Date:

11/02/1999 23:58

Analyst: D\_R

Analyte	Spike Added	Result	Percent Recovery	Lower Limit	Upper Limit
Benzene	50	57	115	61	119
Ethylbenzene	50	58	116	70	118
Methyl tert-butyl ether	50	55	110	72	128
Toluene	50	60	120	65	125
m,p-Xylene	100	120	116	72	116
o-Xylene	50	52	103	72	117
Xylenes,Total	150	172	115	72	116

### Matrix Spike (MS) / Matrix Spike Duplicate (MSD)

Sample Spiked:

RunID:

99100531-02

VARE\_991102E-89949

Units:

ug/L

Analysis Date:

11/03/1999 1:20

D\_R Analyst:

Analyte	Sample Result	MS Spike Added	MS Result	MS % Recovery	MSD Spike Added	MSD Result	MSD % Recovery	RPD	RPD Limit	Low Limit	High Limit
Benzene	ND	20	24	122	20		117	4.06	21	32	164

alifiers:

ND/U - Not Detected at the Reporting Limit

\* - Recovery Outside Advisable QC Limits

B - Analyte detected in the associated Method Blank

D - Surrogate Recovery Unreportable due to Dilution





### **EXXON Company U.S.A.**

2229

Analysis: Method: **Purgeable Aromatics** 

SW8021B

WorkOrder:

99100531

Lab Batch ID:

R4278

### Matrix Spike (MS) / Matrix Spike Duplicate (MSD)

Sample Spiked:

RunID:

99100531-02

.

VARE\_991102E-89949

Units:

ug/L

Analysis Date:

11/03/1999 1:20

Analyst:

D\_R

Analyte	Sample Result	MS Spike Added	MS Result	MS % Recovery	MSD Spike Added	MSD Result	MSD % Recovery	RPD	RPD Limit		High Limit
hylbenzene	ND	20	21	106	20	20	102	3.66	19	52	142
wethyl tert-butyl ether	2.5	20	27	123	20	28	130	5.24	20	39	150
Toluene	ND	20	24	122	20	23	116	4.66	20	38	159
p-Xylene	ND	40	43	107	40	41	103	4.12	17	53	144
Xylene	ND	20	20	99.9	20	19	95.3	4.78	18	53	143
(ylenes,Total	ND	60	63	105	60	60	100	4.88	17	53	143

Qualifiers:

ND/U - Not Detected at the Reporting Limit

\* - Recovery Outside Advisable QC Limits

B - Analyte detected in the associated Method Blank

D - Surrogate Recovery Unreportable due to Dilution





### **EXXON Company U.S.A.**

2229

nalysis: Method:

**Gasoline Range Organics** 

CA GRO

WorkOrder:

99100531

Lab Batch ID:

R4303

RuniD:

alysis Date:

VARE\_991103B-90633

Method Biank Units:

mg/L

Analyst:

Lab Sample ID

Samples in Analytical Batch:

Client Sample ID

11/04/1999 0:28

 $D_R$ 

99100531-02A

MW6E

99100531-04A

RW2

99100531-05A

RW3A

99100531-06A

Trip Blank

Analyte	Result	Rep Limit
Gasoline Range Organics	ND	0,050
Surr. 1,4-Difluorobenzene	97.6	62-144
Surr: 4-Bromofluorobenzene	124.0	44-153

### Laboratory Control Sample (LCS)

RunID:

VARE\_991103B-90628

Units:

mg/L

Analysis Date:

11/04/1999 0:01

Analyst: D\_R

Analyte	Spike Added	Result	Percent Recovery	Lower Limit	Upper Limit
Gasoline Range Organics	1	0.83	83	64	131

### Matrix Spike (MS) / Matrix Spike Duplicate (MSD)

Sample Spiked:

9910731-05A

RuniD:

VARE\_991103B-90635

Units:

mg/L D\_R

Analysis Date:

11/04/1999 1:51

Analyst:

RPD High MS Result MS % MSD **MSD Result** MSD % **RPD** Low MS Analyte Sample Limit Recovery Limit Limit Spike Recovery Result Spike Added Added 0.61 11.4 36 36 160 ND 0.9 0.54 60.2 0.9 67.5 Gasoline Range Organics

alifiers:

ND/U - Not Detected at the Reporting Limit

\* - Recovery Outside Advisable QC Limits

B - Analyte detected in the associated Method Blank

D - Surrogate Recovery Unreportable due to Dilution





### **EXXON Company U.S.A.**

2229

Analysis: Method:

RunID:

**Purgeable Aromatics** 

SW8021B

WorkOrder:

99100531

Lab Batch ID:

R4304

Method Blank

totilou biuilit

Lab Sample ID

Samples in Analytical Batch:

Client Sample ID

Apalysis Date:

VARE\_991103C-90909 11/04/1999 0:28 Units: ug/L

D\_R

Analyst:

99100531-03A

MW6H

99100531-04A

RW2

Analyte	Result	Rep Limit
Benzene	ND	0.50
Ethylbenzene	ND	0.50
Methyl tert-butyl ether	ND	1.0
Toluene	ND	0.50
m,p-Xylene	ND	0.50
o-Xylene	ND	0.50
Xylenes, Total	ND	0.50
Surr: 1,4-Diffuorobenzene	95.6	72-137
Surr. 4-Bromofluorobenzene	96.5	48-156

### Laboratory Control Sample (LCS)

RunID:

VARE\_991103C-90908

Units: ug/L

Analysis Date:

11/03/1999 23:33

Analyst: D\_R

Analyte	Spike Added	Result	Percent Recovery	Lower Limit	Upper Limit
Benzene	50	55	110	61	119
Ethylbenzene	50	54	107	70	118
Methyl tert-butyl ether	50	42	84	72	128
Toluene	50	55	110	65	125
m,p-Xylene	100	100	103	72	116
o-Xylene	50	47	93	72	117
Xylenes,Total	150	147	98	72	116

### Matrix Spike (MS) / Matrix Spike Duplicate (MSD)

Sample Spiked:

9910731-02A

RunID:

VARE\_991103C-90910

Units:

ug/L D\_R

Analysis Date:

11/04/1999 0:56

Analyst:

Analyte	Sample Result	MS Spike Adde	+	MS % Recovery	MSD Spike Added	MSD Result	MSD % Recovery	RPD	RPD Limit	Low Limit	High Limit
Benzene	N	D 2	0 22			16	79.4	30.1*	21	32	164

Qualifiers:

ND/U - Not Detected at the Reporting Limit

\* - Recovery Outside Advisable QC Limits

B - Analyte detected in the associated Method Blank

D - Surrogate Recovery Unreportable due to Dilution





### **EXXON Company U.S.A.**

2229

Method:

**Purgeable Aromatics** 

SW8021B

WorkOrder:

99100531

Lab Batch ID:

R4304

### Matrix Spike (MS) / Matrix Spike Duplicate (MSD)

Sample Spiked:

RunID:

9910731-02A VARE\_991103C-90910

Units:

ug/L

Analysis Date:

11/04/1999 0:56

Analyst: D\_R

Analyte	Sample Result	MS Spike Added	MS Result	MS % Recovery	MSD Spike Added	MSD Result	MSD % Recovery	RPD	RPD Limit		High Limit
ylbenzene	ND	20	19	94.4	20	13	65.0	36.8*	19	52	142
wethyl tert-butyl ether	ND	20	21	104	20	16	82.1	23.5*	20	39	150
Toluene	ND	20	22	109	20	14	72.2	40.2*	20	38	159
-Xylene	ND	40	39	98.3	40	27	67.7	36.9*	17	53	144
ylene	ND	20	19	96.0	20	13	63.5	40.8*	18	53	143
(ylenes,Total	ND	60	58	96.7	60	40	66.7	36.7*	17	53	143

alifiers:

ND/U - Not Detected at the Reporting Limit

\* - Recovery Outside Advisable QC Limits

B - Analyte detected in the associated Method Blank

D - Surrogate Recovery Unreportable due to Dilution





### **EXXON** Company U.S.A.

2229

**Gasoline Range Organics** 

Method:

CA\_GRO

WorkOrder:

99100531

Lab Batch ID:

R4360

Method Blank

Samples in Analytical Batch:

RunID: Apalysis Date: VARE\_991104B-92727

11/05/1999 12:53

Units: mg/L Analyst:

D\_R

Lab Sample ID

Client Sample ID

99100531-03A

MW6H

Analyte	Result	Rep Limit
Gasoline Range Organics	ND	0.050
Sum: 1,4-Difluorobenzene	98.3	62-144
Surr: 4-Bromofluorobenzene	128.4	44-153

### Laboratory Control Sample (LCS)

RunID:

VARE\_991104B-92728

Units:

mg/L

Analysis Date:

11/05/1999 13:48

Analyst: D\_R

Analyte	Spike Added	Result	Percent Recovery	Lower Limit	Upper Limit
Gasoline Range Organics	1	0.81	81	64	131

### Matrix Spike (MS) / Matrix Spike Duplicate (MSD)

Sample Spiked:

9910051-02A

RunID:

VARE\_991104B-94753

Units:

mg/L

Analysis Date:

11/05/1999 11:57

Analyst: D\_R

Analyte	Sample Result	MS Spike Added	MS Result	MS % Recovery	MSD Spike Added	MSD Result	MSD % Recovery		Limit	Limit	High Limit
Gasoline Range Organics	ND	0.9	2	222*	0.9	2	218*	1.53	36	36	160

alifiers:

ND/U - Not Detected at the Reporting Limit

\* - Recovery Outside Advisable QC Limits

B - Analyte detected in the associated Method Blank

D - Surrogate Recovery Unreportable due to Dilution

# Chain of Custody And Sample Receipt Checklist

EXXON		ANT,	U	A.	9	7	7)	ns	3		CH	ΙΑ <del>π</del>		UU-	الحت	RE	OOF	D N	<del>.</del>		-			_ F	age	=	1-	07	_(
<del></del>	ineer: Gene Ortega Phone: (925) 246-8747						1	$\overline{}$		T								UES	T: BOX	١					ОТН	IER			
Consultant Co. Name:		RI		ntact:							}				$\rightarrow$							ĺ			_			Y	
Address: 73 Dig				one:				382-43						601								HERBO		9					
	to, CA 949		— · ··· Fa∷					382-18		<del></del>			602	ቖ		<u> </u>	o		}	ā	_		0	LEAD, TCLP		IGNITABILITY			
	,			<del>``</del>	<del></del>		110)	002 10		<del></del>			₩	0		13.2	S S			8270	  -	PEST	길	鱼		IGNI			
RAS #: 7-0235 Facility/State ID # (TN Only):											WITH MTBE	8010		GRAV. 413.2	8015 DRO			ŀ	PCB ONLY	_ 	METALS, TOLP	0		٥					
AFE # (Terminal Only): Consultant Project #: 2229										MTB	BON		5	•	_	5 🗆	8310	PC	170	MET	7421		MITY						
Location: 2225 Telegraph Ave. (City): Oakland (State): CA							<u>—</u>	S		E	SARI		0	×	2	625	86	_	SE		0		CORROSIVITY						
□ EE □ C&M □ SDT								CONTAINERS	SIZE	5	ALO		3.1 (	GRO	192	0	0	<u>                                    </u>	ş	ר <u>-</u>	239.1		S						
Consultant Work Releas	se #:	1990093	9	BTS	# 90	107	5	41			AT N	R S	严	EH	0	IR 413.1 (	015	0	8270	8100	T 80	>	10	¥E.3	ď				
Sampled By: Blaine Te									771.	+	502	AINE	8020	EAB	418.		800	240	ğ	¥.	PES		LS.	5		VITY			Į
SAMPLE I.D.	DAT		COMP	<del></del>	T	MATRI.	X	r	T	ERVATIVE	NO. O	CONTAINER	BTEX 8020	PURGEABLE HALOCARBON 8010	TPH/IR 418.1	0&6	TPH / GC 8015 GRO 🗶	VOL 8240	SEMI-VOL 8270	PNA/PAH 8100 []	PCB / PEST 8080 [3	TCLP FULLCI VOACI SEMI-VOACI PESTO	METALS, TOTAL O	LEAD, TOTAL	тохлон	REACTIVITY	STATE		
MWGB	10/25	1909	X	<del> </del>	X	1	7115		40 y	al Ha				_		<u> </u>	X	_	-		<del>-</del> -	-	-	<del>-</del> -		L.	CA		
MWGE	1		2 X	+	X				VC	443- 1	3	1	X				X	ļ	1			1					<u> </u>		
MWGH		104			X						3	T	X				X							-					
RW2		10 Z	•	+	X						3	$\prod$	X				X	<u> </u>											
RW3A		93			X						3		X		j		X			-									
TB	V								1	<b>Y</b>	2	. 🗸	X				X												
						1											İ												
TAT		1	I		SPE	CIAL E	ETE	CTION I	IMITS	(Speci	fy)		_ <del></del> .	<u> </u>	REM	ARK	S:	1	·	<del></del>	<u></u>								
******	·•	E	CXON U	ST																	01	110	~~	· ~ ·				<b>~</b>	<u> </u>
	*		ITRACT																			4	27	12			<u>s</u> :		≥
	act US Prior	·   -	JZ\$171VI	UΊ	SPE	CIAL F	REPO	RTING	REQU	IREME	NTS	(Spe	cify)		LA	B US	E ON	ILY		LOT					Stora	age L	ocatio	on	
Other to Sending Sample								110 N.W																					
QA/QC Level         FAX         FAX           Standard         CLP         Other         FAX         The control of the control						AX C-O	D-C W / REPORT WORK ORDER #99100 531 LAB WORK RELEASE #																						
Relinquished By Sampler								Dat	Α		Time				d By:				_ \_										
CUCTODY matthew sinth								16/2	10/26/AT 9: Solom								· · · · · · · · · · · · · · · · · · ·												
CUSTODY										Date Time Received By:									A										
RECORD	Relinquished By Sampler:									Date Time Received By Laboratory: )								-11	2 <i>[[</i> _										
	Trom Iquisi	ica by can	, rore								าก-		5-99	î/	00	V	ŀ				·awi	1/2			7		7		2'
	<u> </u>										۲,	<u>~</u>	<u> </u>	<u> </u>	<u> </u>		Wa	y Bill	#:					<i>J</i> Cool	ef Te	mp:			





### Sample Receipt Checklist

Workorder:	99100531		Received by:		Turnell, Randy
Date and Time Received:	10/28/99 10:00:00 AM		Carrier name:		FedEx
Temperature:	3 c				
Shipping container/cooler in	good condition?	Yes 🗹	No 🗀	Not Present	
Custody seals intact on ship	Yes 🗌	No 🗌	Not Present	<b>✓</b>	
Custody seals intact on sam	Yes 🗌	No 🗌	Not Present	$\checkmark$	
Chain of custody present?		Yes 🗹	No 🗌		
Chain of custody signed whe	Yes 🗹	No 🗌			
Chain of custody agrees with	n sample labels?	Yes 🗹	No 🗌		
Samples in proper container	/bottle?	Yes 🗹	No 🗌		
Sample containers intact?		Yes 🗸	No 🗌		
Sufficient sample volume for	indicated test?	Yes 🗹	No 🗌		
All samples received within holding time?		Yes 🗹	No 🗌		
Container/Temp Blank temperature in compliance?		Yes 🗹	No 🗌		
Water - VOA vials have zero headspace?		Yes 🗹	No 🗔	Not Present	
Water - pH acceptable upon	receipt?	Yes 🗹	No 🗌		