RECEIVED

10:33 am, Sep 08, 2008

Alameda County Environmental Health

March 12, 2008 Project SCA421211 SAP No. 135782

Jerry Wickham Alameda County Health Care Services Agency 1131 Harbor Bay Parkway Alameda, California 94502

Re: Dual-Phase Extraction Feasibility Study and Batch Extraction Workplan Shell-branded Service Station 4226 First Street Pleasanton, California

Dear Mr. Wickham,

Delta Consultants, Inc. (DELTA), on behalf of Shell Oil Products US (SHELL), has prepared this Dual-phase Extraction Feasibility Study Workplan for remediation enhancement at the site referenced above (Figures 1 and 2). This work plan is prepared in response to a letter from the Alameda County Health Care Services Agency (ACHCSA) dated December 14, 2007. The ACHCSA letter indicated that the Draft Corrective Action Plan (CAP) submitted by SHELL dated November 2, 2007 was not sufficient to select the most suitable remedial action for the site. The letter requested that SHELL address technical comments and submit a Pilot Work Plan or Revised Draft CAP by February 14, 2008. Due to data loss resulting from a robbery at our offices DELTA requested and received a deadline extension to March 14, 2008.

RESPONSE TO TECHNICAL COMMENTS

The ACHCSA requested that SHELL evaluate soil vapor extraction (SVE) and dual-phase extraction (DPE) as potential remedial technology for the site. DELTA, in the Draft CAP, had concluded that air sparging and oxygen injection were considered unsuitable due to the fine-grained nature of soils at the site. ACHCSA, based on a review of site boring logs and cross-sections, concluded that highly permeable beds exist within the primarily fine-grained soils at the site.

Soil Descriptions and Classifications

Soil from the ground surface to a depth of approximately 95 feet below ground surface (bgs) is composed of silt, silty fine sand, or clayey fine sand. A geologic cross section is provided as Figure 3. The fine-grained soils are





classified on boring logs as ML, SM, and SC, respectively by the Unified Soil Classification System. The sandy soils typically contain 20% to 40% fines that reduce the permeability of the deposits. In the north-northeastern portion of the site, sediments become coarse grained. Borings MW-1, SB-7 and SB-5 (Attachment A) encountered coarse-grained sediments between a depth of approximately 20 feet and 55 feet bgs consisting of clayey sandy gravel (GP), gravelly sand with silt (SP), and clayey gravel (GC). DELTA concludes these are the soil layers referenced in the ACHCSA letter dated December 14, 2007, described as having moderate to high estimated permeability. A thick deposit of silt (ML) was encountered from approximately 55 feet bgs to the top of the lower aquifer at a depth of approximately 100 feet bgs.

Depth to groundwater in shallow monitoring wells is approximately 30 feet bgs and the groundwater flow direction is north to northeast.

Pumping Tests

Step drawdown tests were conducted to provide data for evaluating various remedial technologies for the Draft CAP. The tests were performed using Wells MW-1 and MW-4 (Figure 2). Well MW-1 is screened in soils described as gravelly sand with silt (SP), sandy gravel (GP), and clayey gravelly sand (SP). Well MW-4 is screened in soils described as sandy lean clay with gravel. The soil contained 10% to 20% gravel, 20% to 30% fine sand, and 50% to 70% clay.

The sustainable pumping rate for well MW-1 was determined to be 0.55 gallons per minute (gpm). A hydraulic conductivity of 3.59×10 -5 cm/sec was calculated using the average pumping rate during the test (0.48 gpm). This value is typical of silt (Freeze and Cherry, 1979) and does seem consistent with boring log descriptions.

The step drawdown test at Well MW-4 produced a sustainable pumping rate of 0.4 gpm. A hydraulic conductivity of 3.17×10 -5 centimeters per second (cm/sec) was calculated using the average pumping rate during the test of 0.48 gpm. This value is typical of silt (Freeze and Cherry, 1979) and is consistent with the description of soils on boring logs. The above results led DELTA to consider all site soils as low permeability.

Distribution of Petroleum Hydrocarbons and Methyl Tert-butyl Ether (MTBE)

Petroleum hydrocarbons and MTBE are concentrated in soils in the 30 to 55 foot depth interval (see Figure 3). The highest concentrations of MTBE were from soil samples in the northern portion of the site. The highest MTBE concentrations in recent soil samples were from MW-4 at depths of 44.5 and 55 feet (0.59 milligrams per kilogram (mg/kg) and 0.56 mg/kg). Tert-butyl alcohol (TBA) was not detected in any soil samples from the boring for well MW-4. A summary of recent soil analytical data is provided as Attachment B. A photoionization detector (PID) spike was recorded in the following borings, all located in the northern portion of the site (Figure2);

- S-1 at 30 and 35 feet bgs (400 and 575 parts per million (ppm),
- B-3 at 30 feet bgs (536 ppm)
- B-5 at 35 feet bgs (887 ppm),
- SB-4 at 35 feet bgs (650 ppm),
- SB-5 at 35 feet bgs (650 ppm)
- MW-4 at 34 to 44 feet bgs (106 to 762 ppm)

The ability to remove these narrow bands of contaminants is uncertain based on groundwater tests which indicated fine-grained soils. No such spikes were recorded for borings MW-3, SB-3 and B-1 located in the

central and southern portion of the site. However, the deepest PID reading in these three borings was at 30 feet bgs.

Analytical results indicate total petroleum hydrocarbons as gasoline (TPH-g), MTBE, and TBA are concentrated in shallow groundwater in the area of wells MW-1, MW-2 and MW-4 in the northern portion of the site (Figure 2). The maximum detected concentration of total petroleum hydrocarbons as gasoline (TPH-g) in groundwater have occurred in wells MW-1, MW-2 and MW-4. The highest concentrations of TPH-g and MTBE in groundwater are currently detected in well MW-4 at 8,200 micro grams per liter (ug/l) and 11,000 ug/l (June 2007). Analyses for the presence of TBA was not performed in groundwater samples from well MW-4. The highest detected current concentration of TBA in groundwater is 1,500 ug/l in well MW-1.

Analytical results indicate that MTBE and TBA have been detected at various depths. MTBE and TBA were detected in deep well MW-1B at 35 ug/l and 7.11 ug/l in the August 22, 2007 sampling.

INTERIM REMEDIAL ACTION WORKPLAN

DELTA/SHELL'S first priority was to reduce off-site migration of contaminants. Approximately 7,000 gallons of groundwater were extracted during activities in 2007. Groundwater extraction was also prompted in an attempt to reverse downward migration of contaminants towards the deeper aquifer. The ACHCSA in their letter dated December 12, 2007 concluded "...no further temporary groundwater extraction is requested at this site."

Based on elevated dissolved TPH-g and MTBE concentrations present in the vicinity of groundwater monitoring well MW-4, Delta recommends the performance of a Dual Phase Extraction (DPE) test. Specifically, Delta recommends a 5 day DPE Feasibility Study for the purpose of evaluating this technique for source area mitigation. The feasibility is assessed by estimating influent hydrocarbon concentration, hydrocarbon mass recovery rates, soil vapor radius of influence (ROI), and groundwater production rates.

Approximately one week after the DPE is completed groundwater extraction will be conducted at MW-1 to address off-site migration. Extraction will be continued until 20,000 gallons of groundwater have been extracted.

The following sections detail the proposed extraction activities.

Chemicals of Concern

TPH-g, MTBE, and TBA are the chemicals of concern in groundwater based on analytical results from previous and ongoing quarterly groundwater monitoring and sampling.

Pre-field Activities

DELTA will prepare a site-specific Health and Safety Plan, which will be reviewed daily by all field personnel. Prior to initiation of field activities, Calclean (or another contractor) and DELTA will notify the Bay Area Air Quality Management District (BAAQMD) of the upcoming event. DELTA and Calclean field personnel will oversee the operations of the 450-CFM system under permit. DELTA will obtain a temporary water storage tank and will extract a maximum of 10,000 gallons of groundwater during the event.

DPE Event

Delta proposes a 5-day High Vacuum DPE Test be conducted by extracting from well MW-4 which contains the highest detected concentration of contaminants. Well MW-4 is 47 feet deep and screened from 37 to 47 feet bgs.

The well casing is four inch diameter, schedule 40 PVC. Groundwater will be lowered by extracting groundwater to expose the well screens. Once the well screen is exposed, soil vapor will be extracted from the well by applying a high vacuum, up to 29 inches of mercury, to the well using a 25-horsepower, liquid ring pump.

Inlet flow rates, applied vacuums, induced vacuums, and inlet hydrocarbon concentrations will be measured at approximately 15-minute intervals for the first 2 hours, at 1 hour intervals during the third hour, at 2-hour intervals from the third hour to the twelfth hour, and at 4 hour intervals up until the 5th day. Vapor concentration will be measured using a Horiba MEXA 324JU, capable of analyzing petroleum hydrocarbons vapors up to 10,000 parts per million by volume (ppmv). Induced vacuums will be measured with vacuum gauges placed on wells MW-1, MW-2, MW-3 in order to monitor the negative pressure gradient induced by DPE. Induced vacuum will be measured hourly.

Using Tedlar bags, vapor samples will be collected from the DPE system influent vapor stream at the start, mid, and end of activities. Influent samples will be collected by the subcontractor and DELTA personnel throughout the test from wells MW-1 and MW-4, separately, and simultaneously. Vapor samples will be analyzed for TPH-g, benzene, toluene, ethybenzene and total xylenes (BTEX), TBA, and MTBE using USEPA Method TO-14. Both the vapor and groundwater samples will be logged on chain-of-custody forms, and submitted to Cal-Science Laboratories, Inc. for analysis. Pre and post groundwater samples will be collected and analyzed for TPH-g; BTEX compounds; MTBE; 1, 2 dichloroethane (1,2 DCA); tert-amyl methyl ether (TAME); TBA, diisoproply ether (DIPE); 1,2-dibromoethane (EDB); ethyl tert-butyl ether (ETBE) and ethanol by USEPA Method 8260B.

Feasibility and Corrective Action Plan Report

Delta will prepare a *Feasibility Testing Results Report* that details the results of the high vacuum, dual phase extraction (HVDPE) tests. The results of the study will be used to evaluate long-term remedial options at the Site.

Possible remedial options for this site consist of one of the following:

- 1) a monitoring and natural attenuation program if dissolved concentrations are reduced to within Agency-acceptable limits,
- 2) a series of short-term remediation events if dissolved concentrations are reduced by 25% or more at the conclusion of this pilot study, or
- 3) full remediation if hydrocarbon concentrations in soil and/or groundwater remain recalcitrant.

Batch Extraction


Approximately one week following completion of the DPE test a batch extraction will be conducted at MW-1 to reduce off-site migration. Water will be pumped into an onsite storage tank until 20,000 gallons have been removed. The groundwater will be disposed by Shell. The system will be visited on a weekly basis to monitor system operation. Monitoring wells MW-1, MW-2 and MW-4 will be sampled on a monthly basis (scheduling to not duplicate quarterly monitoring sampling) with sample analyses for TPHg, BTEX, MTBE and TBA to monitor concentrations.

Please call Richard Garlow (DELTA) (408) 826-1880 or Denis Brown (SHELL) at (707) 865-0251, if you have any questions regarding the contents of this report.

Sincerely,

Delta Consultants, Inc.

Richard A. Garlow, M.S., P.G. Project Manager



Attachments:

Figure 1 – Site Location Map


Figure 2 - Site Map


Figure 3 – Geologic Cross Section

Attachment A - Boring Logs

Attachment B - Soil analytical Data

cc: Denis Brown, Shell Oil Products US, Carson and Monte Rio, CA





MW-2 • GROUNDWATER MONITORING WELL LOCATION

S-1 X DESTROYED WELL

TB-1 Ø <u>ABANDONED TANK BACKFILL</u> <u>WELL LOCATION</u>

B-3 • SOIL BORING LOCATION

A----A' CROSS SECTION DIRECTION

FIGURE 2 SITE MAP

SHELL-BRANDED SERVICE STATION 4226 First Street Pleasanton, California


PROJECT NO.	ORAWN BY
SJ422-6F1-X	AD 6/15/07
FILE NO.	PREPARED BY
SJ422-6F1-X	AD
REVISION NO.	REVIEWED BY



APPROX. SCALE

40 FT

BaseMap from: Cambria Environmental Technology, Inc. and Toxichem Management Systems, Inc.



ATTACHMENT A

BORING LOGS



WELL LOG (TPH-G) G:PLE4226/GINT/PLE4226.GPJ DEFAULT GDT 8/11/99

Cambria Environmental Technology, Inc. 1144 - 65th St. Oakland, CA 94608 Telephone: (510) 420-0700 Fax: (510) 420-9170

BORING/WELL LOG

	NT NA			guiva	Services	LLC		BORING/WELL NAME	MW-1		· · · · · · · · · · · · · · · · · · ·					
	SITE N	AME		le-422				DRILLING STARTED 08-Apr-99								
	ATION					t, Pleas	anton, California	DRILLING COMPLETED	<u>09-Apr-99</u>							
DRILL		IUMBEF		41-039							····		_			
		IETHOD			Orilling			GROUND SURFACE ELE	-		83 ft					
		METER	. <u></u> ₹ 8	ıı					***************************************				_			
	ED BY			. Jakul	_											
REVIE	WED	BY		***************************************												
REMA	RKS		Н	and au				entrance to Shell station on	-				=			
						7					<u> </u>		_			
TPHg (mg/kg)	BLOW COUNTS	RECOVERY	SAMPLE ID	EXTENT	(# bgs) U.S.C.S.	GRAPHIC LOG	LITHO	LOGIC DESCRIPTION		CONTACT DEPTH (ft bgs)	w	ELL DIAGRAM				
			-									D				
			;	I -	4		ASPHALT. FILL.			0.3 1.5		8				
			1	 	-	TYYY	Sandy SILT; (ML); bro	own (10YR4/3); very soft; we	et; 5%	1.5						
		l	ł	11-	ML		clay, 70% silt, 25% fin	ne to medium grained sand; low estimated permeability	low '.							
	- 1	İ	Í	{ }	-		•	,		4.5		×				
				5			SILT; (ML); dark yellor 5% clay, 85% silt, 8% plasticity; low estimate	w brown (10YR4/6); stiff; mo sand, 2% fine grained grave ed permeability.	oist; el; low							
				<u> </u> -	ML					9.7		≺ Portland Type				
				10	ML		38% clay, 50% silt, 2%	low brown (10YR5/8); stiff; of time grained sand, 10% fine grained sand, 10% fine vel; high plasticity; low esting	damp; e to							
<1.0	18 26 30		SB-6	15	-		Clayey Gravelly SAND:	(SP); dark greenish gray		15.0						
		"	15.5	- - -	SP		(5GY4/1); dense; damp medium plasticity; low t permeability; wood frag	o; 20% clay, 50% sand, 30% to moderate estimated	gravel;							
<1.0	13	S - 1	B-6 19.5	-20-	- ML		damp; 15% clay, 50% s	(ML); olive (5Y4/3); very stiff ilt, 35% very fine grained sa ow estimated permeability.	f:	9.3						
:1.0	20 28 30	SI	3-6	- 25			Gravelly SAND with Silt	;; (SP); olive (5Y4/3); dense;	. – – 1	4.5		≺ 2" diam., Schedule 40 PVC				
			5.0		SP		damp; 5% clay, 15% silt sand, 20% gravel; no pla estimated permeability.	, 60% fine to medium graine asticity; high to moderate								
	40 43 45	SB - 30		 -30- 	l P	000	2% clay, 13% siit, 35% n	live (5Y4/3); very dense; da nedium grained sand (red gr ngular to subrounded grave n estimated permeability.	mp; rains),	9.0						
	20 35			-35-		ζď	Clayey Gravelly SAND; (SP); dark yellow brown	34	.0		◆ Bentonite Seal				
		<u>'</u>		l			Continu	ied Next Page			l_	PAGE 1 OF 2				



Cambria Environmental Technology, Inc. 1144 - 65th St. Oakland, CA 94608 Telephone: (510) 420-0700 Fax: (510) 420-9170

BORING/WELL LOG

CLIENT NAME JOB/SITE NAME

Equiva Services LLC BORING/WELL NAME MW-1 ple-4226 **DRILLING STARTED** 08-Apr-99

LOCATION 4226 First Street, Pleasanton, California DRILLING COMPLETED ___09-Apr-99 Continued from Previous Page CONTACT DEPTH (ft bgs) TPHg (mg/kg) GRAPHIC LOG BLOW COUNTS RECOVER EXTENT DEPTH (ft bgs) U.S.C.S. SAMPLE LITHOLOGIC DESCRIPTION WELL DIAGRAM <1.0 (10YR4/6); very dense; damp; 20% clay, 10% silt, 40% medium grained sand, 30% fine to coarse grained gravel SB-6 - 35.0 Monterey (sandstone/claystone, serpentinite, some MnO₂/Fe Sand #3 staining); low plasticity; moderate to low estimated permeability. 45 50/4 <1.0 SB-6 - 40.0 SP $\bar{\Delta}$ @ 44' - moist to wet. 45 45 2"-diam., 0.020" Slotted Schedule 40 PVC 50.0 Clayey GRAVEL with Silt; (GC); dark yellow brown (10YR4/6); very dense; moist to wet; 25% clay, 15% silt, 60/6 20% fine to coarse grained sand, 40% fine to coarse grained gravel. GC 55.2 15 Clayey SILT; (MH); light olive brown (2.5Y5/4); hard; damp; 25% clay, 75% silt; medium to high plasticity; very low estimated permeability; black MnO₂ blebs throughout. 40 MH 58.0 Bottom of Boring @ 58 ft

WELL LOG (TPH-G) GAPLE4226/GINTPLE4226.GPJ DEFAULT.GDT 8/11/99

BORING/WELL LOG



Cambria Environmental Technology, Inc. 1144 - 65th St. Oakland, CA 94608 Telephone: (510) 420-0700 Fax: (510) 420-9170

JOB/ LOC/ PROD DRIL DRIL BORI LOGG REVII REM/	INT NA VISITE N ATION JECT N LER LING N ING DIA GED B' EWED ARKS	IAME IUMB METHO AMET Y	 DD ER	ple- 422 241 Gre- Holl 8" B. J. B. J.	4226 6 First -0395 gg Dril ow-ste akub	ling m auge	Pleas	anton, California	BORING/WELL NAME DRILLING STARTED DRILLING COMPLETED WELL DEVELOPMENT DO GROUND SURFACE ELECTOP OF CASING ELEVAT SCREENED INTERVAL DEPTH TO WATER (First DEPTH TO WATER (Static exit near planter.	ATE (YIELD) VATION ION <u>Not S</u> NA Encountere	9 NA Not Surveyed Surveyed ed) NA 42.50ft (08-Apr-99)						
TPHg (mg/kg)	BLOW	RECOVERY	SAMPLEID	EXTENT	DEPTH (ft bgs)	U.S.C.S.	GRAPHIC	LITHOL	OGIC DESCRIPTION		CONTACT DEPTH (ft bgs)	WELL DIAGRA	λM				
	11 12 19			XXX	5 -	ML		clay, 70% silt, 25% fine plasticity; moderate to SILT: (ML); dark yellow	wn (10YR4/3); very soft; we to medium grained sand; low estimated permeability brown (10YR4/6); stiff; me sand, 2% fine grained graved permeability.	low /. olst;	0.3						
<1.0	15 25 31 18 26 35		\$B-7			ML		38% clay, 50% silt, 2% coarse subangular grav permeability. @ 14.3 - ofive brown (2)	ow brown (10YR5/8); stiff; fine grained sand, 10% fin rel; high plasticity; low estin plasticity; low estin .5Y4/4) mottled with olive; prained gravel; medium pla	e to nated 20%	9.7						
<1.0	11 22 25		SB-7		-20-	GP p		Gravelly SAND with Sill dense; damp; 3% clay, grained sand, 20% fine plasticity; high estimated Clayey Sandy GRAVEL; 20% clay. 20% fine to co	; (SP); olive gray (SY4/2); 15% silt, 62% fine to coars to coarse grained gravel; n	o 5/6); ne to	19.5 20.3						
<1.0	20 20 20		SB-7 - 24.5		-25-	SP :	> 0)	medium plasticity; low to permeability. Gravelly SAND with Silt; dense; damp; 3% clay, 1 sand, 25% fine grained gestimated permeability. Clayey SILT; (ML); stiff; dense control of the sand statement of the sand stateme	moderate estimated (SP); yellow brown (10YR 5% silt, 52% medium grain gravel; no plasticity; high damp; 30% clay, 60% silt,	(5/6); ned	24.3 25.3 4						
:1.0	35 36 40		SB-7 - 29.3		30-	GP. 0		fine grained sand; high p permeability; trace carbo Sandy GRAVEL with Cla (5Y3/2); 15% clay, 5% sil sand, 45% fine to coarse	lasticity; low estimated	ed w	29.0						
	19 20				1	. 60) d	Clayey GRAVEL with Slit	; (GC); yellow brown		34.0						

Continued Next Page



WELL LOG (TPH-G) G.PLE4226/GINTPLE4226.GPJ DEFAULT GOT

Cambria Environmental Technology, Inc. 1144 - 65th St.

BORING/WELL LOG

Oakland, CA 94608 Telephone: (510) 420-0700 Fax: (510) 420-9170

CLIENT NAME	Equiva Services LLC	BORING/WELL NAME	SB-7
JOB/SITE NAME	ple-4226	DRILLING STARTED	07-Арг-99
LOCATION	4226 First Street, Pleasanton, California	DRILLING COMPLETED	07-Apr-99

Continued from Previous Page CONTACT DEPTH (ft bgs) TPHg (mg/kg) RECOVERY GRAPHIC LOG BLOW COUNTS EXTENT U.S.C.S. DEPTH (ft bgs) SAMPLE WELL DIAGRAM LITHOLOGIC DESCRIPTION (10YR5/8); very dense; damp; 35% clay, 15% silt, 10% SB-7 sand, 40% fine to coarse grained gravel (quartz); medium 34.3 plasticity; moderate to low estimated permeability. @ 39' - quartz, siltstone, chert gravels. SB-7 <1.0 - 40.0 GC Ţ @ 44' - moist to wet. 40 50/3 83 SB-7 44.5 Clayey GRAVEL; (GC); yellow brown (10YR5/4); very dense; moist to wet; 20% clay, 10% silt, 10% medium to coarse grained sand, 60% fine grained gravel; medium ▼ Portland Type <1.0 SB-7 -49.5 1/11 plasticity; low to moderate estimated permeability. GC 30 50/3 SB-7 <1.0 - 54.3 Clavey SILT; (MH); mottled yellow brown (10YR4/6) and light brownish gray (2.5Y6/2); hard; dry; 20% clay, 70% silt, 10% very fine to fine grained sand; medium plasticity; SB-7 <1.0 - 59.5 low estimated permeability. ΜН @ 64' - dark brown MnO2 or organic blebs throughout. <1.0 SB-7 - 64.5 69.0 Clayey SILT; (MH); light olive brown (2.5Y5/4); hard; dry; 25% clay, 75% silt; medium plasticity; very low estimated permeability. SB-7 - 69.5 74.5 @ 74' - increasing mottled with yellow brown (10YR5/8)...

Continued Next Page

BORING/WELL LOG




Cambria Environmental Technology, Inc. 1144 - 65th St. Oakland, CA 94608 Telephone: (510) 420-0700 Fax: (510) 420-9170

CLIENT NAME	Equiva Services LLC
JOB/SITE NAME	ple-4226

SB-7 BORING/WELL NAME DRILLING STARTED 07-Apr-99 DRILLING COMPLETED 07-Apr-99

4226 First Street, Pleasanton, California LOCATION Continued from Previous Page CONTACT DEPTH (ft bgs) TPHg (mg/kg) GRAPHIC LOG BLOW COUNTS RECOVERY SAMPLE U.S.C.S. EXTENT DEPTH (ft bgs) WELL DIAGRAM LITHOLOGIC DESCRIPTION @ 74' to 74.5' - black blebs, possibly MnO2. SB-7 - 74.5 30 50/2 SB-7 - 79.5 × MH @ 84' - dark yellow brown (10YR4/6); damp; 30% clay, SB-7 70% silt. - 85.0 46 50 @ 94' - MnO, blebs throughout; becomes siltier. SB-7 95 - 94.5 99.0 Clayey SAND with Gravel; (SC); dark yellow brown (10YR4/6); dense; damp; 30% clay, 5% silt, 50% fine to coarse grained sand, 15% fine grained gravel (quartz); SB-7 SC 100.0 50/3 Bottom of 100.0 Boring @ 100 ft GAPLE4226/GINTAPLE4226.GPJ DEFAULT.GDT 8/11/99 medium plasticity; low to moderate estimated \permeability. Ground water sample (SB-7-GW) collected.

Geologic Log




- 1. Refer to Figure A-1 for explanation of descriptions and symbols.
- 2. Soil descriptions and stratum lines are interpretive and actual changes may be gradual.
 3. Perched water encountered at 49.5 feet BGS.



HARTCROWSER

12/90 J-6006 Figure A-3 Page 1 of 3

Geologic Log



- 1. Refer to Figure A-1 for explanation of descriptions and symbols.
- 2. Soil descriptions and stratum lines are interpretive and actual changes may be gradual.


 3. Perched water encountered at 49.5 feet BGS



HARTCROWSER

12/90 J-6006 Figure A-3 Page 2 of 3

Geologic Log



- Refer to Figure A-1 for explanation of descriptions and symbols.
- Soil descriptions and stratum lines are interpretive and actual changes may be gradual.
 Perched water encountered at 49.5 feet.



HARTCROWSER


J-6006 12/90 Figure A-3 Page 3 of 3

2. Soil description and stratum lines are interpretive

and actual changes may be gradual.

3. No free water encountered.


Geologic Log



HARTCROWSER

J-6006 Figure A-2 Page 1 of 3

Geologic Log




- Refer to Figure A-1 for explanation of descriptions and symbols.
- Soil description and stratum lines are interpretive and actual changes may be gradual.
- 3. No free water encountered.



J-6006 Figure A-2 4/90

Page 2 of 3

Geologic Log



^{1.} Refer to Figure A-1 for explanation of descriptions and symbols.



Figure A-2

Page 3 of 3

^{2.} Soil description and stratum lines are interpretive and actual changes may be gradual.

3. No free water encountered.

1. Refer to Figure A-1 for explanation of descriptions


2. Soil description and stratum lines are interpretive

and actual changes may be gradual.

3. No free water encountered.

and symbols.


Geologic Log



HARTCROWSER

J-6006 Figure A-3 Page 1 of 2

Geologic Log



- 1. Refer to Figure A-1 for explanation of descriptions and symbols.
- 2. Soil description and stratum lines are interpretive and actual changes may be gradual.


 3. No free water encountered.



Figure A-3

Page 2 of 2

Geologic Log



- Refer to Figure A-1 for explanation of descriptions and symbols.
- Soil description and stratum lines are interpretive and actual changes may be gradual.
- 3. No free water encountered.



HARTCROWSER


J-6006

3/90

Figure A-4

Page 1 of 2

Geologic Log



- 1. Refer to Figure A-1 for explanation of descriptions
- and symbols.Soil description and stratum lines are interpretive and actual changes may be gradual.No free water encountered.




J-6006

Figure A-4

Page 2 of 2


Boring Log WA-1

Geologic Log



1. Refer to Figure A-1 for explanation of descriptions and symbols.

Soil description and stratum lines are interpretive and actual changes may be gradual.
 No free water encountered.



J-6006


4/90

Figure A-5

Page 1 of 3

Boring Log WA-1

Geologic Log



- 1. Hefer to Figure A-1 for explanation of descriptions and symbols.
- Soil description and stratum lines are interpretive and actual changes may be gradual.
- 3. No free water encountered,



J-6006


4/90

Figure A-5

Page 2 of 3

Boring Log WA-1

Geologic Log



Refer to Figure A-1 for explanation of descriptions and symbols.

3. No free water encountered.

HARTCROWSER
J-6006 4/90

Figure A-5 Page 3 of 3

Soil description and stratum lines are interpretive and actual changes may be gradual.

	···	••••	Project N		SJ42-26					Shell Oil Products	US	Well No: MW-1B				
			Logged E	Зу:	AP			Locat	ion:	4226 First Street		Page 1 of 6				
	_ 1.1	L	Driller:		Gregg			Date	Drilled:	8/23/2006	Location Map					
De	[اچ	[2	Drilling N	/lethod:	HSA/AK	(7')		Hole	Diamete	r: 12"						
			t .		SS			Hole	Depth:	108'	Please se	ee site map				
Envir	onme	ntal	Casing T		sch 40 F	PVC		Well	Diamete	r: 4 "						
Consu			Slot Size		0.01			Well	Depth:	108'						
1		,	Gravel P		#2/12 sa	ınd			ng Sticku	ıp: -						
				Elevation			Nort			Easting	Easting					
Well Com	pletion	Static	e #	Jing -	Lion (*C	(g	, , , , , , , , , , , , , , , , , , ,									
Backfill Casing		Water Level	Moisture Content	PID Reading (ppm)	Penetration (blows/6")	Depth (feet)	Recovery	/ DESCRIPTION								
					↑	_			AF	~4" asphalt, ~8" base	rock					
						1		<u> </u>				/ II				
						-		<u> </u>		See Cambria's MW-1						
						2—				lithology between 1 a	nd 58.5 fee	et pg				
					ַ קַ	-	_					. ALLEGORIO TOTO TO				
					air knifed & hand augered	3—				1		- 110777				
					nife aug	-	_					, Company				
					I Z B	4	+					A CONTINUE C				
					a E	<u>-</u> -										
						5—	1					AAAAMMITTI .				
						6—										
						"-										
					↓	7—										
	_					-	4									
						8—	+	<u> </u>			<i>m</i> -					
						-	- -				· ·	- barrer				
						9	+									
						-	+									
						10 —	1		1							
						11—										
			1			' ' -										
						12						AAMMAMATTI .				
						'										
						13		<u> </u>								
						-	-	<u> </u>	ł	ARABAY II		A STATE AND ADDRESS OF THE STATE AND ADDRESS O				
						14 —	+		-			I MANY				
						-	-	ļ	1							
						15			1			AND LOOP DATE OF THE STATE OF T				
						-	+		1							
						16 —	1		1			ALIMATER .				
						17—]							
						'' -						ALLEGORY .				
						18										
						-	_					COMPANY .				
						19—	_	ļ								
						ļ <u>.</u>	-	1	-							
******						20		<u> </u>								

**

Delta Environmental Consultants, Inc. Well Completion Static Water	Project No: Logged By: Driller: Drilling Method: Sampling Method Casing Type: Slot Size: Gravel Pack: Elevatio (bud) (bud)	sch 40 PV 0.01 #2/12 san	Lo Da 7') Ho Ho /C W W	e e	Shell Oil Products 4226 First Street 8/23/2006 12" 108' 4" 108' - Easting	Location Map Please se	Well No: MW-1B Page 2 of 6 e site map DESCRIPTION
Backfill Backfi			21				

¥

	Drainet No:	SJ42-26	25 1		Clien	.	Shell Oil Product	s I IS	Well No: MW-1B
	Project No: Logged By:	SJ42-20 AP)1^- I		Local		4226 First Street		Page 3 of 6
P - 11 -	Driller:	Gregg				Drilled:	8/23/2006	Location Map	
Delta	Drilling Method:	HSA/AK	(7')		Hole	Diamete	r: 12"		
Dona	Sampling Metho	l: SS			Hole	Depth:	108'	Please s	ee site map
Environmental	Casing Type:	sch 40 l	PVC			Diamete	т: 4"		
	Slot Size:	0.01				Depth:	108'		
	Gravel Pack:	#2/12 s		N. (1.		ng Sticku			
	Elevati	on		North	iing		Easting		
Well	m	Τ_							
Completion Static	ure sint	ation ("%)	feet		nple	уре			
₩ater	Moisture Content PID Reading	Penetration (blows/6")	Depth (feet)	Recovery	Interval	Soil Type	LI	THOLOGY	/ / DESCRIPTION
Casing Mater Casing Casing	Σο E	P. E.	Det	Şeco	Inte	Š			
****				Щ.				Section 6-17-44-17	
			41						
			42						
			43						
			44						
			45—						
			46 —						
			-						
			47 —						
			10 -						
			48						
			49 —						
			50 —						
			l						
			51 —						
			52 —						
			53 —	<u> </u>					
			_						
			54						
			-						
			55						
			56—						
			-						
 			57—						
			-		 				
			58						
		14			A	ML	SILT: mottled yellow	brown and	d orangish brown, hard,
	dry 8.1	16	59 —			j	80-90% fines, <10%		
		21	60		¥	<u> </u>	low plasticity		

.

Delta Environmental Consultants, Inc.	Environmental Casing Type: Slot Size: Gravel Pack:]]] ,	Hole I Hole I Well I Well I Casin		108' er: 4" 108'	Location Map	Well No: MW-1B Page 4 of 6 ee site map			
Well Completion Static Static Water Completion Static Completion Static Completion Static Completion Static Completion Static Completion Static	Completion Static g to g c				Recovery 60 Interval ald Soil Type			Lľ	LITHOLOGY / DESCRIPTION				
	dry	10.9	10 12 14 11 16 18	61—62—63—64—65—66—67—68—67—67—67—67—72—73—74—75—75—77—78—78—			ML	SILT (cont.)	2 < 10% vo	ry fine grained sands			
	dry	9.1	11 13 16	79— 80		A		(80-90% fines medium plas		ry fine grained sands,			

De Envir Consu	onme	ntal	Project N Logged E Driller: Drilling M Sampling Casing T Slot Size Gravel P	dethod: j Method: ype: ack: Elevation	SJ42-26 AP Gregg HSA/AK SS sch 40 F 0.01 #2/12 sa	(7') PVC	North	Hole Hole Well Well Casir	lion: Drilled: Diamete Depth: Diamete Depth: ng StickL	eter: 12" : 108' Please see site map eter: 4" : 108'			
Backfill Casing aldwoo	tion	Static Water Level	Moisture Content	PID Reading (ppm)	Penetration (blows/6")	Depth (feet)	Recovery g	Interval aldu	Soil Type	LITHOLOGY / DESCRIPTION			
		•	dry	9.9	10 14 18 10 16 21	81 — 82 — 83 — 84 — 85 — 86 — 87 — 91 — 92 — 93 — 95 — 95 — 96 — 97 — 98 — 60		A V V V V V V V V V V	ML SC	hard, 70-80% fines, low to no plasticity (15-25% very	fine grained		
Sand		∇	wet	8.1	16 20	99 – 100				20-30% gravels up t	o 1" diamet	er, 60-70% medium to	

.

	·												
	Project I		SJ42-26	F-1		Clien		Shell Oil Product	US	Well No: MW-1B			
	Logged	Ву:	AP			Loca		4226 First Street		Page 6 of 6			
Delta	Driller:	اد - ما فعداد ا	Gregg	(7t)			Drilled:	8/23/2006	Location Map				
Della	Drilling N		HSA/AK SS	. (7)			Diamete		Diego es	e site map			
Environmental	Casing 1	g Method:	sch 40 F	N/C			Depth: Diamete	108' r: 4"	Flease se	ee site map			
Consultants, Inc.	Slot Size		0.01	VC			Depth:	108'					
Consultants, Inc.	Gravel F		#2/12 sa	and			ng Sticku		-				
		Elevation		<u> </u>	North		3	Easting	1				
				•				-					
Well Completion Statio		Бu	E	£	Sai	mple	4)						
Static	Moisture Content	PID Reading (ppm)	Penetration (blows/6")	Depth (feet)			Soil Type		THOLOGY	DESCRIPTION			
Dackfill Casing Cash	Aois Con	Kg g	low suct	l fg.	§	Interval	Jio	L	INOLOGI	DESCRIPTION			
Ca Ba		🛣	4 c	ا ۵	Recovery	Ĭ	0,						
				_			SC	Clayey SAND with	Gravel (cont	i.)			
				101									
				_									
				102 —	 -								
				103—									
					ennoneral			(00.100/.6	10.0007.5				
Sand —		^-	13	104		$\vdash \uparrow$		(30-40% fines	, 40-60% fir	e to coarse graines sands,			
	wet	0.7	17 19	_	58	╙		10-20% grave	is up to 1" 0	iameter)			
			19	105 —	 	.							
				400	1								
				106—						11. 11. 11. 11. 11.			
			13	107					, 55-65% sa	ind, 10-20% gravels up to			
	wet	0.8	17 20	_		Щ.		2" diameter)					
			20	108 —		▼		Bottom of boring at	08 feet ba				
				-	-			Dottom of Somig ac	00 1001 09				
				109									
				110-									
				-	-								
				111 —	-			***************************************					
				_	-								
				112	+-								
				113 <i>—</i>									
				-									
				114									
				_	₩								
				115	 								
				110 -									
				116—									
				117 —									
					<u> </u>	<u> </u>							
				118	-								
				119									
				120	1								

.

BORING/WELL LOG

PAGE 1 OF 2



Cambria Environmental Technology, Inc. 1144 - 65th St. Oakland, CA 94608 Telephone: (510) 420-0700 Fax: (510) 420-9170

-35-

CLIENT I JOB/SIT LOCATIO PROJEC DRILLEF DRILLIN BORING LOGGEI REVIEW REMARK	E NAM ON IT NUM R G MET DIAME D BY ED BY	E SI 42 BER 24 GI HOD HO ETER 8" B.	nell-bran 26 Firs 1-0395 regg Dri bllow-st Jakub Bork, F	lling em auger RG# 5620	ice sta	nton, California	BORING/WELL NAME DRILLING STARTED DRILLING COMPLETED WELL DEVELOPMENT DA GROUND SURFACE ELEV TOP OF CASING ELEVAT SCREENED INTERVAL DEPTH TO WATER (First DEPTH TO WATER (Statio	ATE (YIELD) /ATION ION <u>372.40 t</u> 26 to 46 Encountered)	372.6 ft above ft bgs 33 NA	5 ft above e msl .0 ft (18-J	e msl		
TPHg (ppm)	BLOW COUNTS	SAMPLEID	EXTENT	(# bgs) U.S.C.S.	GRAPHIC LOG	LITHO	LOGIC DESCRIPTION		CONTACT DEPTH (ft bgs)	WE	ELL DIAGRAM		
<1.0		MW-2-6.3'	5	ML SM SM SM		80% silt, 15% fine gralow to moderate estin low to moderate estin Silty SAND; (SM); ye 43% silt, 50% sand, 8 estimated permeability. 50% silt, 2% fine gral subangular gravel; hi permeability. Silty SAND; (SM); ye 40% silt, 50% sand, 8 estimated permeability. Clayey Silty SAND; (SM); ye 40% silt, 50% sand, 8 estimated permeability SAND; (SM); ye 40% silt, 50% sand, 8 estimated silt silt silt silt silt silt silt silt	ellow brown; stiff; damp; 38 ined sand, 10% fine to coar: gh plasticity; low estimated llow brown; dense; damp; 23% gravel; no plasticity; high ty, SM); yellow brown; stiff; dar 0% sand, 5% gravel; low plasticity; high ty, llow brown; dense; damp; 2 gravel; no plasticity; high ty.	plasticity; ee roots. clay, oderate % clay, se, // clay, h mp; asticity; // clay, h	0.5 4.0 5.8 6.6 10.0 11.0		∛) So	dlam., hedule 40 /C	
<1.0		MW-2-16.5'	-18	SM		moderate estimated Clayey Sil.T; (ML); ye clay, 80% slit, 3% sa estimated permeabili Gravelly Silty SAND; clay, 25% slit, 45% fi gravel to 3/4"; high estimated silty SAND; (clay, 25% silt, 50% s	permeability. bilowish brown; stiff; damp; nd, 2% gravel; medium plas ty. (SM); yellow brown; damp; ne to coarse grained sand, stimated permeability. SM); yellow brown; damp; 1 and, 10% fine gravel.	15% sticity; low 5% 25%	16.5 18.2 22.0		1/11		
<1.0		MW-2-26.0'		GM SM		clay, 30% silt, 20% s to 2".	; (GM); yellow brown; damp and, 40% fine to coarse gra (SM); very dense; damp; 5 25% gravel; no to low plasti imated permeability.	wel; chert	26.0 30.0			entonite Seal onestar Sand	
<1.0	35 50/8 38 50/8 45 50/8	MW-2-30.5'	30	GM		very dense; damp; 1 fine to coarse gravel; permeability. @ 31.7' - color chang	RAVEL; (GM); dark yellow 5% clay, 15% silt, 20% sand; low plasticity; moderate es ge to dark greenish gray; chel; (GC); very dense; wet to 15% silt, 20% sand, 40% g	d, 50% stimated sert to 2". $\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \$	33.5				

Continued Next Page





Cambria Environmental Technology, Inc. 1144 - 65th St. Oakland, CA 94608

Telephone: (510) 420-0700 Fax: (510) 420-9170

CLIENT NAME JOB/SITE NAME Equiva Services LLC Shell-branded service station **BORING/WELL NAME DRILLING STARTED**


MW-2 18-Jan-00

4226 First Street, Pleasanton, California

DRILLING COMPLETED

19-Jan-00

LOCATION Continued from Previous Page CONTACT DEPTH (ft bgs) TPHg (ppm) SAMPLE ID GRAPHIC LOG BLOW DEPTH (ft bgs) U.S.C.S. EXTENT WELL DIAGRAM LITHOLOGIC DESCRIPTION MW-2-35.0' <1.0 Sandy Clayey GRAVEL; (GC); very dense; wet to 4"-diam., saturated; 25% clay, 15% silt, 20% sand, 40% gravel. 0.020" Slotted 50/6 GC Schedule 40 PVC 35 50/6 50/6 40.3 Sandy Gravelly SiLT; (ML); hard; saturated; 12% clay, 58% silt, 15% sand, 15% gravel; medium plasticity; low estimated permeability. 37 50/6 ML 29 43.5 Sandy Clayey SILT; (ML); hard; saturated; 15% clay, 60% silt, 15% sand, 10% gravel. 50/6 ML 45.0 45 Sandy SILT; (ML); hard; saturated; 12% clay, 45% silt, 50/6 43% fine grained sand; slight plasticity; low estimated ML permeability. 12 19 48.0 27 Bottom of Boring @ 48 ft WELL LOG (SHELL) G:PLEASA-4/GINT/PLE4226.GPJ DEFAULT.GDT 6/23/00 PAGE 2 OF 2




1144 Oakl Teler

1144 - 65th St. Oakland, CA 94608 Telephone: (510) 420-0700

Telephone: (510) 420-0700 Fax: (510) 420-9170

BORING/WELL LOG

CLIENT NAME	Equiva Services LLC	BORING/WELL NAME MW-2
JOB/SITE NAME	Shell-branded service station	DRILLING STARTED18-Jan-00
LOCATION	4226 First Street, Pleasanton, California	DRILLING COMPLETED 19-Jan-00
PROJECT NUMBER	241-0395	WELL DEVELOPMENT DATE (YIELD) 03-Feb-00
DRILLER	Gregg Drilling	GROUND SURFACE ELEVATION 372.65 ft above msl
DRILLING METHOD	Hollow-stem auger	TOP OF CASING ELEVATION 372.40 ft above ms
BORING DIAMETER	8"	SCREENED INTERVAL 26 to 46 ft bgs
LOGGED BY	B. Jakub	DEPTH TO WATER (First Encountered) 33.0 ft (18-Jan-00)
REVIEWED BY	S. Bork, RG# 5620	DEPTH TO WATER (Static) NA
REMARKS	Hand augered to 5' bos.	



BORING/WELL LOG



Cambria Environmental Technology, Inc. 1144 - 65th St. Oakland, CA 94608 Telephone: (510) 420-0700 Fax: (510) 420-9170

4226 First Street, Pleasanton, California

CLIENT NAME
JOB/SITE NAME
LOCATION

Equiva Services LLC	BORING/WELL NAME	MW-2
Shell-branded service station	DRILLING STARTED	18-Jan-00
4226 First Street, Pleasanton, California	DRILLING COMPLETED	19-Jan-00


							Continued from Previous Page		-	
(mdd) 6HA1	BLOW	SAMPLEID	EXTENT	DEPTH (ft bgs)	U.S.C.S.	GRAPHIC	LITHOLOGIC DESCRIPTION	CONTACT DEPTH (ft bgs)	WEI	.L DIAGRAM
<1.0	50/6 40 50/6 35 50/6 50/6	MW-2-35.0'			GC		Sandy Clayey GRAVEL; (GC); very dense; wet to saturated; 25% clay, 15% silt, 20% sand, 40% gravel.	40.3		4"-diam., 0.020" Slotted Schedule 40 PVC
	37 50/6 29 50/8			- ·	ML		Sandy Gravelly SILT; (ML); hard; saturated; 12% clay, 58% silt, 15% sand, 15% gravel; medium plasticity; low estimated permeability.	43.5		
	27 50/6 26 50/6		MOXIMOX	 45 	ML ML		Sandy Clayey SILT; (ML); hard; saturated; 15% clay, 60% silt, 15% sand, 10% gravel. Sandy SILT; (ML); hard; saturated; 12% clay, 45% silt, 43% fine grained sand; slight plasticity; low estimated permeability.	45.0		
	19 27		X	- -		<u> </u>		48.0		Bottom of Boring @ 48 ft
antikanikanikanikanikanikanikanikanikanikan		- - -								
4										
0087/9 ds.										
OALUA CARANTA										
-4/6:N 1/V CB 4/2										
err) Gyrteasa										
WELL LOG (SHELL) G:Y-LEASA-4/GIN I-Y-LEAZZG:GFO DEFAULT.GD: 0										PAGE 2 OF 2

BORING/WELL LOG



Cambria Environmental Technology, Inc. 1144 - 65th St. Oakland, CA 94608 Telephone: (510) 420-0700 Fax: (510) 420-9170

BORING/WELL NAME **CLIENT NAME** Equiva Services LLC MW-3 **JOB/SITE NAME** Shell-branded service station DRILLING STARTED 18-Jan-00 DRILLING COMPLETED _ 19-Jan-00 4226 First Street, Pleasanton, California LOCATION WELL DEVELOPMENT DATE (YIELD) 03-Feb-00 **PROJECT NUMBER** 241-0395 DRILLER Gregg Drilling **GROUND SURFACE ELEVATION** 375.90 ft above msl DRILLING METHOD TOP OF CASING ELEVATION 375.05 ft above msl Hollow-stem auger BORING DIAMETER 8" SCREENED INTERVAL 20 to 35 ft bgs B. Jakub DEPTH TO WATER (First Encountered) 25.0 ft (18-Jan-00) LOGGED BY REVIEWED BY S. Bork, RG# 5620 **DEPTH TO WATER (Static)** NA



BORING/WELL LOG



WELL LOG (SHELL) G:PLEASA-4/GINTPLE4226.GPJ DEFAULT.GDT 6/23/00

Cambria Environmental Technology, Inc. 1144 - 65th St. Oakland, CA 94608 Telephone: (510) 420-0700 Fax: (510) 420-9170

CLIENT NAME	Equiva Services LLC	BORING/WELL NAME	MW-3
JOB/SITE NAME	Shell-branded service station	DRILLING STARTED	18-Jan-00
LOCATION	4226 First Street, Pleasanton, California	DRILLING COMPLETED	19-Jan-00

Continued from Previous Page CONTACT DEPTH (ft bgs) TPHg (ppm) SAMPLE ID GRAPHIC LOG BLOW EXTENT U.S.C.S. DEPTH (ft bgs) LITHOLOGIC DESCRIPTION WELL DIAGRAM SILT; (ML); light brown; hard; 10% clay, 80% silt, 10% sand; low plasticity; low estimated permeability. 36 48 ML Bentonite Seal 40.0 Clayey SILT; (ML); hard; 20% clay, 70% silt, 10% fine grained sand; medium plasticity; low estimated permeabillity. 25 42 ML 41.5 Bottom of Boring @ 41.5 ft


		<u></u>	Project No	o:	SJ42-26	F-1		Client		Shell Oil Products	US	Well No: MW-4
			Logged B		ΑP			Locati	lon:	4226 First Street		Page 1 of 3
		1	Driller:	-	Gregg			Date t	Drilled:	8/24/2006	Location Map	
D			Drilling M	ethod:	HSA/AK	(7')		Hole 1	Diameter	: 12"		
		LCI	Sampling		SS	. ,		Hole I	Depth:	50'	Please s	ee site map
Envir	ronme	ntal	Casing Ty		sch 40 F	VC			Diameter	: 4"		
Const			Slot Size:		0.01			Well	Depth:	47'		
Const	manta	, 1110.	Gravel Pa		#2/12 sa	nd			g Sticku	p: <u>-</u>		
				Elevation			Nort			Easting		
								 - 1			<u> </u>	
Vell Com	pletion	Static	e +	PID Reading (ppm)	Penetration (blows/6")	Depth (feet)		mple	<u>\$</u>			- · - · · - · · · · · · · · · · · · · ·
≡ g	,	Water	Moisture Content) Readi (ppm)	etra ws/	E E	Recovery	<u>a</u>	Soil Type	LI ⁻	THOLOGY	/ / DESCRIPTION
Casing Casing Casing Casing Casing Casing Casing Contel Co												
က် ပြ	,			<u>ቤ</u>	<u> </u>		<u>&</u>	=	AF	~4" asphalt, ~8" base	erock	
***	_				1				AF	~4 aspirait, ~6 base	BIOOK	ATT 1440
****						1-		1				
****							+	1				
					'	2-	 -	+				
****	-				a be		-	-			,	
****			1		ger	3-		1				
****					air knifed & hand augered		+	╁				
****					d r	4-	_ -	1				
*****	-				la ja	_	+	1				
****						5-	_	1				
	-					_	+	+				
						6-	_	┪				
****						_		-	ĺ		· · ·	
****					▼	7-		1				
₩								<u> </u>	1			
****					İ	8-		T	1			
*****					3			1	1	Clayey SAND with	Gravel : da	rk brown to orangish brow
*****			dry	0.1	4	9-			sc	loose, 60-70% fine t	o coarse g	rained sands, 20-30% fines
₩		i	"		5	10		1		10-20% gravels up t	o 1" diame	eter
****						10-			1			
****						144]			
*****					1	11-]			
****						10			` \.			
*****						12-] `` <u>`</u> ,			
*****	-					40			CL	Sandy Lean CLAY:	orangish b	orown, very stiff, 5-10%
 						13-]			15% fine grained sands,
*****	-		1		6	111		1		50-60% fines, low pl	lasticity	Anno Att and an an an an an an an an an an an an an
****			moist	7.4	8	14-						
*****	-				12	4.5		V				
*****						15-						
****	-					16-						
*****						10-]			ANTI-
*****	-					17-			`\.			
*****						' ' -						
****	-	1	[18-			sc			
*****	-	1				'0"						
******		İ			7	19-		1]	Clayey SAND: oran	gish browr	n, medium dense, 20-30%
*****		1	moist	2	11	ן יש –				fines, 70-80% fine g	rained san	ds, trace gravels up to 0.5
NXXXXX	1 -	1	1	1	11	20		J		diameter, low plastic	city	


Del Environm Consultant	ental	Project No Logged B Driller: Drilling M Sampling Casing Ty Slot Size: Gravel Pa	y: ethod: Method: ype: ack: Elevation	1	(7') VC und	North	Hole Hole Well Well Casir		50 ' r: 4" 47'	Location Map	Well No: MW-4 Page 2 of 3 ee site map
Cassing Casing	Static Water Level	Moisture Content	PID Reading (ppm)	Penetration (blows/6")	Depth (feet)	Recovery us S	Interval ਰ	Soil Type	LI* Clayey SAND (cont.)	THOLOGY	/ DESCRIPTION
		moist	7.2	6 8 9 11 13 17	21— 22— 23— 24— 25— 26— 27— 28— 29— 31— 32— 33—		*	SP-SC	5-15% fines, 85-95%	Gravel: bro	by: brown, medium dense, ed sands own, medium dense, 20-30% diameter, 50-70% fine to
	V	moist	340	10 16 20	34 -		1	CL	gravels up to 1" diar	neter, 20-3	I: brown, hard, 10-20% 0% fine grained sands enses), 50-70% fines,
Sand		moist	555	12 14 17	36 - 37 -		+				
		moist	762	13 17 20	38 - 39 - 40		1		(orangish bro to 1" diamete fines, low pla	r, 20-30%	mottling, 15-25% gravels up fine grained sands, 45-65%

100	Project No: Logged By		SJ42-26 AP	F-1		ition:	Shell Oil Products 4226 First Street		Well No: MW-4 Page 3 of 3
Delta Environmental Consultants, Inc.	Driller: Drilling Mel Sampling M Casing Typ Slot Size: Gravel Pac	thod: Method: pe:	Gregg HSA/AK SS sch 40 F 0.01 #2/12 sa	VC	Hole Hole Wel Wel	Drilled: Diamete Depth: Diamete Depth: Depth:	50' er: 4" 47'	Please se	ee site map
Well Completion Static Water Level	Moisture	PID Reading (ppm)	Penetration (blows/6")	Depth (feet)	Recovery So Interval ald	Soil Type	LITHOLOGY / DESCRIPTION		
Sand	wet	27	14 17 24 11 17 20	41 — 42 — 43 — 44 — 45 — 46 — 47 — 50 — 51 — 52 — 53 — 55 — 55 — 56 — 57 — 58 — 60 — 60		CL	grained sands	ng, 10-20% s, 50-70% fi rangish brov 5% fines, lo	gravels, 20-30% fine nes wn, hard, 35-45% fine w plasticity

BORING LOG Client Shell Oil Products US **Boring No.** DELTA Project Number B-1 SJ4226F1X XInogen'____ Boring diameter (in.): 8 Casing Material: NA Drilling Date(s): 3/27/07 Address: Sampling Method: Hand Auger/Split Spoon Screen Interval: NA 4226 1st Street **Drilling Company: Gregg** Screen slot size: NA Well Depth (ft.): NA Pleasanton, California Drilling Method: HSA Sand Pack: NA Boring Depth (ft): 35 Casing Diameter (in.): NA Logged By: Andy Persio PID Reading (ppm) Vater Level Depth (ft.) Soil/Rock Graphic Depth (ft.) Soil/Rock Visual Description ASPHALT: 6 inches concrete, 2-3 inches base rock. SC: Clayey SAND, orange brown, 50-60% fine to medium sand, 30-40% fines, 10% gravels up to 1.5 inches in diameter. 100% 13.3 5.5 - 7 feet bgs: as above, clay increasing, more compact, moist. CL: Lean CLAY with sand, light orangish brown, 20-30% fine sand, 70-80% fines, low plasticity, dry. 2.4 83% 10 SC: Clayey SAND, orangish brown, 60-70% fine to medium sand, 30-40% fines, trace gravels, dry. 100% 4.8 15 SC: Clayey SAND with gravel, dark brown to dark gray, 50-60% fine to coarse sand, 30-40% fines, 10-20% gravels up to 1 inch in diameter, 33.3 67% 20 20 (as above, orangish brown, 50-60% fine to coarse sand, 15-25% fines, 40.6 83% 25-30% gravels up to 1 inch in diameter, dry) 25 25 SC: Clayey SAND, orangish brown, 65-70% fine to coarse sand, 25-30% fines, 10% gravels up to 0.5 inches in diameter, dry. 0.2 83% 30 30 CL: Lean CLAY with sand, orangish brown, 75-80% fines, 15-20% fine 0.1 67% sand, low plasticity, wet. 35 35 Bottom of boring = 35 feet bgs. Note: Sampled to 35 feet bgs. 40 Page 1 of 1

BORING LOG Boring No. Client Shell Oil Products US DELTA Project Number B-2 SJ4226F1X XInogen' Boring diameter (in.): 6 Casing Material: NA Drilling Date(s): 3/27/07 Address: Screen Interval: NA Sampling Method: Hand Auger/Split Spoon 4226 1st Street Drilling Company: Gregg Screen slot size: NA Pleasanton, California Well Depth (ft.): NA Drilling Method: HSA Sand Pack: NA Casing Diameter (in.): NA Boring Depth (ft): 35 Logged By: Andy Persio Nater Level Depth (ft.) Soil/Rock Graphic Depth (ft.) Sampled Interval Soil/Rock Visual Description ASPHALT: 6 inches concrete, 1-2 inches base rock. CL: Sandy lean CLAY, dark brown, 60-70% fines, 30-40% fine to medium sand. SC: Clayey SAND, orangish brown, 55-65% fine to medium sand, 35-6.4 45% fines, trace gravels. 5.5 - 7 feet bgs: as above, clay increasing, more compact, dry. (as above, 65-75% fine to medium sand, 25-35% fines, very dense, dry) 0.6 100% 10 10 CL: Sandy CLAY, orangish brown, 20-30% fine sand, 70-80% fines, low plasticity, dry. 0.2 100% 15 15 SC: Clayey SAND, orangish brown, 60-70% fine to coarse sand, 30-40% fines, trace gravels, dry. 0,3 83% 20 20 SC: Clayey SAND with gravel, brown to orangish brown, 50-60% fine to coarse sand, 25-35% fines, 5-25% gravels up to 1 inch in diameter, dry. 67% 5.8 25 25 (same as above, dry) 0.1 50% 30 30 33.2 67% (same as above, dry) 35 35 Bottom of boring = 35 feet bgs. Note: Sampled to 35 feet bgs. 40 Page 1 of 1





BORING LOG Boring No. Client Shell Oil Products US DELTA Project Number **B-5** SJ4226F1X XInogen'____ Casing Material: NA Boring diameter (in.): 6 Address: Drilling Date(s): 3/27-28/07 Sampling Method: Hand Auger/Split Spoon Screen Interval: NA Drilling Company: Gregg 4226 1st Street Screen slot size: NA Well Depth (ft.): NA Pleasanton, California Drilling Method: HSA Sand Pack: NA Boring Depth (ft): 35 Casing Diameter (in.): NA Logged By: Andy Persio Nater Level Depth (ft.) Depth (ft.) Soil/Rock Graphic Sampled Interval Soil/Rock Visual Description ASPHALT: 6 inches concrete, 2 inches base rock. SC: Clayey SAND with gravel, brown, 50-60% fine to medium sand, 20-30% fines, 10-20% gravels up to 1 inch in diameter, dry. 1.7 100% 2.4 100% 10 10 (as above, orangish brown, 50-60% fine to medium sand, 35-45% fines, 5-10% gravels up to 0.5 inches in diameter, dry) 100% CL: Sandy lean CLAY, dark brown to dark gray, 65-75% fines, 25-35% 15 fine sand, trace gravels up to 0.5 inches in diameter, low plasticity, dry. 6.1 100% 20 20 (as above, orangish brown, 60-70% fines, 30-40% fine sand, medium plasticity, dry) 7.4 100% SC: Clayey SAND, orangish brown, 55-65% fine to medium sand, 35-25 25 45% fines, dry. 7.4 67% SC: Clayey SAND with gravel, dark gray, 50-60% fine to coarse sand, 30 30 25--35% fines, 10-20% gravels up to 1.5 inches in diameter, dry. (as above, orangish brown, 50-60% fine to coarse sand, 35-45% fines, 100% 887 5-15% gravels up to 1 inch in diameter, moist) 35 35 Bottom of boring = 35 feet bgs. Note: Sampled to 35 feet bgs. 40 40 Page 1 of 1

Engineer:L.DOOLEY Site: 4212 FIRST ST. DELTA ENV. Date: 09/29/06 10:34 Location: CPT-2 Rf (%) SBT qt (tsf) fs (tsf) U (psi) 600 400 Air Vac Air Vac Air Vac Air Vac Sili Silly Clay
Clayey Silt
Clayey Silt
Silf Fine Grand
Clayey Silt
Sandu Silt
Clayey Silt
Sandu Silt
Sandu Silt
Sandu Silt
Sandu Silt
Sandu Sand -10 -20 Sandy Silt Silty Sand/Sand Sandu Sili Silty Sand/Sand Sandy Silt Silty Sand/Sand Silt Clayey Silt -30 Depth (ft) -40 Stiff Fine Brain Demented Sand Stiff Fine Brain Cemented Sand Clayey Silt Silf Fine Grain Clayey Silt Silt Clayey Silt Silt Clayey Silt -50 No Recove -60 -70 GW Sample -80 Bilt -90 GW|Sample -100 SBT: Soil Behavior Type (Robertson 1990) Max. Depth: 100.23 (ft) Depth Inc.: 0.164 (ft)

ATTACHMENT B

SOIL ANALYTICAL DATA

Table 1 Soil Analytical Results - Shell-branded Service Station Incident# 98995840 4226 First Street, Pleasanton, California

Sample	TPHg	Benzene	Tolucne	Ethylbenzene	Xylene	MTBE
	4		· (concentrations	reported in ppm)		
MW-2-6.3'	<1.0	<0.005	<0.005	<0.005	<0.010	<0.05
MW-2-16.5'	<1.0	< 0.005	< 0.005	< 0.005	< 0.010	< 0.05
MW-2-21.5'	<1.0	< 0.005	<0.005	< 0.005	< 0.010	< 0.05
MW-2-26.0'	<1.0	<0.005	< 0.005	< 0.005	< 0.010	< 0.05
MW-2-30.5'	<1.0	<0.005	<0.005	< 0.005	< 0.010	< 0.05
MW-2-35.0'	<1.0	r <0.005	< 0.005	<0.005	<0.010	< 0.05
MW-3-5.0'	<1.0	<0.005	< 0.005	<0.005	< 0.010	< 0.05
MW-3-10.5'	<1.0	<0.005	< 0.005	< 0.005	< 0.010	<0.05
MW-3-15.5'	<1.0	<0.005	< 0.005	<0.005	<0.010	< 0.05
MW-3-20.5'	<1.0	< 0.005	<0.005	<0.005	<0.010	< 0.05
MW-3-25.5'	<1.0	<0.005	<0.005	<0.005	<0.010	< 0.05

Abbreviations and Notes:

TPHg = Total petroleum hydrocarbons as gasoline
MTBE = Methyl tert-Butyl Ether by EPA 8020.
ppm = parts per million

Samples collected January 18 and 19, 2000

TABLE 1

CHEMICAL ANALYSIS OF SOIL SAMPLES SHELL SERVICE STATION 4226 FIRST STREET PLEASANTON, CALIFORNIA

Concentrations in mg/kg (parts per million)

Boring	Depth (ft)	TFH	Benzene	Toluene	Ethylbenzene	Yulano
SB-1	15	4.2	ND	ND	ND	ND
SB-1	35	18	ND	ND	ND	ND
SB-1	50	ND	ND	ND	ND	ND
SB-2	15	П	ИN	ND	ND	ND
SB-2	30	7.2	ND	0.17	ND	ND
SB-3	10	ND	ND	ND	ND	ND
SB-3	30	ND	ND	ND	ND	ND
WA-1	30	380	2,2	2.7	5,3	32
WA- 1	35	290	1.8	0.35	0.24	1.5
WA-1	40	ND	ND	ND	ND	ND
WA-1	50	ND	ND	ND	ND	ND
100		······································		,		
Detection Lin	nits:	1.0	0.050	0.10	0.10 (), 1.0

Notes:

- 1) TPH Total Petroleum Hydrocarbons (gasoline range) analyzed by EPA Methods 5030/8015
- 2) Benzene, Toluene, Ethylbenzene and Xylene analyzed by EPA Method 8020
- 3) ND-Not Detected at detection limit shown
- 4) SB-1, SB-2 and SB-3 samples collected March 5, 1990 WA-1 samples collected March 6, 1990

TABLE 1

ANALYTICAL RESULTS OF SOIL SAMPLES

Concentrations in mg/kg (parts per million)

SHELL OIL COMPANY 4226 FIRST STREET PLEASANTON, CALIFORNIA

Boring	TPH	Benzene	Toluene	Ethylbenzene	Xylenes
SB4-15	N.D.	N.D.	N.D.	N.D.	N.D.
SB4-35	N.D.	0.023	0.0071	N.D.	0.0055
SB4-50	N.D.	0.030	0.0059	N.D.	N.D.
SB5-35	820	65	3.7	6.5	65
SB5-40	N.D.	N.D.	N.D.	N.D.	N.D.
SB5-50	N.D.	N.D.	N.D.	N.D.	N.D.
DETECTION					
LIMITS:	1.0	0.0050	0.0050	0.0050	0.0050

TPH - Total Petroleum Hydrocarbons (Gasoline Range) analyzed by EPA Methods 5030/8015.
 Benzene, Toluene, Ethylbenzene and Xylene analyzed by EPA Method 8020.

³⁾ ND - Not detected.

Table 1 Soll Analytical Results - Shell-branded Service Station Incident# 98995840 4226 First Street, Pleasanton, California

Sample	TPHg	Benzene	Toluene	Ethyl Benzene	Xylene	MTBE
····	◄					
SB-6-15.5' SB-6-19.5' SB-6-25.0'	<1.0 <1.0 <1.0	<0.0050 <0.0050 <0.0050	<0.0050 <0.0050 <0.0050	<0.0050 <0.0050 <0.0050	<0.0050 <0.0050	<0.025 <0.025
SB-6-30.0' SB-6-35.0' SB-6-40.0'	<1.0 <1.0 <1.0	<0.0050 0.0069	<0.0050 <0.0050	<0.0050 <0.0050	<0.0050 <0.0050 <0.0050	<0.025 <0.025 <0.025
SB-6-45.0'	<1.0	<0.0050 0.1	0.28 <0.0050	<0.0050 <0.0050	<0.0050 <0.0050	<0.025 <0.025
SB-7-15.0' SB-7-19.5' SB-7-24.5' SB-7-29.3' SB-7-34.3' SB-7-40.0' SB-7-44.5' SB-7-59.5'	<1.0 <1.0 <1.0 <1.0 <1.0 83 <1.0 <1.0	<0.0050 <0.0050 <0.0050 <0.0050 <0.0050 <0.0050 <0.0050 <0.0050 <0.0050	<0.0050 <0.0050 <0.0050 <0.0050 <0.0050 0.37 <0.0050 <0.0050	<0.0050 <0.0050 <0.0050 <0.0050 <0.0050 0.26 <0.0050 <0.0050	<0.0050 <0.0050 <0.0050 <0.0050 <0.0050 0.26 <0.0050 <0.0050	<0.025 <0.025 <0.025 <0.025 <0.025 <0.025 <0.025 <0.026
B-7-64.5	<1.0	<0.0050	<0.0050	<0.0050	<0.0050	<0.050

Abbreviations and Notes:

TPHg = Total petroleum hydrocarbons as gasoline

MTBE = Methyl tert-Butyl Ether

ppm = parts per million

Samples collected April 7 through 9, 1999

Table 2 Summary of Soil Analytical Data Shell Service Station

4226 First Street, Pleasanton, CA

Sample Designation	Date Sampled	Depth (feet)		TPH-G (mg/kg)	Benzene (mg/kg)	Toluene (mg/kg)	Xylene and Ethyl-benzene (mg/kg)
S-B	9/27/1985	3.5 to 5	*	2	<0.1	<0.1	<0.4
S-B	9/27/1985	7 to 8.5	*	460	<2.0	2	32
S-B	9/27/1985	10.5 to 12		610	<2.0	3.5	63
S-B	9/27/1985	14 to 15.5		1,300	<2.5	9.6	260
S-B	9/27/1985	19 to 20.5		<2	<0.1	<0.1	<0.4
S-C	9/27/1985	10.5 to 12		<2	<0.1	<0.1	<0.4
S-D	9/27/1985	10.5 to 12	~~~~	<2	<0.1	<0.1	<0.4

Notes:

mg/kg = milligrams per kilogram TPH-G = Total petroleum hydrocarbons as gasoline * Sample of gravel from UST pit

Table 2 Summary of Soil Analytical Data Shell Service Station

4226 First Street, Pleasanton, CA

Sample Designation	Date Sampled	Depth (feet)	TPH-G (mg/kg)	Benzene (mg/kg)	Toluene (mg/kg)	Ethyl-benzene (mg/kg)	Xylene (mg/kg)	MTBE (mg/kg)	TBA (mg/kg)
MW-1B@65'	8/23/2006	65	<2.5	<0.025	<0.00E	.0.005			
MW-1B@69.5'	8/23/2006	69.5			<0.025	<0.025	<0.050	<0.025	<0.250
MW-1B@95'		·	<2.5	<0.025	<0.025	<0.025	<0.050	<0.025	<0.250
	8/23/2006	95	<2.5	<0.025	<0.025	<0.025	<0.050	<0.025	<0.250
MW-4@35'	8/24/2006	35	51	<0.025	< 0.025	< 0.025	<0.050	0.17	<0.250
MW-4@36.5'	8/24/2006	36.5	380	<0.025	<0.025	1.2	1.6	0.092	
MW-4@39.5'	8/24/2006	39.5	6.7	<0.025	<0.025	0.05			<0.250
MW-4@44.5'	8/24/2006	44.5	<2.5	<0.025			0.064	0.038	<0.250
MW-4@50'					<0.025	<0.025	<0.050	0.59	<0.250
	8/24/2006	50	<2.5	<0.025	<0.025	<0.025	< 0.050	0.56.	<0.250

mg/kg = milligrams per kilogram TPH-G = Total petroleum hydrocarbons as gasoline MTBE = Methyl tert-butyl ether