



Underground Contamination Investigations, Groundwater Consultants, Environmental Engineering

5tid 1308

QUARTERLY GROUNDWATER SAMPLING REPORT

(Sampled September 5, 1997)

MATHESON TRUCKING 2500 Poplar Street Oakland, California

October 1, 1997

TABLE OF CONTENTS

I. INTRODUCTION	1
II. FIELD WORK	4
Monitoring Well Sampling	4
Wastewater Generation	5
III. RESULTS OF WATER LEVEL MEASUREMENTS	
IV. LABORATORY RESULTS	8
Laboratory Analysis	8

ATTACHMENT A -- Well Sampling Logs

ATTACHMENT B -- Analytical Results: Groundwater


I. INTRODUCTION

The site location is the Matheson Trucking facility located at 2500 Poplar Street in Oakland, California. It has been maintained as a truck maintenance, fueling, dispatch facility for a number of years. The location of the site is shown in Figure 1.

The layout of the site, along with the locations of previous underground storage tanks, is shown in Figure 2. On August 2, 1994, three underground storage tanks were removed from the site by CNC Services of Antioch, California. The tanks consisted of one 1,000-gallon single-wall steel tank and two 4,000-gallon single-wall steel tanks. Diesel and Gasoline were found to be present in the native soil beneath the 4,000-gallon tank nearest to Poplar Street at concentrations of 44 mg/Kg (ppm) and 1,360 mg/Kg (ppm), respectively.

Diesel and Gasoline were found to be present in the native soil beneath the 1,000-gallon tank, located along Union Street, at concentrations of 22 mg/Kg (ppm) and 550 mg/Kg (ppm), respectively.

On October 29, 1996, the two shallow groundwater monitoring wells MW-1 and MW-2 were installed on the site by Hageman-Aguiar, Inc. On June 10, 1997, the two on-site shallow groundwater monitoring wells MW-1 and MW-2 were sampled for the laboratory analysis for dissolved petroleum constituents. This "round" of groundwater sampling has been conducted as part of the quarterly groundwater monitoring program at the site, as required by the Alameda County Environmental Health Department and the California Regional Water Quality Control Board (RWQCB), San Francisco Bay Region. At the request of Matheson Trucking, an additional round of shallow groundwater sampling was conducted on April 28, 1997, in order to confirm the results of the previous quarterly groundwater sampling.






FIGURE 2. Site Map.

II. FIELD WORK

Monitoring Well Sampling

On September 5, 1997, groundwater samples were collected from each of the on-site monitoring wells MW-1 and MW-2. The location of the monitoring wells are shown on Figure 2 (Site Map). Prior to the groundwater sampling, each well was purged by bailing several casing volumes of water. Field conductivity, temperature, and pH meters were present on-site during the monitoring well sampling. As the purging process proceeded, the three parameters were monitored. Purging continued until readings appeared to have reasonably stabilized. A groundwater sample was subsequently collected using a new clean disposable sampling bailers. The water samples were placed inside appropriate 40 ml VOA vials and 1-liter amber bottles free from any head space. The samples were immediately placed on ice, then transported under chain- of-custody to the laboratory at the end of the work day.

At the time each monitoring well was sampled, the following information was recorded in the field: 1) depth-to-water prior to purging, using an electrical well sounding tape, 2) identification of any floating product, sheen, or odor prior to purging, using a clear bailer, 3) sample pH, 4) sample temperature, and 5) specific conductance of the sample.

Copies of the well sampling logs are included as Attachment A.

Wastewater Generation

All water removed from the wells during purging was drummed and stored on-site until the results of the laboratory analyses were obtained. Based upon these results, it appears that this water may be suitable for on-site landscape irrigation. The ultimate disposal of this waste water is the responsibility of the property owner (waste generator), and is beyond the scope of work as outlined in this report.

III. RESULTS OF WATER LEVEL MEASUREMENTS

Shallow Groundwater Flow Direction

The most recent shallow water table elevations were measured on August 12, 1996. At that time, the shallow groundwater beneath the site was determined to flow in the southerly direction.

Table 1 presents the results of all water level measurements collected since February 1, 1996. In addition to the measurements made during the regular quarterly groundwater monitoring, several additional "rounds" of water table elevations have been conducted in an attempt to establish a record of water table contours at the site. The groundwater elevation in an additional well on the neighboring Findley Adhesives property was previously measured. Since the Findley well has been decommissioned, determination of the shallow groundwater flow direction is no longer possible. The data in Table 1, however, clearly establishes the shallow groundwater flow to be in the south to southeasterly direction.

TABLE 1.

Historical Water Table Elevations
(feet)

	Date of Measurement											
WELL	02-01-96	04-10-96	04-19-96	04-27-96	05-01-96	07-29-96	08-12-96	10-29-96				
MW-1	2.68	3.34	3.12	0.40	2.58	1.30	1.07	0.18				
MW-2	3.52	3.14	3.03	2.62	2.83	1.81	1.75	1.27				
FINDLEY MW-2	4.44	4.02	4.19	4.12	4.06	3.74	3.61					
Flow Direction	SE	SE	SE	SE	SE	S	S					
Hydraulic Gradient	0.0220	0.0070	0.0120	0.050	0.018	0.029	0.031					

	Date of Measurement													
WELL	02-18-97	04-28-97	06-10-97	06-10-97										
MW-1 MW-2	3.06 3.14	1.74 2.22	1.26 1.82	0.52 1.15										
Flow Direction					**************************************									
Hydraulic Gradient														

IV. LABORATORY RESULTS

Laboratory Analysis

All analyses were conducted by a California Sate DOHS certified laboratory in accordance with EPA recommended procedures (Priority Environmental Laboratory, Milpitas, CA).

All shallow groundwater samples were analyzed for 1) total extractable petroleum hydrocarbons as Diesel (EPA method 8015), 2) total petroleum hydrocarbons as Gasoline (EPA method 8015), 3) Benzene, Toluene, Ethylbenzene, and Total Xylenes (EPA method 602), and 4) Methyl Tertiary Butyl Ether (MTBE) by EPA Method 602.

Results of Laboratory Analysis

Table 2 presents the results of the laboratory analysis of the groundwater samples collected from monitoring wells MW-1 and MW-2.

For this round of quarterly sampling, no detectable concentrations of either Diesel, Gasoline, Benzene, Toluene, Ethylbenzene, Total Xylenes or MTBE were found in any of the shallow groundwater samples.

A copy of the laboratory certificate for the water sample analyses is included as Attachment B.


TABLE 2.
Shallow Groundwater Sampling Results

Well	Date	TPH as Diesel (ug/L)	TPH as Gasoline (ug/L)	Benzene (ug/L)	Toluene (ug/L)	Ethyl- benzene (ug/L)	Total Xylenes (ug/L)	MTBE (ug/L)
MW-1	02-02-96 05-01-96	140 ND	120 240	ND ND	1.5 ND	0.5 2.3	5.5 2.8	
	07-29-96	ND	ND	ND	ND	ND	ND	
	10-29-96	ND	ND	ND	ND	ND	ND	
	02-18-97	3,000	ND	ND	ND	ND	ND	ND
	04-28-97	ND	ND	ND	ND	ND	ND	ND
	06-10-97	ND	ND	ND	ND	ND	ND	ND
	09-05-97	ND	ND	ND	ND	ND	ND	ND
MW-2	02-02-96	350	230	0.6	0.9	1.2	3.0	
	05-01-96	ND	1,000	ND	ND	0.5	3.1	
	07-29-96	ND -	ND	ND	ND	ND	ND	
	10-29-96	ND	ND	ND	ND	ND	ND	
	02-18-97	1,400	ND	ND	ND	ND	ND	ND
	04-28-97	ND	430	ND	2.8	1.6	8.2	ND
	06-10-97	ND	ND	ND	ND	ND	ND	ND
	09-05-97	ND	ND	ND	ND	ND	ND	ND
Detection	Limit	50	50	0.5	0.5	0.5	0.5	0.5

ND = Not Detected

QUARTERLY GROUNDWATER SAMPLING REPORT MATHESON TRUCKING 2500 Poplar Street, Oakland, CA.

October 1, 1997



Gary Aguiar

RCE 34262

ATTACHMENT A

Well Sampling Logs

Hageman-Aguiar, Inc. 3732 Mt. Diablo Blvd. Suite 372

3732 Mt. Diablo Blvd. Suite 372 Lafayette, California 94549 (510) 284-1661 Fax (510) 284-1664

Project: Matheson - Oakland Date: 09/05/97
--

WELL#	DTW	PRODUCT	WELL DEPTH	PRODUCT REMOVED	COMMENTS
MW-I	7,64'	none	15.00'		
MW-2	6.88'	none	14.64'		
				- Indiana	
,					
		<u> </u>			
				u .==.	
				<u>.</u>	
			1		
					:
		!			

WELL SAMPLING LOG

vveatner	Sunny E	00-900							
	•	Wilson		Completed/	4:34				
		EVAC	UATION DATA						
Description	on of Measuring Point (
Total Sou of Well B	nded Depth elow MP	14.37'+0.27'		Sample	Collected				
- Depth	to Water Below MP	6.88'	Volat	ile Organics (VOA's)	2				
= Water	Column in Well	7.76	1 Lite	r Amber Glass					
x Casing	Diameter Multiplier	0.169	Polye	othylene (plastic)					
= Gallon	s in Casing	1:31	Othe	r _					
Gallons Pumped	Prior to Sampling	6	Samı	oles Filtered _	·				
Evacuatio	on Method: PVC Bailer _	x	Sample	Method: Evacuation Bailer					
	Acrillyc Bailer _		Disposable Bailer	X_					
	Pump _			Pump					
	Other _		Direct						
		SAMPLING DAT	TA/FIELD PAR						
nspection for Free I	Product: <u>None</u>	, clear							
nspection for Free I thickness to 0.01 fo Time	Product: <u>none</u> pot, if any) 	, clear		14:34					
thickness to 0.01 fo	oot, if any)	_14;27		14:34					
thickness to 0.01 fo Time Gals Removed	oot, if any) 								
Time Gals Removed Temperature	oot, if any) 								
Time Gals Removed Temperature Conductivity	oot, if any) 								
Time Gals Removed Temperature Conductivity	14:23 14:23 1.5 78.0 1.60 × 10 ³ 6.82	14:27 3 76:3 1:57×10 ³ 6:94							
Time Gals Removed Temperature Conductivity	oot, if any)	14127 3 76.3 1157×10 ³		14:34 6 75.5 1.60×10 ³ 6.92					

WELL SAMPLING LOG

Site Loc	ation <u>Mathesa</u>	n - Oakland		Page	of <u>2</u>					
Well Nu	mber <u>M<i>W</i>-1</u>			Date <u>09/05/97</u>						
Weather	Sunny 80	0°- 90°		Time Began <u>14:49</u>						
Samplin	g Personnel <u>* <i>B</i> W</u>	ilson		Completed <u>15:09</u>						
		EVA	CUATION DATA	\						
Descript	tion of Measuring Point (I	MP): <u>WB@G</u>								
	ounded Depth Below MP	14.73'+0.27	•	Sample	Collected					
- Depth	to Water Below MP	7.64	Vola	tile Organics (VOA's)	2					
= Wate	er Column in Well _	7.36	1 Lii	er Amber Glass						
x Casir	ng Diameter Multiplier	0.169	Poly	ethylene (plastic)						
= Gallo	ns in Casing _	1,24	Othe	er _						
Gallons Pumpe	ed Prior to Sampling _	6	Sam	ples Filtered						
Evacuati	ion Method: PVC_Bailer	X	Sample	e Method: Evacuation Bailer						
	Acrillyc Bailer			Disposable Bailer	X					
	Pump			Pump						
	Other	·		Direct						
			/ 5151 5 545							
		SAMPLING DA	TA / FIELD PAF	RAMETERS						
Inspection for Free (thickness to 0.01 t	Product: <u>none</u> foot, if any)	, clear								
Time	14:57	15:01	15:04	15:09						
Gals Removed	1.5	3	4.5	6						
Temperature	70.7	68.7	68.4	68.6						
Conductivity	2.53 x 10 ³	2.69 x 103	2.71×103	2,72 × 103						
рH	7,76	7.29	7,32 7,18							
Color / Odor	Tan	Tan	Tan	<u> </u>						
Turbidity	10W	low	10W	10W						
Other										
Comments:										

ATTACHMENT B

Analytical Results: Groundwater



PRIORITY ENVIRONMENTAL LABS

Precision Environmental Analytical Laboratory

September 10, 1997

PEL # 9709009

HAGEMAN - AGUIAR, INC.

Attn: Randall Wilson

Re: Two water samples for Gasoline/BTEX with MTBE and Diesel analyses.

Project name: Matheson

Project location: Oakland, C.A.

Date sampled: Sept.05, 1997
Date extracted: Sept 08-09, 1997

Date submitted: Sept 08, 1997 Date analyzed: Sept.08-09, 1997

RESULTS:

SAMPLE	Gasolin	e MTBE	Benzene	Toluene	-	Total	Diesel	
I.D.	(ug/L)	(ug/L)	(ug/L)	(ug/L)	Benzene (ug/L)	Xylenes (ug/L)	(ug/L)	
MW - 1 MW - 2	N.D. N.D.	N.D. N.D.	N.D. N.D.	N.D. N.D.	N.D. N.D.	N.D. N.D.	N.D.	
Blank	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	
Spiked Recovery	81.9%		82.5%	94.4%	85.7%	94.2%	97.3%	
Detection limit	50	0.5	0.5	0.5	0.5	0.5	50	
Method of Analysis	5030/ 8015	602	602	602	602	602	3510/ 8015	

David Duong Laboratory Director

1764 Houret Court Milpitas, CA. 95035 Tel: 408-946-9636 Fax: 408-946-9663

PEL # 9709009 INV # 27909

CHAIN OF CUSTODY RECORD

Matheson - Otkland Oaklend				HAGEMAN - AGUIAR, INC. 3732 Mt. Diablo Blvd., Suite 372 Lafayette, CA 94549 (415)284-1661 (415)284-1664 (FAX)					ANALYSIS REQUESTED REMARKS						/		
CROSS REFERENCE NUMBER	DATE	TIME	8 0 1	W A T E A	STA	TION LOC	ATION	1	\ \ \		gir Z		/	/	/	REMARKS	
MW-1	09/05/97	13:15		X	Monitor	rine v	vell	#1	×	X					<u> </u>		
MW-2	09/05/97	12:30		×	u		11	#2	LX.	X		_		<u> </u>			
<u> </u>			ļ	 				•	+		₩	_		 	_		
	 			+							-	 -		-	 	,	
	1		 -	 -					 		 	 	 	 	 		
			 	╁─		·		,	+-		 	 		 	 		
				 	1				†		1			<u> </u>			
													1				
			L														
									_	<u> </u>			<u> </u>				
			<u> </u>	1					ļ	<u> </u>	1				<u> </u>		
				_	ļ		<u> </u>		 	<u> </u>	ļ	ļ	ļ	<u> </u>	ļ		
RELINQUISHED BY	(: (Signatura)	<u> </u>			<u> 1</u>	IDATE Or (BECEIVED BY: 1844]	<u> </u>		<u> </u>		<u> </u>		<u> </u>	. 1-
Barre	Lad I	Vil	, 			TIME II	28/97 . 42	RECEIVED BY: (Sign	1000	-						DATE 9	<u> </u>
RELINQUISHED BY: (Signature)					DATE		RECEIVED BY: (Sig								DATE	<u> </u>	
RELINQUISHED B	V: (Signature)					TIME		RECEIVED BY: (Sig	nah wa)							TIME	
m.cimousnes B	r. (Signante)					DATE TIME		NEUCITED DT. (349)	natul v j							DATE	····
RELINQUISHED B	Y: (Signature)					DATE		RECEIVED FOR LAR				(e)	100	r=7		DATE	
1						TIME			And	Les	$\overline{}$	-	80	ンし	/	TIME	