





98 AUG 19 AM 1:56

August 5, 1998 Project 20805-134.005

Mr. Paul Supple ARCO Products Company P.O. Box 6549 Moraga, California 94570

Re: Quarterly Status Report, First Quarter 1998, for ARCO Service Station No. 6113, located at 785 East Stanley Boulevard, Livermore, California

Dear Mr. Supple:

Pinnacle Environmental Solutions, a division of EMCON (Pinnacle), is submitting the attached report which presents the results of the first quarter 1998 groundwater monitoring program at ARCO Products Company (ARCO) Service Station No. 6113, located at 785 East Stanley Boulevard, Livermore, California (see Figure 1). The semi-annual monitoring program complies with the Alameda County Health Care Services Agency (ACHCSA) requirements regarding underground tank investigations.

Please call if you have questions.

Sincerely,

Pinnacle,

Glen VanderVeen Project Manager

Attachment: Quarterly Status Report, First Quarter 1998

cc: Susan Hugo, ACHCSA

Danielle Stefani, LFD

N:\PJ0\0805\08051340.5AS-98\pzusmer:1

Pinnacle
Rev. 0, 8/05/98

Date:

July 27, 1998

# ARCO QUARTERLY STATUS REPORT

Address:	785 East Stanley Boulevard, Livermore, California
	20805-134.005
one No.:	Paul Supple /(510) 299-8891
o.:	Glen VanderVeen/(510)977-9020
	ACHCSA /Susan Hugo
	one No.:

## **WORK PERFORMED THIS QUARTER (First - 1998):**

1. Prepared and submitted groundwater monitoring report for fourth quarter 1997.

## **WORK PROPOSED FOR NEXT QUARTER (Second - 1998):**


- 1. Prepare and submit quarterly status report for first quarter 1998.
- 2. Perform semi-annual groundwater monitoring and sampling for second quarter 1998.

#### **SEMI-ANNUAL MONITORING:**

Current Phase of Project:	Semi-Annual Groundwater Monitoring
Frequency of Sampling:	Annual (4th Quarter): MW-1, MW-2, MW-3, MW-8, MW-9,
	MW-10.
_	Semi-Annual (2nd/4th Quarter): MW-4 through MW-7, MW-11, MW-12
Frequency of Monitoring:	Semi-Annual (groundwater)
Is Floating Product (FP) Present On-site:	☐ Yes 🏿 No
Bulk Soil Removed to Date :	288 cubic yards of TPH impacted soil
Bulk Soil Removed This Quarter:	None
Water Wells or Surface Waters,	
within 2000 ft., impacted by site:	None
Current Remediation Techniques:	None

#### **ATTACHMENTS:**

• Figure 1 - Site Location





Base map from USGS 7.5' Quad. Map: Livermore, California. Photorevised 1980.

2000 4000 SCALE IN FEET



DATE	NOV. 1997
DWN.	KAJ
APP.	
REV .	
PRO	LECT NO.

805-134.004

FIGURE 1 ARCO PRODUCTS COMPANY SERVICE STATION 6113, 785 E. STANLEY BLVD. LIVERMORE, CALIFORNIA QUARTERLY GROUNDWATER MONITORING SITE LOCATION

Operator: KAJ

EA-SANJOSE—CAD/DRAWINGS: 1:\ OZOOZ\SITELOC.dwg Xrefs: <NONE> Scale: 1 = 1.00 DimScole: 1 = 1.00 Date: 3/12/97 Time: 5:19 PM