



3530 MacArthur, Oakland 5/19/74
12215117976-B
South wall of waste oil pit where
one sample collected (at ~6' deep)
Juliet Shen



3530 MacArthur, Oakland 5/19/74
12215117976-B
Waste oil UST pit w/ stained soil
Soil sample collected from beneath
fill pipe. Juliet Shen



3530 MacArthur, Oakland 5/19/74
12215117976-B
Stained soil observed along all
four sidewalls of
1,000-gallon waste oil UST. Juliet Shen



3530 MacArthur, Oakland 5/19/74
12215117976-B
Stained soil on south wall of
pit (waste oil UST pit).
Juliet Shen



3530 MacArthur 4/26/94
 Gas product piping
 in trench. Broken up
 during excav. Rinsed
 09318221467-2
 0547 1737
 Subject Site



3530 MacArthur 4/26/94
 Gas product piping
 to existing gas USts
 Rinsed
 09318221467-2
 0547 1736
 Subject Site



3530 MacArthur Blvd, Oak 4/26/94
 Stained soil from
 Sample #2 area.
 09318221467-2
 0547 1735
 Subject Site



3530 MacArthur Blvd 4/27/94
 Sampled beneath another set of
 old piping, near former
 dispensers. Cooled area is location
 of sample.
 09318221467-2
 0547 1736
 Subject Site



3530 MacArthur Oakland 5/2/94
 Overview of site & piping trenches
 taken from inside building.
 09318221467-2
 4547 1721
 Juliet Shinn



3530 MacArthur, Oakland 5/2/94
 The circled areas are sample locations
 PX-2 thru PX-5.
 (From overexc. of trench)
 09318221467-2
 4547 1721
 Juliet Shinn



3530 MacArthur Oakland 5/2/94
 The circled areas are sample locations
 PX-2 thru PX-5
 in overexcavated piping trench.
 09318221467-2
 4547 1721
 Juliet Shinn



3530 MacArthur, Oakland 5/2/94
 Sample location PX-1 from overexcavated trench
 09318221467-2
 0547 1732
 Juliet Shinn



3530 MacArthur, Oakland 5/2/94
 Area of overexcavation, in westernmost former piping trench where 1200 ppm gas was initially identified.
 09318221467-2
 0547 1732
 Juliet Shinn



3530 MacArthur, Oakland 5/2/94
 Primary overexcavation area is to the
 extreme right and they well
 we skimming more soil from
 the trench for lower depth piping, in
 center of picture
 09318221467-2
 0547 1732
 Juliet Shinn



Remote Fill piping

vent piping



3530 MacArthur, Oak
12215117976-8 5/19/94
Waste oil UST pit w/ stockpiled
soil in background. Tank hauled
by Erickson Juliet Shur

3530 MacArthur, Oakland 5/19/94
12215117976-8
Groundwater in waste oil UST pit
Stained soil on sidewalls at ~6' deep.
Juliet Shur



3530 MacArthur, Oakland 5/19/94
1,000-gallon waste oil UST. Vent line
gone north. 85318221467-2
Remote fill going east/west. 85318221467-2
Juliet Shur

3530 MacArthur, Oakland 5/19/94
1,000-gallon fiberglass waste oil
UST removed. 85318221467-2
No apparent holes. 85318221467-2
Juliet Shur



3530 MacArthur, Oakland 5/24/99
 12215117976-B
 Sampled g.w. after pumping yesterday
 afternoon & letting it recharge. Slight
 sheen on water. Juliet Shui



3530 MacArthur, Oakland 5/24/99
 12215117976-B
 The first pipe did not appear to
 be sealed & capped or reused.
 Juliet Shui