DEPARTMENT OF TRANSPORTATION

Office of Environmentàl Engineering BOX 23660 MS 8-A OAKLAND, CA 94623-0660 (510) 286-4444 TDD (510) 286-4454



October 4, 2000

Ms. Barbara J. Cook, P.E., Chief Northern California – Coastal Cleanup Operations Branch Department of Toxic Substances Control 700 Heinz Avenue, Building F, Suite 200 Berkeley, CA 94710-2721

Subject:

Former J&A Truck Repair and Container Freight sites 500 Kirkham Street and 1285 5th Street, Oakland, California

Dear Ms. Cook:

The following document is enclosed for your review in accordance with Voluntary Cleanup Agreement No. 4-1625-C for the Cypress Freeway Reconstruction Project:

 Site Investigation Report, Task Order Number 04-192203-RJ Contract Number 43A0012, Former J&A Truck Repair and Container Freight Sites, Oakland, California By Professional Service Industries, Inc., September 22, 2000

Please direct any comments or questions you may have regarding this site to Jill Pollock at (510) 286-5638.

4

Sincerely,

HARRY Y. YAHATA District Director

CELLA MACHAIC

District Branch Chief

Enclosure:

CC: Ms. Betty Grahm, Regional Water Quality Control Board

Ms. Susan Hugo, Alameda Health Agency

BOOK S PA 3. La

SITE INVESTIGATION REPORT TASK ORDER NUMBER 04-192203-RJ CONTRACT NUMBER 43A0012

FORMER J & A TRUCK REPAIR & CONTAINER FREIGHT SITES OAKLAND, CALIFORNIA

prepared for

CALIFORNIA DEPARTMENT OF TRANSPORTATION District 4

111 Grand Avenue Oakland, California

prepared by

Professional Service Industries, Inc.

1320 West Winton Avenue Hayward, California 94545 (510) 785-1111

> September 22, 2000 575-0G011

TABLE OF CONTENTS

STA	ATEMENT OF LIMITATIONS AND PROFESSIONAL CERTIFICATION	iii
1.0	INVESTIGATION SUMMARY	1
2.0	INTRODUCTION	4
	1.1 PROJECT OBJECTIVE	4
	1.2 SITE BACKGROUND	4
	1.2.1 J & A Truck Repair Facility (Site1)	4
	1.2.2 Container Freight Site (Site 2)	6
3.0	GEOLOGY AND HYDROGEOLOGY	
	3.1 GEOLOGY	9
	3.2 HYDROGEOLOGY	9
4.0	SUBSURFACE INVESTIGATION	10
	4.1 PRE-FIELD ACTIVITIES	
	4.1.1 Task Order Meeting	
	4.12 Health and Safety Plan	
	4.1.3 Utility Clearance	
	4.1.4 Project Permits	
	4.2 SOIL BORINGS	
	4.2.1 Soil Sampling Protocol	12
	4.2.2 Soil Classification	12
•	4.3 MONITORING WELL INSTALLATION AND DEVELOPMENT	
	4.4 DECONTAMINATION PROCEDURES	
	4.5 STORAGE AND DISPOSAL OF GENERATED WASTE	13
	4.6 MONITORING WELL SAMPLING	14
5.0	LABORATORY ANALYSIS PROGRAM	15
6.0	FIELD QUALITY ASSURANCE/QUALITY CONTROL	
	6.1 SAMPLE IDENTIFICATION	16
	6.2 CHAIN-OF-CUSTODY PROCEDURES	16
	6.3 FIELD INSTRUMENTS	16
7.0	DATA EVALUATION AND DISCUSSION	17
	7.1 J & A REPAIR SITE (SITE JA)	
	7.2 CONTAINER FRIGHT SITE (SITE CF)	25
8.0	CONCLUSIONS AND RECOMMENDATIONS	37

TABLE OF CONTENTS (continued)				
REFERENCES41				
<u>FIGURES</u>				
	FIGURE 2: FIGURE 3:	SITE LOCATION MONITORING WELL LOCATIONS GROUNDWATER ELEVATION CONTOUR MAP DISTRIBUTION OF CONTAMINANTS IN SOIL DISTRIBUTION OF CONTAMINANTS IN GROUNDWATER		
	TABLES			
	TABLE 1: TABLE 2:	GROUNDWATER ELEVATION AND PARAMETERS SUMMARY OF SOIL ANALYTICAL RESULTS: ORGANICS - J&A TRUCK REPAIR - (SITE JA)		
	TABLE 3:	SUMMARY OF SOIL ANALYTICAL RESULTS: METALS - J & A TRUCK REPAIR (SITE JA)		
	TABLE 4:	SUMMARY OF GROUNDWATER ANALYTICAL RESULTS: ORGANICS -		
	TABLE 5:	J & A TRUCK REPAIR (SITE JA) SUMMARY OF GROUNDWATER ANALYTICAL RESULTS: METALS J &		
	TABLE 6:	A TRUCK REPAIR (SITE JA) SUMMARY OF SOIL ANALYTICAL RESULTS: ORGANICS - CONTAINER FRIGHT (SITE CF)		
	TABLE 7:	SUMMARY OF SOIL ANALYTICAL RESULTS: METALS - CONTAINER FRIGHT (SITE CF)		
	TABLE 8:	SUMMARY OF GROUNDWATER ANALYTICAL RESULTS:ORGANICS - CONTAINER FRIGHT (SITE CF)		
	TABLE 9:	SUMMARY OF GROUNDWATER ANALYTICAL RESULTS:METALS - CONTAINER FRIGHT (SITE CF)		
<u>APPENDICES</u>				
APPENDIX A: APPENDIX B: APPENDIX A: APPENDIX D: APPENDIX E:		B: BORING LOGS A: SURVEY DATA D: LABORATORY RESULTS AND CHAIN-OF-CUSTODY RECORDS E: PERMITS		
APPENDIX F: APPENDIX G:				

STATEMENT OF LIMITATIONS AND PROFESSIONAL CERTIFICATION

Information provided in this Site Investigation Report (SIR), prepared by Professional Service Industries, Inc. (PSI), is intended exclusively for the use of Caltrans for the evaluation of subsurface conditions as it pertains to the subject sites. The professional services provided have been performed in accordance with practices generally accepted by other geologists, hydrologists, hydrogeologists, engineers, and environmental scientists practicing in this field. No other warranty, either expressed or implied, is made. As with all subsurface investigations, there is no guarantee that the work conducted will identify any or all sources or locations of contamination.

This SIR is issued with the understanding that Caltrans is responsible for ensuring that the information contained herein is brought to the attention of the appropriate regulatory agency. This SIR has been reviewed by a geologist who is registered in the State of California and whose signature and license number appears below.

Frank Poss, R.E.A. Senior Hydrogeologist

6hn D. Whiting, R.G.

No. 5951

Senior Geologist

A Confortileou Adriana Constantinescu, R.E.A.

1.0 INVESTIGATION SUMMARY

Professional Service Industries, Inc. (PSI) has been retained by the California Department of Transportation (Caltrans), under Task Order Number 04-192203-RJ and Contract Number 43A0012, to prepare this Site Investigation Report to assess current soil and groundwater conditions at the Former J & A Truck Repair Facility, located at 500 Kirkham Street (Site JA) and Container Freight (Site CF), located at 1285 5th Street, in the City of Oakland, California (subject site; Figure 1).

Seven soil boreholes were advanced on the two sites named above using a hollow-stem auger drill rig. All of the boreholes were completed as groundwater monitoring wells on April 25 and 26, 2000. Seven groundwater samples and one duplicate were collected from the new wells on May 2, 2000.

Based on the information presented in this report, the following conclusions have been reached:

- None of the soil samples collected from the Site JA contained detectable levels of total
 petroleum hydrocarbon as gasoline (TPH-G), total petroleum hydrocarbon as diesel
 (TPH-D), motor oil, organochlorine pesticides, and polychlorinated biphenyls. Five
 volatile organic compounds (VOCs) (1,1-Dichloroethane, Naphthalene, Styrene, 1,1,1Trichloroethane, and Trichlorotrifluorethane) and five semi-VOS (SVOCs)
 (Acenaphthylene, Fluoranthene, Naphthlene, Phenanthrene, and Pyrene) were
 detected at levels well below the Cypress Preliminary Remedial Goals (PRG) levels
 for soil.
- Ten metals (Arsenic, Barium, Chromium, Cobalt, Copper, Lead, Nickel, Thallium, Vanadium, Zinc) were detected above the detection limit in the soil samples collected for this investigation from the Site JA. The detected levels were well below the Cypress PRGs.
- Groundwater samples collected from the four new groundwater monitoring wells
 installed at Site JA did not contain motor oil, organochlorine pesticides or PCBs above
 the detection limits. Fourteen VOCs were detected in the water samples collected
 from this site. The detected concentrations of VOCs are less than the detected
 amounts in the grab groundwater sample collected on August 30, 1995. The highest
 levels of contaminants were detected in the groundwater sample collected from the
 groundwater monitoring well JA-4, located down gradient of the former site sumps.
- Soil samples collected from the Site CF contained detectable levels of TPH-G, TPH-D, and motor oil. TPH-G was detected at levels between 0.69 mg/kg and 0.77 mg/kg.

TPH-D was detected at levels ranging between 19 mg/kg to 370 mg/kg. The detected levels decrease with depth, between 0.5 m to 2 m (1.65 feet to 6 feet).

- Two VOCs (benzene and naphthalene) were detected at levels above the detection limit. Both values are well below the previous maximum detected levels.
- Sixteen SVOCs were detected in the tested soil samples above the detection limit. All
 of the detected levels were below the previous maximum detected levels at Site CF.
- Organochlorine pesticides as 4,4'-DDD was detected only in two soil samples, with the maximum level of 9.3 mg/kg.
- Aroclor-1260 was the only PCBs detected at a level of 0.082 mg/kg, with 0.918 mg/kg below the industrial PRG level for soil. Previous soil sampling performed at this site did not report PCBs above the detection limit.
- Ten metals were detected at concentrations well below the maximum detected levels reported by the previous subsurface investigations.
- Groundwater samples collected from the three new installed wells at the Site CF contained detectable levels of TPH-G, TPH-D, VOCs, and SVOCs. TPH-G was detected in all groundwater samples at levels between 0.5 mg/L and 94 mg/L. TPH-D was detected in two groundwater samples collected from the wells CF-1 and CF-2 at levels between 2.8 mg/L and 21 mg/L.
- Nine VOCs were detected in the water samples collected during this investigation at the Site CF. One groundwater sample collected from the groundwater monitoring well CF-2 contained eight of the detected VOCs. Benzene, Carbon Disulfide, Ethylbenzene, Naphthalene, Styrene, Toluene, 1,2,4-Trimethylbenzene, Trichloroethene, and Xylenes were detected at levels above the MCL/EPA Region 9 PRG levels for drinking water.
- Nineteen SVOCs were detected in the groundwater samples tested during this investigation. Eighteen of the SVOCs detected levels were well below the maximum detected levels reported by the previous investigations.
- Motor oil, organochlorine pesticides, and PCBs were not detected in the groundwater samples collected from the Site CF.

 Only one metal was detected above the detection limit in the groundwater samples collected for this investigation from the Site CF. The detected level was 0.28 mg/l of barium.

Based on the results presented in this report, PSI recommends the following course of action:

• Groundwater monitoring be continued at the Site JA and Site CF, on a quarterly basis. According to the DTSC requirements, total dissolved solids (TDS) measurements should be collected. Also, filtered and unfiltered samples from the Site CF should be analyzed for SVOCs using EPA Method 8270.

1.0 INTRODUCTION

Professional Service Industries, Inc. (PSI) has been retained by the California Department of Transportation (Caltrans), under Task Order Number 04-192203-RJ and Contract Number 43A0012, to prepare this Site Investigation Report to assess current soil and groundwater conditions at the Former J & A Truck Repair Facility, located at 500 Kirkham Street (Site JA) and Container Freight (Site CF), located at 1285 5th Street, in the City of Oakland, California (subject site; Figure 1).

The scope of work for this investigation included:

- Drill 7 soil borings to a maximum depth of 5 meters (16.4 feet) (4 soil borings at Site 1 and 3 soil borings at Site 2),
- Install seven new groundwater monitoring wells in the drilled soil borings and survey the designated points,
- Develop, purge, and sample new monitoring wells to characterize groundwater in the upper aquifer (Merritt Sand Aquifer),
- Perform chemical analyses of soil and groundwater samples,
- Perform sieve analysis of one soil sample per each site and at changes in lithology (if any) to characterize the shallow aquifer,
- Prepare a technical report describing the investigation and interpretation of the data generated.
- Perform quarterly groundwater quality monitoring and reporting for a minimum of one year.

2.1 PROJECT OBJECTIVE

The objective of the project is to determine the general presence and concentration of contaminants of concern in the groundwater at each site and monitor these concentrations over a minimum of one year.

2.2 SITE BACKGROUND

2.2.1. J&A Truck Repair Facility (Site JA)

The former J & A Truck Repair facility was located at 500 Kirkham Street, in the City of Oakland, County of Alameda, California. For the extension of Cypress Freeway, Caltrans purchased the property from Mr. Barney Smilo, in the summer of 1994. The 1996 report prepared by Jonas and Associates, Incorporated (JAI) showed that an inspection of the site in 1979 by Alameda County Health Department (ACHD) revealed the presence of a white pigment, titanium oxide (TiO₂) in a storm drain southwest of the site. The California

Department of Health Services (DHS), currently known as Department of Toxic Substances Control (DTSC), performed an inspection on October 28, 1980, due to a citizen complaint. The inspector found "improper storage and disposal of hazardous wastes which include spills on soil, disposal into dumpster and onto adjacent property and storage in a pit" (JAI, 1996).

In March 1981, the DHS performed another inspection and an area of dead vegetation adjacent to a hole was observed on the eastern side of the site. Analysis of soil samples collected by DHS revealed the presence of pesticides and heavy metals in the surface soils. DHS and the California Regional Water Quality Control Board (RWQCB) recommended corrective action to clean-up contaminated soil and prevent future releases. No documentation exists to verify if any corrective action was performed at the site.

On June 23, 1992, GeoResource Consultants, Inc. (GeoResource) drilled one soil boring in the southeastern portion of this site, as part of a series of investigations on the site area performed for Caltrans. Two soil samples were collected at 0.3 and 1 meter (m) (1 and 3 feet) below ground surface (bgs) and submitted for laboratory analysis of organochlorine pesticides and Title 26 metals. The 1996 JAI 's report indicated that no organochlorine pesticides were detected in either of the two soil samples. The soil sample collected at 0.3 m (1 feet) bgs contained 81 mg/kg of lead.

The environmental assessment at this site continued in October 1994, when Environmental Solutions, Inc. (ESI) collected wipe samples of the former warehouse interior walls and soil and groundwater samples in the underground storage tank (UST) area and the remaining area of the site. Results of the wipe sample analysis indicated detectable concentrations of total recoverable petroleum hydrocarbons (TRPH), Metals, Organochlorine Pesticides, Polychlorinated Biphenyls (PCBs), Semi-Volatile Organic Compounds (SVOCs) and Volatile Organic Compounds (VOCs) on the interior walls of the warehouse. ESI subsurface investigation showed that, in general, soils on the site have been reported to be impacted by TRPH, Lead, and low concentrations of SVOCs and VOCs. The ESI's study showed that groundwater beneath the site has been impacted by TRPH, TPH-G, unknown compounds in the diesel range, oil and grease, metals, and VOCs (JAI, 1996).

All the structures on the property were demolished in April 1995. On August 30, 1995, under ACHD's supervision, one 1,100-gallon steel gasoline underground storage tank (UST) was removed from the western side of the property. At the time of the UST removal, two soil samples were collected from the walls of the excavation, at a depth of approximately 7 feet below ground surface. Petroleum hydrocarbons were detected in only one soil sample collected from the western side of the excavation pit at the following

concentrations: 5,500 mg/kg of total petroleum hydrocarbons as gasoline (TPH-G), 40 mg/kg of benzene, 260 mg/kg of toluene, 100 mg/kg of ethylbenzene, and 52 mg/kg of total xylenes. One groundwater sample was collected from the bottom of the excavation pit. Total petroleum hydrocarbons were detected in the groundwater sample at the following concentrations: 32 mg/l of TPH-G, 5.6 mg/l of benzene, 5.1 mg/l of toluene, 0.063 mg/l of ethylbenzene, and 5.5 mg/l of total xylenes. Lead was detected at 0.11 mg/l. One composite soil sample was collected from the soil stockpile and contained the following contaminants: barium (39 mg/kg), cadmium (0.5 mg/kg), chromium (17 mg/kg) lead (13 mg/kg), and mercury (0.05 mg/kg). Approximately forty cubic yards of soil was excavated and stockpiled at the site. Following waste characterization, on November 16, 1995, the soil stockpile along with the other soil excavated from the former J & A Truck Repair site was transported and disposed at ECDC Environmental, located in East Carbon, Utah as non-RCRA hazardous waste solid (JAI, 1995).

From November 13 through November 16, 1995, approximately 3,426.3 m³ (4,700 cubic yards) of soil was excavated to an approximate depth of 1.8 m (6 feet) bgs, by MCM Construction, Inc. (MCM). A total of 92 soil samples were collected from the walls and the bottom of the excavation pit. Thirty-two of the soil samples were collected from the walls of the excavation at depths of approximately three feet bgs. In addition, 60 samples were collected at the bottom of the excavation pit, at depth of approximately 1.8 m (6 feet) bgs. Twenty-five chemicals were detected in the tested soil samples. evaluation of the data and an estimation of human health risk was performed by SOMA Corporation of Emeryville, California. The estimation of risk was based on a quantitative comparison of the soil sample analytical results (both excavation and site characterization samples) with US EPA Region 9 Preliminary Remedial Goals (PRGs) and the calculation of equivalent risks. For the carcinogenic compounds, only the 95 percent upper confident limit (UCL) concentration for PCB was found to exceed the PRG value. estimated excess carcinogenic risk for the identified chemicals is 7.88E-06. Without the excess carcinogenic risk from the PCB, the total estimated excess carcinogenic risk for the identified chemicals would be 5.01E-07. For the identified non-carcinogenic compounds, none of the 95 percent UCL concentrations exceeded the corresponding PRG values, that is, individual chemical hazard quotients were less than a value of 1. The total hazard index for the identified non-carcinogenic compounds was also less than a value of 1 (2.89E-01) (JAI, 1996).

2.2.2. Container Freight Site, Oakland, California (Site CF)

The Container Freight site is located at 1285 5th Street in Oakland, Alameda County, California. According to Environmental Solutions, Inc.'s (ESI) report dated June 21, 1995, this site has been operated as a warehouse and distribution facility since 1967. Site activities consisted of unloading cargo from freight trains and transferring to trucks. Prior

to this use, the site was owned by the Commissary Department of the South Pacific Rail Road (SPRR). It is not known what site activities took place at the site when it was owned by SPRR. Caltrans purchased the site in 1994 in connection with the reconstruction of the Cypress Freeway. The Site CF is currently vacant because the former warehouse was demolished in May, 1995 to prepare for the construction of nine footings for an aerial structure of the main freeway alignment and an embankment for the 5th Street on and off ramps. A 700-gallon diesel UST, located in front of the former warehouse building, was removed from the site in late August 1995 (JAI, 1995).

On June 24, 1992, GeoResource Consultants (GRC) drilled four soil borings to depths ranging from 1.06 m to 2.6 m (3.5 to 8.5) feet bgs around the former diesel UST. One groundwater sample was collected using a Hydropunch sampling device. None of the soil and groundwater samples analyzed showed the presence of TPH-D at or above reported detection limits.

In November 1994, Environmental Solutions, Inc. (ESI) performed soil and groundwater sampling in the truck parking area in the back of the warehouse building advancing seven soil borings. In March 1995, ESI resumed the soil and groundwater sampling within the footprint of the former warehouse after it was demolished, advancing four more soil borings. Laboratory analysis results of soil samples collected from the former parking area have been impacted by petroleum hydrocarbons, heavy metals (mainly copper and lead), VOCs, and SVOCs. No PCBs were detected at or above the detection limits. A coal tar odor was detected in three of the soil borings at depths ranging from approximately 0.65 m to 1.32 m (2 to 4 feet) bgs. TRPH was detected at concentrations up to 1,000 mg/kg in three of the soil borings. Lead concentrations exceeding 50 mg/kg were detected in all tested soil samples, with a maximum concentration of 27,000 mg/kg in one of the soil samples collected at 1.05 m (3.5 feet bgs). Groundwater samples collected by ESI beneath the former truck parking area and beneath the former warehouse building has been impacted by TRPH, VOCs, metals, and SVOCs. Acetone was detected only in one groundwater sample taken from under the former warehouse site with a concentration of 78 µg/L. Benzene, toluene, ethylbenzene, and xylenes (BTEX) group was detected at concentrations ranging from 39 to 2,400 μg/L. Styrene, arsenic, nickel, and chromium were detected at concentrations exceeding National Pollutant Discharge Elimination System (NPDES) and East Bay Municipal Utilities District (EBMUD) permit discharge limits.

The "Underground Storage Tank Report" issued by JAI in 1995, presented that one 700-gallon steel UST was closed at the end of August 1995. Two soil samples collected from the tank pit contained detectable levels of TPH-G, Lead, and BTEX group. Unknown hydrocarbons in the diesel and motor oil range were also detected. The groundwater collected from the excavation pit contained none of the petroleum hydrocarbon

compounds tested for. Only one unknown hydrocarbon compound in the kerosene range was detected at a concentration of 0.63 mg/l (JAI, 1995).

Additional soil sampling performed by Harding Lawson Associates in the area of Cypress Freeway re-alignment on November 24, 1997 revealed that shallow soil samples collected at 0.3 m (1 foot) and 1 m (3 feet) bgs contained detectable levels of oil and grease, an unknown petroleum hydrocarbon, naphthalene, toluene, benzene, mercury barium, chromium, cobalt copper, lead, molybdenum, nickel, vanadium, and zinc.

3.0 SITE GEOLOGY AND HYDROGEOLOGY

3.1 Site Geology

The subject site is located within a large region known as the Coast Ranges geomorphic province. This region is characterized by extensive folding, faulting and fracturing of variable intensity (Norris, 1990). The faults and folds trend northwesterly and comprise the pronounced northwest trending ridge-valley system. The oldest geologic formations in the Bay Area are probably of Jurassic age (138-205 million years ago). These formations have been subject to repeated episodes of deformation. By comparison, the youngest formations (Quaternary age – last 2 million years) have been only mildly flexed.

According to the "Geologic Map of the Flatland Deposits of the Southern Part of the San Francisco Bay Region" the subject site is underlain by fine-grained alluvium that consists of unconsolidated, plastic, moderately to poorly sorted silt and clay, rich in organic material. On the basis of borings drilled and logged at the subject site, the soil types encountered consist of the following:

- At Site JA, approximately 0.6 meter (m) (2 feet) of fill consisting of gravelly sand and silty sand was underlain by a green, poorly graded sand.
- At Site CF, the upper soil unit consisted of approximately 1.5 m (5 feet) of well graded gravelly silty sand, underlain by a poorly graded fine sand interbedded with clayey silt.

3.2 Site Hydrogeology

Environmental Solutions, Inc.' (ESI) s report issued on April 3, 1995 mentioned that the Merritt Sand is the first encountered subsurface aquifer, and is usually unconfined. The Merritt Sand is believed to be continuous across much of west Oakland south to Alameda Island. At the Site JA, the depths to groundwater were between 1.17 m to 1.89 m (3.83 feet to 6.2 feet). At the Site CF, the depths to groundwater were between 0.832 m to 1.54 m (2.73 feet to 5.06 feet). The Merritt Sand aquifer extends to a depth of approximately 18.3 m (60 feet) bgs, where Temascal Formation is believed to provide a competent aquitard between it and the deeper confined aquifer present in the Alameda Formation. ESI's report stated also, that based on aquifer pump test data, the Merritt Sand has a hydraulic conductivity on the order of 10⁻³ to 10⁻² centimeters per second. (cm/sec). The next aquifer below the Merritt Sand aquifer is the Alameda Formation which ranges from 36.6 m (120 feet) to 48.8 (160 feet). In general, this aquifer is confined, and is believed to be continuous across much of west Oakland, with a thickness of over 60.96 m (200 feet).

4.0 SUBSURFACE INVESTIGATION

This section describes the methodology that was implemented during the soil and groundwater investigation at the site. The objectives of the sampling procedures were to provide an accurate assessment of the current soil and groundwater conditions and to minimize the potential for cross-contamination during sampling operations.

4.1 PRE-FIELD ACTIVITIES

This section describes the tasks PSI performed prior to initiating any field activities. These tasks included:

- 1) attending the Caltrans Task Order Meeting;
- 2) reviewing of pertinent results of past site investigation reports;
- 3) preparing the Pre-Work Site Visit Checklist;
- 4) locating any underground utility lines in conjunction with Underground Service Alert (USA); and
- 5) obtaining two Caltrans Encroachment permits from the Caltrans Maintenance Permit Office and two Drilling Permits from Alameda County Public Works Agency.

4.1.2 Task Order Meeting and Pre--Work Site Visit

A Task Order Meeting was completed on March 10, 2000, with Mr. Frank Poss and Ms. Adriana Constantinescu of PSI and Ms. Jill Pollock and Mr. Peter Altherr of Caltrans in attendance. The primary purpose of the meeting was to familiarize PSI with site conditions that may impact field operations.

At the Pre-Work Site Visit on March 10, 2000, the boring locations were determined and a Pre-Work Site Visit Checklist was completed. Topics specified in the checklist included identification of borehole locations, confirmation of underground utility clearance, location of water/power supply sources, and storage areas for drill cuttings.

4.1.2 Health and Safety Plan

Prior to the commencement of field activities at the site, a site-specific Health and Safety Plan (HSP) was developed in compliance with 29 CFR 1910.120 and Title 8 California Code of Regulations, § 5192, under the supervision of a Certified Industrial Hygienist. The HSP was revised by DTSC and their conclusions were presented in a Memorandum dated April 20, 2000. The HSP was designed to address the potential hazardous materials that may be encountered during field activities at the site. Further, the HSP was

designed to minimize the exposure to potentially hazardous materials and unsafe working conditions to on-site personnel.

4.1.3 Utility Clearance

At least 48 hours prior to drilling activities, PSI contacted Underground Service Alert (USA) to identify utility lines that may underlie the areas of investigation. Two USA numbers were obtained for this project: 0074308 for Site JA and 0074319 for Site CF.

4.1.4 Project Permits

PSI obtained two drilling permits (one per each site) from Alameda County-Public Works Department and two encroachment permits from Caltrans – District 4, prior to drilling. Copies of permits are included in Appendix E.

4.2 SOIL BORINGS

Seven soil borings were advanced to investigate the soil and groundwater quality at the sites. The boring locations are presented in Figure 2 and were selected by Caltrans to assess the soil and groundwater quality down gradient of the former USTs and the effectiveness of the remedial excavations performed at both sites. The local groundwater gradient dips gently to the southeast towards the estuary (Laidlaw, 1995). V&W Drilling of Rio Vista, California provided the drilling services.

The borings were drilled using a hollow stem augers rig. The borings were extended to a maximum depth of approximately 5 meter (m) (16.4 feet bgs) and were 0.20 m (8 inches) in diameter.

At Site JA, soil samples were collected at the groundwater interface to assess the residual levels of contaminants in soil, if any, after the remedial excavation performed at this site. Groundwater was encountered at 2.3 m (7.5 feet) and 2.22 m (7 feet) below ground surface(bgs). Soil samples were collected at 2.2 m (7 feet) and at 1.95 m (6.5 feet) bgs.

At Site CF, four soil samples per boring were proposed to be collected at depths of 0.5, 1, and 2 m (1.64, 3.28, and 6.56 feet, respectively) bgs and at the groundwater interface to assess the vertical and horizontal extent of soil contamination, if any. Because groundwater was encountered at 2 m (6.56 feet) bgs, only three soil samples were collected from each boring. Field work for drilling and soil sampling activities were conducted in accordance with the field procedures described in Appendix A.

4.2.1 Soil Sampling Protocol

Soil samples were collected by a PSI geologist working under the supervision of a State of California Registered Geologist. The samples were collected using a 0.05 meter (2 inches) diameter stainless steel sampler containing three brass tubes. Upon retrieval of the sampler, a representative undisturbed soil sample was preserved for chemical analyses in a 0.15 meter (6 inches) stainless steel tube. Once the sampler was retrieved the ends of the sample tube were covered with Teflon sheets and capped with polyethylene end caps. The soil sample was labeled and placed in a zip-lock bag in a chilled cooler.

The soil samples were logged on chain-of-custody records and transported to Centrum Analytical of Redlands, California, a California Department of Health Services certified hazardous materials testing laboratory, following chain-of-custody protocol.

4.2.2 Soil Classification

Soil was described by a PSI geologist and recorded on a field boring log for each boring drilled. The data recorded on the logs were based on examination of soil samples retrieved and drilling conditions observed in the field. Boring logs included information regarding the location of the boring, type of sampler used, and geologic descriptions of materials encountered.

Soils were classified according to the "Soil and Rock Logging Classification Manual" prepared by the State of California, Department of Transportation. The Soil and Rock Logging Classification Manual is consistent with the Unified Soil Classification System. Other information to be recorded on the logs included indications of contamination and the occurrence of groundwater. Organic vapor analyzer (OVA) measurements for soil samples were recorded on the field boring logs.

4.3 MONITORING WELL INSTALLATION AND DEVELOPMENT

Following drilling of the borings, PSI installed four groundwater monitoring wells at Site JA and three groundwater monitoring wells at Site CF (see Figure 2 for selected locations). The wells were installed through the hollow-stem augers. The well casings consisted of 5.08-centimeter (cm) (2-inch) inside diameter Schedule 40 PVC casing with 0.0508 cm (0.020-inch) machine-slotted screen. The selection of the screen size and filter pack material was performed using the description presented in the referenced reports of the first encountered aquifer as consisting of the Merritt sand, a yellowish brown silty and clayey sand. The length of screen was 4 m (14 feet). The sand filter pack was placed slow free-fall, from the bottom of the borehole until approximately 0.6 m (2 feet) bgs. The

drilling measuring tape was also moved continuously inside the annular space to prevent the bridging. In addition, the volume of the filter pack required was calculated and recorded before placement and the actual volume used was determined and recorded during well construction. The sand pack extended approximately 0.3 meters (1 feet) above the screen interval. Monterey-type number 3 sand was used for the sand pack. Approximately 0.3 meter (1 foot) of hydrated bentonite chips was placed above the sand pack by slow free-fall; neat cement mixed at a ratio of 5 gallons of water per 94-pound sack of cement provided the annular seal from the top of the bentonite to grade [approximately 0.3 m (1 foot)]. Well casing (including the well locking cap was completed approximately 0.05 m (2 inches) bellow the traffic-rated road box (Christie box) cover. The road box was completed approximately one inch above the existing grade surface to allow for precipitate run off. All concrete works, both inside and outside the road traffic box, were completed with a smooth finish.

The groundwater monitoring wells were initially developed in order to clean the well and stabilize the sand and disturbed aquifer materials from around the screened internal perforations. Well development was accomplished by bailing.

4.4 DECONTAMINATION PROCEDURES

Decontamination procedures were implemented to maintain sample integrity and to prevent cross-contamination between sampling locations. All sampling equipment was cleaned with a non-phosphate detergent and rinsed twice with deionized water prior to use at a new sampling location or was pressure washed. Sampling equipment included:

- Stainless-steel sampling equipment,
- Drilling equipment,
- Groundwater sampling equipment, and
- Sounders.

4.5 STORAGE AND DISPOSAL OF GENERATED WASTES

Water from equipment cleaning, well development, well purging activities, and soil cuttings were stored in individually labeled 55-gallon drums. The drums were placed on the southwestern corner of the Site CF and had metals covers. Each drum was labeled with the project number and location, generation date and soil boring number.

Disposition of the soil cuttings and waste water will be determined upon receipt of laboratory analytical results of the soil and water samples. PSI will arrange for the

management and appropriate disposal of soil and water generated during the field activities under Contract 43A0012.

4.6 MONITORING WELL SAMPLING

Prior to groundwater sampling, the groundwater elevation was measured from the top of the well casing using an electrical sounder. Static water levels were measured to the nearest \pm 0.003 m (0.01 foot) from the top of the casing. The data is presented in Table 1 and Figure 3. The elevation survey of the top of the well casings was performed by a State of California licensed surveyor and data was submitted in both metric and English units using the vertical datum NGVD 1929 and horizontal datum CCS27 Zone 3. The results of the survey are included in Appendix C. This data was collected to allow calculation of the hydraulic gradient. Each monitoring well was purged of a minimum of three well volumes until pH, conductivity, and temperature stabilized. The purging was completed by bailing.

Samples used to be analyzed for volatile organic compounds were collected first. The groundwater samples were collected according to PSI's standard protocol, presented in Appendix A.

Following groundwater sample collection, the samples were logged on a chain-of-custody record and stored in an ice chest at 4 degrees Celsius. Sample preservatives were utilized as instructed by the analytical laboratory. All transportation and handling of the groundwater samples followed chain-of-custody protocol.

5.0 LABORATORY ANALYSIS PROGRAM

The soil and groundwater samples collected during this investigation were submitted to Centrum Analytical, a State of California Department of Health Services certified hazardous waste laboratory. A summary of the types of analyses and analytical methods is presented below and in the Table 2 through Table 7. Copies of the analytical results are attached in Appendix D.

All soil and groundwater samples collected were analyzed for the following constituents:

- EPA Modified 8015 TPH-Gasoline
- EPA Method 8015 modified TPH as Diesel (TPH-D)
- EPA Method 8015 modified Motor Oil
- ICAP EPA Method 6010 Heavy Metals
- EPA Method 8260B Volatile Organic Compounds (VOCs); including MTBE and oxygenates.
- EPA Method 8270C Semi-Volatile Organic Compounds (SVOCs).

Soil and groundwater samples collected from the Site JA and from the proposed groundwater monitoring well CF-1, located on Site CF, were tested for extra constituents, as follows:

- EPA Method 8081 Organochlorine pesticides
- EPA Method 8082 PCBs.

During groundwater purging and sampling the following parameters were measured:

- pH (field measurement)
- Conductivity (field measurement)
- Temperature (field measurement)

Grain size distribution of two soil samples collected from the Site JA and one soil sample collected from the Site CF were analyzed to characterize the shallow aquifer materials conditions. Results of the grain size tests are attached in Appendix D.

6.0 FIELD QUALITY ASSURANCE/QUALITY CONTROL

The following equipment calibration procedure and field documentation procedures were implemented by PSI field personnel.

6.1 SAMPLE IDENTIFICATION

Soil samples collected in the field were labeled according to standard protocol, as described in Appendix A.

6.2 CHAIN-OF-CUSTODY PROCEDURES

Chain-of-Custody records were used to document sample handling and shipping procedures. Chain-of-Custody records traced the samples from collection, through any custody transfers to the analytical laboratory. Information recorded on the Chain-of-Custody records included location of sample collection, sample identification, number, date and time of collection, number and type of sample containers, and analyses requested. The shipping conditions were also described on the Chain-of-Custody records. The name of the sampler(s) as well as the name of the person relinquishing the samples were documented. Chain-of-Custody procedures are described in Appendix A.

6.3 FIELD INSTRUMENTS

An organic-vapor analyzer (OVA) was used in the field for health and safety monitoring, as well as site assessment purposes. The OVA was used as an indicator of total petroleum hydrocarbons in soil samples and for health and safety purposes. A copy of the on-site calibration and air monitoring data sheet is attached to our report in Appendix F.

7.0 DATA EVALUATION AND DISCUSSION

Summaries of the analytical results are presented in Table 2 through Table 9. A copy of the laboratory reports and chain-of-custody records are included in Appendix D.

7.1 J & A TRUCK REPAIR SITE (SITE JA)

Laboratory Analytical Results - Soil

Tables 2 and 3 present a statistical analysis of the analytical data for soil samples collected at Site JA. For each contaminant a count of concentrations reported above the detection limit, a concentration maximum, a concentration minimum, a concentration average of the detected concentrations, and concentration standard deviation is provided.

Oil and Grease

The soil oil and grease analytical results are presented in Table 2 and Figure 4. Oil and grease was not detected above the detection limit of 10 mg/kg from soil samples collected during this investigation. The JAI's investigation performed in 1996, identified oil and grease in five of the soil samples collected from the walls of the remedial excavation at concentrations ranging from 88 mg/kg to 200 mg/kg (JAI, 1996).

Total Petroleum Hydrocarbons - Diesel (TPH-D)

The TPH-D analytical results for soil samples are presented in Table 2 and Figure 4. TPH-D was not detected in the soil samples collected from this site during this investigation. TPH-D was not detected in the previous investigations performed at Site JA (JAI, 1996).

<u>Total Petroleum Hydrocarbons – Gasoline (TPH-G)</u>

The TPH-G analytical results for soil samples are presented in Table 2 and Figure 4. TPH-G was not detected in the soil samples collected during this investigation at Site JA. Soil samples collected from the bottom of the remedial excavation performed at the subject site in 1995, contained TPH-G at levels between 13 mg/kg and 3,100 mg/kg (JAI, 1996).

Volatile Organic Compounds (VOC) detected by EPA Method 8260B.

The VOC analytical results for soil samples collected during this investigation are presented in Table 2 and Figure 4. Five VOCs were detected in the four collected soil samples. The detected levels are well bellow the Cypress Preliminary Remedial Goals (PRG)s for each specific chemical.

1,1-Dichloroethane was detected in three soil samples collected from soil borings JA-1, JA-3, and JA-4 (0.001 mg/kg, same as the detection limit). This level is with 0.419 mg/kg below the Cypress PRG for this chemical.

Naphthalene was detected in two soil samples collected from soil borings JA-3 and JA-4 at levels between 0.003 to 0.02 mg/kg. The maximum detected value is with 81.98 mg/kg below the Cypress PRG level for soil. The average concentration was 0.0115 mg/kg.

Styrene was detected in two of the soil samples collected from the soil borings JA-2 and JA-3 at a level equal with the detection limit of 0.001 mg/kg. No Cypress PRG was provided for this chemical.

1,1,1-Trichloroethane was detected in all soil samples collected during this investigation from the Site JA. Detected levels ranged from 0.005 to 0.007 mg/kg. The maximum detected level is with 469.993 mg/kg below the Cypress PRG level. The average concentration for 1,1,1-Trichloroethane was 0.006 mg/kg.

Trichlorotrifluorethane was detected in all four soil samples collected from the Site JA at levels between 0.005 to 0.008 mg/kg. The average concentration was 0.007 mg/kg. No Cypress PRG for soil is provided for this chemical.

Semi-Volatile Organic Compounds (SVOCs) by EPA Method 8270C

The SVOC analytical results for soil samples collected during this investigation are presented in Table 2 and Figure 4. Five SVOCs were detected in the tested soil samples. The detected levels are well below the Cypress PRG levels for soil for each specific chemical.

Acenaphthylene was detected only in one soil sample collected from the soil boring JA-3. at a detected level of 0.055 mg/kg. No Cypress PRG is provided for this chemical.

Fluoranthene was detected only in one soil sample collected from the soil boring JA-3 at 2.25 m (7 feet) below ground surface (bgs). The detected level was 0.072 mg/kg, with 2299.928 mg/kg below the Cypress PRG level for soil.

Napthalene was detected only in one soil sample collected from the soil boring JA-3. The detected level was 0.28 mg/kg which is with 81.72 mg/kg below the Cypress PRG for soil.

Phenanthrene was detected only in one soil sample collected from the soil boring JA-4. The detected level was 0.1 mg/kg, with 0.034 mg/kg above the detection limit. No Cypress PRG for soil is provided for this chemical.

Pyrene was detected only in one soil sample collected from the soil boring JA-4. The detected level was 0.14 mg/kg, with 1,699.86 mg/kg below the Cypress PRG level for soil.

Organochlorine Pesticides by EPA Method 8080

Organochlorine pesticides were not detected in the soil samples collected for this investigation. Only one confirmatory soil samples collected after the 1995 remedial excavation showed detectable concentrations of organochlorine pesticides (0.005 mg/kg of p,p-DDE) (JAI, 1996).

PCBs by EPA Method 8080

PCBs were not detected above the detection limits in the soil samples collected during this investigation. The confirmatory soil samples collected after the remedial excavation showed detectable concentrations of PCBs (up to 1.2 mg/kg of Aroclor) (JAI, 1996).

Metals by EPA Method 6010

Ten metals were detected above the detection limit in the soil samples collected for this investigation. The detected levels were well below the PRGs for the industrial soils. Antimony, Beryllium, Cadmium, Mercury, Molybdenum, Selenium, and Silver were not detected in the soil samples collected during this investigation. No metals were reported by the previous investigation above the Cypress PRGs for soil.

Antimony was not detected above the detection limit in the four soil samples collected during this investigation at Site JA. Previous soil samples analytical results did not report levels above the Cypress PRG level for soil.

Arsenic was detected in all soil samples at levels between 2.1 mg/kg and 3.0 mg/kg. The average value was 2.5 mg/kg. The maximum detected value is with 1.6 mg/kg below the Cypress PRG value for soil.

Barium was detected in all soil samples at levels between 37 mg/kg and 56 mg/kg. The average value was 46.75 mg/kg. The maximum detected value is with 11,944 mg/kg below the Cypress PRG value for soil.

Chromium was detected in all soil samples at levels between 30 mg/kg and 48 mg/kg. The average value was 37.75 mg/kg.

Cobalt was detected in all soil samples at levels between 4.6 mg/kg and 5.8 mg/kg. The average value was 5.325 mg/kg. No Cypress PRG value for soil is provided for cobalt.

Copper was detected in all soil samples at levels between 5.3 mg/kg and 8.4 mg/kg. The average value was 7.025 mg/kg. The maximum detected value is with 4,991.6 mg/kg below the Cypress PRG value for soil.

Lead was detected in all soil samples at levels between 1.5 mg/kg and 3.9 mg/kg. The average value was 2.475 mg/kg. The maximum detected value is with 836.1 mg/kg below the Cypress PRG value for soil.

Nickel was detected in all soil samples at levels between 26 mg/kg and 35 mg/kg. The average value was 31.25 mg/kg. The maximum detected value is with 9 mg/kg below the Cypress PRG value for soil.

Thallium was detected in two soil samples collected from soil borings JA-1 and JA-3, at levels between 19 mg/kg and 34 mg/kg. The average value was 26.5 mg/kg. The maximum detected value is with 7 mg/kg above the Cypress PRG value for soil.

Vanadium was detected in all soil samples at levels between 21 mg/kg and 30 mg/kg. The average value was 26.75 mg/kg. The maximum detected value is with 1,170 mg/kg below the Cypress PRG value for soil.

Zinc was detected in all soil samples at levels between 19 mg/kg and 26 mg/kg. The average value was 23.25. The maximum detected value is with 49,974 mg/kg below the Cypress PRG value for soil.

Soil Sieve Analysis

Two soil samples collected from the soil borings JA-2 and JA-4 were tested by PSI Geotechnical Laboratory, located in Corona, California. The soil sample collected from soil boring JA-2 at 2.25 m (7 feet) below ground surface was described as an orange-

brown silty fine and medium sand (SM). For this soil sample, 99% of the soil particles passed sieve #4 and 18% of the soil particles passed sieve #200. Soil sample collected from soil boring JA-4 at 1.5 m (5 feet) below ground surface was described a black gravelly sand (SP) with brown clayey sand with gravel (SC). For this soil sample, 62% of the soil particles passed sieve #4 and 18% of the soil particles passed sieve #200.

Laboratory Analytical Results - Groundwater

Groundwater samples were collected from the four new four installed groundwater monitoring wells, after developing and purging. Wells were purged until pH, temperature, and conductivity stabilized. Average measurements were pH (6.7), temperature (17.8 C), and conductivity (3,951 microSiemens).

No floating product or product sheen was observed in any groundwater sample collected at Site JA. Floating product was not reported in the previous investigations (JAI, 1996 and ESI, 1995).

Table 4 and 5 present a statistical analysis and a summary of the groundwater analytical data. For each contaminant a count of concentrations reported above the detection limit, a concentration maximum, a concentration minimum, a concentration average of the detected concentrations, and concentration standard deviation is provided.

Motor Oil

The groundwater oil and grease analytical results are presented in Table 4 and Figure 5. Motor oil was not detected above the detection limit of 10mg/L in the water samples collected during this investigation. Oil and grease was reported only in the grab groundwater sample collected from this site near the former UST for the ESI's investigation at a level of 2 mg/l (ESI, 1995).

Total Petroleum Hydrocarbons - Diesel

The TPH-D analytical results are presented in Table 4 and Figure 5. TPH-D was detected only in the groundwater sample collected from groundwater monitoring well JA-2 (0.8 mg/l). Well JA-2 is located along the western side of the property, at the limit of the remedial excavation. It is noted that TPH-D was not detected in the grab groundwater sample collected on August 30, 1995 (JAI, 1996, Figure 1-13).

Total Petroleum Hydrocarbons - Gasoline

The TPH-G analytical results are presented in Table 4 and Figure 5. TPH-G was detected only in one groundwater sample collected from groundwater monitoring well JA-2 (0.77 mg/l). This level is well below the levels of TPH-G detected in the previous grab groundwater sample collected on August 30, 1995 (32 mg/L) (JAI, 1996, Figure 1-13).

Volatile Organic Compounds (VOCs) by EPA Method 8260

Fourteen VOCs were detected in the water samples collected from the new four installed groundwater monitoring wells. VOCs analytical results are presented in Table 4 and Figure 5. One groundwater sample collected from well JA-4 contained thirteen of the detected VOCs. This groundwater monitoring well is located down-gradient of the former on-site sumps. The other three groundwater samples contained only minor amounts of detected VOCs. The detected concentrations of VOCs are less than the detected amounts in the grab groundwater sample collected on August 30, 1995 (JAI, 1996).

- 1,1-Dichloroethane was detected only in one groundwater sample collected from well JA-4 (0.0082mg/l). This level is with 0.0032 mg/l above the MCL for drinking water for this compound. No 1,1-Dichloroethane was reported before for this project site.
- 1,2 Dichloroethane was detected only in one groundwater sample collected from well JA-2 (0.0088mg/l). This level is with 0.0083 mg/kg above the EPA Region 9 PRG level for tap water for this compound. No 1,2-Dichloroethane was reported before for this project site.
- 1,1-Dichloroethene was detected only in one groundwater sample collected from well JA-4 (0.0062 mg/l). This level is with 0.00608 mg/kg above the EPA Region 9 PRG level for drinking water for this compound. No 1,2-Dichloroethene was reported before for this project site.

Naphthalene was detected in all four groundwater samples collected from this project site. The detected levels ranged between 0.0013 to 0.0083 mg/l. The average value of 0.0058 mg/l. The maximum level is with 0.0021 mg/l above the EPA Region 9 PRG level for tap water. No naphthalene was reported before in the grab groundwater sample collected at Site JA.

Tetrachloroethene (PCE) was detected only in one groundwater sample collected from the well JA-4 (0.13 mg/l). This level is with 0.125 mg/l above the MCL for drinking water. Trichloroethene (TCE) was detected in two of the tested groundwater monitoring wells, JA-2 and JA-4. The detected levels were 0.0007 and 0.63 mg/l, respectively. Only the level detected in well JA-4 is with 0.625 mg/l above the MCL for drinking water.

Vinyl chloride was detected only in one groundwater sample collected from the well JA-4 (0.0011 mg/l). This level is with 0.006 mg/l above the MCL for drinking water.

Benzene was detected only in the groundwater sample collected from well JA-4 (0.0007mg/l). This level is with 0.0093 mg/l below the MCL for drinking water for this compound and well below the previous maximum detected level in the grab groundwater sample collected on August 30, 1995 (32 mg/l) (JAI, 1996).

Chloroform was detected only in one groundwater sample collected from well JA-4 (0.0017mg/l). This level is with 0.0093 mg/kg below the EPA Region 9 PRG level for tap water for this compound.

Cis-1,2-Dichloroethene was detected only in one groundwater sample collected from well JA-4 (0.057 mg/l). No 1,2-Dichloroethane was reported before for this project site. No MCL or EPA Region 9 PRG is provided for this chemical.

Trans-1,2-Dichloroethene was detected only in one groundwater sample collected from well JA-4 (0.0008 mg/l). No trans-1,2-Dichloroethane was reported before for in the grab groundwater samples collected for this project site. No MCL or EPA Region 9 PRG is provided for this chemical.

1,1,1-Trichloroethane and 1,1,2-Trichloroethane were detected only in the well JA-4 at levels of 0.0042 and 0.0006 mg/l, respectively. These two levels are with 0.1958 mg/l and 0.0044 mg/l below the MCLs for drinking water.

Trichlorotrifluoroethane was detected only in one groundwater sample collected from the well JA-4 (0.0075 mg/l). This level is with 0.1425 mg/l below the MCL for drinking water.

Semivolatile Organic Compounds (SVOCs) using EPA Method 8270

SVOCs analytical results are presented in Table 4 and Figure 5. Only one compound was detected by EPA Method 8270: napthalene, in the groundwater sample collected from well JA-1 (0.002mg/l). This level is with 0.0042 mg/l below the PRG level for tap water. Naphthalene levels detected by EPA Methods 8270 and 8260 cannot be compared because different sample preparation methods were used in the laboratory.

Organochlorine Pesticides by EPA Method 8080

Organochlorine pesticides were not detected above the detection limit in the groundwater samples collected for this investigation. The previous investigation results do not present detected levels of organochlorine pesticides above the detection limits.

Polychlorinated Biphenyls (PCBs)

Polychlorinated Biphenyls (PCBs) were not detected above the detection limits in the groundwater samples collected for this investigation. The previous investigation results did not present detected levels of PCBs above the detection limits in the tested grab groundwater samples.

7.2 CONTAINER FREIGHT SITE (SITE CF)

Laboratory Analytical Results - Soil

Tables 6 and 7 present a statistical analysis of the analytical data for soil samples collected at former Container Freight site (Site CF). For each contaminant a count of concentrations reported above the detection limit, a concentration maximum, a concentration minimum, a concentration average of the detected concentrations, and concentration standard deviation is provided.

Motor Oil

The soil motor oil analytical results are presented in Table 6 and Figure 4. Oil and grease was detected above the detection limit in 8 of the ten tested soil samples, at levels between 23 mg/kg to 630 mg/kg. The maximum level (630 mg/kg) was detected in the soil boring advanced for groundwater monitoring well CF-1, at 0.5 meters (m) (1.64 feet below ground surface (bgs)). The motor oil concentration decreases with depth, i.e. at 2.0 m (6.56 feet) the detected level was 35 mg/kg. In the soil boring CF-2, the maximum detected level was 520 mg/kg at 1 m bgs. Soil samples collected from soil boring CF-3 contained comparable levels of motor oil (<100 mg/kg). Motor oil levels detected in the soil samples collected at the time of the former UST removal were 180 mg/kg to 1,100 mg/kg (JAI, 1995). Possible motor oil was reported by 1997 investigation performed by Harding Lawson Associates (HLA) at a level of 7,900 mg/kg.

Total Petroleum Hydrocarbons - Diesel (TPH-D)

The TPH-D analytical results for soil samples are presented in Table 6 and Figure 4. TPH-D was detected in all tested soil samples collected during this investigation, at levels ranging between 19 mg/kg to 370 mg/kg. The detected levels decrease with depth only in the soil samples collected from soil boring CF-1. The results of the soil samples collected from CF-2 and CF-3 did not present the same trend. TPH in the diesel range was detected by a previous subsurface investigation at a level up to 380 mg/kg in the soil sample collected from the former UST excavation pit (JAI, 1995). HLA's soil sampling performed in 1997 showed up to 2,600 mg/kg of TPH-D.

Total Petroleum Hydrocarbons - Gasoline

The TPH-G analytical results for soil samples are presented in Table 6 and Figure 4. TPH-G was detected only in two of the soil samples collected during this investigation from this site, in soil borings CF-1 and CF-2. The detected levels were 0.77 mg/kg and

0.69 mg/kg. These levels were below the level of TPH-G detected at the time of former UST removal (6.4 mg/kg).

Volatile Organic Compounds (VOC) detected by EPA Method 8260B.

The VOC analytical results for soil samples collected during this investigation are presented in Table 6 and Figure 4. Two VOCs (benzene and naphthalene) were detected in the soil samples collected from this site. Benzene was detected in two soil samples collected at 1 m and 3 m below ground surface (bgs) from soil borings CF-1 and CF-2 (0.001 mg/kg and 0.4 mg/kg, respectively, with an average of 0.2 mg/kg). The maximum value is below the previous maximum detected level of 13 mg/kg (Caltrans, 1998).

Naphthalene was detected in seven soil samples collected at different depths (0.5 m, 1 m, 2 m, and 3 m bgs) from soil borings CF-1, CF-2, and CF-3. The detected levels were between 0.005 and 390 mg/kg which are below the previous maximum detected value of 2,600 mg/kg (Caltrans, 1998). The average concentration was 56 mg/kg.

Semi-Volatile Organic Compounds (SVOCs) by EPA Method 8270C

The SVOC analytical results for soil samples collected during this investigation are presented in Table 6 and Figure 4. Sixteen SVOCs were detected in the tested soil samples, as follows:

Benzo[a]anthracene was detected in five soil samples collected from all soil borings, at detected levels between 0.91 mg/kg and 16 mg/kg. The maximum detected level (16 mg/kg) is below the previous maximum detected level of 300 mg/kg (Caltrans, 1998).

Benzo[a]pyrene was detected in 7 soil samples collected from all soil borings, at detected levels between 0.79 mg/kg to 40 mg/kg. The average value was 9.75 mg/kg. The maximum detected level (40 mg/kg) is below the previous maximum detected level of 520 mg/kg (Caltrans, 1998).

Benzo[b]fluoranthene was detected in 8 soil samples collected from all soil borings at depths between 0.5 m and 2 m, at detected levels between 0.59 mg/kg to 47 mg/kg. The average value was 10.7 mg/kg. The maximum detected level (47 mg/kg) is below the previous maximum detected level of 240 mg/kg (Caltrans, 1998).

Benzo[k]fluoranthene was detected in 7 soil samples collected from all soil borings at depths between 0.5m and 2 m bgs, at detected levels between 0.61 mg/kg and 47 mg/kg.

The average value was 12.1 mg/kg. The maximum detected level (47 mg/kg) is below the previous maximum detected level of 140 mg/kg (Caltrans, 1998).

Dibenzo[a,h]anthracene was detected in 3 soil samples collected from the soil borings CF-2 and CF-3 at depths between 1 m and 2 m bgs, at detected levels between 1.2 mg/kg to 6.3 mg/kg. The average value was 3.1 mg/kg. The maximum detected level (6.3 mg/kg) is below the previous maximum detected level of 67 mg/kg (Caltrans, 1998).

Indeno[1,2,3-cd]pyrene was detected in 4 soil samples collected from the soil borings CF-2 and CF-3 at depths between 0.5 to 2 m bgs, at detected levels between 2.6 mg/kg to 30 mg/kg. The average value was 13.5 mg/kg. The maximum detected level (30 mg/kg) is below the previous maximum detected level of 480 mg/kg (Caltrans, 1998).

Acenaphthene was detected only in one soil sample collected from the soil boring CF-2, at 0.5 m bgs (0.34 mg/kg). The detected level is below the previous maximum detected level of 170 mg/kg (Caltrans, 1998).

Acenaphthylene was detected in five soil samples collected from the soil borings CF-1 at 2 m bgs, CF-2 at 0.5 m and 2 m bgs, and CF-3 at 1 and 2 m bgs. The detected levels were between 0.675 mg/kg and 2 mg/kg. The maximum detected level (2 mg/kg) is below the previous maximum detected level of 230 mg/kg (Caltrans, 1998).

Anthracene was detected in five soil samples collected from all soil borings, at detected levels between 0.5 mg/kg and 4.6 mg/kg. The average value was 2 mg/kg. The maximum detected level (4.6 mg/kg) is below the previous maximum detected level of 180 mg/kg (Caltrans, 1998).

Benzo[g,h,i]perylene was detected in 7 soil samples collected from all soil borings at depths between 0.5 m and 2 m, at detected levels between 1 mg/kg to 33 mg/kg. The average value was 9.7 mg/kg. The maximum detected level (33 mg/kg) is below the previous maximum detected level of 700 mg/kg (Caltrans, 1998).

Chrysene was detected in 7 soil samples collected from all soil borings at depths between 0.5 m and 2 m bgs, at detected levels between 0.62 mg/kg and 19 mg/kg. The average value was 5.67 mg/kg. The maximum detected level (19 mg/kg) is below the previous maximum detected level of 470 mg/kg (Caltrans, 1998).

Fluoranthene was detected in 7 soil samples collected from all soil borings at depths between 0.5 m and 2 m bgs, at detected levels between 0.59 mg/kg to 62 mg/kg. The

average value was 16.7 mg/kg. The maximum detected level (62 mg/kg) is below the previous maximum detected level of 1,100 mg/kg (Caltrans, 1998).

Fluorene was detected in 4 soil samples collected from the soil borings CF-2 and CF-3 at depths between 0.5 m and 2 m, at detected levels between 0.53 mg/kg to 1.6 mg/kg. The average value was 0.88 mg/kg. The maximum detected level (1.6 mg/kg) is below the previous maximum detected level of 160 mg/kg (Caltrans, 1998).

Naphthalene was detected in 6 soil samples collected from all soil borings at depths between 0.5 m to 2 m. The detected levels were between 0.37 mg/kg and 2.4 mg/kg. The average value was 1.3 mg/kg. The maximum detected level (2.4 mg/kg) is below the previous maximum detected level of 2,600 mg/kg (Caltrans, 1998).

Phenanthrene was detected in 7 soil samples collected from all soil borings at depths between 0.5 m and 2 m. The detected levels were between 0.81 mg/kg to 26 mg/kg. The average value was 8.5 mg/kg. The maximum detected level (26 mg/kg) is below the previous maximum detected level of 1,800 mg/kg (Caltrans, 1998).

Pyrene was detected in 8 soil samples collected from all soil borings at depths between 0.5 m and 2 m bgs. The detected levels were between 0.85 mg/kg to 74 mg/kg. The average value was 8.5 mg/kg. The maximum value (74 mg/kg) is below the previous maximum detected level of 1,200 mg/kg (Caltrans, 1998).

Organochlorine Pesticides by EPA Method 8080

Organochlorine pesticides were detected only in the soil samples collected for this investigation from the soil borings CF-1 and CF-2. No organochloride pesticides were tested by the previous soil samplings performed at this site (Caltrans, 1998).

4,4-DDE was detected at two different levels, 0.5 m and 1 m bgs, in soil boring CF-1. The detected levels were between 0.009 mg/kg and 0.018 mg/kg. The average value was 0.0135 mg/kg.

4,4'-DDD was detected in two soil samples collected from soil borings CF-1 and CF-2, at levels between 0.003 mg/kg and 9.3 mg/kg. The average value was 4.6 mg/kg.

Dieldrin was detected only in one soil sample collected at 1 m bgs, from the soil boring CF-1, at a level of 0.002 mg/kg.

Endosulfan I was detected only in one soil sample collected at 0.5 m bgs, in the soil boring CF-1, at a level of 0.006 mg/kg.

PCBs by EPA Method 8080

PCBs as Arochlor-1260 was detected above the detection limit only in one soil sample collected from the soil boring CF-1 at 0.5 m bgs. The detected concentration is 0.082 mg/kg. Previous soil samplings performed at this site did not report PCBs above the detection limits.

Metals by EPA Method 6010

Twelve metals were detected above the detection limit in the soil samples collected for this investigation from the Container Freight site. Antimony, Beryllium, Selenium, Silver, and Thallium were not detected in the soil samples collected during this investigation.

Arsenic was detected in 9 soil samples at levels between 2.5 mg/kg and 12 mg/kg. The average value was 6.2 mg/kg. The maximum detected value is below the previous maximum detected value of 22 mg/kg (Caltrans, 1998).

Barium was detected in all soil samples at levels between 18 mg/kg and 130 mg/kg. The average value was 83.33 mg/kg. The maximum detected value is below the previous maximum detected value of 310 mg/kg (Caltrans, 1998).

Cadmium was detected in 2 soil samples at levels between 0.62 mg/kg and 0.28 mg/kg. The average value was 0.72 mg/kg. The maximum detected value is below the previous maximum detected value of 3.7 mg/kg (Caltrans, 1998).

Chromium was detected in all soil samples at levels between 2.9 mg/kg and 35 mg/kg. The average value was 22.8 mg/kg. The maximum detected value is below the previous maximum detected value of 5,000 mg/kg (Caltrans, 1998).

Cobalt was detected in all soil samples at levels between 0.59 mg/kg and 8.8 mg/kg. The average value was 5.46 mg/kg. The maximum detected value is below the previous maximum detected value of 2.2 mg/kg (Caltrans, 1998).

Copper was detected in all soil samples at levels between 14 mg/kg and 80 mg/kg. The average value was 43.9 mg/kg. The maximum detected value is below the previous maximum detected value of 920 mg/kg (Caltrans, 1998).

Lead was detected in all soil samples at levels between 22 mg/kg and 74 mg/kg. The average value was 54.7 mg/kg. The maximum detected value is below the previous maximum detected value of 27,000 mg/kg (Caltrans, 1998).

Mercury was detected in all soil samples at levels between 0.18 mg/kg and 0.3 mg/kg. The average value was 0.242 mg/kg. The maximum detected value is below the previous maximum detected value of 2.6 mg/kg (Caltrans, 1998).

Molybdenum was detected in all soil samples at levels between 0.66 mg/kg and 1.4 mg/kg. The average value was 0.88 mg/kg.

Nickel was detected in all soil samples at levels between 7.6 mg/kg and 41 mg/kg. The average value was 24.6 mg/kg. The maximum detected value is below the previous maximum detected value of 72 mg/kg (Caltrans, 1998).

Vanadium was detected in all soil samples at levels between 13 mg/kg and 37 mg/kg. The average value was 26.55 mg/kg. The maximum detected value is below the previous maximum detected value of 38 mg/kg (Caltrans, 1998).

Zinc was detected in all soil samples at levels between 30 mg/kg and 230 mg/kg. The average value was 108.8 mg/kg. The maximum detected value is below the previous maximum detected value of 17,000 mg/kg (Caltrans, 1998).

All concentrations of the ten metals detected during this investigation at the Site CF are below their maximum detected levels reported by the previous subsurface investigations performed at this site.

Soil Sieve Analysis

One soil sample collected from the soil boring CF-2 at 0.75 m (2.25 feet) bgs was tested by PSI Geotechnical Laboratory, located in Corona, California. The soil sample was described as a black gravelly sand (SW). For this soil sample, 62% of the soil particles passed sieve #4 and 18% of the soil particles passed sieve #200.

Laboratory Analytical Results - Groundwater

Groundwater samples were collected from the three new installed groundwater monitoring wells, after developing and purging. Wells were purged until pH, temperature, and conductivity stabilized. Average measurements were pH (6.9), temperature (18.7 C), and conductivity (1430 microSiemens).

No floating product was observed in any groundwater sample collected at the Site CF. A dark-gray color and sulfide and volatile odors were observed at the time of the groundwater sampling. Floating product was not reported in the previous investigations (JAI, 1996 and ESI, 1995).

Table 8 and 9 present a statistical analysis and a summary of the groundwater analytical data. For each contaminant a count of concentrations reported above the detection limit, a concentration maximum, a concentration minimum, a concentration average of the detected concentrations, and concentration standard deviation is provided.

Motor Oil

The groundwater TPH-motor oil analytical results are presented in Table 8 and Figure 5. Motor oil was not detected above the detection limits of 0.4 to 4.0 mg/L in the water samples collected during this investigation, at this site. No motor oil was reported in the grab groundwater samples collected from this site by the previous investigations (JAI, 1996 and JAI, 1995).

<u>Total Petroleum Hydrocarbons – Diesel</u>

The TPH-D analytical results are presented in Table 8 and Figure 5. TPH-D was detected in two groundwater samples collected from wells CF-1 and CF-2 (21 mg/kg and 2.8 mg/l, respectively). The average value was 8.5 mg/kg.

Total Petroleum Hydrocarbons - Gasoline

The TPH-G analytical results are presented in Table 8 and Figure 5. TPH-G was detected in all groundwater samples collected from this site at levels between 0.5 mg/l to 94 mg/l. TPH-G was detected in the grab groundwater sample collected on August 30, 1995 at a level of 32 mg/L (JAI, 1996, Figure 1-13).

Volatile Organic Compounds (VOCs) by EPA Method 8260

Nine VOCs were detected in the water samples collected from the new installed groundwater monitoring wells at Site CF. VOCs analytical results are presented in Table 8 and Figure 5. One groundwater sample collected from well CF-2 contained eight of the detected VOCs. The detected concentrations of VOCs are less than the detected amounts in the grab groundwater sample collected on August 30, 1995 (JAI, 1996).

Benzene was detected in all groundwater samples at levels between 0.0009 mg/l and 34 mg/l. The average value was 8.6 mg/l. The maximum detected level is with 33.999 mg/l above the MCL for drinking water for this compound. Previous investigations detected a maximum level of 2.4 mg/l of benzene (Caltrans, 1998).

Carbon Disulfide was detected only in one groundwater sample collected from well CF-2 (0.068 mg/l). This chemical was not reported by the previous subsurface investigations (Caltrans, 1998).

Naphthalene was detected in all groundwater samples collected from this site at levels between 0.0017 mg/l and 19 mg/l. The average value was 5.9 mg/L. Previous investigations detected a maximum level of 23 mg/l of naphthalene (Caltrans, 1998).

Styrene was detected in two groundwater samples collected from the wells CF-1 and CF-2 at levels between 0.0008 mg/l and 0.59 mg/l. The average value was 0.29 mg/l. The maximum detected level is with 0.49 mg/l above MCL for drinking water for this compound. Previous investigations detected a maximum level of 0.061 mg/l of styrene.

Toluene was detected in two groundwater samples collected from the wells CF-1 and CF-2 at levels between 0.01 mg/l and 1.6 mg/l. The average value was 0.54 mg/l. The maximum detected level is with 1.45 mg/l above the MCL for drinking water for this compound. Previous investigations detected a maximum level of 0.29 mg/l of toluene (Caltrans, 1998).

1,2,4-Trimethylbenzene was detected only in one groundwater sample collected from well CF-2 (0.0014 mg/l). This level is with 0.0036 mg/kg above the EPA Region 9 PRG level for tap water for this compound. No 1,2,4-Trimmethylbenzene was reported before for this project site (Caltrans, 1998).

Trichloroethene was detected only in one groundwater sample collected from well CF-1 (0.19 mg/l). This level is with 0.185 mg/l above the MCL for drinking water for this compound. No trichloroethene was reported before for this project site (Caltrans, 1998).

Ethylbenzene was detected in two of the groundwater samples collected from wells CF-1 and CF-2 (0.34 mg/l and 0.012 mg/l, respectively). This level is with 0.36 mg/l below the MCL for drinking water for this compound. Previous investigations detected a maximum level of 0.140 mg/l of ethylbenzene Caltrans, 1998).

Xylenes (total) were detected only in one groundwater sample collected from well CF-2 (0.011 mg/l). This level is 1.739 mg/l below the MCL for drinking water for this compound. Previous investigations detected a maximum level of 0.120 mg/l of xylenes (Caltrans, 1998).

Semivolatile Organic Compounds (SVOCs) using EPA Method 8270

SVOCs analytical results are presented in Table 8 and Figure 5. Nineteen SVOCs were detected by EPA Method 8270 in the groundwater samples collected from Site CF, as follows:

Benzo[a]anthracene was detected only in one groundwater sample collected from well CF-3 (0.004 mg/l). This value is with 0.003908 mg/l above the EPA Region 9 PRG level for tap water. Previous investigations detected a maximum level of 2.8 mg/l (Caltrans, 1998).

Benzo[a]pyrene was detected in two groundwater samples collected from the wells CF-2 and CF-3 at levels between 0.003 mg/l and 0.008 mg/l. The average value was 0.004 mg/l. The maximum detected level is with 0.0078 mg/l above the EPA Region 9 PRG level for tap water. Previous investigations detected a maximum level of 5,000 mg/l (Caltrans, 1998).

Benzo[b]fluoranthene was detected in two groundwater samples collected from the wells CF-2 and CF-3 at levels between 0.003 mg/l and 0.01 mg/l. The average value was 0.005 mg/l. The maximum detected level is with 0.009908 above the EPA Region 9 PRG level for tap water. Previous investigations detected a maximum level of 2.5 mg/l (Caltrans, 1998).

Benzo[k]fluoranthene was detected in two groundwater samples collected from the wells CF-2 and CF-3 at levels between 0.003 mg/l and 0.01 mg/l. The average value was 0.005 mg/l. The maximum detected level is with 0.00908 above the EPA Region 9 PRG level for drinking water. Previous investigations detected a maximum level of 2.7 mg/l (Caltrans, 1998).

Indeno[1,2,3-cd]pyrene was detected in only one groundwater sample collected from well CF-3 (0.006 mg/l). This level is with 0.00508 mg/l above the EPA Region 9 PRG level for tap water. Previous investigations detected a maximum level of 3,300 mg/l (Caltrans, 1998).

Naphthalene was detected in all groundwater samples at levels between 0.007 mg/l to 5.5 mg/l. The average value was 1.8 mg/l. The maximum detected level is with 5.4938 mg/l above the EPA region 9 PRG level for tap water. Previous investigations detected a maximum level of 23 mg/l (Caltrans, 1998).

Acenaphthene was detected only in two groundwater samples collected from the wells CF-1 and CF-2 at levels between 0.004 mg/l and 0.008 mg/l. The average value was

0.005 mg/l. The maximum detected level is 0.366 mg/l below EPA Region 9 PRG level for tap water. Previous investigations detected a maximum level of 4.2 mg/l (Caltrans, 1998).

Acenaphthylene was detected only in one groundwater sample collected from well CF-2 (0.069 mg/l). Previous investigations detected a maximum level of 3.6 mg/l (Caltrans, 1998). No MCL/PRG for drinking water was published for this chemical.

Anthracene was detected in two groundwater samples collected from the wells CF-2 and CF-3 at levels between 0.001 mg/l and 0.007 mg/l. The average value was 0.005 mg/l. The maximum detected level is with 1.793 below the EPA Region 9 PRG level for tap water. Previous investigations detected a maximum level of 4.3 mg/l (Caltrans, 1998).

Benzo[g,h,i]perylene was detected in one groundwater sample collected from the well CF-3 (0.009 mg/l Previous investigations detected a maximum level of 5.1 mg/l, (Caltrans, 1998). No MCL/EPA Region 9 PRG level is provided for this chemical.

Chrysene was detected in two groundwater samples collected from the wells CF-2 and CF-3 at levels between 0.002 mg/l and 0.006 mg/l. The average value was 0.0037 mg/l. The maximum detected level is with 0.0032 mg/l below the EPA Region 9 PRG level for tap water. Previous investigations detected a maximum level of 5.8 mg/l (Caltrans, 1998).

Dibenzofuran was detected in two groundwater samples collected from the wells CF-1 and CF-2 at a level of 0.003 mg/l. This detected level is with 0.021 mg/l below the EPA Region 9 PRG level for tap water. Previous investigations detected a maximum level of 0.000002 mg/l (Caltrans, 1998).

Fluoranthene was detected in all groundwater samples collected, at detected levels between 0.007 mg/kg and 0.014 mg/kg. The average value was 0.011 mg/kg. The maximum detected level is with 1.486 mg/l below the EPA Region 9 PRG level for tap water. Previous investigations detected a maximum level of 12 mg/l (Caltrans, 1998).

Fluorene was detected in two groundwater samples collected from the wells CF-1 and CF-2 at levels between 0.013 mg/l and 0.016 mg/l. The maximum detected level is with 0.224 mg/l below the PRG level for tap water. Previous investigations detected a maximum level of 1.6 mg/l (Caltrans, 1998), with 0.224 mg/l above the EPA Region 9 PRG level for tap water.

2-Methylnaphthalene was detected in two groundwater samples collected from the wells CF-1 and CF-2, at detected levels between 0.022 mg/kg and 0.067 mg/kg. The average

value was 0.032 mg/kg. Previous investigations did not report detected levels for this chemical (Caltrans, 1998).

4-Methylphenol was detected only in one groundwater sample collected from the well CF-2 (0.17 mg/l and 0.041 mg/l (duplicate)). The maximum detected level is with 0.01 mg/l below the EPA Region 9 PRG level for tap water. Previous investigations detected a maximum level of 0.370 mg/l (Caltrans, 1998) which is with 0.19 mg/l above the PRG level.

Phenanthrene was detected in all groundwater samples at levels between 0.004 mg/l to 0.055 mg/l. The average value was 0.035 mg/l. Previous investigations detected a maximum level of 22 mg/l (Caltrans, 1998).

Phenol was detected in two groundwater samples collected from the wells CF-1 and CF-2, at levels between 0.011 mg/l and 0.046 mg/l. The average value was 0.027 mg/l. The maximum detected level is with 21.959 mg/l below the EPA Region 9 PRG for tap water. Previous investigations detected a maximum level of 0.24 mg/l (Caltrans, 1998).

Pyrene was detected in all groundwater samples, at levels between 0.011 mg/l and 0.018 mg/l. The average value was 0.0145 mg/l. The maximum detected level is with 0.162 mg/l below the EPA Region 9 PRG level for tap water. Previous investigations detected a maximum level of 14 mg/l (Caltrans, 1998).

As presented above, eighteen of the SVOCs detected levels were well below the maximum detected levels reported by the previous investigations performed at this site.

Organochlorine Pesticides by EPA Method 8080

Organochlorine pesticides were not detected in the water samples collected during this investigation at Site CF. Previous investigations did not report detectable levels of organochlorine pesticides in the tested groundwater samples.

PCBs by EPA Method 8080

PCBs were not detected above the detection limit in the water samples collected during this investigation at Site CF. Previous investigations did not report detectable levels of PCBs in the groundwater samples.

Metals by EPA Method 6010

Only one metal was detected above the detection limit in the groundwater samples collected for this investigation from the Container Fright site. The detected level was 0.28 mg/l of barium. This detected level is with 2,599 mg/l below the EPA Region 9 PRG for tap water.

Previous investigations reported the following maximum levels of metals in the site groundwater: 0.054 mg/l of arsenic, 0.11 mg/l of barium, 0.006 mg/l cadmium, 1.4 mg/l of total chromium, 0.02 mg/l of cobalt, 7.0 mg/l of copper, 14 mg/l of lead, 0.008 mg/l of mercury, 1.8 mg/l of nickel, 0.01 mg/l of vanadium, and 28 mg/l of zinc.

7.0 CONCLUSIONS AND RECOMMENDATIONS

Conclusions

Based on the information presented in this report, the following conclusions have been reached:

Site JA

- None of the soil samples collected from the Site JA contained detectable levels of TPH-G, TPH-D, motor oil, organochlorine pesticides, and polychlorinated biphenyls. Five VOCs(1,1-Dichloroethane, Naphthalene, Styrene, 1,1,1-Trichloroethane, and Trichlorotrifluorethane) and five SVOCs (Acenaphthylene, Fluoranthene, Naphthlene, Phenanthrene, and Pyrene) were detected at levels well below the industrial PRG levels for soil.
- Ten metals (Arsenic, Barium, Chromium, Cobalt, Copper, Lead, Nickel, Thallium, Vanadium, Zinc) were detected above the detection limit in the soil samples collected for this investigation from the Site JA. The detected levels were well below the industrial PRG levels for soils. Antimony, Beryllium, Cadmium, Mercury, Molybdenum, Selenium, Silver, and Thallium were not detected in the soil samples collected during this investigation at Site JA. No metals were reported by the previous investigations above the industrial PRG levels for soil.
- Groundwater samples collected from the four new groundwater monitoring wells installed at Site JA did not contain motor oil, organochlorine pesticides or PCBs above the detection limits. Only seven of the detected VOCs (1,1-Dichloroethane, 1,2-Dichloroethane, 1,1-Dichloroethene, Naphthalene, Tetrachloroethane (PCE), Trichloethene (TCE), and Vinyl Chloride) were above MCL/EPA Region 9 PRG levels for drinking water. The highest levels of contaminants were detected in the groundwater sample collected from the groundwater monitoring well JA-4, located down gradient of the former site sumps.

Site CF

 Soil samples collected from the Site CF contained detectable levels of TPH-G, TPH-D, and motor oil. TPH-G was detected at levels between 0.69 mg/kg and 0.77 mg/kg. TPH-D was detected at levels ranging between 19 mg/kg to 370 mg/kg. The detected levels decrease with depth, between 0.5 m to 2 m (1.65 feet to 6 feet).

- Two VOCs (benzene and naphthalene) were detected at levels above the detection limit. Only maximum level of naphthalene was with 200 mg/l above the Cypress PRG level for soil. Sixteen SVOCs were detected in the tested soil samples above the detection limit. All of the detected levels were well below the maximum detected levels reported by the previous investigations performed at this site. The highest levels of SVOCs were detected in the soil samples collected from the boring CF-2 at 2 m (6 feet) below ground surface.
- Organochlorine pesticides as 4,4'-DDD was detected only in two soil samples, with the maximum level (9.3 mg/kg).
- Aroclor-1260 was the only PCBs detected at a level of 0.082 mg/kg. Previous soil samplings performed at this site had not reported PCBs levels above the detection limits.
- Twelve metals were detected in the collected soil samples at levels above the detection limits.
- Groundwater samples collected from the three new installed groundwater monitoring wells of the Site CF contained detectable levels of TPH-G, TPH-D, VOCs, and SVOCs. TPH-G was detected in all groundwater samples at levels between 0.5 mg/L and 94 mg/L. TPH-D was detected in two groundwater samples collected from the wells CF-1 and CF-2 at levels between 2.8 mg/L and 21 mg/L.
- Nine VOCs were detected in the water samples collected during this investigation.
 One groundwater sample collected from the groundwater monitoring well CF-2
 contained eight of the detected VOCs. Benzene, Carbon Disulfide, Ethylbenzene,
 Naphthalene, Styrene, Toluene, 1,2,4-Trimethylbenzene, Trichloroethene, and
 Xylenes were detected at levels above the MCL/EPA Region 9 PRG levels for
 drinking water.
- Nineteen SVOCs were detected in the groundwater samples tested during this investigation. Eighteen of the SVOCs detected levels were well below the maximum detected levels reported by the previous investigations.
- Motor oil, organochlorine pesticides, and PCBs were not detected in the groundwater samples collected from the Site CF.
- Only one metal (barium) was detected above the detection limit in the groundwater samples collected for this investigation from the Site CF.


Recommendations


Based on the results presented in this report, PSI recommends the following course of action:


• Continued groundwater monitoring at the Site JA and Site CF, on a quarterly basis. According to the DTSC recommendations, total dissolved solids (TDS) measurements should be collected. Also, filtered and unfiltered water samples from the Container Freight site should be analyzed for SVOCs using EPA Method 8270.


REFERENCES


- 1. Caltrans, 1999, Task Order # 04-192203-RJ, "Site Investigation for J & A Truck Repair and Container Freight, In Alameda County, California", prepared for Caltrans, February, 2000.
- 2. Caltrans, 1999, Contract NO. 43A0012.
- 3. Caltrans, 1996, 'Soil and Rock Logging Classification Manual (Field Guide)", prepared for Office of Structural Foundations, August 1996.
- 4. Caltrans, March 1998, "Remedial Design and Implementation Plan Container Freight, 1285 Fifth Street, Oakland".
- 5. Environmental Solutions, Inc. (ESI), April 1995, "Preliminary Endangered Assessment J & A Truck Repair", prepared for Caltrans.
- 6. Environmental Solutions, Inc. (ESI), April 1995, "Preliminary Endangered Assessment Container Freight", prepared for Caltrans.
- 7. Geological Survey Professional Paper 943: "Flatland Deposits Their Geology and Engineering Properties and Their Importance to Comprehensive Planning" by E.J. Helley and K.R. Lajoie, 1979.
- 7. Jonas and Associates, November 1995, "Underground Storage Tank Closure Report, J & A Truck Repair", prepared for Caltrans.
- 8. Jonas and Associates, November 1996, "Remedial Action Completion Report, J & A Truck Repair", prepared for Caltrans.
- 9. Laidlaw Environmental Services, August 31, 1995, "Site Investigation Report, Union Pacific Railroad Property, 5th and Union Street, Oakland, California", prepared for Union Pacific Railroad, Omaha, Nebraska.
- 10. Robert Norris and Robert Webb, 1990, "Geology of California".
- 11. USGS, 1993, 7.5 minute topographical map titled, "Oakland West Quadrangle", California.











GROUNDWATER ELEVATION AND PARAMETERS
J & A TRUCK REPAIR (SITE JA) AND CONTAINER FREIGHT (SITE CF)

TABLE 1

OAKLAND, CALIFORNIA

Sample Location	Date	TOC Elevation (feet msl)*	Depth To Groundwater	Groundwater Elevation (feet msl)*	Temperature (°C)	Conductivity (mS/cm)	21
CF-1	5/2/00	14.07	5.06	9.01	14.4	4760	7.3
CF-2	5/2/00	10.2	3.8	6.4	14.8	17.85**	6.41
CF-3	5/2/00	9.67	2.73	6.94	22.2	5360	5.95
JA-1	5/2/00	15.12	6.2	8.92	16.9	1380	7.15
JA-2	5/2/00	13.15	4.53	8.62	16.7	2175	7.03
JA-3	5/2/00	12.64	3.97	8.67	17.3	1144	6.68
JA-4	5/2/00	12.58	3.83	8.75	19.2	1584.00	6.52

Notes:

mS/cm = milliseimens per centimeter

NM = Not Measured

All measurements are recorded in feet.

* TOC Measurements are from data supplied by ENGINEERING ASSOCIATES

Feet msl = feet above mean sea level

^{**} Conductivity values for CF-2 were confirmed by the second groundwater sampling event performed on 8/7/00.

TABLE 2 STATISTICAL ANALYSIS AND SUMMARY OF SOIL ANALYTICAL RESULTS: ORGANICS J & A TRUCK REPAIR (SITE JA) OAKLAND, CALIFORNIA

ANALYTICAL METHOD	DETECTED	JA-1 7:0 FT	JA2 7.0 FT	JA-3 7:0 FT	JA-4 6.5 FT	DETECTION LIMIT	CYPRESS PRG		STA	ISTICAL FUN	ICTION	
क्षा कर को का जाने विकास का		unce de mariemen						count	max	min	Average	STD.DEV
EPA METHOD 8015	TPH-G	ND	ND	ND	ND	0.5	NA	0	NA	NA	NA	NA
EPA METHOD 8015	TPH-D	ND	ND	ND	ND	10	100	Ð	NA	NA	NA	NA
EPA METHOD 8015	MOTOR OIL	ND	ND	ND	ND	10	NA	0	NA	NA	NA	NA
	1,1 Dichloroethane	0.001	ND	0.001	0.001	0.001	0.42-3.8	3	0.001	0.001	0.001	NA
	Naphthalene	ND	ND	0.003	0.02	0.002	82	. 2	0.02	0.003	0.0115	0.012021
VOC by EPA 8260B	Ştyrenə	ND	0.001	0.001	ND	0.001	NA	2	0.001	0.001	0.001	NA
•	1,1,1-Trichloroethane	0.007	0.005	0.006	0.006	0.001	470	4	0.007	0.005	0.006	0.000816
	Trichlorotrifluorethane	0.008	0.007	0.006	0.007	0.005	NA	4	0.008	0.006	0.007	0.000816
	Acenaphthylene	ND	ND	0.055	ND	0.033	ΝA	1	0.055	0.055	0.055	NA
	Fluoranthene	. ND	ND	0.072	ND	0.033	2,300	1	0.072	0.072	0.072	NA
SVOC by EPA 8270C	Naphthalene	ND	ND	0.28	ND	0.033	82	1	0.28	0.28	0.28	NA
-	Phenanthrene	ND	ND	ND	0.1	0.066	NA	1	0.1	0.1	0.1	NA
	Pyrene	ND	ND	ND	0.14	0.033	1,700	1	0.14	0.14	0.14	NA
ORGANOCHLORINE PESTICIDES by EPA 8081		ND	ND	ND	ND	0.001-0.020	NA	0	NA	NA	NA	NA .
PCBs by EPA 8082		ND	ND	ND	ND	0.05	NA	0	NA	NA	NA	NA

Notes:

ND = Not Detected

Depth is presented in feet below ground surface.

All samples are reported as total concentration in milligrams per kilograms (a), unless indicated.

VOC = Total of Volatile Organic Compounds

SVOC = Semi-Volatile Organic Compounds

PRG = Pretiminary remediation goals (EPA Region 9)

count = Number of concentrations reported above the detection limit

max = Maximum value

min = Minimum value

average = Average of the detected values above the detection limit

TABLE 3 STATISTICAL ANALYSIS AND SUMMARY OF SOIL ANALYTICAL RESULTS: METALS J & A TRUCK REPAIR - SITE JA OAKLAND, CALIFORNIA

SAMPLE I.D.	DEPTH (F	SB	AS	BA	BE	CD	CR -	CO	CU	РВ	HG	MO	NI I	SE	AG -	TL	¥γ	ZN
JA1	7	ND	2.1	37	ND	ND	30	4.6	5.3	1.5	ND	ND	26	ND	ND	19	21	19
JA2	7	ND	2.5	47	ND	ND	35	5.3	6.8	2	ND	ND	32	ND	ND	ND	27	23
JA3	7	ND	3.0	47	ND	ND	38	5.6	8.4	3.9	ND	ND	32	ND	ND	34	29	25
JA4	6.5	ND	2.4	56	ND	ND	48	5.8	7.6	2.5	ND	ND	35	ND	ND	ND	30	26
CYPRESS PRG		67	4.6-19*	12,000	1.8-0.2	24-2.7	NA	NA	5,000	840	45	830	400-44	830	830	14-27*	1,200	50,000
DETECTION L		2.50	0.50	0.50	0.50	0.05	0.50	0.50	0.50	0.50	0,10	0.50	1.00	2.50	0.50	2.50	0.50	10.00
	count	0	4	4	0	0	4	4	4	4	0	0	4	0	0	2	4	4
STATISTICAL	max	NA	3	56	NA	NA	48	5.8	8.4	3.9	NA	NA	35	NA	NA	34	30	26
FUNCTION	min	NA	2.1	37	NA	NA	30	4.6	5.3	1.5	NA	NA	26	NA	NA	19	21	19
	Average	NA	2.5	46.75	NA	NA	37.75	5.325	7.025	2.475	NA	NA	31.25	NA	NA	NA	26.75	23.25
	STD.DEV.	NA	0.37417	7.76209	NA	NA	7.58837	0.5252	1.32256	1.03401	NA	NA	3.77492	NA	NA	NA	4.03113	3.0957

Notes:

Depth is presented in feet below ground surface
ND = Not detected at or above the laboratory detection limits
Metals are designated by their symbol on the periodic table of elements.
All samples are reported as total concentration in milligrams per kilogram (mg/kg), unless indicated.

PRG = Preliminary remediation goals (EPA Region 9)

NA = Not Available/Not applicable

count = Number of concentrations reported above the detection limit.

max = Maximum value

min = Minimum value

average = Average of the detected values above the detection limit

TABLE 4

STATISTICAL ANALYSIS AND SUMMARY OF GROUNDWATER ANALYTICAL RESULTS: ORGANICS J & A TRUCK REPAIR (SITE JA) OAKLAND, CALIFORNIA

ANALYTICAL METHOD	COMPOUND	JA-1	JA-2	JA-3	JA-4	DETECTION LIMIT	MCL*/ PRG(mg/L)				UNCTION	Maring Street Committee Co
	all Al Villerby son said		an da ven					count	max*	* min	Average	STD.DEV.
EPA METHOD 8015	TPH-G	ND	0.77	ND	ND	0.5	NA	1	0.77	0.77	0.77	NA
EPA METHOD 8015	TPH-D	ND	0.8	ND	ND	0.4	NA	1	0.8	0.8	0.8	NA
EPA METHOD 8015	Motor Oil	ND	ΝĐ	ND	ND	10	NA	0	NA	NA	NA	NA
	Benzene	ND	ND	ND	0.0007	0.0005	0.001*	1	0.0007	0.0007	0.0007	NA
	Chloroform	ND	ND	ND	0.0017	0.0005	0.011	1	0.0017	0.0017	0.0017	NA
	1,1-Dichloroethane	ND	ND	ND	0.0082	0.0005	0.005*	1	0.0082	0.0082	0.0082	NA
	1,2-Dichloroethane	ND	0.0088	ND	ND	0.0005	0.0005*	1	0.0088	8800,0	0.0088	NA
	1,1-Dichloroethene	ND	ND	ND .	0.0062	0.0005	0.00012	1	0.0062	0.0062	0.0062	NA
	cis-1,2-Dichloroethene	ND	ND	ND	0,057	0.0005	0.006	1 1	0.057	0.057	0.057	NA
VOCs by EPA 8260B	trans-1,2-Dichloroethene	ND	ND	ND	0.0008	0.0005	0.01	1	0.0008	0.0008	0.0008	NA
•	Napthalene	0,0083	0.0083	0.0024	0.0013	0,0005	0.0062	4	0.0083	0.0013	0.00508	0.0037509
·	Tetratchloroethene	ND	ND	ND	0.13	0.0005	0.005*	1	0.13	0.13	0.13	NA
	1,1,1-Trichloroethane	ND	ND	ND	0.0042	0.0005	0.2*	1	0.0042	0.0042	0.0042	NA
	1,1,2-Trichloroethane	ND	ND	ND	0.0006	0,0005	0.005*	1	0.0006	0.0006	0.0006	NA
	Trichloroethene	ND	0.0007	ND	0.63	0.0005	0.005*	2	0.63	0.0007	0.31535	0.4449823
	Trichlorotrifluoroethane	NO	ND	ND	0.0075	0.005	0.15*	1	0.0075	0.0075	0.0075	NA
	Vinyl Chloride	ND	NĐ	ND	0.0011	0.0005	0.0005*	1	0.0011	0.0011	0.0011	NA
SVOCs by EPA 8270C	Napthalene	0.002	ND	ND	ND	0.0011	0.0062	1	0.002	0.002	0.002	NA
ORGANOCHLORINE PESTICIDES by EPA 8081		ND	ND	ND	ND	0.00005-0.001	NA	0	NA	NA	NA	NA
PCBs by EPA 8082		ND	ND	ND	ND	0.001	0.000034	0	NA	NA	NA	NA

Notes:

ND = Not Detected

MCL* - Maximum contaminant levels for the primary drinking water chemical Where MCL were not available EPA Region 9 Preliminary Remediation Goals for tap water were presented, if available.

All samples are reported as total concentration in milligrams per kilogram (mainly unless indicated.

VOCs = Volatile Organic Compounds

SVOCs = Semi-Volatile Organic Compounds

count = Number of concentrations reported above the detection limit

max ≖ Maximum value

min = Minimum value

average = Average of the detected values above the detection limit

TABLE 5 STATISTICAL ANALYSIS AND SUMMARY OF GROUNDWATER ANALYTICAL RESULTS: METALS J & A TRUCK REPAIR - SITE JA OAKLAND, CALIFORNIA

SAMPLE I.D.		SB	AS	ВА	BE	CD	CR	co	CU	PB	HG	МО	NI NI	SE	AG	ŢĻ	· V	2N
JA-1		ND	ND	0.1600	ND	ND	ND	ND	ND	ND	ND	ND	0.0450	ND	ND	ND	ND	0.1200
JA-2		ND	ND	0.1500	ND	ND	0.0100	ND	ND	ND	ND	ND	0.0350	ND	ND	ND	ND	0.1000
JA-3		ND	ND	0.1800	ND	ND	ND	ND	ND	ND	ND	ND	0.0300	ND	ND	ND	ND	0.1200
JA-4		ND	ND	0.1200	ND	ДN	ND	ND	ND	ND	ND	ND	0.0270	ND	ND	ND	ND	ND
PRG		15.0000	0.0450	2600	73.0000	18.0000	NA	2200	1400	0.0036	11.0000	180	730	180	180	NA	260	1100
DETECTION LIMIT		0.0150	0.0100	0.0100	0.0100	0.0100	0.0100	0.0100	0.0100	0.0100	0.0002	0.1000	0.0100	0.0150	0.0100	0.0100	0.0100	0.1000
	count	0.0000	0.0000	4.0000	0.0000	0.0000	1.0000	0.0000	0.0000	0.0000	0.0000	0.0000	4.0000	0.0000	0.0000	0.0000	0.0000	3.0000
STATISTICAL	max	0.0000	0.0000	0.1800	NA	NA	0.0100	0.0000	0.0000	0.0000	NA	NA	0.0450	NA	NA	NA	0.0000	0.1200
FUNCTION	min	0.0000	0.0000	0.1200	NA	NA	0.0100	0.0000	0.0000	0.0000	NA	NA	0.0270	NA	NA	NA	0.0000	0.1000
	AVERAGE	NA	NA	0.1525	NA	NA	0.0100	NA	NA	NA	NA	NA	0.0343	NA	NA	NA	NA	0.1133
	STD.DEV.	NA	NA	0.0250	NA	NA	NA	NA	NA	NA	NA	NA	0.0079	NA	NA	NA	NA	0.0115

Notes:

ND = Not detected at or above the laboratory detection limits

Metals are designated by their symbol on the periodic table of elements.

All samples are reported as total concentration in milligrams per kilogram (mg/L), unless indicated.

PRG = Preliminary remediation goals (EPA Region 9) for tap water

NA = Not Available/Not applicable

count = Number of concentrations reported above the detection limit

max = Maximum value

min = Minimum value

average = Average of the detected values above the detection limit

TABLE 6

STATISTICAL ANALYSIS AND SUMMARY OF SOIL ANALYTICAL RESULTS: ORGANICS CONTAINER FRIGHT (SITE CF) OAKLAND, CALIFORNIA

ANALYTICAL METHOD	DETECTED COMPOUND	CF1-0.5	CF1-1.0	CF1-2.0	CF2-0.5	CF2-1.0	CF2-2.0	CF2-3	CF3-0.5	CF3-1.0	CF3-2.0	DETECTION LIMIT		STATIS	TICAL FUI	NCTION	
	Carolina (Carolina de		美術業		Preferance.	ent in	Salin Garage	les dili			(Marie Marie		count	max	min	Average	STO.DEV.
EPA METHOD 8015	TPH-G	ND	0.77	ND	ND	ND	0.69	NT	ND	ΝĐ	ND	0.5	2	0.77	0.69	0.73	0.056569
EPA METHOD 8015	TPH-D	370	70	19	60	220	140	NT	22	140	110	10-100	9		19	127.8889	
EPA METHOD 8015	MOTOR OIL	630	100	35	44	520	ND	NT	23	78	58	10-100	8	630	23	186	243.0961
VOCs by EPA 8260B	Benzene	ND	0.001	ND	ND	ND	ND	0.4	ND	ND	ND	0.001] 2	0,4	0.001	0,2005	0.282136
	Napthalene	ND	0.98	1.5	0.009	0,005	ND	390	0.008	0.009	ND	0.002	7	390	0.005	56.073	
	Acenaphthene	ND	ND	ND	0.34	ND	ND	NT	ND	ND	ND	0.33	1	0.34	0.34	0.34	
	Acenaphthylene	ND	ИD	0.67	0.85	ND	0.69	NT	ND	2	1.8	0.033	5	2	0.67	1.202	
	Anthracene	ND	ND	0.5	1.5	ND	1.4	NT	ND	4.6	2	0.33	5	4.6	0.5	2	1.550806
	Benzo(a)anthracene	ND	ND	0.91	1.7	ND	5.7	NT	ND	16	5.5	0.66	5	16	0.91	5.962	6.015207
	Велго(а)ругеле	ND	0.79	1.7	3.2	1.2	12	NT	ND	40	9.4	0.66	7	40	0.79	9.755714	14.03173
1	Benzo[b]fluoranthene	0.59	1	2	4	1.8	17	NT	ND	47	12	0.33	8	47	0.59		į .
	Benzo(g,h,i)perylene	ND	1	2	3.5	1.6	17	NT	ND	33	10	0.99	7	33	1	9.728571	11,79897
SVOCs by EPA 8270C	Benzo(k)fluoranthene	0.61	1	2	4	1.8	17	NT	ND	47	12	0.33	8	47	0.61	10.67625	
	Chrysene	ND	0.62	1.4	2.1	0.76	8.7	NT	ND	19	7.1	0.33	7	19	0.62	5.668571	6.702028
1	Dibenzo[a,h]anthracene	ND	ND	ND	ND	ND	1.8	NT	ND	6.3	1.2	0.99	3	6.3	1.2	3.1	2.787472
ŧ	Fluoranthene	0.59	1.5	3.3	7.6	ND	22	NT	ND	62	20	0,33	7	62	0.59	16.71286	21.77158
	Fluorene	ND	ND	ND	0.65	ND	1.6	NT	ND	0.53	0.74	0.33	4	1.6	0.53	0.88	0.487647
	Indeno[1,2,3-cd]pyrene	ND	ND	ND	2.6	ND	14	NT	ND	30	7.5	1.3	4,	30	2.6	13.525	11.93465
	Napthalene	ND	0.83	2.2	0.37	ND	2.4	NT	ND	0.85	1.3	0.33	6	2.4	0.37	1.325	0.812964
	Phenanthrene	ND	1	2.6	7.6	0.81	7.8	NT	ND	26	14	0.66	7	26	0.81	8.544286	
	Pyrene	0.85	2.2	4.8	9.3	2.7	29	NT	ND	74	27	0.33	. 8	74.	0.85	18.73125	
	4,4'-DDD	ND	0.003	NĐ	9.3	ND	ND	NT	ND	МD	ND	0.001-0.02	2	9.3	0.003	4.6515	6.573972
ORGANOCHLORINE PESTICIDES	4,4'-DDE	0.018	0.009	ND	ND	ND	ND	NT	ND	ND	ND	0.002	2	0.018	0.009	0.0135	
by EPA 8081	Dieldrin	ND	0.002	ND	ND	ND	ND	NT	ND	NĐ	ND	0.002	1	0,002	0.002	0.002	
	Endosulfan t	0.006	NĎ	ND	ND	ND	ND	NT	ND	ND	ND	0.001	1	0,006	0.006	0.006	
PCBs by EPA 8082	Aroclor-1260	0.082	ND	ND	ND	ND	ND .	NT	ND	ND	ND	0.05	1	0.082	0.082	0.082	NA

Notes:

ND = No! Detected

Depth is presented in feet below ground surface.

All samples are reported as total concentration in milligrams per kilogram (mg/kg), unless indicated.

VOCs = Total of Volatile Organic Compounds

SVOCs = Semi-Volatile Organic Compounds

PRG = Pretiminary remediation goals (EPA Region 9)

NA = Not Available/Not Applicable

count = Number of concentrations above the detection limit

max = Maximum value

min = Minimum value

average = Average of the detected values above the detection limit

TABLE 7
SUMMARY OF SOIL ANALYTICAL RESULTS: METALS
CONTAINER FREIGHT (SITE CF)
OAKLAND, CALIFORNIA

SOIL SAMPLE I.D.	DEPTH (m)	SB	⊭ AS □	BA	BE#	e CD	CR#	co"	gu	- РВ	HG	MO	· NL · -	♣ SE 4	AG.	TL	alle Valu	/- ZN
CF1-0.5	0.5	ND	4.7	130	ND	ND	30	7.8	30	49	ND	0.66	33	ND	ND	ND	32	89
CF1-1.0	1	ND	8.8	120	ND	ND	35	8.8	51	49	0.3	1	41	ND	ND	ND	37	87
CF1-2.0	2	ND	5.8	130	ND	0.82	.27	6.4	36	74	0.23	1.4	25	ND	ND	ND	26	150
CF2-0.5	0.5	ND	5.9	71	ND	ND	20	6.2	41	65	0.24	ND	19	ND	ND	ND	28	76
CF2-1.0	1	ND	5.4	99	ND	ND	29	6.6	38	64	0.26	0.71	30	ND	ND	ND	31	87
CF2-2.0	2	ND	12.0	55	ND	0.62	7.1	2.5	80	48	ND	ND	12	ND	ND	ND	13	230
CF3-0.5	0.5	ND	2.5	.77	ND	ND	22	4.1	14	73	0.18	ND	16	ND	ND	ND	19	50
CF3-1.0	1	ND	6.0	18	ND	ND	2.9	0.59	71	22	ND	ND	7.6	ND	ND	ND	25	30
CF3-2.0	2	ND	5.1	50	ND	ND	32	6.2	34	48	ND	0.67	38	ND	ND	ND	28	180
DETECTION												4 d			4.00	46 (KSL) 463	0.50	40.00
LIMIT	surjuni -të li Budës	2,50	0.50	0,50	0.50	0.05	0,50	0,50	0.50	0.50	0.10	0.50	1.00	2,50	1.00	2,50	0.50	10.00
	count	0	9	9	0	2	9	9	9	9	5	5	9	0	0	0	9	9
STATISTICAL	max	NA	12	130	NA	0.82	35	8.8	80	74	0.3	1.4	41	NA	NA	NA	37	230
FUNCTION	min	NA	2.5	18	NA	0.62	2.9	0.59	14	22	0.18	0.66	7.6	NA	NA	NA	13	30
	AVERAGE	NA	6.24444	83.3333	NA	0.72	22.7778	5.46555556	43.8889	54.6667	0.242	0.888	24.6222	NA	NA	NA	26.5556	108.778
	STD.DEV.	. NA	2.70329	39.2428	NA	0.14142	11.1376	2.60378144	20.5514	16.2942	0.04382	0.31854	11.7339	NA	NA	NA	7.12585	64.751

Notes:

ND = not detected at or above the laboratory detection limits

Metals are designated by their symbol on the periodic table of elements.

All samples are reported as total concentration in milligrams per kilogram (mg/kg), unless indicated.

NA = Not Available/Not Applicable

count = Number of concentrations above the detection limit

max = Maximum value

min = Minimum value

average = Average of the detected values above the detection limit

TABLE 8

STATISTICAL ANALYSIS AND SUMMARY OF GROUNDWATER ANALYTICAL RESULTS CONTAINER FREIGHT (SITE CF) OAKLAND, CALIFORNIA

ANALYTICAL METHOD	COMPOUND	CF-1	CF-2	CF-3	CF-10	DETECTION LIMIT	MCL*/ PRG(mg/L)		eTAT!	TICAL FU	VOTION	
ANALTHUAL METHOD	I COMPOND	Q(F)	VF-4	11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		1	I volubri	count			average	STD.DEV.
EPA METHOD 8015	TPH-G	94	54	0.5	7.7	0,5-50	NA.	4	94	0.5		
EPA METHOD 8015	TPH-D	21	2.8	ND	1.8	0.4-4.0	NA.	3	21.	1.8	8.533333	10.80802
EPA METHOD 8015	Motor Oil	ND	ND	ND	ND	0.4-4.0	NA	0	NA.	NA NA	NA	NA
	Benzene	34	0.33	0.0009	0.27	0.0005	0,001*	4	34	0.0009	8.650225	16.90046
	Carbon Disulfide	ND	0.068	ND	ND	0.0005		1	0.068	0.068	0.068	NA
	Ethylbenzene	0.34	0.012	ND	0.013	0.0005	0.7*	3	0.34	0.012	0.121667	0.189083
	Napthalene	19	3	0.0017	1.6	0.0005	0.0062	4	19	0.0017	5.875425	8.829638
VOCs by EPA 8260B	Styrene	0.59	0.0008	ND	ND	0.0005	0,1*	2	0.59	0.0008	0.2954	0.416627
,	Toluene	1.6	0.01	ND	0.014	0,0005	0.15*	3	1.6	0.01	0.541333	0.916834
· ·	1,2,4-Trimethylbenzene	ND	0.0014	ND	ND	0.0005	0.005	1	0.0014	0.0014	0.0014	NA
<u></u>	Trichloroethene	0.19	ND.	ND	ND	0.0005	0.005*	1	0.19	0.19	0.19	NA
	Xylenes (total)	ND	0.011	ND	ND	0.005	1.75*	1	0.011	0.011	0.011	NA
	Acenaphthene	0.008	0.004	ND	0.004	0.001	0.37	3	0.008	0.004	0.005333	0.002309
	Acenaphthylene	ND	0.069	ND	0.031	0.001	NA	2	0.069	0.031	0.05	0.02687
·	Anthracene	ND	0.006	0.007	0.001	0.006	1.8	3	0.007	0.001	0.004667	0.003215
	Benzo(a)anthracene	ND	ND	0.004	ND :	0.002	0.000092	1,	0.004	0.004	0.004	NA
	Benzo(a)pyrene	ND	0.003	800.0	0.002	0.002	0.0002*	3	0.008	0.002	0.004333	0.003215
	Benzo(b)fluoranthene	ND	0.003	0.01	0.003	0.001	0.000092	3	0.01	0.003	0.005333	0.004041
	Benzo(g,h,ijperylene	ND	ND	9.009	ND	0.003	N/A	1	0.009	0.009	0.009	NA
	Benzo[k]fluoranthene	ND	0.003	0.01	0.003	0.001	0.00092	3	0.01	0.003	0.005333	0.004041
	Chrysene	ND	0.003	0.006	0.002	0.001	0.0092	3	0.006	0.002	0.003667	0.002082
SVOCs by EPA 8270C	Dibenzofuran	0.003	0.003	ND	0.003	0.001	0.024	3	0.003	0.003	0.003	0
	Fluoranthene	0.007	0.014	0.012	0.011	0.001	1.5	4.	0.014	0,007	0.011	0.002944
	Fluorene	0.013	0.016	ND	0.014	0.001	0.24	3	0.016	0.013	0.014333	0.001528
	Indeno[1,2,3-cd]pyrene	ND	ND .	0.006	ND	0.004	0.00092	1	0.006	0.006	0.006	NA
1	2-Methylnaphthalene	0.067	0.022	ND	0.008	0.001	NA .	3	0,067	800.0	0.032333	0.030827
•	4-Methylphenol	ND	0.17	ND	0.041	0,005	0.18	2	0.17	0.041	0.1055	0.091217
	Naphthalene	5,5	1.2	0.007	0.52	0.001	0.0062	4	5.5	0.007	1.80675	2.510184
	Phenanthrene	0.055	0.048	0.004	0.033	0.002	NA	4	0.055	0.004	0.035	0.022613
	Phenol	0.024	0.046	ND	0.011	0.004	22	3	0.046	0.011	0.027	0.017692
	Pyrene	0.011	0.018	0.016	0.013	0.001	0.18	4	0.018	0.011	0.0145	0.003109
ORGANOCHLORINE PESTICIDES by EPA 8080	All Compounds	ND	ND	ND	ND	0.00005-0.001	NA	. 0	NA	ŅA	ŅA	NA
PCBs by EPA 8080	All Compounds	ND	МĐ	ND	ND	0.001	0.000034	0	NA	NA	NA	NA

Notes:

ND = Not Detected

MCL* • Maximum coordaminants levels for the primary drinking water chemicals/ Where MCL were not available EPA Region @ Preliminary Remediation Goals were presented, if available.

All samples are reported as total concentration in milligrams per kilogram (mg/L), unless indicated.

VOCs = Votatile Organic Compounds

SVOCs = Semi-Volatile Organic Compounds

TPH-G = Total petroleum hydrocarbons as gasoline TPH-D = Total petroleum hydrocarbons as diesel

* = MCL is for either a single isomer or the sum of the isomers

NA = Not Available/Not Applicable

count = Number of Tests

max = Maximum value

min = Minimum value

gverage = Average value of the detected values above the detection limit

TABLE 9

SUMMARY OF GROUNDWATER ANALYTICAL RESULTS: METALS CONTAINER FREIGHT (SITE CF) OAKLAND, CALIFORNIA

SOIL SAMPLE I.D		SB	AS	BA	8E	· CD	CR	co	[®] CÜ ⋅	≹ PB □	HG	МО	NI -	SE -	* AG	TL	1 V	≜ĕZŅ∉
CF-1		ND	ND	0.28	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
CF-2		ND	NĐ	ND	ND	ND	ND	ND	ND	NĐ	ND							
CF-3		ND	ND	ND	ND	ND	ND	ND	ND	ND	ND							
CF-10		ND	ND	ND	ND	ND	ND	ND	ND	ND	ND							
DETECTION LIMIT		0.30	0.20	0.20	0.20	0.20	0.20	0.20	0.20	0.20	0.0002	0.20	0.20	0.30	0,20	0.20	* 0.20	2.00
	count	NA	NA	1	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
STATISTICAL	max	NA	NA	0.28	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
FUNCTION	min	NA	NA	0.28	NA .	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	AVERAGE	NA	NA	0.28	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	STD.DEV.	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA							

Notes:

ND = not detected at or above the laboratory detection limits

Metals are designated by their symbol on the periodic table of elements.

All samples are reported as total concentration in milligrams per kilogram (mg/L), unless indicated.

NA = Not Available/Not Applicable

count = Number of concentrations above the detection limit

max = Maximum value

min = Minimum value

average = Average of the detected values above the detection limit

APPENDIX A

FIELD PROCEDURES

APPENDIX A FIELD PROCEDURES

I. DRILLING OF SOIL BORINGS AND COLLECTION OF SOIL SAMPLES

The following procedures will be used for the drilling and sampling of the soil borings drilled at the site:

- 1. Drilling will be conducted by V&W Drilling Environmental under the supervision of PSI. Drilling equipment will be pressure washed at the beginning of the day and between soil borings.
- 2. Prior to the commencement of drilling activities at the site, Underground Service Alert (USA) will be contacted to identify underground utilities in the areas that the borings will be located.
- Boring logs for the soil borings drilled at the site will be prepared under the supervision of a State of California Registered Geologist. The soil cuttings observed during drilling will be described in accordance with the Unified Soil Classification System.
- 4. Soil samples will be collected using a California stainless steel sampler with 2-inch diameter. When the boring has been advanced to the appropriate sampling depth, a 2-inch diameter sampler lined with 2-inch diameter brass tubes will be placed in the open boring. When the sampler is advanced to the appropriate depth an undisturbed soil sample will be collected by pushing the sampler into the subsurface using a 140 pounds hammer.
- 5. Once the sampler has been retrieved the ends of the sample tube will be covered with Teflon sheets and capped with polyethylene end caps. The sample will be labeled and placed in a zip-lock bag in a chilled cooler pending delivery to the laboratory for analysis.
- 6. Soil samples will be assigned identification numbers such as JA1-0.5, where JA1 indicates the site name, boring 1 and -0.5 indicates that the sample was collected at 0.5 meters bgs from boring 1 at that site. The samples will be labeled with the sampling designation, depth, date, client name, and project number.
- 7. Soil samplers will be washed between sampling intervals with Alconox soap followed by two deionized-water rinses.

- 8. Chain-of-custody procedures using chain-of-custody forms will be used to document sample handling and transportation.
- 9. A Century 128 organic vapor analyzer (OVA) or equivalent device will be used to monitor volatile organic compounds (VOCs) in the ambient air during drilling at the site in accordance with the site health and safety plan. VOC concentrations in the soil will be measured and recorded on the borings logs for depths that soil samples were collected. VOCs in the soil will be measured at the sampling depths by partially filling a zip-loc bag with soil. The components of the soil are allowed to volatilize and fill the headspace in the tube for at least 10 minutes prior to inserting the OVA probe through one of the end caps and recording the measurements.
- 10. Soil cuttings and steam wash water generated during drilling activities at the site will be contained in Department of Transportation (DOT) approved 55-gallon drums. The drums will be labeled with the contents, date, well or boring number, client name, and project number.

II FIELD DOCUMENTATION OF SAMPLING PROCEDURES

The following outline describes the procedures adhered by PSI for proper sampling documentation.

- 1. Sampling procedures will be documented in a field notebook that will contain:
 - 1. Sample collection procedures
 - 2. Date and time of collection
 - Date of shipping
 - 4. Sample collection location
 - 5. Sample identification number(s)
 - Intended analysis
 - 7. Quality control samples
 - 8. Sample preservation
 - 9. Name of sampler
 - 10. Any pertinent observations

- 2. Samples will be labeled with the following information:
 - 1. Sample number
 - 2. Well number
 - Date and time sample was collected
 - 4. Sampler's name
 - 5. Sample preservatives (if required)
- 3. The following is the sample designation system for the site:

For Borings, the samples will be labeled JA(Boring Number)-(Depth) (i.e. sample collected from boring 1 at 0.5 m (1.65 feet) would be JA1-0.5)

For groundwater samples (W) (Boring Number) (i.e. WJA4)

- 4. Handling of the samples will be recorded on a chain of custody form which shall include:
 - 1. Site name
 - 2. Signature of Collector
 - Date and time of collection
 - 4. Sample identification number
 - 5. Number of containers in sample set
 - 6. Description of sample and container
 - 7. Name and signature of persons, and the companies or agencies they represent, who are involved in the chain of possession
 - 8. Inclusive dates and times of possession
 - 9. Analyses to be completed

III. GROUNDWATER SAMPLING

The following are procedures that will be implemented while performing well monitoring, well purging, and water sampling.

1. All non-disposable equipment will be washed prior to entering the boring with an Alconox solution, followed by two tap water rinses and a deionized water rinse.

- 2. Groundwater samples will be collected after purging three to five well casing volumes. Purged water will be stored in 55-gallon drums for future disposal. Physical parameter measurements (temperature, pH, and specific conductance) will be closely monitored throughout the well purging process and will be used as indicators for assessing sufficient purging.
- Water samples will be collected with a single-use Teflon bailer. The water will be immediately decanted into laboratory-supplied vials and bottles. The containers will be overfilled, capped, labeled, and placed in a chilled cooler prior to delivery to the laboratory for analysis. Table 2 attached to this appendix presents the container type and preservation method required by the EPA methods. Also, Table 3 is presenting the detection limits that will be used by Centrum Analytical Laboratories for the required EPA methods.
- 5. Chain-of-custody procedures, including chain-of-custody forms, will be used to document water sample handling and transport from collection to delivery to the laboratory for analyses.
- 6. Groundwater samples will be delivered to the State-certified hazardous waste laboratory within approximately 24-hours of collection.

APPENDIX B
BORING LOGS

301	LD	<u> </u>		AC	LOG	-				BORING NO:	JA-1	
					·					SHEET 1	OF	1
1						PROJECT NAME:	J&AT	RUCK RE	PAIR (S	ITE 1), OAKLANI		<u>-</u>
						PROJECT NUMBER:	575-0G	011		DATE: 4/26/00		
						NORTHINGS:				EASTINGS:		
]						DRILLING COMPANY:		DRILLING	3			
						DRILLING METHOD:		W-STEM	AUGER			
						BORING DIAMETER:	20 cm	(8 inch)		DEPTH:	5 m (16.4 f	eet)
T								GROUND	WATER	LEVELS		
Į.						DATE			COMM		DEP	TH BGS
						4/26/00		GROUND	WATER E	NCOUNTERED	-2.3	m (~7.5 FEET)
F				_								
DEРТН (m)	SAMPLE NO.	RECOVERY	SAMPLE INTERVAL	BLOW COUNT	DE	ESCRIPTION		PID (PPM)	uscs	Ri	EMARKS	
_										Asphalt Pavement		
					Fill (gravelly sand) to appro	eximately 0.6 m (2 feet).			sw			
7 .—							 .		1			
<u> </u>							*					
_										Groundwater encou	ntered at ~2.3	m (7.5 feet).
T _												(1.0 1001).
2			110.135.4									
	JA1-7.0		0.230	ļ	Sand, poorly graded, mediu	m sand, green, damp to wet.			SP			
F -				_		······································						
፲ "−									<u> </u>			
3—								 	-	ļ		
T		ľ]			
<u> </u>]			
4								ļ			·	
–				_	<u> </u>	<u> </u>						
-				_				<u> </u>	1			
5_								<u> </u>	-			
,												
				<u> </u>]			·
								ļ				
6									-			
-									+			
			1								·	
7—]			
-				<u> </u>								
				-					-			
				 				 	l	<u></u>		
8-								 	1			
									1			
			<u> </u>]			
9									1			
									-	Tatal J# "	140 11	
_								 -	,	Total depth = 5 meters		
T						<u> </u>		 		Soil borehole was or monitoring well.	Javerted in a	groundwater
1 10 —								 		1		
						1,000	ED BY: O	hein Maner				
T						LUGG	20 61: 0	hris Merri		···		

GROUNDWATER ENCOUNTERED -2	1
PROJECT NUMBER: 575-0G011 DATE: 4/26/00 NORTHINGS: EASTINGS: DRILLING COMPANY: V & W DRILLING DRILLING METHOD: HOLLOW-STEM AUGER BORING DIAMETER: 20 cm (8 inch) DEPTH: 5 m (16.4 GROUNDWATER LEVELS DATE COMMENTS DEP ###### GROUNDWATER ENCOUNTERED ~2	
PROJECT NUMBER: 575-0G011 DATE: 4/26/00 NORTHINGS: EASTINGS: DRILLING COMPANY: V & W DRILLING DRILLING METHOD: HOLLOW-STEM AUGER BORING DIAMETER: 20 cm (8 inch) DEPTH: 5 m (16.4 GROUNDWATER LEVELS DATE COMMENTS DEP ###### GROUNDWATER ENCOUNTERED2	
NORTHINGS: EASTINGS: DRILLING COMPANY: V & W DRILLING DRILLING METHOD: HOLLOW-STEM AUGER BORING DIAMETER: 20 cm (8 inch) DEPTH: 5 m (16.4 GROUNDWATER LEVELS DATE COMMENTS DEP ###### GROUNDWATER ENCOUNTERED2	
DRILLING COMPANY: V & W DRILLING DRILLING METHOD: HOLLOW-STEM AUGER BORING DIAMETER: 20 cm (8 inch) DEPTH: 5 m (16.4 GROUNDWATER LEVELS DATE COMMENTS DEP ###### GROUNDWATER ENCOUNTERED -2	
BORING DIAMETER: 20 cm (8 inch) DEPTH: 5 m (16.4 GROUNDWATER LEVELS DATE COMMENTS DEP ###### GROUNDWATER ENCOUNTERED ~2	
GROUNDWATER LEVELS DATE COMMENTS DEP ###### GROUNDWATER ENCOUNTERED ~2	
DATE COMMENTS DEP ##### GROUNDWATER ENCOUNTERED2	feet)
##### GROUNDWATER ENCOUNTERED -2	<u> </u>
###### GROUNDWATER ENCOUNTERED ~2	TH BGS
	3 m (-7.5 FEET)
H (m) H (m) H (m) H (m) H (m)	
(m) A (m)	
¶ + 1 w 1♥15 lQ l	
부 군 이 트 의 DESCRIPTION PID USCS REMARKS	
DESCRIPTION PID USCS REMARKS	
B S S W P P P P P P P P P P P P P P P P P	
Asphalt Pavement	
Fill (silty sand) to approximately 0.8 m (2.5 feet).	
	1 1 1 1 2 2
Groundwater encountered at ~2.	3 m (7.5 feet).
2 18	
2 — JA2-7.0	

3— 4—	
4_	<u> </u>
] -	
	·-····································
6—	
7—	
8—	
] 9— — — — — — — — — — — — — — — — —	
Total depth = 5 meters (16.4 fee) bas.
Soil borehole was converted in a	
10 monitoring well.	
LOGGED BY: Chris Merritt	

	<u> </u>	LD	<u>U</u>	KI	N	i LOG	_				BORING NO:	JA-3
											SHEET 1	OF 1
							PROJECT NAME:	J&AT	RUCK RI	EPAIR (S	SITE 1), OAKLANI	0
							PROJECT NUMBER:	575-0G	011		DATE: 4/26/00	
							NORTHINGS:				EASTINGS:	
							DRILLING COMPANY:	V & W	DRILLING	3		
							DRILLING METHOD:	HOLLO	W-STEM	AUGER	1	
							BORING DIAMETER:	20 cm (DEPTH:	5 m (16.4 feet)
٦									GROUND	WATER	LEVELS	
							DATE				MENTS	DEPTH BGS
							4/26/00		GROUND	WATER E	NCOUNTERED	-2.3 m (-7.5 FEET)
\neg	-		Г									
	DEPTH (m)	SAMPLE NO.	RECOVERY	SAMPLE INTERVAL	BLOW COUNT	DE	ESCRIPTION		PID (PPM)	uscs	RI	EMARKS
	_					Fill (silby cond) to an environ	-t-1: 0 D . (0 D C .)	<u> </u>			Asphalt Pavement	
	1					Fill (sitty sand) to approxima	ately 0.8 m (2.5 feet).			SM		
٦	1									ł		
	'_									1		
	· —										Groundwater encour	ntered at ~2.3 m (7.5 feet).
					18							
	2	JA3-7.0		15.		Sand, poorly graded, medius	m sand, green, damp to wet.		<u></u>			
	_			\$. * <u> </u>	50/5	graded, media	m sand, green, damp to wet.			SP	The color turns brow	
	_									ł	THE COICH TURES BLOW	m
	3									Í		<u> </u>
]		
٦	_											
									<u> </u>			
	4											
٦												·
	-											
	5									·		
٦	-				_	<u> </u>						
								· · · · · · · · · · · · · · · · · · ·				 -
	6—							**				
٦												-
	-						· .					
	7_											
7	<u>'</u> _											
											<u> </u>	
										}		
٦	8 —											
	-							· · · · · ·	 			
	9_											
										_	Total depth = 5 mete	
7						<u> </u>					Soil borehole was co	onverted in a groundwater
	10 —										monitoring well.	
												-
							LOGG	ED BY: CI	hris Merrit	t		
_						<u> </u>	<u>-</u> -1				······································	

201	L, D	U	KI	N	i LOG					BORING NO:	JA-4
		-]					
Ţ						PROJECT NAME:	ΙΖΔΤ	BLICK D	EDAID /		OF 1
L						PROJECT NUMBER:	575-00	1000 KI	EPAIR (S	SITE 1), OAKLAN	
						NORTHINGS:	3/3-00	<u> </u>		DATE: 4/26/00	
Ţ						DRILLING COMPANY: V & W DRILLING					
L						DRILLING METHOD:					
						ROPING DIAMETED: 20 (6: 1)					
						DOTAING DIAMETER.				DEPTH:	5 m (16.4 feet)
İ						DATE		GROUND			
						DATE		<u> </u>		MENTS	DEPTH BG\$
						4/26/00		GROUND	WATER E	NCOUNTERED	-2.2 m (-7 FEET)
			T .	Г	· · · · · · · · · · · · · · · · · · ·			ļ		· · · · · · · · · · · · · · · · · · ·	
DEРТН (m)	SAMPLE NO.	RECOVERY	SAMPLE INTERVAL	BLOW COUNT	DE	ESCRIPTION		PID (PPM)	USCS	R	EMARKS
L —				<u> </u>						Asphalt Pavement	
				L	Fill (silty sand) to approxima	ately 1.5 m (5 feet).			SM	- production	
_				_							
1			1	12							**************************************
-				13							
2				14						Groundwater encou	ntered at ~2.2 m (7 feet).
				16							
2-	JA4-6.5		S. Sayes		Sand, poorly graded, mediu	m sand amos down to wat		ļ	0.0		
				26	grada, media	in saird, green, damp to wet.		.,	SP	The sets to the	
				\Box		· · · · · · · · · · · · · · · · · · ·		-		The color turns brow	<u>/n</u>
3					· · · · · · · · · · · · · · · · · · ·						-
P										·	
				<u> </u>							
4				_							
_											
											
			ŀ			. <u></u>					
5											
										<u> </u>	
											
6						······································		 			
-				<u> </u>							
_ —											
				<u> </u>							
7—				 							
└				 		<u> </u>					
				 				<u> </u>			
-				 							
8						·				<u> </u>	
							-			 	
								 			
9											
									j	Total depth = 5 mete	ers (16.4 feet) bgs.
┛				<u> </u>	 					Soil borehole was co	poverted in a groundwater
_10										monitoring well.	
			<u></u>	لــــا							
						LOGGE	D BY: C	nris Merrit	t		-

SO	IL B	O	RI	N(3 LOG						BORING NO:	CF-1
											SHEET 1	OF 1
1					Ţ.	PROJECT NAME						
• 1					<u>[</u>	PROJECT NUME						
				•		NORTHINGS:					EASTINGS:	
•					<u>[</u>	DRILLING COMP	PANY: V & W DRILLING					
.					<u>[</u>	DRILLING METH	IOD: HC	LLO	W-STEM	AUGER		<u>,</u>
					Į <u>s</u>	BORING DIAME						
1					L				ROUND	WATER	LEVELS	
					1	DA	TE				MENTS	DEPTH BGS
tl					Ļ	4/25/00			GROUND		NCOUNTERED	-2 m (-6 FEET)
! ├──					r							
DЕРТН (m)	SAMPLE NO.	RECOVERY	SAMPLE INTERVAL	BLOW COUNT	DES	SCRIPTION			PID (PPM)	uscs	RI	EMARKS
ין —											Asphalt Pavement	-
-	CF1-0.5			100.25	Gravelly sand, well graded, fir gravel, brown, dry to damp.	ne to coarse sand, v	vith fine to coar	se		sw		
	0.170.3		300 Jan	21	graver, brown, dry to damp.				0			is, hard to start drive at
1	CF1-1.0		11.		Gravelly-silty sand, as above.	 -			0		0.5 m to 0.65 m.	
				39								
l												
2				40							Groundwater encour	ntered at ~2 m (6 feet).
'l —	CF1-2.0		. 16.1		As above: sampple grades da	mp to wet in tubes.	· · · · · · · · · · · · · · · · · · ·					
. —				30	Gravelly sand, poorly graded, grayish-green.	tine sand with coar	se gravel, wet,		0	SP		
					grayion-gradit.							
3—	:				· · · · · · · · · · · · · · · · · · ·							
2— 2— 3— 3— 4—												
4												
-												
5—												
_												
.										:		
[
6						·						
. –		İ										
- - 7-												
7			ļ							'		
I —				Щ						·		
-												
						·					<u> </u>	
- 8-												
9—			į	_]								
9 —				_								
J -												
ļ — ¦											Total depth = 5 mete	
¶		-	}	_	· - ··· <u>-</u> -							nverted in a groundwater
10 —											monitoring well.	
							LOGGED BY	r: Ch	ris Merrit	t	, <u></u>	

SOIL BORING LOG BORING NO: CF-2													
										SHEET 1	OF		
1						PROJECT NAME		CONTAINER FREIGHT (SITE 2), OAKLAND					
i						PROJECT NUMB		575-0G011 DATE: 4/25/00					
						NORTHINGS:				EASTINGS:		-	
						DRILLING COMP	ANY: V & W DRILLING						
4						DRILLING METH							
						BORING DIAMET	TER: 20 c	m (8 inch)		DEPTH:	5 m (16.4	feet)	
1								GROUNI	WATER	RLEVELS			
						DA	TE		COM	MENTS	DEF	TH BGS	
						4/25/00		GROUN	WATER E	NCOUNTERED	-2	m (-6 FEET)	
1	<u> </u>		1	1		<u> </u>							
DEРТН (m)	SAMPLE NO.	RECOVERY	SAMPLE INTERVAL	BLOW COUNT	DE	ESCRIPTION		PID (PPM)	uscs	REMARKS			
] _										Asphalt Pavement			
_				13	Gravelly silty sand, well grad	ded, fine to coarse sar	nd, with fine to		sw				
 -	CF2-0.5			38	coarse gravel and silt, brow	n, dry to damp.		0	4	Lot of concrete deb	ris, hard to st	art drive at	
1-	CF2-1.0		Series de la company	30			·		-{	0.5 m to 0.65 m.			
_			i, indi	50/3*	 			0	-				
_					Clayey sand, poorly graded	fine sand with clay, by	rown, damp.		SP				
2— 2— 3—				11					-	Groundwater encou	intered at ~2	m (6 feet)	
1 _	CF2-2.0			8				1			(4 1000).		
				4	Gravelly silty sand, well grad		nd with gravel	0	sw				
					(fine to coarse), with traces	of fines, wet, black.							
3	CF2-3.0		P P4		Clayey sand, poorly graded	fine cond with day d	and annu da bland		SP	<u> </u>			
						inte saile will cay, u	aik gray to triatr	c, wet.	35	Soil cuttings smell I	ikė sewage/n	otten eggs.	
1 =								 -	1		 		
4—									1				
l —													
T —						<u> </u>			_				
<u> </u>									-				
5—					· · · · · · · · · · · · · · · · · · ·								
T _					,				1			·	
1 _									1				
6]				
T —									_				
1 —				-					4				
				-					-1				
7—									-				
1 _									4				
								<u> </u>	1				
8—]				
1 —				<u> </u>					1				
				-	<u> </u>				4				
			1	-			· · · · · · · · · · · · · · · · · · ·	 	-				
] 9—									\dashv				
						····			1	Total depth = 5 me	ers (16.4 fee	t) bas.	
]	Soil borehole was d			
10				<u> </u>						monitoring well.			
<u> </u>	<u> </u>	L		<u> </u>		· · · · · · · · · · · · · · · · · · ·	,		<u> </u>				
LOGGED BY: Ch								: Chris Mer	itl				

SOIL BORING LOG											BORING NO: CF-3			
-			-		<u> </u>]			1	SHEET 1				
						PROJECT NAME:	CONTA	UNER ER	SIGHT (SITE 2), OAKLAN				
						PROJECT NUMBER:	575-0G			DATE: 4/25/00				
						NORTHINGS:	2.000	<u>~ 1 1 </u>		EASTINGS:	<u> </u>			
						DRILLING COMPANY:	V&W	DRILLING	-	LASTINGS.				
						DRILLING METHOD:		W-STEM						
						BORING DIAMETER:	20 cm (DEPTH:	5 m (16.4 feet)			
r								GROUND			3 fit (10.4 leet)			
L						DATE			COMM		DEPTH BGS			
						4/25/00		GROUND		NCOUNTERED	~2.2 m (~7 FEET)			
F				,				<u> </u>			E.E.III (-7 FCE1)			
DEPTH (m)	SAMPLE NO.	RECOVERY	SAMPLE INTERVAL	BLOW COUNT	DE	ESCRIPTION		PID (PPM)	USCS	R	EMARKS			
L —				<u></u>						Asphalt Pavement				
_	C32-0.5			45	Sandy gravel, well graded, to coarse sand, gray/black, da	fine to coarse gravel, with fine to	·		GW					
	L-32-0.3			5	coarse sand, gray/black, da	amp.		0	ł	-				
1—	CF3-1.0			4				0	1					
				4		 		-	1	Groundwater encou	ntered at ~0.31 m (3 feet).			
_			'			fine to coarse sand, with fine to			sw		morod de otor in (a root).			
_ 2			Project (2	coarse gravel, black, wet, w	ith traces of fines.]					
-	CF3-2.0		المصوفاة	3	Silt, green, wet, with low pla	adiait.		<u> </u>	l					
-	1			 -	Oilt, green, wet, with low pie	isticity.		<u> </u>	ML.					
3_								 	1					
3—		ŀ			Clayey silt, green, wet, with	moderate plasticity.			ML					
									1					
_]					
4				-				 	-	 				
-				\vdash	<u> </u>				1	·				
						<u> </u>		 	1					
5									<u></u>					
P				<u></u>										
<u> </u>				\vdash				ļ	4		· · · · · · · · · · · · · · · · · · ·			
			-	-					-					
6—					-			 	1					
	1							 	†					
									1					
7_]					
-				<u> </u>	<u> </u>			 	-					
								 	4					
						· · · · · · · · · · · · · · · · · · ·	·	 	+					
8—		1							1	-				
]					
		1		<u></u>				ļ, <u> </u>	1					
9—		1		-	 			<u> </u>	-					
-				\vdash					-	Total depth = 5 met	am (16 4 foot) has			
_								 	1		onverted in a groundwater			
T 10 _		1			1			1	1	manitoring well.	and a groundwater			
<u> </u>	<u> </u>		<u> </u>						<u> </u>					
[LOGGE	D BY: C	hris Merri	tt					

WELL/BORING NO: JA-1 to JA-4 and CF-1 to MONITORING WELL CONSTRUCTION DATA PERMIT NO: PROJECT NO: 575-0G011 DATE: 04/25 & 26/00 | PROJECT NAME: OAKLAND WELL SITE LOCATION PLAN: SEC: TWN: RGE: LAT: LONG: DRILLING CO: V & W DRILLING DRILL CREW: ☐ SHALLOW ☐ SINGLE CASED MONITORING WELL TYPE: PERMANENT ☐ INTERMEDIATE ☐ DOUBLE CASED ☐ RECOVERY TOTHER MON OTHER ☐ TEMPORARY DEEP WELL SCHEMATIC **INSTALLATION DATA** DECON. STEAM CLEAN SHIGH PRESSURE WASH TOC ABOVE CASING TYPE: PVC ☐ STAINLESS ☐ TEFLON ☐ OTHER GROUND IF RISER BOX JOINTS: THREADED WELDED COUPLED SCREWED OTHER OR STICKUP N/A M. PIT CASING: YES NO DESCRIBE N/A FT. WELL SCREEN: PVC STAINLESS TEFLON OTHER BOREHOLE ANNULAR DIAMETER DRILLING SOLID STEM IN HOLLOW STEM ■ MUD ROTARY BACKFILL METHOD: AIR ROTARY DIRECT PUSH HAND AUGER IN. 22 cm. BIT SIZE: 2" 4" 6" 8" 12" OTHER IN 20 cm. DRILLING MUD: NONE WATER BENTONITE 0.7 FT. CASING OTHER CEMENT [DIAMETER CENTRALIZER: YES Пио TOTAL BENTONITE [] 5 cm. WELL GROUT 🔲 🖁 2 IN. COMPLETION: FLUSH MOUNT STICKUP ☐ RISER BOX SILICA SAND DEPTH SCH: 40 PVC LOCK TYPE: DOLPHIN MASTER KEY NO. NATIVE SOIL [FROM OTHER OTHER 🗌 🌋 TOC PAD: 2'X2' 4'X4' OTHER CUTTINGS: DRUMMED NUMBER OF DRUMS 5 M. 16,4 FT. SPREAD OTHER SEAL BENTONITE 15 cm. ☐ MASONRY SAND DEVELOPMENT NONE BAILING DUMPING AIRLIFT 0.5 FT. OTHER METHOD: SURGE & BLOCK OTHER TIME: 10 MIN 20 MIN OTHER MIN AMOUNT ☐,5 GAL ☐ 10 GAL OTHER GAL WATER BEFORE: 🗹 SILTY TURBID □ OPAQUE □.CLEAR FILTER WATER AFTER: SILTY □ OPAQUE CLEAR PACK WELL EVIDENT ODOR: YES NO TYPE SCREEN DEVELOPMENT TORUMMED NUMBER OF DRUMS 15, FT. LENGTH TYPE WATER: SPREAD TREATED POTW OTHER #3 SAND FT. M. OVÉR WELL SUMP ☐ YES ☐ NO IN. (CROSS OUT IF NOT DRILLED) A contrative PREPARED BY:

PSI Rev. 12/95 APPENDIX C: SURVEY DATA

MONITORING WELL LOCATIONS AND ELEVATIONS

IN THE VICINITY OF

500 KIRKHAM STREET

OAKLAND, CALIFORNIA

The following tables represent a summary of the Horizontal and Vertical Locations for the seven wells at or near the site. Values are shown for both FEET and METERS.

ELEVATIONS (MSL)

WELL ID	ELEV. (M)	ELEV. (Ft)
JA-4	3.83	12.58
JA-3	3.85	12.64
JA-2	4.01	13.15
JA-1	4.61	15.12
CR-3	2.95	9.67
CR-2	3.11	10.20
CR-1	4.29	14.07

Notes: Elevations were derived directly in feet and converted to meters using the standardized equation: 1 Meter = 39.37 / 12 Feet,

Elevations were based upon information provided by CalTrans: Flight Cross @ 5th & Kirkham having an elevation of 11.05 - Mean Sea Level (MSL).

Elevations were taken upon the top of the well casing pvc pipe inside of the casting.

å TB

To PSI

1320 West Winton Avenue Hayward, California

Attention: Ms. Adriana Constantinesc

From: Gilbert E. Hayes

Engineering Associates

P.O. Box 11078

Oakland, California; 94611-0078

Re Kirkham Streeet Monitoring Wells

Dear: Adriana:

After receiving the necessary monument coordinates from CalTrans this afternoon, I have re-calculated the values for the wells as follows:

Values are Per Cal Trans Values for the found monuments, and are accurate to within 0.1

POINT	NORTHING	EASTING	NOTES/COMMENTS
A829	479609,3440	1482692.9010	Found CalTrans Mon
A831	479582.0667	1482524.9894	Found CalTrans Mon
FD77	479491.1410	1483018.4670	Fnd. Tag in Curb
CF1	479332.7425	1482561.2768	M. Well
CF2	479195,0284	1482408.2584	M. Well
CF3	479037.4057	1482450.1000	M. Well
JA4	479665.4877	1482589,9081	M. Well
JA3	479699.0678	1482525.4298	M. Well
JA2	479728.5120	1482476.9972	M. Well
JA1	479916.6308	1482518.7732	M. Well

Please call if you have any questions.

g

APPENDIX D

LABORATORY RESULTS AND CHAIN-OF-CUSTODY RECORDS

CERTIFIED HAZARDOUS WASTE TESTING LABORATORY . CHEMICAL AND BIOLOGICAL ANALYSES

Client:

PSI

1320 W. Winton Ave.

Hayward, CA 94545

Date Sampled:

04/26/00

Date Received:

04/28/00

Job Number:

16373

Project: Caltrans - J&A Trucking

CASE NARRATIVE

The following information applies to samples which were received on 04/28/00:

The samples were received at the laboratory chilled and sample containers were intact.

Unless otherwise noted below, the Quality Control acceptance criteria were met for all samples for every analysis requested.

Report approved by:

Robert R. Clark, Ph.D. Laboratory Director

ELAP # 1184

DL: Detection Limit -- The lowest level at which the compound can reliably be detected under normal laboratory conditions.

ND: Not Detected -- The compound was analyzed for but was not found to be present at or above the detection limit.

NA: Not Analyzed - Per client request, this analyte was not on the list of compounds to be analyzed for.



Metals

Client: PSI

Project: Caltrans - J&A Trucking

Job No: 16373 Matrix: Soil Analyst: RLB/TLR Date Sampled:

04/26/00

Date Received: Date Digested:

04/28/00

: Date Analyzed:

05/01/00

Batch Number:

05/02-06/00 6010S1551

		Sample ID:	Blank	JA1-7.0	JA2-7.0	JA3-7.0	JA4-6.5
Element	Method #	DL	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg
Antimony	6010	2.5	ND -	ND	ND	ND	ND
Arsenic	6010	0.50	ND	2.1	2.5	3.0	2.4
Barium	6010	0.50	ND.	37	47	47	56
Beryllium	6010	0.50	ND	ND	ND	ND	ND
Cadmium	6010	0.50	ND	ND	ND	ND	ND
Chromium	6010	0.50	ND	30	35	38	48
Cobalt	6010	0.50	ND	4.6	5.3	5.6	5.8
Copper	6010	0.50	ND	5.3	6.8	8.4	7.6
Lead	6010	0.50	ND	1.5	2.0	3.9	2.5
Mercury	7471	0.10	ND	ND	ND	ND	ND
Molybdenum	6010	0.50	ND	ND	ND	ND	ND
Nickel	6010	1.0	ND	26	32	32	
Selenium	6010	2.5	ND	ND	ND	ND	ND
Silver	6010	1.0	ND	ND	ND	NO	ND
Thallium	6010	2.5	ND	ND	ND	ND	ND
Vanadium	6010	0.5	ДŃ	21	27	29	30
Zinc	6010	10	ND	19	23	25	26
					2020000000		



QC Sample Report - Metals

Matrix: Soil

Batch #: 6010S1551

MS/MSD Sample ID: JA1-7.0

	Batch P	recision	Results	:		Batch A	ccurac	y Results:	
Metal	Spike Sampte Recovery mg/Kg	Spike Duplicate Recovery mg/Kg	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass / Fail	Spike Concentration mg/Kg	% Recovery LCS	Acceptance Limits Percent Recovery	Pass / Fail
Antimony	52.2	52.0	0%	20%	Pass	50	112	75 - 125	Pass
Arsenic	51.8	52.0	0%	20%	Pass	50	107	75 - 125	Pass
Barium	85.9	86.4	1%	20%	Pass	50	105	75 - 125	Pass
Beryllium	50.7	52.3	3%∵	20%	Pass	50	107	75 - 125	Pass
Cadmium	48.2	48.7	1%	20%	Pass	50	107	75 - 125	Pass
Chromium	79.1	81.5	3%	20%.	Pass	50	108	75 - 125	Pass
Cobalt	53.0	53.9	2%	20%	Pass	50	108	75 - 125	Pass
Copper	57,4	58,2	1%	20%	Pass	50	108	75 (25	Pass
Lead	50.7	50.6	0%	20%	Pass	50	107	75 - 125	Pass
Mercury	2.74	2.80	2%	20%	Pass	2.5	111	75 125	Pass
Molybdenum	52.2	52.2	0%	20%	Pass	50	113	75 - 125	Pass
Nickef	75.4	77.7	3%	20%	Pass	50	108	75 - 125	Pass
Selenium	48.1	48.9	2%	20%	Pass	50	103	75 - 125	Pass
Silver	49.1	50.1	2%	20%	Pass	50	104	75 - 125	Pass
Thallium	48.0	48.8	2%	20%	Pass	50	107	75 - 125	Pass
Vanadium	70.3	71.2	1%	20%	Pass	50	109	75 4 125	Pass
Zinc	69.0	70.1	2%	20%	Pass	50	115	75 - 125	Pass

Ana	lytical	Not	es

LCS: Laboratory Control Sample

MS: Matrix Spike

RPD: Relative Percent Difference

LCSD: Laboratory Control Sample Duplicate

MSD: Matrix Spike Duplicate



Modified 8015 - Fuel Screen

Client:

PSI

JL

Project:

Caltrans - J&A Trucking

Job No.:
Matrix:

16373 Soil

Analyst:

Date Sampled:

04/26/00

Date Received:

04/28/00

Date Extracted:

05/01/00

Date Analyzed:

05/01/00

Batch Number:

8015DS1909

Fuel Identified:	Diesel	Motor Oil	Detection Limits
Units:	mg/kg		mg/kg
Blank	ND	ND	10
JA1-7.0	ND	ND	10
JA2-7.0	ND	DN	10
JA3-7.0	ND	ND	10
JA4+6.5	ND	ND	10



QC Sample Report - EPA 8015M Diesel

Matrix: Soil

Batch #: 8015DS1909

Batch Accuracy Results

Analyte	Spike Concentration mg/Kg	% Recovery LCS	Acceptance Limits % Recovery	Pass/Fail
Olesel	100	82	70 - 130	Pass

Analytical Notes:	
·	
	,
· ·	

Batch Precision Results

Analyte Dieset	. ගි අ 82	<u>ज दें</u> 75	<u>∝ ⊆</u>	29%	Pass
	Spike Sample Recovery mg/Kg	Spike Duplicate Recovery mg/Kg	Relative Percent Difference (RPD)	pper Control Limit PD	ass/Fail

MS:	Matrix	Spike	Sample	ı
MSC): Matri	x Spik	e Duplic	ate

Analytical Notes:	
İ	
[
5	
<u> </u>	
ĺ	
Ì	
]	



Modified 8015 - Total Volatile Hydrocarbons as Gasoline

Client:

PSI

Project:

Caltrans - J&A.Trucking

Job No.:

16373

Matrix:

Soil CP

Analyst:

Date Sampled:

04/26/00

Date Received:

04/28/00

Date Analyzed:

05/01/00

Batch Number:

8015GS2591

	Detection Limit	Petroleum Hydrocarbons as	
Sample ID	mg/kg	Gasoline mg/kg	
Method Blank	0.50	ND ND	
JA1-7.0	0.50	ND	, (504, 504)
JA2-7.0	0.50	NO	
JA3-7.0	0.50	ND	**************************************
JA4-6:5	0.50	ND	

Breedland - Florida Parker



QC Sample Report - EPA 8015M Gasoline

Matrix: Soil

Batch #: 8015GS2591

Batch Accuracy Results

Sample ID: Laboratory Contr	Spike Concentration mg/Kg	% Recovery LCS	Acceptance Limits % Recovery	Pass/Fail
Gasoline	10.0	100	70 - 130	Pass

Analytical Note	:
	-
·	

Batch Precision Results

Analyte	Spike Sample Recovery mg/Kg	Spike Duplicate Recovery mg/Kg	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass/Fail
Gasoline	7.24	7.37	2%	30%	Pass

	Analytical Notes:
İ	
	·

MS: Matrix Spike Sample MSD: Matrix Spike Duplicate



EPA 8080 - Organochlorine Pesticides & PCBs

Client:

PSI

Project:

Caltrans - J&A Trucking

Job No.: 16373 Matrix: Soil Analyst: TPW Date Sampled:

04/26/00

Date Received: 04/2
Date Extracted: 05/0

04/28/00 05/01/00

Date Analyzed:

05/05/00

Batch Number: PESTS0249

·····	Sample ID:	Biank	JA1-7.0	JA2-7.0	JA3-7.0	JA4-6.5
Pesticides	DL	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg
Aldrin	0.001	ND	ND	ND	ND	ND
Alpha-BHC	0.001	ND	NÐ	ND	ND	ND CONTRACTOR
Beta-BHC	0.001	ND	ND	ND	ND.	ND
Delta-BHC	0.001	ND	ND	ND	ND	ND
Gamma-BHC (Lindane)	0.001	ND	ND	ND	ND	ND
Chlordane:	0.010	ND	ND	NO	ND	ND
4,4'-DDD	0.002	ND	ND	ND	ND	ND
4,4'-DDE	0.002	NO	ND	ND	ND	ND
4,4'-DDT	0.002	ND	ND	ND	ND	ND
Dieldrin	0.002	NO	ŃĎ	ND.	ND	ND
Endosulfan I	0.001	ND	ND	ND	ND	ND
Endosulfan II	0.002	ND	ND	ND	ND	ND
Endosulfan sulfate	0.002	ND	ND	ND	ND	ND
Endrin	0.002	ND	ND	MD.	ND	ND
Endrin Aldehyde	0.002	ND	ND	ND	ND	ND
Endrin Kefone	0.010	ND	ND	ND	ND	ND
Heptachlor	0.001	ND	ND	ND	ND	ND
Heptachlor Epoxide	0.001	ND	ND	ND	ND	ND
Methoxychlor	0.010	ND	ND	ND	ND	ND
Toxaphene	0.020	ND	ND.	ND	ND	NO
PCBs			<u> </u>	<u> </u>	<u> </u>	
Aroclor-1016	0.050	ND	NÐ	ND	ND	ND
Aroclor-1221	0.050	ND	ND	ND	ND	ND
Aroclor-1232	0.050	ND	ND ND	ND	ND	ND
Aroclor-1242	0.050	ND	ND	ND	ND	ND
Aroclor-1248	0.050	ND	ND	МD	ND	ND
Aroclor-1254	0.050	ND	ND	ND	ND	ND
Aroctor-1260	0.050	ND	ND	ND	NO	NO

Surrogates (% recovery) Limits: 50 - 150

	Sample ID:	Blank	JA1-7.0	JA2-7.0	JA3-7.0	JA4-6.5
Tetrachioro-m-xylene		117	135	118	118	131

QC Sample Report - EPA 8080 Pesticides

(800) 798-9336

Matrix: Soil

Batch #: PESTS0249

Batch Accuracy Results

Sample ID: Laboratory Cont	rol Sample			
Analyte	Spike Concentration mg/Kg	% Recovery LCS	Acceptance Limits % Recovery	Pass/Fail
Lindane	0.0066	90	32 - 127	Pass
Heptachlor	0.0066	98	34 - 1/1	Pass
Aldrin	0.0066	109	42 - 122	Pass
Dieldrin	0.026	88	36 - 146	Pass
Endrin	0.026	102	30 - 147	Pass
DOT	0.026	93	25 - 160	Pass
Aroclor 1242	0.0667	83	75 - 127	Pass

Analytical Notes:	<u> </u>
:	. 11
	·
• ,	

Batch Precision Results

MS/MSD Sample ID: Labor	atory Conti	rol Sample	· · · · · · · · · · · · · · · · · · ·		
Analyte	Spike Sample Recovery mg/Kg	Spike Duplicate Recovery mg/Kg	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass/Fail
Lindane	0.0030	0.0028	7%	25%	Pass
Heptachlor	0.0033	0.0036	9%	25%	Pass
Aldrin	0.0036	0.0035	3%	25%	Pass
Dieldrin	0.0117	0.0108	8%	25%	Pass
Endrin	0.0135	0.0117	14%	25%	Pass
DDT	0.0124	0.0112	10%	25%	Pass

Analytical Notes:

MS: Matrix Spike Sample MSD: Matrix Spike Duplicate

(800) 798-9336

Client:

PSI

16373

Project:

Caltrans - J&A Trucking

Job No.: Matrix:

Analyst:

Soil **MBH**

04/26/00

Date Sampled: Date Received: 04/28/00

Date Analyzed:	05/01/00
Batch Number:	M48260S182
*	

	Sample ID:	Blank	JA1-7.0	JA2-7.0	JA3-7.0	JA4-6.5	:
Compounds	· DL	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg	·
Acetone	0.05	ND	ND	ND	ND	ND	
tert-Amyl Methyl Ether (TAM		ND	NO	ND	ND	ND	
Benzene	0.001	ND	ND	ND	ND	ND	tururururur.
Bromobenzene	0,005	D.	ND	NĐ	ND :	ND	
Bromochloromethane	0.005	. ND	ND	ND	ND	ND	arrielelel
Bromodichloromethane	0.001	ND	NO	ND	NO	ND	
Bromoform	0.005	ND	ND	ND	ND	ND	11111111111
Bromomethane	0.01	ND	ND	NĐ	ND	ND	
tert-Butanol (TBA)	0.05	ND	ND	ND	ND	ND	
2-Butanone (MEK)	0.01	ND	NO	ND	ND	ND	
n-Butylbenzene	0.002	ND	ND	ND	ND	ND	(Hereit)
sec-Butylbenzene	0.002	ND	NO	ND	ND	ND	
tert-Butylbenzene	0.002	ND	ND	ND	ND	ND	210000
Carbon disulfide	0.01	ND	ND	ND	ΝĎ	ND STATE	
Carbon tetrachloride	0.001	ND	ND	ND	ND	ND	
Chlorobenzene	0,001	ND	NO	ND	ND		555555
Chloroethane	0.005	ND	ND	ND	ND	ND	
Chloroform	0.002	ND	ND	NO	ND	ND	
Chloromethane	0.001	ND	ND	ND	ND	ND	
2-Chlorotoluene	0,002	ND	ND	NĐ	ND	ND	03355
4-Chlorotoluene	0.002	ND	ND	ND	ND	ND	
Dibromochloromethane	0.002	ND	ND	ND	NO	ND:	
1,2-Dibromoethane	0.002	ND	ND	ND	ND		
1,2-Dibromo-3-chloropropan		ND	NO	NO	ND	ND ND	-1-1-1-1-1-1-
Dibromomethane	0.001	ND	ND	ND	ND	ND	
1;2-Dichlorobenzene	0.001	ND	NO	NO	ND		1414141
1,3-Dichlorobenzene	0.002	ND	ND	ND	ND	ND	
1,4-Dichlorobenzene	0.002	סא	NO	ND ON	ND	ND	erene. Ordetetet i
Dichlorodifluoromethane	0.005	ND	ND	ND	ND	NO	
1:1-Dichloroethane	0.001	NO	0.001	ם מא	0.001	ND	
1,2-Dichloroethane	0.001	ND	ND		cialataista latataista (s. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.	0.001	
1,1-Dichloroethene	0.005	ND	ND	ND	ND	ND	
cis-1,2-Dichloroethene	0.002	ND		ND	ND:	ND	
trans-1,2-Dichloroethene	0.002	NO NO	ND	ND	ND	ND	,,,,,,,,,,
1,2-Dichloropropane	0.002	**********	NO	ND	ND	ND	
1,3-Dichloropropane	0.001	ND	ND	ND	ND	ND	.,,,,,,,
2,2-Dichloropropane	0.001	ND	ND:	ND	ND	ND	
1.1-Dichloropropene	0.001 0.001	ND	ND	ND	ND	ND	ururururur
161 Aprillabilabile	0.001	ND	ND	NO	ND	ND	

04/26/0(800) 798-9336

Client:

PSI

Project:

Caltrans - J&A Trucking

Job No.: Matrix:

16373 Soil

Analyst:

MBH

Date Sampled:

Date Received:

Date Analyzed:

Batch Number:

04/28/00 05/01/00

M48260S182

	Sample ID:	Blank	JA1-7.0	JA2-7.0	JA3-7.0	JA4-6.5
Compounds	DL	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg
cis-1,3-Dichloropropene	0.001	ND.	ND	ND	ND	ND
trans-1,3-Dichloropropene	0.001	ND	ND	ND	ND	ND
Diisopropyl Ether (DIPE)	0.005	ND	ND	ND	ND	ND
Ethylbenzene	0.001	ND	NO	ND	ND	ND CONTRACTOR
Ethyl tert-Butyl Ether (EtBE)	0.005	ND	ND	ND	ND	ND
Hexachlorobutadiene	0.001	ND	ND	ND	SENDER	ND:
2-Hexanone	0.01	ND	ND	ND	ND	ND
lsopropylbenzene:	0.001	ND	NØ	ND	ND	ND SEE SEE
p-Isopropyltoluene	0.002	ND	ND	ND	ND	ND
Methylene chloride	0.02	ND	ND	DA	ND	ND ND
4-Methyl-2-pentanone	0.01	ND	ND	ND	ND	ND
Methyl fert-Butyl Ether (MfB	E) 0.005	NÓ	ND	ND	ND	ND
Napthalene	0.002	ND	ND	ND	0.003	0.020
n-Propylbenzene	0.001	ND	ND	ND	ND	ND:
Styrene	0.001	ND	0.001	0.001	ND	0.001
1,1,1,2-Tetrachloroethane	9.001	ND	ND	ND	ND	ND
1,1,2,2-Tetrachloroethane	0.002	ND	ND	ND	ND	ND
Tetrachloroethene	0.001	ND	ND	ND:	ND	ND
Toluene	0.001	ND	ND	ND	ND	ND
1,2,3-Trichlorobenzene	0.002	ND	ND	ND	ND	ND
1,2,4-Trichlorobenzene	0.002	ND	ND	ND	ND	ND
1,1,1-Trichloroethane	0:001	ND	0.007	0.005	0.006	0.00s
1,1,2-Trichloroethane	0.003	ND	ND	ND	ND	ND
Trichloroethene	0.001	ND	NO	ND	ND	ND
1,2,3-Trichloropropane	0.003	ND	ND	ND	ND	ND
Trichlorofluoromethane	0.001	ND	NO	ND	ND	ND
Trichlorotrifluoroethane	0.005	ND	0.008	0.007	0.006	0.007
1,2,4-Trimethylbenzene	0.001	ND	ND	ND	ND	ND
1,3,5-Trimethylbenzene	0.001	ND	ND	ND	ND	ND
Viriyl chloride	0.002	ND	ND	סא	ND	ND
Xylenes (total)	0.003	ND	ND	ND	ND	ND

Surrogates (% recovery) Limits: 80 - 130

	, 100					
Sample ID:	Blank	JA1-7.0	JA2-7.0	JA3-7.0	JA4-6.5	
Dibromofluoromethane						
Toluene-d8	102	94	110	101	100	
Bromofluorobenzene	98	97	106	102	00001 97 00000000	



QC Sample Report - EPA Method 8260

Matrix: Soil

Batch #: MS48260S182

Batch Accuracy Results

Sample ID: Laboratory Contr	roi Sample			
Analyte	Spike Concentration mg/Kg	% Recovery LCS	Acceptance Limits % Recovery	Pass/Fail
1,1-Dichloroethene	0.020	107	59 - 172	Pass
Benzene	0.020	93	66 142	Pass
Trichloroethene	0.020	90	71 - 137	Pass
Тоіцеле	0.020	88	59 - 139	Pass
Chlorobenzene	0.020	94	60 - 133	Pass

Analytical Notes:	
<u>-</u>	
	1
	-
·	l
	.
·	
·	
	ı

Batch Precision Results

MS/MSD Sample ID: 16350-1									
Analyte	Spike Sample Recovery mg/Kg	Spike Duplicate Recovery mg/Kg	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass/Fail				
1,1-Dichloroethene	0.0225	0.0235	4%	22%	Pass				
Senzene	0.0196	0.0198	1%	21%	Pass				
Trichloroethene	0.0202	0.0190	6%	24%	Pass				
Toluene	0.0195	0.0176	10%	21%	Pass				
Chlorobenzene	0.0201	0.0201	0%	21%	Pass				

Analytical Notes:	
·	
	•
1	,

MS: Matrix Spike Sample
MSD: Matrix Spike Duplicate



04/26/00

EPA 8270 Semivolatile Organics

Client: PSI Date Sampled: Project: Caltrans - J&A Trucking Date Received:

 Project:
 Caltrans - J&A Trucking
 Date Received:
 04/28/00

 Job No.:
 16373
 Date Extracted:
 05/03/00

 Matrix:
 Soil
 Dates Analyzed:
 05/05/00

 Analyst:
 TPW
 Batch Number:
 8270S0621

	Sample ID:	Blank	JA1-7.0	JA2-7.0	JA3-7.0	JA4-6.5	
Compound	DL	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg	
Acenaphthene	0.033	ND	ND.	, ND	· ND	ND	
Acenaphthylene	0.033	ND	ON	ND	0.055	ND	
Anthracene	0.033	ND	ND	ИD	ND	ND	
Benzojajanthracene	0.066	ND	ND	NO	··· ND	ND	
Benzo(a)pyrene	0.066	ND	ND	ND	ND	ND	
Benzo[b]fluoranthene	0.033	ND	ND	GM	NĐ	ND	
Benzo(g,h,i]perylene	0.099	ND	ND	ND	ND	ND	
Benzo[k]fluoranthene	0.099	ND	NO	NO	ND	ND	
Benzyl alcohol	0.13	ND	ND	ND	ND	ND	
bis(2-Chloroethoxy)methal	ne 0.066	ND	ND	NO	ND	ND	
bis(2-Chloroethyl)ether	0.066	ND	ND	ND	ND	ND	
bis(2-Chloroisopropyl)ethe	r 0.099	ND	NO	NO	NØ	ND	
bis(2-Ethylhexyl)phthalate	0.33	ND	ND	ND	ND	ND	
4-Bromophenylphenylethe	r 0.033	ND	ND	ND	ND	ND	
Butylbenzylphthalate	0.033	ND	ND	ND	ND	ND	
4-Chloro-3-methylphenol	0.16	ND:	ND	NO	ΝD	ND	
4-Chloroaniline	0.16	ND	ND	ND	ND	ND	
2-Chloronaphthalene	0.033	ND:	ND	NĐ	ND	ND	
2-Chlorophenol	0.13	ND	ND	ND	ND	ND	
4-Chlorophenylphenylethe	r 0.033	ND	ND	NO	ND	ND	
Chrysene	0.033	ND	ND	ND	ND	ND	
Di-n-butylphthalate	0.33	ND	NO	ND	CN	ND	
Di-n-octylphthalate	0.033	ND	ND	ND	ND	ND	
Dibenzo[a,h]anthracene	0.099	ND	NO	NO	ND	ND	
Dibenzofuran	0.033	ND	ND	ND	ND	ND	.,.,
1,2-Dichlorobenzene	0.033	ND	ND	NO	ND	ND	
1,3-Dichlorobenzene	0.033	ND	ND	ND	ND	ND	
1,4-Dichlorobenzene	0.033	ND	NO	NO	NO	ND	
3,3-Dichlorobenzidine	0.13	ND	ND	ND	ND	ND	
2.4-Dichlorophenol	0.16	ND	ND	ND	ФИ	ND	
Diethylphthalate	0.33	ND	ND	ND	ND	ND	
2.4-Dimethylphenol	0.099	ND	ND	NO	ND	ND	
Dimethylphthalate	0.033	ND	ND	ND	ND	ND	
4.6-Dinitro-2-methylpheno	0.33	ND	ND	ND	ND	ND	
2,4-Dinitrophenol	1.6	ND	ND	ND	ND	ND	
2,4-Dinitrotoluene	0.033	ND	NO	NO	ND	ND	



EPA 8270 Semivolatile Organics

Client: PSI
Project: Caltrans - J&A Trucking

Job No.: 16373 Matrix: Soil Analyst: TPW Date Sampled: 04/26/00
Date Received: 04/28/00
Date Extracted: 05/03/00
Dates Analyzed: 05/05/00

Batch Number: 8270S0621

	Sample ID:	Blank	JA1-7.0	JA2-7.0	JA3-7.0	JA4-6.5	
Compound	DL	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg	
2,6-Dinitrotoluene	0.099	ND	ND	ND	ND	ND	
Fluoranthene	0.033	ND	ND	GN	0:072	ND	
Fluorene	0.033	ND	ND	ND ND	ND	ND	
Hexachlorobenzene	0.033	ND.	ND	····ND····	МÐ	ND	
Hexachlorobutadiene	0.033	ND	ND	ND	ND	ND .	
Hexachlorocyclopentadien	ie 1.6	ND	ND	ND	ND	ND	
Hexachloroethane	0.033	ND	ND	ND	ND	ND	
Indeno[1,2,3-c;d]pyrene	Q.13	ND	ND	ND	ND	ND	
Isophorone	0.033	ND	ND	ND	ND	ND	
2-Methylnaphthalena	0.033	ND	ND	ND	ND	ON	
2-Methylphenol	0.16	ND	ND	ND	ND.	ND .	
4-Methylphenol	0.16	ND	МĎ	NΦ	ND	ND	
N-Nitrosodi-n-propylamine	0.033	ND	МD	ND	ND	ND	
N-Nitrosodiphenylamina	0.033	ND	ND	ND.	ND	ND	
Naphthalene	0.033	ND	ND -	ND	0.28	ND	
2-Nitroaniline	0.099	ND	ND	NΦ···	QN	ND	
3-Nitroaniline	0.099	ND	ND	ND	ND .	ND	
4-Nitroaniline	0.33	ND	ND	ND	ND.	ND	
Nitrobenzene	0.099	ND	ND	ND	ND	ND	
2-Nitrophenol	0.13	ND	ND	ND	ND	ND	
4-Nitrophenol	0.33	ND	ND	ND	ND	ND	
Pentachiorophenol	1.6	ND	ND	ND	ND	ND	
Phenanthrene	0.066	ND	ND	ND	0.10	ND	
Phenol	0.13	ND	ND	NO	ND	ND	
Pyrene	0.033	ND	ND	ND	0.14	ND	
1,2,4-Trichlombenzene	0.033	ND	ND	ΝD	ND	ND	
2,4,5-Trichlorophenol	0.2	ND	ND	ND	ND	ND	
2,4,6-Trichlorophenol	0.33	ND	NO	ŃĎ	NØ	ND	

Surrogates (Limits) in Percent Recovery

Sample ID:	Blank	JA1-7.0	JA2-7.0	JA3-7.0	JA4-6.5	
2-Fluorophenol (25 - 121%)	7.5	84	81	87	79	
Phenol-D5 (24 - 113%)	73	82	80	87	77	
Nitrabenzene-D5 (23 - 120%)	60	.67	65	71	64	
2-Fluorobiphenyl (30 - 115%)	77	83	84	87	80	
2,4,6-Tribromophenot (19 - 122%)	90	92	94	95	87	
p-Terphenyl-D14 (18 - 137%)	86	82	84	108	80	



QC Sample Report - EPA 8270

Batch #: 8270S0621

Matrix: Soil

Sample	ID:	Laboratory	Control	Sample
--------	-----	------------	---------	--------

Analyte	Spike Concentration mg/Kg	% Recovery LCS	Acceptance Limits % Recovery	Pass/Fail
Phenol	2.66	80	5 - 112	Pass
2-Chlorophenol	2.66	94	23 - 134	Pass
1,4-Dichlorobenzene	1.33	. 91	20 - 124	Pass
N-Nitrosodi-n-propytamine	1.33	71	0 - 230	Pass
1,2,4-Trichlorobenzene	1.33	96	44 - 142	Pass
4-Chloro-3-Methylphenol	2.66	90	22 - 147	Pass
Acenaphthene	1.33	89	47 - 145	Pass
4-Nitrophenol	2.66	104	0 - 132	Pass
2,4-Dinitrotoluene	1.33	92	39 - 139	Pass
Pentachlorophenol	2.66	126	14 - 176	Pass
Pyrene	1.33	90	52 - 115	Pass

Analytical Notes:

Batch Precision Results

MS/MSD Sample ID: Laboratory Control Sample

Analyte	Spike Sample Recovery mg/Kg	Spike Dupticate Recovery mg/Kg	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass/Fail
Phenol	2.12	1.95	9%	35%	Pass
2-Chlorophenol	2.50	2.27	10%	50%	Pass
1,4-Dichlorobenzene	1.22	1.12	9%	27%	Pass
N-Nitrosodi-n-propylamine	0.95	88.0	7%	38%	Pass
1,2,4-Trichlorobenzene	1.28	1.16	10%	23%	Pass
4-Chloro-3-Methylphenol	2.39	2.23	7%	33%	Pass
Acenaphthene	1.18	1.09	8%	23%	Pass
4-Nitrophenol	2.77	2.60	6%	50%	Pass
2,4-Dinitrotoluene	1.23	1.15	6%	47%	Pass
Pentachlorophenol	3.36	3.11	8%	47%	Pass
Pyrene	1.20	1.11	8%	36%	Pass

Analytical Notes:	
·	
·	
1	
1	
·	
1	

290 TENNESSEE STREET

(909) 798-9336 • (800) 798-9336

REDLANDS, CA 92373 www.centrum-labs.com

FAX (909) 793-1559 iab@centrum-labs.com

Centrum Job # 16373 **Chain of Custody Record**

							/:		P	lea:	se (Circ	e A	nal	yse	s R	equ	est	ed		\geq	
Project No: Project Man Client Name (Report and Blike			Phone:	244 745	3	HATRUCKENG CONTAINER FREE 1111 510 785-1192 20 W. WINTON AVE HYWARO, CA 94545	Please Fuel Screen, Carbon Chair	is only	BTEX/MIBE Only	H), 413.2	! ``	(8260B " 80278 C. EL, 21. 53	MtBE Conf. Only	8270C) 625	8080: Pesticides, PCBs(Pest/PCB)		Metals: (Title 22 (CAM) RCRA, PP	TSS, Conductivity	t, Hex Cr			Turn-Around Time 24 Hr. RUSH* 48 Hr. RUSH* Normal TAT Requires PRIOR approval, additional charges apply Requested due date:
Centrum ID (Cab use only)	Sample ID (As It should appear on report)	Date sampled	Time sampled	Samp		Site location Containers # and type	: 👙	8015M: Gas	8021B: BI	418.1 (TRPH),	WHOS	GCMS: (8)	GCMS: M	GCMS: (82	8080: Pest		Metals:	pH, TDS,	Flashpoint,		, .	Remarks/Special Instructions
1	TA1-7.0	4-26-11	0834	501	2	1355	X	X			X	X		X	X		X					
2	TA2-7.0	1	1050	-			X	\times			X	Χ		X	X	l _	X					
3	JA3-7.0		1305				X	X			X	Χ		X	Χ		X					
Ý	JA4-6.5	V	1516	•	,	•	X	X			X	X		X	X		X	_				
1 ' / 1 '	hed by: (Sampler's Signature) S MERRITT	1	Dato: 4-27-00	Time:	٥	3) Relinquished by:	Date		Time		ĺ	be c										Sample Disposal
2) Received	by:		Date:	Time:		4) Received by: 5) Relinquished by:	Date		Time		C	mple istod:	y sea	ls?	۵	Yes	γ'n	۵,			1	☐ Client will pick up ☐ Return to client
constitutes	y of samples and the signature of authorization to perform the an and Conditions set forth on the b	alyses spec	cified abov		- 1		9ale	, 28	Time	α		l sam Cour										A Lab disposal
Laboratory	Notes:					V 0						R	E	LE	⊇V:	e(۷. ح	(7		⊦° (-	Sample Locator No.

Centrum Job # 16393

290 TENNESSEE STREET

(909) 798-9336 • (800) 798-9336

REDLANDS, CA 92373 FAX (909) 793-1559 **Chain of Custody Record**

Please Circle Analyses Requested	\
Project No: Project Name: ALTRANS	Turn-Around Time ☐ 24 Hr. RUSH*
Project Manager: Phone: Fax: \$10785-1111 \$10785-1112 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	☐ 48 Hr. RUSH* III Normal TAT
Project No: Project Name: Project Manager: Pr	*Requires PRIOR approval, additional charges apply Requested due date:
(Report and Billing) Centrum ID Sample ID Combined Sampled Control ID Con	Remarks/Special Instructions
1 JA-1	BEOKEN BOTTLE
2 JA-2 1045 1 10 XX XX XX	# 2 LITER BOTTLE BROKEN
3 JA-3 1150 10 XX XX XX	# LITER BOTTLE
4 JA-4 1220 10 XX XX XX X	# ! LITER BOTTLE BROKEN.
5 CF-1 1615 8 XX XX XX	
6 CF-2 1415 B8 XX XX X	
7 CF-3 1 1335 10 XX XX X	
8 CF-10 1530 8 XX XX X	
1) Relinquished by: (Sampler's Signature) (1) REST MERETT 5-2-00 (1000) Date: Time: 3) Relinquished by: Date: Time: To be completed by Laboratory personne	
2) Received by: Date: Time: 4) Received by: Date: Time: Samples chilled? Date: Time: Custody seals?	Field Client will pick up
The delivery of samples and the signature on this chain of custody form Signature Containers Container	to Vi Lab disposal
constitutes authorization to perform the analyses specified above under the Terms and Conditions set forth on the back hereof. 6) Received for Laboratory by: 73 1:00	led
Laboratory Notes: FILTER METALS	Sample Locator No.
	F-14VOA



CERTIFIED HAZARDOUS WASTE TESTING LABORATORY . CHEMICAL AND BIOLOGICAL ANALYSES

Client: PSI

> 1320 W. Winton Ave. Hayward, CA 94545

Date Sampled:

05/02/00

Date Received:

05/03/00

Job Number:

16393

Project: CT J&A Truck/Container Freight

CASE NARRATIVE

The following information applies to samples which were received on 05/03/00:

The samples were received at the laboratory chilled and sample containers were intact.

Unless otherwise noted below, the Quality Control acceptance criteria were met for all samples for every analysis requested.

6010B: Some samples were run at a dilution due to sample matrix effects; consequently, reporting limits were raised.

Report approved

Laboratory Director

ELAP # 1184

DL: Detection Limit -- The lowest level at which the compound can reliably be detected under normal laboratory conditions.

NO: Not Detected -- The compound was analyzed for but was not found to be present at or above the detection limit.

NA: Not Analyzed - Per client request, this analyte was not on the list of compounds to be analyzed for.



Metals

Client: PSI

Project: CT J&A Truck/Container Freight

Job No: 16393 Matrix Water Analyst: RLB/TLR Date Sampled: Date Received:

05/02/00

Date Digested:

05/03/00 05/04/00

Date Analyzed:

05/04-15/00

Batch Number: 6010W1555

·		Sample ID:	Blank	JA-1	JA-2	JA-3	JA-4
Element	Method #	DL	mg/L	mg/L	mg/L	mg/L	mg/L
Antimony	6010B	0.015	ND	ND	ND	ND	ND
Arsenic	6010B	0.010	ND	ND	ND	ND	ND
Barium	6010B	0.010	ND	0.16	0.15	0.18	0.12
Beryllium	6010B	0.010	ND	ND	ND	ND	ND
Cadmium	6010B	0.010	ND	ND	ND	ND	ND
Chromium	6010B	0.010	NĐ	ND	0.010	ND	ND
Cobalt	6010B	0.010	ND	ND	ND	ND	ND
Соррег	6010B	0.010	ND	ND	ND	ND	ND
Lead	6010B	0.010	ND	ND	ND	ND	ND
Mercury	7470	0.0002	ND	ND	ND	NO	ND C
Molybdenum	6010B	0.010	ND	ND	ND	ND	ND
Nickel	6010B	0.010	ND.	0.045	0.035	0.030	0,027
Selenium	6010B	0.015	ND	ND	ND	ND	ND
Silver	6010B	0.010	ND	ND	Й	ND	ND
Thallium	6010B	0.010	ND	ND	ND	ND	ND
Vanadium	6010B	0.010	ND	ND	ND	ND	ND
Zinc	6010B	0.10	ND	0.12	0.10	0.12	ND
				1			

Metals

Client: PSI

Project: CT J&A Truck/Container Freight

Job No: 16393 Matrix: Water Analyst: RLB/TLR Date Sampled:

05/02/00

Date Received:

05/03/00

Date Digested: Date Analyzed: 05/04/00

Batch Number:

05/04-15/00 6010W1555

	·	·	<u> </u>		<u> </u>					
F1		Sample ID:	CF-1	CF-2	CF-3	CF-10				
Element	Method #	DL*	mg/L	mg/L	mg/L	mg/L				
Antimony	6010B	0.30	. ND	ND	ND , ··	ND		•		
Arsenic	60108	0.20	ND	ND	ND	ND	1000 (1900) 1			
Barium	6010B	0.20	0.28	ND	ND	ND		CONTRACTOR 1		
Beryllium	6010B	0.20	ND	ND	ND	ND				
Cadmium	6010B	0.20	ND	ND	ND	ND	. 1.25	• ***** 4	** .*.	
Chromium	6010B	0,20	ND	ND	ND	DI	a she s			
Cobait	6010B	0.20	ND	ND	ND	ND		- :	-	
Copper	6010B	0.20	ND:	ND	ND	ND				
Lead	6010B	0.20	ND	ND	ND	ND	. + • • • • • • • • • • • • • • • • • •	p -		
Mercury	7470	0.0002	ND	ND	ND	ND			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Molybdenum	6010B	0.20	ND	ND	ND	ND				
Nickel	6010B	0.20	ND	ND	ND	ND				
Selenium	6010B	0.30	ND	ND	ND	ND				
Silver	6010B	0.20	ND	ND	ND	ND				
Thallium	6010B	0.20	ND	ND	ND	ND	• :			
Vanadium	6010B	0.20	ND	ND	ND	ND	75.		:	
Zinc	6010B	2.0	ND	ND	ND	ND				
			8000							

^{*}See Case Narrative regarding raised reporting limits.



QC Sample Report - Metals

Matrix: Water
Batch #: 6010W1555
MS/MSD Sample ID: JA-1

	* - 1	Batch F	recision	Results	s:		Batch A	its:			
Metal		Spike Sample Recovery mg/L	Spike Duplicate Recovery mg/L	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass / Fail	Spike Concentration mg/L	% Recovery LCS	Acceptance Limits	Percent Recovery	Pass / Fail
Antimony		1.01	- 1.07	6%	20%	Pass	1,0	101	75 -		Pass
Arsenic		0.99	1.05	5%	20%	Pass	1.0	97	75 -	and a second second	Pass
Barium	Maria Maria National Assessment	1.21	1.21	1%	20%	Pass	1.0	102	en a procession de constitució	125	Pass
Beryllium		0,95	1.01	6%	20%	Pass	1.0	98	75 -	125	Pass
Cadmium		1.02	1.02	0%	20%	Pass	1.0	103	75 -	125	Pass
Chromium		1,00	1.02	2%	20%	Pass	1.0	101	75 -		Pass
Cobalt		1.01	1.02	1%	20%	Pass	1.0	103	医双氯甲基 经通知 "不不是	125	Pass
Copper		1.05	1.06	1%	20%	Pass	1.0	103	75 -	40 4 4 4	Pass
Lead		0.97	1.03	6%	20%	Pass	1.0	100	the and the second	125	Pass
Mercury		2.51	2.59	3%	20%	Pass	0.005	110	Control of the Control	125	Pass
Molybdenum		1.01	1.07	6%	20%	Pass	1.0	101	inine dining begin eta e e	125	Pass
Nickel		1.02	1.06	4%	20%	Pass	1.0	101	75 -	125	Pass
Selenium		0.97	1.03	6%	20%	Pass	1.0	98	75 -	200 - 20	Pass
Silver**		1.03	1.06	3%	20%	Pass	1.0	103		125	Pass
Thallium		0.96	1.00	4%	20%	Pass	1.0	98	75 -	- 24	Pass
Vanadium	12 12 12 12 12 12 12 12 12 12 12 12 12 12 1	1.05	1.06	0%	20%	Pass	1.0	104	the second second	125	Pass
Zinc		1.13	1.13	0%	20%	Pass	1.0	113	75 -	erana a mara	Pass

Analytical Notes

**The MS/MSD for this analyte did not meet the acceptance criteria due to a sample matrix effect.

The LCS / LCSD pair was used to provide precision data for this batch.

LCS: Laboratory Control Sample

LCSD: Laboratory Control Sample Duplicate

MS: Matrix Spike

RPD: Relative Percent Difference

MSD: Matrix Spike Duplicate



Modified 8015 - Fuel Screen

Client

PSI

Project:

CT J&A Truck/Container Freight

Job No.:

16393

Matrix; Analyst: Water JL

Date Sampled:

05/02/00

Date Received:

05/03/00

Date Extracted:

05/08/00..

Date Analyzed:

05/09/00

Batch Number:

8015DW1914

Fuel Identified:	Diesel	Motor Oil	Detection Limits
Units:	mg/L	mg/L	mg/L
Blank JA-1	ND	ON	0.40
ј д- т Ј Д-2	ND 0,8	ND	0.40
16-7 (18-8)	ND	ND ND	0.40 0.40
IA 4	ND	ND	0.40
<mark>CF-1</mark>	21	ND	4.0
3F-2 3F-3	2.8	ND	0.40
.r-> ≥F-10	ND 1.8	ND ND	0.40 0.40
		e de la companya de l	

QC Sample Report - EPA 8015M Diesel

Matrix: Water

Batch #: 8015DW1914

Batch Accuracy Results

Sample ID: Laboratory Co	Spike Concentration mg/L	% Recovery LCS	Acceptance Limits % Recovery	Pass/Fail
Diesel	0.8	77	70 - 130	Pass

Analytical Notes	3: ·
i.	

Batch Precision Results

MS/MSD Sample ID: Laboratory Control Sample

Analyte	Spike Sample Recovery mg/L	Spike Duplicate Recovery mg/L	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass/Fail
Diesel	0.62	0.64	3%	25%	Pass

Analytical Notes:		

MS: Matrix Spike Sample MSD: Matrix Spike Duplicate



Modified 8015 - Total Volatile Hydrocarbons as Gasoline

Client: PSI 05/02/00 Date Sampled: Project: CT J&A Truck/Container Freight Date Received: 05/03/00 Job No.: 16393 Date Analyzed: 05/04/00 Matrix: Water Batch Number: 8015GW2593 Analyst: CP

		Detection Limit	Petroleum Hydrocarbons a Gasoline	as
Sample ID		mg/L	mg/L_	
Method Blank		0.5	ND	
JA-1		0.5	ND	eri digeria kerûan regelêrê girekê dir. Ye le
JA-2		0.5	0.77	
JA-3	ernni (filologia) — vor i november voltablent filologia (voltable) i miner	0.5	ND	in which is the fe
JA-4		0.5	ND ND	
CF-1	PROJEKO O 1995 UNIO 24 GENERA SER MOREZU A DE O T	50.0	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	
CF-2		50.0	54	
CF-3	n Mathier in terretary (1991) in the Charles (1994) in 1994 (1994) in 1994 (1994) in 1994 (1994) in 1994 (1994)	0.5	0.50	in i diku a daam T
CF-10		5.0	7.7	
	ted in the Martin in the internal and the provinces of the con-		보다 하다 나를 12 12일에 보는 것이다. 	
	·罗·斯·克尔克(罗克斯·莱克)。 -	[編集] (영화) 1 (陳왕) 1 (1) -		
e e e e e e e e e e e e e e e e e e e	경영화 기계하다 보고 사이 기 (중요한) 기계			
grafia de la Caracteria de la Caracteria de la Caracteria de la Caracteria de la Caracteria de la Caracteria d La companya de la Caracteria				
		San San San San San San San San San San		
	and the state of the control of	endia.	a section of	
1.0		1 .		
		# 1		



QC Sample Report - EPA 8015M Gasoline

Matrix: Water

Batch #: 8015GW2593

Batch Accuracy Results

Analyte	Spike Concentration mg/L	% Recovery LCS	Acceptance Limits % Recovery	ass/Fail
Gasoline	10.0	100	70 - 130	Pass

Analyt	cal Notes:
	•
ļ	· ·
1 .	

Batch Precision Results

MS/MSD Sample ID: La	boratory Conti	rol Sampl	e		
Analyte	Spike Sample Recovery mg/L	Spike Duplicate Recovery mg/L.	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass/Fail
Gasoline	10.05	9.25	8%	25%	Pass

MS: Matrix Spike Sample MSD: Matrix Spike Duplicate



EPA 8080 - Organochlorine Pesticides & PCBs

Client: PSI

Project: CT J&A Truck/Container Freight

Job No.: 16393 Matrix: Water Analyst: TPW Date Sampled: 05/02/00

Date Received: 05/03/00 Date Extracted: 05/06/00 Date Analyzed: 05/08/00

Batch Number: PESTW0251

	Sample ID:	Blank	JA-1	JA-2	JA-3	JA-4	CF-1
Pesticides	DL	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L
Aldrin	0.0001	ND	· ND	ND	ND	ND	ND
Alpha-BHC	0.0001	ND	ND	ND	ND	ND	ND
Beta-BHC	0.0001	ND	ND	ND	ND	ND	ND
Delta-BHC	0.0001	ND	ND	ND .	ND	ND	ND
Gamma-BHC (Lindane)	0.0001	ND	ND	ND	ND	ND	ND
Chlordane	0.0001	ND	ND	ND	ND	ND .	ND
4,4'-DDD	0.0002	ND	ND	ND	ΝĎ	ND	ND
4,4'-DDE	0.0002	ND	ND	ND.	ND	ND	ND.
4,4'-DDT	0.0002	ND	ND	ND -	ND	ND	ND
Dieldrin	0.0002	ND	ND	ND	ND	ND	ND
Endosulfan I	0.0001	ND	ND	ND	ND	ND	ND
Endosulfan II	0.0002	ND	ND	ND	ND	ND	ND
Endosulfan sulfate	0.0002	ND	ND	ND	ND	ND	ND
Endrin	0.0002	ND	МD	ND	OND	ND	ND
Endrin Aldehyde	0.0002	ND	ND	ND	ND	ND	ND
Endrin Ketone	0.001	ND	ND	ND	ND	ND	ND
Heptachlor	0.00005	ND	ND	ND	ND	ND	ND
Heptachlor Epoxide	0.00005	ND	ND	ND	ND	ND	ND
Methoxychlor	0.0005	ND	ND	ND	ND	ND	ND
Toxaphene	0.001	ND	ND	ND	ND.	ND	ND ND
PCBs					110	110	NO
Aroclar-1016	0.001	ND	ND	ND	ND	ND	ND
Aroclor-1221	0.001	ND	ND	ND	ND	ND	ND
Aroclor-1232	0.001	ND	ND	ND:	ND	ND:	ND.
Aroclor-1242	0.001	ND	ND	ND	ND	ND	ND
Arocler-1248	0.001	ND	ND	ND	ND .		ND:
Aroclor-1254	0.001	ND	ND	ND	ND	ND	ND
Aroclor-1260	0.001	ND	ND	ND	ND	ND	ND

Surrogates (% recovery) Limits: 50 - 150

	Sample ID:	Blank	JA-1	JA-2	JA-3	JA-4	CF-1
			1.	· .			
Tetrachloro-m-xylene		126	117	93	102	105	121

QC Sample Report - EPA 8080 Pesticides

Matrix: Soil

Batch #: PESTW0251

Batch Accuracy Results

Sample ID: Laboratory Cont	rol Sample)		
Analyte	Spike Concentration µg/L	% Recovery LCS	Acceptance Limits % Recovery	Pass/Fail
Lindane	0.1	87	32 - 127	Pass
Heptachlor	0.1	108	34 - 111	Pass
Aldrin	.0.1	103	42 - 122	Pass
Dieldrin	0.4	76	36 - 146	Pass
Endrin	0.4	86	30 - 147	Pass
TOD	0.4	73	25 - 160	Pass
Aroclor 1242	2.0	93	75 - 127	Pass

Analytical Notes:

Batch Precision Results

MS/MSD Sample ID: Laboratory Control Sample

Analyte	Spike Sample Recovery mg/L	Spike Duplicate Recovery mg/L	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass/Fail
Lindane	0.087	0.085	2%	25%	Pass
Heptachlor	0.108	0.107	1%	25%	Pass
Aldrin	0.103	0.102	1%	25%	Pass
Dieldrin	0.300	0.290	3%	25%	Pass
Endrin	0.340	0.330	3%	25%	Pass
ТОО	0.290	0.290	0%	25%	Pass

MS: Matrix Spike Sample
MSD: Matrix Spike Duplicate

Analytical Notes:



Client:

PSI

Project:

CT J&A Truck/Container Freight

Job No.: Matrix: 16393

Analyst:

Water JMR Date Sampled:

05/02/00

Date Received:

05/03/00

Date Analyzed:

05/04-12/00

Batch Number:

M4S8260W2096

	Sample ID:	Blank	JA-1	JA-2	JA-3	JA-4	CF-2
Compounds	DL	μg/L	μg/L	μg/L	μg/L	μ g/ L	μg/L
Acetone	50	ND _	ND	ND	ND	ND	ND
tert-Amyl Methyl Ether (TA		ND	ND	ND	ND	ND	ND .
Benzene	0.5	ND	ND	ND	ND	0.7	330
Bromobenzene	1.0	ND	ND	ND	ND	ND	ND
Bromochloromethane	1.0	ND	ND	ND	ND	ND	ND
Bromodichloromethane	0.5	ND	ND	ND	ND	ND	ND
Bromoform	0.5	ND	ND	ND	ND	ND	ND
Bromomethane	0.5	ND	ND	ND	ND	ND	ND
tert-Butanol (TBA)	50	ND	ND	ND	ND	ND	ND
2-Butanone (MEK)	10	ND :	ND	ND	ND	ND	ND
n-Butylbenzene	0.5	ND	ND	ND	ND	ND	ND
sec-Butylbenzene	0,5	ND	ND.	ND	ND	ND	ND
tert-Butylbenzene	0.5	ND	ND	ND	ND	ND	ND
Carbon disulfide	. 10	ND	ND	ND	ND	ND	68
Carbon tetrachloride	0.5	ND	ND	ND	ND	ND	ND
Chlorobenzene	0.5	ND	DA	ND	ND	ND	ND
Chloroethane	0.5	ND	ND	ND	ND	ND	ND
Chloroform	0.5	ND	ND	ND	ND	1.7	ND
Chloromethane	0.5	ND	ND	ND	ND	ND	ND
2-Chlorotoluene	0.5	ND	ND	ND	ND	ND	ND
4-Chlorotoluene	0.5	ND	ND	ND	ND	ND	ND
Dibromochloromethane	0.5	ND	ND	ND	ND	ND	ND
1,2-Dibromoethane	0.5	ND	ND	ND	ND	ND	ND
1,2-Dibromo-3-chloropropa	ne 10	ND	ND	ND	ND	ND	ND
Dibromomethane	0.5	ND	ND	ND	ND	ND	ND
1,2-Dichlorobenzene	0.5	ND	ND	ND	ND	ND	ND
1,3-Dichlorobenzene	0.5	ND	ND	ND	ND	ND	ND
1,4-Dichlorobenzene	0.5	ND	ND	ND	ND	ND	ND
Dichlorodifluoromethane	0.5	ND	ND	ND	ND	ND	ND
1,1-Dichloroethane	0.5	ND	ND	ND	ND	8.2	ND
1,2-Dichloroethane	0.5	ND	ND	8.8	ND	ND	ND
1,1-Dichloroethene	0.5	ND	ND .	ND	ND	6.2	ND
cis-1,2-Dichloroethene	0.5	ND	ND	ND	ND	57	ND
trans-1,2-Dichloroethene	0.5	ND	ND	ND	ND	0.8	NO
1,2-Dichloropropane	0.5	ND	ND	ND	ND	ND	ND
1,3-Dichloropropane	0.5	ND	ND	ND	ND	ND	NO:
2,2-Dichloropropane	0.5	ND	ND	ND	ND	ND	ND
1,1-Dichloropropene	0.5	ND	ND	ND	ND	ND	ND



Client:

PSI

Project:

CT J&A Truck/Container Freight

Job No.: Matrix: Analyst:

Water

16393

JMR

Date Sampled:

Date Received:

Date Analyzed:

05/02/00 05/03/00 05/04-12/00

Batch Number:

M4S8260W2096

	Sample ID:	Blank	JA-1	JA-2	JA-3	JA-4	CF-2
Compounds	DL	μg/L	μg/L	μg/L	μg/L	μg/L	μg/L
cis-1,3-Dichloropropene	0.5	ND	ND	ND	ND	ND	ND
trans-1,3-Dichloropropene	0.5	ND	ND	. ND	ND	ND .	ND
Diisopropyl Ether (DIPE)	5.0	ND	ND	ND	ND	ND	ND
Ethylbenzene	0,5	ND	ND	ND	ND	ND	12
Ethyl tert-Butyl Ether (EtBE)	5.0	ND	ND	ND	ND	ND	ND
Hexachlorobutadiene	0.5	ND	ND	ND	ND	ND	ND
2-Hexanone	10	ND	ND	. ND	ND	ND	ND
lsopropylbenzene	0.5	ND	ND	ND	ND	ND	ND
p-isopropyitoluene	0.5	ND	ND	ND	ND	ND	ND
Methylene chloride	20	ND	ND.	ND	ND	ND C	ND
4-Methyl-2-pentanone	5.0	. ND	ND	ND	ND	ND	ND
Methyl-tert-butyl ether (MtBI	≣) 1.0	ND	ND	. ND	ND	ND	ND
Napthalene	0.5	ND	8.3	8.3	2.4	1.3	2,900
n-Propylbenzene	0.5	ND	ND	ND	ND	ND.	ND .
Styrene	0.5	ND	ND	ND	ND	ND	0.8
1,1,1,2-Tetrachloroethane	0.5	ND	ND	ND	ND	ND	ND
1,1,2,2-Tetrachioroethane	1.0	ND	ND	ND	ND	ND	ND
Tetrachloroethene	0.5	ND	ND	ND	ND	130	ND
Toluene	0.5	ND	ND	ND	ND	ND	10
1,2,3-Trichlorobenzene	0.5	ND	ND	ND	ND	ND	ND
1,2,4-Trichtorobenzene	0.5	ND	ND	ND	ND	ND	ND
1,1,1-Trichloroethane	0.5	ND	ON.	ND	ND	4.2	ND
1,1,2-Trichloroethane	0.5	ND	ND	ND	ND	0.6	ND
Trichloroethene	0.5	ND	ND	0.7	ND	630	ND
1,2,3-Trichloropropane	0.5	ND	ND	ND	ND	ND	ND :
Trichlorofluoromethane	0.5	ND	ND	ND	ND:	ND	ND
Trichlorotrifluoroethane	5.0	ND	ND	ND	ND	7.5	ND
1,2,4-Trimethylbenzene	0.5	ND	ND	ND	ND	ND:	1.4
1,3,5-Trimethylbenzene	0.5	ND	ND	ND	ND	ND	ND
Vinyl chloride	0.5	ND	ND	ND	ND.	1.1	ND
Xylenes (total)	1.5	ND	ND	ND	ND	ND	11

Surrogates (% recovery) Limits: 80 - 130

	Sample ID:	Blank	JA-1	JA-2	JA-3	JA-4	CF-2
Dibromofluoromethane		106	107	108	107	104	112
Toluene-d8		104	106	107	105	105	112
Bromofluorobenzene		102	100	101	101	101	98



Client:

PSI

Project:

CT J&A Truck/Container Freight

Job No.: Matrix:

16393 Water

Analyst:

JMR

Date Sampled:

05/02/00

Date Received:

05/03/00

Batch Number:

Date Analyzed: 05/04-12/00 M4S8260W2096

	Sample ID:	CF-3							· <u> </u>	•	
Compounds	DL	μg/L									
Acetone	50	ND				·	···				
tert-Amyl Methyl Ether (TA	ME) 5.0	ND	ua paggagas na Cunstandas 11	14 (0048-04 11 (0048-04	19094, 19693 2007, 300, 300	155000000000 15500000000000			100 A 500 A	i Antonio de La Taragada	1.02(352) 1.02(352) 1.02(352)
Benzene	0.5	0.9	at numbered services	e in cooleannear ji r	- CARPOOLOGISTON	1,0000000000000000000000000000000000000			3,000 A 300 A	ka ningagaya. L	
Bromobenzene	1,0	ND				-255250.d - 25525550.d	9198y6saa 	10000000000000000000000000000000000000		1. The second	
Bromochloromethane	1.0	ND	· · · · · · · · · · · · · · · · · · ·	1.10.48568543	1. 55 (800)800410	. 1048664A	9888885Ay	1 000 E 6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	-13753
Bromodichloromethane	0.5	ND	Nagaran in					High says y	1.70	1990	
Bromoform	0.5	ND	 N. E. ANDROSES 	- 1. Vece (\$4.5 m)	440.5000399	in March 199	Perment I	- 30000 e	· while	100 (4.34)	10 5.38Ens
Bromomethane	0.5	ND						346 200		1,42	
tert-Butanol (TBA)	50	ND	a maka a Milagaya k	590.150.11	100voende kij	2007-12097 (2	A MALE	4.00m (1964年) 	****	1	115
2-Butanone (MEK)	10	ND						4 57-4		7 to	- 19
n-Butylbenzene	0.5	ND				250	de abee		1.5	٠,	
sec-Butylbenzene	0.5	. ND	31:1411 Culton							1.7	
tert-Butylbenzene	0.5	ND			alak toruttana 1		arent a.	elva esetu. V			PT.
Carbon disulfide	10	ND		17 (1966) 1966 1966 - 1966 1966 - 1966		1 00 Z					
Carbon tetrachioride	0.5	ND				i astali	** * ***		i		. 671 3
Chlorobenzene	0.5	ND					1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1.50	, ,		Ä.,
Chloroethane	0.5	ND			• .						• • •
Chloroform	0.5	NO			P. 1		1.5	1.1	::::		× 13
Chloromethane	0.5	ND					••••			,	٠.
2-Chlorotoluene	0.5	ND	. Second	144	* 1	Malana.			de la		45
4-Chlorotoluene	0.5	ND					•				•
Dibromochloromethane	0.5	ND		i (fila)			100				. 973
1,2-Dibromoethane	0.5	ND						* *****			
1,2-Dibromo-3-chloropropa	ane 10	ND						2 - 2 -	٠.		٠٠.
Dibromomethane	0.5	ND	• • • •								
1,2-Dichlorobenzene	0.5	ND					. '				
1,3-Dichlorobenzene	0.5	ND									
1,4-Dichlorobenzene	0.5	ND									:
Dichlorodifluoromethane	0.5	ND									
1,1-Dichloroethane	0.5	ND	o Hije			-1					÷.
1,2-Dichloroethane	0.5	ND									
1,1-Dichloroethene	0.5	ND	12. 6	P				-			
cis-1,2-Dichloroethene	0.5	ND									
trans-1,2-Dichloroethene	0.5	ND		•							
1,2-Dichloropropane	0.5	ND			,						
1,3-Dichloropropane	0.5	ND			-						
2,2-Dichloropropane	0.5	ND									
1,1-Dichloropropene	0.5	ND:									



Client:

PSI

Project:

CT J&A Truck/Container Freight

Job No.:

16393

Matrix: Analyst: Water **JMR**

Date Sampled:

05/02/00

Date Received:

05/03/00

Date Analyzed:

05/04-12/00

Batch Number: M4S8260W2096

	Sample ID:	CF-3			1.			• •	-			
Compounds	DL	μg/L	٠,	<u> </u>							.	·
cis-1,3-Dichloropropene	0.5	. ND					,		-			
trans-1,3-Dichloropropeле	0:5	ND				. 100 W. 1	100 100 100 100 100 100 100 100 100 100		y 2500			
Diisopropyl Ether (DIPE)	5.0	ND	3 8840 68600	69 TRUM 1.7 V	TOTAL TERM	Karabaya 11		103000000	FOR PARTY			1 1 14
Ethylbenzene	0.5	ND								er kojej (26 e33
Ethyl tert-Butyl Ether (EtBE)	5.0	ND	Siekonej innaasti.	rr Bugara (Burr	, in the second proper		- 4 35467900	in the paragraphic project	A 104022113 -	Missa Chicle	sinda Jarki Ta	atriks())
Hexachlorobutadiene	0.5	ND						1000000	20000000			3 14 Y.S
2-Hexanone	10	ND	************		190000000000000000000000000000000000000	, kilba desara	. 4000,600.50	r Gert Gestebbli	0.0000000	eran ana	0000 0000	Strint
Isopropylbenzene	0.5	ND	violony y Karonini		The second	12 PM 1 - 3 2 2 2 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3					n jojej	1 1 1 1 1
p-Isopropyltoluene	0.5	ND	00000 440,50	The Plane State	a 10 shear	11.78227.	1 616 20 340	r mansemen				
Methylene chloride	20	ND			SP N		- 24 (M)		ar Nami			i (;
4-Methyl-2-pentanone	5.0	ND		- Western	, 5 S S			a in established	10485	3		• •
Methyl-tert-butyl ether (MtBE	E) 1.0	ND	Service (Service)				14.99			72.34.		
Napthalene	0.5	1.7	******			10.270.00	17. ***	14 (11 A) 44 (8)	1 • 11.52575.5	nas valasys	F 125 F 12 G	
n-Propylbenzene	0.5	ND			1. 1650,255 1. 1650,255	. (M308000) . (M308000)						
Styrene	0.5	ND	** ********		r was as the second	V 104 (300 B)	i dadam	nama a see Sa	0.0000000000000000000000000000000000000	gar regerint		8 1 Q4
1,1,1,2-Tetrachloroethane	0.5	ND				30 m	2.60					
1,1,2,2-Tetrachloroethane	1.0	ND						1 35 ST 14 DE	e dia sindiri	9 ** * - ** <u>*</u> -		
Tetrachloroethene	0.5	ND	2.28.4	1. July 1. Jul			JA 3	fey for	1 13.50			, i
Toluene	0.5	ND	-						46	441 A		. :
1,2,3-Trichlorobenzene	0.5	ND	edugat in Garage	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			: 5	27.1	14, 84			
1,2,4-Trichlorobenzene	0.5	ND			•							
1,1,1-Trichloroethane	0.5	ND		14.5	- 1 - 1		1	1.				
1,1,2-Trichloroethane	0.5	ND	,						47			
Trichloroethene	0.5	ND					64		1,25 - 1			
1,2,3-Trichloropropane	0.5	ND										
Trichlorofluoromethane	0.5	ND		- 1500	÷			1.50	14.7			,
Trichlorotrifluoroethane	5.0	ND										
1,2,4-Trimethylbenzene	0.5	ND		10.00				1.1				
1,3,5-Trimethylbenzene	0.5	ND								•		
Vinyl chloride	0.5	ND							*			
Xylenes (total)	1.5	ND							5.1			

Surrogates (% recovery) Limits: 80 - 130

241.094.00 (NICCOTC	Ty Entites, ou	- 130			
	Sample ID:	CF-3		·	
Dibromofluoromethane		107			
Toluene-d8		109	•		
Bromofluorobenzene		98			



Client:

PSI

Project:

CT J&A Truck/Container Freight

Job No.: Matrix:

16393 Water

Analyst:

JMR

Date Sampled:

05/02/00

Date Received:

05/03/00

Date Analyzed:

05/04-12/00

Batch Number: M4S8260W2096

	Sample ID:	CF-10							-	
Compounds	DL	μg/L	- <u> </u>							
Acetone	1250	ND	4.							4
tert-Amyl Methyl Ether (TAM	IE) 125	ND			y 154000.		**************************************			
Benzene	13	270		n - 1 100000000	e. Government	e in a green of the second	ing housings.	a philosophic and	Con Standard Telengted Co.	in produced by the last
Bromobenzene	25	ND					y) contra	
Bromochloromethane	25	ND				e inches	in internation		1 24 1 124 11V	1986511444
Bromodichloromethane	13	ND			7100					
Bromoform	13	ND		., ., ., ., .,						
Bromomethane	13	ND					en gerege Gwys Coloder			
tert-Butanol (TBA)	1250	ND								
2-Butanone (MEK)	250	ND								
n-Butylbenzene	13	ND								
sec-Butylbenzene	. 13	ND					1777 (M. G.) 1888 (M.)			
tert-Butylbenzene	13	ND		•						
Carbon disulfide	250	ND								
Carbon tetrachloride	13	ND								
Chlorobenzene	13	ND								
Chloroethane	13	ND								
Chloroform	13	ND								
Chloromethane	13	ND								
2-Chlorotoluene	13	ND						1.44		
4-Chlorotoluene	13	ND								
Dibromochloromethane	13	ND				1.30	1.4			tal .
1,2-Dibromoethane	13	ND								
1,2-Dibromo-3-chloropropa	and the second section of the second	ND			1 . Ži		# # 1	18.5		
Dibromomethane	13	ND								
1,2-Dichlorobenzene	13	ND				3.5		3. 3		
1,3-Dichlorobenzene	13	ND								10
1,4-Dichlorobenzene	13	ND								
Dichlorodifluoromethane	13	ND								
1,1-Dichloroethane	13	ND			15			2500	1.5	
1,2-Dichloroethane	13	ND								
1,1-Dichloroethene	13	ND		1.5	:					
cis-1,2-Dichloroethene	13	ND	_							
trans-1,2-Dichloroethene	13	ND			-					
1,2-Dichloropropane	. 13	ND								
1,3-Dichloropropane	13	ND	•					•		
2,2-Dichloropropane	13	ND								
1,1-Dichloropropene	13	ND								



Client:

PSI

Project:

CT J&A Truck/Container Freight

Job No.: Matrix

16393 Water

Analyst:

JMR

Date Sampled:

Date Received: Date Analyzed:

05/02/00 05/03/00 05/04-12/00

Batch Number:

M4S8260W2096

Sa	mple ID:	CF-10	
Compounds	DL	μg/L	
cis-1,3-Dichloropropene	13	ND	
trans-1,3-Dichloropropene	13	ND	3 22 0 0 5 6 2
Diisopropyl Ether (DIPE)	125	ND	å tro
Ethylbenzene	13	13	
Ethyl tert-Butyl Ether (EtBE)	125	ND	472 ().d }
Hexachlorobutadiene	13	ND	
2-Hexanone	250	ND	1 - 1.12 - 1 -
Isopropyibenzene	13	ND	
p-Isopropyltoluene	13	ND	
Methylene chloride	500		
4-Methyl-2-pentanone	125	ND	
Methyl-tert-butyl ether (MtBE)	25	ND	
Napthalene	13	1,600	
n-Propylbenzene	13		
Styrene	13	ND	
1,1,1,2-Tetrachloroethane	13	[1] SNOVE 경험 경험 : [2] 그 사람들은 비리는 비전 : [20] - [2]	
1,1,2,2-Tetrachloroethane	25	ND	·
Tetrachloroethene	13	GONDA SANGER SECTION OF THE STATE OF THE SANGER SECTION OF THE SAN	yka.
Toluene	13	14	
1,2,3-Trichlorobenzene	13	하는 ND를 보고싶다고 불통이 보고 있는 사람들은 말로 보고 있다.	
1,2,4-Trichlorobenzene	13	ND	
1,1,1-Trichloroethane	13		
1,1,2-Trichloroethane	13	ND	
Trichloroethene	13	(5) NO (1) (14) (1) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4	
1,2,3-Trichloropropane	13	ND	
Trichlorofluoromethane	13	kali nd aga Tajika (jigin da sa alifuda kali da sa	
Trichlorotrifluoroethane	125	ND	
1,2,4-Trimethylbenzene	13		
1,3,5-Trimethylbenzene	13	ND	
Vinyl chloride	13		
Xylenes (total)	38	ND	

Surrogates 1% recove	ry) Limits: 60	- 130							
	Sample ID:	CF-10	 						
Dibromofluoromethane		111		-	-	 *4	1 2 -		
Toluene-d8		109							
Bromoffuorobenzene		101	**					14	



Client

PSI

Project:

CT J&A Truck/Container Freight

Job No.: Matrix: 16393 Water

Analyst:

1,1-Dichloropropene

JMR

Date Sampled:

05/02/00

Date Received:

05/03/00

Date Analyzed: Batch Number:

05/04-12/00 M4S8260W2096

· · ·	Sample ID:	CF-1									
Compounds	DL	μ g/ L									
Acetone	5000	ND									
tert-Amyl Methyl Ether (TAM	IE) 500	ND	1923923 33.860 CA	0.00		- Ann Mil Fulf ber			11911		
Benzene	50	34,000	1		200.0000	20.43.00		112124	170 7	Alexandre .	
Bromobenzene	100	ND	3 174 000 700 1 2 1 3 2 4 5 5 7 1	- 000000 to			11.53 (\$5.53)			- merica. 1.879	
Bromochloromethane	100	ND		1000				14.000.00	2.440 (095)	W0 1 1 4 1	
Bromodichloromethane	50	ND		130% (1955) - 1866 (1957) - 1866 (1958)							
Bromoform	50	ND				. ****	********	1 10000000	Terris India Agrico		
Bromomethane	50	ND		- NYAC.	SEP 14.			15 AT	11. No. 11.	1.471	1.1
tert-Butanol (TBA)	5000	ND				** * :					
2-Butanone (MEK)	1000	ND			2.5		100	6 B. 10		:57.2	
n-Butylbenzene	50	ND	•					* * *			
sec-Butylbenzene	50	ND					in ng ig	3-15/35 7753		radio.	18.20
tert-Butylbenzene	50	ND	er a araner		entrare en el	. ar .a. f.a	uhana is mia	7 77 7 FE 14	e lunce en kirt		1 3 7 4 5 1
Carbon disulfide	1000	ND	7 % S.		rum ya mwa Majadarka	ry i reseas. De AGRECE			r kreiter.		
Carbon tetrachloride	50	ND	11150-00	rath was the				i ya mana		. 9	
Chlorobenzene	50	ND			7-34			200-0		- 12 5 1 - 12 5 1	1000
Chloroethane	50	ND									**
Chloroform	50	ND	i gede Viga			19 19			. 1.91	1979	
Chloromethane	50	ND		** ** .							
2-Chiorotoluene	50	ND	Elega.	34.5		2	2				
4-Chlorotoluene	50	ND	****		****			•			
Dibromochloromethane	50	ND		77.		•					
1,2-Dibromoethane	50	ND			.*						
1,2-Dibromo-3-chloropropar	ne 1000	ND	2.42	**.14			7.3				
Dibromomethane	50	ND	***	1, 11		••	•			•	
1,2-Dichlorobenzene	50	ND					1				
1,3-Dichlorobenzene	50	ND									
1,4-Dichlorobenzene	50	ND							1.		
Dichlorodifluoromethane	50	ND		· ·							
1,1-Dichloroethane	50	ND							-		
1,2-Dichloroethane	50	ND	•	* .							
1.1-Dichloroethene	50	ND	1,2 13	32.					-		
cis-1,2-Dichloroethene	50	ND			* .						
trans-1,2-Dichloroethene	50	ND	: .		5			. :			
1,2-Dichloropropane	50	ND									
1,3-Dichloropropane	50	ND					-	•			٠
2,2-Dichloropropane	50	ND									

ND



Client:

PSI

Project:

CT J&A Truck/Container Freight

Job No.:

16393

JMR

Matrix:

Water

Analyst:

Date Analyzed:

Date Sampled: 05/02/00 Date Received:

05/03/00 05/04-12/00

Batch Number: M4S8260W2096

	Sample ID:	CF-1	
Compounds	DŁ	μg/L	
cis-1,3-Dichloropropene	50	ND	
trans-1,3-Dichloropropene	50	NO	
Diisopropyl Ether (DIPE)	500	- ND	
Ethylbenzene	50	340	
Ethyl tert-Butyl Ether (EtBE)	500	ND	ses present de l'acceptant de la company de la company de la company de 2000, especialement de la company de 2 Transferie
Hexachlorobutadiene	50	ND	
2-Hexanone	1000	ND	
Isopropylbenzene	50	ND	
p-Isopropyitoluene	50	ND	
Methylene chloride	2000	ND.	
4-Methyl-2-pentanone	500	ND	
Methyl-tert-butyl ether (MtBl	≣) 100	. ND	
Napthalene	50	19,000	
n-Propylbenzene	50	ND	
Styrene	50	590	Markara di Salamatan da di Salamatan da Maria di Salamatan di Salamatan da Salamatan da Salamatan da Maria da M Markara di Salamatan da di Salamatan da Maria di Salamatan di Salamatan da Salamatan da Salamatan da Maria da M
1,1,1,2-Tetrachloroethane	50	ND	1985년 - 1985년 시간 : 1985년 - 1985년 - 1985년 - 1985년 - 1985년 - 1985년 - 1985년 - 1985년 - 1985년 - 1985년 - 1985년 - 198 1985년 - 1985년
1,1,2,2-Tetrachloroethane	100	ND	
Tetrachloroethene	50	ND	
Toluene	50	1,600	
1,2,3-Trichlorobenzene	50	ND	
1,2,4-Trichlorobenzene	50	ND	
1, 1, 1-Trichloroethane	50	ND	STANCE OF THE SECOND SECTION AND THE SECOND
1,1,2-Trichloroethane	50	ND	
Trichloroethene	50	190	
1,2,3-Trichloropropane	50	ND	
Trichlorofluoromethane	50	ND	
Trichlorotrifluoroethane	500	ND	
1,2,4-Trimethylbenzene	50	ND	
1,3,5-Trimethylbenzene	50	ND	
Vinyl chloride	50	ND	緊急하게 되어 되는 사람이 없는 것이 하는 것이다.
Xylenes (total)	150	ND	

Surrogates (% recovery) Limits: 80 - 130

	7,	
	Sample ID: CF-1	
Dibromofluoromethane	1105 - 110	
Toluene-d8	115	
Bromofluorobenzene	98	



QC Sample Report - EPA Method 8260

Matrix: Water

.Batch #: MS48260W2096

Batch Accuracy Results

Sample ID: Laboratory Control Sample

Analyte	Spike Concentration μg/L	% Recovery LCS	Acceptance Limits % Recovery	Pass/Fail
1,1-Dichloroethene	20	113	59 - 172	Pass
Benzene	20	122	66 - 142	Pass
Trichloroethene	20	120	71 - 137	Pass
Toluene	20	113	59 - 139	Pass
Chlorobenzene	20	96	60 - 133	Pass

Analytical Notes:

Batch Precision Results

MS/MSD Sample ID: Laboratory Control Sample

Analyte	Spike Sample Recovery µg/L	Spike Duplicate Recovery µg/L	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass/Fail
1,1-Dichloroethene	22.7	24.5	8%	22%	Pass
Benzene	24.4	26.4	8%	21%	Pass
Trichloroethene	23.9	25.0	4%	24%	Pass
Toluene	22.8	24.6	8%	21%	Pass
Chlorobenzene	19.2	21.2	10%	21%	Pass

MS: Matrix Spike Sample
MSD: Matrix Spike Duplicate

Analytical Notes:



Client: PSI -Date Sampled: 05/02/00 CT J&A Truck/Container Freight Project: Date Received: 05/03/00 Job No.: 16393 Date Extracted: 05/05/00 Matrix. Water Dates Analyzed: 05/06-08/00 Analyst: TPW Batch Number: 8270W0622

	Sample ID:	Blank	JA-1	JA-2	JA-3	JA-4	
Compound	DL	mg/L	mg/L	mg/L	mg/L	mg/L	
Acenaphthene	0.0011	ND	ND	ND	: ND	ND	
Acenaphtnylene	0.0011	ND	ND	ND	ND	ND	
Anthracene	0.0011	ND	ND	ND	ND	ND	· · · · · · · · · · · · · · · · · · ·
Benzo[a]anthracene	0,0022	ND	ND:	ND	ND	ND	
Benzo(a)pyrene	0.0022	ND	ND T	ND	ND	ND	v
Benzo[b]fluoranthene	0.0011	ND	ND :	ND:	ND	ND	t, Krain, i
Benzo(g,h,i)perylene	0.0033	ND	ND	ND	ND	ND	
Benzo[k]fluoranthene	0.0011	ND	. ■ DD	ND/	ND	ND	
Benzyl alcohol	0.0044	ND	ND	ND	ND	ND	
bis(2-Chloroethoxy)metha	n e 0.0022	ND -	ND	ND:	ND	ND	
bis(2-Chloroethyl)ether	0.0022	ND	ND	ND	ND	ND	i e di tore 'rei-
bis(2-Chloroisopropyl)ethe	er 0.0033	ND	ND	ND	NO	ND	
bis(2-Ethylhexyl)phthalate		ND	ND	ND	ND	ND	i d'armendes,
4-Bromophenylphenylethe	r 0.0011	ND	ND	ND	ND	ND	e et lagget and Sie Frankling
Butylbenzylphthalate	0.0011	ND	ND	ND	ND	ND	
4-Chloro-3-methylphenol	0.0055	ND	ND	ND	ND	ND	
4-Chloroaniline	0.0055	ND	ND	ND	ND	ND	
2-Chloronaphthalene	0.0011	ND	ND	ND	ND	ND	
2-Chlorophenol	0.0044	ND	ND	ND	ND	ND	
4-Chlorophenylphenylethe	r 0.0011	ND	ND	ND	ND	ND	
Chrysene	0.0011	ND	ND	ND	ND	ND	* *
Di-n-butylphthalate	0.011	ND	ND	ND	ND	ND	.11 . 4.
Di-n-octylphthalate	0.0011	ND	ND	ND	ND	ND	
Dibenzo[a,h]anthracene	0.0033	ND	ND	ND	ND	ND	
Dibenzofuran	0.0011	ND	ND	ND	ND	ND	
1,2-Dichlorobenzene	0.0011	ND	ND	ND	ND	ND	
1,3-Dichlorobenzene	0.0011	ND	ND	ND	ND	ND	
1,4-Dichlorobenzene	0:0011	ND	ND	ND	ND	ND	
3,3-Dichlorobenzidine	0.0044	ND	ND	ND	ND	ND	
2,4-Dichlorophenol	0.0055	ND	ND	ND	ND	ND	
Diethylphthalate	0.011	ND	ND	ND	ND	ND	:
2,4-Dimethylphenol	0.0033	ND	ND	ND:	ND	ND	,
Dimethylphthalate	0.0011	ND	ND	ND	ND	ND	
4,6-Dinitro-2-methylpheno	l 0.011	ND	ND	ND	ND	ND	
2,4-Dinitrophenol	0.055	ND	ND	ND	ND	ND	
2,4-Dinitrotoluene	0.0011	.ND	ND	ND	ND	ND	



Client:

PSI

Project: CT J&A Truck/Container Freight Job No.:

16393

Matrix: Water Analyst: TPW

Date Sampled:

05/02/00

Date Received: 05/03/00 Date Extracted: 05/05/00

Dates Analyzed: Batch Number:

05/06-08/00 8270W0622

	Sample ID:	Blank	JA-1	JA-2	JA-3	JA-4	
Compound	DL	mg/L	mg/L	mg/L	mg/L	mg/L	
2,6-Dinitrotoluene	0.0033	ND	ND	ND	ND	ND	
Fluoranthene	0.0011	ND	ND	ND	ND	ND	<u> </u>
Fluorene	0.0011	ND	ND	ND	ND	ND	
Hexachlorobenzene	0.0011	ND	ND	ND	ND	ND	
Hexachlorobutadiene	0.0011	ND	ND	ND	ND	ND	well is the tribity in
Hexachlorocyclopentadier	ne 0,055	ND	ND	ND	ND	ND	
Hexachloroethane	0.0011	ND	, ND	ND	ND	ND	ing a line of the sign of the
Indeno[1,2,3-cd]pyrene	0.0044	ND	ND	ND	ND	ND	
Isophorone	0.0011	ND	ND	ND	ND	ND	7 34 W.
2-Methylnaphthalene	0.0011	ND	ND	ND	ND	ND	
2-Methylphenoi	0.0055	ND	ND	ND	ND	ND	. 30 . 3 . 34 . 3 . 7
4-Methylphenol	0.0055	ND	ND	ND	ND	ND .	
N-Nitroso-di-n-propylamir	ne 0.0011	ND	ND	ND	ND	ND	
N-Nitrosodiphenylamine	0.0011	ND	ND	ND:	ND	ND	1,74
Naphthalene	0.0011	ND	0.002	ND	ND	ND	,
2-Nitroaniline	0.0033	ND	ND	ND	ND	ND	
3-Nitroaniline	0.0033	ND	ND	ND	ND	ND	**
4-Nitroaniline	0,011	ND	ND	ND	ND	ND	
Nitrobenzene	0.0033	ND	ND	ND	ND	ND	
2-Nitrophenol	0.0044	ND	ND	ND	ON	ND	
4-Nitrophenol	0.011	ND	ND	ND	ND	ND	
Pentachlorophenol:	0.055	ND	ND	ND	ND	ND	
Phenanthrene	0.0022	ND	ND	ND	ND	ND	
Phenoi	0.0044	ND	ND	ND	ND	ND	
Pyrene	0.0011	ND	ND	ND	ND	ND	
1,2,4-Trichlorobenzene	0:0011	ND	ND	ND	ND	ND	
2,4,5-Trichlorophenol	0.0066	ND	ND	ND	ND	ND	
2,4,6-Trichlorophenol	0.011	ND	ND	ND	ND	ND	

Surrogates (Limits) in Percent Recovery

Sample ID:	Blank	JA-1	JA-2	JA-3	JA-4
2-Fluorophenol (21 - 100%)	104	52	59	59	52
Phenol-D5 (10 - 94%)	82	34	38	39	34
Nitrobenzene-D5 (35 - 114%)	108	62	60	60	59
2-Fluorobiphenyl (43 - 116%)	90	72	75	71	69
2,4,6-Tribromophenol (10 - 123%)	97	82	103	96	89
p-Terphenyl-D14 (33 - 141%)	108	85	90	88	85



Client: PSI Date Sampled: 05/02/00 Project: CT J&A Truck/Container Freight Date Received: 05/03/00 Job No.: 16393 Date Extracted: 05/05/00 Matrix: Water Dates Analyzed: 05/06-08/00 TPW Analyst: Batch Number: -8270W0622

	mple ID:	Blank	CF-1	CF-2	CF-3	CF-10
Compound	DL	mg/L	mg/L	mg/L	mg/L	mg/L
Acenaphthene .	0.001	ND	800.0	0.004	ND	0.004
Acenaphthylene	0.001	ND	ND	0.069	ND	0.031
Anthracene	0.001	ND	0.006	0.007	0.001	0.006
Benzo[a]anthracene	0:002	. ND	ND	ND	0.004	ND -
Benzo(a)pyrene	0.002	ND	ND	0.003	800.0	0.002
Benzo(b)fluoranthene	0.001	ND	ND	0.003	0.010	0.003
Benzo(g,h,i]perylene	0.003	ND	ND	ND	0.009	ND
Benzo[k]fluoranthene	0.001	ND	ND	0.003	0.010	0.003
Benzyl alcohol	0.004	ND	ND	ND	ND	ND
bis(2-Chloroethoxy)methane	0.002	ND	ND	ND	ND	ND
bis(2-Chloroethyl)ether	0.002	ND	ND	ND	ND	ND
bis(2-Chloroisopropyi)ether	0.003	ND	ND	ND	ND	ND
bis(2-Ethylhexyl)phthalate	0.01	ND	ND	ND	ND	ND
4-Bromophenylphenylether	0.001	ND	ND	ND	ND	ND
Butylbenzylphthalate	0.001	ND	ND	ND	ND	ND
4-Chloro-3-methylphenol	0.005	ND	ND	NO	ND	ND
4-Chloroaniline	0.005	ND	ND	ND	ND	ND
2-Chloronaphthalene	0.001	ND	ND	ND	ND	ND
2-Chlorophenol	0.004	ND	ND	ND	ND	ND
4-Chlorophenylphenylether	0,001	ND	ND	ND	ND	ND
Chrysene	0.001	ND	ND	0.003	0.006	0.002
Di-n-butylphthalate	0.01	ND	ND	ND	ND .	ND
Di-n-octylphthalate	0.001	ND	ND	ND	ND	ND
Dibenzo(a,h]anthracene	0.003	ND	ND	ND	ND	ND
Dibenzofuran	0.001	ND	0.003	0.003	ND	0.003
1,2-Dichlorobenzene	0.001	ND	ND	ND	ND:	ND.
1,3-Dichlorobenzene	0.001	ND	ND	ND	ND	ND
1,4-Dichlorobenzene	0.001	ND	ND	ND	ND	ND
3,3-Dichlorobenzidine	0.004	ND	ND	ND	ND	ND
2,4-Dichlorophenol	0.005	ND	ND	ND	ND	ND
Diethylphthalate	0.01	ND	ND	ND	ND	ND
2,4-Dimethylphenol	0.003	ND	ND	ND	ND	ND
Dimethylphthalate	0.001	ND	ND	ND	ND	ND
4,6-Dinitro-2-methylphenol	0.01	ND	ND	ND	ND	ND
2,4-Dinitrophenol	0.05	ND	ND	ND	ND	ND
2,4-Dinitrotoluene	0.001	ND	ND	ND	ND	ND



Client: PSI Date Sampled: 05/02/00 Project: CT J&A Truck/Container Freight 05/03/00 Date Received: Job No.; 16393 Date Extracted: 05/05/00 Matrix: Water Dates Analyzed: 05/06-08/00 Analyst: TPW Batch Number: 8270W0622

	Sample ID:	Blank	CF-1	CF-2	CF-3	CF-10	
Compound	DL	mg/L	mg/L	mg/L	mg/L	mg/L	
2,6-Dinitrotoluene	0.003	ND	ND	ND	ND	ND	
Fluoranthene	0.001	ND	0.007	0.014	0.012	0.011	
Fluorene	0.001	ND	0.013	0.016	ND	0.014	* * **** **** **** *
Hexachlorobenzene	0.001	ND	. ND	ND.	ND	ND	
Hexachlorobutadiene	0.001	ND	ND	ND	ND	ND	588 - 1 K - K - K - SK - K - SK - K - SK - K -
Hexachlorocyclopentadier	ne 0:05	ND	GN	ND	ND	ND	
Hexachloroethane	0.001	ND	ND	ND	ND	ND	ig in the distance of
Indeno[1,2,3-cd]pyrens	0.004	ND	ND	ND	0.006	ND	
isophorone	0.001	ND	ND	ND	ND	ND	
2-Methylnaphthalene	0,001	ND	0.067	0.022	ND	800.0	
2-Methylphenol	0.005	ND	ND	ND	ND	ND	A A AND GO THE
4-Methyiphenol	0.005	ND	ND	0.17	ND	0.041	
N-Nitroso-di-n-propylamin	e 0.001	ND	ND	ND	ND	ND	ar in an and a said and a said
N-Nitrosodiphenylamine	0.001	ND	ND	ND	ND	ND	
Naphthalene	0.001	ND	5.5	1.2	0.007	0.52	e i neferal grida
2-Nitroaniline	0.003	ND /	ND	ND	ND	ND	
3-Nitroaniline	0.003	ND	ND	ND	ND	ND	
4-Nitroaniline	0.01	ND	ND	ND	ND.	ND	. •
Nitrobenzene	0.003	ND	ND	ND	ND	ND	
2-Nitrophenol	0.004	ND	ND	ND	ND	ND	To produce a
4-Nitrophenol	0.01	ND	ND	ND	ND	ND	
Pentachlorophenol	0.05	ND	ND	ND	ND	ND	100
Phenanthrene	0.002	ND	0.055	0.048	0.004	0.033	
Phenoi	0.004	ND	0.024	0.046	ND	0.011	
Pyrene	0.001	ND	0.011	0.018	0.016	0.013	
1,2,4-Trichlorobenzene	0.001	ND	ND	ND	ND	ND	*
2,4,5-Trichlorophenol	0.006	ND	ND	ND	ND	ND	
2,4,6-Trichlorophenol	0.01	ND:	ND	ND	TI L. NO	ND	

Surrogates (Limits) in Percent Recovery

Sample ID:	Blank	CF-1	CF-2	CF-3	CF-10	
2-Fluorophenol (21 - 100%)	104	30	59	37	49	
Phenol-D5 (10 - 94%)	82	40	40	25	37	
Nitrobenzene-D5 (35 - 114%)	108	38	65	39	51	
2-Fluorobiphenyl (43 - 116%)	90	59	64	62	56	
2,4,6-Tribromophenol (10 - 123%)	97	32	89	40	79	
p-Terphenyl-D14 (33 - 141%)	108	44	83	67	72	



QC Sample Report - EPA 8270

Batch #: 8270W0622

Matrix: Water

Batch Accuracy Results

Sample	ID:	Laborat	ory	Control	Sample

Analyte	Spike Concentration µg/L	% Recovery LCS	Acceptance Limits % Recovery	Pass/Fail
Phenol	80	43	5 - 112	Pass
2-Chlorophenol	80	106	23 - 134	Pass
1,4-Dichlorobenzene	40	94	20 - 124	Pass
N-Nitrosodi-n-propylamine	40	79	0 - 230	Pass
1,2,4-Trichlorobenzene	40	83	44 - 142	Pass
4-Chloro-3-Methylphenol	80	84	22 - 147	Pass
Acenaphthene	40	84	47 - 145	Pass
4-Nitrophenol	80	48	0 - 132	Pass
2,4-Dinitrotoluene	40	88	39 - 139	Pass
Pentachlorophenol	80	132	14 - 176	Pass
Pyrene	40	103	52 - 115	Pass

Analytical Notes:

Batch Precision Results

MS/MSD Sample ID: Laboratory Control Sample

Analyte	Spike Sample Recovery µg/L	Spike Duplicate Recovery µg/L	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass/Fail
Phenol	34.7	31.8	9%	35%	Pass
2-Chlorophenol	85.2	75.5	12%	50%	Pass
1,4-Dichlorobenzene	37.4	34.3	9%	27%	Pass
N-Nitrosodi-n-propylamine	31.8	29.8	6%	38%	Pass
1,2,4-Trichlorobenzene	33.3	35.8	7%	28%	Pass
4-Chloro-3-Methylphenol	66.9	73.0	9%	33%	Pass
Acenaphthene	33.7	33.9	1%	23%	Pass
4-Nitrophenol	29.7	37.8	24%	50%	Pass
2,4-Dinitrotoluene	35.1	37.9	8%	47%	Pass
Pentachiorophenol	105.7	105.4	0%	47%	Pass
Pyrene	41.2	41.1	0%	36%	Pass

Analy	rtical.	Notes:

Page	24	af	24

Centrum Analytical Laboratories, Inc.

Centrum Job # 16368
Page 1 of ____

290 TENNESSEE STREET

REDLANDS, CA 92373 www.contrum-labs.com

(909) 798-9336 • (800) 798-9336

FAX (909) 793-1559 lab@centrum-labs.com **Chain of Custody Record**

***************************************								/		Ple	eas	е С	ircl	e A	naly	yses	Re	que	este	ad		$\overline{}$	
Project No:		تر		Project Na		K CONTAINER FREI	GHT	n Chain					524.2			/ <u>A</u>		å.					Turn-Around Time
Project Mar	ager:			Phone:		Fax:		arbo				3	$\mathbb{C} \mid$			Į į		≴	ج ا				☐ 24 Hr. RUSH* ☐ 48 Hr. RUSH*
FRAN	UK POSS			510	785.	1111 510785-1	192	en, C		اد	ı	7	36	4		(g	`	2	ctivi				Normal TAT
Ctient Name (Report and Billi) :			Address: (Report and Bi	1 'S	TOW WINTON A. FAYNARD CA. 94545	IE.	8015M: Diesel Fuel Screen, Carbon	uly	8021B: BTEX/MIBE Only	413.2	TPHMO-EPA8015M	100 A	GCMS: MtBE Conf. Only	5) 628	8080: Pesticides, PCBs, PestiPCB	$\ $		S, Conductivity	ex Cr			*Requires PRIOR approval, additional charges apply
					,			1	sas o	Ĕ	H.	0		#BE	32700	Stick	╢	劃	, TSS,	J.			Requested due date:
Centrum ID	Sample ID (As it should appear on report)		ate npled	emiT belgmss	Sample matrix	Site location	Containers: # and type	3015M:(D	8015M: C	8021B: E	418.1 (TRPH),	11/12	GCMS: (GCMS: #	GCMS: (8270C,) 625	8080: Pe	ľ	Metals:(PH, 73S,	Flashpoint, Hex			Remarks/Special Instructions
	CF3-015	4-	75-it	0905	SOIL		1 brass tube	X	X		Ť	X	X		X		7)	Z					
2	CF3-1.0	'	<u> </u>	0928			1	X	X	\neg		хİ	X		X		7	ΧÌ					
3	CF3-2.0	-		0936				X	X	十		ΧÏ	X		X		1	X					
4	CF2-0.5			1104	1			X	V	_		ΧÌ	X		X			ΧÌ				\neg	
5	CFZ-1.0		r	1116				X	X	_		ZI	X		X		T)	ΧÌ					
ا ا	CF2-2,0	H		1137				X	\			X	X		X		Í	Ż					
<i>1</i>	CFZ-3.0	H		1156				 	7	1	ľ		지								Ī		
8	CF1-0.5			1330				X	\mathbf{x}^{\dagger}	7		X	X		\overline{X}	X	7	X				Ì	
9	CF1-10	H		357	1			X	`			X	X		X	X		ΧÌ					
	——————————————————————————————————————	\mathbb{I}	,	1424	•		$\overline{}$	X	刘	7	1	又	Ź		Ŋ	X		X			Î		
	CF1-20 shed by: (Sample's Signature) IS MERRETT	1 Y		Date:	Time:	3) Relinquished by:		Date	-	lime:						by Lai		-					Sample Disposal
2) Received				Date:	Time:	4) Received by:		Date	1	lime:						yQ. □Ye		_		tom	Field	'	☐ Client will pick up ☐ Return to client
The deliver	y of samples and the signature	on thi	s chal	in of custo	dy form	5) Relinquished by:		Date		ilme:		All	sam	ple c	onta	iners k	ntaci	er Y	øy.				Lab disposal
	authorization to perform the an and Conditions set forth on the				e under ,	B) Received for Laboratory by:		Date L	17	rime: 11 Z	- 1	Д	Cour	er	Š.	Syled	EX		tand	Cârr	led	ļ	
Laboratory	Notes:					eri Series de la constante de	0			<u>., , , , , , , , , , , , , , , , , , , </u>	<u> </u>	-											Sample Locator No.
	•																		1				E-5



Centrum Analytical Laboratories, Inc.

CERTIFIED HAZARDOUS WASTE TESTING LABORATORY . CHEMICAL AND BIOLOGICAL ANALYSES

Client: P

1320 W. Winton Ave.

Hayward, CA 94545

Date Sampled:

04/25/00

Date Received:

04/27/00

Job Number:

16368

Project: J&A Truck/Container Freight

CASE NARRATIVE

The following information applies to samples which were received on 04/27/00:

The samples were received at the laboratory chilled and sample containers were intact.

Unless otherwise noted below, the Quality Control acceptance criteria were met for all samples for every analysis requested.

8260: Some surrogate recoveries were outside the acceptance limits due to reproducible sample matrix effects.

8270: The samples were run at a dilution due to high levels of hydrocarbons in the sample; consequently, detection limits were raised.

Report/approved by:

Robert R. Clark, Ph.D. Laboratory Director

ELAP # 1184

DL: Detection Limit - The lowest level at which the compound can reliably be detected under normal laboratory conditions.

ND: Not Detected - The compound was analyzed for but was not found to be present at or above the detection limit.

NA: Not Analyzed -- Per client request, this analyte was not on the list of compounds to be analyzed for.



Metals

Client: PSI

Project: J&A Truck/Container Freight

Job No: 16368 Matrix: Soil Analyst: RLB/TLR Date Sampled:

04/25/00

Date Received: Date Digested: 04/27/00 05/01/00

Date Analyzed: Batch Number: 05/02-06/00 6010S1551

Sample ID: Blank CF3-0,5 CF3-1.0 CF3-2.0 CF2-0.5 CF2-1.0 Element Method # DL mg/Kg mg/Kg mg/Kg mg/Kg mg/Kg mg/Kg Antimony 6010B 2.5 ND ND ND ND ND ND Arsenic 6010B 0.50 ND 2.5 6.0 5.1 5.9 5.4 Barium 6010B 0.50 ND 77 18 50 71 99 Beryllium 6010B 0.50 ND ND ND ND ND ND. Cadmium 6010B 0.50 ND ND ND ND ND ND Chromium 6010B 0.50 ND 22 2.9 32 20 29 Cobalt 6010B 0.50 ND 4.1 0.59 6.2 6.2 6.6 Copper 6010B 0.50 ND 14 71 34 41 38 Lead 6010B 0.50 ND 73 22 48 65 64 Mercury 7471 0.10 ND. 0.18 ND ND 0.24 0.26 Molybdenum 6010B 0.50 ND ND ND 0.67 ND 0.71 Nickel: 6010B 1.0 ND 16 7.6 38 19 30 Selenium 6010B 2,5 ND ND ND ND ND ND Silver 6010B 1.0 ND ND ND. ND: ND ND Thallium 6010B 2.5 ND ND ND ND ND ND Vanadium 6010B 0.50 ND 19 25 28 28 31 Zinc 6010B 10 ND 50 30 180 76 87



Metals

Client: PSI .

J&A Truck/Container Freight Project:

Job No: 16368 Matrix: Soil Analyst: RLB/TLR Date Sampled: Date Received: 04/25/00

Date Digested:

04/27/00

Date Analyzed:

05/01/00 05/02-06/00

Batch Number:

6010S1551

		Sample ID:	CF2-2.0	CF1-0.5	CF1-1.0	CF1-2.0	
Element	Method #	DL	mg/Kg	mg/Kg	mg/Kg	mg/Kg	
Antimony .	6010B	2.5	ND	ND	ND :	ND	
Arsenic	6010B	0.50	12	4.7	8.8	5.8	
Barium	6010B	0.50	55	130	120	130	
Beryllium	6010B	0.50	ND:	ND	ND	ND	
Cadmium	6010B	0.50	0.62	ND	ND	0.82	Ministration (Thursday) (Services Services)
Chromium	6010B	0,50	7.1	30	35	27	
Cobalt	6010B	0.50	2.5	7.8	8.8	6.4	ekki (in interest erele elik ingeliet
Copper	6010B	0.50	80	30	51	36	
Lead	6010B	0.50	48	49	49	00 kun 2000 kan 1800 bila. 74	
Mercury	7471	0.10	ND	ND	0.30	0.23	
Molybdenum	6010B	0.50	ND	0.66	1.0	1.4	elenty legis, settyja var si
Nickel	6010B	-1.0	12	33	41	25	
Selenium	60108	2.5	ND	ND	ND	ND	
Silver	6010B	1.0	ND	ND	ND	ND	
Thallium	60108	2.5	ND	ND	ND	ND	Ner Control
Vanadium	60108	0.50	13	32	37	26	gradult in it.
Zinc	60108	10	230	89	87	150	



QC Sample Report - Metals

Matrix: Soil

Batch #: 6010S1551

MS/MSD Sample ID: 16373-1

	Batch i	recision	Results	5:		Batch A	Accuracy	Results:	· ·
Metal	Spike Sample Recovery mg/Kg	Spike Duplicate Recovery mg/Kg	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass / Fail	Spike Concentration mg/Kg	% Recovery LCS	Acceptance Limits Percent Recovery	Pass / Fait
Antimony	53.5	53.0	1%	20%	Pass	- 50	113	75 - 125	Pass
Arsenic	51.8	52.0	0%	20%	Pass	50	107	75 - 125	Pass
Barium	85.9	86.4	1%	20%	Pass	50	105	75 - 125	Pass
8eryllium:	50.7	52.3	3%	20%	Pass	50	107	75 - 125	Pass
Cadmium	48.2	48.6	1%	20%	Pass	50	107	75 - 125	Pass
Chromium	79.1	81.5	3%	20%	Pass	50	108	75 - 125	Pass
Cobalt	53.0	53.9	2%	20%	Pass	50	108	75 - 125	Pass
Copper	57.4	58.2	1%	20%	Pass	50	108	75 - 125	Pass
Lead	50.7	50.6	0%	20%	Pass	50	107	75 - 125	Pass
Mercury	2.74	2:80	2%	20%	Pass	2.5	111	75 - 125	Pass
Molybdenum	52.2	52.2	0%	20%	Pass	50	113	75 - 125	Pass
Nickel	73.7	75.1	2%	20%	Pass	50	107	75 - 125	Pass
Selenium	48.1	48.9	2%	20%	Pass	50	103	75 - 125	Pass
Silver	49.1	50.1	2%	20%	Pass	50	104	75 - 125	Pass
Thallium	48.0	48.8	2%	20%	Pass	50	107	75 - 125	Pass
Vanadium	70.3	71.2	1%	20%	Pass	50	109	75 - 125	Pass
Zinc	69.0	70.1	2%	20%	Pass	50	115	75 - 125	Pass

Analytical N	otes
--------------	------

LCS: Laboratory Control Sample

LCSD: Laboratory Control Sample Duplicate

MS: Matrix Spike

RPD: Relative Percent Difference

MSD: Matrix Spike Duplicate



Modified 8015 - Fuel Screen

Client:

PSI

Project:

J&A Truck/Container Freight

Job No.: Matrix:

16368

Analyst:

Soil JL

Date Sampled:

04/25/00

Date Received:

04/27/00

. Date Extracted:.

05/01/00

Date Analyzed:

05/01-02/00

Batch Number:

8015DS1909

8015DS1910

Fuel Identified:	Diesel	Motor Oil	Detection Limits
Units:	mg/kg	mg/kg	mg/kg
Blank	ND	ND	10
CF3-0.5	22	23	10
CF3-1,0	140	78	10
CF3-2.0	110	58	
CF2-0.5	60	44	20
CF2-1.0	220		्रकामा गाविकामा विकास । १९८५ । 20
CF2-2.0	140	ND ND	100
CF1-0.5	370	630	100
CF1-1.0	70	100	ATTROPORT TRANSPORTS OF THE PARTY OF
CF1-2.0	19	35	20 10
	ni Germania ya wa mata wa sana ƙasar ƙasar ƙasar ƙasar ƙasar ƙasar ƙasar ƙasar ƙasar ƙasar ƙasar ƙasar ƙasar ƙ	ngan kalan 1996 ang makabasan sa	IU

QC Sample Report - EPA 8015M Diesel

Matrix: Soil

Batch #: 8015DS1909

Batch Accuracy Results

Sample ID: Laboratory	Control Sample	÷ ·		
Analyte	Spike Concentration mg/Kg	% Recovery LCS	Acceptance Limits % Recovery	Pass/Fail
Diesel	100	82	70 - 130	Pass

Analytical Notes:	<u>. </u>
	•
	· .

Batch Precision Results

MS/MSD Sample ID:Laboratory Control Sample						
Control Sample	Spike Sample Recovery mg/Kg	Spike Duplicate Recovery mg/Kg	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass/Fail	
Diesel	82	75	9%	29%	Pass	

MS:	Matrix 8	Spike S	iample
MSC): Matrix	Soike	Duplicate

Analytical	Notes	:		
			·	
-				
-				

QC Sample Report - EPA 8015M Diesel

Matrix: Soil

Batch #: 8015DS1910

Batch Accuracy Results

Analyte	Spike Concentration mg/Kg	% Recovery LCS	Acceptance Limits % Recovery	Pass/Fail
Diesel	100	104	70 - 130	Pass

Analytical No	tes:	
	*	

Batch Precision Results

MS/MSD Sample ID:Laboratory Control Sample

Control Sample	Spike Sample Recovery mg/Kg	Spike Duplicate Recovery mg/Kg	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass/Fail
Diesel	104	97	7%	29%	Pass

MS:	Matrix	Spike	Sample	
MSC): Matri	x Spik	e Duplica	ate

Analytical Notes:	
	•



Modified 8015 - Total Volatile Hydrocarbons as Gasoline

Client: PSI
Project: J&A Truck/Container Freight

Job No.: 16368 Matrix: Soil Analyst: CP Date Sampled: 04/25/00

Date Received: 04/27/00

Date Analyzed: 05/01/00

Batch Number: 8015GS2591

		Detection	Petroleum Hydrocarbons as
Sample ID		Limit mg/kg	Gasoline mg/kg
Method Blank		0.50	ND
CF3-0.5	A TO TO THE PROPERTY AND AND AND AND AND AND AND AND AND AND	0.50	ND
CF3-1.0		0.50	ND
CF3-2.0		0.50	ND
CF2-0.5		0.50	ND
CF2-1.0		0.50	ND
CF2-2.0		0.50	0.69
CF1-0.5	en en en en en en en en en en en en en e	0.50	ND
CF1-1.0		0.50	0.77
CF1-2.0	n koloni emmo superem judo	0.50	, ND
s i jaksātija i i i i i	。 我可以指数1、数数数2、	Natalyskia is	
	€ €	1	
·			
	e Carrier e e		A CONTRACTOR OF THE SECOND
		** **	
			



EPA 8080 - Organochlorine Pesticides & PCBs

Client: PSI

Project: J&A Truck/Container Freight

Job No.: 16368 Matrix: Soil Analyst: TPW Date Sampled: 04/25/00
Date Received: 04/27/00
Date Extracted: 05/01/00

Date Analyzed: 05/05/00 Batch Number: PESTS0249

	Sample ID:	Blank	CF1-0.5	CF1-1.0	CF1-2.0	
Pesticides	DL	mg/Kg	mg/Kg	mg/Kg	mg/Kg	
Aldrin	0.001	ND	ND	ND	ND	
Alpha-BHC	0.001	ND	ND	ND	ND	
Beta-BHC	0.001	ND	ND	ND	ND	2000 000 000 000 000 000 000 000 000 00
Delta-BHC	0.001	ND	ND	ND	ND	
Gamma-BHC (Lindane)	0.001	ND	ND	ND	ND	Listania izvirilisti karinga karing ing 1992. Tanggaran
Chlordane	0.010	ND.	ND	ND	ND	
4,4'-DDD	0.002	ND	ND	0.003	ND	3/1931.c/0331363.441.155/146144.146-94144.155
4,4'-DDE	0.002	ND	0.018	0.009	ND	heralisa aki mengin dahi
4,4'-DDT	0.002	ND	ND	ND	ND	
Dieldrin	0.002	- ND∞	ND	0.002	ND	
Endosulfan I	0.001	ND	0.006	ND	ND	
Endosulfan II	0.002	ND	ND.	ND	ND	
Endosulfan sulfate	0.002	ND	ND	ND	ND	
Endrin	0.002	ND	ND	ND	ND	Tang Amerikan at s
Endrin Aldehyde	0.002	ND	ND	ND	ND	
Endrin Ketone	0,010	ND	ND	ND	ND	174 A.A. (175 A.A. 177 A.
Heptachlor	0.001	ND	ND	ND	ND	
Heptachlor Epoxide	0.001	ND	ND	ND	ND	
Methoxychlor	0.010	ND	ND	ND	ND	and product of the second
Toxaphene	0.020	ND	ND	מא	ND	Salar Salar Salar Salar Salar Salar Salar Salar Salar Salar Salar Salar Salar Salar Salar Salar Salar Salar Sa
PCBs		<u> </u>		110		
Aroclor-1016	0.050	ND	ND	ND	ND	e Ada Fala La
Araclor-1221	0.050	ND	ND	ND	ND	
Aroclor-1232	0,050	ND	ND	ND	ND	
Aroclor-1242	0.050	ND	ND	ND	ND	
Aroclor-1248	0,050	ND	ND	ND	ND	
Aroclor-1254	0.050	ND	ND	ND	ND	
Aroclor-1260	0.050	ND	0.082	ND `	ND ND	
and the state of t		g. 13.161-1921, 6.52	U.UOZ.	INU"	NU	

Surrogates (% recovery) Limits: 50 - 150

	Sample ID:	Blank	CF1-0.5	CF1-1.0	CF1-2.0	·
Tetrachioro-m-xylene		117	77	86	100	•



EPA 8080 - Organochlorine Pesticides & PCBs

Client: PSI Date Sampled: 04/25/00 Project: J&A Truck/Container Freight Date Received: 04/27/00 Job No.: 16368 Date Extracted: 05/01/00 Matrix: Soil Date Analyzed: 05/05/00 Analyst: TPW Batch Number: PESTS0249

	Sample ID:	Blank	CF1-0.5	CF1-1.0	CF1-2.0
Pesticides	· DL	mg/Kg	mg/Kg	mg/Kg	mg/Kg
Aldrin	0.001	ND	ND	ND	ND
Alpha-BHC	0,001	ND	ND	ND	ND
Beta-BHC	0.001	ND	ND	ND	ND
Delta-BHC	0.001	ND.	ND	ND	ND
Gamma-BHC (Lindane)	0.001	ND	ND	ND	ND
Chlordane	0.010	ND	ND	ND	ND
4,4'-DDD	0.002	ND	ND	0,003	ND
4,4'-ODE	0.002	ND	0.018	0.009	A PND A PROPERTY OF A SECOND
4,4'-DDT	0.002	ND	ND	_ ND	ND
Dieldrin	0.002	∴ ND	ND	0.002	ND
Endosulfan I	0.001	ND	0.006	ND	ND
Endosulfan II	0.002	ND .	ND	ND	ND
Endosulfan sulfate	0.002	ND	ND	ND	ND
Endrin	0.002	ND	ND -	ND	ND .
Endrin Aldehyde	0.002	ND	ND	ND	ND
Endrin Ketone	0.010	ND	ND	ND	Maria Maria Maria Maria Maria Maria Maria Maria Maria Maria Maria Maria Maria Maria Maria Maria Maria Maria Ma
Heptachlor	0.001	ND	ND	ND	ND
Heptachlor Epoxide	0.001	ND	ND	ND	ND ND
Methoxychlor	0.010	ND	ND	ND	ND
Toxaphene	0.020	ND	ND	ND	ND
PCBs					
Aroclor-1016	0.050	ND	ND	ND	mera ND egree of the second
Aroclor-1221	0.050	ND	ND	ND	ND
Aroclor-1232	0.050	ND	ND	ND	ND:
Aroclor-1242	0.050	DN	ND	ND	ND
Aroclor-1248	0.050	ND	ND	ND	ND
Aroclor-1254	0.050	ND	ND	ND	ND
Aroclor-1260	0.050	ND .	0.082	ND	ND

Surrogates (% recovery) Limits: 50 - 150

	Sample ID:	Blank	CF1-0.5	CF1-1.0	CF1-2.0	
		i di May				
Tetrachloro-m-xylene		117	77	86	100	

QC Sample Report - EPA 8080 Pesticides

Matrix: Soil

Batch #: PESTS0249

Batch Accuracy Results

	Laboratory	

Analyte	Spike Concentration mg/Kg	% Recovery LCS	Acceptance Limits % Recovery	Pass/Fail
Lindane	0.0066	90	32 - 127	Pass
Heptachlor	0.0066	98	34 - 111	Pass
Aldrin	0.0066	109	42 - 122	Pass-
Dieldrin	0.026	88	36 - 146	Pass
Endrin	0.026	102	30 - 147	Pass
TDD	0.026	93	25 - 160	Pass
Aroctor 1242	0.0667	83	75 - 127	Pass

Analytical Notes:

				•
	-			•
			•	
1.				
[*
1				-
1				
1		-		
L				

Batch Precision Results

MS/MSD Sample ID: Laboratory Control Sample

Analyte	Spike Sample Recovery mg/Kg	Spike Duplicate Recovery mg/Kg	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass/Fail
Lindane	0.0030	0.0028	7%	25%	Pass
Heptachlor	0.0033	0.0036	9%	25%	Pass
Aldrin	0.0036	0.0035	3%	25%	Pass
Dieldrin	0.0117	0.0108	8%	25%	Pass
Endrin	0.0135	0.0117	14%	25%	Pass
DDT	0.0124	0.0112	10%	25%	Pass

MS: Matrix Spike Sample MSD: Matrix Spike Duplicate Analytical Notes:



Client:

PSI

Project:

J&A Truck/Container Freight

Job No.: Matrix:

16368 'Soil

Analyst: JMR

Date Sampled:

04/25/00

Date Received:

04/27/00 05/03-12/00

Date Analyzed: Batch Number:

MS48260S2093

	Sample ID:	Blank	CF3-0.5	CF3-1.0	CF3-2.0	CF2-0.5	CF2-1.0
Compounds	DL	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg
Acetone	0.05	ND	ND	ND	ND	ND	ND
tert-Amyl Methyl Ether (TAN	AE 0.005	ND	ND	ŅD	ND	ND	ND
Benzene	0.001	ND	ND	ND	· ND	ND	ND
Bromobenzene	0.005	ND	NĐ	ND .	ND	ND	ND
Bromochloromethane	0.005	ND	ND	ND	ND	ND	ND
Bromodichloromethane	0.001	ND	ND	ND	. NĐ	ND	NĐ
Bromoform	0.005	ND	ND .	ND	ND	ND	ND
Bromomethane	0.01	ND	ND	ND	NO	ND	ND
tert-Butanol (TBA)	0.05	ND	ND	ND	ND	ND	ND
2-Butanone (MEK)	0.01	ND	ND	ND	NO	ND -	ND
n-Butylbenzene	0.002	ND	ND	ND	ND	ND	ND
sec-Butylbenzene	0.002	ND	ND	ND		ND.	ND
tert-Butylbenzene	0.002	ND	ND	ND	ND	ND	ND
Carbon disulfide	0.01	ND	ND	ND	ND	ND	ND
Carbon tetrachloride	0.001	ND	ND	ND	ND	ND	ND
Chlorobenzene	0.001	ND	ND	ND	ND	ND	ND
Chloroethane	0.005	ND	ND	ND	ND	ND	ND
Chloroform	0.002	ND	ND	ND	ND	ND	ND
Chloromethane	0.001	ND	ND	ND	ND	ND	ND
2-Chlorotoluene	0.002	ND	ND	ND	ND	ND	ND
4-Chlorotoluene	0.002	ND	ND	ND	ND	ND	ND
Dibromochloromethane	0.002	ND	ND	ND	ND	ND	ND
1,2-Dibromoethane	0.002	ND	ND	ND	ND	ND	ND
1,2-Dibromo-3-chloropropa	ne 0:01	ND	ND	ND	ND	ND	NĐ
Dibromomethane	0.001	ND	ND	ND	ND	ND	ND
1,2-Dichlorobenzene	0.001	ND	ND	ND	ND	ND	ND
1,3-Dichlorobenzene	0.002	ND	ND	ND	ND	ND	ND
1,4-Dichlorobenzene	0.002	ND	ND	ND	ND	ND	ND
Dichlorodifluoromethane	0.005	ND	ND	ND	ND	ND	ND
1,1-Dichloroethane	0.001	ND	ND	ND	ND	ND	ND
1,2-Dichloroethane	0.001	ND	ND	ND	ND	ND	ND
1,1-Dichloroethene	0.005	ND	ND	ND	ND	ND	ND
cis-1,2-Dichloroethene	0.002	ND	ND	ND	ND	ND	ND
trans-1,2-Dichloroethene	0.002	ND	ND	ND	ND	ND	ND
1,2-Dichloropropane	0.001	ND	ND	ND	ND	ND	ND
1,3-Dichloropropane	0.001	ND:	ND	ND	ND	ND	ND
2,2-Dichloropropane	0.001	ND	ND	ND	ND	ND	ND
1,1-Dichtoropropene	0.001	ND:	ND	ND	ND	ND:	ND



Client:

JMR

Project:

Job No.: 16368 Soil

Matrix: Analyst: J&A Truck/Container Freight

Date Sampled:

Date Received: -

04/27/00

Date Analyzed: Batch Number: 05/03-12/00

04/25/00

MS48260S2093

	Sample ID:	Blank	CF3-0.5	CF3-1.0	CF3-2.0	CF2-0.5	CF2-1.0
Compounds	DL	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg
cis-1,3-Dichloropropene	0.001	. ND	ND	ND	ND	ND	ND
trans-1,3-Dichloropropene	0.001	ND:	ND	ND	ND	ND	ND
Diisopropyl Ether (DIPE)	0.005	ND	ND	ND	ND	ND	ND
Ethylbenzene	0.001	ND	ND	ND	ND	ND	ND
Ethyl tert-Butyl Ether (Et8E	0.005	ND	ND.	ND	ND	ND	ND
Hexachlorobutadiene	0.001	ND	ND	ND	ND	ND	ND
2-Hexanone	0.01	ND	ND	ND	ND	ND	ND
Isopropylbenzene	0.001	ND	ND	ND	ON C	ND	ND
p-Isopropyltoluene	0.002	ND	ND	ND	ND	ND	ND
Methylene chloride	0.02	ND	ND	ND	ND	ND	ND
4-Methyl-2-pentanone	0.01	ND	ND	ND	ND	ND	ND
Methyl tert-Butyl Ether (MtE	3E) 0.005	ND	ND	ND	ND	ND	ND
Napthalene	0.002	ND	0.008	0.009	ND	0.009	0.005
n-Propylbenzene	0.001	ND	מא	ND	ND	ND	ND ND
Styrene	0.001	ND	ND	ND	ND	ND	ND
1,1,1,2-Tetrachloroethane	0.001	ND	ND	ND	ND	ND	ND
1,1,2,2-Tetrachloroethane	0.002	ND	ND	ND	ND	ND	ND
Tetrachloroethene	0.001	ND	ND	ND	ND	ND	ND .
Toluene	0.001	ND	ND	ND	ND	ND	ND
1,2,3-Trichlorobenzene	0.002	ND	ND	ND	ND	ND	ND
1,2,4-Trichlorobenzene	0.002	ND	ND	ND	ND	ND	ND
1,1,1-Trichloroethane	0.001	ND	ND	ND	ND	ND	МD
1,1,2-Trichloroethane	0.003	ND	ND	ND	ND	ND	ND
Trichloroethene	0.001	ND	ND	ND	ND	ND	ND
1,2,3-Trichloropropane	0.003	ND	ND	ND	ND	ND	ND
Trichlorofluoromethane	0,001	ND	ND	ND	ND	ND	ND
Trichlorotrifluoroethane	0.005	ND	ND	ND	ND	ND	ND
1,2,4-Trimethylbenzene	0.001	ND	ND	ND	ND	ND	ND
1,3,5-Trimethylbenzene	0.001	ND	ND	ND	ND	ND	ND
Vinyl chloride	0.002	ND	ND	ND	ND	ND	ND
Xylenes (total)	0.003	ND	ND	ND	ND	ND	ND

Surrogates (% recovery) Limits: 80 - 130

	Sample ID:	Blank	CF3-0.5	CF3-1.0	CF3-2.0	CF2-0.5	CF2-1.0
Dibromofluoromethane		106	112	174*	111	112	115
Toluene-d8	•	104	103	99	103	103	104
Bromofluorobenzene	·	1:0:1	96	45*	90	98	96

^{*}See Case Narrative regarding surrogate recoveries outside the acceptance limits.



Client:

PSI

Project:

J&A Truck/Container Freight

Job No.: Matrix:

16368

Analyst:

Soil

JMR

Date Sampled:

04/25/00

Date Received:

04/27/00

Date Analyzed:

05/03-12/00

Batch Number:

MS48260S2093

	Sample ID:	CF2-2.0	CF1-0.5	CF1-1.0	Ţ.
Compounds	DL -	mg/Kg	mg/Kg	mg/Kg	
Acetone	0.05	ND	ND	ND	
tert-Amyl Methyl Ether (T	Contraction of the contraction o	ND	ND	ND	
Benzene	0.001	ND	ND	0.001	******
Bromobenzene	0.005	ND	ND	ND	
Bromochloromethane	0.005	ND	ND	ND	19.5.
Bromodichloromethane	0.001	ND	ND	ND	8
Bromoform	0.005	ND	ND	ND	
Bromomethane	0,01	ND	ND	ND:	
tert-Butanol (TBA)	0.05	ND	ND	ND	
2-Butanone (MEK)	0,01	ND	ND	ND	
n-Butylbenzene	0.002	ND	ND	ND	• · · · ·
sec-Butylbenzene	0.002	ND: :	ND.	ND	
tert-Butylbenzene	0.002	- ND	ND	ND	
Carbon disulfide	0.01	ND	ND	ND	
Carbon tetrachloride	0.001	ND	ND	ND	
Chlorobenzene	0.001	ND	ND	NO. The second of the second o	4.23
Chloroethane	0.005	ND	ND	ND	,
Chloroform	0.002	ND	ND	NO NO CONTRACTOR OF THE PARTY O	
Chloromethane	0.001	ND	ND	ND	
2-Chlorotoluene	0.002	ND	NO	ND TELESCOPE AND	
4-Chlorotoluene	0.002	ND	ND	ND	
Dibromochloromethane	0.002	ND	ND	in Andrews and the second	
1,2-Dibromoethane	0.002	ND	ND	ND	
1,2-Dibramo-3-chloropro	pane 0.01	ND	ND	ND 1344 CHARLES TO SECOND TO SECOND TO SECOND TO SECOND TO SECOND TO SECOND TO SECOND TO SECOND TO SECOND TO S	
Dibromomethane	0.001	ND	ND	ND	
1,2-Dichlorobenzene	0.001	ND	ND	J. M. NDO GARAGO AND AND AND AND AND AND AND AND AND AND	2
1,3-Dichlorobenzene	0.002	ND	ND	ND	
1,4-Dichlarobenzene	0.002	ND	ND	ND 2	
Dichtorodifluoromethane	0.005	ND	ND	ND	
1,1-Dichloroethane	0.001	ND	ND	NACINDE CONTRACTOR AND CONTRACTOR	
1,2-Dichloroethane	0.001	ND	ND	ND	
1,1-Dichloroethene	0.005	ND	ND	NO NO	
cis-1,2-Dichloroethene	0.002	ND	ND	ND	
trans-1,2-Dichloroethene	0.002	ND	ND	ND	
1,2-Dichloropropane	0.001	ND	ND	ND	
1,3-Dichloropropane	0.001	ND	ND	ND	
2,2-Dichloropropane	0.001	ND	ND	ND	
1,1-Dichloropropene	0:001	ND	ND	ND	



Client:

PSI

Project:

J&A Truck/Container Freight

Job No.:

16368

Matrix:

Soil Analyst: **JMR** Date Sampled:

Date Received:

Date Analyzed:

04/27/00 05/03-12/00

04/25/00

Batch Number:

MS48260S2093

	Sample ID:	CF2-2.0	CF1-0.5	CF1-1.0	
Compounds	DL	mg/Kg	mg/Kg	mg/Kg	
cis-1,3-Dichloropropene	0.001	ND	. ND	ND	
trans-1,3-Dichloropropene	0,001	ND	ND	ND.	
Diisopropyl Ether (DIPE)	0.005	ND	ND	- ND	
Ethylbenzene	0.001	ND	ND	ND	
Ethyl tert-Butyl Ether (EtBE	0.005	ND	ND	ND	
Hexachlorobutadiene	0,001	ND	ND	ND	
2-Hexanone	0.01	ND	ND	ND	remember 1991 mengatah basak Lili Masa mesasasa dalam 1991 yan 1991 mga Hali Wali S
Isopropylbenzene	0.001	ND.	ND	ND	
p-isopropyitoluene	0.002	ND	ND	ND	in a recommendation of the commentary of the second comments of the
Methylene chloride	0.02	ND	NĐ	ND	
4-Methyl-2-pentanone	0.01	ND	ND	ND	
Methyl tert-Butyl Ether (Mt	3E) 0.005	- ND	ND	ND	
Napthalene	0.002	ND	ND	0.098	in the first season and the second second second second second second second second second second second second
n-Propylbenzene	0.001	ND	ND	ND	
Styrene	0.001	ND	ND	ND	
1,1,1,2-Tetrachioroethane	0.001	ND	ND	ND	「姚孝 왕이는 약화를 한 그 목모다
1,1,2,2-Tetrachloroethane	0.002	ND	ND	ND	
Tetrachloroethene	0.001	ND	ND	ND	
Toluene	0.001	ND	ND	ND	
1,2,3-Trichlorobenzene	0.002	ND	ND	ND	그렇게 젖으리는 뭐 그는 그는 말
1,2,4-Trichlorobenzene	0.002	ND	ND	ND	
1,1,1-Trichloroethane	0.001	ND	ND	ND	그렇게 가는 그리는 어려운 가는 사람이 그렇
1,1,2-Trichloroethane	0.003	ND	ND	ND	
Trichloroethene	0.001	ND	ND	ND	马克斯 基準的 医异种氏征 医多形术
1,2,3-Trichloropropane	0.003	ND	ND	ND	
Trichlorofluoromethane	0.001	ND	ND	ND	
Trichlorotrifluoroethane	0.005	ND	ND	ND	·
1,2,4-Trimethylbenzene	0.001	ND	ND	ND	
1,3,5-Trimethylbenzene	0.001	ND	ND	ND	
Vinyl chloride	0.002	ND	ND	ND	
Xylenes (total)	0.003	ND	ND	ND	

Surrogates (% recovery) Limits: 80 - 130

	Sample ID:	CF2-2.0	CF1-0.5	CF1-1.0
Dibromofluoromethane		109	107	112
Toluene-d8		110	105	101
Bromofluorobenzene		99	96	94



Client:

PSI

Project:

J&A Truck/Container Freight

Job Na.: Matrix:

Analyst

16368

Soil **JMR** Date Sampled: Date Received:

04/25/00 04/27/00

Date Analyzed: Batch Number:

05/03-12/00 MS48260S2093

·	Sample ID:	CF1-2.0
Compounds	DL	mg/Kg
Acetone	5.0	ND
tert-Amyl Methyl Ether (TA		ND
Benzene	0.1	ND
Bromobenzene	0.5	ND
Bromochioromethane	0.5	ND
Bromodichloromethane	0.1	ND
Bromoform	0.5	ND
Bromomethane	0.5	ND
tert-Butanol (TBA)	5.0	ND
2-Butanone (MEK)	1.0	ND
n-Butyibenzene	0.2	ND
sec-Butylbenzene	0.2	ND
tert-Butylbenzene	0.2	ND
Carbon disulfide	1.0	ND
Carbon tetrachloride	0.1	ND
Chlorobenzene	0.1	ND ND
Chloroethane	0.5	ND
Chloroform	0.2	TO NO.
Chloromethane	0.1	ND
2-Chlorotoluene	0.2	
4-Chlorotoluene	0.2	ND
Dibromochloromethane	0.2	ND ND
1,2-Dibromoethane	0.2	ND
1,2-Dibromo-3-chloropropa		
Dibromomethane	0.1	ND
1,2-Dichlorobenzene	0.1	
1,3-Dichlorobenzene	0.2	ND
1,4-Dichlorobenzene	0.2	ND ND
Dichlorodifluoromethane	0.5	ND
1,1-Dichloroethane	0.1	
1,2-Dichloroethane	0.1	ND
1,1-Dichloroethene	0.5	
cis-1,2-Dichloroethene	0.2	ND
trans-1,2-Dichloroethene	0.2	ND and the second of the secon
1,2-Dichloropropane	0.1	ND .
1,3-Dichloropropane	0.1	··· ND
2,2-Dichloropropane	0.1	ND
1,1-Dichloropropene	0.1	ND



Client:

PSI

Project:

J&A.Truck/Container Freight

Job No.:

16368

Matrix: Analyst:

Soil **JMR**

Date Sampled:

Date Received:

Batch Number:

Date Analyzed:

04/27/00 05/03-12/00

04/25/00

MS48260S2093

	Sample ID:	CF1-2.0
Compounds	DL	mg/Kg
cis-1,3-Dichloropropene	0.1	ND
trans-1,3-Dichloropropene	0.1	ND
Diisopropyl Ether (DIPE)	0.5	ND
Ethylbenzene	0.1	ND
Ethyl tert-Butyl Ether (EtBE	0.5	ND
Hexachlorobutadiene	0.1	ND
2-Hexanone	1.0	ND
Isopropylbenzene	0,1	ND
p-Isopropyltoluene	0.2	ND
Methylene chloride	2.0	ND
4-Methyl-2-pentanone	1.0	ND .
Methyl tert-Butyl Ether (MtE		ND
Napthalene	0.2	1.5
n-Propylbenzene	0.1	ND
Styrene	0.1	ND
1,1,1,2-Tetrachloroethane	** 1	ND
1,1,2,2-Tetrachloroethane	0.2	ND
Tetrachloroethene	0.1	ND
Toluene	0.1	ND
1,2,3-Trichlorobenzene	0.2	
1,2,4-Trichlorobenzene	0.2	ND
1,1,1-Trichloroethane	0.1	
1,1,2-Trichloroethane	0.3	ND .
Trichloroethene	0.1	
1,2,3-Trichloropropane	0.3	ND
Trichlorofluoromethane	0,1	
Trichlorotrifluoroethane	0.5	ND
1,2,4-Trimethylbenzene	0.1	
1,3,5-Trimethylbenzene	0.1	ND
Vinyl chloride	0.2	
Xylenes (total)	0.3	ND

Surrogates (% recovery) Limits: 80 - 130

	Sample ID:	CF1-2.0	
Dibromofluoromethane		109	
Toluene-d8		105	
Bromofluorobenzene		101	



Client:

PSI

Project:

J&A Truck/Container Freight

Job No.; Matrix: 16368

Matrix: Analyst: Soil JMR Date Sampled:

:d: 04

04/25/00

Date Received:

04/27/00

Date Analyzed:

05/03-12/00

Batch Number: MS48260S2093

	nple ID:	CF2-3.0	
Compounds	DL	mg/Kg	
Acetone	13	ND	_
tert-Amyl Methyl Ether (TAME	1.3	ND	id işeçi
Benzene	0.3	0.4	0.890
Bromobenzene	1.3	ND	
Bromochloromethane	1.3	ND	3444
Bromodichloromethane	0.3	ND	
Bromoform	1.3	ND	(1.886)
Bromomethane	1.3	ND	. N. () - ()
tert-Butanol (TBA)	13	ND	** :
2-Butanone (MEK)	2.5	ND CONTROL OF THE CON	
n-Butylbenzene	0.5	ND	
sec-Butylbenzene	0.5	ND	33
tert-Butylbenzene	0.5	ND	***
Carbon disulfide	2.5	ND	33
Carbon tetrachloride	0.3	ND	1.67
Chlorobenzene	0.3		
Chloroethane	1.3	ND	:1
Chloroform	0.5	在ENDETER TEXT EXPLORED LINE LINE TO A LOTTER LINE	
Chloromethane	0.3	ND	
2-Chlorotoluene	0.5		$\mathcal{L}_{\frac{1}{2}}$
4-Chlorotoluene	0.5	ND	
Dibromochloromethane	0.5		
1,2-Dibromoethane	0.5	ND	
1,2-Dibromo-3-chloropropane	2.5		
Dibromomethane	0.3	ND	
1,2-Dichlorobenzene	0.3	HENDER BEINDE BERTHAR DE STANDER DE STANDER DE STANDER DE STANDER DE STANDER DE STANDER DE STANDER DE STANDER	
1,3-Dichlorobenzene	0.5	ND	
1,4-Dichlorobenzene	0.5	e ND emilione, a company of the comp	
Dichlorodifluoromethane	1,3	ND	
1,1-Dichloroethane	0.3	ND CONTRACTOR OF THE CONTRACTO	
1,2-Dichloroethane	0.3	ND	
1,1-Dichloroethene	1.3	ND 1	
cis-1,2-Dichloroethene	0.5	ND	·
trans-1,2-Dichloroethene	0.5	ND	
1,2-Dichloropropane	0.3	ND	
1,3-Dichloropropane	0.3	ND	
2,2-Dichloropropane	0.3	ND	
1,1-Dichloropropene	0.3	ND	



Client:

PSI

Project:

J&A Truck/Container Freight

Job No.: Matrix:

Soil

Analyst:

16368

JMR

Date Sampled:

Date Received:

04/25/00 04/27/00

Date Analyzed:

05/03-12/00

Batch Number:

MS48260S2093

	Sample ID:	CF2-3.0
Compounds	DL	mg/Kg
cis-1,3-Dichloropropene	. 0.3	ND
trans-1,3-Dichloropropene	0.3	ND
Diisopropyl Ether (DIPE)	1.3	ND
Ethylbenzene -	0.3	ND
Ethyl tert-Butyl Ether (EtBE	1.3	ND
Hexachlorobutadiene	0.3	ND:
2-Hexanone	2.5	ND
Isopropylbenzene	0.3	ND
p-isopropyltoluene	0.5	ND
Methylene chloride	5	ND
4-Methyl-2-pentanone	2.5	ND
Methyl tert-Butyl Ether (Mti	· " 不是我们的,我就是一个一个一个一个一个一个一个一个	ND
Napthalene	0.5	390
n-Propylbenzene	0.3	ND
Styrene	0.3	ND
1,1,1,2-Tetrachloroethane	0.3	ND
1,1,2,2-Tetrachloroethane	0.5	ND .
Tetrachloroethene	0.3	ND
Toluene	0.3	ND
1,2,3-Trichlorobenzene	0.5	
1,2,4-Trichlorobenzene	0.5	ND
1,1,1-Trichloroethane	0:3	ND .
1,1,2-Trichloroethane	0.8	ND
Trichtoroethene	0.3	ND .
1,2,3-Trichloropropane	0.8	ND
Trichlorofluoromethane	0.3	그 (M D 기울) 등 대한 대통이 그림은 말했다면 함께 되었다.
Trichlorotrifluoroethane	1.3	ND
1,2,4-Trimethylbenzene	0.3	
1,3,5-Trimethylbenzene	0.3	ND
Vinyl chloride	0.5	
Xylenes (total)	8.0	ND

Surrogates (% recovery) Limits: 80 - 130

	Sample ID:	CF2-3.0			
Dibromofluoromethane		106	**	4	•
Toluene-d8		104			
Bromofluorobenzene	-	102			

QC Sample Report - EPA Method 8260

Matrix: Soil

Batch #: MS48260S2093

Batch Accuracy Results

Sample ID: Laboratory Cor	itrol Sampl	8		
Analyte	Spike Concentration mg/Kg	% Recovery LCS	Acceptance Limits % Recovery	Pass/Fail
1,1-Dichloroethene	0.020	96	59 - 172	Pass
Benzene	0.020	103	66 - 142	Pass
Trichloroethene	0.020	100	71 - 137	Pass
Toluene	0.020	99	59 - 139	Pass
Chiorobenzene	0.020	86	60 - 133	Pass

Analytical Notes:

Batch Precision Results

MS/MSD Sample ID: 16379-1

Analyte	Spike Sample Recovery mg/Kg	Spike Duplicate Recovery mg/Kg	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass/Fail
1,1-Dichloroethene	0.0259	0.0255	2%	22%	Pass
Benzene	0.0243	0.0247	2%	21%	Pass
Trichloroethene	0.0225	0.0226	0%	24%	Pass
Toluene	0.0216	0.0214	1%	21%	Pass
Chlorobenzene	0.0197	0.0197	0%	21%	Pass

Analytical Notes:
·
•
· .
•

MS: Matrix Spike Sample
MSD: Matrix Spike Duplicate



Client: PSI

Project: J&A Truck/Container Freight

Job No.: 16368 Matrix: Soil

Analyst: TPW

Date Sampled:

04/25/00

Date Received:
Date Extracted:

04/27/00 05/02/00

Dates Analyzed:

05/04-05/00

Batch Number:

8270S0620

	Sample ID:	Blank	CF3-0.5	CF3-1.0	CF3-2.0	CF2-0.5	CF2-1.0
Compound	DL.*	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg
Acenaphthene	0.33	ND	ND	ND	ND	0.34	ND
Acenaphthylene	0.33	ND	ND	2.0	1.8	0,85	ND
Anthracene	0.33	ND	ND	4.6	2.0	1.5	ND
Benzo[a]anthracene	0.66	ND	ND	16	5.5	1.7	ND
Benzo[a]pyrene	0.66	ND	ND	40	9.4	3.2	1.2
Benzo[b]fluoranthene	0.33	ND	ND	47	12	4.0	1.8
Benzo[g,h,i]perylene	0.99	ND	ND	33	10	3.5	1.6
Benzo[k]fluoranthene	0.33	ND	ND	47	12	4.0	1.8
Benzyl alcohol	1.3	ND	ND	ND	ND	ND	ND
bis(2-Chloroethoxy)metha	ne 0.66	ND	ND	ND	ND	ND	ND
bis(2-Chloroethyl)ether	0.66	ND	ND	ND	ND	ND	ND
bis(2-Chłoroisopropyt)ethe	г 0.99	ND	ND	ND	ND	ND	ND
bis(2-Ethylhexyl)phthalate	3,3	ND	ND	ND	ND	ND	ND
4-Bromophenylphenylethe	r 0.33	ND	ND	ND	ND	ND	ND
Butylbenzylphthalate	0.33	ND	ND	ND	ND	ND	ND
4-Chloro-3-methylphenol	1.6	ND	ND	ND	ND	ND	ND
4-Chloroaniline	1.6	ND	ND	ND	ND	ND	ND
2-Chloronaphthalene	0.33	ND	ND	ND	ND	ND	ND
2-Chlorophenol	1.3	ND	ИD	ND	ND	ND	ND
4-Chlorophenylphenylethe	r 0:33	ND	ND	ND	ND	ND	NO
Chrysene	0.33	ND	ND	19	7.1	2.1	0.76
Di-n-butylphthalate	3.3	ND	ND	ŃΟ	NO	ND	ND
Di-n-octylphthalate	0.33	ND	ND	ND	ND	ND	ND
Dibenzo[a,h]anthracene	0.99	ND	ND	6.3	1.2	ND	ND
Dibenzofuran	0.33	ND	ND	ND	ND	ND	ND
1,2-Dichlorobenzene	0.33	ND	ND	ND	ND	ND	ND
1,3-Dichlorobenzene	0.33	ND	ND	ND	ND	ND	ND
1,4-Dichlorobenzene	0.33	ND	ND.	ND	ND	ND	ND
3,3-Dichlorobenzidine	1.3	ND	ND	ND	ND	ND	ND
2,4-Dichlorophenol	1.6	ND	ND	ND	ND	ND	ND
Diethylphthalate	3.3	ND	ND	ND	ND	ND	ND
2,4-Dimethylphenol	0.99	ND	ND	ND	ND	ND	ND
Dimethylphthalate	0.33	ND	ND	ND	ND	ND	ND
4,6-Dinitro-2-methylpheno	1 3.3	ND	ND	ND	ND	ND	ND
2,4-Dinitrophenol	16	ND	ND	ND	ND	ND	ND
2,4-Dinitrotoluene	0.33	ND	ND	ND	ND	ND	ND



Client: Project:

PSI

J&A Truck/Container Freight

Job No.: 16368

Matrix: Soil Analyst: TPW Date Sampled:

04/25/00

Date Received: 04/2

Date Extracted:

04/27/00 05/02/00

Dates Analyzed:

05/04-05/00.

Batch Number: 8270S0620

	Sample ID:	Blank	CF3-0.5	CF3-1.0	CF3-2.0	CF2-0.5	CF2-1.0
Compound	DL*	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg
2,6-Dinitrotoluene	0.99	ND	ND	ND	ND	ND	ND
Fluoranthene	0.33	ND ::	ND	62	20	7.6	ND
Fluorene	0.33	ND	ND	0.53	0.74	0.65	ND
Hexachlorobenzene	0.33	ND	ND	ND	ND	ND	ND
Hexachlorobutadiene	0.33	ND	ND	ND	ND	ND	ND
Hexachlorocyclopentadier	ne - 16	ND	ND	ND	ND	ND	ND
Hexachloroethane	0.33	ND	ND	ND	ND	ND	ND
Indeno[1,2,3-c,d]pyrene	1.3	ND	ND	30	7.5	2.6	ND
Isophorone	0.33	ND	ND	ND	ND	ND	ND
2-Methylnaphthalene	0.33	ND	ND	ND	ND	ND	ND
2-Methylphenol	1.6	ND	ND	ND	ND	ND	ND
4-Methylphenol	1.6	ND	ND	ND	ND	ND	ND
N-Nitrosodi-n-propylamin	e 0.33	ND	ND	ND	ND	ND	ND
N-Nitrosodiphenylamine	0.33	NO	ND	ND	ND	ND	ND
Naphthalene	0.33	ND	ND	0.85	1.3	0.37	ND
2-Nitroaniline	0.99	ND	ND	ND	ND	ND	ND
3-Nitroaniline	0.99	ND	ND	ND	ND	ND	ND
4-Nitroaniline	3.3	ND	ND	ND	ND	ND	ND
Nitrobenzene	0.99	ND	ND	ND	ND	ND	ND
2-Nitrophenol	1,3	ND	ND	ND:	ND	ND	ND
4-Nitrophenol	3.3	ND	ND	ND	ND	ND	ND
Pentachlorophenol	16	ND	ND	ND	ND	ND	ND
Phenanthrene	0.66	ND	ND	26	14	7.6	0.81
Phenol	1.3	ND	ND	ND	ND	ND	ND
Pyrene	0.33	ND	ND	74	27	9.3	2.7
1,2,4-Trichlorobenzene	0.33	ND	ND	ND	ND	ND	ND
2,4,5-Trichlorophenol	2	ND	ND	ND	ND	ND	ND
2,4,6-Trichlorophenol	3.3	ND	ND	ND	ND	ND	ND

^{*} See Case Narrative regarding higher than usual detection limits.

Surrogates (Limits) in Percent Recovery

Sample ID:	Blank	CF3-0.5	CF3-1.0	CF3-2.0	CF2-0.5	CF2-1.0
2-Fluorophenol (25 - 121%)	98	101	106	101	100	92.
Phenol-D5 (24 - 113%)	96	101	104	98	97	94
Nitrobenzene-D5 (23 - 120%)	79	81	87	79	80	75
2-Fluorobiphenyl (30 - 115%)	94	102	105	99	102	97
2,4,6-Tribromophenol (19 - 122%)	103	107	107	103	103	105
p-Terphenyl-D14 (18 - 137%)	107	100	90	110	102	97



Client: PSI **Project**: J&A Truck/Container Freight

CF2-2.0

CF1-0.5

Job No.: 16368 Matrix: Soil Analyst; 🕟 TPW

Sample ID:

Date Sampled: 04/25/00 Date Received: 04/27/00 Date Extracted: 05/02/00

Dates Analyzed: 05/04-05/00 Batch Number: 8270S0620 CF1-1.0 CF1-2.0

Compound	_DL*	mg/Kg	mg/Kg	mg/Kg	mg/Kg	
Acenaphthene	0.33	ND	ND	ND	ND	
Acenaphthylene	0.33	0.69	ND	ND	0.67	
Anthracene	0.33	1.4	ND	ND	0.50	
Benzo[a]anthracene	0.66	5.7	ND	CM	0.91	
Benzo(a)pyrene	0.66	12	ND	0.79	1. 7	
Benzo[b]fluoranthene	0.33	17	0.59	1,0	2.0	
Benzo(g,h,i]perylene	0.99	17	ND	1.0	2.0	
Benzo(k)fluoranthene	0.33	17	0.61	1.0	2.0	
Benzyl alcohol	1.3	ND	ND	ND	ND	
bis(2-Chloroethoxy)methane	0.66	ND	ND	ND	ND	en waa saawaa sa tay wan no y
bis(2-Chloroethyl)ether	0.66	ND	ND	ND	ND	
bis(2-Chloroisopropyl)ether	0.99	NO	ND.	ND	ND	Valtis isaassa kassa ka k
bis(2-Ethylhexyl)phthalate	3.3	ND	ND	ND	ND	
4-Bromophenylphenylether	0.33	ND	ND	ND	ND	
Butylbenzylphthalate	0.33	ND	ND	ND	ND	
4-Chloro-3-methylphenol	1.6	ND	ND	ND	ND	
4-Chloroaniline	1.6	ND	ND	ND	ND	
2-Chloronaphthalene	0.33	ND	ND	ND	ND	
2-Chlorophenol	1.3	ND	ND	ND	ND	
4-Chlorophenylphenylether	0:33	ND	ND	ND	ND	
Chrysene	0.33	8.7	ND	0.62	1.4	
Di-n-butylphthalate	3.3	ND	ND	ND	ND	
Di-n-octylphthalate	0.33	ND	ND	ND	ND	
Dibenzo(a,h]anthracene	0.99	1.8	ND	ND :	ND	
Dibenzofuran	0.33	ND	ND	ND	ND	
1,2-Dichlorobenzene	0.33	ND	ND	ND	ND	
1,3-Dichlorobenzene	0.33	ND	ND	ND	ND	
1,4-Dichlorobenzene	0.33	ND	ND	ND	ND	
3,3-Dichlorobenzidine	1.3	ND	ND	ND	ND	ma Programme and the
2,4-Dichlorophenol	1.6	ND	ND	ND	ND	
Diethylphthalate	3.3	ND	ND	ND	ND	
2,4-Dimethylphenol	0:99	ND	ND	ND	ND .	er.
Dimethylphthalate	0.33	ND	ND	ND	ND	
4.6-Dinitro-2-methylphenol	3.3	ND	ND:	ND	ND	
2,4-Dinitrophenol	16	ND	ND ND	ND		
2,4-Dinitrotoluene	0.33	ND	ND		ND	
	0.00	NO.	שאו	ND	ND	



Client: Project: PSI

J&A Truck/Container Freight

Date Sampled: Date Received:

04/25/00

Job No.:

Analyst:

16368

04/27/00

Matrix: Soil TPW

Date Extracted: Dates Analyzed: 05/02/00

Batch Number: 🦠

05/04-05/00 8270S0620

<u> </u>	Sample ID:	CF2-2.0	CF1-0.5	CF1-1.0	CF1-2.0	
Compound	DL*	mg/Kg	mg/Kg	mg/Kg	mg/Kg	
2,6-Dinitrotoluene	0.99	ND	ND	ND	ND	
Fluoranthene	0,33	22	0.59	1.5	3.3	
Fluorene	0.33	1.6	ND	ND	ND	i e i recommenda e para de la composición del composición de la composición de la composición de la composición de la composición de la composición de la composición de la composición de la composición de la composición de la composición de la composición de la composición de la composición de la composición de la composición de la composición de la co
Hexachlorobenzene	0,33	ND	ND	ND	ND	
Hexachlorobutadiene	0.33	ND	ND	ND	ND	
Hexachlorocyclopentadie	ene 16	ND	ND	ND	ON	
Hexachloroethane	0.33	ND	ND	ND	ND	
Indeno[1,2,3-c,d]pyrene	1.3	14	ND	ND	1.3	
Isophorone	0.33	ND	ND	ND	ND	Transfer of Property Control of
2-Methylnaphthalene	0.33	ND	ND	ND	ND	
2-Methylphenol	1.6	ND	ND	ND	ND	
4-Methylphenol	1.6	ND	ND	ND .	ND	
N-Nitrosodi-n-propylamir	ne 0.33	ND	ND	ND	ND	
N-Nitrosodiphenylamine	0.33	ND	ND	ND	ND	
Naphthalene	0.33	2.4	ND	0.83	2.2	and the second of the second o
2-Nitroaniline	0.99	ND	ND	ND	ND	
3-Nitroaniline	0.99	ND	ND	ND	ND	The second secon
4-Nitroaniline	3.3	ND	ND	ND	ND	
Nitrobenzene	0.99	ND	ND	ND	ND	and the second of the second
2-Nitrophenol	1.3	ND	ND	ND	ND	
4-Nitrophenol	3.3	ND	ND	ND	ND	The second of the Mark of the Mark of the Control o
Pentachlorophenol	16	ND	ND	ND	NO	
Phenanthrene	0.66	7.8	ND	1.0	2.6	
Phenol	1.3	ND	ND	ND	ND	: "
Pyrene	0.33	29	0.85	2.2	4.8	
1,2,4-Trichlorobenzene	0.33	ND	ND	ND	ND	and the second
2,4,5-Trichlorophenal	2	ND	ND	ND	ND	
and a second of the second	2.00		—	· - -		

^{*} See Case Narrative regarding higher than usual detection limits.

ND

Surrogates (Limits) in Percent Recovery

2,4,6-Trichlorophenot

Sample ID:	CF2-2.0	CF1-0.5	CF1-1.0	CF1-2.0	
2-Fluorophenol (25 - 121%)	82	71	89	89	
Phenol-D5 (24 - 113%)	84	93	92	90	
Nitrobenzene-D5 (23 - 120%)	70	78	75	73	•
2-Fluorobiphenyl (30 - 115%)	91	96	95	93	. "
2,4,6-Tribromophenol (19 - 122%)	105	31	90	101	•
p-Terphenyl-D14 (18 - 137%)	96	104	110	107	

ND:

ND

ND



QC Sample Report - EPA 8270

Batch #: 8270S0620

Matrix: Soil

Sample	ID:	Laboratory	y Control Sample	3
--------	-----	------------	------------------	---

Analyte	Spike Concentration mg/Kg	% Recovery LCS	Acceptance Limits % Recovery	Pass/Fail
Phenol	2.66	91	5 - 112	Pass
2-Chlorophenoi	2.66	102	23 - 134	Pass
1,4-Dichlorobenzene	1.33	100	20 - 124	Pass
N-Nitrosodi-n-propylamine	1.33	81	0 - 230	Pass
1,2,4-Trichlorobenzene	1.33	105	44 - 142	Pass
4-Chloro-3-Methylphenol	2.66	103	22 - 147	Pass
Acenaphthene	1.33	100	47 - 145	Pass
4-Nitrophenol	2.66	108	0 - 132	Pass
2,4-Dinitrotoluene	1.33	103	39 - 139	Pass
Pentachlorophenol	2.66	132	14 - 176	Pass
Pyrene	1.33	101	52 - 115	Pass

Analytical Notes:	

Batch Precision Results

MS/MSD Sample ID: Laboratory Control Sample

Analyte	Spike Sample Recovery mg/Kg	Spike Duplicate Recovery mg/Kg	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass/Fail
Phenoi	2.42	2.38	1%	35%	Pass
2-Chlorophenol	2.71	2.70	0%	50%	Pass
1,4-Dichlorobenzene	1.34	1.06	23%	27%	Pass
N-Nitrosodi-n-propylamine	1.08	1.06	2%	38%	Pass
1,2,4-Trichlorobenzene	1.40	. 1.35	4%	23%	Pass
4-Chloro-3-Methylphenol	2.74	2.58	6%	33%	Pass
Acenaphthene	1.33	1.28	4%	23%	Pass
4-Nitrophenol	2.89	2.75	5%	50%	Pass
2,4-Dinitrotoluene	1.37	1.31	4%	47%	Pass
Pentachlorophenol	3.51	3.49	0%	47%	Pass
Pyrene	1.35	1.34	1%	36%	Pass

Analytical Notes:

rage:	20	Οt	۷:	
-------	----	----	----	--



Metals

Client: PSI

Project: CT J&A Truck/Container Freight

Job No: 16393 Matrix: Water Analyst: RLB/TLR Date Sampled: Date Received: 05/02/00 05/03/00

Date Digested:

05/04/00

Date Analyzed: 05/04-15/00 Batch Number: 6010W1555

	S	ample ID:	Blank	JA-1	JA-2	JA-3	JA-4	
Element	Method #	DL	mg/L	mg/L	mg/L	mg/L	mg/L	
Antimony	6010B	0.015	ND	ND	ND	ND	ND	,
Arsenic	6010B	0.010	ND	ON	ND	ND	ND	
Barium	6010B	0.010	ND	0.16	0.15	0.18	0.12	
Beryllium	6010B	0.010	ND	ND	ND	ND	ND	
Cadmium	6010B	0.010	ND	ND	ND	ND	ND	· · · ·
Chromium	6010B	0.010	ND	ND	0.010	ND	ND	
Cobalt	6010B	0.010	ND	ND	ND	ND	ND	
Copper	6010B	0.010	ND	ND	ND	ND	ND	er gjall Laste dalla
Lead	6010B	0.010	ND	ND	ND	ND	ND	aginga, a laab
Mercury	7470	0.0002	ND	ND	ON	DN	ND	
Molybdenum	6010B	0.010	ND	ND	ND	ND	ND	
Nickel	6010B	0_010	ND	0.045	0.035	0.030	0.027	
Selenium	6010B	0.015	ND	ND	ND	ND	ND	
Silver	6010B	0.010	ND	GN	ND	ND	ND	
Thallium	60108	0.010	ND	ND	ND	ND	ND	
Vanadium	6010B	0.010	ND	ND	ND	ND	ND	
Zinc	6010B	0.10	ND	0.12	0.10	0.12	ND	
State of the state of	人名马克格 医线管		183					



Metals

Client: PSI

Project: CT J&A Truck/Container Freight

Job No: 16393 Matrix: Water Analyst: RLB/TLR Date Sampled: Date Received: 05/02/00

Date Digested:

05/03/00 05/04/00

Date Analyzed:

05/04-15/00

Batch Number: 6010W1555

	Sa	mple ID:	CF-1	CF-2	CF-3	CF-10	
Element	Method #	DL*	mg/L	mg/L	mg/L	mg/L	
Antimony	6010B	0.30	ND	ND	ND	ND	¥
Arsenic	6010B	0.20	ND	ND	ND	ND	
Barium	6010B	0.20	0.28	ND	ND	ND	STARASTONES, A SPECIAL AREA (1997) Factor
Beryllium	6010B	0.20	ND	· ND	ND:	ND	
Cadmium	6010B	0.20	ND	ND	ND	ND	en et tragger et in den grad grit, de lind internet. Die en
Chromium	6010B	0.20	ND	ND	ND	ND	
Cobalt	6010B	0.20	ND	ND	ND	ND	a de la companya de la companya de la companya de la companya de la companya de la companya de la companya de
Copper	6010B	0.20	ND	ND	ND	ND	
Lead	6010B	0.20	ND	ND	ND	ND	
Mercury	7470	0.0002	ND	ND	ND	ND	
Molybdenum	6010B	0.20	ND	ND	ND	ND	A BROOK IN THE TO STORE TO SEE TO SEE
Nickel	6010B	0.20	ND⋯	ND	. ND	ND	
Selenium	6010B	0.30	ND	ND	ND	ND	
Silver	6010B	0.20	ND	ND	ND	ND	in the second of
Thallium	6010B	0.20	ND	ND	ND	ND	
Vanadium	6010B	0.20	ND	ND	ND	ND	
Zinc	6010B	2.0	ND	ND	ND	ND	

^{*}See Case Narrative regarding raised reporting limits.



QC Sample Report - Metals

Matrix: Water Batch #: 6010W1555 MS/MSD Sample ID: JA-1

•	Batch f	Precision	Result	s:		Batch Accuracy Results:			
Metal	Spike Sample Recovery mg/L	Spike Duplicate Recovery mg/L	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass / Fail	Spike Concentration mg/L	% Recovery LCS	Acceptance Limits Percent Recovery	Pass / Fail
Antimony	1.01	1.07	6%	20%	Pass	1.0	101	75 - 125	Pass
Arsenic	0.99	1.05	5%	20%	Pass	1.0	97	75 - 125	Pass
Barium	1.21	1.21	1%	20%	Pass	1.0	102	75 - 125	Pass
Beryllium	0.95	1.01	6%	20%	Pass	1.0	98	75 - 125	Pass
Cadmium	1.02	1.02	0%	20%	Pass	1.0	103	75 - 125	Pass
Chromium	1.00	1.02	2%	20%	Pass	1.0	101	75 - 125	Pass
Cobalt	1.01	1.02	1%	20%	Pass	1.0	103	75 - 125	Pass
Соррег	1,05	1.06	1%	20%	Pass	1.0	103	75 - 125	Pass
Lead	0.97	1.03	6%	20%	Pass	1.0	100	75 - 125	Pass
Mercury	2.51	2.59	3%	20%	Pass	0.005	110	75 - 125	Pass
Molybdenum	1.01	1.07	6%	20%	Pass	1.0	101	75 - 125	Pass
Nickel	1.02	1.06	4%	20%	Pass	1.0	101	75 - 125	Pass
Selenium	0.97	1.03	6%	20%	Pass	1.0	98	75 - 125	Pass
Silver**	1.03	1.06	3%	20%	Pass	1.0	103	75 - 125	Pass
Thallium	0.96	1.00	4%	20%	Pass	1.0	98	75 - 125	Pass
Vanadium	1.05	1.06	0%	20%	Pass	1.0	104	75 - 125	Pass
Zinc	1.13	1.13	0%	20%	Pass	1.0	113	75 - 125	Pass

Analytical Notes

**The MS/MSD for this analyte did not meet the acceptance criteria due to a sample matrix effect.

The LCS / LCSD pair was used to provide precision data for this batch.

LCS: Laboratory Control Sample

LCSD: Laboratory Control Sample Duplicate

MS: Matrix Spike

RPD: Relative Percent Difference

MSD: Matrix Spike Duplicate



Modified 8015 - Fuel Screen

Client: PSI

Project: CT J&A Truck/Container Freight

Job No.: 16393 Matrix: Water Analyst: JL

 Date Sampled:
 05/02/00

 Date Received:
 05/03/00

 Date Extracted:
 05/08/00

 Date Analyzed:
 05/09/00

8015DW1914

Batch Number:

	Fuel Ide	entified	i:			Diese	٠			Moto					Detect Limit	
	, _	Units	3:	·		mg/L	`			mg/l	L				mg/l	
Blank			6605 86000			ND		(10000000) (200000000000000000000000000000		NĐ					0.40	1,177
JA-1		autom a	- 58 60, 1555	i. N. P. Millerensia	50 949 55 56 4. 1	□ND	orday.			ND					0.40	
JA-2						8.0				ND	0.0896 444				0.40)
JA-3		. gaga ay j	-2025-77	. 1	. roug y godjaga	DM		s sejmens	111555555	ND	ng sanga awar sa	Valdos deglos no		uiki yesi m	0.40	
JA-4 CF-1			1.000			ND		- 1000 -		ND	1.000				0.40	100
CF-2			C 1802-1	- Bookidge Establish		21 2.8			-25 kibaldaké nya	ND	proportion.			ja japa	4.0	
CF-3			. 24663465 . 4 . 25040875	1000 000000000000000000000000000000000		VD		- 62466664		ON ND	AT 600 R 1 1		, impores e Daler (gr.)		0.40	
CF-10						1.8				ND	v158.88510				0.40	
											1 (0.5.1) 1 (0.5.1) 1 (0.5.5)	i Cressii Literatu				
																i. Ar
	n jiraa		postel Till III		· . · . · . · . · . · . · . · . · . · .			1884 11884 11894				i jari di Mari	4 (A) 4 (A)	•	ż	
: 4 - 5	• •	•						## ## # 1		en ger		1. 14.1				
		٠.				1 % - 1 % - 1 %					. • *		1			
				•							()				,	
							W _p									

QC Sample Report - EPA 8015M Diesel

Matrix: Water

Batch #: 8015DW1914

Batch Accuracy Results

Analyte	Spike Conce mg/L	% Recovery	Acceptance I % Recovery	Pass/Fail
	Concentration	, LCS	Limits	

Analytical Note	es:	
		•
	•	
1		
1		

Batch Precision Results

MS/MSD Sample ID: Laboratory Control Sample

Analyte	Spike Sample Recovery mg/L	Spike Duplicate Recovery mg/L	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass/Fail
Diesel	0.62	0.64	3%	25%	Pass

	Analytical Notes:	
ı		
ı		
١	·	
ŀ	[
ł	ľ	
١	·	
1	·	
ł	1	
1		
1		
1		
1		

MS: Matrix Spike Sample MSD: Matrix Spike Duplicate



Modified 8015 - Total Volatile Hydrocarbons as Gasoline

Client: PSI
Project: CT J&A Truck/Container Freight

Job No.: 16393 Matrix: Water Analyst: CP

 Date Sampled:
 05/02/00

 Date Received:
 05/03/00

 Date Analyzed:
 05/04/00

 Batch Number:
 8015GW2593

	Detection	Petroleum Hydrocarbons a	is
	Limit	Gasoline	
Sample ID	mg/L	mg/L	.74 (8.38 (82) - 52) Karel 1 (8.38
Method Blank	0.5	ND	
	0.5	ND	
JA-2	0.5	0.77	
JA-3	0.5	, ND	
JA-4	0.5	ND	
CF-1	50.0	200. (200.) (1. 10. 10. 10. 10. 10. 10. 10. 10. 10. 1	
CF-2	50.0	54	
CF-3	0.5	0.50	
CF-10	25.0	27	



QC Sample Report - EPA 8015M Gasoline

Matrix: Water

Batch #: 8015GW2593

Batch Accuracy Results

Sample ID: Laboratory Conti	Concentration	% Recovery LCS	cceptance Limits Recovery	'ass/Fail
Analyte	Spike mg/L	% %	Acce % Re	Pass
Gasoline	10.0	100	70 - 130	Pass

Analytical Notes:	
· ·	

Batch Precision Results

9.25

10.05

MS/MSD Sample ID: Laboratory Control Sample

MS:	V	latrix S	pike	S	ample
MSC) :	Matrix	Spik	ę	Duplicate

Gasoline

Analytical Notes:								
		· · · · ·						
·								
÷			•					

25%

Pass



EPA 8080 - Organochlorine Pesticides & PCBs

Client: PSI

Project: CT J&A Truck/Container Freight

Job No.: 16393 Matrix: Water Analyst: TPW Date Sampled: 05/02/00
Date Received: 05/03/00
Date Extracted: 05/06/00

Date Analyzed: 05/08/00 Batch Number: PESTW0251

· · · · · · · · · · · · · · · · · · ·	Sample ID:	Blank	JA-1	JA-2	JA-3	JA-4	CF-1
Pesticides	DL	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L
Aldrin	0.0001	ND	ND	ND	. ND	ND	ND
Alpha-BHC	0.0001	ND	* ND:	ND	ND	ND	ND
Beta-BHC	0.0001	ND	ND	ND	ND	ND	ND
Delta-8HC	0.0001	ND	ND	ND	ND	ND	ND
Gamma-BHC (Lindane)	0.0001	ND	ND	ND	ND	ND	ND
Chlordane	0:0001	ND	ND	ND	ND	ND	ND
4,4'-DDD	0.0002	ND	ND	ND	ND	ND	ND
4,4'-DDE	0.0002	ND		ND	ND //	ND	ND
4,4'-DDT	0.0002	ND	ND	ND	ND	ND	ND
Dieldrin	0.0002	ND	ND	ND	ND.	ND	ND
Endosulfan I	0.0001	ND	ND	ND	ND	ND	ND
Endosulfan II	0.0002	ND	ND	ND	ND	ND	ND
Endosulfan sulfate	0.0002	ND	ND	ND	ND	ND	ND
Endrin	0.0002	ND	ND	ND	NO	ND	ND
Endrin Aldehyde	0.0002	ND	ND	ND	ND	ND	ND
Endrin Ketone	0.001	ND	ND	ND	ND .	NO	ND.
Heptachlor	0.00005	ND	ND	ND	ND	ND	ND
Heptachlor Epoxide	0.00005	ND	ND	ND	ND	ND	ND
Methoxychlor	0.0005	ND	ND	ND	ND	ND	ND
Toxaphene	0.001	ND	ND	ND	ND	ND	CN
PCBs							
Arocior-1016	0.001	ND	ND	ND	ND	ND	. ND
Aroclor-1221	0.001	ND	ND	ND	ND	ND	ND
Aroclor-1232	0.001	ND	ND	ND	ND	ND	ND
Aroclor-1242	0.001	ND	ND	ND	ND	ND	ND
Aroclor-1248	0.001	ND	ND	ND	ND:	ND	ND
Aroclor-1254	0.001	ND	ND	ND	ND	ND	ND
Aroclor-1260	0.001	ND	ND	ND	ND	ND	ND

Surrogates (% recovery) Limits: 50 - 150

	Sample ID:	Blank	JA-1	JA-2	JA-3	JA-4	CF-1
					THU.		
etrachloro-m-xylene		126	117	93	102	105	121



QC Sample Report - EPA 8080 Pesticides

Matrix: Soil

Batch #: PESTW0251

Batch Accuracy Results

Sample ID: Laboratory Con	trol Sample	****		·
Analyte	Spike Concentration μg/L	% Recovery LCS	Acceptance Limits % Recovery	Pass/Fail
Lindane	0.1	87	32 - 127	Pass
Heptachlor	0.1	108	34 - 111	Pass
Aldrin	0.1	103	42 - 122	Pass
Dieldrin	0.4	76	36 - 146	Pass
Endrin	0.4	. 86	30 - 147	Pass
DDT	0.4	. 73	25 - 160	Pass
Aroclor 1242	2.0	93	75 - 127	Pass

Analytical Notes:

Batch Precision Results

MS/MSD Sample ID: Laboratory Control Sample

Analyte	Spike Sample Recovery mg/L	Spike Duplicate Recovery mg/L	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass/Fail
Lindane	0.087	0.085	2%	25%	Pass
Heptachlor	0.108	0.107	1%	25%	Pass
Aldrin	0.103	0.102	1%	25%	Pass
Dieldrin	0.300	0.290	3%	25%	Pass
Endrin	0.340	0.330	3%	25%	Pass
DDT	0.290	0.290	0%	25%	Pass

MS:	Matrix	Spike S	Sample
MSC): Matri	x Spike	Duplicate

Analytical Notes:



Client:

PSI

Project:

CT J&A Truck/Container Freight

Job No.:

16393

Matrix. Analyst: Water JMR :

Date Sampled:

05/02/00

Date Received:

05/03/00

Date Analyzed:

05/04-12/00

Batch Number:

	Sample ID:	Blank	JA-1	JA-2	JA-3	JA-4	CF-2
Compounds	DL	μg/L	μg/L	μg/L	μ g/L	μg/L.	μg/L
Acetone	50	ND	ND,	ND .	ND .	. ND	ND
tert-Arnyl Methyl Ether (TAM	E) 5.0	ND	ND	ND	ND	ND	ND
Benzene	0.5	ND	ND	ND	ND-	0.7	330
Bromobenzene	1.0	ND	ND	ND	ND	ND	ND
Bromochloromethane	1.0	ND.	ND	ND	ND	ND	ND
Bromodichloromethane	0.5	ND	ND	ND	ND	ND	ND
Bromoform	0.5	ND	ND	ND	ND	ND	ND
Bromomethane	0,5	ND	ON	ND	ND	ND	ND
tert-Butanol (TBA)	50	ND	ND	ND	ND	ND	ND
2-Butanone (MEK)	10	ND	ND	ND	ND	ND	ND
n-Butylbenzene	0.5	ND	ND	ND	ND	ND	ND
sec-Butylbenzene	0.5	ND	ND	ND	ND	ND	ND
tert-Butylbenzene	0.5	, ND	ND	ND	ND	ND	ND
Carbon disulfide	10	ND	ND	ND	.NĐ	ND:	68
Carbon tetrachloride	0.5	ND	ND	ND	ND	ND	ND
Chlorobenzene	0.5	ND	ND	ND	ND	ND	ND
Chloroethane	0.5	ND	ND	ND	ND	ND	ND
Chloroform	0.5	ND	ND	ND	ND	1.7	ND
Chloromethane	0.5	ND	ND	ND	ND	ND	ND
2-Chlorotoluene	0.5	ND	ND	ND	ND	ND	ND
4-Chlorotoluene	0.5	ND	ND	ND	ND	ND	ND
Dibromochloromethane	0.5	ND	ND	ND	ND	ND	ND
1,2-Dibromoethane	0.5	ND	ND	ND	ND	ND	ND
1,2-Dibromo-3-chloropropar	ne 10	ND	ND	ND	ND	ND	ND
Dibromomethane	0.5	ND	ND	ND	ND	ND	ND
1,2-Dichlorobenzene	0.5	ND	ND	ND	ND	ND	ND:
1,3-Dichlorobenzene	0.5	ND	ND	ND	ND	ND	ND
1,4-Dichlorobenzene	0.5	ND	ND	ND	ND	ND	ND .
Dichlorodifluoromethane	0.5	ND	ND	ND	ND	ND	ND
1,1-Dichloroethane	0.5	ND	ND	ND	ND	8.2	ND
1,2-Dichloroethane	0.5	ND	ND	8.8	ND	ND	ND
1,1-Dichloroethene	0.5	ND	ND	ND	ND	6.2	ND
cis-1,2-Dichloroethene	0.5	ND	ND	ND	ND	57	ND
trans-1,2-Dichloroethene	0.5	ND	ND	ND	ND	8.0	ND
1,2-Dichloropropane	0.5	ND	ND	ND	ND	ND	ND
1,3-Dichloropropane	0.5	ND	ND	ND	ND	ND	ND
2,2-Dichloropropane	0.5	ND	ND	ND	ND	ND	ND
1,1-Dichloropropene	0.5	ND	ND	ND	ND	ND	ND



Client:

PSI

. Project:

CT J&A Truck/Container Freight

Job No.:

16393

Matrix: Analyst: Water **JMR**

Date Sampled:

Date Received:

05/02/00 05/03/00

Date Analyzed:

05/04-12/00

Batch Number:

M4S8260W2096

	Sample ID:	Blank	JA-1	JA-2	JA-3	JA-4	CF-2
Compounds	DL	μg/L	μ g/ L	μg/L	μg/L	μg/L	μg/L
cis-1,3-Dichloropropene	0.5	ND	ND	ND	ND	ND	ND
trans-1,3-Dichtoropropene	0.5	ND	ND	ND	ND	ND	ND
Diisopropyl Ether (DIPE)	5.0	ND	ND	ND	ND	ND	ND
Ethylbenzene	0,5	ND	ND	ND	ND	ND	12
Ethyl tert-Butyl Ether (EtBE)	5.0	ND	ND	ND	ND	ND	. ND
Hexachlorobutadiene	0.5	ND	, ND	ND	ND	ND	ND
2-Hexanone	10	ND	ND	ND	ND	ND	ND
tsopropylbenzene	0.5	ND	NĐ	ND	ND	· · ND · ·	ON
p-Isopropyltoluene	0.5	ND	ND	ND	ND	ND	ND
Methylene chloride	20	ND	ND .	ND	ND	ND	ND
4-Methyl-2-pentanone	5.0	ND	ND	ND	ND .	ND	ND
Methyl-tert-butyl ether (MtSI	E) 1.0	ND	ND	ND	ND	ND	ND
Napthalene	0.5	ND	8.3	8.3	2.4	1.3	2,900
n-Propylbenzene	0.5	ND	ND	ND	ND	ND	ND
Styrene	0.5	ND	ND	ND	ND	ND	8.0
1,1,1,2-Tetrachloroethane	0.5	ND	ND	ND	ND	ND	ND
1,1,2,2-Tetrachloroethane	1.0	ND	ND	ND	ND	ND	ND
Tetrachloroethene	0.5	ND	ND .	ND	ND	130	ND
Toluene	0.5	ND	ND	ND	ND	ND	10 -
1,2,3-Trichlorobenzene	0.5	ND	ND	ND	ON NO	ND	ND
1,2,4-Trichlorobenzene	0.5	ND	ND	ND	ND	ND	ND
1,1,1-Trichloroethane	0.5	ND	ND	ND	/ ND	4.2	ND
1,1,2-Trichloroethane	0.5	ND	ND	ND	ND	0.6	ND
Trichloroethene	0.5	ND	ND	0.7	ND	630	ND
1,2,3-Trichloropropane	0.5	ND	ND	ND	ND	ND	ND .
Trichlorofluoromethane	0.5	ND	ND	ND	ND	ND	ND
Trichlorotrifluoroethane	5.0	ND	ND	ND	ND	7.5	ND
1,2,4-Trimethylbenzene	0.5	ND	ND	ND	ND:	ND	1.4
1,3,5-Trimethylbenzene	0.5	ND	ND	ND	ND	ND	ND
Vinyl chloride	0.5	ND	ND	ND	ND	1,1	ND
Xylenes (total)	1.5	ND	ND	ND	ND	ND	11

Surrogates (% recovery) Limits: 80 - 130

	Sample ID:	Blank	JA-1	JA-2	JA-3	JA-4	CF-2
Dibromofluoromethane	tage a set	106	107	108	107	104	112
Toluene-d8		104	106	107	105	105	112
Bromofluorobenzene		102	100	101	101	101	98



Client:

PSI

Project:

CT J&A Truck/Container Freight

Job No.:

16393

Matrix: Analyst: Water JMR

Date Sampled:

05/02/00 05/03/00

Date Received: Date Analyzed:

05/04-12/00

Batch Number:

M4S8260W2096

	Sample ID:	CF-3
Compounds	DL.	μg/L
Acetone	50	ND
tert-Amyl Methyl Ether (TAM	E) 5.0	ND
Benzene	0.5	0.9
Bromobenzene	1,0	ND
Bromochloromethane	1.0	ND
Bromodichloromethane	0,5	ND
Bromoform	0.5	ND
Bromomethane	0.5	ND
tert-Butanol (TBA)	50	ND
2-Butanone (MEK)	10	ND
n-Butylbenzene	0.5	ND
sec-Butylbenzene	0.5	ND
tert-Butylbenzene	0.5	, ND
Carbon disulfide	10	ND
Carbon tetrachloride	0.5	ND
Chlorobenzene	0.5	ND
Chloroethane	0.5	ND
Chloroform	0.5	NO
Chloromethane	0.5	ND
2-Chlorotoluene	0.5	ND
4-Chlorotoluene	0.5	ND
Dibromochloromethane	0.5	
1,2-Dibromoethane	0.5	ND
1,2-Dibromo-3-chloropropar	ne 10	
Dibromomethane	0.5	ND
1,2-Dichlorobenzene	0.5	ND:
1,3-Dichlorobenzene	0.5	ND ·
1,4-Dichlorobenzene	0.5	~~ (ND) 설계에 관심한 말을 수십시다. 사람들은 사이트 하셨다면요. The Color
Dichlorodifluoromethane	0.5	ND .
1,1-Dichloroethane	0.5	
1,2-Dichloroethane	0.5	ND
1,1-Dichloroethene	0.5	ND to the first of the second
cis-1,2-Dichloroethene	0.5	ND
trans-1,2-Dichloroethene	0.5	
1,2-Dichloropropane	0.5	ND
1,3-Dichloropropane	0.5	A ND CONTRACTOR OF THE CONTRAC
2,2-Dichloropropane	0.5	ND
1,1-Dichloropropene	0.5	ND



Client:

PSI

Project: CT J&A Truck/Container Freight

Job No.:

Matrix: Analyst: 16393

. Water JMR

Date Sampled:

05/02/00

Date Received:

05/03/00

Date Analyzed:

05/04-12/00

Batch Number: .

M4S8260W2096

	Sample ID:	CF-3	
Compounds	DL	μ g/L	
cis-1,3-Dichloropropene	0.5	ND	
trans-1,3-Dichloropropene	0.5	ND.	
Diisopropyl Ether (DIPE)	5.0	ND	
Ethylbenzene	0.5	* ND	
Ethyl tert-Butyl Ether (EtBE)	5.0	ND	
Hexachtorobutadiene	0.5	ND	
2-Hexanone	10	ND	
Isopropylbenzene	0_5	ND	
p-isopropyltoluene	0.5	ND	
Methylene chloride	20	ND	
4-Methyl-2-pentanone	5.0	ND	
Methyl-tert-butyl ether (MtBE	E) 1.0	ND	
Napthalene	0.5	1.7	
n-Propylbenzene	0.5	ND	
Styrene	0.5	ND	
1, 1, 1, 2-Tetrachloroethane	0.5	ND	유통 경우는 바로 가는 가는 것이 되었다. 이 경우를 가지 않는 것이다.
1,1,2,2-Tetrachloroethane	1.0	ND	
Tetrachloroethene	0.5	ND	#####################################
Toluene	0.5	ND	
1,2,3-Trichlorobenzene	0.5	ND	
1,2,4-Trichlorobenzene	0.5	ND	
1,1,1-Trichloroethane	0.5	ND	
1,1,2-Trichloroethane	0.5	ND	
Trichloroethene	0.5	ND	
1,2,3-Trichloropropane	0.5	ND	
Trichiorofluoromethane	0.5	ND	
Trichlorotrifluoroethane	5.0	ND	
1,2,4-Trimethylbenzene	0.5	ND	
1,3,5-Trimethylbenzene	0.5	ND	
Vinyl chloride	0.5	ND	16 · 보통 : 16 · 16 · 16 · 16 · 16 · 16 · 16 · 16
Xylenes (total)	1.5	ND	

Surrogates (% recovery) Limits: 80 - 130

	Sample ID:	CF-3	
Dibromofluoromethane	4	107	
Toluene-d8		109	
Bromofluorobenzene		98	



Client:

PSI

Project:

CT J&A Truck/Container Freight

Job No.: Matrix: 16393 Water

JMR

Analyst:

6303

Date Sampled: Date Received:

05/02/00 05/03/00

Date Analyzed:

05/04-12/00

Batch Number: N

M4S8260W2096

	Sample ID:	CF-10	
Compounds	DL	μg/L	
Acetone	1250	ND	
tert-Amyl Methyl Ether (TAM	E) 125	ND	
Benzene	13	270	
Bromobenzene	25	ND:	
Bromochloromethane	25	ND	
Bromodichloromethane	13	ND:	
Bromoform	13	ND	
Bromomethane	13	**ND	
tert-Butanoi (TBA)	1250	ND	
2-Butanone (MEK)	250	ND	
n-Butylbenzene	13	ND	
sec-Butylbenzene	13	ND	
tert-Butylbenzene	13	ND	
Carbon disulfide	250	ND	
Carbon tetrachloride	13	ND	
Chlorobenzene	13	ND	
Chloroethane	13	ND	
Chloroform	13	ND	
Chloromethane	13∙	ND	
2-Chlorotoluene	13	ND	
4-Chlorotoluene	13	ND	
Dibromochloromethane	13	ND	
1,2-Dibromoethane	13	ND ·	
1,2-Dibromo-3-chloropropar	ne 250		
Dibromomethane	13	ND	
1,2-Dichlorobenzene	13		
1,3-Dichlorobenzene	13	ND	
1,4-Dichlorobenzene	13	H ND THE PROPERTY OF THE PROPE	
Dichlorodifluoromethane	13	ND	
1,1-Dichloroethane	13	NO	
1,2-Dichloroethane	13	ND	
1,1-Dichloroethene	13		
cis-1,2-Dichloroethene	13	ND	
trans-1,2-Dichloroethene	13	ND	•
1,2-Dichloropropane	13	ND .	
1,3-Dichloropropane	13	ND:	
2,2-Dichloropropane	13	ND	•
1,1-Dichloropropene	13	ND	·



Client: PSI

Project: CT J&A Truck/Container Freight

Job No.; Matrix: 16393 Water

Analyst: JMR

Date Sampled: Date Received: 05/02/00 05/03/00

Date Analyzed:

05/04-12/00

Batch Number: M4S8260W2096

	Sample ID:	CF-10					•.		
Compounds	DL.	μg/L							
cis-1,3-Dichloropropene	13	ND							
trans-1,3-Dichloropropene	13	ND		Lari Nesseri. Sur Deserti. Lesses especialis	National Control	l terro a la . Li casa di Si		100 AV 100 AV	
Diisopropyl Ether (DIPE)	125	ND				eviner versions s	2011-000-1-111	. 1000 200 200 1	1.001.44.50
Ethylbenzene	13	13		der Greener 1 St. Frank 1984				a a formata i da n Signal ya nya nya m	
Ethyl tert-Butyl Ether (EtBE)	125	ND	* .				• • • • •		
Hexachlorobutadiene	13	ND			,4,43000 (00) , 3,43000 (00)	0.9900000999 0.9800988		21,200 0800000 80 06860 805 8	region brasile.
2-Hexanone	250	NĎ		٠.					
Isopropylbenzene	13	ND							
p-isopropyltoluene	13	ND		٠.					
Methylene chloride	500	ND							1.143
4-Methyl-2-pentanone	125	ND						:	
Methyl-tert-butyl ether (MtBE	≣) 25	. ND							
Napthalene	13	1,600							
n-Propylbenzene	13	ND							
Styrene	13	ND							
1,1,1,2-Tetrachloroethane	13	ND						1801. T 302 Miles	
1,1,2,2-Tetrachloroethane	25	ND							
Tetrachtoroethene	13	ND			mari	19518			
Toluene	13	14							
1,2,3-Trichlorobenzene	13	ND						·	
1,2,4-Trichlorobenzene	13	ND							
1,1,1-Trichloroethane	13	ND					New York	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	
1,1,2-Trichloroethane	13	ND							
Trichloroethene	13	ND						415.55	
1,2,3-Trichloropropane	13	ND		. 9					
Trichlorofluoromethane	13	ND		144.6	445.4	ta de			
Trichlorotrifluoroethane	125	ND							
1,2,4-Trimethylbenzene	13	ND		11 NI V		12	41.		•
1,3,5-Trimethylbenzene	13	ND							
Vinyl chloride	.13	ND	No.		* *		•	•	
Xylenes (total)	38	ND							

Surrogates (% recovery) Limits: 80 - 130

-	Sample ID: CF-10	
Dibromoffuoromethane	A company 10,1 Terminal production of the company	
Toluene-d8	109	
Bromofluorobenzene	101	



Client:

PSI 1

Project:

Job No.:

16393

Matrix: Analyst: CT J&A Truck/Container Freight

Water JMR · Date Sampled:

05/02/00

Date Received: Date Analyzed: 05/03/00 05/04-12/00

Batch Number: M4S8260W2096

	Sample ID:	CF-1
Compounds	DL	μg/L
Acetone	5000	ND
tert-Amyl Methyl Ether (T.	AME) 500	ND
Benzene	- 50	34,000
Bromobenzene	100	ND
Bromochloromethane	- 100	ND
Bromodichloromethane	50	ND
Bromoform	50	ND
Bromomethane	50	ND
tert-Butanol (TBA)	5000	ND.
2-Butanone (MEK)	1000	ND
n-Butylbenzene	50	ND
sec-Butylbenzene	50	NO
tert-Butylbenzene	50	ND
Carbon disulfide	1000	ND
Carbon tetrachloride	50	ND
Chlorobenzene	50	
Chloroethane	50	ND
Chloroform	50	ND
Chloromethane	50	ND
2-Chlorotoluene	50	
4-Chlorotoluene	50	ND
Dibromochloromethane	50	
1,2-Dibromoethane	50	n de com antende en mande en de estada de estada de la composição de la composição de la composição de la comp ND
1,2-Dibromo-3-chloropro	pane 1000	THE NO. THE PROPERTY OF THE PR
Dibromomethane	50	nter travalente da la compania de la compania de la compania de la compania de la compania de la compania de l ND
1,2-Dichlorobenzene	50	
1,3-Dichlorobenzene	50	ND
1,4-Dichlorobenzene	50	READATES AND A CARREST AND A SECOND
Dichlorodifluoromethane	50	ND
1,1-Dichloroethane	50	THE NOW THE PROPERTY OF THE PR
1,2-Dichloroethane	50	ND
1,1-Dichloroethene	50	
cis-1,2-Dichloroethene	50	ND
trans-1,2-Dichloroethene		ND THE THE RESERVE THE PROPERTY OF THE PROPERT
1,2-Dichloropropane	50	ND
1,3-Dichloropropane	50	ND NO NO NO NO NO NO NO NO NO NO NO NO NO
2,2-Dichloropropane	50	ND
1,1-Dichloropropene	50	ND



Client: PSI
Project: CT J&A Truck/Container Freight

Job No.: 16393 Matrix: Water Analyst: JMR

 Date Sampled:
 05/02/00

 Date Received:
 05/03/00

 Date Analyzed:
 05/04-12/00

 Batch Number:
 M4\$8260W2096

	Sample ID:	CF-1	
Compounds	DL	μg/L	
cis-1,3-Dichloropropene	- 50	ND	
trans-1,3-Dichloropropene	50	ND	
Diisopropyl Ether (DIPE)	500	ND	
Ethylbenzene	50	340	
Ethyl tert-Butyl Ether (EtBE) 500	ND	
Hexachlorobutadiene	50	ŇD	
2-Hexanone	1000	ND	Andrews Andrews Section in Missing State (MISSING STATES OF A SECTION AND AND AND AND AND AND AND AND AND AN
Isopropyibenzene	50	ND	
p-isopropyltoluene	50	ND	
Methylene chlaride	2000	NO	
4-Methyl-2-pentanone .	500	· ND	Harman seed taken ka manada makan mara Marika a ka maran ka ka ka ka ka ka ka ka ka ka ka ka ka
Methyl-tert-butyl ether (MtB	E) 100	ND	
Napthalene	50	19,000	
n-Propylbenzene	50	. ND	
Styrene	50	590	
1,1,1,2-Tetrachloroethane	50	מא	
1,1,2,2-Tetrachloroethane	100	ND	
Tetrachloroethene	50	ND	望起奔露,身边是一块一点,像多是大大。 ———————————————————————————————————
Toluene	50	1,600	
1,2,3-Trichlorobenzene	50	ND	· 유리 및 스마트를 가면 그 보고 및 그리고 (Lie) (1986)
1,2,4-Trichlorobenzene	50	ND	
1,1,1-Trichloroethane	50	ND	물통하다 보는 건물 경기에 되었다. 그런 항공의 보통 등 보다 보다는 하다.
1,1,2-Trichloroethane	50	ND	
Trichloroethene	50	190	
1,2,3-Trichloropropane	50	ND	
Trichlorofluoromethane	50	ND .	
Trichlorotrifluoroethane	500	ND	
1,2,4-Trimethylbenzene	50	ND	
1,3,5-Trimethylbenzene	50	ND	
Vinyl chloride	50	ND	
Xylenes (total)	150	ND	

Surrogates (% recovery) Limits: 80 - 130

Garrogates (70 1000 vc	19) Liitita. 00	- 130			
	Sample ID:	CF-1			
Dibromofluoromethane		110			
Toluene-d8		115		÷	
Bromofluorobenzene		98	•		

QC Sample Report - EPA Method 8260

Matrix: Water

Batch #: MS48260W2096

Batch Accuracy Results

Sample ID	: Laborator	y Control Sample
-----------	-------------	------------------

Analyte	Spike Concentration μg/L	% Recovery LCS	Acceptance Limits % Recovery	Pass/Fail
1,1-Dichloroethene	20	113	59 - 172	Pass
Benzene	20	122	66 - 142	Pass
Trichloroethene	20	120	71 - 137	Pass
Toluene	20	113	59 - 139	Pass
Chiorobenzene	20	96	60 - 133	Pass

Analytical Notes:

1

Batch Precision Results

MS/MSD Sample ID: Laboratory Control Sample

Analyte	Spike Sample Recovery µg/L	Spike Duplicate Recovery µg/L	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass/Fail
1,1-Dichloroethene	22.7	24.5	8%	22%	Pass
Benzene	24.4	26.4	8%	21%	Pass
Trichtoroethene	23.9	25.0	4%	24%	Pass
Toluene	22.8	24.6	8%	21%	Pass
Chlorobenzene	19.2	21.2	10%	21%	Pass

MS: Matrix Spike Sample
MSD: Matrix Spike Duplicate

Analytical Notes:



Client: PSI Date Sampled: 05/02/00 Project: CT J&A Truck/Container Freight Date Received: 05/03/00 Job No.: 16393 Date Extracted: 05/05/00 Matrix: Water Dates Analyzed: 05/06-08/00 Analyst: TPW Batch Number: 8270W0622

<u></u>	Sample ID:	Blank	JA-1	JA-2	JA-3	JA-4	
Compound	DL	mg/L	mg/L	mg/L	mg/L	mg/L	
Acenaphthene	0.0011	ND	ND	ND	ND	ND .	
Acenaphthylene	0.0011	ND	ND	ND	ND .	ND	
Anthracene	0.0011	ND	ND	ND	ND	ND	resignation of the
Benzo(ajanthracene	0.0022	ND	ND	ND	ND	ND	
Benzo[a]pyrene	0.0022	ND	ND	ND	ND	ND	
Benzo[b]fluoranthene	0.0011	ND.	ND	ND	ND	ND	
Benzo[g,h,i]perylene	0.0033	ND	ND	ND	ND	ND	1 6 4 20 mg - 1 1 2 mg
Benzo(k)fluoranthene	0:0011	ND	ND	ND	ND	ND	
Benzyl alcohol	0.0044	ND	ND .	ND	ND	ND	, marka e i i romi
bis(2-Chloroethoxy)metha	ine 0.0022	ND	. ND	ND	ND	NO	
bis(2-Chloroethyl)ether	0.0022	ND	ND	ND	ND	ND	* . 1 · · · · · · · · · · · · · · · · · ·
bis(2-Chloroisopropyl)ethi	er 0.0033	ND	ND	ND	ND ,	ND	
bis(2-Ethylhexyl)phthalate	0.011	ND	ND	ND	ND	ND	e Millia (di Propositionia) Tra
4-Bromophenylphenylethe	er 0.0011	ND	ND	ND	ND	ND	e and section
Butylbenzylphthalate	0.0011	ND	ND	ND	ND	ND	
4-Chloro-3-methylphenol	0.0055	ND	ND	ND	ND	ND	n ng sa 1992. Malakaran sa ka
4-Chloroaniline	0.0055	ND	ND	ND	ND	ND	
2-Chloronaphthalene	0.0011	ND	ND	ND	ND	ND	
2-Chlorophenol	0.0044	ND	ND	ND	ND	ND	13.11.39
4-Chlorophenylphenylethe	er 0.0011	ND	ND	ND	ND	ND	
Chrysene	0.0011	ND	ND	ND	ND	ND	
Di-n-butylphthalate	0.011	ND	ND	ND	ND	ND	
Di-n-octylphthalate	0.0011	ND	ND	ND	ND	ND	
Dibenzo[a,h]anthracene	0.0033	ND	ND	ND	ND	ND	
Dibenzofuran	0.0011	ND	ND	ND	ND	ND	
1,2-Dichlorobenzene	0.0011	ND	ND	ND	ND	ND	
1,3-Dichlorobenzene	0.0011	ND	ND	ND	ND	ND	
1,4-Dichlorobenzene	0.0011	ND	ND	ND.	ND	ND :	
3,3-Dichlorobenzidine	0.0044	ND	ND	ND	ND	ND	
2,4-Dichlorophenol	0.0055	ND	ND	ND	ND	ND	
Diethylphthalate	0.011	ND	ND	ND	ND	ND	
2,4-Dimethylphenol	0.0033	ND	ND	ND	ND	ND	
Dimethylphthalate	0.0011	ND	ND	ND	ND	ND	
4,6-Dinitro-2-methylpheno		ND	ND	ND	ND	ND ND	
2,4-Dinitrophenol	0.055	ND	ND	ND	ND	ND	
2,4-Dinitrotoluene	0.0011	ND:	ND	ND	ND	ND	



Client PSI 05/02/00. Date Sampled: Project: CT J&A Truck/Container Freight Date Received: 05/03/00 Job No.: 16393 Date Extracted: 05/05/00: Matrix: Water Dates Analyzed: 05/06-08/00 Analyst: **TPW** Batch Number: 8270W0622

	Sample ID:	Blank	JA-1	JA-2	JA-3	JA-4	* .
Compound	DL	mg/L	mg/L	mg/L	mg/L	mg/L	• .
2,6-Dinitrotoluene	0.0033	ND	ND	, ND	ND	ND	
Fluoranthene	0.0011	ND.	ON .	ND	ND	ND	
Fluorene	0.0011	ND	ND	ND	ND	ND	
Hexachlorobenzene	0.0011	ND	ND	ND	ND	ND '	
Hexachlorobutadiene	0.0011	ND	ND	ND	ND	ND	
Hexachlorocyclopentadien	ne 0.055	ND	+ ND	ND	ND	ND	
Hexachloroethane	0.0011	ND	ND.	ND	ND	ND	
Indeno[1,2,3-cd]pyrene	0.0044	ND	ND	ND	ND	ND	
Isophorone	0.0011	ND	ND	ND	ND	ND	
2-Methylnaphthalene	0.0011	ND	ND	ND	ND	NO	
2-Methylphenol	0.0055	ND	ND	ND	ND	. ND	
4-Methylphenol	0.0055	ND	ND -	ND	ND	ND	
N-Nitroso-di-n-propylamin	ne 0.0011	ND	ND	ND	ND	ND	
N-Nitrosodiphenylamine	0.0011	ND	ND	ND	ND	ND	
Naphthalene	0.0011	ND	0.002	ND	ND	ND	
2-Nitroaniline	0.0033	ND	ND	ND	ND	ND	
3-Nitroaniline	0.0033	ND	ND	ND	ND	ND	
4-Nitroaniline	0.011	ND	ND	ND	ND	ND	
Nitrobenzene	0.0033	ND	ND	ND	ND	ND	
2-Nitrophenol	0.0044	ND	ND	ND	ND	ND	
4-Nitrophenol	0.011	DN	ND	ND	ND	ND	
Pentachlorophenol	0.055	ND	ND	ND	ND	ND	
Phenanthrene	0.0022	ND	ND	ND	ND	ND	
Phenol	0.0044	ND	ND	ND	ND	NO	
Pyrene	0.0011	ND	ND	ND	ND	ND	
1,2,4-Trichlorobenzene	0.0011	ND	ND	ND	ND	ND	
2,4,5-Trichlorophenol	0.0066	ND	ND	ND	ND	ND	
2,4,6-Trichlorophenol	0.011	ND	ND	ND	ND	ND	

Surrogates (Limits) in Percent Recovery

Sample ID:	Blank	JA-1	JA-2	JA-3	JA-4	
2-Fluorophenol (21 - 100%)	104	52	59	59	52	
Phenol-D5 (10 - 94%)	82	34	38	39	34	
Nitrobenzene-D5 (35 - 114%)	108	62	60	60	59	
2-Fluorobiphenyl (43 - 116%)	90	72	75	71	69	
2,4,6-Tribromophenal (10 - 123%)	97	82	103	96	89	
p-Terphenyl-D14 (33 - 141%)	108	85	90	88	85	



Client; PSI Date Sampled: 05/02/00 Project: CT J&A Truck/Container Freight Date Received: 05/03/00 Job No.: 16393 Date Extracted: 05/05/00 Matrix: Water Dates Analyzed: 05/06-08/00 Batch Number: Analyst: 8270W0622

	Sample ID:	Blank	CF-1	CF-2	CF-3	CF-10	
Compound	DL	mg/L	mg/L	mg/L	mg/L	mg/L	-
Acenaphthene	0.001	ND	800.0	0.004	ND	0.004	
Acenaphthylene	0,001	ND	ND	0.069	ND	0.031	
Anthracene	0.001	ND	0.006	0.007	0.001	0.006	
Benzo[a]anthracene	0.002	ND	ND	ND	0.004	ND	
Benzo(a)pyrene	0.002	ND	ND	0.003	800.0	0.002	
Benzo[b]fluoranthene	0.001	ND :	ND	0.003	0.010	0.003	
Benzo[g,h,i]perylene	0.003	ND	ND	ND	0.009	ND	
Benzo[k]fluoranthene	0.001	ND	ND	0.003	0.010	0.003	
Benzyl alcohol	0.004	ND	ND	ND	ND	ND	
bis(2-Chloroethoxy)metha	ne 0.002	ND	ND	ND		ND	
bis(2-Chloroethyl)ether	0.002	ND	ND	ND	ND	ND	
bis(2-Chloroisopropyl)eth	er 0.003	ND	ND	ND	ND	ND	
bis(2-Ethylhexyl)phthalate	0.01	. ND	ND	ND	ND	МD	,
4-Bromophenylphenylethe	er 0.001	ND	ND	ND	ND	ND	
Butylbenzylphthalate	0.001	ND	ND	ND	ND	ND	
4-Chloro-3-methylphenol	0.005	ND	ND	ND	ND	ND	
4-Chloroaniline	0.005	ND	ND	ND	ND	ND .	
2-Chloronaphthalene	0.001	ŇD	GN	ND	ND	ND	
2-Chlorophenol	0.004	ND	ND	ND	ND	ND	
4-Chlorophenylphenylethe	er 0.001	ND	ND	ND	ND	ND	
Chrysene	0.001	ND	ND	0.003	0.006	0.002	
Di-n-butylphthalate	0.01	ND	ND	ND	ND	ND	
Di-n-octylphthalate	0.001	ND	ND	ND	ND	ND	
Dibenzo[a,h]anthracene	0.003	ND	ND	ND	ND	ND	,
Dibenzofuran	0.001	ND	0.003	0.003	ND	0.003	
1,2-Dichlorobenzene	0.001	ND	ND	ND	NO	ND	
1,3-Dichlorobenzene	0.001	ND	ND	ND	ND	ND	
1,4-Dichlorobenzene	0.001	ND	ND	ND	D D	ND	
3,3-Dichlorobenzidine	0.004	ND	ND	ND	ND	ND	** *
2,4-Dichlorophenol	0.005	ND	ND	ND	ND	ND	
Diethylphthalate	0.01	ND	ND	ND	ND	ND	
2,4-Dimethylphenal	0.003	ND	ND	ND	ND	ND	e.
Dimethylphthalate	0.001	ND	ND	ND	ND	ND	
4,6-Dinitro-2-methylphen		ND	ND	ND	ND	ND	
2,4-Dinitrophenol	0.05	ND	ND	ND	ND	ND	
2,4-Dinitrotoluene	0.001	ND	ND	ND	ND	ND	



Client: PSI Date Sampled: 05/02/00 Project: CT J&A Truck/Container Freight Date Received: 05/03/00 Job No.: 16393 Date Extracted: 05/05/00 Matrix: Water Dates Analyzed: 05/06-08/00 Analyst: TPW Batch Number: 8270W0622

	Sample ID:	Blank	CF-1	CF-2	CF-3	CF-10	
Compound	DL	mg/L	mg/L	mg/L	mg/L	mg/L	
2,6-Dinitrotoluene	0.003	ND	ND	ND	ND	ND	
Fluoranthene	0,001	ND	0.007	0.014	0.012	0.011	
Fluorene	.0.001	ND	0.013	0.016	ND	0.014	1 6 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Hexachlorobenzene	0.001	ND	ND	ND	ND	ND	
Hexachlorobutadiene .	0.001	ND	ND	ND	ND	ND	The second section of the section of the section of the second section of the section of t
Hexachlorocyclopentadien	e 0.05	ND	ND	ND	ND	ND	
Hexachloroethane	0.001	ND	ND	ND	ND	ND	ering the property of the
Indeno[1,2,3-cd]pyrene	0.004	NO	ND	ND	0.006	ND	
Isophorone	0.001	ND	ND	ND	ND	ND	
2-Methylnaphthalene	0.001	ND	0.067	0.022	ND	0.008	
2-Methylphenol	0.005	ND	ND	ND	ND	ND	
4-Methylphenol	0.005	ND	ND	0.17	ND	0.041	
N-Nitroso-di-n-propylamin	e 0.001	ND	ND	ND	ND	ND	
N-Nitrosodiphenylamine	0.001	ND	ND	ND	ND	ND	4954257
Naphthalene	0.001	ND	5.5	1.2	0.007	0.52	
2-Nitroaniline	0.003	ND	ND	ND	ND	ND	
3-Nitroaniline	0.003	ND	ND	ND	ND	ND	
4-Nitroaniline	0.01	ND	ND	ND	ND	NO	
Nitrobenzene	0.003	ND	ND	ND	ND	ND	
2-Nitrophenol	0,004	ND	ND	ND	ND	ND	3. 其数4.5 L3
4-Nitrophenol	0.01	ND	ND	ND	ND	ND	· · · · · ·
Pentachlorophenol	0.05	ND	ND	ND	ND	ND	
Phenanthrene	0.002	ND	0.055	0.048	0.004	0.033	eelet el.
Phenol	0.004	ND	0.024	0.046	ND	0.011	
Pyrene	0.001	ND	0.011	0.018	0.016	0.013	***
1,2,4-Trichlorobenzene	0.001	ND	ND	ND	ND	ND	
2,4,5-Trichlorophenol	0.006	ND	ND	ND	ND	ND	
2,4,6-Trichlorophenol	0.01	ND	ND	ND	ND	ND	

Surrogates (Limits) in Percent Recovery

Sample ID:	Blank	CF-1	CF-2	CF-3	CF-10	
2-Fluorophenol (21 - 100%)	104	30	59	37	49	
Phenol-D5 (10 - 94%)	82	40	40	25	37	
Nitrobenzene-D5 (35 - 114%)	108	38	65	39	51	
2-Fluorobiphenyl (43 - 116%)	90	59	64	62	56	
2,4,6-Tribromophenol (10 - 123%)	97	32	- 89	40	79	
p-Terphenyl-D14 (33 - 141%)	108	44	83	67	72	



QC Sample Report - EPA 8270

Batch #: 8270W0622

Matrix: Water

Batch Accuracy Results

Sample ID: Laboratory Contr	<u>of Sample</u>)		
Analyte	Spike Concentration μg/L	% Recovery LCS	Acceptance Limits % Recovery	Pass/Fail
Phenol	80	43	5 - 112	Pass
2-Chlorophenol	80	106	23 - 134	Pass
1,4-Dichlorobenzene	40	94	20 - 124	Pass
N-Nitrosodi-n-propylamine	40	79	0 - 230	Pass
1,2,4-Trichlorobenzene	40	83	44 - 142	Pass
4-Chloro-3-Methylphenol	80	84	22 - 147	Pass
Acenaphthene-	40	84	47 - 145	Pass
4-Nitrophenol	80	48	0 - 132	Pass
2,4-Dinitrotoluene	40	88	39 - 139	Pass
Pentachlorophenol	80	132	14 - 176	Pass
Pyrene	40	103	52 - 115	Pass

Batch Precision Results

MS/MSD Sample ID: Laboratory Control Sample

Analyte	Spike Sample Recovery µg/L	Spike Duplicate Recovery µg/L	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass/Fail
Phenol	34.7	31.8	9%	35%	Pass
2-Chlorophenol	85.2	75.5	12%	50%	Pass
1,4-Dichlorobenzene	37.4	34.3	9%	27%	Pass
N-Nitrosodi-n-propylamine	31.8	29.8	6%	38%	Pass
1,2,4-Trichlorobenzene	33.3	35.8	7%	28%	Pass
4-Chloro-3-Methylphenol	66.9	73.0	9%	33%	Pass
Acenaphthene	33.7	33.9	1%	23%	Pass
4-Nitrophenol	29.7	37.8	24%	50%	Pass
2,4-Dinitrotoluene	35.1	37.9	8%	47%	Pass
Pentachlorophenol	105.7	105.4	0%	47%	Pass
Pyrene	41.2	41.1	0%	36%	Pass

		-	
٠.		10	
	3		

Analytical Notes:

Analytical N	atac:



Centrum Analytical Laboratories, Inc.

CERTIFIED HAZARDOUS WASTE TESTING LABORATORY . CHEMICAL AND BIOLOGICAL ANALYSES

Client: PSI

1320 W. Winton Ave.

Hayward, CA 94545

Date Sampled:

04/26/00

Date Received:

04/28/00

Job Number:

16373

Project: Caltrans - J&A Trucking

CASE NARRATIVE

The following information applies to samples which were received on 04/28/00:

The samples were received at the laboratory chilled and sample containers were intact.

This report is being re-issued at the request of our client. There have been no changes in the results as previously reported. The date of re-issue is 06/14/00.

Unless otherwise noted below, the Quality Control acceptance criteria were met for all samples for every analysis requested.

Report approved by:

Robert R. Clark, Ph.D.

Laboratory Director

ELAP # 2419

DL: Detection Limit -- The lowest level at which the compound can reliably be detected under normal laboratory conditions.

ND: Not Detected -- The compound was analyzed for but was not found to be present at or above the detection limit.

NA: Not Analyzed -- Per client request, this analyte was not on the list of compounds to be analyzed for.



Metals

Client: PSI

Project: Caltrans - J&A Trucking

Job No: 16373 Matrix: Soil Analyst: RLB/TLR Date Sampled: 04/26/00

Date Received: 04/28/00

Date Digested: 05/01/00

Date Analyzed: 05/02-06/00

Batch Number 6010S1551

	•	Sample ID:	Blank	JA1-7.0	JA2-7.0	JA3-7.0	JA4-6.5	
Element	Method #	DL	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg	
Antimony	6010	2.5	ND	ND	· ND · .	ND	ND	
Arsenic	6010	0.50	ND	2.1	2.5	3.0	2.4	
Barium	6010	0.50	ND	37	47	47	56	
Beryllium	6010	0,50	ND .	ND	.ND	ND	ND	
Cadmium	6010	0.50	ND	ND	ND	ND ·	ND	
Chromium	6010	0.50	ND	30	35	38	48	
Cobalt	6010	0.50	ND	4.6	5.3	5.6	5.8	
Copper	6010	0.50	ND	5,3	6.8	8.4	7.6	
Lead	6010	0.50	ND	1.5	2.0	3.9	2.5	
Mercury	7471	0.10	- ND		• ND	ND	ND	
Molybdenum	6010	0.50	ND	ND	ND	ND	ND	• " "
Nickel	6010	1.0	ND	26	32	32	35	
Selenium	6010	2.5	ND	ND	ND	ND	ND	
Silver	6010	1.0	ND	ND	ND	ND	ND	
Thallium	6010	2.5	ND	ND	ND	ND	ND	
Vanadium	6010	0.5	ND	21	27	29	30	
Zinc	6010	10	ND	19	23	25	26	
			o de Salada de la compansión de la compa		randari (1.12) Waliota			



QC Sample Report - Metals

Matrix: Soil

Batch #: 6010S1551

MS/MSD Sample ID: JA1-7.0

	Batch P	recision	Results	; :		Batch A	ccuracy	/ Results:	
Metal	Spike Sample Recovery mg/Kg	Spike Duplicate Recovery mg/Kg	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass / Fail	Spike Concentration mg/Kg	% Recovery LCS	Acceptance Limits Percent Recovery	Pass / Fail
Antimony	52.2	52.0	0%	20%	Pass	50	.112	75 - 125	Pass
Arsenic	51.8	52.0	0%	20%	Pass	50	107	75 - 125	Pass
Barium	85.9	86.4	1%	20%	Pass	50	105	75 - 125	Pass
Beryllium	50.7	52.3	3%	20%	Pass	.50	107	75 - 125	Pass
Cadmium	48.2	48.7	1%	20%	Pass	50	107	75 - 125	Pass
Chromium	79.1	81.5	3%	20%	Pass	50	108	75 - 125	Pass
Cobalt	53.0	53.9	2%	20%	Pass	50	108	75 - 125	Pass
Copper	57,4	58.2	1%	20%	Pass	50	108	75 - 125	Pass
Lead	50.7	50.6	0%	20%	Pass	50	107	75 - 125	Pass
Mercury	2.74	2,80	2%	20%	Pass	2.5	111	75 - 125	Pass
Molybdenum	52.2	52.2	0%	20%	Pass	50	113	75 - 125	Pass
Nickel	75.4	77.7	3%	20%	Pass	50	108	75 - 125	Pass
Selenium	48.1	48.9	2%	20%	Pass	50	103	75 - 125	Pass
Silver	49.1	50.1	2%	20%	Pass	50	104	75 - 125	Pass
Thallium	48.0	48.8	2%	20%	Pass	50	107	75 - 125	Pass
Vanadium	70.3	71.2	1%	20%	Pass	and the first property of the con-	109	75 - 125	Pass
Zinc	69.0	70.1	2%	20%	Pass	50	115	75 - 125	Pass

Anal	vtical	Notes

LCS: Laboratory Control Sample

LCSD: Laboratory Control Sample Duplicate

MS: Matrix Spike

RPD: Relative Percent Difference

MSD: Matrix Spike Duplicate



Modified 8015 - Fuel Screen

Client: PSI
Project: Caltrans - J&A Trucking

Job No.: 16373 Matrix: Soil Analyst: JL Date Sampled: 04/26/00
Date Received: 04/28/00
Date Extracted: 05/01/00
Date Analyzed: 05/01/00
Batch Number: 8015DS1909

	Fuel Identified:	Diesel	Motor Oil	Detection Limits
· · ',	Units:	mg/kg	mg/kg	mg/kg
Blank		ND	ND	10
JA1-7.0	Libertura de la Prima de Caracter Laboración (No. 1990). El macros en contrator de	ND	ND	.10 Hassias et en la construcción son e
JA2-7.0	CANNEL CALLA LACT CLASSANCE EN CASE EN CONSULAR	ND ND	ND	10
JA3-7.0 JA4-6.5	rough, germ, was or or only going the low list from the begin	ND ND	ND ND	10 10
r dirikki halikwi '				
30.00				

QC Sample Report - EPA 8015M Diesel

Matrix: Soil

Batch #: 8015DS1909

Batch Accuracy Results

Analyte	Spike Concentration mg/Kg	% Recovery L	Acceptance Li % Recovery	Pass/Fail
Diesel	100	82	70 - 130	Pass

	Analy	/tica	l Not	es:	•		
	-					-	
		•		٠.			
		•					
ļ	i		,				
			* -				

Batch Precision Results

MS/MSD Sample ID:Laboratory Control Sample

Analyte	Spike Sample Recovery mg/Kg	Spike Duplicate Recovery mg/Kg	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass/Fail
Diesel	82	75	9%	29%	Pass

Analytical Note:	s:	
!		

MS: Matrix Spike Sample MSD: Matrix Spike Duplicate



Modified 8015 - Total Volatile Hydrocarbons as Gasoline

04/26/00 Client: PSI Date Sampled: 04/28/00 Date Received: Caltrans - J&A Trucking Project: 05/01/00 16373 Date Analyzed: Job No.: Batch Number: Matrix: Soil 8015GS2591 CP. Analyst:

	Detection Limit	Petroleum	n Hydrocarbons as Gasoline	**
Sample ID	mg/kg		mg/kg	
Method Blank	0.50		ND	
JA1-7.0	0.50		ND	
JA2-7.0	0.50		ND	
JA3-7.0	0.50		ND	
JA4-6.5	0.50		ND	
nakan di parawan kanan di Kabupatèn Barangan. Manangan di Kabupatèn Barangan di Kabupatèn Barangan di Kabupatèn Barangan Barangan Barangan Barangan Baranga				
) 100 milya 178 in 1884 - 1885 - 1885 - 1886 - 1886 - 1886 - 1886 - 1886 - 1886 - 1886 - 1886 - 1886 - 1886 - 1				
	[1] : 1 전 1 [11] : 1 : 1 : 1 : 1 : 1 : 1 : 1 : 1 : 1			
	erska (filozopiská) oz Affalikov (·····································	in the second of	elet regel
	and the Militer for water or	original (in Light) has been able to		
in the state of th				



QC Sample Report - EPA 8015M Gasoline

Matrix: Soil

Batch #: 8015GS2591

Batch Accuracy Results

Analyte	Spike Concentration mg/Kg	% Recovery LCS	Acceptance Limits % Recovery	Pass/Fail
Gasoline	10.0	100	70 - 130	Pass

Analytical	Notes:	- ``	
		į.	-
	•		
		× 5	
			•
	•		

Batch Precision Results

Analyte	Spike Sample Recovery mg/Kg	Spike Duplicate Recovery mg/Kg	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass/Fail
Gasoline	7.24	7.37	2%	30%	Pass

Analytical Notes.	

MS: Matrix Spike Sample MSD: Matrix Spike Duplicate

MS/MSD Sample ID: 16369-1



EPA 8080 - Organochlorine Pesticides & PCBs

Client: PSI

Project: Caltrans - J&A Trucking

Job No.: 16373 Matrix: Soil Analyst: TPW Date Sampled: 04/26/00
Date Received: 04/28/00
Date Extracted: 05/01/00

Date Extracted: 05/01/00
Date Analyzed: 05/05/00
Batch Number: PESTS0249

	Sample ID:	Blank	JA1-7.0	JA2-7.0	JA3-7.0	JA4-6.5	
Pesticides	DL	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg	
Aldrin	0.001	ND	ND	ND	ND	, ND	
Alpha-BHC	0,001	ND	ND	ND	ND	ND	
Beta-BHC	0.001	ND	ND	ND	ND	ND	
Delta-BHC	0.001	ND	ND	ND	ND	ND	
Gamma-BHC (Lindane)	0.001	ND	ND	ND	ND	ND .	
Chlordane	0.010	ND	ND	ND	ND:	ND ···	
4,4'-DDD	0.002	ND	ND	ND	ND	ND	
4,4'-DDE	0.002	ND	ND	ND	ND	ND	
4,4'-DDT	0.002	ND	ND	ND	ND	ND	
Dieldrin	0.002	ND -	ND	ND	ND	ND	
Endosulfan l	0.001	ND	ND	ND	ND	ND	
Endosulfan II	0,002	ND	ND	ND	ND	ND	
Endosulfan sulfate	0.002	ND	ND	ND	ND	ND	
Endrin	0.002	ND	ND	ND	ND	ND	
Endrin Aldehyde	0.002	ND	ND	ND	ND	ND	
Endrin Ketone	0.010	ND	ND	ND	ND	ND	
Heptachlor	0.001	ND	ND	ND	ND	ND	
Heptachlor Epoxide	0.001	ND	ND	ND	ND	ND	
Methoxychlor	0.010	ND	ND	ND	ND	ND	
Toxaphene	0.020	ND	ND	ND	ND	ND	
PCBs							
Aroclor-1016	0.050	ND	ND	ND	ND	NO	
Aroclor-1221	0.050	ND	ND	ND	ND	ND.	
Aroclor-1232	0.050	ND	ND	ND	ND	ND:	
Aroclor-1242	0.050	ND	ND	ND	ND	ND	
Aroclor-1248	0.050	ND	ND	ND	ND	ND	
Aroclor-1254	0.050	ND	ND	ND	ND	ND	
Arocior-1260	0.050	ND	ND	ND	ND	ND	

Surrogates (% recovery) Limits: 50 - 150

	Sample ID:	Blank	JA1-7.0	JA2-7.0	JA3-7.0	JA4-6.5	
		i dis-				1	*
etrachloro-m-xylene		117	135	118	118	131	
	100000	4115	1.1	The Array		2.5	

QC Sample Report - EPA 8080 Pesticides

(800) 798-9336

Matrix: Soil

Batch #: PESTS0249

Batch Accuracy Results

Sample ID: Laboratory Control Sample							
Analyte	Spike Concentration mg/Kg	% Recovery LCS	Acceptance Limits % Recovery	Pass/Fail			
Lindane	0.0066	90	32 - 127	Pass			
Heptachlor	0.0066	98	34 - 111	Pass			
Aldrin:	0.0066	109	42 - 122	Pass			
Dieldrin	0.026	88	36 - 146	Pass			
Endrin	0.026	102	30 - 147	Pass			
ТООТ	0.026	93	25 - 160	Pass			
Aroclor 1242	0.0667	83	75 - 127	Pass			

Analytical Notes:

Batch Precision Results

MS/MSD Sample ID: Laboratory Control Sample

Analyte	Spike Sample Recovery mg/Kg	Spike Duplicate Recovery mg/Kg	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass/Fail
Lindane	0.0030	0.0028	7%	25%	Pass
Heptachlor	0.0033	0.0036	9%	25%	Pass
Aldrin	0.0036	0.0035	3%	25%	Pass
Dieldrin	0.0117	0.0108	8%	25%	Pass
Endrin	0.0135	0.0117	14%	25%	Pass
DOT	0.0124	0.0112	10%	25%	Pass

MS: Matrix Spike Sample
MSD: Matrix Spike Duplicate

Analytical Notes:

Centrum

(800) 798-9336

Client:

PSI

Project: Caltrans - J&A Trucking

Job No.: 16373 Matrix: Soil Analyst: MBH Date Sampled: Date Received:

04/26/00 04/28/00

Date Analyzed: Batch Number: 05/01/00 M48260S182

	Sample ID:	Blank	JA1-7.0	JA2-7.0	JA3-7.0	JA4-6.5
Compounds	DL	mg/Kg	mg/Kg	. mg/Kg	mg/Kg	mg/Kg
Acetone	0.05	ND	ND	ND	ND	ND
tert-Amyl Methyl Ether (TAN	/E 0.005	ND	ND	ND	ND	\ ND
Benzene	0.001	ND	ND	ND	ND	ND
Bromobenzene	0.005	· ND	NĐ	ND:	ND	ND
Bromochloromethane	0.005	ND	ND	ND	ND	ND
Bromodichloromethane	0.001	ND	NĐ	ND	NO	ND
Bromoform	0.005	ND	ND	. ND	ND	ND
Bromomethane	0.01	ND	ND	ND	ND	ND
tert-Butanol (TBA)	0.05	ND	ND	ND	ND	ND
2-Butanone (MEK)	0.01	ND	NĐ	ND	ND	ND
n-Butylbenzene	0.002	ND	ND	ND	ND	ND
sec-Butylbenzene	0,002	ND	ND	ND	ND	ND
tert-Butylbenzene	0.002	ND	ND	ND	ND	ND
Carbon disulfide	0.01	ND	ND	ND	ND	ND
Carbon tetrachioride	0.001	ND	ND	ND	ND	ND
Chlorobenzene	0.001	ND	ND	ND	ND	ND
Chloroethane	0.005	ND	ND	ND	ND	ND
Chloroform	0.002	ND	ND .	ND	ND .	ND
Chloromethane	0.001	ND	ND	ND	ND	ND
2-Chlorotoluene	0.002	ND	ND	ND	ND	ND
4-Chlorotoluene	0.002	ND	ND	ND	ND	ND
Dibromochloromethane	0.002	ND	ND	ND	ND	ND
1,2-Dibromoethane	0.002	ND	ND	ND	ND	ND
1;2-Dibromo-3-chloropropa	ne 0,01	ND	ND	ND	ND	ND
Dibromomethane	0.001	ND	ND	ND	ND	ND
1,2-Dichlorobenzene	0.001	ND	ND	ND	ND	ND
1,3-Dichlorobenzene	0.002	ND	ND	ND	ND	ND
1,4-Dichlorobenzene	0.002	ND	ND	ND	ND	ND
Dichlorodifluoromethane	0.005	ND	ND	ND	ND	ND
1,1-Dichloroethane	0.001	ND	0.001	ND	0.001	0.001
1,2-Dichloroethane	0.001	ND	ND	ND	ND	ND
1,1-Dichloroethene	0.005	ND	ND	ND	ND	ND
cis-1,2-Dichloroethene	0.002	ND	ND	ND	ND	ND
trans-1,2-Dichloroethene	0.002	ND	ND	ND	ND	ND
1,2-Dichloropropane	0.001	ND	ND	ND	ND	ND
1,3-Dichloropropane	0.001	ND	ND	ND	ND	ND
2,2-Dichloropropane	0.001	ND	ND	ND	ND	ND
1,1-Dichloropropene	0.001	ND.	ND:	ND	ND	ND

Client:

PSI

Project:

Caltrans - J&A Trucking

Job No.: Matrix:

16373

Analyst:

Soil

MBH

Date Sampled:

Date Received:

Date Analyzed:

Batch Number:

04/28/00) 798-9336

05/01/00

M48260S182

	Sample ID:	Blank	JA1-7.0	JA2-7.0	JA3-7.0	JA4-6.5	
Compounds	DL.	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg	
cis-1,3-Dichloropropene	0.001	ND	ND	ND	ND	ND	dimana ao amin'ny faritr'i
trans-1,3-Dichloropropene	0,001	ND	ND	ND	ND	ND	
Diisopropyl Ether (DIPE)	0.005	ND	ND	ND	ND	ND	
Ethylbenzene	0.001	ND	- ND	ND	ND	ND	
Ethyl tert-Butyl Ether (EtBE	0.005	- ND	ND .	ND	ND	ND	
Hexachlorobutadiene	0.001	ND	ND	ND	ND	ND	
2-Hexanone	0.01	ND	ND	ND	ND	ND	
tsopropylbenzene	0.001	ND	ND	ND	ND	ND	
p-Isopropyltoluene	0.002	ND	ND	ND	ND	ND	
Methylene chloride	0.02	ND	NĐ	ND	ND	NO	
4-Methyl-2-pentanone	0.01	ND	ND	ND	ND	ND	
Methyl tert-Butyl Ether (Mtl	BE) 0:005	ND	ND	ND.	ND	ND	
Napthalene	0.002	ND	ND	ND	0.003	0.020	
n-Propylbenzene	0.001	ND	ND	ND	ND	ND	
Styrene	0.001	ND	0.001	0.001	ND	0.001	. •
1,1,1,2-Tetrachloroethane	0.001	ND	NÐ	ND	ND :	ND	
1,1,2,2-Tetrachloroethane	0.002	ND	ND	ND	ND	ND	
Tetrachloroethene	0.001	ND	ND	ND	NĐ	ND	
Toluene	0.001	ND	ND	ND	ND	ND	
1,2,3-Trichlorobenzene	0.002	ND	ND	ND	ND	ND	
1,2,4-Trichlorobenzene	0.002	ND	ND	ND	ND	ND	
1,1,1-Trichloroethane	0.001	ND	0.007	0.005	0.006	0.006	
1,1,2-Trichloroethane	0.003	ND	ND	ND	ND	ND	
Trichloroethene	0.001	ND	ND	NO	ND	DM	Maria de la Companya
1,2,3-Trichloropropane	0.003	ND	ND	ND	ND	ND	•
Trichlorofluoromethane	0.001	ND	ND	ND	ND	ND	
Trichlorotrifluoroethane	0.005	ND	0.008	0.007	0.006	0.007	
1,2,4-Trimethylbenzene	0.001	ND	ON	ND	ND:	ND	
1,3,5-Trimethylbenzene	0.001	ND	ND	ND	ND	ND	
Vinyl chloride	0.002	ND	ПО	ND	ND	ND	
Xylenes (total)	0.003	ND	NO	ND	NĎ	ND	

Surrogates (% recovery) Limits: 80 - 130

	Sample ID:	Blank	JA1-7.0	JA2-7.0	JA3-7.0	JA4-6.5	
Dibromofluoromethane		102	105	98	101	104	
Toluene-d8		102	94	110	101	100	
Bromofluorobenzene		96	97	106	102	97	



QC Sample Report - EPA Method 8260

Matrix: Soil

Batch #: MS48260S182

Batch Accuracy Results

Sample ID: Laboratory Cor	ntrol Sample	е	<u> </u>	
Analyte	Spike Concentration mg/Kg	% Recovery LCS	Acceptance Limits % Recovery	Pass/Fail
1,1-Dichloroethene	0.020	107	59 - 172	Pass
Benzene	0.020	93	66 - 142	Pass
Trichloroethene	0.020	90	71 - 137	Pass
Toluene	0.020	88	59 - 139	Pass
Chlorobenzene	0.020	94	60 - 133	Pass

Analytic	al Notes:	
		,
	•	•
	•	
	4	

Batch Precision Results

MS/MSD Sample ID: 16350-1

Analyte	Spike Sample Recovery mg/Kg	Spike Duplicate Recovery mg/Kg	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass/Fail
1,1-Dichloroethene	0.0225	0.0235	4%	22%	Pass
Benzene	0.0196	0.0198	1%	21%	Pass
Trichloroethene	0.0202	0.0190	6%	24%	Pass
Toluene	0.0195	0.0176	10%	21%	Pass
Chlorobenzene	0.0201	0.0201	0%	21%	Pass

۸۵۰	Isolati	Notes
ana.	ivucai	Notes

MS: Matrix Spike Sample
MSD: Matrix Spike Duplicate



Client: PSI
Project: Caltrans - J&A Trucking
Job No.: 16373

Matrix: Soil Analyst: TPW

 Date Sampled:
 04/26/00

 Date Received:
 04/28/00

 Date Extracted:
 05/03/00

 Dates Analyzed:
 05/05/00

 Batch Number:
 8270S0621

	Sample ID:	Blank	JA1-7.0	JA2-7.0	JA3-7.0	JA4-6.5
Compound	DL	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg
Acenaphthene	0.033	ND	ND	ND	ND ·	ND
Acenaphthylene	0.033	ND	ND	ND	0.055	ND
Anthracene	0.033	ND	ND	ND	ND	ND
Benzo[a]anthracene	0.066	ND	ND	ND	ND	ND
Benzo[a]pyrene	0.066	ND	ND	ND	ND	ND
Benzo[b]fluoranthene	0.033	ND	מא	ND	ND	NO
Benzo(g,h,i)perylene	0.099	ND	ND	ND	ND	ND
Benzo(k)fluoranthene	0.099	ND	ND	ND	ND :	ND
Benzyl alcohol	0.13	ND	ND	ND	ND	ND
bis(2-Chloroethoxy)metha	ne 0.066	ND	ND.	ND	ND	ND
bis(2-Chloroethyl)ether	0.066	ND	ND	ND	ND	ND
bis(2-Chloroisopropyl)ethe	A to a character of a character of the c	ND	ND	NO	ND	ND
bis(2-Ethylhexyl)phthalate	0.33	ND	ND	ND	ND	ND
4-Bromophenylphenylethe	r 0.033	ND	ND	ND	ND	ND
Butylbenzylphthalate	0.033	ND	ND	ND	ND	ND
4-Chloro-3-methylphenol	0.16	ND	ND	ND	ND	ND
4-Chloroaniline	0.16	ND	ND	ND	ND	ND
2-Chloronaphthalene	0.033	ND	ND	ND	ND	ND
2-Chlorophenol	0.13	ND	ND	ND	ND	ND
4-Chlorophenylphenylethe	r 0.033	ND	ND	ND	ND	ND
Chrysene	0.033	ND	ND	ND	ND	ND
Di-n-butylphthalate	0:33	ND	ND	ND	ND	ND
Di-n-octylphthalate	0.033	ND	ND	ND	ND	ND
Dibenzo[a,h]anthracene	0.099	ND	ND	ND	ND	ND
Dibenzofuran	0.033	ND	ND	ND	ND	ND
1,2-Dichlorobenzene	0.033	ND	ND	ND	ND	ND
1,3-Dichlorobenzene	0.033	ND	ND	ND	ND	ND
1,4-Dichlorobenzene	0.033	ND	ND	ND	ND	ND
3,3-Dichlorobenzidine	0.13	ND	ND	ND	ND	ND
2,4-Dichlorophenol	0.16	ND	ND	ND	ND:	ND
Diethylphthalate	0.33	ND	ND	ND	ND	ND
2,4-Dimethylphenol	0.099	ND	ND	ND	ND	ND
Dimethylphthalate	0.033	ND	ND	ND	ND	ND
4,6-Dinitro-2-methylpheno		ND	ND	ND	ND	ND
2,4-Dinitrophenol	1.6	ND	ND	ND	ND	ND
2,4-Dinitrotoluene	0.033	ND	ND	ND	ND	ND:



EPA 8270 Semivolatile Organics

Client: PSI Date Sampled: 04/26/00 Project: Caltrans - J&A Trucking Date Received: 04/28/00 Job No.: 16373 Date Extracted: 05/03/00 Matrix: Soil Dates Analyzed: 05/05/00 Analyst: **TPW** Batch Number: 8270S0621

•	Sample ID:	Blank	JA1-7.0	JA2-7.0	JA3-7.0	JA4-6.5
Compound	DL	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg
2,6-Dinitrotoluene	0.099	ND	ND	ND	ND	ND
Fluoranthene	0.033	ND	ND	ND	0.072	ND
Fluorene	0.033	ND	ND	ND	ND	ND
Hexachlorobenzene	0,033	ND	ND	ND	ND	ND
Hexachlorobutadiene	0.033	ND	ND	ND	ND	ND
Hexachlorocyclopentadier	ne 1,6	ND	ND	ND	ND	ND
Hexachloroethane	0.033	ND	ND	ND	ND	ND
Indeno[1,2,3-c,d]pyrene	0.13	ND	: ND	ND	ND	NO
Isophorone	0.033	ND	ND	ND	ND	ND
2-Methylnaphthalene	0.033	ND	DM	ND	ND:	ND
2-Methylphenol	0.16	ND	ND	ND	ND	ND
4-Methylphenol	0.16	ND	ND	ND:	ND	ND
N-Nitrosodi-n-propylamin	e 0.033	ND	ND	ND	ND	ND
N-Nitrosodiphenylamine	0.033	ND	ND	ND	ND	ND
Naphthalene	0.033	ND	ND	ND	0.28	ND
2-Nitroaniline	0.099	ND	ND	ND	ND	ND
3-Nitroaniline	0.099	ND	ND	ND	ND	ND
4-Nitroaniline	0.33	ND	ND	ND	ND	ND
Nitrobenzene	0.099	МD	ND	ND	ND	ND
2-Nitrophenol	0.13	ND	ND	ND	ND	ND
4-Nitrophenol	0.33	ND	ND	ND	ND	ND
Pentachiorophenol	1.6	ND	ND	ND	ND	ND
Phenanthrene	0.066	ND	ND	ND	0.10	ND
Phenol	0.13	ND	ND	ND	ND:	ND
Pyrene	0.033	ND	ND	ND	0.14	ND
1,2,4-Trichlorobenzene	0.033	ND	ND	ND	ND	ND
2,4,5-Trichlorophenol	0.2	ND	ND	ND	ND	ND
2,4,6-Trichlorophenol	0.33	ND	ND	ND	ND	ND

Surrogates (Limits) in Percent Recovery

Sample ID:	Blank	JA1-7.0	JA2-7.0	JA3-7.0	JA4-6.5	
2-Fluorophenol (25 - 121%)	75	84	81	87	79	
Phenoi-D5 (24 - 113%)	73	82	80	87	. 77	
Nitrobenzene-D5 (23 - 120%)	60	67	65	71	64	
2-Fluorobiphenyl (30 - 115%)	77	83	84	87	80	
2,4,6-Tribromophenol (19 - 122%)	90:	92	94	95	87	
p-Terphenyl-D14 (18 - 137%)	86	82	84	108	80	



QC Sample Report - EPA 8270

Batch #: 8270S0621

Matrix: Soil

Sample 1D	: Laboratory	/ Control	Sample
-----------	--------------	-----------	--------

Analyte	Spike Concentration mg/Kg	% Recovery LCS	Acceptance Limits % Recovery	Pass/Fail
Phenoi	2.66	. 80	5 - 112	Pass
2-Chlorophenol	2.66	94	23 - 134	Pass
1,4-Dichlorobenzene	1.33	91	20 - 124	Pass
N-Nitrosodi-n-propylamine	1.33	71	0 - 230	Pass
1,2,4-Trichlorobenzene	1.33	96	44 - 142	Pass
4-Chloro-3-Methylphenol	2.66	90	22 - 147	Pass
Acenaphthene	1.33	89	47 - 145	Pass
4-Nitrophenol	2.66	104	0 - 132	Pass
2,4-Dinitrotoluene	1.33	92	39 - 139	Pass
Pentachlorophenol	2.66	126	14 - 176	Pass
Pyrene	1.33	90	52 - 115	Pass

Analytica	l Notes:

Batch Precision Results

MS/MSD Sample iD: Laboratory Control Sample

Analyte	Spike Sample Recovery mg/Kg	Spike Duplicate Recovery mg/Kg	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass/Fail
Phenol	2.12	1.95	9%	35%	Pass
2-Chlorophenol	2.50	2.27	10%	50%	Pass
1,4-Dichlorobenzene	1.22	1.12	9%	27%	Pass
N-Nitrosodi-n-propylamine	0.95	0.88	7%	38%	Pass
1,2,4-Trichlorobenzene	1.28	1.16	10%	23%	Pass
4-Chloro-3-Methylphenol	2.39	2.23	7%	33%	Pass
Acenaphthene	1.18	1.09	8%	23%	Pass
4-Nitrophenol	2.77	2.60	6%	50%	Pass
2,4-Dinitrotoluene	1.23	1.15	6%	47%	Pass
Pentachlorophenol	3.36	3.11	8%	47%	Pass
Pyrene	1.20	1.11	8%	36%	Pass

Analytical	Notes:	
	•	
<u> </u>		
1		

QC Sample Report - EPA 8015M Gasoline

Matrix: Soil

Batch #: 8015GS2591

Batch Accuracy Results

Sample ID: Laboratory Con		-				
	Spike Concentration mg/Kg	Recovery LCS		cceptance Limits	% Recovery	ass/Fail
Analyte	Spike (mg/Kg	% ~		Acc	%	Pass
Gasoline	10.0	100	70	•	130	Pass

Analytical Notes:	
•	
·	
	100


Batch Precision Results

MS/MSD Sample ID: 16369-1


Analyte	Spike Sample Recovery mg/Kg	Spike Duplicate Recovery mg/Kg	Relative Percent Difference (RPD)	Upper Control Limit RPD	Pass/Fail
Gasoline	7.24	7.37	2%	30%	Pass

Analytical Notes:	
·	


MS: Matrix Spike Sample MSD: Matrix Spike Duplicate













APPENDIX E PROJECT PERMITS

MCDO A CITATERIT DEDRATE	<u> </u>		
NCROACHMENT PERMIT	Permit No	•	
	· · · · · · · · · · · · · · · · · · ·	<u> VSV-0671</u>	
	Dist/Co/R	tie/PM -880-32.1	
mpliance with (Check one):	04-Ala	-000-32.1	•
	Date		
Your application of March 13, 2000		20, 2000	
	Fee Paid	20, 2000	Deposit
Utility Notice No of	\$		\$
Agreement No of	Performa	nce Bond Amount (1)	Payment Bond Amount (2)
R/W Contract No.	Bond Cor	npany	·
R/W Contract No of	Bond Nur		10-126-10
	שווט אווים	moer (1)	Bond Number (2)
O: PSI	-		
1320 W. Winton Avenue	'		
Hayward, CA 94545			
		-	
Attn: Frank Poss	ı		
Phone: (510) 785-1111	, PERMIT	TEE	
the subject to the following, PERMISSION IS HEREBY GRAN	Private Andrews		
GRAN	ATED to:		
four holes and collect ground water samples for E	nvironmental Inv	estigation ner C	altrans Project FA No
92203 at Kirkham Street on State Highway 04-Ala-88	0 Post Mile 32 1	in Oakland	attans roject LA 110.
and the same same of the so	0, 1 03: 1/1110 32.1	in Cartaid.	
wo days before work is started under this permit, noti-	oa aholl ha airran	to and annualist	1 - 6 1 11
perations, public safety and traffic central shall be ab	ce shall be given	to, and approva	of construction details,
perations, public safety, and traffic control shall be ob	tained from State	Representative	N. Freitag, 600
evelling Blvd., San Leandro, 94579, 510-614-5951, v	veekdays, betwee	en 8:00 AM and	4:30 PM.
1147 60 1 1 1 1 1 1 1			
mnediately following completion of the work perm	itted herein, the	e permittee sha	ll fill out and mail the
ice of completion attached to this permit.			
personnel shall wear hard hats and orange vests, sha	irts, or jackets as	appropriate duri	ing construction.
	-	•	_
ne following attachments are also included as part of this permit (Check	: applicable):	In addition to fee, the	e permittee will be billed actual
Yes No General Provisions	· · · · · · · · · · · · · · · · · · ·	costs for:	
es No Utility Maintenance Provisions		☐ Yes ⊠ No	Review
I Yes ☑ No Special Previsions		Yes No	
had/on Mikin A Cal Offfa			inspection
es No A Cal-OSHA permit required prior to beginnin	g work:		Inspection Field Work
# A Cal-OSHA permut required prior to beginning	g work:	_	
#		(If any Cal	Field Work trans effort expended)
# Yes No The information in the environmental documental tation has been review	(If any Cal	Field Work trans effort expended)	
# Yes No The information in the environmental document permit is void unless the work is completed before December 31	ntation has been review	(If any Cal	Field Work trans effort expended)
# Permit is void unless the work is completed before December 31 is permit is to be strictly construed and no other work other than speci	tation has been review , 2000 fically mentioned is he	(If any Cal	Field Work Itrans effort expended) ior to approval of this permit.
# Yes No The information in the environmental document permit is void unless the work is completed before December 31	tation has been review , 2000 fically mentioned is he	(If any Cal	Field Work Itrans effort expended) ior to approval of this permit.
# Permit is void unless the work is completed before December 31 is permit is to be strictly construed and no other work other than speci	tation has been review , 2000 fically mentioned is he d environmental clears	(If any Cal	Field Work Itrans effort expended) ior to approval of this permit.
# Permit is void unless the work is completed before December 31 is permit is to be strictly construed and no other work other than speci	, 2000 fically mentioned is he denvironmental clears APPROVED:	(If any Cal yed and considered pr creby authorized. ances have been obtai	Field Work Itrans effort expended) for to approval of this permit. ned.
# Pres No The information in the environmental document permit is void unless the work is completed before December 31 has permit is to be strictly construed and no other work other than speci	ntation has been review , 2000 fically mentioned is he denvironmental clears APPROVED: HARRY Y. YAH	(If any Cal	Field Work Itrans effort expended) for to approval of this permit. ned.
# Permit is void unless the work is completed before December 31 is permit is to be strictly construed and no other work other than speci	, 2000 fically mentioned is he denvironmental clears APPROVED:	(If any Cal yed and considered pr creby authorized. ances have been obtai	Field Work Itrans effort expended) for to approval of this permit. ned.
# Permit is void unless the work is completed before December 31 is permit is to be strictly construed and no other work other than speci	ntation has been review , 2000 fically mentioned is he denvironmental clears APPROVED: HARRY Y. YAH	(If any Cal yed and considered pr creby authorized. ances have been obtai	Field Work Itrans effort expended) for to approval of this permit. ned.

The site of the work shall be enclosed by suitable barricades, signs and lights, as approved by State's representative, to warn and protect traffic effectively.

No excavation shall be left open overnight without written permission from the Caltrans representative or unless otherwise specified herein.

Certain details of work authorized hereby are shown on permittee's plan submitted with request for permit in conjunction with Caltrans Contract No.43A0012.

The work authorized under this permit shall also be coordinated by Jill Pollock, at (510) 286-5638 Environmental Engineering.

Any collected survey data requested by Caltrans shall be furnished to Caltrans without charge.

Any required traffic control shall be performed in accordance with provision sp-14 of Caltrans Contract No.43A0012.

The resulting holes shall be backfilled as per Caltrans requirements and as directed by the State representative.

STATE OF CALIFORNIA. DEPARTMENT OF TRANSPORTATION ENCROACHMENT PERMIT GENERAL PROVISIONS R-0045 (REV. 8/98)

AUTHORITY: The Department's authority to issue encroachment pennits is provided under. Div. I. Chpt. 3, Art. 1, Sect. 660 to 734 of the Streets and Highways Code.

REVOCATION: Encroachment permits are revocable on five days notice unless otherwise stated on the permit and except as provided by law for public corporations, franchise holders, and utilities. These General Provisions and the Encroachment Permit Utility Provisions are subject to modification or abrogation at any time. Permittees' joint use agreements, franchise rights, reserved rights or any other agreements for operating purposes in State highway right of way are exceptions to this revocation.

DENIAL FOR NONPAYMENT OF FEES: Failure to pay permit fees when due can result in rejection of future applications and denial of permits.

ASSIGNMENT: No party other than the permittee or permittee's authorized agent is allowed to work under this permit.

ACCEPTANCE OF PROVISIONS: Permittee understands and agrees to accept these General Provisions and all attachments to this permit, for any work to be performed under this permit.

BEGINNING OF WORK: When traffic is not impacted (see Number 35), the permittee shall notify the Department's representative, two (2) days before the intent to start permitted work. Permittee shall notify the Department's Representative if the work is to be interrupted for a period of five (5) days or more, unless otherwise agreed upon. All work shall be performed on weekdays during regular work hours, excluding holidays, unless otherwise specified in this permit.

STANDARDS OF CONSTRUCTION: All work performed within highway right of way shall conform to recognized construction standards and current Department Standard Specifications. Department Standard Plans High and Low Risk Facility Specifications, and Utility Special Provisions. Where reference is made to "Contractor and Engineer." these are amended to be read as "Permittee and Department representative."

PLAN CHANGES: Changes to plans, specifications, and permit provisions are not allowed without prior approval from the State representative.

INSPECTION AND APPROVAL: All work is subject to monitoring and inspection. Upon completion of work, permittee shall request a final inspection for acceptance and approval by the Department. The local agency permittee shall not give final construction approval to its contractor until final acceptance and approval by the Department is obtained.

PERMIT AT WORKSITE: Permittee shall keep the permit package or a copy thereof, at the work site and show it upon request to any Department representative or law enforcement officer. If the permit package is not kept and made available at the work site, the work shall be suspended.

CONFLICTING ENCROACHMENTS: Permittee shall yield start of work to ongoing, prior authorized, work adjacent to or within the limits of the project site. When existing encroachments conflict with new work, the permittee shall bear all cost for rearrangements, (e.g., relocation, alteration, removal, etc.).

PERMITS FROM OTHER AGENCIES: This permit is invalidated if the permittee has not obtained all permits necessary and required by law, from the Public Utilities Commission of the State of California (PUC), California Occupational Safety and Health Administration (Cal-OSHA), or any other public agency having jurisdiction.

PEDESTRIAN AND BICYCLIST SAFETY: A safe minimum passageway of 1.21 meter (4") shall be maintained through the work area at existing pedestrian or bicycle facilities. At no time shall pedestrians be diverted onto a portion of the street used for vehicular traffic. At locations where safe alternate passageways cannot be provided, appropriate signs and barricades shall be installed at the limits of construction and in advance of the limits of construction at the nearest crosswalk or intersection to detour pedestrians to facilities across the street.

PUBLIC TRAFFIC CONTROL: As required by law, the permittee shall provide traffic control protection warning signs, lights, safety devices, etc., and take all other measures necessary for traveling public's safety. Day and aight time lane closures shall comply with the Manuals of Traffic Controls, Standard Plans, and Standard

Specifications for traffic control systems. These General Provisions are not intended to impose upon the permittee, by third parties, any duty or standard of care, greater than or different from, as required by law.

- 15. MINIMUM INTERFERENCE WITH TRAFFIC: Perminee shall plan and conduct work so as to create the least possible inconvenience to the traveling public; traffic shall not be unreasonably delayed. On conventional highways, permittee shall place properly attired flagger(s) to stop or warn the traveling public in compliance with the Manual of Traffic Controls and Instructions to Flaggers Pamphlet.
- 16. STORAGE OF EQUIPMENT AND MATERIALS: Equipment and material storage in State right of way shall comply with Standard Specifications, Standard Plans, and Special Provisions. Whenever the permittee places an obstacle within 3.63 m (12') feet of the traveled way, the permittee shall place temporary railing (Type K).
- 17. CARE OF DRAINAGE: Permittee shall provide alternate drainage for any work interfering with an existing drainage facility in compliance with the Standard Specifications, Standard Plans and/or as directed by the Department's representative.
- RESTORATION AND REPAIRS IN RIGHT OF WAY: Permittee
 is responsible for restoration and repair of State highway right of
 way resulting from permitted work (State Streets and Highways
 Code, Sections 670 et. seq.).
- 19. RIGHT OF WAY CLEAN UP: Upon completion of work, permittee shall remove and dispose of all scraps, brush, timber, materials, etc. off the right of way. The aesthetics of the highway shall be as it was before work started.
- COST OF WORK: Unless stated in the permit, or a separate written
 agreement, the permittee shall bear all costs incurred for work
 within the State right of way and waives all claims for
 indemnification or contribution from the State.
- ACTUAL COST BILLING: When specified in the permit, the Department will bill the permittee actual costs at the currently set hourly rate for encroachment permits.
- 22 AS-BUILT PLANS: When required, permittee shall submit one (1) set of as-built plans in compliance with Department's requirements. Plans shall be submitted within thirty (30) days after completion and approval of work.

As-Built plans or accompanying correspondence shall not include disclaimer statements of any kind. Such statements shall constitute non-compliance with these provisions. Failure to provide complete and signed As-Built plans shall be cause for bond or deposit retention by the Department.

- 23. PERMITS FOR RECORD PURPOSES ONLY: When work in the right of way is within an area under a Joint Use Agreement (JUA) or a Consent to Common Use Agreement (CCUA), a fee exempt permit is issued to the permittee for the purpose of providing a notice and record of work. The Permittee's prior rights shall be preserved without the intention of creating new or different rights or obligations. "Notice and Record Purposes Only" shall be stamped across the face of the permit.
- BONDING: The permittee shall file bond(s), in advance, in the amount set by the Department. Failure to maintain bond(s) in full force and effect will result in the Department stopping of all work and revoking permit(s). Bonds are not required of public corporations or privately owned utilities, unless permittee failed to comply with the provision and conditions under a prior permit. The surery company is responsible for any latent defects as provided in California Code of Civil Procedures, Section 337.15. Local agency permittee shall comply with requirements established as follows: In recognition that project construction work done on State property will not be directly funded and paid by State, for the purpose of protecting stop notice claimants and the interests of State relative to successful project completion, the local agency permittee agrees to require the construction contractor furnish both a payment and performance bond in the local agency's name with both bonds complying with the requirements set forth in Section 3-1.02 of State's current Standard Specifications before performing any project construction work. The local agency permittee shall defend, indemnify, and hold harmless the State, its officers and employees from all project construction related claims by contractors and all stop notice or mechanic's lien claimants. The local agency also agrees to remedy, in a timely manner and to State's satisfaction, any latent defects occurring as a result of the project construction work.
- 25. FUTURE MOVING OF INSTALLATIONS: Permittee understands and agrees to rearrange a permitted installation upon request by the Department, for State construction, reconstruction, or maintenance

TATE OF CALIFORNIA • DEPARTMENT OF TRANSPORTATE LISTOMER SERVICE QUESTIONNAIRE 166 (REV. 3/98)	TON			
100 (1124.000)			PERMIT NUMBER	1101 71
ar Customer,		-	0400-NS	00611
Our goal is to provide the best service complete this questionnaire. Your common areas which may need improvement.	lents will enabl	e us to see no	Please take a w we are doing	few minutes overall and
PLEASE TELL US	HOW WE'RE	DOING	$\overline{\mathbf{Q}}$	
SIDE THE OFFICE	EXCELLENT	VERY GOOD	GOOD	POOR
taff courteous and helpful	· · · · ·			··· ·····
ff quick and efficient				
xplanations and instructions clear				· ·
LEPHONE ANSWERING			.	· · · · · · · · · · · · · · · · · · ·
imely response			T T	
ceiving information or answers				
ISPECTION				
pector courteous and helpful				
re-construction meeting set and held in a				
nely manner				
pector at job site frequently				
spector able to answer questions and all with problems				
VERALL PERFORMANCE			<u> </u>	
at would you say is our overall erformance?				· · · · · · · · · · · · · · · · · · ·
nere a staff person you would like to immend?	STAFF'S NAME		<u> </u>	
MMENTS:				
E (Optional)		BUSINESS PHON	E NI IMPED	2475
		()	E NOMBER	DATE

ALE OF CALIFORNIA • DEPARTMENT OF TRANSPORTATION				
NCROACHMENT PERMIT	Permit N	Permit No.		
		NSV-0669		
	Dist/Co/	Rie/PM 1-880-32.0		
mpliance with (Check one):	04-A18	1-000-32.0		
•				
•.	Date			
Your application of March 13, 2000	March	20, 2000		
There are an	Fee Paid		Deposit	
Utility Notice No of			\$	
Agreement No of	<u>-</u> -	ance Bond Amount (1)	Payment Bond Amount (2)	
_R/W Contract No. of	Bond Co	ompany		
OI	Bond Nu	ımber (1)	Bond Number (2)	
)	
0: PSI				
1320 W. Winton Avenue				
Hayward, CA 94545				
Attn: Frank Poss	•	•		
Phone: (510) 785-1111	, PERMI	ITEE		
_	—			
ad subject to the following, PERMISSION IS HEREBY GRAI	NTED to:			
) four holes and collect ground water samples for E 92203 at Fifth Street on State Highway 04-Ala-880, P	nvironmental In	vestigation per C	altrans Project EA No.	
I sales in State Inghway 04-Ala-860, I	ost MHE 32.0 III	Oakland.		
wo days before work is started under this permit, noti	as aball be airea	. +	- M	
perations, public safety, and traffic control shall be ob	ce shan be given	o Deservation	of construction details,	
velling Blvd., San Leandro, 94579, 510-614-5951, v	realised from Stat	e Representative	N. Freitag, 600	
5 21. di, 3 di 13 di 16 di 16, 5 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	weekdays, betwe	en 8:00 Alvi and	4:30 PM.	
mmediately following completion of the work pern	sittad bayain th	o moumeittee elect	1 6314 1 3 45	
ice of completion attached to this permit.	ntieu nerein, th	e bermiisee suai	i illi out and mali the	
to this permit.				
personnel shall wear hard hats and orange vests, sh	i rt a or igalegta oa	annyanyiata dari		
r	iris, or jackets as	appropriate duri	ng construction.	
he following attachments are also included as part of this permit (Check	b 1: 1: ->	f - 4 Por a Cont		
	с аррисавіе):	in addition to tee, the	permittee will be billed actual	
Ges ☐ No General Provisions Ses ☑ No Utility Maintenance Provisions			•	
Yes No Special Previsions		☐ Yes ☒ No	Review Inspection	
Yes No A Cal-OSHA permit required prior to beginnin	g work:	Ĭ Yes	Field Work	
<u>#</u>		(If any Cal	rans effort expended)	
Yes No The information in the environmental document	station has been review	ved and considered pri	or to approval of this permit	
be permit is void unless the work is completed before December 31			or to approvar or this permit.	
his permit is to be strictly construed and no other work other than speci	<u>·</u>	المحادية والمعادية		
roject work shall be commenced until all other necessary permits an	d environmental clear	ereoy authorizeu. ances have been obtair	ned.	
	APPROVED:			
	TADDSUS SUL	TATEA DOLL COM		
	BY:	HATA, District Dire	ector	
	(\$15	\square	
		19 Lac		
	G. J. BATTAGI	INI, District Perm	it Engineer	

The site of the work shall be enclosed by suitable barricades, signs and lights, as approved by State's representative, to warn and protect traffic effectively.

No excavation shall be left open overnight without written permission from the Caltrans representative or unless otherwise specified herein.

Certain details of work authorized hereby are shown on permittee's plan submitted with request for permit in conjunction with Caltrans Contract No.43A0012.

The work authorized under this permit shall also be coordinated by Jill Pollock, at (510) 286-5638 Environmental Engineering.

Any collected survey data requested by Caltrans shall be furnished to Caltrans without charge.

Any required traffic control shall be performed in accordance with provision sp-14 of Caltrans Contract No.43A0012.

The resulting holes shall be backfilled as per Caltrans requirements and as directed by the State representative.

STATE OF CALIFORNIA. DEPARTMENT OF TRANSPORTATION ENCROACHMENT PERMIT GENERAL PROVISIONS R-0045 (REV. 898)

AUTHORITY: The Department's authority to issue encroachment permits is provided under, Div. 1, Chpt. 3, Art. I. Sect. 660 to 734 of the Streets and Highways Code.

REVOCATION: Encroachment permits are revocable on five days notice unless otherwise stated on the permit and except as provided by law for public corporations, franchise holders, and utilities. These General Provisions and the Encroachment Permit Utility Provisions are subject to modification or abrogation at any time. Permittees' joint use agreements, franchise rights, reserved rights or any other agreements for operating purposes in State highway right of way are exceptions to this revocation.

DENIAL FOR NONPAYMENT OF FEES: Failure to pay permit fees when due can result in rejection of future applications and denial of permits.

ASSIGNMENT: No party other than the permittee or permittee's authorized agent is allowed to work under this permit.

ACCEPTANCE OF PROVISIONS: Permittee understands and agrees to accept these General Provisions and all attachments to this permit, for any work to be performed under this permit.

BEGINNING OF WORK: When traffic is not impacted (see Number 35), the permittee shall notify the Department's representative, two (2) days before the intent to start permitted work. Permittee shall notify the Department's Representative if the work is to be interrupted for a period of five (5) days or more, unless otherwise agreed upon. All work shall be performed on weekdays during regular work hours, excluding holidays, unless otherwise specified in this permit.

STANDARDS OF CONSTRUCTION: All work performed within highway right of way shall conform to recognized construction standards and current Department Standard Specifications, Department Standard Plans High and Low Risk Facility Specifications, and Utility Special Provisions. Where reference is made to "Contractor and Engineer." these are amended to be read as "Permittee and Department representative."

PLAN CHANGES: Changes to plans, specifications, and permit provisions are not allowed without prior approval from the State representative.

INSPECTION AND APPROVAL: All work is subject to monitoring and inspection. Upon completion of work, permittee shall request a final inspection for acceptance and approval by the Department. The local agency permittee shall not give final construction approval to its contractor until final acceptance and approval by the Department is obtained.

PERMIT AT WORKSITE: Permittee shall keep the permit package or a copy thereof, at the work site and show it upon request to any Department representative or law enforcement officer. If the permit package is not kept and made available at the work site, the work shall be suspended.

CONFLICTING ENCROACHMENTS: Permittee shall yield start of work to ongoing, prior authorized, work adjacent to or within the limits of the project site. When existing encroachments conflict with new work, the permittee shall bear all cost for rearrangements, (e.g., relocation, alteration, removal, etc.).

PERMITS FROM OTHER AGENCIES: This permit is invalidated if the permittee has not obtained all permits necessary and required by law, from the Public Utilities Commission of the State of California (PUC), California Occupational Safety and Health Administration (Cal-OSHA), or any other public agency having jurisdiction.

PEDESTRIAN AND BICYCLIST SAFETY: A safe minimum passageway of 1.21 meter (4') shall be maintained through the work area at existing pedestrian or bicycle facilities. At no time shall pedestrians be diverted onto a portion of the street used for vehicular traffic. At locations where safe alternate passageways cannot be provided, appropriate signs and barricades shall be installed at the limits of construction and in advance of the limits of construction at the nearest crosswalk or intersection to detour pedestrians to facilities across the street.

PUBLIC TRAFFIC CONTROL: As required by law, the permittee shall provide traffic control protection warning signs, lights, safety devices, etc., and take all other measures necessary for traveling public's safety. Day and night time lane closures shall comply with the Manuals of Traffic Controls, Standard Plans, and Standard

Specifications for traffic control systems. These General Provisions are not intended to impose upon the permittee, by third parties, any dury or standard of care, greater than or different from, as required by law.

- 15. MINIMUM INTERFERENCE WITH TRAFFIC: Permittee shall plan and conduct work so as to create the least possible inconvenience to the traveling public: traffic shall not be unreasonably delayed. On conventional highways, permittee shall place properly attired flagger(s) to stop or warn the traveling public in compliance with the Manual of Traffic Controls and Instructions to Flaggers Pamphlet.
- 16. STORAGE OF EQUIPMENT AND MATERIALS: Equipment and material storage in State right of way shall comply with Standard Specifications, Standard Plans, and Special Provisions. Whenever the permittee places an obstacle within 3.63 m (12) feet of the traveled way, the permittee shall place temporary railing (Type K).
- 17. CARE OF DRAINAGE: Permittee shall provide alternate drainage for any work interfering with an existing drainage facility in compliance with the Standard Specifications, Standard Plans and/or as directed by the Department's representative.
- RESTORATION AND REPAIRS IN RIGHT OF WAY: Permittee is responsible for restoration and repair of State highway right of way resulting from permitted work (State Streets and Highways Code, Sections 670 et. seq.).
- RIGHT OF WAY CLEAN UP: Upon completion of work, permittee shall remove and dispose of all scraps, brush, timber, materials, etc. off the right of way. The aesthetics of the highway shall be as it was before work started.
- 20. COST OF WORK: Unless stated in the permit, or a separate written agreement, the permittee shall bear all costs incurred for work within the State right of way and waives all claims for indemnification or contribution from the State.
- ACTUAL COST BILLING: When specified in the permit, the Department will bill the permittee actual costs at the currently set hourly rate for encroachment permits.
- AS-BUILT PLANS: When required, permittee shall submit one (1) set of as-built plans in compliance with Department's requirements. Plans shall be submitted within thirty (30) days after completion and approval of work.

As-Built plans or accompanying correspondence shall not include disclaimer statements of any kind. Such statements shall constitute non-compliance with these provisions. Failure to provide complete and signed As-Built plans shall be cause for bond or deposit retention by the Department.

- 23. PERMITS FOR RECORD PURPOSES ONLY: When work in the right of way is within an area under a Joint Use Agreement (JUA) or a Consent to Common Use Agreement (CCUA), a fee exempt permit is issued to the permittee for the purpose of providing a notice and record of work. The Permittee's prior rights shall be preserved without the intention of creating new or different rights or obligations. "Notice and Record Purposes Only" shall be stamped across the face of the permit.
- BONDING: The permittee shall file bond(s), in advance, in the amount set by the Department. Failure to maintain bond(s) in full force and effect will result in the Department stopping of all work and revoking permit(s). Bonds are not required of public corporations or privately owned utilities, unless permittee failed to comply with the provision and conditions under a prior permit. The surery company is responsible for any latent defects as provided in California Code of Civil Procedures, Section 337.15. Local agency permittee shall comply with requirements established as follows: in recognition that project construction work done on State property will not be directly funded and paid by State, for the purpose of protecting stop notice claimants and the interests of State relative to successful project completion, the local agency permittee agrees to require the construction contractor furnish both a payment and performance bond in the local agency's name with both bonds complying with the requirements set forth in Section 3-1.02 of State's current Standard Specifications before performing any project construction work. The local agency permittee shall defend, indemnify, and hold harmless the State, its officers and employees from all project construction related claims by contractors and all stop notice or mechanic's lien claimants. The local agency also agrees to remedy, in a timely manner and to State's satisfaction, any latent defects occurring as a result of the project construction work.
- ES. FUTURE MOVING OF INSTALLATIONS: Permittee understands and agrees to rearrange a permitted installation upon request by the Department, for State construction, reconstruction, or maintenance

ATE OF CALIFORNIA • DEPARTMENT OF TRANSPORTATI USTOMER SERVICE QUESTIONNAIRE D166 (REV. 3/98)	NON			
1100 (MEV. W30)			PERMIT NUMBER 0400-11	510669
ar Customer,				3000
Our goal is to provide the best service complete this questionnaire. Your commay areas which may need improvement.	e possible to o ents will enabl	eur customers. e us to see ho	Please take a w we are doing	few minute overall and
PLEASE TELL US H	HOW WE'RE	DOING	V	
SIDE THE OFFICE	EXCELLENT	VERY GOOD	GOOD	POOR
aff courteous and helpful				
ff quick and efficient			· -	
planations and instructions clear				
LEPHONE ANSWERING				<u> </u>
nely response				
ceiving information or answers				
SPECTION				l
pector courteous and helpful				
e-construction meeting set and held in a ely manner				
pector at job site frequently	<u> </u>			
pector able to answer questions and all with problems	·			
ERALL PERFORMANCE				<u> </u>
at would you say is our overall formance?		<u> </u>	·	·
nere a staff person you would like to	STAFF'S NAME			·
mmend?	STAFFS NAME	·		
E (Optional)		BUSINESS PHON	E NUMBER	DATE

CHATURE M Contoutileten DATE 3-14-2000

r, Q2



ALAMEDA COUNTY PUBLIC WORKS AGENCY

WATER RESOURCES SECTION 951 TURNER COURT, SUITE 300, HAYWARD, CA 94545-2651 PHONE (510) 670-5575 ANDREAS GODFREY FAX (510) 674-3282 (510) 670-5248 ALVIN KAN 782-1939

[<u> </u>
DRILLING PERM	IIT APPLICATION
FOR APPLICANT TO COMPLETE DEATION OF PROJECT SOO KIRKHAM CETEER OAKLAND ALAMEDA COUNTY CALIFORNIA	POR OFFICE USE PERMIT NUMBER
iliformia Cogrdinates Source 1. Accuracy ± n. 1. Accuracy ± n. 1. Accuracy ± n. 1. Accuracy ± n. 1. Accuracy ± n. 1. Accuracy ± n.	PERMIT CONDITIONS
CLIENT COYP THE CALTRANS - DISTRICT 4 dress III GRAND Are Phone (50) 256-538 Clity DAKLAND, CA Zip 94612-3717 PLICANT THE PLICANT CONSTANTINESCUE PROJECT GRAND SPECIAL FOR (50) 785-1192	Circled Permit Requirements Apply A. GENERAL 1. A permit application should be submitted so as to arrive at the ACPWA office five days prior to proposed starting date. 2. Submit to ACPWA within 60 days after completion of permitted work the original Department of Water Resources Well Completion Report
Address 320 Liver Ive Phane (570) 785 - 1111 PE OF PROJECT Geotechnical Investigation Calhadia Protection General Gen	Permit is void if project not begun within 90 days of approval date. B. WATER SUPPLY WELLS 1. Minimum surface seal thickness is two inches of cement grout placed by tremie. 2. Minimum seal depth is 50 feet for municipal and industrial wells or 20 feet for domestic and irrigation
New Domestic	wells unless a leaser depth is specially approved. CCCROUNDWATER MONITORING WELLS INCLUDING PIEZOMETERS 1. Minimum surface seal thickness is two inches of cornent grout placed by tremie.
Cable 0 Other 0 LLER'S LICENSLAW, C-57-720904	2. Minimum seal depth for monitoring wells is the maximum depth practicable or 20 feet. D. GEOTECHNICAL Backfill bore hole with compacted cuttings or heavy bentonite and upper two feet with compacted material.
Drill Role Diameter 8 in. Maximum asing Diameter 2 in. Depth 6.5 ft. urface Seal Depth 2 ft. Number 4	cement grout shall be used in place of compacted cuttings. E. CATHODIC Fill hole above anode zone with concrete placed by tremic. P. WELL DESTRUCTION
STIMATED STARTING DATE 3-27 Co. C.	See attached. G. SPECIAL CONDITIONS
icroby agree to comply with all requirements of this permit and ameda County Ordinance No. 73-68.	APPROVED SOME SCHOOL DATE 08-14-0

1 mm mos 2101051932

r. U3



ALAMEDA COUNTY PUBLIC WORKS AGENCY

WATER RESOURCES SECTION 951 TURNER COURT, SUITE 300, HAYWARD, CA 94545-1651 PHONE (510) 670-5975 ANDREAS GODFREY FAX (510) 670-6162-(510) 670-5248 ALVIN KAN 782-1939

DRILLING PERM	IT APPLICATION
	- INI DICATION
FOR APPLICANT TO COMPLETE	
OCATION OF PROJECT 1285 FIFTH Steet	FOR OFFICE USE
OAKLAND, CA	PERMIT NUMBER WOO - 11 O WELL NUMBER APN
ifornia Coordinates Squree	M
PN 000 - 0390-003 - 122/17/320	PERMIT CONDITIONS
LIENT . OO3	Circled Permit Requirements Apply
ame_CALTRANS - DISTRICT4	(A.)GENERAL
ddress /// GRAND Arc Phone /5/0/286-5238 ity OAKCAND CA Zip 946/2-37/7	A permit application should be submitted so as to arrive at the ACPWA office five days advent
PPLICANT	Anabased starting date.
AME_ F. S. I - ABRANA ADNSTRAID WAR.	2. Submit to ACPWA within 60 days after completion of permitted work the original Department of Water
stress (320 La Charles) 45 Fax (610) 785-1/92	Resources Well Completion Repo
iv Harmar CA Zip 94526	
YPE OF PROJECT	3. Permit is void if project not begun within 90 days of
fell Construction	B. WATER SUPPLY WELLS
Cathodic Protection General	I. Minimum surface seal thickness is two inches of
Water Supply It Comment	cement grout placed by tremie.
Montioring Walt D	2. Minimum seal depth is 50 feet for municipal and
-	industrial wells or 20 feet for domestic and irrigation
OPOSED WATER SUPPLY WELL USE	WS03 UBICSS 1 lesses densit le annul u
Replacement Domestic	
for desirate a	MCLODING PIEZOMETERS
Industrial U Cither	Minimum surface seal thickness is two laches of
ILLING METHOD	cement grout placed by tremie
Mud Rotary D Alexania	Minimum seal depth for monitoring wells is the
Cable C Other C	D. GEOTECHNICAL
· · · · · · · · · · · · · · · · · · ·	Backfill bare hale with compacted cuttings or heavy
LLER'S LICENSE NO. C-57-720904	bentonite and upper two feet with compacted material.
LL PROJECTS	VI AROWN OF EUSpecied contemporates
Drill Hole Diameter ! 8	
Asing Districtor	· · = + • •
before Seed Death 19.5 R.	Fill hole above anode zone with concrete placed by tremie. F. WELL DESTRUCTION
Number 3	See attached.
PTECHNICAL PROJECTS	C. SPECIAL CONDITIONS
Umber of Borings	
lole Diameter in. Depth ft.	
MATED STARTING DATE 3-27- 2000	1 -
IMATED COMPLETION DATE 1-28 - 2000	APPROVED Frank L. Cold DATE 03-14-0
sby agree to comply with all requirements of this permit and	DAIBO // C
ieda County Ordinance No. 73-68.	•

PPLICANT'S

MAR 14 2000 16:05

APPENDIX F

ON-SITE CALIBRATION AND AIR MONITORING DATA SHEET

ON-SITE CALIBRATION AND AIR MONITORING DATA

Caltrans South Oakland Maitenance Station Oakland, CALIFORNIA

PSI PROJECT NUMBER:575-9G011

Air monitoring data in the breathing zone shall be documented at the subject site. Please identify calibration dates prior to and after sampling, the type of instrumentation, calibration gas, span setting (OVA), location, and corresponding concentrations. Please sign your name as the person(s) responsible for calibration and air sampling.

SALIBRATION

			· · · · · · · · · · · · · · · · · · ·	MORETO	CENCO		
(PE DE JOST	D A T E	TIME	INSTRU MENT SERIAL NO.	CALIBRA TION GAS (TYPE/ CONC.)	SPAN SETTING	READIN G (PPM)	SIGNATURE
	4-25.00	1000	58013-27363-2	28 150 BUT YER	E.	0.0	em AREA
	4-25-00	แ 30				0.0	CM BZ-CFZ
-	4-25-00	1330	A			0.0	CF I CUTTIALS TO 5'
							·
_							

APPENDIX G CYPRESS PRELIMINARY REMEDIAL GOALS

Cypress Preliminary Remedial Goals

	Compound		PRG
-	Carcinogens:		(mg/kg soil)
		benzo(a)anthracene *	0.3 - 30
		benzo(b)fluoranthene *	0.3 - 30
		benzo(k)fluoranthene *	0.3 - 30
		benzo(a)pyrene *	0.03 - 3
		chrysene *	3 - 300
		dibenzo(ah)anthracene *	0.03 - 3
		indeno(1,2,3-cd) pyrene *	0.3 - 30
		benzene	3.5 - 31
		tetrachloroethylene	10 - 92
		trichloroethylene	27 - 250
		vinyl chloride	0.1 - 0.94
		chloroform	12 - 110
		1,1-dichloroethylene	0.42 - 3.8
•		1,4-chlorobenzene	13 - 120
•	N I====:		13 - 120
	Noncarcinogens:	fluoranthene	2300
		pyrene	1700
		ethylbenzene	74
		toluene	280
:		xylene	99
	•	1,1-dichloroethane	380
		1,1,1-trichloroethane	470
		chlorobenzene	160
		1,2-dichlorobenzene	360
		naphthalene	82 .
	Matal		
	Metals:	Antimony	67
		Arsenic **	19
		Barium	12,000
		Beryllium	1.8 - 0.2
		Cadmium	24 - 2.7
	•	Chremium (III)	170,000
		Chromium (VI)	0.68 - 0.076
		Copper	5,000
		Fluorine	10,000
		Lead	840
		Mercury	45
		Molybdenum	830
		Nickel	400 - 44
		Selenium	830
		Silver	830
		Thallium **	27
		Vanadium	1,200
		Zinc	50,000
	Descrit value		Commission of the Commission o
	Petrolium Hydrocarbons:	TRPH $(c_{23}-c_n)$?	1,000
		Diesel > " (-	100
	4	TRPH $(c_{23} - c_n)$? Diesel $(c_{10} - c_{22})$?	100

* The range for these compounds are recalculations of the original Cypress PRGs.

** The Arsenic PRG is 4.6 ppm while the background level is 19 ppm.

The Thalium PRG is 14 ppm while the background level is 27 ppm.

(When there is no known human contamination at the site, the background levels are used. contamination at the site the PRG levels are used.)

06/24/99