# Jitramar

Ultramar, Inc.

525 W. Third Street

Hanford, CA 93232-0466 (209) 582-0241

P.O. Box 466

ENVIRONMENTAL PROTECTION

96 DEC 17 AM 9: 58

Telecopy: 209-585-5685 Credit 209-583-3330 Administrative 209-583-3302 Information Services 209-583-3358 Accounting

December 13, 1996

Include analysis (n MTBE- Sce and dated Avg 1996 -2 events (3/96 + 6/96) were (\*Detect limit for MTBE

Ms. Eva Chu Department of Environmental Health

Alameda County Health Care Services 1131 Harbor Bay Parkway, Room 250

Alameda, CA 94502-6577

SUBJECT:

BEACON STATION NO. 604, 1619 FIRST STREET, LIVERMORE,

**CALIFORNIA** 

Dear Ms. Chu:

Enclosed is a copy of the Third Quarter 1996 Ground Water Monitoring Report for the above-referenced Ultramar facility. Also included is a copy of the Quarterly Status Report which describes the work completed this quarter and the work anticipated to be completed next quarter.

The wells were also sampled for biodegradation parameters this quarter. indicate that the upgradient well MW-1 contained a higher nitrate concentration than the wells within the plume. This suggests that some natural biodegradation is taking place along with the active remediation.

Please call if you have any questions regarding this site.

Sincerely,

**ULTRAMAR INC.** 

Terrence A. Fox

Senior Project Manager

Tenence A. Fry

Marketing Environmental Department

CC:

Mr. Cecil Fox, San Francisco Bay Region, RWQCB

Mr. Jim Ellis, Ellis Partners Inc., 351 California Street, Suite 1120,

San Francisco, CA 94104

Mr. Leon Crane, GCL





## Ultramar

Ultramar, Inc. PO Box 466 525 W. Third Street Hanford, CA 93232-0466 (209) 582-0241

Telecopy: 209-585-5685 Credit 209-583-3330 Administrative 209-583-3302 Information Services 209-583-3358 Accounting

#### **ENVIRONMENTAL PROJECT** QUARTERLY STATUS REPORT

DATE REPORT SUBMITTED: December 13, 1996

QUARTER ENDING: September 30, 1996

**SERVICE STATION NO.:** 604

ADDRESS: 1619 First Street, Livermore, CA

COUNTY: Alameda

**ULTRAMAR CONTACT:** Terrence A. Fox

TEL. NO: 209-583-5545

### BACKGROUND:

In November 1992, three underground storage tanks were removed. Hydrocarbons were detected and the excavation was extended to a depth of 27 feet in the southwest corner. Hydrocarbons were detected in the sample collected from the base of the overexcavation.

In May and June 1993, three monitoring wells (MW-1 through MW-3), three vapor wells (VW-1 through VW-3), and one boring were drilled. The soil plume has been defined.

The site has been placed on a quarterly monitoring program.

In March 29 and 30, 1994, four additional offsite wells (MW-4 through MW-7) were installed. The ground-water plume is not defined downgradient.

In June 1994, performed assessment on the Livermore Arcade Shopping Center Property by drilling borings and collecting ground-water samples using a Hydropunch tool.

In June 1994, performed vapor extraction and ground-water extraction tests.

In September and October 1995, installed of vapor extraction and air sparging wells.



Beacon Station 604 Quarterly Status Report Page 2

## **SUMMARY OF THIS QUARTER'S ACTIVITIES:**

Performed quarterly monitoring on September 16, 1996. Continued to operate remediation system.

#### RESULT OF QUARTERLY MONITORING:

Monitoring data indicates that the benzene concentration increased in MW-1 from not detected to 70 ppb and in MW-7 from 98 ppb to 140 ppb. The benzene concentration decreased in MW-2 from 7,300 ppb to 510 ppb, in MW-5 from 38 ppb to 29 ppb, and in MW-6 from 8,600 ppb to 6,400 ppb. MW-3 and MW-4 were not sampled this quarter.

#### PROPOSED ACTIVITY OR WORK FOR NEXT QUARTER:

**ACTIVITY** 

**ESTIMATED COMPLETION DATE** 

Continue quarterly monitoring program.

Continue to operate the of remediation system.