June 30, 1993

131.0100.003

Alameda County Environmental Health Services Hazardous Materials Division 80 Swan Way Room 200 Oakland, California 94621

Attention: Ms. Susan Hugo

QUARTERLY GROUNDWATER MONITORING REPORT MAY 1993 SAMPLING EVENT EMERY BAY PLAZA 1650 65TH STREET EMERYVILLE, CALIFORNIA

Dear Ms. Hugo:

This letter presents data collected by PES Environmental, Inc. (PES) during the May 20, 1993 quarterly groundwater monitoring conducted at Emery Bay Plaza, located at 1650 65th Street in Emeryville, California (Plate 1). PES has been retained by Emery Bay Plaza to conduct groundwater monitoring at the site. PES also provides operation, maintenance and monitoring of a groundwater extraction and treatment system at the site.

The purpose of the groundwater monitoring program at this site is to: (1) evaluate the presence of hydrocarbons in groundwater; (2) provide data to assess the performance and effectiveness of the groundwater remedial program; and (3) monitor seasonal water level variations at the site. The monitoring is performed in accordance with California Regional Water Quality Control Board (RWQCB) guidelines and the approved remedial action plan for this site.

BACKGROUND

Six monitoring wells and one extraction well were installed at the site (Plate 2) following removal of an on site underground storage tank (UST) in July 1987 and several offsite USTs in September and October 1989. Groundwater has been monitored since November, 1989. An activated carbon groundwater treatment system was installed and its operation was begun in December 1990. Discharges of treated groundwater are to the sanitary sewer under the authority of an East Bay Municipal Utility District wastewater discharge permit (Permit No.

Ms. Susan Hugo June 30, 1993 Page 2

¥

502-45131). The present sampling is the fifteenth consecutive sampling event since groundwater monitoring was initiated, and the seventh to be conducted by PES.

GROUNDWATER ELEVATIONS

Water-level Measurement Procedures

Prior to sampling, the groundwater level in each of the six monitoring wells was measured to a precision of 0.01 feet using an electronic water-level indicator. Prior to each measurement, the portion of the water-level indicator that was submerged in the well was cleaned with a mild detergent solution and rinsed with de-ionized water.

Results

Water-level data were converted to water-level elevations referenced to mean sea level (MSL). A groundwater elevation map constructed from the data is presented on Plate 3. An historical summary of groundwater elevations for wells at the site is presented in Table 1.

Water levels have fluctuated since the February 18, 1993 sampling event. Water levels in upgradient Wells MW-5 and MW-7 have increased slightly while all others, except MW-2, have decreased slightly. The water level in Well MW-2, which is near Extraction Well EW-1, did not change between the February and May monitoring events. Based on measured water levels on May 20, 1993, groundwater flow direction at the site was calculated to be toward the southwest, with an approximate gradient of 0.01 foot per foot. This is generally consistent with historical groundwater flow direction and gradient.

GROUNDWATER SAMPLING AND ANALYTICAL TESTING

Sampling Protocol

Groundwater samples were collected on May 20, 1993 by Blaine Tech Services, Inc. (Blaine Tech) from Monitoring Wells MW-2, MW-3, MW-4, MW-5, MW-6, and MW-7. Prior to sampling, the groundwater was visually inspected to assess the presence of floating product. A minimum of three well volumes were evacuated prior to sampling using a teflon bladder pump. During pumping the discharge water was measured for pH, temperature, electrical conductivity and turbidity. Groundwater samples were collected with a clean teflon bailer and decanted into clean 40-milliliter glass vials with teflon lined caps.

Ms. Susan Hugo June 30, 1993 Page 3

Samples were immediately labeled to designate sample number, time and date collected, and analysis requested, and stored in a chilled, thermally insulated cooler for transport to the analytical laboratory for chemical analysis. The information collected during the groundwater sampling and the chain of custody records are presented in a groundwater sampling report prepared by Blaine Tech, provided in Appendix A.

A sample (Sample 93135A) was collected on May 20, 1993 by PES from the extraction well (Well EW-1), to monitor chemical conditions of extracted groundwater. The sample was collected from a sample tap located on piping upstream of the treatment system. Water was purged from the sample tap for approximately one minute prior to collection of the sample. Three 40-milliliter glass vials with teflon-lined caps were filled directly from the sample tap.

Analytical Program

Groundwater samples from all wells including the extraction well were analyzed by Coast-to-Coast Analytical Services, Inc. (Coast to Coast) in Benicia, California, a State-certified chemical analysis laboratory. Samples were analyzed for total petroleum hydrocarbons quantified as gasoline (TPH gas) and benzene, toluene, ethylbenzene, and total xylenes (BTEX) by EPA Test Method 8020/8015. The groundwater sample from the extraction well was analyzed by EPA Test Method 5030/8240 and Cal DHS Draft TPH (Modified).

Analytical Results

Detectable levels of TPH gas and BTEX were found in all wells except Well MW-6. Consistent with historical monitoring data, Well MW-2, located within the backfill of the soil excavation at the former onsite UST, exhibited the highest levels of dissolved hydrocarbons (TPH and BTEX).

Analytical results for all wells, including historical monitoring results for the previous sampling events and relevant federal and state standards, are presented in Table 2. Laboratory reports and chain of custody records are provided in Appendix B. The distribution of hydrocarbons in groundwater at the site on April 20, 1993 is presented on Plate 4.

SUMMARY

Groundwater elevations have fluctuated slightly since the February 18, 1993 sampling. The groundwater flow direction continues to be southwest. Concentrations of petroleum hydrocarbons in groundwater samples did not change significantly from the last monitoring event.

Ms. Susan Hugo June 30, 1993 Page 4

If you have any questions or comments, please do not hesitate to call either of the undersigned.

Yours very truly,

PES ENVIRONMENTAL, INC.

Paul R. Lohman Staff Engineer

Robert S. Creps, P. E. Associate Engineer



Attachments:

Table 1	Summary of Groundwater Elevations
Table 2	Summary of Analytical Results for Groundwater Samples
Plate 1	Site Location Map
Plate 2	Well Location Map
Plate 3	Groundwater Elevation Contours on May 20, 1993
Plate 4	Dissolved Hydrocarbons in Groundwater on May 20, 1993
Appendix A	Groundwater Sampling Report
Appendix B	Analytical Laboratory Reports

pc: Mr. Thomas Gram - P. O. Partners Ms. Lynn Tolin - Emery Bay Plaza

Mr. Matt Dulka - Hanson, Bridgett, Marcus, Vlahos & Rudy

Table 1. Summary of Groundwater Elevations Through May 1993
Emery Bay Plaza
1650 65th Street, Emeryville, California

Well	Date	Measured	Top of	Depth to	Groundwater
Number		by	Casing	Water	Elevations
			(feet MSL)	(feet)	(feet MSL)
MW-2	21-Feb-90	ES	15.75	11.72	4.03
14144-2	25-May-90	ES	15.75	11.83	3.92
	29-Aug-90	ES	15.75	11.72	4.03
	29-Nov-90	ES	15.75	11.99	3.76
	1-Mar-91	ES ES	15.79	12.87	2.92
	28-May-91	ES	15.79	12.21	3.58
	1-Aug-91	ES	15.79	NA	NA
	27-Jan-92	PES	15.79	11.78	4.01
	28-Feb-92	PES	15.79	11.70	4.09
	28-May-92	PES	15.79	11.83	3.96
	27-Aug-92	PES	15.79	12.28	3.50
	10-Nov-92	PES	15.79	12.28	3.39
	18-Feb-93	PES	15.79	12.40	3.79
		PES		12.00 12.00	3.79 3.79
	20-May-93	PES	15.79	12.00	3.79
MW-3	21-Feb-90	ES	12.45	9.18	3.27
	25-May-90	ES	12.45	9.25	3.20
	29-Aug-90	ES	12.45	9.50	2.95
	29-Nov-90	ES	12.45	9.80	2.65
	1-Mar-91	ES	12.43	9.51	2.92
	28-May-91	ES	12.43	9.03	3.40
	1-Aug-91	ES	12.43	NA	NA
	27-Jan-92	PES	12.43	9.44	2.99
	28-Feb-92	PES	12.43	8.80	3.63
	28-May-92	PES	12.43	8.80	3.63
	27-Aug-92	PES	12.43	9.18	3.25
	10-Nov-92	PES	12.43	9.44	2.99
	18-Feb-93	PES	12.43	7.59	4.84
	20-May-93	PES	12.43	8.21	4.22
MW-4	21-Feb-90	ES	12.24	8.63	3.61
141 A A+	25-May-90	ES	12.24	8.58	3.66
	29-Aug-90	ES	12.24	8.50	3.74
	29-Nov-90	ES	12.24	8.74	3.50
	1-Mar-91	ES	12.24	8.65	3.59
	28-May-91	ES	12.24	8.57	3.67
	1-Aug-91	ES	12.24	NA	NA
	27-Jan-92	PE\$	12.24	8.62	3.62
			12.24	8.52	3.72
	28-Feb-92	PES			
	28-May-92	PES	12.94	8.35	3.89

Table 1. Summary of Groundwater Elevations Through May 1993
Emery Bay Plaza
1650 65th Street, Emeryville, California

Well Number	Date	Measured by	Top of Casing (feet MSL)	Depth to Water (feet)	Groundwater Elevations (feet MSL)
MW-4	27-Aug-92	PES	12.24	9.00	3.24
(continued)	10-Nov-92	PES	12.24	8.85	3.39
	18-Feb-93	PES	12.24	8.17	4.07
	20-May-93	PES	12.24	8.21	4.03
MW-5	21-Feb-90	ES	12.81	6.91	5.90
	25-May-90	ES	12.81	7.58	5.23
	29-Aug-90	ES	12.81	7.75	5.06
	29-Nov-90	ES	12.81	8.17	4.64
	1-Mar-91	ES	12.82	8.11	4.71
	28-May-91	ES	12.82	7.39	5.43
	1-Aug-91	ES	12.82	NA	NA
	27-Jan-92	PES	12.82	7.90	4.92
	28-Feb-92	PES	12.82	7.73	5.09
	28-May-92	PES	12.82	7.18	5.64
	27-Aug-92	PES	12.82	7.54	5.28
	10-Nov-92	PES	12.82	7.90	4.92
	18-Feb-93	PES	12.82	6.58	6.24
	20-May-93	PES	12.82	6.29	6.53
MW-6	1-Mar-91	ES	12.03	8.59	3.44
	28-May-91	ES	12.03	8.35	3.68
	1-Aug-91	· ES	12.03	NA	NA
	27-Jan-92	PES	12.03	8.32	3.71
	28-Feb-92	PES	12.03	8.08	3.95
	28-May-92	PES	12.03	8.04	3.99
	27-Aug-92	PES	12.03	8.48	3.55
	10-Nov-92	PES	12.03	8.52	3.51
	18-Feb-93	PES	12.03	8.14	3.89
	20-May-93	PES	12.03	8.46	3.57

Table 1. Summary of Groundwater Elevations Through May 1993
Emery Bay Plaza

1650 65th Street, Emeryville, California

Well Number	Date	Measured by	Top of Casing (feet MSL)	Depth to Water (feet)	Groundwate Elevations (feet MSL)
MW-7	1-Mar-91	ES	12.9	7.51	5.39
	28-May-91	ES	12.9	7.07	5.83
	1-Aug-91	ES	12.9	NA	NA
	27-Jan-92	PES	12.9	7.28	5.62
	28-Feb-92	PES	12.9	7.04	5.86
	28-May-92	PES	12.9	6.81	6.09
	27-Aug-92	PES	12.9	7.12	5.78
	10-Nov-92	PES	12.9	7.80	5.10
	18-Feb-93	PES	12.9	6.54	6.36
	20-May-93	PES	12.9	6.17	6.73

NOTES:

Ft MSL = feet above Mean Sea Level

ES = Engineering-Science, Inc. PES = PES Environmental, Inc.

NA = Information not available at this date.

Table 2. Summary of Analytical Results for Groundwater Samples Through May, 1993
Emery Bay Plaza
1650 65th Street, Emeryville, California

Well Number	Sample Date	Sampled by	TPH as Gasoline	TPH as Diesel	Benzene	Toluene	Ethyl- Benzene	Total Xylenes	Purgeable Halocarbons	Lead
Hamber	<i>Date</i>		Gusonno	D10001	MCL = 0.001	DAL = 0.1		-		MCL = 0.005
B.834. O	Nov-89	EC	100	NA	8.4	7.4	2.4	13	0.015 *	0.05
MW-2		ES	54	NA NA	7.8	5.6	1.6	8.4	0.032 *	0.021
	Feb-90	ES		NA NA			1.6	7.6	0.032	0.025
	May-90	ES	40		7.8 9	7.5 8		8.9	0.040 *	0.0059
	Aug-90	ES	49	4.6			ND	7.4	0.040 NA	0.0059 NA
	Nov-90	ES	73	3.5	6.9	5.9	1.4 1	7.4 7.7	NA NA	NA NA
	Mar-91	ES	72	1.8	5.5	6.6				
	May-91	ES	31	ND	8.4	4.7	1.7	6.3	NA	NA
	Aug-91	ES	47 	ND	7.6	1.6	7.3	7.8	NA	NA
	Jan-92	PES	77	NA	10	8.7	2	7.6	NA	NA
	28-Feb-92	PES	70	NA	9.1	6.4	0.53	7.4	NA	NA
	28-May-92	PES	54	NA	8.0	4.8	2.4	6.2	NA	NA
	27-Aug-92	PES	47	NA	2.7	2.9	3.4	9.2	NA	NA
	10-Nov-92	PES	45	< 20	6.6	4.0	2.0	5.8	< 0.05	NA
	18-Feb-93	PES	14	NA	2.3	0.81	0.67	1.4	NA	NA
	20-May-93	PES	43	NA	7.3	5.2	1.5	5.5	NA	NA
MW-3	Nov-89	ES	0.13	NA	0.0022	ND	ND	0.003	ND	ND
	Feb-90	ES	ND	NA	0.0025	ND	ND	ND	NA	0.011
	May-90	ES	ND	ИĎ	0.002	ND	ND	ND	ND	NA
	Aug-90	ES	ND	0.8	0.0044	0.0029	ND	0.0054	NA	NA
	Nov-90	ES	0.9	0.8	0.0034	ND	ND	ND	NA	NA
	Mar-91	ES	ND	ND	0.025	0.025	0.0053	0.32	NA	NA
	May-91	ES	ND	ND	0.0026	ND	ND	ND	NA	NA
	Aug-91	ES	ND	ND	0.0019	ND	ND	ND	NA	NA
	Jan-92	PES	0.092	NA	0.0024	< 0.0003	0.0006	< 0.0003	NA	NA
	28-Feb-92	PES	0.160***	NA	0.0028	< 0.0003	0.0007	0.0005	NA	NA

Table 2. Summary of Analytical Results for Groundwater Samples Through May, 1993
Emery Bay Plaza
1650 65th Street, Emeryville, California

Well Number	Sample Date	Sampled by	TPH as Gasoline	TPH as Diesel	Benzene	Toluene	Ethyl- Benzene	Total Xylenes	Purgeable Halocarbons	Lead
	·····				MCL = 0.001	DAL = 0.1	MCL = 0.68	MCL = 1.75		MCL = 0.005
MW-3	28-May-92	PES	< 0.05	NA	0.0025	< 0.0005	< 0.0005	< 0.0005	NA	NA
	27-Aug-92	PES	0.37	NA	0.004	< 0.001	< 0.0005	< 0.0005	NA	NA
	10-Nov-92	PES	0.24	< 0.1	0.0042	< 0.0003	< 0.0003	< 0.0006	< 0.0003	NA
	18-Feb-93	PES	0.14	NA	0.0018	< 0.0005	< 0.0005	< 0.0005	NA	NA
	20-May-93	PES	0.072	NA	0.0031	< 0.0005	< 0.0005	< 0.0005	NA	NA
MW-4	Nov-89	ES	0.2	NA	0.0023	ND	ND	ND	ND	ND
	Feb-90	ES	ND	NA	ND	ND	ND	ND	NA	0.006
	May-90	ES	ND	ND	0.001	ND	ND	ND	ND	NA
	Aug-90	ES	ND	0.8	0.0089	0.0071	ND	0.0094	NA	NA
	Nov-90	ES	ND	0.7	0.0027	ND	ND	ND	NA	NA
	Mar-91	ES	NA	ND	0.003	ND	ND	ND	NA	NA
	May-91	ES	NA	ND	0.0024	ND	ND	ND	NA	NA
	Aug-91	ES	NA	ND	0.0015	ND	ND	ND	NA	NA
	Jan-92	PES	< 0.05	NA	0.0022	0.0004	< 0.0003	0.0007	NA	NA
	28-Feb-92	PES	< 0.05	NA	0.0016	< 0.0003	< 0.0003	0.0003	NA	NA
	28-May-92	PES	< 0.05	NA	0.0015	< 0.0005	< 0.0005	< 0.0005	NA	NA
	27-Aug-92	PES	0.08	NA	0.003	< 0.001	< 0.0005	0.0005	NA	NA
	10-Nov-92	PES	0.18	< 0.1	0.06	0.0009	< 0.0003	< 0.0006	< 0.0003	NA
	18-Feb-93	PE\$	0.06	NA	0.0017	< 0.0005	< 0.0005	< 0.0005	NA	NA
	20-May-93	PES	< 0.05	NA	0.0022	< 0.0005	<0.0005	< 0.0005	NA	NA
MW-5	Nov-89	ES	ND	NA	0.074	ND	ND	0.0042	ND	ND
	Feb-90	ES	ND	NA	0.2	ND	ND	ND	NA	0.012
	May-90	ES	ND	ND	0.11	ND	ND	ND	ND	NA
	Aug-90	ES	ND	0.7	0.066	0.0022	ND	0.0038	NA	NA
	Nov-90	ES	0.6	0.9	0.069	ND	ND	ND	NΑ	NA
	Mar-91	ES	ND	1.1	0.066	0.0023	ND	ND	NA	NA

Table 2. Summary of Analytical Results for Groundwater Samples Through May, 1993
Emery Bay Plaza
1650 65th Street, Emeryville, California

Well Number	Sample Date	Sampled by	TPH as Gasoline	TPH as Diesel	Benzene	Toluene	Ethyl- Benzene	Total Xylenes	Purgeable Halocarbons	Lead
					MCL = 0.001	DAL = 0.1	MCL = 0.68	MCL = 1.75		MCL = 0.005
MW-5	May-91	ES	ND	ND	0.11	ND	ND	ND	NA	NA
(cont.)	Aug-91	ES	ND	ND	0.078	0.0021	ND	ND	NA	NA
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Jan-92	PES	0.19	NA	0.09	0.0005	< 0.0003	0.0006	NA	NA
	28-Feb-92	PES	0.23***	NA	0.11	0.0009	< 0.0003	0.0005	NA	NA
	28-May-92	PES	0.13	NA	0.10	< 0.0005	< 0.0005	< 0.0005	NA	NA
	27-Aug-92	PES	0.52	NA	0.083	0.002	< 0.0005	< 0.0005	NA	NA
	10-Nov-92	PES	0.24	< 0.1	0.074	0.001	< 0.0003	< 0.0006	< 0.0003	NA
	18-Feb-93	PES	0.19	NA	0.056	0.0006	< 0.0005	< 0.0005	NA	NA
	20-May-93	PES	< 0.2	NA	0.056	< 0.002	< 0.002	< 0.002	NA	NΑ
MW-6	Мау-90	ES	NA	ND	ND	ND	ND	ND	ND	ND**
	Aug-90	ES	NA	ND	NA	NA	NA	NA	NA	ND**
	Nov-90	ES	1.2	1.4	0.0012	ND	ND	ND	0.0012	NΑ
	Mar-91	ES	ND	ND	ND	ND	ND	ND	NA	NA
	May-91	ES	ND	ND	ND	ND	ND	ND	NA	NA
	Aug-91	ES	ND	ND	ND	ND	ND	ND	NA	NA
	Jan-92	PES	< 0.05	NA	< 0.0003	< 0.0003	< 0.0003	< 0.0003	NA	NA
	28-Feb-92	PES	< 0.05	NA	< 0.0003	< 0.0003	< 0.0003	< 0.0003	NA	NA
	28-May-92	PES	< 0.05	NA	< 0.0005	< 0.0005	< 0.0005	< 0.0005	NA	NA
	27-Aug-92	PES	< 0.05 * * *	NA	< 0.0005	< 0.001	< 0.0005	< 0.0005	NA	NA
	10-Nov-92	PES	< 0.050	< 0.1	< 0.0003	< 0.0003	< 0.0003	< 0.0006	< 0.0003	NA
	18-Feb-93	PES	< 0.050	NΑ	< 0.0005	< 0.0005	< 0.0005	< 0.0005	NA	NA
	20-May-93	PES	<0.05	NA	< 0.0005	< 0.0005	< 0.0005	< 0.0005	NA	NA
MW-7	May-90	ES	NA	0.6	0.24	ND	ND	ND	0.24	ND**
	Aug-90	ES	ND	ND	0.081	0.0018	ND	ND	0.0844	ND**
	Nov-90	ES	ND	0.8	0.054	ND	ND	ND	0.054	NA
	Mar-91	ES	ND	ND	0.1	0.0036	ND	ND	NA	NA

Table 2. Summary of Analytical Results for Groundwater Samples Through May, 1993
Emery Bay Plaza
1650 65th Street, Emeryville, California

Well Number	Sample Date	Sampled by	TPH as Gasoline	TPH as Diesel	Benzene	Toluene	Ethyl- Benzene	Total Xylenes	Purgeable Halocarbons	Lead
			<u></u>	 	MCL = 0.001	DAL = 0.1	MCL = 0.68	MCL = 1.75		MCL = 0.005
MW-7	Maγ-91	ES	ND	ND	0.12	0.0027	ND	NĐ	NA	NA
(cont.)	Aug-91	ES	ND	ND	0.074	0.0033	ND	ND	NA	NA
, ,	Jan-92	PES	0.27	NA	0.025	0.0005	< 0.0003	0.0008	NA	NA
	1-Feb-92	PES	0.1***	NA	0.033	0.0007	< 0.0003	0.0007	NA	NA
	28-May-92	PES	0.15	NA	0.021	< 0.0005	< 0.0005	< 0.0005	NA	· NA
	27-Aug-92	PES	0.44	NA	0.011	0.001	< 0.0005	< 0.0005	NA	NA
	10-Nov-92	PES	0.37	< 0.1	0.031	0.0012	< 0.0003	0.0012	< 0.0003	NA
	18-Feb-93	PES	0.27	NA	0.077	0.0013	< 0.0005	0.0014	NA	NA
	20-May-93	PES	0.3	NA	0.15	0.003	< 0.002	0.003	NA	NA
EW-1	May-90	ES	20	ND	7.5	4.5	1	6.3	0.068	ND**
	Aug-90	ES	NA	3.5	6	4.2	ND	4.6	0.016 *	ND**
	Nov-90	ES	47	3.1	6	3.4	1	4.7	NA	NA
	17-Dec-90	ES	NA	NA	11	7.9	2.2	10	NA	NA
	19-Dec-90	ES	NA	NA	3.7	2.5	ND	2.3	NA	NA
	21-Dec-90	ES	NA	NA	3.2	2.2	ND	1.7	NA	NA
	27-Dec-90	ES	NA	NA	2.9	2.1	0.16	1.5	NA	NA
	4-Jan-91	ES	NA	NA	3.2	2.8	ND	ND	NA	NA
	11-Jan-91	ES	NA	NA	3	2.4	0.2	1.8	NA	NA
	6-Feb-91	ES	NA	NA	0.47	0.23	0.011	0.39	NA	NA
	13-Feb-91	ES	NA	NA	1.2	0.28	ND	0.36	NA	NA
	15-Mar-91	ES	NA	NA	0.13	0.085	0.006	0.17	NA	NA
	3-Jul-91	ES	NA	NA	1.3	0.95	0.22	1.4	NA	NA
	1-Aug-91	ES	NA	NA	0.22	0.19	0.013	0.27	NA	NA
	16-Aug-91	ES	NA	NA	0.17	0.16	0.013	0.19	NA	NA
	13-Nov-91	ES	NA	NA	3.1	0.27	0.04	0.22	NA	NA
	29-Jan-92	PES	2.7	NA	0.57	0.15	0.007	0.26	NA	NA
	3-Mar-92	PES	25	NA	3.6	2.6	0.53	2.6	NA	NA

Table 2. Summary of Analytical Results for Groundwater Samples Through May, 1993
Emery Bay Plaza
1650 65th Street, Emeryville, California

Well Number	Sample Date	Sampled by	TPH as Gasoline	TPH as Diesel	Benzene	Toluene	Ethyl- Benzene	Total Xylenes	Purgeable Halocarbons	Lead
		<u> </u>			MCL = 0.001	DAL = 0.1	MCL = 0.68	MCL = 1.75		MCL = 0.005
EW-1	28-May-92	PES	16	NA	3.3	3.2	0.75	2.6	NA	NA
(cont.)	29-Jun-92	PES	7	NA	2.2	3.1	0.27	1.4	NA	NA
_	21-Jul-92	PES	1.6	NA	0.22	0.017	< 0.0005	0.1	NA	NA
	27-Aug-92	PES	NS	NS	NS	NS	NS	NS	NS	NS
	23-Sep-92	PES	5.2	NA	1.1	0.59	0.1	1.0	NA	NA
	27-Oct-92	PES	1.3	NA	0.22	0.06	0.005	0.11	NA	NA
	24-Nov-92	PES	7.1	NA	1.4	1.1	0.12	0.89	NA	NA
	18-Feb-93	PES	7.2	NA	1.4	0.93	0.21	1	NA	NA
	09-Mar-93	PES	4.6	NA	0.99	0.75	0.062	0.84	NA	NA
	21-Apr-93	PES	4.9	NA	0.27	0.18	0.02	0.19	NA	NA
	13-May-93	PES	2.6	NA	0.52	0.11	0.023	0.33	NA	NA

NOTES:

ES = Engineering-Science, Inc.

PES = PES Environmental, Inc.

NA = Not analyzed

ND = Not detected above method detection limit.

NS = Not sampled.

<0.0005 = Not detected above indicated method detection limit.

MCL = California Maximum Contaminant Level, current as of January 1991.

DAL = Department of Health Services Action Levels, current as of January 1991.


TPH = Total Petroleum Hydrocarbons

^{* = 1,2-}Dichlorethane concentration (only 1,2-Dichloroethane detected).

^{** =} Organic Lead

^{*** =} TPH quantified as gasoline but chromatogram pattern was not typical of gasoline.

^{**** =} Small amount of Diesel 2 was detected in sample.




PES Environmental, Inc.Engineering & Environmental Services

REVIEWED BY

Site Location Map 1650 65th Street Emeryville, California

•




Er

PES Environmental, Inc.
Engineering & Environmental Services

Well Location Map 1650 65th Street Emeryville, California

JOB NUMBER REVIEWED 131.01.003






Groundwater Elevation Contours on May 20, 1993 1650 65th Street Emeryville, California

JOB NUMBER REVIEWED BY 131.01.003

DATE 6/93 REVISED DATE

REVISED DATE






Dissolved Hydrocarbons in Groundwater on May 20, 1993 1650 65th Street Emeryville, California

4

JOB NUMBER REVIEWED BY 131.01.003

DATE 6/93 REVISED DATE

REVISED DATE



BLAINE TECH SERVICES INC.

985 TIMOTHY DRIVE SAN JOSE, CA 95133 (408) 995-5535 FAX (408) 293-8773

June 4, 1993



PES Environmental, Inc. 1682 Novato Blvd., Suite 100 Novato, CA 94947

Attn: Paul Lohman

SITE: P.O. Partners 1650 65th Street Emeryville, California

DATE: May 20, 1993

GROUNDWATER SAMPLING REPORT 930520-A-1

Blaine Tech Services, Inc. performs specialized environmental sampling and documentation as an independent third party. In order to avoid compromising the objectivity necessary for the proper and disinterested performance of this work, Blaine Tech Services, Inc. does not participate in the interpretation of analytical results or become involved with the marketing or installation of remedial systems.

This report deals with the groundwater well sampling performed by our firm in response to your request. Data collected in the course of our work at the site is presented in the TABLE OF WELL MONITORING DATA. This data was collected during our inspection, well evacuation, and sample collection. Measurements include the total depth of the well and depth to water. Water surfaces were further inspected for the presence of immiscibles. A series of electrical conductivity, pH, and temperature readings were obtained during well evacuation and at the time of sample collection. Recharge performance can be evaluated by comparing the anticipated three, four, or five case volume evacuation gallonage with the volume which could actually be purged.

TABLE OF WELL MONITORING DATA

Well I.D.	MW-2			MW-3			MW-4			MW-5		
Date Sampled	05/20/9	3		05/20/	93		05/20/9	3		05/20/	93	
Well Diameter (in.)	2			4			4			4		
Total Well Depth (ft.)	26.66			18.29			15.92			18.04		
Depth To Water (ft.)	12.00			8.21			8.21			6.29		
Free Product (in.)	NONE			NONE			NONE			NONE		
Reason If Not Sampled												
							5.01			7.63		
1 Case Volume (gal.)	2.39			6.55			_			7.03		
Did Well Dewater?	МО			NO			NO					
Gallons Actually Evacuated	7.5			20.0			16.0			23.0		
Purging Device	BAILER			MIDDLE	BURG		MIDDLEB	URG		MIDDLE	BURG	
Sampling Device	BAILER			BAILER			BAILER			BAILER	t .	
	15-10	15.00	15:26	12:41	12:48	12:55	13;38	13:44	13:50	11:00	11:08	11:16
Time	15:18	15:22		65.1	64.4	65.5	70.0	69.7	69.7	64.6	64.6	64.6
Temperature (Fahrenheit)	66.1	65.2	65.7		7.9	7.9	70.0	8.0	8,0	7.4	7.2	7.2
рН	6.3	8.0	8.1	7,8					8800	2900	3000	3000
Conductivity (micromhos/cm)	8000	6400	5800	4000	4100	4000	8400	8700				
Nephelometric Turbidity Units	>200	>200	>200	14.46	14.38	14.71	20.3	18.12	18.84	22.7	11.96	7.80
BTS Chain of Custody	930520-	-A-1		930520	-A-1		930520-	A-1		930520	-A-1	
BTS Sample I.D.	MW-2			MW-3			MW-4			MW-5		
DHS HMTL Laboratory		O COAST		COAST	TO COAS	т	COAST T	O COAST		COAST	TO COAS	Ť
Analysis		S), BTEX			AS), B1			S), BTEX			AS), BI	
Wilsthore	III (Gr	WALLEY		1111 (0	,		2011 (01)	-,, 515%			,,	

TABLE OF WELL MONITORING DATA

Well I.D.	MW-6			MW-7		
Date Sampled	05/20/93	3		05/20/9	3	
Well Diameter (In.)	4			4		
Total Well Depth (ft.)	18.77			18.80		
Depth To Water (ft.)	8.46			6.17		
	WAVE			Mana		
Free Product (in.)	NONE			NONE		
Reason If Not Sampled						
1 Case Volume (gal.)	6.70			8,20		
Did Well Dewater?	NO			NO		
Gallons Actually Evacuated	21.0			25.0		
Purging Device	MIDDLEBU	IRG		MIDDLEB	URG	
Sampling Device	BAILER			BAILER		
Time	14:13	14:20	14:27	11:37	11:46	11:55
Temperature (Fahrenheit)	66.5	66.5	66.4	63.6	63.7	63.2
На	8.2	8.2	8.2	7.6	7.7	7.8
Conductivity (micromhos/cm)	>10.000	>10,000	>10,000	1900	1700	1900
Nephelometric Turbidity Units	13.29	8.74	14.82	42.1	19.9	19.4
BTS Chain of Custody	930520-A	<u>-1</u>		930520-	A-1	
BTS Sample I.D.	MW-6			MW-7		
DHS HMTL Laboratory	COAST TO	COAST		COAST T	O COAST	
Analysis	TPH (GAS				S), BTEX	

Selection of Sampling Equipment

The determination of what apparatus is to be used on particular wells may be made by the property owner, but is usually made by the professional consultant directing the performance of the monitoring on the property owner's behalf. When no specific requirement is made, our personnel will select equipment that will accomplish the work in the most efficient manner. Our personnel are equipped with a variety of sampling devices that include USGS/Middleburg pumps, down hole electric submersible pumps, air lift pumps, suction pumps, and bailers made of both Teflon and stainless steel.

USGS/Middleburg pumps and bailers were selected for the collection of samples at this site.

USGS/Middleburg Positive Displacement Sampling Pumps: USGS/Middleburg positive displacement sampling pumps are EPA approved pumps appropriate for use in wells down to two inches in diameter and depths up to several hundred feet. The pump contains a flexible Teflon bladder which is alternately allowed to fill with well water and then collapsed. Actuation of the pump is accomplished with compressed air supplied by a single hose to one side of the Teflon membrane. Water on the other side of the membrane is squeezed out of the pump and up a Teflon conductor pipe to the surface. Evacuation and sampling are accomplished as a continuum. The rate of water removal is relatively slow and loss of volatiles almost non-existent. There is only positive pressure on the water being sampled and there is no impeller cavitation or suction. The pumps can be placed at any location within the well, can draw water from the very bottom of the well case, and are virtually immune to the erosive effects of silt or lack of water which destroy other types of pumps.

Disadvantages associated with Middleburg pumps include their high cost, low flow rate, temperamental operation, and cleaning requirements which are both elaborate and time consuming.

Bailers: A bailer, in its simplest form, is a hollow tube which has been fitted with a check valve at the lower end. The device can be lowered into a well by means of a cord. When the bailer enters the water, the check valve opens and liquid flows into the interior of the bailer. The bottom check valve prevents water from escaping when the bailer is drawn up out of the well.

Two types of bailers are used in groundwater wells at sites where fuel hydrocarbons are of concern. The first type of bailer is made of a clear material such as acrylic plastic and is used to obtain a sample of the surface and the near surface liquids in order to detect the presence of visible or measurable fuel hydrocarbon floating on the surface. The second type of bailer is made of Teflon or stainless steel and is used as an evacuation and/or sampling device.

Bailers are inexpensive and relatively easy to clean. Because they are manually operated, variations in operator technique may have a greater influence than would be found with more automated sampling equipment. Also where fuel hydrocarbons are involved, the bailer may include near surface contaminants that are not representative of water deeper in the well.

STANDARD PRACTICES

Evacuation

Groundwater well sampling protocols call for the evacuation of a sufficient volume of water from the well to insure that the sample is collected from water than has been newly drawn into the well from the surrounding geologic formation. The protocol used on these wells called for a volumetric removal of three case volumes with stabilization of standard water parameters. There are situations where up to ten case volumes of evacuation may be removed, especially when attempting to stabilize turbidity in undeveloped wells. Different professional consultants may specify different levels of evacuation prior to sampling or may request that specific parameters be used to determine when to collect the sample. Our personnel use several standard instruments to record the changes in parameters as the well is evacuated. These instruments are used regardless of whether or not a specific volumetric standard has been called for. As a result, the consultant will always be provided with a record of the pH, EC, and temperature changes that occurred during the evacuation process. Additional information obtained with different types of instruments (such as dissolved oxygen and turbidity meters) can also be collected if requested in advance.

Effluent Materials

The evacuation of purge water creates a volume of effluent water which, in most cases, must be contained. Blaine Tech Services, Inc. will place this water in appropriate containers of the client's choice or bring new DOT 17 E drums to the site which are appropriate for the containment of the effluent materials. The determination of how to properly dispose of the effluent water must usually await the results of laboratory analyses of the sample collected from the groundwater well.

Observations and Measurements

Included in the scope of work are routine measurements and investigative procedures which are intended to determine if the wells are suitable for evacuation and sampling. These include measurement (from the top of the well case) of the total depth of the well; the depth to water, and the thickness of any free product zone (FPZ) encountered. The presence of a significant free product zone may interfere with efforts to collect a water sample that accurately reflects the condition of groundwater lying below the FPZ. This interference is caused by adhesion of petroleum to any device being lowered through the FPZ and the likelihood that minute globules of petroleum may break free of the sampling device and be included in the sample. Accordingly, evaluation of analytical results from

wells containing any amount of free petroleum should take into account the possibility that positive results have been skewed higher by such an inclusion. The decision to sample or not sample such wells is left to the discretion of our field personnel at the site and the consultant who establishes sampling guidelines based on the need for current information on groundwater conditions at the site.

Sampling Methodology

Samples were obtained by standardized sampling procedures that follow an evacuation and sample collection protocol. The sampling methodology conforms with State and Regional Water Quality Control Board standards and specifically adheres to EPA requirements for apparatus, sample containers and sample handling as specified in publication SW 846 and the T.E.G.D. which is published separately.

Sample Containers

Sample material is collected in specially prepared containers appropriate to the type of analyses intended. Our firm uses new sample containers of the type specified by either EPA or the RWQCB. Often times analytical laboratories wish to supply the sample containers because checks performed on these bottles are often part of a comprehensive laboratory QC program. In cases where the laboratory does not supply sample containers our personnel collect water samples in new containers that are appropriate to the type of analytical procedure that the sample is to receive. For example, 40 ml volatile organic analysis vials (VOAs) are used when analysis for gasoline and similar light volatile compounds is intended. These containers are prepared according to EPA SW 846 and will usually contain a small amount of preservative when the analysis is for TPH as gasoline or EPA 602. Vials intended for EPA 601 analysis and EPA 624 GCMS procedures are not preserved. The closure of volatile organic analysis water sample containers is accomplished with an open headed (syringe accessible) plastic screw cap brought down on top of a Teflon faced septum which is used to seal the sample without headspace.

Water samples intended for semivolatile and nonvolatile analysis such as total oil and grease (TOG) and diesel (TPH HBF) are collected and transported in properly prepared new glass liter bottles. Dark amber glass is used in the manufacture of these bottles to reduce any adverse effect on the sample by sunlight. Antimicrobial preservative may be added to the sample liquid if a prolonged holding time is expected prior to analysis. Closure is accomplished with a heavy plastic screw cap.

Groundwater well samples intended for metals analysis are transported in new plastic bottles and preserved with nitric acid. Our personnel can field filter the sample liquid prior to placing it in the sample container if instructed to perform this procedure.

Sample Handling Procedures

Water samples are collected in any of several appropriate devices such as bailers, Coliwasas, Middleburg sampling pumps etc. which are described in detail only as warranted by their employment at a given site. Sample liquid is decanted into new sample containers in a manner which reduces the loss of volatile constituents and follows the applicable EPA procedures for handling volatile organic and semi-volatile compounds.

Groundwater samples that are to receive metals analyses can be filtered prior to being placed in the plastic sample bottles that contain the nitric acid preservative. The filtration process employs new glass containers which are discarded and laboratory quality disposable filtering containers which are also discarded. A frequently used filtering procedure employs a vacuum pump to draw sample material through a 0.45 micron filter. The 0.45 micron pore size is standard, but the amount of filter available varies with the type of package selected. Filters are selected on the basis of the relative turbidity of the water sample. Samples which are relatively clean can be efficiently filtered with relatively inexpensive filters while very turbid water will require a very large filter with a high tolerance for sediments. One of several such filters our firm uses are the Nalgene Type A filters in which an upper and lower receptacle chamber are affixed to the filter. Sample material is poured into the upper chamber and a vacuum pump attached to the lower chamber. Simple actuation of the vacuum pump induces the flow of water through the filter and into the lower chamber. The sample is then decanted into the laboratory container and the filter assembly discarded. Cartridge type flow-through filters are more expensive but can be fitted directly to the discharge line of most sampling pumps (USGS/Middleburg pumps) and electric submersible pumps.

Following collection, samples are promptly placed in an ice chest containing prefrozen blocks of an inert ice substitute such as Blue Ice or Super Ice. The samples are maintained in either an ice chest or a refrigerator until delivered into the custody of the laboratory.

Sample Designations

All sample containers are identified with both a sampling event number and a discrete sample identification number. Please note that the sampling event number is the number that appears on our chain of custody. It is roughly equivalent to a job number, but applies only to work done on a particular day of the year rather than spanning several days as jobs and projects often do.

Chain of Custody

Samples are continuously maintained in an appropriate cooled container while in our custody and until delivered to the laboratory under our standard chain of custody. If the samples are taken charge of by a different party (such as another person from our office, a courier, etc.) prior to being delivered to the laboratory, appropriate release and acceptance records are made on the chain of custody (time, date, and signature of the person releasing the samples followed by the time, date and signature of the person accepting custody of the samples).

Hazardous Materials Testing Laboratory

The samples obtained at this site were transported in cooled ice chest to the office of Blaine Tech Services, Inc. to be stored in a refrigerator overnight. The following day, the samples were released into the custody of a courier for delivery to Coast to Coast Analytical Services.

Personnel

All Blaine Tech Services, Inc. personnel receive 29 CFR 1910.120(e)(2) training as soon after being hired as is practical. In addition, many of our personnel have additional certifications that include specialized training in level B supplied air apparatus and the supervision of employees working on hazardous materials sites. Employees are not sent to a site unless we are confident they can adhere to any site safety provisions in force at the site and unless we know that they can follow the written provisions of an SSP and the verbal directions of an SSO.

In general, employees sent to a site to perform groundwater well sampling will assume an OSHA level D (wet) environment exists unless otherwise informed. The use of gloves and double glove protocols protects both our employees and the integrity of the samples being collected. Additional protective gear and procedures for higher OSHA levels of protection are available.

Decontamination

All apparatus is brought to the site in clean and serviceable condition. The equipment is decontaminated after each use and before leaving the site. Decontamination procedures include complete disassembly of the device to a point where a jet of steam cleaner water can be directed onto all the internal surfaces. Blaine Tech Services, Inc. frequently modifies apparatus to allow complete disassembly and proper cleaning.

Please call if we can be of any further assistance.

Richard C. Blaine

RCB/skt

attachments: chain of custody

BLAINE		IMOTHY DRIVE IOSE, CA 95133			CONDL	JCT ANA	LYSIS T	O DETECT		ILAB COL	27	6	dasi	<u>/ DHS</u> #	_
ECH SERVICES	inc. FA)	(408) 995-5535 (408) 293-8773								ALL ANALYSES MUS SET BY CALIFORNIA	T MEET : DHS AN	SPECIFIO D			;
HAIN OF CUSTODY 93052019 LIENT DE C			RS							□ EPA □ LIA □ OTHER			□RWGC	B REGION	_
THE POPPLE	COMENTIK TOEKS		CONTAINERS	13						SPECIAL INSTRUCT		5 <i>C</i> .	- 1080 1311	nembel	
1650 la	574 J	7	ITE ALL C	3						Att	rv: R	ave L	chman		
MARYVII.	MATRIX C	ONTAINERS	= COMPOSITE ALL	af						Loui	f-	e			'n
AMPLE LD.	\o ≤ \ TOT/	N.	ő				\perp		L	ADD'L INFORMATION			CONDITION	LAB SAMPLE #	
<u> 4445 — </u>	W 3										Rev	fine			_
mu/7	3										l				
111/3	3														_
ull 4	3										,			•	
	1 3												,		_
 	7/3								1		1	/			_
		-			-	_				 	V				_
			-		-				+					 	
		+	\vdash		\dashv										
						_			ļ						¥.,
,															
AMPLING DATE TIME	SAMPLING PERFORME	ED BY	1/1	UU.	7		1	,	1	RESULTS NEEDED NO LATER THAN					
ELEASED BY		(NOATI			TIME	'10	REG	EIVED BY		7			DATE 5-3/-	TIME 93 14:11	_
ELEASED BY	···	DATI			TIME	7.0	HE	CEIVEO BY	/// /	1			DATE	TIME	Η,
LEASED BY		DATE	Ē		TIME		/ REC	CEIVED BY	,		-		DATE	TIME	-
HIPPED VIA		IDATE	E SEN	 -	TIME	CENT	7	LEA#							_



San Luis Obispo, CA • Benicia, CA • Camarillo, CA • San Jose, CA • Goleta, CA Anaheim, CA • Tempe, AZ • Valparaiso, IN • Westbrook, ME • Indianapolis, IN

NorCal Division (San Jose Laboratory) 2059 Junction Ave.

San Jose, CA 95131 (408) 955-9077

CLIENT: Paul Lohman

PES Environmental Inc

1682 Novato Boulevard, Suite 100

Novato, CA 94947

Lab Number: JJ-0653-6

Project : 930520A1 PO Partners,

Emeryville

Analyzed : 06/01/93

Analyzed by: CB

Method : E8020/8015M

REPORT OF ANALYTICAL RESULTS

Page 1 of 1

SAMPLE DESCRIPTION	MATRIX	SAMPLED BY	SAMI	PLED DATE	RECEIVED
MW 2	Monitoring Water	Jeff Cartes	05	5/20/93	05/21/93
CONSTITUENT		(CAS RN)	*PQL µg/L	RESULI µg/L	r note
BTEX + TPH (Gasoline)					1
Benzene			200.	7300.	
Toluene			200.	5200.	
Ethylbenzene			200.	1500.	
Xylenes			200.	5500.	
Total Petroleum Hydrocarbons (Gasoline)		20000.	43000.	
Percent Surrogate Recovery	•			103.	

San Jose Lab Certifications: CAELAP #1204

*RESULTS listed as 'ND' were not detected at or above the listed PQL (Practical Quantitation Limit)

(1) EXTRACTED by EPA 5030 (purge-and-trap)

06/01/93 GC2/601B308 MC/mcc GC2-060193 Respectfully submitted,

COAST-TO-COAST ANALYTICAL SERVICES, INC.

Marissa Coronel Laboratory Director



San Luis Obispo, CA • Benicia, CA • Camarillo, CA • San Jose, CA • Goleta, CA Anaheim, CA • Tempe, AZ • Valparaiso, IN • Westbrook, ME • Indianapolis, IN

NorCal Division (San Jose Laboratory) 2059 Junction Ave.

San Jose, CA 95131 (408) 955-9077

CLIENT: Paul Lohman

PES Environmental Inc

1682 Novato Boulevard, Suite 100

Novato, CA 94947

Lab Number: JJ-0653-3

Project : 930520Al PO Partners,

Emeryville

Analyzed : 05/28/93

Analyzed by: CB

Method : E8020/8015M

REPORT OF ANALYTICAL RESULTS

Page 1 of 1

SAMPLE DESCRIPTION	MATRIX	MATRIX SAMPLED BY SAMPLED DAT					
MW 3	Monitoring Water	Jeff Cartes	05	5/20/93	05/21/93		
CONSTITUENT	· · · · · · · · · · · · · · · · · · ·	(CAS RN)	*PQL µg/L	RESULI µg/L	note		
BTEX + TPH (Gasoline)			<u></u>		1		
Benzene			0.5	3.1			
Toluene			0.5	ND			
Ethylbenzene			0.5	ND			
Xylenes			0.5	ND			
Total Petroleum Hydrocarbons (Gasoline	⊋)		50.	72.			
Percent Surrogate Recovery				105.			

San Jose Lab Certifications: CAELAP #1204

*RESULTS listed as 'ND' were not detected at or above the listed PQL (Practical Quantitation Limit)

(1) EXTRACTED by EPA 5030 (purge-and-trap)

06/01/93 GC2/527B335 MC/mcc GC2-052793 Respectfully submitted,

COAST-TO-COAST ANALYTICAL SERVICES, INC.

Marissa Coronel

Laboratory Director



San Luis Obispo, CA • Benicia, CA • Camarillo, CA • San Jose, CA • Goleta, CA Anaheim, CA • Tempe, AZ • Valparaiso, IN • Westbrook, ME • Indianapolis, IN

NorCal Division (San Jose Laboratory) 2059 Junction Ave.

San Jose, CA 95131 (408) 955-9077

CLIENT: Paul Lohman

PES Environmental Inc

1682 Novato Boulevard, Suite 100

Novato, CA 94947

Lab Number: JJ-0653-4

Project: 93052

: 930520A1 PO Partners,

Emeryville

Analyzed : 05/28/93

Analyzed by: CB

Method : E8020/8015M

REPORT OF ANALYTICAL RESULTS

Page 1 of 1

SAMPLE DESCRIPTION	MATRIX	SAMPLED BY	SAME	PLED DATE	RECEIVED
MW 4	Monitoring Water	Jeff Cartes	05	5/20/93	05/21/93
CONSTITUENT		(CAS RN)	*PQL µg/L	RESULI µg/L	NOTE
BTEX + TPH (Gasoline)					1
Benzene			0.5	2.2	
Toluene			0.5	ND	
Ethylbenzene			0.5	ND	
Xylenes			0.5	ND	
Total Petroleum Hydrocarbons (Gasol	ine)		50.	ND	
Percent Surrogate Recovery	-			106.	

San Jose Lab Certifications: CAELAP #1204

*RESULTS listed as 'ND' were not detected at or above the listed PQL (Practical Quantitation Limit)

(1) EXTRACTED by EPA 5030 (purge-and-trap)

06/01/93 GC2/527B334 MC/mcc GC2-052793 Respectfully submitted,

COAST-TO-COAST ANALYTICAL SERVICES, INC.

Marissa Coronel Laboratory Director



San Luis Obispo, CA • Benicia, CA • Camarillo, CA • San Jose, CA • Goleta, CA Anaheim, CA • Tempe, AZ • Valparaiso, IN • Westbrook, ME • Indianapolis, IN

NorCal Division (San Jose Laboratory) 2059 Junction Ave.

San Jose, CA 95131 (408) 955-9077

CLIENT: Paul Lohman

PES Environmental Inc

1682 Novato Boulevard, Suite 100

Novato, CA 94947

Lab Number: JJ-0653-1

Project

: 930520A1 PO Partners,

Emeryville

Analyzed : 05/28/93

METAATTTE

Analyzed by: CB

Method : E8020/8015M

Page 1 of 1

SAMPLE DESCRIPTION	MATRIX	SAMPLED BY	SAM	PLED DATE	RECEIVED
MW 5	Monitoring Water	Jeff Cartes	0:	5/20/93	05/21/93
CONSTITUENT	,	(CAS RN)	*PQL µg/L	RESULI µg/L	r note
BTEX + TPH (Gasoline)					
Benzene			2.	56.	
Toluene			2.	ND	
Ethylbenzene			2.	ND	
Xylenes			2.	ND	
Total Petroleum Hydrocarbons (Gasoline)		200.	ND	
Percent Surrogate Recovery	•			105.	

REPORT OF ANALYTICAL RESULTS

San Jose Lab Certifications: CAELAP #1204

*RESULTS listed as 'ND' were not detected at or above the listed PQL (Practical Quantitation Limit)

(1) EXTRACTED by EPA 5030 (purge-and-trap)

06/01/93 GC2/527B337 MC/mcc GC2~052793 Respectfully submitted,

COAST-TO-COAST ANALYTICAL SERVICES, INC.

Marissa Coronel

Laboratory Director



San Luis Obispo, CA • Benicia, CA • Camarillo, CA • San Jose, CA • Goleta, CA Anaheim, CA • Tempe, AZ • Valparaiso, IN • Westbrook, ME • Indianapolis, IN

NorCal Division (San Jose Laboratory) 2059 Junction Ave.

San Jose, CA 95131 (408) 955-9077

CLIENT: Paul Lohman

PES Environmental Inc

1682 Novato Boulevard, Suite 100

Novato, CA 94947

Lab Number: JJ-0653-5

Project : 930520A1 PO Partners,

Emeryville

Analyzed : 05/28/93

Analyzed by: CB

Method : E8020/8015M

REPORT OF ANALYTICAL RESULTS

Page 1 of 1

SAMPLE DESCRIPTION	MATRIX	SAMPLED BY	SAMI	PLED DATE	RECEIVED	
MW 6	Monitoring Water	g Jeff Cartes 05/20/9		5/20/93	3 05/21/93	
CONSTITUENT		(CAS RN)	*PQL μg/L	RESULI µg/L	NOTE	
BTEX + TPH (Gasoline)				MD	1	
Benzene Toluene			0.5 0.5	ND ND		
Toruene Ethylbenzene			0.5	ND		
Xylenes			0.5	ND		
Total Petroleum Hydrocarbons (Gasolin	ie)		50.	ND		
Percent Surrogate Recovery	•			102.		

San Jose Lab Certifications: CAELAP #1204

*RESULTS listed as 'ND' were not detected at or above the listed PQL (Practical Quantitation Limit)

(1) EXTRACTED by EPA 5030 (purge-and-trap)

06/01/93 GC2/527B329 MC/mcc GC2-052793 Respectfully submitted,

COAST-TO-COAST ANALYTICAL SERVICES, INC.

Marissa Coronel

Laboratory Director



San Luis Obispo, CA • Benicia, CA • Camarillo, CA • San Jose, CA • Goleta, CA Anaheim, CA • Tempe, AZ • Valparaiso, IN • Westbrook, ME • Indianapolis, IN

NorCal Division (San Jose Laboratory) 2059 Junction Ave.

San Jose, CA 95131 (408) 955-9077

CLIENT: Paul Lohman

PES Environmental Inc

1682 Novato Boulevard, Suite 100

Novato, CA 94947

Lab Number: JJ-0653-2

Project

: 930520A1 PO Partners,

Emeryville

Analyzed

: 05/28/93

Analyzed by: CB

Method

: E8020/8015M

REPORT OF ANALYTICAL RESULTS

Page 1 of 1

SAMPLE DESCRIPTION	MATRIX	MATRIX SAMPLED BY SAMPLED DA				
MW 7	Monitoring Water	Jeff Cartes	0	05/20/93 0		
CONSTITUENT		(CAS RN)	*PQL µg/L	RESULI µg/L	NOTE	
BTEX + TPH (Gasoline)					1	
Benzene			2.	150.		
Toluene			2.	3.		
Ethylbenzene			2.	ND		
Xylenes			2.	3.		
Total Petroleum Hydrocarbons (Gasoline	:)		200.	300.		
Percent Surrogate Recovery	•			107.		

San Jose Lab Certifications: CAELAP #1204

*RESULTS listed as 'ND' were not detected at or above the listed PQL (Practical Quantitation Limit) (1) EXTRACTED by EPA 5030 (purge-and-trap)

06/01/93 GC2/527B337 MC/mcc GC2-052793 Respectfully submitted,

COAST-TO-COAST ANALYTICAL SERVICES, INC.

Marissa Coronel Laboratory Director



San Luis Obispo, CA • Benicia, CA • Camarillo, CA • San Jose, CA • Goleta, CA Anaheim, CA • Tempe, AZ • Valparaiso, IN • Westbrook, ME • Indianapolis, IN

NorCal Division (San Jose Laboratory) 2059 Junction Ave.

San Jose, CA 95131 (408) 955-9077

QC Batch ID: GC2-052793

CLIENT: Coast-to-Coast Analytical Services, Inc.

Analyzed : 05/27/93

Analyzed by: CB

Method :

: E8020/8015M

METHOD BLANK

REPORT OF ANALYTICAL RESULTS

Page 1 of 1

SAMPLE DESCRIPTION	MATRIX	SAMPLED BY	SA	MPLED DATE R	ECEIVED
METHOD BLANK	Aqueous				
CONSTITUENT		(CAS RN)	*PQL μg/L	RESULT µg/L	NOTE
PURGEABLE AROMATICS (BTEX)				•	
Benzene			0.5	ND	
Toluene			0.5	ND	
Ethylbenzene			0.5	ND	
Xylenes			0.5	ND	
Total Petroleum Hydrocarbons (Gasoline	;)		50.	ND	

San Jose Lab Certifications: CAELAP #1204

*RESULTS listed as 'ND' were not detected at or above the listed PQL (Practical Quantitation Limit)

06/01/93 GC2/527B304 MC/mcc JJ0631-1 Respectfully submitted,

COAST-TO-COAST ANALYTICAL SERVICES, INC.

Marissa Coronel

Laboratory Director



San Luis Obispo, CA • Benicia, CA • Camarillo, CA • San Jose, CA • Goleta, CA Anaheim, CA • Tempe, AZ • Valparaiso, IN • Westbrook, ME • Indianapolis, IN

NorCal Division (San Jose Laboratory) 2059 Junction Ave.

San Jose, CA 95131 (408) 955-9077

QC Batch ID: GC2-052793

CLIENT: Coast-to-Coast Analytical Services, Inc.

: 05/27/93 Analyzed

Analyzed by: CB

: E8020/8015M Method

QC MATRIX SPIKE

REPORT OF ANALYTICAL RESULTS

Page 1 of 1

SAMPLE DESCRIPTION	MATRIX	SAMPLED BY	7	SAMPLED DA	TE RECE	IVED
MATRIX SPIKE	Aqueous			-		
CONSTITUENT		ORIGINAL RESULT	SPIKE AMOUNT	RESULT µg/L	₽REC	NOTE
PURGEABLE AROMATICS (BTEX)						_
Benzene		ND	5.0	4.8	96.	
Toluene		ND	5.0	4.8	96.	
Ethylbenzene		ND	5.0	4.5	90.	
Xylenes		ND	15.	14.	93.	
Total Petroleum Hydrocarbons (Gasolin	ne)	ND	120.	130.	108.	

San Jose Lab Certifications: CAELAP #1204

*RESULTS listed as 'ND' were not detected at or above the listed PQL (Practical Quantitation Limit)

06/01/93 GC2/527B323 MC/mcc JJ0631-1

Respectfully submitted,

COAST-TO-COAST ANALYTICAL SERVICES, INC.

Marissa Coronel

Laboratory Director



San Luis Obispo, CA • Benicia, CA • Camarillo, CA • San Jose, CA • Goleta, CA Anaheim, CA • Tempe, AZ • Valparaiso, IN • Westbrook, ME • Indianapolis, IN

NorCal Division (San Jose Laboratory) 2059 Junction Ave.

San Jose, CA 95131 (408) 955-9077

QC Batch ID: GC2-052793

CLIENT: Coast-to-Coast Analytical Services, Inc.

: 05/27/93 Analyzed

Analyzed by: CB

Method

: E8020/8015M

QC MATRIX SPIKE REPORT OF ANALYTICAL RESULTS

Page 1 of 1

SAMPLE DESCRIPTION	MATRIX	SAMI	PLED BY	SAMPLED DATE RECEIVED			
MATRIX SPIKE DUPLICATE	Aqueous						<u></u>
CONSTITUENT		ORIGINAL RESULT	SPIKE AMOUNT	RESULT µg/L	%REC	%DIFF	NOTE
PURGEABLE AROMATICS (BTEX)	<u> </u>						
Benzene		ND	5.0	5.1	102.	6.1	
Toluene		ND	5.0	5.0	100.	4.1	
Ethylbenzene		ND	5.0	4.8	96.	6.5	
Xylenes		ND	15.	15.	100.	6.9	
Total Petroleum Hydrocarbons (Gasoline	:)	ND	120.	120.	100.	8.	

San Jose Lab Certifications: CAELAP #1204

*RESULTS listed as 'ND' were not detected at or above the listed PQL (Practical Quantitation Limit)

06/01/93 GC2/527B324 MC/mcc JJ0631-1

Respectfully submitted,

COAST-TO-COAST ANALYTICAL SERVICES, INC.

Marissa Coronel Laboratory Director

TECH SERVICES INC FAX (408) 293-8773 ALL ANALYSES MUST MEET SPECIFICATIONS AND DETECTION LIFE SET BY CALIFORNIA DHS AND RWQCB REGION I LIA OTHER SPECIAL INSTRUCTIONS BILL ANALYSES MUST MEET SPECIFICATIONS AND DETECTION LIFE SET BY CALIFORNIA DHS AND RWQCB REGION OTHER SPECIAL INSTRUCTIONS BILL ANALYSES MUST MEET SPECIFICATIONS AND DETECTION LIFE SET BY CALIFORNIA DHS AND RWQCB REGION OTHER SPECIAL INSTRUCTIONS BILL ANALYSES MUST MEET SPECIFICATIONS AND DETECTION LIFE SET BY CALIFORNIA DHS AND FAX (408) 293-8773 ALL ANALYSES MUST MEET SPECIFICATIONS AND FRWQCB REGION OTHER SPECIAL INSTRUCTIONS BILL ANALYSES MUST MEET SPECIFICATIONS AND DETECTION LIFE SET BY CALIFORNIA DHS AND FAX (408) 293-8773 ALL ANALYSES MUST MEET SPECIFICATIONS AND DETECTION LIFE SET BY CALIFORNIA DHS AND FRWQCB REGION ATTW. PAUL Lohmon FAX (408) 293-8773 ALL ANALYSES MUST MEET SPECIFICATIONS AND FRWQCB REGION OTHER SPECIAL INSTRUCTIONS BILL ANALYSES MUST MEET SPECIFICATIONS AND FRWQCB REGION FRWQCB REGION ATTW. PAUL Lohmon FRWGCB REGION ATTW. PAUL Lohmon FRWGCB REGION ATTW. PAUL LOHMON ATTW. PAUL LOHMON ATTW. PAUL LOHMON FRWGCB REGION ATTW. PAUL LOHMON FRWGCB RE	BLAINE	985 TIMOTHY E SAN JOSE, CA		C	ONDUCT ANA	LYSIS TO DE	TECT	ILAB COCE	stro	Coas	DHS#
CHAIN OF CUSTORY 205209 CLIENT RS ENVIRONMENTAL SITE PO PARTICLES CLIENT ROLL INSTRUCTIONS BILL TO RESERVITATION OF ATTO: PAUL Lobinary LATTU: PAUL Lobinary LATTU: PAUL Lobinary LATTU: PAUL Lobinary LAMPIELD SAMPLING PERFORMED BY MATE STATUS SAMPLING SAMPLING SAMPLING PERFORMED BY MATE STATUS RESULTS NEEDED NOLATER THAN STATUS SAMPLING PROBLEMS THAN STATUS SAMPLING SAMPLING SAMPLING PERFORMED BY MATE STATUS SAMPLING SAM								ALL ANALYSES MUS SET BY CALIFORNIA	T MEET SPECIFI	ICATIONS AI	NO DETECTION LIMITS
SAMPLING DATE TIME SAMPLING DATE TIME SAMPLING PERFORMED BY MATER TIME SAMPLED BY MATER	93052011		s					LIA		∏RWC	QCB REGION
SAMPLING DATE TIME COMPLETED SAMPLING PERFORMED BY MATE TIME SAMPLET TIME COMPLETED SAMPLET STATUS CONDITION LAB SAMPLE DATE TIME COMPLETED SAMPLET SAMPLING PERFORMED BY MATE TIME SAMPLET STATUS CONDITION LAB SAMPLE DATE TIME OF THE SAMPLING PERFORMED BY MATE TIME SAMPLING PERFORMED BY MATE TIME STATUS CONDITION LAB SAMPLE DATE TIME SAMPLING PERFORMED BY MATE TIME SAMPLING PERFORMED BY MATE TIME STATUS CONDITION LAB SAMPLE DATE TIME SAMPLING PERFORMED BY MATE TIME STATUS CONDITION LAB SAMPLE DATE TIME SAMPLE DATE TIME SAMPLE DATE TIME STATUS CONDITION LAB SAMPLE DATE TIME SAMPLE DATE TIME SAMPLE DATE TIME STATUS CONDITION LAB SAMPLE DATE TIME S	SITE POPALTA 1650 655 EMBRYVILLE	s St	COMPOSITE ALL	gra Otel				Brill to	PES E W. PAUL L	NVIVO	nmentsel
SAMPLING DATE TIME SAMPLING PERFORMED BY WILLS MULZ SAMPLING DATE TIME SAMPLING PERFORMED BY WILLS MELEASED BY WILLS MELEASED BY WILLS MATE TIME RECEIVED BY SAMPLING PERFORMED BY WILLS MATE TIME SECRIFICATION MATE	SAMPI.E I.D.	″ [™] TOTAL						ADD'L INFORMATION	STATUS	CONDITION	LAB SAMPLE #
SAMPLING DATE TIME SAMPLING PERFORMED BY WILLS WIN Z SAMPLING DATE TIME SAMPLING PERFORMED BY WILLS WELLS NEEDED NO LATER THAN WHELE ASED BY WILLS WHATE TIME RESULTS NEEDED NO LATER THAN WHICH ASED BY WILLS WHATE TIME RECEIVED BY S-21-93 14:10 RELEVED BY WILLS DATE TIME 15-21-93 14:10 DATE TIME 15/21/93 14:30 Shelle Hout 15/21/93 14:30 Shelle Hout	MW 5	10 3							Routine		136653-1
SAMPLING DATE TIME SAMPLING PERFORMED BY WILLS WHAT THE SAMPLING PERFORMED BY WILLS WHATE TIME RECEIVED BY DATE TIME TRELEMENT DATE TIME RECEIVED BY DATE TIME SOLUTION TO THE SAMPLING PERFORMED BY WILLS DATE TIME SOLUTION TO THE SAMPLING PERFORMED BY DATE SOLUTION TO THE SAMPLING PERFORMED	Mul 7	13									2
SAMPLING DATE TIME SAMPLING PERFORMED BY WILLS PRELEASED BY TO PERFORMED BY TO PE	Mul 3	1 2									3
SAMPLING DATE TIME SAMPLING PERFORMED BY WILLS PRELEASED BY TO PERFORMED BY TO PE		1 2 -						· · · · · · · · · · · · · · · · · · ·	·····	 	1
SAMPLING DATE TIME SAMPLING PERFORMED BY WILLS RESULTS NEEDED NO LATER THAN RELEASED BY RECEIVED BY RECEIVED BY DATE TIME S-21-93 14:10 RECEIVED BY RECEIVED BY DATE TIME S-21-93 14:10 SHULLE HOUTE S-21-93 14:10 SHULLE HOUTE S-21-93 14:10 SHULLE HOUTE	MW 7								/	 	
SAMPLING DATE TIME SAMPLING PERFORMED BY MILES RESULTS NEEDED NO LATER THAN RELEASED BY DATE TIME RESOLVED BY DATE TIME RELEASED BY DATE TIME STORY DATE TIME RECEIVED BY DATE TIME STORY DATE S	mw 6									1	5
RELEASED BY STATE TIME PRECEIVED BY DATE TIME 5-2,-93 14:10 TIME SECEIVED BY DATE TIME DATE TIME SOLVED BY DATE TIME DATE TIME SOLVED BY	MWZ	7 3							V	 	6
RELEASED BY DATE TIME RECEIVED BY DATE TIME 5-2,-93 14:10 RELEASED BY DATE TIME AECEIVED BY DATE TIME TIME TO SHIPLE TO STORY TO											ļ
RELEASED BY DATE TIME RECEIVED BY DATE TIME 5-2,-43 14:10 RELEASED BY DATE TIME AECEIVED BY DATE TIME DATE TIME 5-2,-43 14:10 RELEASED BY DATE TIME SECENCE BY DATE TIME 5-2,-43 14:10 RELEASED BY DATE TIME 5-2,-43 14:10										 	
RELEASED BY DATE TIME RECEIVED BY DATE TIME 5-2,-43 14:10 RELEASED BY DATE TIME AECEIVED BY DATE TIME DATE TIME 5-2,-43 14:10 RELEASED BY DATE TIME SECENCE BY DATE TIME 5-2,-43 14:10 RELEASED BY DATE TIME 5-2,-43 14:10											
RELEASED BY DATE TIME RECEIVED BY DATE TIME 5-2,-43 14:10 RELEASED BY DATE TIME AECEIVED BY DATE TIME DATE TIME 5-2,-43 14:10 RELEASED BY DATE TIME SECENCE BY DATE TIME 5-2,-43 14:10 RELEASED BY DATE TIME 5-2,-43 14:10	SAMPLING DATE TIME	SAMPLING PERFORMED BY	11/1				i	RESULTS NEEDED		1	<u> </u>
RELEMENTE DAVENDOIT (3) 10ATE TIME RECEIVED BY (43) DATE TIME S6/21/93 1430 Shelle Hoyt (3) 16/21/93 1430	100 100 RELEASED BY 1		NOATE			A REOFIVE	D BY			IDATE	TIME
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Old Ultio	U		13 1	4:10	Mhi	a 1/2	A.		5-21	-93 14:11
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	· /// // //	L (G)	DATE 05/2/		IME .	AECEIVE	DEV (1 C 3)	DATE	193 Who
🖈					<u>· / </u>	RECEIVE	D BY	noge	· · · · · ·	_ <u>,</u>	TIME
SHIPPED VIA DATE SENT TIME SENT COOLER #	SHIPPED VIA		DATE SEN	ır r	IME SENT	COOLER#					

.



CLIENT: Andy Briefer

PES Environmental Inc

Novato, CA 94947

1682 Novato Boulevard, Suite 100

Air, Water & Hazardous Waste Sampling, Analysis & Consultation Certified Hazardous Waste, Chemistry, Bacteriology & Bioassay Laboratories

San Luis Obispo, CA • Benicia, CA • Camarillo, CA • San Jose, CA • Goleta, CA Anaheim, CA • Tempe, AZ • Valparaiso, IN • Westbrook, ME • Indianapolis, IN

NorCal Division (Benicia Laboratory) 6006 Egret Court, Benicia, California 94510 (707) 747-2757 FAX (707)747-2765

Lab Number: BJ-0365-1

Project : 131.01.00.001 P.O.

Partners

Analyzed : 05/20/93

Analyzed by: HC

Method: EPA 8260

REPORT OF ANALYTICAL RESULTS

Page 1 of 1

		SAMPLED DATE RECEIVED			
Aqueous	Paul Lohman	05/13/93		05/14/93	
	(CAS RN)	*PQL µg/L	RESULI µg/L	r note	
				1,2,3	
	(71432)	1.	520.		
	(108883)	2.	110.		
	(100411)	1.	23.		
		1.	330.		
		100.	2600.		
			94.		
	Aqueous	(CAS RN) (71432) (108883)	(CAS RN) *PQL μg/L (71432) 1. (108883) 2. (100411) 1.	(CAS RN) *PQL RESULT μg/L μg/L (71432) 1. 520. (108883) 2. 110. (100411) 1. 23. 1. 330. 100. 2600.	

Benicia Lab Certifications: CAELAP #1719; L.A.Co.CSD #10185

*RESULTS listed as 'ND' were not detected at or above the listed PQL (Practical Quantitation Limit)

- (1) EXTRACTED by EPA 5030 (purge-and-trap)
- (2) ANALYZED by CAL DHS DRAFT TPH (modified) and EPA 8240 (GC/MS)
- (3) High concentration of some analytes caused the sample to be run diluted resulting in raised Practical Quantitation Limits for analytes. Refer to instrument blank for undiluted Practical Quantitation Limits.

05/21/93 INCOS 50-387 EPP/dpo/epp BJE2011 Respectfully submitted,

COAST-FO-COAST ANALYTICAL SERVICES, INC.

Emma P. Popek, CHMM

Laboratory Manager



San Luis Obispo, CA • Benicia, CA • Camarillo, CA • San Jose, CA • Goleta, CA Anaheim, CA • Tempe, AZ • Valparaiso, IN • Westbrook, ME • Indianapolis, IN

NorCal Division (Benicia Laboratory) 6006 Egret Court, Benicia, California 94510

(707) 747-2757FAX (707)747-2765

QC Batch ID: BJE20I1

CLIENT: Coast-to-Coast Analytical Services, Inc.

: 05/20/93 Analyzed

Analyzed by: HC

: EPA 8260 Method

METHOD BLANK

REPORT OF ANALYTICAL RESULTS

Page 1 of 1

SAMPLE DESCRIPTION	MATRIX	SAMPLED BY	SAI	MPLED DATE R	ECEIVED
METHOD BLANK	Aqueous				
CONSTITUENT		(CAS RN)	*PQL μg/L	RESULT μg/L	NOTE
BTEX + TPH (Gasoline)					1,2
Benzene		(71432)	0.5	ND	
Toluene		(108883)	1.	ND	
Ethylbenzene		(100411)	0.5	ND	
Xylenes, Total		•	0.5	ND	
Total Petroleum Hydrocarbons (Gasoline	}		50.	ND	
Percent Surrogate Recovery	•			89.	

Benicia Lab Certifications: CAELAP #1719; L.A.Co.CSD #10185

*RESULTS listed as 'ND' were not detected at or above the listed PQL (Practical Quantitation Limit)

(1) EXTRACTED by EPA 5030 (purge-and-trap)

(2) ANALYZED by CAL DHS DRAFT TPH (modified) and EPA 8240 (GC/MS)

05/21/93 INCOS 50-387 EPP/dpo/epp BJ0365-1

Respectfully submitted,

COAST-TO-COAST ANALYTICAL SERVICES, INC.

Emma P. Popek, CHMM

Laboratory Manager



San Luis Obispo, CA • Benicia, CA • Camarillo, CA • San Jose, CA • Goleta, CA Anaheim, CA • Tempe, AZ • Valparaiso, IN • Westbrook, ME • Indianapolis, IN

NorCal Division (Benicia Laboratory) 6006 Egret Court, Benicia, California 94510 (707) 747-2757 FAX (707)747-2765

QC Batch ID: BJE20I1

CLIENT: Coast-to-Coast Analytical Services, Inc.

Analyzed : 05/20/93

Analyzed by: HC

Method : EPA 8260

QC SPIKE

REPORT OF ANALYTICAL RESULTS

Page 1 of 1

SAMPLE DESCRIPTION	MATRIX	SAMPLED B	Y	SAMPLED DAT	TE RECE	IVED
QC SPIKE	Aqueous					
CONSTITUENT		*PQL μg/L	SPIKE AMOUNT	result µg/l	*REC	NOTE
BTEX + TPH (Gasoline)		<u> </u>				1,2
Benzene		0.5	20.	18.	90.	
Toluene		1.	69.	63.	91.	
Ethylbenzene		0.5	19.	17.	89.	
Xylenes, Total		0.5	91.	83.	91.	
Total Petroleum Hydrocarbons (Gasoline)	100.	710.	600.	85.	
Percent Surrogate Recovery	•		100.	93.		

Benicia Lab Certifications: CAELAP #1719; L.A.Co.CSD #10185

*RESULTS listed as 'ND' were not detected at or above the listed PQL (Practical Quantitation Limit)

(1) EXTRACTED by EPA 5030 (purge-and-trap)

(2) ANALYZED by CAL DHS DRAFT TPH (modified) and EPA 8240 (GC/MS)

05/21/93 INCOS 50-387 EPP/dpo/epp BJ0365-1 Respectfully submitted,

COAST TO-COAST ANALYTICAL SERVICES, INC.

Emma P. Popek, CHMM Laboratory Manager



San Luis Obispo, CA • Benicia, CA • Camarillo, CA • San Jose, CA • Goleta, CA Anaheim, CA • Tempe, AZ • Valparaiso, IN • Westbrook, ME • Indianapolis, IN

NorCal Division (Benicia Laboratory) 6006 Egret Court, Benicia, California 94510 (707) 747-2757 FAX (707)747-2765

QC Batch ID: BJE20I1

CLIENT: Coast-to-Coast Analytical Services, Inc.

Analyzed : 05/20/93

Analyzed by: HC

Method : EPA 8260

QC SPIKE

REPORT OF ANALYTICAL RESULTS

Page 1 of 1

SAMPLE DESCRIPTION	MATRIX	SA	MPLED BY	SAMP	LED DA	re rece	IVED
QC SPIKE DUPLICATE	Aqueous					7	
CONSTITUENT		* PQL μg/L	SPIKE AMOUNT	RESULT µg/L	*REC	*DIFF	NOTE
BTEX + TPH (Gasoline)							1,2
Benzene		0.5	20.	16.	80.	12.	
Toluene		1.	69.	60.	87.	4.9	
Ethylbenzene		0.5	19.	17.	89.	0.	
Xylenes, Total		0.5	91.	84.	92.	1.2	
Total Petroleum Hydrocarbons (Gasoline)	50.	710.	730.	103.	20.	
Percent Surrogate Recovery	•		100.	94.			

Benicia Lab Certifications: CAELAP #1719; L.A.Co.CSD #10185

05/21/93 INCOS 50-387 EPP/dpo/epp BJ0365-1 Respectfully submitted,

COAST-TO-COAST ANALYTICAL SERVICES, INC.

Emma P. Popek, CHMM Laboratory Manager

^{*}RESULTS listed as 'ND' were not detected at or above the listed PQL (Practical Quantitation Limit)

⁽¹⁾ EXTRACTED by EPA 5030 (purge-and-trap)

⁽²⁾ ANALYZED by CAL DHS DRAFT TPH (modified) and EPA 8240 (GC/MS)

PES Environmental, Inc. Engineering & Environmental Services										
JOB NUMBER: 131.01.00.001										

CHAIN OF CUSTODY RECORD

Novato, California 94947 (415) 899-1600 FAX (415) 899-1601

										S	AMPLI	ERS	i. F) <u>Au</u>	۱	Lo	HC	1 <u>A</u> [~	4			. [AN,	ALYS	SIS RE	QUES	STED			7
NAME.	1 004	TION:	31.0 P.O. er: An	PAR	ZTNE	: 25	 Z			 F	ECOR	IDEF)() R	~£()					-	0	0 0	lant Metals	Benzene/Toluene/Xylene Total Petrol, Hydrocarb.	\\					
	МО	DATE		<u> </u>	AMPLE OR LAB	NUMBER NUMBER		CODE EPA 601/8010 EPA 601/8010 EPA 602/8020 EPA 625/8240 EPA 625/8240	MATRIX # CONTAINERS # CONTAINERS # PRESERY. DEPTH COL QA CODE IN MTD CODE CODE CODE							EPA 602/8020 EPA 602/8020 EPA 625/8270 Priority Pollutant Metals	Benzene/Tol Total Petrol.	TPHGA	BYEX		, .											
YR 9 3	05	 	122	293 593	3 1 3	5 K			\(\frac{1}{2} \)	<u>/</u>					3 3 3												X	X			036	5
				-		NOTES			•					BI	LING	าบีเรา	·ED E	Y: (Sig	gnature	 CI	HAIN OF CU	JSTOC ECEN				ıre)	<u>M</u>		CATI	<u> </u>	ПМЕ	

NOTES	CHAIN OF CUSTODY RECORD											
NORMAL TURNAROUND	RELINQUISHED BY: Signature) RELINQUISHED BY: Signature)	RECEIVED BY: (Signature) RECEIVED BY: (Signature)	S/14/932 DATE T	IME 120 IME								
	RELINQUISHED BY: (Signature)	RECEIVED BY: (Signature) RECEIVED BY: (Signature)		IME								
	RELINQUISHED BY; (Signature) DISPATCHED BY; (Signature) DATE	TIME RECEIVED FOR LAB BY:		IME								
	METHOD OF SHIPMENT:	(Signature)										
Laboratory Copy Project	ct Office Copy Field or Office Copy Yellow Pink											