



RECEIVED

3:48 pm, May 27, 2009

Alameda County
Environmental Health

IT Corporation

1921 Ringwood Avenue
San Jose, CA 95131-1721
Tel. 408.453.7300
Fax. 408.437.9526

A Member of The IT Group

January 22, 2001
Project 311-038.1A

Mr. Chuck Headlee
Regional Water Quality Control Board
San Francisco Bay Region
1515 Clay Street, Suite 1400
Oakland, California 94612

Re: 76 Service Station 5430
Quarterly Summary Report
Fourth Quarter 2000

Dear Mr. Headlee:

As directed by Mr. David DeWitt of Tosco Marketing Company, IT Corporation (IT) is forwarding the quarterly summary report for the following location:

<u>Service Station</u>	<u>Location</u>
5430	1935 Washington Avenue, San Leandro

If you have questions or comments, please do not hesitate to contact our office at (408) 453-7300.

Sincerely,

IT Corporation

Timothy L. Ripp
Project Geologist

Enclosure

cc: Mr. David DeWitt, Tosco Marketing Company
Mr. Tom Peacock, Alameda County Environmental Health Care Services

Quarterly Summary Report Fourth Quarter 2000

76 Service Station 5430
1935 Washington Avenue at Castro Street
San Leandro, California

County STID #: 1747

County: Alameda

BACKGROUND

Unocal files suggest that a product line leak occurred in June 1976, and that one of the original underground gasoline storage tanks failed a precision test in October 1981. In December 1981, the two original steel gasoline storage tanks were replaced with two fiberglass gasoline storage tanks. There are currently six on-site groundwater monitoring wells and one off-site groundwater monitoring well in use at the site. In July 1997, three off-site exploratory borings were drilled on the property to the south of the 76 station. Based on the findings of that investigation, the lateral extent of hydrocarbon impact to groundwater is considered delineated. The product dispensers and associated underground product piping were replaced in July and August 1998. The underground waste oil storage tank was also removed and replaced with an aboveground waste oil storage tank.

RECENT QUARTER ACTIVITIES

Semi-annual groundwater monitoring and sampling activities performed in September 2000 were reported in November 2000.

NEXT QUARTER ACTIVITIES

Semi-annual groundwater monitoring and sampling will be performed in March 2001.

CHARACTERIZATION/REMEDIAL STATUS

Soil contamination delineated? Yes.
Dissolved groundwater delineated? Yes.
Free product delineated? Not applicable.
Amount of groundwater contaminant recovered this quarter? None.
Soil remediation in progress? Not applicable.
Anticipated start date? Not applicable.
Anticipated completion date? Not applicable.
Dissolved/free product remediation in progress? No.
Anticipated start? Unknown.
Anticipated completion? Unknown.

CONSULTANT: IT Corporation

January 22, 2001
Project 311-058.1A

Mr. Chuck Headlee
Regional Water Quality Control Board
San Francisco Bay Region
1515 Clay Street, Suite 1400
Oakland, California 94612

Re: 76 Service Station 5760
Quarterly Summary Report
Fourth Quarter 2000

Dear Mr. Headlee:

As directed by Mr. David DeWitt of Tosco Marketing Company, IT Corporation (IT) is forwarding the quarterly summary report for the following location:

<u>Service Station</u>	<u>Location</u>
5760	376 Lewelling Boulevard, San Lorenzo

If you have questions or comments, please do not hesitate to contact our office at (408) 453-7300.

Sincerely,

IT Corporation



Timothy L. Ripp
Project Geologist

Enclosure

cc: Mr. David DeWitt, Tosco Marketing Company
Ms. Amy Leech, Alameda County Environmental Health Care Services