99 NOV -2 PH 3:58

October 29, 1999

STID 130

NBPODONO16 11/24/99

REPORT

of SOIL AND GROUNDWATER ASSESSMENT ASE JOB NO. 3411

at
Hutch's Carwash
17945 Hesperian Boulevard
San Lorenzo, California

Submitted by:
AQUA SCIENCE ENGINEERS, INC.
208 West El Pintado Road
Danville, CA 94526
(925) 820-9391

TABLE OF CONTENTS

<u>SEC</u>	CTION	<u>PAGE</u>
1.0	INTRODUCTION	1
2.0	SITE HISTORY	1
	2.1 Soil and Groundwater Assessment, December 19982.2 UST Closure Activities	1 1
3.0	SCOPE OF WORK	2
4.0	DRILLING SOIL BORINGS AND COLLECTING SAMPLES	3
	4.1 Drilling and Collection of Soil Samples4.2 Site Specific Geology	3 4
5.0	ANALYTICAL RESULTS FOR SOIL	4
6.0	MONITORING WELL CONSTRUCTION, DEVELOPMENT AND SAMPLING	5
	 6.1 Monitoring Well Construction 6.2 Monitoring Well Development 6.3 Monitoring Well Sampling 	5 5 6
7.0	GROUNDWATER ELEVATIONS	6
8.0	ANALYTICAL RESULTS FOR GROUNDWATER	7
9.0	CONCLUSIONS AND RECOMMENDATIONS	8
10.0	REPORT LIMITATIONS	9
LIS	Γ OF TABLES	
TAB	LE 1 ANALYTICAL RESULTS FOR SOIL	5
TAB	LE 2 GROUNDWATER ELEVATIONS	7
TAB	LE 3 ANALYTICAL RESULTS FOR GROUNDWATER	7

LIST OF FIGURES

FIGURE 1 SITE LOCATION MAP

FIGURE 2 SITEPLAN

FIGURE 3 GROUNDWATER ELEVATION CONTOUR MAP

LIST OF APPENDICES

APPENDIX A PERMIT

APPENDIX B BORING LOGS AND WELL CONSTRUCTION DETAILS

APPENDIX C ANALYTICAL REPORT AND CHAIN OF CUSTODY FORM FOR

SOIL SAMPLES

APPENDIX D WELL SAMPLING FIELD LOGS

APPENDIX E ANALYTICAL REPORT AND CHAIN OF CUSTODY FORM FOR

GROUNDWATER SAMPLES

1.0 INTRODUCTION

This report presents the methods and findings of Aqua Science Engineers, Inc. (ASE)'s soil and groundwater assessment at the Hutch's Carwash property located at 17945 Hesperian Boulevard in San Lorenzo, California (Figure 1). The site assessment activities were initiated by Mr. Kirk Hutchison, owner of the property, in order to comply with the request made by Mr. Scott Seery of the Alameda County Health Care Services Agency (ACHCSA) in his letters dated May 10 and July 29, 1999 (Appendix A). The letters request a soil and groundwater assessment at the site which would include the installation of groundwater monitoring wells.

2.0 SITE HISTORY

2.1 Soil and Groundwater Assessment, December 1998

On December 1, 1998, eight soil borings were drilled at the site using a Geoprobe hydraulic sampling rig (Figure 2). Borings BH-A and BH-B were located near the former fuel dispensers. The remaining borings (BH-C through BH-H) were located in areas surrounding the underground storage tanks (USTs).

Soil samples were collected from each of the eight borings and were analyzed for total petroleum hydrocarbons as gasoline (TPH-G) by modified EPA Method 5030/8015, benzene, toluene, ethyl benzene and total xylenes (collectively known as BTEX) and methyl tertiary butyl ether (MTBE) by EPA Method 8020, and total lead by EPA Method 6010. None of the soil samples contained significant concentrations of any of the compounds analyzed. Groundwater samples were collected from the six deeper borings and were analyzed for TPH-G, BTEX and MTBE. The water samples contained elevated hydrocarbon concentrations. For complete details of the afore-mentioned assessment activities. see the ASE Assessment Report dated December 22, 1998.

2.2 UST Closure Activities

On January 21, 1999, ASE provided project management support for the closure-in-place of the two 5,000 gallon USTs and one 10,000 gallon UST at the subject site (Figure 2). Hutch's Carwash plans on using the former fuel tanks for a water-reclamation system for their car washing operations. This proposed plan for the USTs' closure-in-place and subsequent re-use as water holding tanks was previously approved by the ACHCSA.

Clearwater Environmental Management, Inc. (Clearwater) mobilized to the site on January 21, 1999 with a pressure washing unit and a vacuum truck for UST evacuation. Using the pressure washer, the interior of the piping systems and each UST was rinsed. The rinsate and residual fuel was then removed from each UST using the vacuum truck. The liquid was transported by Clearwater from the site to the Alviso Independent Oil facility in Alviso, California where it was recycled.

Using a remote camera and television screen supplied by Rescue Rooter, the interior of each UST was inspected by ASE and Mr. Weston of the ACHCSA. It was visually obvious that the interior of the USTs had been coated with a sprayed-on coating that appeared shiny in most views. There did not appear to exist any obvious integrity failures, staining or scaling.

Hutch's personnel later filled each of the USTs to capacity with water then sealed all pipe and tank openings with caps and plugs as necessary. For complete details regarding the UST closure activities, see the ASE UST Closure Report dated February 8, 1999.

3.0 SCOPE OF WORK

The scope of work for this assessment was to further delineate the hydrocarbon plume previously identified in the Geoprobe borings drilled in 1998. The scope of work is as follows:

- 1) Prepare a workplan and site specific health and safety plan for approval by the ACHCSA.
- 2) Obtain a subsurface drilling permit from the Alameda County Public Works Agency (ACPWA). Call Underground Service Alert (USA) to have all public utilities in the area marked prior to drilling.
- 3) Drill three (3) soil borings at the site for the installation of groundwater monitoring wells.
- 4) Analyze two soil samples collected from each soil boring at a CAL-EPA certified environmental laboratory TPH-G, BTEX, MTBE and total lead.
- 5) Install 2-inch diameter groundwater monitoring wells in each boring described in task 3.
- 6) Develop the monitoring wells.

Hutch's Carwash Report - October 1999

- 7) Collect groundwater samples from each monitoring well for analyses.
- 8) Analyze the groundwater samples at a CAL-EPA certified analytical laboratory for TPH-G, BTEX and MTBE.
- 9) Survey the top of casing elevation of each well, and determine the groundwater flow direction and gradient beneath the site.
- 10) Prepare a report detailing the methods and findings of this assessment.

Details of this assessment follow.

4.0 DRILLING SOIL BORINGS AND COLLECTING SAMPLES

4.1 Drilling and Collection of Soil Samples

Prior to drilling, ASE obtained an Alameda County Public Works Agency (ACPWA) drilling permit (Appendix A). ASE also notified Underground Service Alert (USA) to have underground public utilities in the vicinity of the site marked prior to drilling.

On September 29, 1999, West Hazmat Drilling of Newark, California drilled soil borings MW-1, MW-2 and MW-3 at the site using a Mobile B-61 drill rig equipped with 8-inch diameter hollow-stem augers (Figure 3). Groundwater monitoring wells MW-1, MW-2 and MW-3 were subsequently constructed in these borings. The drilling was directed by ASE senior geologist Robert E. Kitay, R.G.

Undisturbed soil samples were collected at 5-foot intervals as drilling progressed for lithologic and hydrogeologic description and for possible chemical analyses. The samples were collected by driving a split-barrel drive sampler lined with 2-inch diameter brass tubes ahead of the auger tip with successive blows from a 140-lb. hammer dropped 30-inches. One tube from each sampling interval was immediately trimmed, sealed with Teflon tape, plastic end caps and duct tape, labeled, sealed in a plastic bag and stored on ice for transport to Chromalab, Inc. of Pleasanton, California (ELAP #1094) under chain of custody. Soil from the remaining was described by an ASE geologist using the Unified Classification System and was screened for volatile compounds with an Organic Vapor Meter (OVM). The soil was screened by emptying soil from one of the sample tubes into a plastic bag. The bag was then sealed and placed in the sun for approximately 10 minutes. After the

hydrocarbons were allowed to volatilize, the OVM measured the vapor in the bag through a small hole punched in the bag. OVM readings are used as a screening tool only, since the procedures are not as rigorous as those used in the laboratory.

Drilling equipment was steam-cleaned prior to use and between borings, and sampling equipment was washed with a TSP solution between sampling intervals to prevent cross-contamination. Steam cleaning rinsate and drill cuttings were contained in sealed and labeled 55-gallon steel drums and left on-site for temporary storage until off-site disposal can be arranged.

4.2 Site Specific Geology

Sediments encountered during drilling generally consisted of clayey silt/sandy silt from beneath the asphalt surface to 7.5-feet bgs, and sandy silt, silty sand and/or sand from 7.5-feet bgs to 27-feet bgs. Groundwater was encountered at approximately 15.5-feet bgs. The boring log and well construction details are included as Appendix B.

5.0 ANALYTICAL RESULTS FOR SOIL

Two soil samples collected from each boring were submitted to Chromalab, Inc. for analysis. One of the soil samples was from either 10.5 or 11.0-feet bgs and the other sample was from 15.0-feet bgs. These samples were analyzed for TPH-G by modified EPA Method 5030/8015, BTEX and MTBE by EPA Method 8020, and total lead by EPA Method 6010. The analytical results are tabulated in Table One, and a copy of the certified analytical report and chain of custody form are included in Appendix C.

The only hydrocarbons detected in the soil samples were 24 ppm TPH-G in the soil sample collected from 15.0-feet bgs in boring MW-1, 200 ppm MTBE in the soil sample collected from 10.5-feet bgs in boring MW-1, 0.011 ppm MTBE in the soil sample collected from 11.0-feet bgs in boring MW-2 and 0.070 ppm in the soil sample collected from 15.0-feet bgs in boring MW-2. Lead was detected in the soil sample collected from 15.0-feet bgs in boring MW-1 at 5.0 ppm and in the soil sample collected from 15.0-feet bgs in boring MW-3 at 6.0 ppm. No other hydrocarbons or lead were detected in any of the samples analyzed.

-4-

TABLE ONE
Summary of Chemical Analysis of SOIL Samples
All results are in parts per million

Boring	Depth Sampled	TPH Gasoline	Benzene	Toluene	Ethyl Benzene	Total Xylenes	МТВЕ	Total Lead
MW-1	10.5' 15.0'	< 1.0 2 4	< 0.0050 < 0.62	< 0.0050 < 0.62	< 0.0050 < 0.62	< 0.0050 < 0.62	200 < 0.62	< 5.0 5.0
MW-2	11.0' 15.0'	< 1.0 < 1.0	< 0.0050 < 0.0050	< 0.0050 < 0.0050	< 0.0050 < 0.0050	< 0.0050 < 0.0050	$\begin{smallmatrix}0&.&0&1&1\\0&.&0&7&0\end{smallmatrix}$	< 5.0 < 5.0
MW-3	10.5° 15.0°	< 1.0 < 1.0	< 0.0050 < 0.0050	< 5.0 6.0				

Notes:

Detectable concentrations are in **bold**.

Non-detectable concentrations are noted by the less than symbol (<) followed by the detection limit.

6.0 MONITORING WELL CONSTRUCTION, DEVELOPMENT AND SAMPLING

6.1 Monitoring Well Construction

Groundwater monitoring wells MW-1, MW-2 and MW-3 were constructed in borings MW-1, MW-2 and MW-3, respectively. The wells are constructed with 2-inch diameter, 0.020-inch factory slotted, flush-threaded, schedule 40 PVC well screen and blank casing. The wells are screened between 10-feet bgs and 27-feet bgs to monitor the first water bearing zone encountered. Lonestar #3 Monterey sand occupies the annular space between the borehole and the casing from the bottom of the boring to approximately 2-feet above the well screen. A 1-foot thick hydrated bentonite layer separates the sand from the overlying cement surface seal. The wellhead is secured with a locking wellplug beneath an at-grade, traffic-rated vault.

6.2 Monitoring Well Development

On October 4, 1999, ASE associate geologist Ian Reed developed the three monitoring wells using multiple episodes of surge-block agitation and bailer and pump evacuation. Over ten well casing volumes of water were

-5-

removed from each well during development, and evacuation continued until the water was relatively clear. Well development purge water was contained in sealed and labeled 55-gallon steel drums and left on-site for temporary storage until off-site disposal can be arranged. No free-floating hydrocarbons or sheen were present on the surface of groundwater during well development.

6.3 Monitoring Well Sampling

On October 6, 1999, ASE associate geologist Ian Reed collected groundwater samples from all three site monitoring wells for analysis. No free-floating hydrocarbons or sheen were present on the surface of groundwater in any of the monitoring wells. However, hydrocarbon odors were present in water purged from monitoring well MW-1, and a slight hydrocarbon odor was present in groundwater purged from monitoring well MW-2. Prior to sampling, the wells were purged of four well casing volumes of groundwater. The pH, temperature and conductivity of the purge water were monitored during evacuation, and samples were not collected until these parameters stabilized. Samples were collected from each well using new, unused polyethylene bailers. The groundwater samples were decanted from the bailers into 40-ml volatile organic analysis (VOA) vials, preserved with hydrochloric acid, labeled, placed in protective foam sleeves, and stored on ice for transport to Chromalab, Inc. of Pleasanton, California under chain of custody. Well sampling purge water was contained in sealed and labeled 55-gallon steel drums and left on-site for temporary storage until off-site disposal can be arranged. Appendix D for a copy of the Field Logs.

7.0 GROUNDWATER ELEVATIONS

On October 15, 1999, ASE surveyed the top of casing elevation of each site monitoring well relative to a site datum. The top of casing elevation of monitoring well MW-1 was set to 35.00-feet based on data interpolated from a USGS topographic map.

The depth to groundwater was measured in each site well prior to sampling on October 6, 1999 with an electric water level sounder. Top of casing elevations, depth to groundwater measurements and groundwater elevations are presented in Table Two, and groundwater elevation (potentiometric surface) contours are plotted on Figure 3. Groundwater appeared to generally flow to the northwest beneath the site at a gradient of approximately 0.002-feet/foot.

TABLE TWO

Well I.D.	Date of Measurement	Top of Casing Elevation (relative to project datum)	Depth to Water (feet)	Groundwater Elevation (project data)
	10-06-99	35.00	15.58	19.42
MW-2	10-06-99	35.21	15.84	19.37
المراج والم	10-06-99	34.47	14.98	19.49

8.0 ANALYTICAL RESULTS FOR GROUNDWATER

The groundwater samples were analyzed by Chromalab for TPH-G by modified EPA Method 5030/8015 and BTEX and MTBE by EPA Method 8020. The analytical results are tabulated in Table Three, and copies of the certified analytical report and chain of custody form are included in Appendix E.

TABLE THREE

Certified Analytical Results of GROUNDWATER Samples

All results are in parts per billion

Well	TPH Gasoline	Benzene	Toluene	Ethyl Benzene	Total Xylenes	
MW-1	1,500	3.3	2.3	2 7	7 2	1 2 0
MW-2	< 50	< 0.5	< 0.5	< 0.5	< 0.5	1 8
MW-3	< 50	< 0.5	< 0.5	< 0.5	< 0.5	< 5.0
DHS MCL	NE		150	700	1,750	13

Notes:

Detectable concentrations are in bold.

Non-detectable concentrations are noted by the less than symbol (<) followed by the detection limit.

DHS MCL = California Department of Health Services maximum contaminant level for drinking water

NE = DHS MCL not established

The groundwater sample collected from monitoring well MW-1 contained 1,500 parts per billion (ppb) TPH-G, 3.3 ppb benzene, 2.3 ppb ethyl benzene, 27 ppb toluene, 72 ppb total xylenes and 120 ppb MTBE. The groundwater sample collected from monitoring well MW-2 contained 18 ppb MTBE. No TPH-G or BTEX were detected in groundwater samples collected from monitoring well MW-2. No hydrocarbons were detected in groundwater samples collected from monitoring well MW-3.

The benzene and MTBE concentrations in groundwater samples collected from monitoring well MW-1 exceeded California Department of Health Services (DHS) maximum contaminant levels (MCLs) for drinking water. In addition, the MTBE concentration in groundwater samples collected from monitoring well MW-2 also exceeded the DHS MCL for drinking water.

9.0 CONCLUSIONS AND RECOMMENDATIONS

The only hydrocarbons detected in the soil samples were 24 ppm TPH-G in the soil sample collected from 15.0-feet bgs in boring MW-1, 200 ppm MTBE in the soil sample collected from 10.5-feet bgs in boring MW-1, 0.011 ppm MTBE in the soil sample collected from 11.0-feet bgs in boring MW-2 and 0.070 ppm in the soil sample collected from 15.0-feet bgs in boring MW-2. Lead was detected in the soil sample collected from 15.0-feet bgs in boring MW-1 at 5.0 ppm and in the soil sample collected from 15.0-feet bgs in boring MW-3 at 6.0 ppm. No other hydrocarbons or lead were detected in any of the soil samples analyzed.

The groundwater flow is to the northwest beneath the site at a gradient of approximately 0.002-feet/foot.

The groundwater sample collected from monitoring well MW-1 contained 1,500 ppb TPH-G, 3.3 ppb benzene, 2.3 ppb ethyl benzene, 27 ppb toluene, 72 ppb total xylenes and 120 ppb MTBE. The groundwater sample collected from monitoring well MW-2 contained 18 ppb MTBE. No TPH-G or BTEX were detected in groundwater samples collected from monitoring well MW-2. No hydrocarbons were detected in groundwater samples collected from monitoring well MW-3.

The benzene and MTBE concentrations in groundwater samples collected from monitoring well MW-1 exceeded DHS MCLs for drinking water. In addition, the MTBE concentration in groundwater samples collected from monitoring well MW-2 also exceeded the DHS MCL for drinking water. All

of the hydrocarbon concentrations detected are below those detected during the previous soil and groundwater assessment.

ASE recommends that this site be placed on a quarterly groundwater monitoring program. Based on this sampling schedule, the next sampling is scheduled for January 2000.

10.0 REPORT LIMITATIONS

The results of this assessment represent conditions at the time of the soil and groundwater sampling, at the specific locations where the samples were collected, and for the specific parameters analyzed by the laboratory.

It does not fully characterize the site for contamination resulting from unknown sources, or for parameters not analyzed by the laboratory. work cited in this report was prepared under of the laboratory the CAL-EPA certified direction of an independent laboratory. The laboratory is solely responsible independent contents and. conclusions of the chemical analysis data.

Aqua Science Engineers appreciates the opportunity to provide environmental consulting services for this project. Should you have any questions or comments, please feel free to call us at (925) 820-9391.

Respectfully submitted,

AQUA SCIENCE ENGINEERS, INC.

Robert E. Kitay, R.G., R.E.A.

Senior Geologist

Rely E. Kitan

Attachments: Figures 1 through 3

Appendices A through E

cc: Mr. Kirk Hutchison, Hutch's Car Wash

Mr. Amir Gholami, Alameda County Health Care Services Agency

Mr. Chuck Headlee, California Regional Water Quality Control Board


No. 6586

-9-



NORTH

NOT TO SCALE





LOCATION MAP

Hutch's Carwash 17945 Hesperian Boulevard San Lorenzo, California

AQUA SCIENCE ENGINEERS, INC.

Figure 1





APPENDIX A

Drilling Permit

DCT 07 1998 10:10 FR ALA CO PUB UK HED REE

516 TO 919258374865

P.22.62



ALAMEDA COUNTY PUBLIC WORKS AGENCY

WATER RESOURCES SECTION 951 TURNER COURT. SUITE 300, HAYWARD, CA 94546-2681 PHONE (\$10) \$70-575 ANDREAS GODFREY FAX (\$10) \$70-5252 (\$10) \$70-514 ALVIN KAR

for applicant to complete	FOR OFFICE USE
LOCATION OF PROJECT Hutch's Comments	PERMIT NUMBER 98WR485
- to 750 Hand Parlan Blud.	WELL NUMBER
San Lorenzo, WA	APN
California Caerdinales Source ft. CCE ft. CCE ft. CCE	FERRIT CONDITIONS
Kin	Circled Fermit Requirements Apply
CLIENT	(A) GENERAL
Harrie Haddis Carwash	I. A parmit application chould be submitten so as as
Lity San Loren 20 feet 21 99501	Prive as the VCLAN office tive gate being to
City San Larenda, Get Zin 9950)	Property Exists as a second
APPLICANT	2) Butter to ACPWA within 60 cays after completion of
Kime figure Science Engineers The	PRINTED WORK INT Missional Transpose and the contract of the c
The Bank William To Bank 1977 170-	COSCILLE WEST WEST THE DARKET OF THE PARTY O
Accres 200 100 100 100 PRONE 925-820-935/	well projects, or drilling logs and location everth for grotechnical projects.
City Danville Cat Zip 54524	1) Permit is roid if project not begun within PC days of
TYPE OF PROJECT	IDELIAC: USA
Well Construction Gustechnical Investigation	E WATER SUPPLY WELLS
Cathodic Protection 11 General Proceedings and	. Minimum surface seal thickness is not inches
Water Stopply D Cognamination	STANCE STUDY DIRECT by burning
Meniuming C Well Demyetten 7	2. Minimum soul death is 80 for the mentalest and
	moustant walls or 20 feet for democrate and indexion
Proposed Water Supply well use	
New Demessie D Replacement Demestic D	ALANAOUD AUTE MOVILOTING MALLS
Monitori O infrance	Including Piezometers
Industrial II Other	i. Minimum anifoce real unukause is two larges of
DRILLING METROD:	Commit exect signal by remain.
	2. Minimum and dupth for monitoring wells is the
The second of th	D. GEOTECHNICAL
A CASSOST	Backfill bare halo with sommersed sudings or heavy
DAULLER'S LICENSE NO. 6-57 485/65 (Grace)	benwaln and upper two feet with compacted material.
	40 APRILLED OF IDIRECTOR CONTRACTOR OF THE PROPERTY OF THE PRO
WILL PROJECTS	1 VALGEDI ATOMI (INST.) THE SMOOT IN TAKEN AS
Drill Hels Dismoner in Maximum	
Surface Seed Done to the Dopeth fu	Fill hale above anone zone with commen placed by brenic.
all for Number	F. WELL DESTRUCTION See entend.
CEOTECHNICAL PROJECTS	C. SPECIAL CONDITIONS
Number of Beringer 34	
lieft Diemour Z-min. Depth 30 g	•
Table A many	\wedge 1 + .
ESTIMATED STARTING DATE 12-1-98 ESTIMATED COMPLETION DATE 12-1-98	
2 WILLELION DATE	APPROVED 1116
	DATE TO THE PARTY OF THE PARTY
tereby iltre in comply with all exquirements of this permit and Limpels County Ordinance No. 73. 20	
A simple County Ordinance No. 73-68.	
• . •	
APPLICANT'S PIII	
C. Klay DATE 11-13-98	
2ATE 11-13-78	
	•
₹	•

WW TOTAL PAGE.62 **

APPENDIX B

Boring Logs and Well Construction Details

SOIL BORING LOG AND MONIT	ORING WELL CO	OMPLETION DETAILS MONITORING WELL: MW-1		
Project Name: Hutch's Car Wash	Project Location: S	ion: San Lorenzo, CA Page 1 of 1		
Driller: West Hazmat Drilling	Type of Rig: Hollow	w-Stem Auger Size of Drill: 8.0" Diameter		
Logged By: Robert Kitay	Date Drilled: Sep	otember 29, 1999 Checked By: Robert E. Kitay, R.G.		
WATER AND WELL DATA	Tot	al Depth of Well Completed: 27.0'		
Depth of Water First Encountered: 16	We	ell Screen Type and Diameter: 0.020" slotted, 2" sch. PVC		
Static Depth of Water in Well: 16'	We	ell Screen Slot Size: 0.020"		
Total Depth of Boring: 27.0	Тур	pe and Size of Soil Sampler: 2.0" I.D. Split Barrell		
	SAMPLE DATA	DESCRIPTION OF LITHOLOGY		
Depth in Fe Description Interval Blow Counts	Water Level Graphic Log Depth in F	standard classification, texture, relative moisture, density, stiffness, odor-staining, USCS designation.		
y		Asphalt		
Stree Box Locking Well Ca	- O	Clayey SiLT (ML); dark yellow brown; medium stiff; dry; 85% silt; 10% clay; 5% fine sand; low plasticity; low estimated K; no odor		
Sch 40 PV Sch 40 PV 8 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	5	; 		
o tille Seal		Silty SAND (SM); olive brown; medium dense; damp; 90% fine sand; 10% silt; non-plastic; medium estimated K; slight hydrocarbon odor		
-15 -1525		5 moist at 15'		
-20 #to 8 9 11	-2	Silty CLAY (CH); olive brown; stiff; wet; 80% clay; 20% silt; high plasticity; very low estimated K; strong hydrocarbon odor Silty SAND (SM); olive; medium dense; wet; 85% fine sand; 15% silt; non-plastic; medium estimated k;		
-25 emails 24 28 24 28	-2	strong hydrocarbon odor 5 SAND (SW); olive; dense; wet; 90% fine to coarse sand; 5% sub-rounded gravel to 0.2" diameter; 5% silt; non-plastic: high estimated k; strong hydrocarbon odor End of boring at 27.0"		
-30	-3	о		
		aqua science engineers, inc.		

÷

SOIL BORING LOG AND MONITORING WELL COMPLETION DETAILS MONITORING WELL: MW-2							
Project Name: Hutch's Car Wash	Project Location	on: San Lorenzo, CA Page 1 of 1					
Driller: West Hazmat Drilling	Type of Rig: I	Hollow-Stem Auger Size of Drill: 8.0" Diameter					
Logged By: Robert Kitay	Date Drilled:	September 29, 1999 Checked By: Robert E. Kitay, R.G.					
WATER AND WELL DATA		Total Depth of Well Completed: 27.0'					
Depth of Water First Encountered: 16		Well Screen Type and Diameter: 0.020" slotted, 2" sch. PVC					
Static Depth of Water in Well: 16'		Well Screen Slot Size: 0.020"					
Total Depth of Boring: 27.0		Type and Size of Soil Sampler: 2.0" I.D. Split Barrell					
	SAMPLE DATA	DESCRIPTION OF LITHOLOGY					
Depth in Feet Description Interval Blow Counts MACOUNTS	Water Level Graphic Log	standard classification, texture, relative moisture, density, stiffness, odor-staining, USCS designation.					
O Street Box		O Asphalt					
Locking Well C	ap	Clayey SILT (ML); dark yellow brown; medium stiff; dry; 85% silt; 10% clay; 5% fine sand; low plasticity; low estimated K; no odor					
Sch 40 PVC Portland Cement Portland School		_ - 5 -					
2" ID Blank	i6	Silty SAND (SM); yellow brown; medium dense; damp; 90% fine sand; 10% silt; non-plastic; medium estimated K; slight hydrocarbon odor					
2 2 2 2 2 2 2 3 3 3 3 3 3 3 3 3 3 3 3 3	Ā	-15 Sandy SILT (ML); yellow brown; medium stiff; moist; 80% silt; 15% fine sand; 5% clay; low plasticity; low estimated K; slight hydrocarbon odor					
-20 slotte		olive; wet; 50-60% silt; 35-45% fine sand; 5% clay; slight hydrocarbon odor					
-25 games 3 Sand		= 25 sand stringers at 25'					
		End of boring at 27.0'					
-30		-30					
		aqua science engineers, inc.					

SOIL BORING LOG AND MONITORING WELL COMPLETION DETAILS MONITORING WELL: MW-3 Project Location: San Lorenzo, CA Page 1 of 1 Type of Rig: Hollow-Stern Auger Size of Drill: 8.0" Diameter Logged By: Robert Kitay Date Drilled: September 29, 1999 Checked By: Robert E. Kitay, R.G. WATER AND WELL DATA Depth of Well Completed: 27.0' Weil Screen Type and Diameter: 0.020" slotted, 2" sch. PVC Weil Screen Type and Diameter: 0.020" slotted, 2" sch. PVC Weil Screen Siot Size: 0.020" DESCRIPTION OF LITHOLOGY Signature	SOU BORING L	OG AN	D MC	MITC) PINI	c WELL	COM	IPI ETION D	FTAIL:	s	MONITORING	G WELL: MW-3
Drillor: West Hazmat Drilling Logged By: Robert Kitay Date Drillod: September 29, 1999 Checked By: Robert E. Kitay, R.G. WATER AND WELL DATA Depth of Water First Encountered: 16' Well Screen Type and Diameter: 0.020' slotted, 2' sch. PVC Static Depth of Water in Well: 16' Well Screen Slot Size: 0.020' Total Depth of Boring: 27.0' Type and Size of Soil Sampler: 2.0' LD. Split Barrell DESCRIPTION OF LITHOLOGY standard classification, texture, relative moisture, density, stiffness, odor-staining, USCS designation. O Stree Box DETAIL O Stree Box Size Soil Sampler: 2.0' LD. Split Barrell DESCRIPTION OF LITHOLOGY standard classification, texture, relative moisture, density, stiffness, odor-staining, USCS designation. O Asphalt Sandy SILT (ML); dark yellow brown; medium ethi; damp; 55% silt; 40% fine sand; 5% clay; low plasticity; low estimated K; no odor Silty SAND (SM); yellow brown; medium dense, damp; 60% fine sand; 5% clay; non-plastic; low estimated K; no odor Silty SAND (SM); yellow brown; medium stiff; damp; 65% silt; 50% fine sand; 5% clay; low plasticity; low estimated K; no odor Silty SAND (SM); yellow brown; medium stiff; damp; 65% silt; 50% fine sand; 5% clay; low plasticity; low estimated K; no odor End of boring at 27.0' End of boring at 27.0'								<u> </u>				
Date Drilled: September 29, 1999 Checked By: Robert E. Kitay, R.G. WATER AND WELL DATA Total Depth of Well Completed: 27.0' Well Screen Type and Diameter: 0.020* slotted, 2* sch. PVC Static Depth of Water in Well: 16* Well Screen Type and Diameter: 0.020* slotted, 2* sch. PVC Static Depth of Boring: 27.0' Type and Size of Soil Sampler: 2.0* I.D. Split Barrell BORING Soil Depth of Boring: 27.0' Type and Size of Soil Sampler: 2.0* I.D. Split Barrell DESCRIPTION OF LITHOLOGY Standard classification, texture, relative moisture, density, stiffness, odor-staining, USCS designation.								<u></u>		f Drill	i: 8.0° Diamete	
Water And Well Data Depth of Water First Encountered: 16' Well Screen Type and Diameter: 0.020" Static Depth of Water In Well: 16' Total Depth of Boring: 27.0' Type and Size: 0.020" DESCRIPTION OF LITHOLOGY Light Size: 0.020" DESCRIPTION OF LITHOLOGY Light Size: 0.020" Asphalt Sandy Sill: (ML); dark yellow brown; medium stiff; damp; 55% sill; 40% fine sand; 5% clay; non-plastic; low estimated K; no odor Silly SAND (SM); yellow brown; medium dense; damp; 60% fine sand; 5% clay; non-plastic; low estimated K; alight no odor Silly SAND (SM); yellow brown; medium stiff; damp; 65% sill; 30% fine sand; 5% clay; non-plastic; low estimated K; slight no odor Silly SAND (SM); yellow brown; medium stiff; damp; 65% sill; 30% fine sand; 5% clay; low plasticity; low estimated K; slight no odor End of boring at 27.0' End of boring at 27.0'												
Depth of Water First Encountered: 16' Static Depth of Water in Well: 16' Total Depth of Boring: 27.0' Type and Size of Soil Sampler: 2.0" LD. Split Barrell BORING DETAIL BORING DETA			Α								<u> </u>	<u>. </u>
Static Depth of Water in Well: 16' Total Depth of Boring: 27.0' Type and Size of Soil Sampler: 2.0" I.D. Split Barrell DESCRIPTION OF LITHOLOGY standard classification, texture, rolative moisture, deneity, stiffness, odor-staining, USCS designation. DESCRIPTION OF LITHOLOGY standard classification, texture, rolative moisture, deneity, stiffness, odor-staining, USCS designation. Asphalt Sandy Sill. (ML); dark yellow brown; medium elff; damp; 55% silt; 40% fine sand; 5% clay; low plasticity; low estimated K; no odor Silty SAND (SM); yellow brown; medium dense, damp; 60% fine sand; 35% silt; 5% clay; non-plastic; low estimated K; no odor Silty SAND (SM); yellow brown; medium elff; damp; 65% silt; 30% fine sand; 5% clay; low plasticity; low estimated K; slight no odor Sandy Sill. (ML); dark yellow brown; medium elff; damp; 65% silt; 30% fine sand; 5% clay; non-plastic; low estimated K; no odor Silty SAND (SM); yellow brown; medium elff; damp; 65% silt; 30% fine sand; 5% clay; low plasticity; low estimated K; slight no odor Sandy Sill. (ML); dark yellow brown; medium elff; damp; 65% silt; 30% fine sand; 5% clay; low plasticity; low estimated K; slight no odor Sandy Sill. (ML); yellow brown; medium elff; damp; 65% silt; 30% fine sand; 5% clay; low plasticity; low estimated K; slight no odor Sandy Sill. (ML); yellow brown; medium elff; damp; 65% silt; 30% fine sand; 5% clay; low plasticity; low estimated K; slight no odor Sandy Sill. (ML); yellow brown; medium elff; damp; 65% silt; 30% fine sand; 5% clay; low plasticity; low estimated K; slight no odor Sandy Sill. (ML); yellow brown; medium elff; damp; 65% silt; 30% fine sand; 5% clay; low plasticity; low estimated K; alight no odor Sandy Sill. (ML); yellow brown; medium elff; damp; 65% silt; 30% fine sand; 5% clay; low plasticity; low estimated K; alight no odor	1			: 16'				•	<u>`</u>			2" ech PVC
Total Depth of Borling: 27.0' Type and Size of Soll Sampler: 2.0" I.D. Split Barrell DESCRIPTION OF LITHOLOGY standard classification, texture, relative moisture, density, stiffness, odor-staining, USCS designation. O Asphalt Sandy SILT (ML); dark yellow brown; medium stiff; damp; 55% silt; 40% fine sand; 5% clay; low plasticity; low estimated K; no odor Silty SAND (SM); yellow brown; medium stiff; damp; 65% silt; 30% fine sand; 5% clay; low plasticity; low estimated K; slight no odor Sandy SILT (ML); yellow brown; medium stiff; damp; 65% silt; 30% fine sand; 5% clay; low plasticity; low estimated K; slight no odor Sandy SILT (ML); yellow brown; medium stiff; damp; 65% silt; 30% fine sand; 5% clay; low plasticity; low estimated K; slight no odor Sity SAND (SM); yellow brown; medium stiff; damp; 65% silt; 30% fine sand; 5% clay; low plasticity; low estimated K; slight no odor Sandy SILT (ML); yellow brown; medium stiff; damp; 65% silt; 30% fine sand; 5% clay; low plasticity; low estimated K; slight no odor End of boring at 27.0' End of boring at 27.0'							 -				0.020 510100	
SOILTROCK SAMPLE DATA BEARING DETAIL BORING DETAIL SAMPLIST SAMPL SIIT. (ML); yellow brown; medium stiff; damp; 65% silt; 30% fine sand; 5% clay; non-plastic; low estimated K; slight no odor SIIty SAND (SM); yellow brown; medium stiff; damp; 65% silt; 30% fine sand; 5% clay; non-plastic; low estimated K; slight no odor BORING DETAIL SAMPLIST SAMPL SIIT. (ML); yellow brown; medium stiff; damp; 65% silt; 30% fine sand; 5% clay; low plasticity; low estimated K; slight no odor MORING DETAIL SAMPLIST SAMPL SIIT. (ML); yellow brown; medium stiff; damp; 65% slit; 30% fine sand; 5% clay; low plasticity; low estimated K; slight no odor MORING DETAIL SAMPLIST SAMPL							 				2.0" l.D. Split I	Barreil
Some particles and the second particles and th				ЮСК	ŞAMF	LE DATA					· ·	
Asphalt Sandy SILT (ML); dark yellow brown; medium stiff; damp; 55% silt; 40% fine sand; 5% clay; low plasticity; low estimated K; no odor Silty SAND (SM); yellow brown; medium dense; damp; 60% fine sand; 35% silt; 5% clay; non-plastic; low estimated K; no odor Silty SAND (SM); yellow brown; medium dense; damp; 60% fine sand; 35% silt; 5% clay; non-plastic; low estimated K; no odor Silty SAND (SM); yellow brown; medium stiff; damp; 65% silt; 30% fine sand; 5% clay; low plasticity; low estimated K; slight no odor moist at 15' End of boring at 27.0' Sandy SILT (ML); yellow brown; medium stiff; damp; 65% silt; 30% fine sand; 5% clay; low plasticity; low estimated K; slight no odor moist at 15' End of boring at 27.0'	.≦ BORING	escription	nterval	/M (ppmv)	ater Level	3raphic Log	Jepth in Fe		ciassi	fication	on, texture, rel	ative moisture,
Sandy SILT (ML); dark yellow brown; medium stiff; damp; 55% silt; 40% fine sand; 5% clay; low plasticity; low estimated K; no odor Silty SAND (SM); yellow brown; medium dense; damp; 60% fine sand; 35% silt; 5% clay; non-plastic; low estimated K; no odor Silty SAND (SM); yellow brown; medium dense; damp; 60% fine sand; 35% silt; 5% clay; non-plastic; low estimated K; no odor Sandy SILT (ML); yellow brown; medium stiff; damp; 65% silt; 30% fine sand; 5% clay; low plasticity; low estimated K; silght no odor moist at 15' End of boring at 27.0'				ĺδ	👸						<u> </u>	· · · · · · · · · · · · · · · · · · ·
Silty SAND (SM); yellow brown; medium dense; damp; 60% fine sand; 35% silt; 5% clay; non-plastic; low estimated K; no odor Sandy SILT (ML); yellow brown; medium stiff; damp; 65% silt; 30% fine sand; 5% clay; low plasticity; low estimated K; slight no odor moist at 15' End of boring at 27.0'		ement o			LEP		0	Sandy SILT damp; 55%	silt; 40	0% fii	ne sand; 5% cl	
Sandy SiLT (ML); yellow brown; medium stin; damp; 65% silt; 30% fine sand; 5% clay: low plasticity; low estimated K; slight no odor moist at 15' 20 25 25 26 27 28 8 7 7 10 11 20 20 20 20 21 20 20 20 20 20 20 20 20 20 20 20 20 20	-1 0	2" ID Blank So Seal	8 8 8	356	5			60% fine sa	and; 35	% sil		
- End of boring at 27.0' - 30 - 30		slotted sch. 40 PVC Bento	8 8 8 7 7 S 5		_			65% silt; 30 estimated K	0% fine (; slight	san	d; 5% clay; low	
-30 End of boining at 27.0	- - - -25	↑ ↑ 2" dlameter 0.020" § Sand					25					
	_ _ _30	\$					- - -30					

APPENDIX C

Analytical Report and Chain of Custody Form For Soil Samples Environmental Services (SDB)

Submission #: 1999-10-0016

Date: October 8, 1999

Aqua Science Engineers, Inc.

208 West El Pintado Road Danville, CA 94526

Attn.: Mr. Robert Kitay

Project: 3411

Hutch's Car Wash

Site:

17945 Hesperian Blvd.

San Lorenzo, CA.

Dear Mr. Kitay,

Attached is our report for your samples received on Thursday September 30, 1999. This report has been reviewed and approved for release. Reproduction of this report is permitted only in its entirety.

Please note that any unused portion of the samples will be discarded after October 30, 1999 unless you have requested otherwise. We appreciate the opportunity to be of service to you. If you have any questions, please call me at (925) 484-1919.

Sincerely

Pierre Monette

Environmental Services (SDB)

Submission #: 1999-10-0016

Reported on: 10/08/1999 18:26

Summary Report

From: Pierre Monette

To: Aqua Science Engineers, Inc.

Attn: Robert Kitay

Phone: (925) 820-9310 Fax: (925) 837-4853

Project #:

3411

Project: Site: Hutch's Car Wash 17945 Hesperian Blvd.

	San I	.orenzo, CA.		
MW-1-10.5` on 09/29/1999 09:20	LabID: 1999-10-0016-004	Results	<u>RL</u>	<u>Units</u>
G/BTEX with MTBE (8015M/8020)	Gasoline	ND	1.0	mg/Kg
	Benzene	ND	0.0050	mg/Kg
	Toluene	ND	0.0050	mg/Kg
	Ethyl benzene	ND	0.0050	mg/Kg
	Xylene(s)	ND	0.0050	mg/Kg
	MTBE	200	0.0050	mg/Kg
Lead (6010B)	Lead	ND	5.0	mg/Kg
MW-1-15.0° on 09/29/1999 09:28	<u>LabID: 1999-10-0016-005</u>	Results	<u>RL</u>	<u>Units</u>
G/BTEX Extract	Gasoline	24	10	mg/Kg
	Benzene	ND	0.62	mg/Kg
	Toluene	ND	0.62	mg/Kg
	Ethyl benzene	ND	0.62	mg/Kg
	Xylene(s)	ND	0.62	mg/Kg
	MTBE	ND	0.62	mg/Kg
Lead (6010B)	Lead	5.0	5.0	mg/Kg
MW-2-11.0` on 09/29/1999 11:00	<u>LabID: 1999-10-0016-006</u>	Results	<u>RL</u>	<u>Units</u>
G/BTEX with MTBE (8015M/8020)	Gasoline	ND	1.0	mg/Kg
	Benzene	ND	0.0050	mg/Kg
	Toluene	ND	0.0050	mg/Kg
	Ethyl benzene	ND	0.0050	mg/Kg
	Xylene(s)	ND	0.0050	mg/Kg
	MTBE	0.011	0.0050	mg/Kg
Lead (6010B)	Lead	ND	5.0	mg/Kg
MW-2-15.0` on 09/29/1999 11:07	LabID: 1999-10-0016-007	Results	<u>RL</u>	<u>Units</u>
G/BTEX with MTBE (8015M/8020)	Gasoline	ND	1.0	mg/Kg
	Benzene	ND	0.0050	mg/Kg
	Toluene	ND	0.0050	mg/Kg
	Ethyl benzene	ND	0.0050	mg/Kg
	Xylene(s)	ND	0.0050	mg/Kg
	MTBE	0.070	0.0050	mg/Kg
Lead (6010B)	Lead	ND	5.0	mg/Kg
MW-3-10.5` on 09/29/1999 13:26	LabID: 1999-10-0016-008	<u>Results</u>	<u>RL</u>	<u>Units</u>
G/BTEX with MTBE (8015M/8020)	Gasoline	ND	1.0	mg/Kg
RL = Reporting Limit Surr. = Surrogate				

1220 Quarry Lane * Pleasanton, CA 94566-4756

Telephone: (925) 484-1919 * Facsimile: (925) 484-1096

Printed on: 10/08/1999 18:26

Environmental Services (SDB)

Submission #: 1999-10-0016

Reported on: 10/08/1999 18:26

Summary Report

From: Pierre Monette

To: Aqua Science Engineers, Inc.

Attn: Robert Kitay

Lead (6010B)

Phone: (925) 820-9310 Fax: (925) 837-4853

Project #:

3411

Project:

Hutch's Car Wash

6.0

Site:

17945 Hesperian Blvd.

Address - Control of the Control of	San Lorenzo, CA.						
MW-3-10.5` on 09/29/1999 13:26	LabID: 1999-10-0016-008	<u>Results</u>	<u>RL</u>	<u>Units</u>			
G/BTEX with MTBE (8015M/8020)	Benzene	ND	0.0050	mg/Kg			
	Toluene	ND	0.0050	mg/Kg			
	Ethyl benzene	ND	0.0050	mg/Kg			
•	Xylene(s)	ND	0.0050	mg/Kg			
	MTBE	ND	0.0050	mg/Kg			
Lead (6010B)	Lead	ND	5.0	mg/Kg			
MW-3-15.0` on 09/29/1999 13:35	LabID: 1999-10-0016-009	Results	<u>RL</u>	<u>Units</u>			
G/BTEX with MTBE (8015M/8020)	Gasoline	ND	1.0	mg/Kg			
	Benzene	ND	0.0050	mg/Kg			
	Toluene	ND	0.0050	mg/Kg			
	Ethyl benzene	ND	0.0050	mg/Kg			
	Xylene(s)	ND	0.0050	mg/Kg			
	MTBE	ND	0.0050	mg/Kg			

Lead

RL = Reporting Limit Surr. = Surrogate

mg/Kg

5.0

Environmental Services (SDB)

Total Lead

Aqua Science Engineers, Inc.

Danville, CA 94526

Attn: Robert Kitay

Phone: (925) 820-9310 Fax: (925) 837-4853

Project #: 3411

Project: Hutch's Car Wash

Site:

17945 Hesperian Blvd.

San Lorenzo, CA.

Samples Reported

Sample ID	Matrix	Date Sampled	Lab#
MW-1-10.5	Soil	09/29/1999 09:20	4
MW-1-15.0`	Soil	09/29/1999 09:28	5
MW-2-11.0`	Soil	09/29/1999 11:00	6
MW-2-15.0`	Soil	09/29/1999 11:07	7
MW-3-10.5	Soil	09/29/1999 13:26	8
MW-3-15.0°	Soil	09/29/1999 13:35	9

Environmental Services (SDB)

To: Aqua Science Engineers, Inc. Test Method:

6010B

Submission #: 1999-10-0016

Attn.: Robert Kitay

Prep Method:

3050B

Total Lead

Sample ID:

MW-1-10.5°

Lab Sample ID: 1999-10-0016-004

Project:

3411

Received:

09/30/1999 16:31

Site:

Hutch's Car Wash

Extracted:

10/06/1999 08:17

17945 Hesperian Blvd. San Lorenzo, CA.

Sampled:

09/29/1999 09:20

QC-Batch:

1999/10/06-02.15

Matrix:

Compound	Result	Rep.Limit	Units	Dilution	Analyzed	Flag
Lead	ND	5.0	mg/Kg	1.00	10/06/1999 11:41	

Environmental Services (SDB)

To: Aqua Science Engineers, Inc.

Test Method:

6010B

Submission #: 1999-10-0016

Attn.: Robert Kitay

Prep Method:

3050B

Total Lead

Sample ID:

MW-1-15.0°

Lab Sample ID: 1999-10-0016-005

Project:

3411

Received:

Hutch's Car Wash

09/30/1999 16:31

Site:

Extracted:

10/06/1999 08:17

17945 Hesperian Blvd. San Lorenzo, CA.

Sampled:

09/29/1999 09:28

QC-Batch:

1999/10/06-02.15

Matrix:

Compound	Result	Rep.Limit	Units -	Dilution	Analyzed	Flag
Lead	5.0	5.0	mg/Kg	1.00	10/06/1999 11:45	

Submission #: 1999-10-0016

Environmental Services (SDB)

To: Aqua Science Engineers, Inc. Test Method:

6010B

Attn.: Robert Kitay

Prep Method:

3050B

Total Lead

Sample ID:

MW-2-11.0°

Lab Sample ID: 1999-10-0016-006

Project:

3411

Received:

09/30/1999 16:31

Hutch's Car Wash

10/06/1999 08:17

Site:

17945 Hesperian Blvd. San Lorenzo, CA.

Extracted:

Sampled:

09/29/1999 11:00

QC-Batch:

1999/10/06-02.15

Matrix:

Compound	resuit	Rep.Limit	Units	Dilution	Analyzed	Flag
Lead	ND	5.6	mg/Kg	1.00	10/06/1999 11:49	

Submission #: 1999-10-0016

CHROMALAB, INC.

Environmental Services (SDB)

To: Aqua Science Engineers, Inc. Test Method:

6010B

Attn.: Robert Kitay

Prep Method:

3050B

Total Lead

Sample ID: MW-2-15.0`

Lab Sample ID: 1999-10-0016-007

Project:

3411

Received:

09/30/1999 16:31

Hutch's Car Wash

Site:

17945 Hesperian Blvd.

Extracted:

10/06/1999 08:17

San Lorenzo, CA.

Sampled:

09/29/1999 11:07

QC-Batch:

1999/10/06-02.15

Matrix:

Compound	rvesuit	Rep.Limit	Units	Dilution	Analyzed	Flag
Lead	ND	5.0	mg/Kg	1.00	10/06/1999 11;53	

Environmental Services (SDB)

Aqua Science Engineers, Inc.

Attn.: Robert Kitay

Test Method:

6010B

Submission #: 1999-10-0016

Prep Method:

3050B

Total Lead

Sample ID:

MW-3-10.5

Lab Sample ID: 1999-10-0016-008

Project:

3411

Received:

09/30/1999 16:31

Hutch's Car Wash

Site:

17945 Hesperian Blvd.

Extracted:

10/06/1999 08:17

To:

San Lorenzo, CA.

Sampled:

09/29/1999 13:26

QC-Batch:

1999/10/06-02.15

Matrix:

Soil

Compound	Result	Rep.Limit	Units	Dilution	Analyzed	Flag
Lead	ND	5.0	mg/Kg	1 00	10/06/1999 11:56	

Printed on: 10/11/1999 09:02

Environmental Services (SDB)

To: Aqua Science Engineers, Inc.

Test Method:

6010B

Submission #: 1999-10-0016

Attn.: Robert Kitay

Prep Method:

3050B

Total Lead

Sample ID:

MW-3-15.0`

Lab Sample ID: 1999-10-0016-009

Project:

3411

Received:

09/30/1999 16:31

Hutch's Car Wash

Site:

17945 Hesperian Blvd. San Lorenzo, CA.

Extracted:

10/06/1999 08:17

Sampled:

09/29/1999 13:35

QC-Batch:

1999/10/06-02.15

Matrix:

Compound	Result	Rep.Limi	t Units	Dilution	Analyzed	Flag
Lead	6.0	5.0	mg/Kg	1.00	10/06/1999 12:16	-

CHROMALAB, INC. Environmental Services (SDB)

Submission #: 1999-10-0016

To: Aqua Science Engineers, Inc.

Test Method:

6010B

Attn.: Robert Kitay

Prep Method:

3050B

Batch QC Report Total Lead

Method Blank

Soil

QC Batch # 1999/10/06-02.15

MB:

1999/10/06-02.15-024

Date Extracted: 10/06/1999 08:17

Compound	Result	Rep.Limit	Units	Analyzed	Flag	
Lead	ND	1.0	mg/Kg	10/06/1999 11:11		ĺ

Submission #: 1999-10-0016

Environmental Services (SD8)

To: Aqua Science Engineers, Inc.

Test Method:

6010B

Attn: Robert Kitay

Prep Method:

3050B

Batch QC Report

Total Lead

Laboratory Control Spike (LCS/LCSD)

Soil

QC Batch # 1999/10/06-02.15

LCS:

1999/10/06-02.15-027

Extracted: 10/06/1999 08:17

Analyzed: 10/06/1999 11:23

LCSD:

1999/10/06-02.15-028

Extracted: 10/06/1999 08:17

Analyzed: 10/06/1999 11:28

Compound	Conc.	[mg/Kg]	Ехр.Солс.	[mg/Kg]	Recov	ery [%]	RPD	Ctrl. Limi	ts [%]	Flag	S
	LCS	LCSD	LCS	LCSD	LCS	LCSD	[%]	Recovery	RPD	LCS	LCSD
Lead	101	96.0	100.0	100.0	101.0	96.0	5.1	80-120	20		

1220 Quarry Lane * Pleasanton, CA 94566-4756 Telephone: (925) 484-1919 * Facsimile: (925) 484-1096

Submission #: 1999-10-0016

Gas/BTEX (Methanol Extraction)

Aqua Science Engineers, Inc.

Danville, CA 94526

Phone: (925) 820-9310 Fax: (925) 837-4853

Project: Hutch's Car Wash

Attn: Robert Kitay

Project #: 3411

Site:

17945 Hesperian Blvd.

San Lorenzo, CA.

Samples Reported

Sample ID	Matrix	Date Sampled	Lab#
MW-1-15.0`	Soil	09/29/1999 09:28	5

Submission #: 1999-10-0016

Environmental Services (SDB)

To: Aqua Science Engineers, Inc.

Test Method:

8020 8015M

Attn.: Robert Kitay

Prep Method:

5030

Gas/BTEX (Methanol Extraction)

Sample ID:

MW-1-15.0`

Lab Sample ID: 1999-10-0016-005

Project:

3411

Received:

09/30/1999 16:31

Hutch's Car Wash

Site:

17945 Hesperian Blvd.

Extracted:

10/07/1999 15:55

Sampled:

San Lorenzo, CA. 09/29/1999 09:28

QC-Batch:

1999/10/07-05.02

Matrix:

Compound	Result	Rep.Limit	Units	Dilution	Analyzed	Flag
Gasoline	24	10	mg/Kg	1,00	10/07/1999 15:55	g
Benzene	ND	0.62	mg/Kg	1.00	10/07/1999 15:55	Ŭ
Toluene	ND	0.62	: mg/Kg	1.00	10/07/1999 15:55	
Ethyl benzene	ND	0.62	mg/Kg	1.00	10/07/1999 15:55	
Xylene(s)	ND	0.62	mg/Kg	1.00	10/07/1999 15:55	
MTBE	ND	0.62	mg/Kg	1.00	10/07/1999 15:55	
Surrogate(s)			1			
Trifluorotoluene	59.1	53-125	%	.00	10/07/1999 15:55	
4-Bromofluorobenzene-FID	71.2	58-124	%	.00	10/07/1999 15:55	

Submission #: 1999-10-0016

Environmental Services (SDB)

To: Aqua Science Engineers, Inc. Test Method:

8020

8015M

Attn.: Robert Kitay

Prep Method:

5030

Batch QC Report

Gas/BTEX (Methanol Extraction)

Method Blank

Soil

QC Batch # 1999/10/07-05.02

MB:

1999/10/07-05.02-001

Date Extracted: 10/07/1999 14:11

Compound	Result	Rep.Limit	Units	Analyzed	Flag
Gasoline	ND	10	mg/Kg	10/07/1999 14:11	
Benzene	ND	0.62	mg/Kg	10/07/1999 14:11	
Toluene	ND	0.62	: mg/Kg	10/07/1999 14:11	
Ethyl benzene	ND	0.62	mg/Kg	10/07/1999 14:11	
Xylene(s)	ND	0.62	mg/Kg	10/07/1999 14:11	
MTBE	ND	0.62	. mg/Kg	10/07/1999 14:11	
Surrogate(s)			:		
Trifluorotoluene	102.0	53-125	%	10/07/1999 14:11	
4-Bromofluorobenzene-FID	101.0	58-124	%	10/07/1999 14:11	

Printed on: 10/11/1999 09:01

Environmental Services (SDB)

Aqua Science Engineers, Inc.

Test Method:

8020 8015M

Submission #: 1999-10-0016

.

5030

Attn: Robert Kitay

To:

Prep Method:

Batch QC Report

Gas/BTEX (Methanol Extraction)

Laboratory Control Spike (LCS/LCSD)

Soil

QC Batch # 1999/10/07-05.02

LCS:

1999/10/07-05.02-002

Extracted: 10/07/1999 10:00

Analyzed:

10/07/1999 10:00

LCSD:

1999/10/07-05.02-003

Extracted: 10/07/1999 10:27

Analyzed:

10/07/1999 10:27

Compound	Сопс.	[mg/Kg]	Exp.Conc.	[mg/Kg]	Recov	ery [%]	RPD	Ctrl. Limi	its [%]	Flag	gs
	LCS	LCSD	LCS	LCSD	LCS	LCSD	[%]	Recovery	RPD	LCS	LCSD
Gasoline	0.508	0.499	0.625	0.625	81.3	79.8	1.9	75-125	35		-
Benzene	0.143	0.149	0.125	0.125	114.4	119.2	4.1	77-123	35		
Toluene	0.148	0.142	0.125	0.125	118.4	113.6	4.1	78-122	35		
Ethyl benzene	0.152	0.138	0,125	0.125	121.6	110.4	9.7	70-130	35		
Xylene(s)	0.399	0.423	0.375	0.375	106.4	112.8	5,8	75-125	35	1	
Surrogate(s) Trifluorotoluene	570	568	500	500	114.0	113.6		53-125			
4-Bromofluorobenzene-FI	474	466	500	500	94.8	93.2		58-124			1

Printed on: 10/11/1999 09:01

Environmental Services (SDB)

To: Aqua Science Engineers, Inc.

Test Method:

8020

8015M

Submission #: 1999-10-0016

Attn:Robert Kitay

Prep Method: 5030

Legend & Notes

Gas/BTEX (Methanol Extraction)

Analyte Flags

g

Hydrocarbon reported in the gasoline range does not match our gasoline standard.

Gas/BTEX and MTBE

Aqua Science Engineers, Inc.

Danville, CA 94526

Phone: (925) 820-9310 Fax: (925) 837-4853

Project: Hutch's Car Wash

Attn: Robert Kitay

Project #: 3411

Site:

17945 Hesperian Blvd.

San Lorenzo, CA.

Samples Reported

Sample ID	Matrix	Date Sampled	Lab#
MW-1-10.5`	Soil	09/29/1999 09:20	4
MVV-2-11.0`	Soil	09/29/1999 11:00	6
MW-2-15.0`	Soil	09/29/1999 11:07	7
MW-3-10.5`	Soil	09/29/1999 13:26	8
MVV-3-15.0`	Soil	09/29/1999 13:35	9

Submission #: 1999-10-0016

CHROMALAB, INC.

Environmental Services (SDB)

To: Aqua Science Engineers, Inc. Test Method:

8020

8015M

Attn.: Robert Kitay

Prep Method:

5030

Gas/BTEX and MTBE

Sample ID:

MW-1-10.5

Lab Sample ID: 1999-10-0016-004

Project:

3411

Received:

09/30/1999 16:31

Hutch's Car Wash

10/06/1999 21:44

Site:

17945 Hesperian Blvd. San Lorenzo, CA.

Extracted:

Sampled:

09/29/1999 09:20

QC-Batch:

1999/10/06-01.04

Matrix:

Soil

Compound	Result	Rep.Limit	Units	Dilution	Analyzed	Flag
Gasoline	ND	1.0	mg/Kg	1.00	10/06/1999 21:44	
Benzene	ND	0.0050	mg/Kg	1.00	10/06/1999 21:44	
Toluene	ND	0.0050	mg/Kg	1.00	10/06/1999 21:44	
Ethyl benzene	ND	0.0050	mg/Kg	1.00	10/06/1999 21:44	
Xylene(s)	ND	0.0050	mg/Kg	1.00	10/06/1999 21:44	
MTBE	200	0.0050	mg/Kg	1.00	10/06/1999 21:44	
Surrogate(s)						
Trifluorotoluene	87.3	53-125	%	1.00	10/06/1999 21:44	
4-Bromofluorobenzene-FID	76.7	58-124	%	1.00	10/06/1999 21:44	

Aqua Science Engineers, Inc.

Environmental Services (SDB)

Test Method:

8020

Submission #: 1999-10-0016

8015M

Attn.: Robert Kitay

To:

Prep Method:

5030

Gas/BTEX and MTBE

Sample ID:

MW-2-11.0`

Lab Sample ID: 1999-10-0016-006

Project:

3411

Received:

09/30/1999 16:31

Hutch's Car Wash

Site:

17945 Hesperian Blvd.

Extracted:

10/06/1999 19:56

San Lorenzo, CA. 09/29/1999 11:00

QC-Batch:

1999/10/06-01.04

Matrix:

Sampled:

Soil

Compound	Result	Rep.Limit	Units	Dilution	Analyzed	Flag
Gasoline	ND	1.0	mg/Kg :	1.00	10/06/1999 19:56	·
Benzene	ND	0.0050	: mg/Kg	1.00	10/06/1999 19:56	
Toluene	ND	0.0050	mg/Kg :	1.00	10/06/1999 19:56	
Ethyl benzene	ND .	0.0050	mg/Kg	1.00	10/06/1999 19:56	
Xylene(s)	ND	0.0050	, mg/Kg ;	1.00	10/06/1999 19:56	
MTBE	0.011	0.0050	mg/Kg	1.00	10/06/1999 19:56	
Surrogate(s)						
Trifluorotoluene	84.4	53-125	%	1.00	10/06/1999 19:56	
4-Bromofluorobenzene-FID	73.8	58-124	%	1.00	10/06/1999 19:56	

Aqua Science Engineers, Inc.

Environmental Services (SDB)

Test Method:

8020

8015M

Submission #: 1999-10-0016

Attn.: Robert Kitay

To:

Prep Method:

5030

Gas/BTEX and MTBE

Sample ID:

MW-2-15.01

Lab Sample ID: 1999-10-0016-007

Project:

3411

Received:

09/30/1999 16:31

Hutch's Car Wash

Site:

17945 Hesperian Blvd.

Extracted:

10/06/1999 20:23

San Lorenzo, CA.

Sampled: Matrix:

09/29/1999 11:07 Soil

QC-Batch:

1999/10/06-01.04

Compound

Compound	Result	Rep.Limit	Units	Dilution	Analyzed	Flag
Gasoline	ND	1.0	i mg/Kg	1.00	10/06/1999 20:23	
Benzene	ИD	0.0050	mg/Kg	1.00	10/06/1999 20:23	
Toluene	ND	0.0050	mg/Kg	1.00	10/06/1999 20:23	
Ethyl benzene	ND	0.0050	mg/Kg	1.00	10/06/1999 20:23	
Xylene(s)	ND	0.0050	mg/Kg	1.00	10/06/1999 20:23	
MTBE	0.070	0.0050	mg/Kg	1.00	10/06/1999 20:23	
Surrogate(s)						
Trifluorotoluene	91.7	53-125	%	1.00	10/06/1999 20:23	
4-Bromofluorobenzene-FID	82.8	58-124	%	1.00	10/06/1999 20:23	

Environmental Services (SDB)

Aqua Science Engineers, Inc.

Test Method:

8020 8015M

Submission #: 1999-10-0016

Attn.: Robert Kitay

Prep Method:

5030

Gas/BTEX and MTBE

Sample ID:

MW-3-10.5°

Lab Sample ID: 1999-10-0016-008

Project:

3411

Received:

09/30/1999 16:31

To:

Hutch's Car Wash

Extracted:

10/06/1999 20:50

Site:

17945 Hesperian Blvd. San Lorenzo, CA.

Sampled:

09/29/1999 13:26

QC-Batch:

1999/10/06-01.04

Matrix:

Soil

Compound	Result	Rep.Limit	Units	Dilution	Analyzed	Flag
Gasoline	ND	1.0	mg/Kg :	1.00	10/06/1999 20:50	
Benzene	ND	0.0050	mg/Kg :	1.00	10/06/1999 20:50	
Toluene	ND	0.0050	: mg/Kg	1.00	10/06/1999 20:50	
Ethyl benzene	ND	0.0050	ma/Ka	1.00	10/06/1999 20:50	
Xylene(s)	ND	0.0050	mg/Kg	1.00	10/06/1999 20:50	
MTBE	ND	0.0050	mg/Kg	1.00	10/06/1999 20:50	
Surrogate(s)						
Trifluorotoluene	80.8	53-125	%	1.00	10/06/1999 20:50	
4-Bromofluorobenzene-FID	70.1	58-124	%	1.00	10/06/1999 20:50	

Submission #: 1999-10-0016

Environmental Services (SDB)

To: Aqua Science Engineers, Inc.

Test Method:

8020 8015M

Attn.: Robert Kitay

Prep Method:

5030

Gas/BTEX and MTBE

Sample ID:

MW-3-15.0`

Lab Sample ID: 1999-10-0016-009

Project:

3411

Received:

09/30/1999 16:31

Hutch's Car Wash

Site:

17945 Hesperian Blvd. San Lorenzo, CA.

Extracted:

10/06/1999 21:17

Sampled:

09/29/1999 13:35

QC-Batch:

1999/10/06-01.04

Matrix:

Soil

Compound	Result	Rep.Limit	Units	Dilution	Analyzed	Flag
Gasoline	ND	1.0	mg/Kg	1.00	10/06/1999 21:17	
Benzene	ND	0.0050	mg/Kg	1.00	10/06/1999 21:17	
Toluene	ND	0.0050	mg/Kg	1.00	10/06/1999 21:17	
Ethyl benzene	ND	0.0050	mg/Kg	1.00	10/06/1999 21:17	
Xylene(s)	ND	0.0050	mg/Kg	1.00	10/06/1999 21:17	
MTBE	ND	0.0050	mg/Kg	1.00	10/06/1999 21:17	
Surrogate(s)						
Trifluorotoluene	85.7	53-125	%	1.00	10/06/1999 21:17	
4-Bromofluorobenzene-FID	70.6	58-124	%	1.00	10/06/1999 21:17	

Submission #: 1999-10-0016

CHROMALAB, INC.

Environmental Services (SDB)

To: Aqua Science Engineers, Inc.

Test Method: 8015M

8020

Attn.: Robert Kitay

Prep Method:

5030

Batch QC Report Gas/BTEX and MTBE

Method Blank

Soil

QC Batch # 1999/10/06-01.04

MB:

1999/10/06-01.04-001

Date Extracted: 10/06/1999 06:44

Compound	Result	Rep.Limit	Units	Analyzed	Flag
Gasoline	ND	1.0	mg/Kg	10/06/1999 06:44	
Benzene	ND	0.0050	mg/Kg	10/06/1999 06:44	
Toluene	ND	0.0050	mg/Kg	10/06/1999 06:44	
Ethyl benzene	ND	0.0050	mg/Kg	10/06/1999 06:44	
Xylene(s)	ND	0 0050	mg/Kg	10/06/1999 06:44	
MTBE	ND	0.0050	mg/Kg	10/06/1999 06:44	
Surrogate(s)					
Trifluorotoluene	96.2	53-125	%	10/06/1999 06:44	
4-Bromofluorobenzene-FID	91.6	58-124	%	10/06/1999 06:44	

Submission #: 1999-10-0016

Environmental Services (SDB)

To: Aqua Science Engineers, Inc.

Test Method:

8020 8015M

Prep Method:

5030

Batch QC Report

Gas/BTEX and MTBE

Laboratory Control Spike (LCS/LCSD)

Soil

QC Batch # 1999/10/06-01.04

LCS:

Attn: Robert Kitay

1999/10/06-01.04-002

Extracted: 10/06/1999 07:11

Analyzed: 10/06/1999 07:11

1999/10/06-01.04-003

Extracted: 10/06/1999 07:38

LCSD:

Analyzed: 10/06/1999 07:38

Compound	Conc.	[mg/Kg]	Exp.Conc.	[mg/Kg]	Recov	ery [%]	RPD	Ctrl. Lim	its [%]	[%] Flags	
	LCS	LCSD	LCS	LCSD	LCS LCSD		[%]	Recovery	Recovery RPD		LCSD
Gasoline	0.620	0.467	0.500	0.500	124.0	93.4	28.2	75-125	35		
Benzene	0.0907	0.0865	0.1000	0.1000	90.7	86.5	4.7	77-123	35		
Toluene	0.0871	0.0825	0.1000	0.1000	87.1	82.5	5.4	78-122	35		
Ethyl benzene	0.0847	0.0807	0.1000	0.1000	84.7	80.7	4.8	70-130	35		
Xylene(s)	0.253	0.243	0.300	0.300	84.3	81.0	4.0	75-125	35		
: Surrogate(s)											
Trifluorotoluene	464	436	500	500	92.8	87.2		53-125			
. 4-Bromofluorobenzene-FI	590	471	500	500	118.0	94.2		58-124			

Aqua Science Engineers, Inc. 208 W. El Pintado Road Danville, CA 94526 (925) 820-9391 FAX (925) 837-4853

Chain of Custody

FAX (925) 8 	37-2	<i>4853</i>												9				PAG	E	1 0	F	1				
SAMPLER (SIGNA				•	ONE NO.		PRO.	JECT N	AME	140	1 to la	.	~	Josi	<u></u>				NO.							
RahLE, A ANALY	Vito.	7	6 9	25)820-	939/											たって		7 DATE	<u> </u>	7-29-	99					
ANALY	/SK	3 RE	QUES	T	_			<u>π</u>									ĺ									
SPECIAL INSTRUCTIONS: NO. OF					TPH-GAS / MTBE & BTEX (EPA 5030/8015-8020)	TPH-GASOLINE (EPA 5030/8015)	TPH-DIESEL (EPA 3510/8015)	PURGEABLE HALOCARBONS (EPA 601/8010)	PURGEABLE AROMATICS (EPA 602/8020)	VOLATILE ORGANICS (EPA 624/8240)	SEMI-VOLATILE ORGANICS (EPA 625/8270)	ZEASE (20)	LUFT METALS (5) (EPA 6010+7000)	CAM 17 METALS (EPA 6010+7000)	PCBs & PESTICIDES (EPA 608/8080)	ORGANOPHOSPHORUS PESTICIDES (EPA 8140) (EPA 608/8080)	ORGANOCHLORINE HERBICIDES (EPA 8150)	FUEL OXYGENATES (EPA 8260)	4	1 Pb		COMPOSITE				
	DATE	TIME	MATRIX	NO, OF SAMPLES	TPH-G/ (EPA 50	TPH-G/ (EPA 50	TPH-DIE (EPA 3:	PURGE/ (EPA 60	PURGEA (EPA 60	VOLATIL (EPA 62	SEMI-V((EPA 62	OIL & GREASE (EPA 5520)	LUFT ME (EPA 60	CAM 17 (EPA 60	PCBs & (EPA 6	ORGAN PESTIC (EPA 6	ORGAN HERBIC	FUEL O	HarD	Total		COMF				
	9/29	9:15	Soil	1															×							
MW-1 105		9:20	1		入			,							·-					ኦ						
MU-1 15.0		9:28			Х			-												X						
MW-2 6.0'		10:55		!		_			_	ļ	:					·			×							
MW2 110		11:00			\rightarrow															×						
MW-Z 15.0'	1 1	11:07			\times															×						
MW-3 6.0		13:18																	×							
MW-3 10,5	1.1	13:26		j	><															×						
MW 3 15.0	\bigvee	13:35	V/	V/	X										, ,					X						
														•	f.J											
RELINQUISHED BY: REALE HAS Bignature)	time	· ·)	RECEIVED BY: 093099 RECEIVED BY: 10.00 (signature) (time)				RELINI (signar	QUISHE ture)	DBY:	(time)	1209	RECE MC (signa	IVED BY	(LABO	RATOR Vsus (time	rgton	COMMENTS: 5-DAY T.A.T.									
Robert E-Kite printed name)	(date	9-30 /77 :)	19 RICHARD DENTY (printed name) (date) 0 9/3				RICHARD DEWY O(printed name) (date) (D. Harrington (printed name) (date) /63/					3/	クィ	VA!	′ 1,	H.I						
Company- ASE	Company-			COMPANY- CHROMALAI				Company-			Compa	any-				Comp.	any-				1					

APPENDIX D

Well Sampling Field Logs

aqua science de la compansione del compansione della compansione d

WELL SAMPLING FIELD LOG

Project Name and Address: _ Job #:	Date of sampling: _ Sampled by:	10-6-99
Total depth of well (feet):	<u> 26.5</u> Well dian	neter (inches):Z"
Depth to water before sampli	ng (feet):	
Thickness of floating product Depth of well casing in water	if any:	&
Depth of well casing in water	(feet): 10,972	
Number of gallons per well of	casing volume (gallons):	
Number of well casing volum	nes to be removed:	<u>7</u>
Req'd volume of groundwater	to be purged before sam	pling (gallons): <u> </u>
Equipment used to purge the	well: ardicated	. Sailer
Time Evacuation Began: 100 Approximate volume of grou	Time Evacuat	ion Finished: 1028
Did the well as dwell by	nawater purged:	
Did the well go dry?: 100 Time samples were collected:	After how ma	any gallons:
Depth to water at time of sa	mulina: 15 59	
Percent recovery at time of	compliance Off	7
Percent recovery at time of Samples collected with: Sample color:	sampling. 11	L
Sample color: and builting	Odor: 141	C oder
Description of sediment in sa	ample:	0.401
The second secon		
CHEMICAL DATA		ا مورونات
Volume Purged Temp	pH Conductiv	/ity
70.(<u>6.77</u> 387	· · ·
<u> </u>	<u>, 99</u> 392	
<u> </u>	<u>us7</u> 309	
4 1.0	<u>6.9</u> 3 <u>401</u>	
		<u>:</u>
	Sign of	
SAMPLES COLLECTED		
_		
Sample # of containers Volume & 40 ml		Analysis
Mw-1 3 40m1	<u> </u>	_ TPH-6/ BTEX/MTBE



WELL SAMPLING FIELD LOG

Project Name and Address:	HUTCHS CAR NASH
Job #:	Date of sampling: $k-l_c-99$
Well Name: Mw-2	Date of sampling: $k-l_o-99$ Sampled by: 1712
Total depth of well (feet):	76.5 Well diameter (inches) 21
To all a little and the second	16 011
Thickness of floating product if	(feet):
Depth of well casing in water (f	feet):
Number of gallons per well casi	ing volume (gallons):
Number of well casing volumes	to be removed:
	be purged before sampling (gallons): 7.2
Equipment used to purge the wa	rell: Aldreated bodge
Time Evacuation Began: 0935	_ Time Evacuation Finished: 0950
Approximate volume of groundy	water purged:
Did the well go dry?:NO	After how many gallons:6455
Time samples were collected:	6955
Depth to water at time of sampl	ling:
Percent recovery at time of sam	npling: 999/4
Samples collected with:	dedreate ballet
Sample color: <u>vellew say</u>	Odor: Stight ItC
Description of sediment in samp	ple;
CHEMICAL DATA	= ⁻
Volume Purged Temp 2 71.0 3 72.1 4 71.3	Conductivity 587 7.04 542 6.87 542
SAMPLES COLLECTED	
Sample # of containers Volume & typ MW-Z 3 40-MI	Vers V Analysis TPH-6/BTEX/MTBE
· ·	σ

aqua science La Esta engineers inc.

WELL SAMPLING FIELD LOG

Project Name and Address:	HUTCH'S CAR WASH
Job #: 31//	Date of sampling: $10-6-99$
Job #:	Date of sampling: 10-6-99 Sampled by: 1172
Total depth of well (feet):	26.9' Well diameter (inches): 24
Depth to water before sample	ing (feet):14.58'
Thickness of floating product	if any:
Depth of well casing in water	if any: er (feet):
Number of gallons per well	casing volume (gallons): 2.6
Number of well casing volume	mes to be removed; 4
	r to be purged before sampling (gallons): 8.1
Equipment used to purge th	e well: dedicated barter
Time Evacuation Began: 69	undwater purged: 8-5
Approximate volume of gro	undwater purged:8-5
Did the well go dry?: NO	After how many gallons:
Time samples were collected	After how many gallons: 6415
Denth to water at time of a	ampling: 14.99
Percent recovery at time of	sampling: 99 99
Samples collected with:	dedicated Enjer
Sample color:yellow &	ey Odor: nonc
Description of sediment in :	sample:
CHEMICAL DATA	
Values Durand Tax	
Volume Purged Temp	pH Conductivity Cult
7,01	$-\frac{100}{100}$
	724 - 41
	$\frac{7.1}{2.69}$ $\frac{901}{540}$
	0 17
SAMPLES COLLECTED	
SAMI LES COLLECTED	
Sample # of containers Volume	er type container Prog. Toods. Analysis
Mu-3 # 3	& type container Pres Iced? Analysis 40-m1 VOAs V V APHAN BOEV/MORE
MEN'S &	

APPENDIX E

Analytical Report and Chain of Custody Form For Groundwater Samples Environmental Services (SDB)

Submission #: 1999-10-0206

Date: October 19, 1999

Aqua Science Engineers, Inc. 208 West El Pintado Road Danville, CA 94526

Attn.: Mr. lan T. Reed

Project: 3411

Hutches Car Wash

Site:

17945 Hesperian Blvd.

San Lorenzo

Dear Mr. Reed,

Attached is our report for your samples received on Tuesday October 12, 1999. This report has been reviewed and approved for release. Reproduction of this report is permitted only in its entirety.

Please note that any unused portion of the samples will be discarded after November 11, 1999 unless you have requested otherwise. We appreciate the opportunity to be of service to you. If you have any questions, please call me² at (925) 484-1919.

Sincerely,

Pierre Monette

Gas/BTEX and MTBE

Aqua Science Engineers, Inc.

⊠_ 208 West El Pintado Road

Danville, CA 94526

Attn: Ian T. Reed

Phone: (925) 820-9391 Fax: (925) 837-4853

Project #: 3411

Project: Hutches Car Wash

Site: 17

17945 Hesperian Blvd.

San Lorenzo

Samples Reported

Sample ID	Matrix	Date Sampled	Lab#
MW-1	Water	10/06/1999 10:30	1
MW-2	Water	10/06/1999 09:55	2
MW-3	Water	10/06/1999 09:15	3

Environmental Services (SDB)

To: Aqua Science Engineers, Inc.

Test Method:

8020 8015M

Submission #: 1999-10-0206

Attn.: Ian T. Reed

Prep Method:

5030

Gas/BTEX and MTBE

Sample ID:

MW-1

Lab Sample ID: 1999-10-0206-001

Project:

3411

Received:

10/12/1999 17:08

Hutches Car Wash

Site.

17945 Hesperian Blvd.

Extracted:

10/18/1999 16:02

San Lorenzo

Sampled:

10/06/1999 10:30

QC-Batch:

1999/10/18-01.01

Matrix:

Water

Compound	Result	Rep.Limit	Units	Dilution	Analyzed	Flag
Gasoline	1500	50	ug/L	1.00	10/18/1999 16:02	
Benzene	3.3	0.50	ug/L	1.00	10/18/1999 16:02	
Toluene	2.3	0.50	ug/L	1.00	10/18/1999 16:02	
Ethyl benzene	27	0.50	ug/L	1.00	10/18/1999 16:02	
Xylene(s)	72	0.50	ug/L	1.00	10/18/1999 16:02	
MTBE	120	5.0	ug/L	1.00	10/18/1999 16:02	
Surrogate(s)						
Trifluorotoluene	98.9	58-124	%	1.00	10/18/1999 16:02	•
4-Bromofluorobenzene-FID	119.3	50-150	%	1.00	10/18/1999 16:02	

Environmental Services (SDB)

To: Aqua Science Engineers, Inc.

Test Method:

8020

8015M

Submission #: 1999-10-0206

Attn.: Ian T. Reed

Prep Method:

5030

Gas/BTEX and MTBE

Sample ID:

MW-2

Lab Sample ID: 1999-10-0206-002

Project:

3411

10/12/1999 17:08

Received:

Site:

Hutches Car Wash

10/13/1999 21:08

17945 Hesperian Blvd. San Lorenzo

Extracted:

Sampled:

10/06/1999 09:55

QC-Batch:

1999/10/13-01.01

Matrix:

Water

Compound	Result	Rep.Limit	Units	Dilution	Analyzed	Flag
Gasoline	ND	50	ug/L	1.00	10/13/1999 21:08	·
Benzene	ND	0.50	ug/L	1.00	10/13/1999 21:08	
Toluene	ND	0.50	ug/L	1.00	10/13/1999 21:08	
Ethyl benzene	ND	0.50	ug/L	1.00	10/13/1999 21:08	
Xylene(s)	ND	0.50	ug/L	1.00	10/13/1999 21:08	
MTBE	18	5.0	ug/L	1.00	10/13/1999 21:08	
Surrogate(s)						
Trifluorotoluene	97.4	58-124	%	1.00	10/13/1999 21:08	
4-Bromofluorobenzene-FID	79.4	50-150	%	1.00	10/13/1999 21:08	

Submission #: 1999-10-0206

Environmental Services (SDB)

To: Aqua Science Engineers, Inc. Test Method:

8020 8015M

Attn.: Ian T. Reed

Prep Method:

5030

Gas/BTEX and MTBE

Sample ID:

MW-3

Lab Sample ID: 1999-10-0206-003

Project:

3411

Received:

Hutches Car Wash

10/12/1999 17:08

Site:

10/13/1999 20:39

17945 Hesperian Blvd. San Lorenzo

Extracted:

Sampled:

10/06/1999 09:15

QC-Batch:

1999/10/13-01.01

Matrix:

Water

Compound	Result	Rep.Limit	Units	Dilution	Analyzed	Flag
Gasoline	ND	50	ug/L	1.00	10/13/1999 20:39	1. 17.11
Benzene	ND	0.50	ug/L	1.00	10/13/1999 20:39	
Toluene	ИD	0.50	ug/L	1.00	10/13/1999 20:39	
Ethyl benzene	ND	0.50	ug/L	1.00	10/13/1999 20:39	
Xylene(s)	ND	0.50	ug/L	1.00	10/13/1999 20:39	
MTBE	ND	5.0	ug/L	1.00	10/13/1999 20:39	
Surrogate(s)						
Trifluorotoluene	88.8	58-124	%	1.00	10/13/1999 20:39	
4-Bromofluorobenzene-FID	77.8	50-150	%	1.00	10/13/1999 20:39	

Submission #: 1999-10-0206

Environmental Services (SDB)

To: Aqua Science Engineers, Inc.

Test Method:

8020

8015M

Attn.: Ian T. Reed

Prep Method:

5030

Batch QC Report
Gas/BTEX and MTBE

Method Blank

Water

QC Batch # 1999/10/13-01.01

MB:

1999/10/13-01.01-001

Date Extracted: 10/13/1999 05:20

Compound	Result	Rep.Limit	Units	Analyzed	Flag
Gasoline	ND	50	ug/L	10/13/1999 05:20	
Benzene	ND	0.5	ug/L	10/13/1999 05:20	
Toluene	ND	0.5	ug/L	10/13/1999 05:20	
Ethyl benzene	ND	0.5	ug/L	10/13/1999 05:20	
Xylene(s)	ND	0.5	ug/L	10/13/1999 05:20	
MTBE	ND	5.0	ug/L	10/13/1999 05:20	
Surrogate(s)	,				
Trifluorotoluene	89,4	58-124	%	10/13/1999 05:20	
4-Bromofluorobenzene-FID	73.6	50-150	%	10/13/1999 05:20	

Submission #: 1999-10-0206

CHROMALAB, INC.

Environmental Services (SDB)

To: Aqua Science Engineers, Inc.

Test Method:

8020

8015M

Attn.: lan T. Reed

Prep Method:

5030

Batch QC Report
Gas/BTEX and MTBE

Method Blank

Water

QC Batch # 1999/10/18-01.01

MB:

1999/10/18-01.01-001

Date Extracted: 10/18/1999 06:04

Compound	Result	Rep.Limit	Units	Analyzed	Flag
Gasofine	ND	50	ug/L	10/18/1999 06:04	
Benzene	ND	0.5	ug/L	10/18/1999 06:04	
Toluene	ND	0.5	ug/L	10/18/1999 06:04	
Ethyl benzene	ND	0,5	ug/L	10/18/1999 06:04	
Xylene(s)	ND	0.5	ug/L	10/18/1999 06:04	
MTBE	ND	5.0	ug/L	10/18/1999 06:04	
Surrogate(s)					
Trifluorotoluene	92.0	58-124	%	10/18/1999 06:04	
4-Bromofluorobenzene-FID	68.2	50-150	%	10/18/1999 06:04	

Environmental Services (SDB)

Aqua Science Engineers, Inc. To:

Test Method:

8020

8015M

Submission #: 1999-10-0206

Attn: Ian T. Reed

Prep Method:

5030

Batch QC Report

Gas/BTEX and MTBE

Laboratory Control Spike (LCS/LCSD)

Water

QC Batch # 1999/10/13-01.01

LCS:

1999/10/13-01.01-002

Extracted: 10/13/1999 07:45

Analyzed: 10/13/1999 07:45

LCSD:

1999/10/13-01.01-003

Extracted: 10/13/1999 08:12

Analyzed: 10/13/1999 08:12

Compound	Conc.	[ug/L]	Exp.Conc.	[ug/L]	Recovery [%]		RPD	Ctrl. Lim	its [%]	Flags	
	LCS	LCSD	LCS	LCSD	LCS	LCSD	[%]	Recovery	RPD	LCS	LCSD
Gasoline	424	477	500	500	84.8	95.4	11.8	75-125	20		
Benzene	106	110	100.0	100.0	106.0	110.0	3.7	77-123	20		
Toluene	105 112		100.0	100.0	105.0	112.0	6,5	78-122	20		
Ethyl benzene	103	108	100.0	100.0	103.0	108.0	4.7	70-130	20		
Xylene(s)	309	324	300	300	103.0	108.0	4.7	75-125	20		
Surrogate(s)											
Trifluorotoluene	543	556	500	500	108.6	111.2		58-124			
4-Bromofluorobenzene-FI	409	446	500	500	81.8	89.2		50-150			

Environmental Services (SDB)

To: Aqua Science Engineers, Inc. Test Method:

8020 8015M

Submission #: 1999-10-0206

5030

Attn: Ian T. Reed

Prep Method:

Batch QC Report

Gas/BTEX and MTBE

Laboratory Control Spike (LCS/LCSD)

Water

QC Batch # 1999/10/18-01.01

LCS:

1999/10/18-01.01-002

Extracted: 10/18/1999 06:32

Analyzed: 10/18/1999 06:32

LCSD:

1999/10/18-01.01-003

Extracted: 10/18/1999 06:59

Analyzed: 10/18/1999 06:59

Recovery [%] RPD Ctrl. Limits [%] Flags [ug/L] Compound Conc. [ug/L] Exp.Conc. LCS LCS LCSD Recovery RPD LCSD LCS LCSD LCS LCSD [%] 500 95.6 93.0 2.8 75-125 20 478 465 500 Gasoline 106 100,0 100.0 105.0 106.0 0.9 77-123 20 105 Benzene 110 100.0 100,0 109.0 110.0 0.9 78-122 20 Toluene 109 100.0 105.0 106.0 0.9 70-130 20 100.0 Ethyl benzene 105 106 75-125 20 314 316 300 300 104.7 105.3 0.6 Xylene(s) Surrogate(s) 105.0 106.2 58-124 500 531 500 Trifluorotoluene 525 500 89.2 87.2 50-150 446 436 500 4-Bromofluorobenzene-Fl

> 1220 Quarry Lane * Pleasanton, CA 94566-4756 Telephone: (925) 484-1919 * Facsimile: (925) 484-1096

Printed on: 10/20/1999 07:41

Aqua Science Engineers, Inc. 208 W. El Pintado Road Danville, CA 94526 (925) 820-9391 FAX (925) 837-4853

Chain of Custody

FAX (925)	837-4	1853																PAGE	<u> </u>	/OF	1	
SAMPLER (SIGN	ATURE)			(PHC	ONE NO.))	PROJ	JECT N	AME	H	utche	·3 (ar W	aşh				JOBI	10	34	[]	
ilaT	Pe	ed	(925) 820.93 T	391		ADDR	RESS			1794	5 p	1000	in b	1vd.	5 cm 1	kienz c	DATE		0-12-	47	
			QUES	T				25 25			S.					00	6					
S-day TAT				BTEX 802C	:		YKBC	ATIC5	ற	GARC				7ES	10KU A Ø14 O)	点 N S 15	ES					
			TPH-GAS / MT3E & BTEX (EPA 5030/8015-8020)	TPH-GASOLINE (EPA 5030/8015)	TPH-DIESEL (EPA 3510/8015)	PURGEABLE HALOCARBONS (EPA 601/8010)	PURGEABLE AROMATICS (EPA 602/8020)	VOLATILE ORGANICS (EPA 624/8240)	SEMI-VOLATILE ORGANICS (EPA 625/8270)	575E 20)	LUFT METALS (5) (EPA 60:0+7000)	CAM 17 METALS (EPA 6010+7000)	PCBs & PESTICIDES (EPA 608/8080)	ORGANOPHOSPHORUS PESTICIDES (EPA 0140) (EPA 606/8080)	ORGANOCHLORINE HERBICIDES (EPA 8150)	FUEL OXYGENATES (EPA 8260)				COMPOSITE		
SAMPLE ID.	DATE	TIME	MATRIX	NO. OF SAMPLES	TPH-GA9 (EPA 50	1PH-GA9 (EPA 50	TPH-DIE	PURGEAI (EPA 60	PURGEAI (EPA 60	YOLATILE (EPA 62	SEMI-VC (EPA 62	OIL& GREASE (EPA 5520)	LUFT ME (EPA 6C	CAM 17) (EPA 60	PCBs & (EPA 6	ORGAN PESTIC (EPA 6	ORGAN	FUEL 0) (EPA 8)				COMF
MW-1	16-6- 99	103c	water	3	X														,			
MW-2	14-心質	0955	wester	3	\geq			ž,						<u></u>								
MV-3	106-48	0915	reatier	3				7. *				_								,		
																						
					·.													•			<u> </u>	
									-													
						-													- 			
RELINQUISHED BY UCTPUED (olgnature)	í: √ (tima		RECEIVI (signati		(time)			IQUISHE	DBY:	(time)		R⊼CI ∭.C (olga	EMED B Lucil aburo)	Y LABO	RATO! Www.	RY:	CON	COMMENT S :				
lan T. Rece												\supset .	Har	VIN	gtor	1] Cdo TIT				
(printed name)	(dat	(e)	(printed		(date)			ed name	;)	(date)		D. Harvington (printed name) (date) Company- 10/12/99 Chromalab 1708			_	5 day TAT.						
Company-	F	\cap	Compar	ıy-			Comp	any-				Ch	rany- Some	rlsb	. /c . /	112/99 70 8	5					
AS	<u>'</u>	(<u>_l</u>				<u> </u>					i				<u> </u>						