

October 12, 1999

Project Number 192-01-03

Mr. Hooshang Hadjian Foothill Beacon 7240 Dublin Boulevard Dublin, CA 94568

Subject:

Report of Groundwater Monitoring at Foothill Beacon, 16210 Foothill Boulevard, San Leandro, California

This Groundwater Monitoring Report describes the site history, field work and laboratory analysis results for a sampling event at the subject property.

The project site is located at 16210 Foothill Boulevard, San Leandro, California. The site is currently used as a convenience store that retails gasoline under the name Foothill Beacon.

SITE BACKGROUND

Four underground storage tanks were removed from this site by California Petroleum Equipment, Inc., of Fresno on January 28, 1997. There were two 8,000 gallon tanks and two 5,000 gallon tanks, single wall steel, and appeared to be in fair condition, with some pitting evident on the tanks with close inspection.

The Alameda County inspector probed the pitted areas and found two 1/4" to 1/2" holes at the end of one of the 5,000 gallon tanks. The holes were about three feet from the bottom of the tank at the weld by the tank cylinder and tank end. Although the metal was soft enough to disintegrate with the probing of a screwdriver, it appears that the tank did not leak from these spots. The tanks were sitting in about four feet of water, and if the tanks leaked, water would have been three to four feet deep in this tank. Since no water was pumped from the tank during service, the tank was apparently intact until removal. Groundwater was eleven feet below grade surface on the day of the tank removal, as measured by a tape measure.

Soil samples were collected from the tank excavation. Sample analysis results show up to 360 ppm TPH-g, up to 9.4 ppm MTBE, up to 2.3 ppm benzene, up to 2.3 ppm toluene, up to 3.0 ppm ethyl-benzene, and up to 98 ppm xylenes.

Three monitoring wells were installed and soil samples were taken by Parker Environmental Services on October 13, 1998, results found in Table 1.

Table 1 - Soil Sample Analysis Results Foothill Beacon Samples Taken October 13, 1998

Sample	TPH-g	MTBE	Benzene	Toluene	Ethylbenzene	Xylenes
MW-1 @ 25.5	' ND	ND	ND	ND	ND	ND
MW-1 @ 30.5	' ND	ND	ND	ND	ND	ND
MW-2 @ 5.5	' ND	ND	ND	ND	ND	ND
MW-2 @ 10.5	' ND	ND	ND	ND	ND	ND .
MW-2 @ 15.5	' ND	ND	ND	ND	ND	ND
MW-3 @ 5.5	' ND	1.8	ND	ND	0.005	0.019
MW-3 @ 10.5	' ND	0.38	ND	ND	ND	ND
MW-3 @ 15.5	' ND	0.34	ND	ND	ND	ND -
Detect. Limit	1.0	0.05	0.005	0.005	0.005	0.005

ND means not detected. Results are in µg/L or parts per billion.

From the survey and depth to groundwater measurement data, the site groundwater on October 26, 1998 was approximately ten feet below grade surface (BGS) and the gradient direction was N 79.83 °E, with an apparent gradient of 0.0082 ft./ft. The gradient on November 2, 1998 was found to have an apparent gradient direction of S 69.30 °E, with an average gradient of 0.0036 ft./ft.

Groundwater samples were obtained from the wells on November 2, 1998 and analyzed for TPH as gasoline (EPA method 5030/8015) with BTEX and MTBE (method 602). Sample analysis shows no TPH-g, BTEX or MTBE detected in MW-1 and MW-2. TPH-g and BTEX were not detected in MW-3, but MTBE was detected at 190 parts per billion (ppb).

The first quarter groundwater monitoring of February 1999 showed groundwater about 10 feet BGS, with gradient direction S 63.15° E and apparent slope of 0.003 ft/ft. Sample analysis only showed MTBE in MW-3 at 340 ppb. All other analysis showed non-detect.

Current Activities

Sampling and measurements were done on August 24, 1999. Prior to sampling, the groundwater elevations were measured using an electric water level meter. Initial depths below ground surface were as follows:

Table 2: Groundwater Evaluation Foothill Beacon 16210 Foothill Boulevard Measured August 24, 1999

Well	Casing Elevation	Depth to Water	Ground Water Elevation
MW-1	138.57	11.43	127.14
MW-2	137.94	10.65	127.29
MW-3	138.88	11.58	127.30

elevation above mean sea level, in feet

Groundwater gradient direction on August 24, 1999 was S 52.26° E at an apparent slope of 0.0023 ft/ft. Figure 2 shows apparent groundwater gradient.

Between seven and fourteen gallons were removed from each well, more than three well volumes. All purge water was placed in a sealed plastic drum and remains on site. Samples were taken from the end of the discharge hose at a flow rate of less than one liter per minute. The water from each well was placed in two 40-milliliter vials filled so that there was no air (head space) remaining in them. Samples were labeled and placed on ice in a cooler for transport to a state certified hazardous materials testing laboratory, McCampbell Analytical of Pacheco, California.

Sampling equipment was cleaned in one bucket with TSP Substitute and rinsed in two separate buckets with tap water, then rinsed with deionized water after use at each well. All purge water and equipment wash water was placed in a plastic drum and remains on-site. A copy of the Water Level Measurements Form is attached to this report.

The samples were analyzed for TPH-gasoline, MTBE and BTEX using EPA Methods 8015 and 8020. A copy of the laboratory report and Chain of Custody form are attached to this report. Results are shown in Table 3 and Figure 3, the Hydrocarbon Concentration Map.

Table 3 - Groundwater Sample Analysis Results Foothill Beacon Samples collected August 24, 1999

Sample #	TPH-g	MTBE	Benzene	Toluene	Ethylbenzene	Xylenes
MW-1	ND	ND	ND	ND	ND	ND
MW-2	ND	ND	ND	ND	ND	ND
MW-3	ND	81	ND	ND	ND	ND
Det. Limit	50	5.0	0.5	0.5	0.5	0.5

ND means not detected. Results are in µg/L or parts per billion.

The analysis results are similar to samples taken when the wells were installed and the first quarter – but the lowest results to date.

Future Directions

One additional quarterly monitoring event is scheduled. This additional sampling test will provide seasonal tracking of gradient as well as groundwater in MW-3. Copies of this report will be forwarded to the Alameda County Environmental Management Department, and to the California Regional Water Quality Control Board, San Francisco Bay Region.

Sincerely:

PARKEŘ ENVIRONMENTAL SERVICES

James D. Parker President

Reviewed By:


Gary D. Lowe, R.G., C.E.G.


Principal, Hydrogeologist

H₂OGEOL, A GroundWater Consultancy

Attachments

cc: Mr. Robert Weston, Alameda County Environmental Management Department Mr. Lester Feldman, San Francisco Bay Regional Water Quality Control Board





FOOTHILL BOULEVARD

580 FREEWAY

Wells measured on August 24, 1999

→ = monitoring well

[X.X] = groundwater elevation


= line of equal elevation

Location of site features are approximate.

Scale: 1'' = 30'

PARKER Environmental Services 190 East 7th Street Pittsburg, CA 94565 (925) 439-1024

Figure 2 - Groundwater Gradient Foothill Beacon 16210 Foothill Boulevard San Leandro, CA



Key:→ = monitoring well (X.X) = TPH-g


 $\{X,X\} = Benzene$

[X.X] = MTBE

580 FREEWAY

Samples collected August 24, 1999. Results are in parts per billion (ppb).

Location of site features are approximate.



PARKER Environmental Services 190 East 7th Street Pittsburg, CA 94565 (925) 439-1024

Figure 3, Groundwater Sample Results
Foothill Beacon
16210 Foothill Boulevard
San Leandro, CA

9/99


110 2nd Avenue South, #D7, Pacheco, CA 94553-5560 Telephone: 925-798-1620 Fax: 925-798-1622 http://www.mccampbell.com E-mail: main@mccampbell.com

Parker Environmental Services	Client Project ID: Foothill Beacon, San	Date Sampled: 08/24/99	
190 East 7th Street	Leandro	Date Received: 08/30/99	
Pittsburg, CA 94565	Client Contact: Jim Parker	Date Extracted: 08/30/99	
	Client P.O:	Date Analyzed: 08/30/99	

EPA mem	ods 5030, modified	8015, and 8	3020 or 602; Ca	lifornia RW	QCB (SF Bay	Region) met		30)	<u> </u>
Lab ID	Client ID	Matrix	TPH(g) ^t	МТВЕ	Beozene	Toluene	Ethylben- zene	Xylenes	% Recovery Surrogate
18212	93/FB/MW-1	w	ND	ND	ND	ND	ND	ND	96
18213	93/FB/MW-2	w	ND	ND	ND	ND	ND	ND	96
18214	93/FB/MW-3	w	ND	81	ND	ИD	ND	ND	88
							6		
						-			
			-		-				
				,		•			:
		'							
	·		-						
	i	-							- -
		-	· · <u></u> i		•				
Reportin	g Limit unless tated; ND means	w	50 ug/L	5.0	0.5	0.5	0.5	0.5	
not detec	eted above the rting limit	S	1.0 mg/kg	0.05	0.005	0.005	0.005	0.005	

^{*} water and vapor samples are reported in ug/L, wipe samples in ug/wipe, soil and sludge samples in mg/kg, and all TCLP and SPLP extracts

The following descriptions of the TPH chromatogram are cursory in nature and McCampbell Analytical is not responsible for their interpretation: a) unmodified or weakly modified gasoline is significant; b) heavier gasoline range compounds are significant(aged gasoline?); c) lighter gasoline range compounds (the most mobile fraction) are significant; d) gasoline range compounds having broad chromatographic peaks are significant; biologically altered gasoline?; e) TPH pattern that does not appear to be derived from gasoline (?); f) one to a few isolated peaks present; g) strongly aged gasoline or diesel range compounds are significant; h) lighter than water immiscible sheen is present; i) liquid sample that contains greater than ~5 vol. % sediment; j) no recognizable pattern.



cluttered chromatogram; sample peak coelutes with surrogate peak

QC REPORT FOR HYDROCARBON ANALYSES

Date:

08/29/99-08/30/99

Matrix:

WATER

	Concent	ration	(ug/L)	1	% Reco	very	
Analyte	Sample (#17000)	MS	MSD	Amount Spiked	MS	MSD	RPD
TPH (gas) Benzene Toluene	0.0	100.4 9.6 9.5	102.1 9.2 9.2	100.0 10.0 10.0	100.4 96.0 95.0	102.1 92.0 92.0	1.7 4.3 3.2
Ethyl Benzene Xylenes	0.0	9.6 29.5	9.4 28.2	10.0 30.0	96.0 98.3	94.0 94.0	2.1 4.5
TPH(diesel)	0.0	8420	8662	7500	112	115	2.8
TRPH (oil & grease)	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Rec. = (MS - Sample) / amount spiked x 100

RPD = $((MS - MSD) / (MS + MSD)) \times 2 \times 100$

16525 ZDE35 PARKER ENVIRONMENTAL SERVICES CHAIN OF CUSTODY 190 East 7th Street PEPTOR & :3TAD PAGE_1 of 1 Pittsburg, CA 94565 Sample Source: Phone: 925-439-1024 Foothill Beacon Fax: 925-439-2566 16210 Foothill Blvd. SAMPLER(S): James La San Leandro, California SAMPLER'S SIGNATURE: SAMPLE RECIEPT: TOTAL No. of CONTAINERS CONTAINERS CHAIN OF CUSTODY SEALS RECTO GOOD CONDITION/COLD, TPH-gasoline + BTEX & MTBE CONFORMS TO RECORD LAB NO. 1644 Ë NUMBER FAX RESULTS TO (510) 373-9222 SAMPLE ID DATE TIME MATRIX LAB ID. 18212 9 g /FB/MW-1 8 1/4/99 WATER х 8:12 93, /FB/MW-2 8 12499 WATER х 8:36 2 18213 93 /FB/MW-3 8 2499 WATER 4 Х 2 8:57 18214 PRESERVATION > **GOOD CONDITION APPROPRIATE** STANDARD HEAD SPACE ABSENT TURNAROUND TIME RELINQUISHED BY: RELINQUISHED-BY: SIGNATURE garre To SIGNATURE TIME TIME PRINTED NAME James Lowe 11:29 PRINTED NAME Gary D. Lowe DATE H_2OCEOL H20GEOL COMPANY 8/24/99 COMPANY RECEIVED BY: RECEIVED BY LABORATORY:: SIGNATURE SIGNATURE TIME TIME PRINTED NAME - 4 : 8/30/99 Gary D. Lowe PRINTED NAME DATE DATE H_2OGEOL COMPANY

4 12499

COMPANY McCAMPBELL ANALYTICAL,INC.

/ /99

PARKER ENVIRONMENTAL SERVICES LOG OF WELL SAMPLING ACTIVITIES

				Footh	nill Beacon					
Well Iden	tification:	<u>MW- }</u> F	roject Nam	e: <u>1621</u>	O Foothill Blvd	., Sa	an Leandro,	CA		Date: 8 /24/99
Sampled I	ьу: Дос	mos Your		Weat	her Conditions	:			· · · · · · · · · · · · · · · · · · ·	
Well Loca	rtion:			Well	Casing Diamete	er:		<u>:h</u>	Depth of Well C	asing: <u>19</u> 4.29
Acasuring	Point: To	p of PVC Casing	initial	Depth to V	/ater: _L	13	_ Fi	nal	Depth to Water;	Not measured
asing Vo	olume (1 vol.	/ 3 vol): 4,5	4/13.6	2_			Well Bore	hole	Volume:	
urging M	ethod:	Centrifugal Pump Grundfos Subme Centrifugal Pump	rsible Pump /ES-60 Sub	mersible	- 	Sa	ampling Met	hod		bmersible Pump
		ES-40/-60 Subm	ersible Pum	<u>х</u>	_					p @ <1L/min.
omments		e below	Total Disc	charge:	(5		Ca	niaı	g Volumes Purged:	3.30
aste Wa	ter Disposal:	To drum.								
arting Ti		: 43					. •			
me Pump	on:	550							•	• • • •
Date	Time	Gal. Purged	рН	T deg. F	Diluted S.C.		Dif. Factor		S.C. (µS/cm)	Color
/24/99	<i>පි</i> :රජ	13	7.30	67,5		×		_	2570	1
	8:08	13/2	7,29	67.4		×			2570	-
	8 09	14	7.29	67.7		×			2500	
	8:11	14/2	7.29	67,8		×	-	-	2560	
	:		122.	1000		ऻ			2 30 0	
	:		<u> </u>			×		# #		
	:			-		\vdash	 			
	:					×		=		1
	:		-			×		=		
	: 1		<u> </u>			×		_		
-	:					x		=		
Sample	Identification	on: <u>93</u> /FB/M	w-{		Sample Time:		9.12 TUF		DITY ANALYSIS	
Finishin	g Time:		-		Tim	e A	nalyzed:		NTU V	alue:

PARKER ENVIRONMENTAL SERVICES LOG OF WELL SAMPLING ACTIVITIES

				Footh	vill Beacon					
Well Ident	tification:	<u>mw-2</u>	Project Name	: <u>1621</u>	O Foothill Blvd.	, S	an Leandro,	CA	Da	ite: <u>8_/24/99</u>
Sampled b	р у : <u></u>	ac Try	_	Weat	her Conditions	:				
Weil Locat	tion:			Well	Casing Diamete	9F3		<u>:h</u>	Depth of Well Cas	ing: <u>24.55</u>
Measuring	Point: Top	o of PVC Casing	Initial	Depth to W	/ater: 10,6	5	Fi	nal I	Depth to Water:	Not measured
Casing Vo	lume (1 vol.,	3 vol): 2.2	7/6.80	2			Well Bore	hole	Volume:	
Purging Mo	ethod:	Centrifugal Pump Grundfos Subme Centrifugal Pump	rsible Pump		- -	Sa	ampling Met	hod	Peristaltic Pum Grundfos Subn Teflon Bailer	
	•	ES-40/-60 Subm	ersible Pump	X					ES Sub. Pump	@ < 11 /min
	•				-				CO OGD. I BIIIP	₩ < I Dmin.
Purging Ra	ite: See	below	Total Disc	harge:	8.4	<u> </u>	Ca	gnise	Volumes Purged:	3.74
Comments	:	<u>_</u>	·							· _ ·
Waste Wat	ter Disposal:	To drum			·					
Starting Tid	me: B	- 16								
Time Pump		: 21								
Date	Time	Gal. Purged	pН	T deg. F	Diluted S.C.	Γ	Dil. Factor		S.C. (µS/cm)	Color
3 /24/99	8:30	6.3	7.16	68.0		×		_	2450	
	A :32	7	7.26	683		\vdash	·			· - · · · · · · · · · · · · · · · · · ·
	7 :33	7.5	7,25			×	1	2=	2450	
				69.5		×	<u> </u>	=	2920	·
	9:34	_8	7.25	68.5		×		==	2450	
						×		_		i
	:					×	1	=		
					-	×		=		
	;	·			<u> </u>			\vdash		
	:					×		=		
	:		 		· · · · · · · · · · · · · · · · · · ·	×		=		
			-		-	x		=		
	- :					×		=		
Sample	klentificatio	n: <u>93</u> /FB/M	iw-2		Sample Time:		<u>8:36</u>	—-	_	
							TUF	RBID	ITY ANALYSIS	
Finishing	g Time:	-	_		Tim	e A	naiyzed:		NTU Val	lue:

PARKER ENVIRONMENTAL SERVICES LOG OF WELL SAMPLING ACTIVITIES

Vell Ident											
	itication:	MW-3 F	Project Name	1621	O Foothill Blvd.	, Sa	n Leandro,	CA		Date:	8 /24/99
empled t	ov:	gonestons		West	her Conditions:	:	 				
'eli Locat	tion:			Well (Casing Diamete	ж.	2-inc	<u>:h</u>	Depth of Well C	Casing:	24.3
easuring	Point: <u>To</u>	p of PVC Casing	Initial	Depth to W	/ater: 11.	58	<u>.</u> Fir	nel D	Pepth to Water:	Not	measured
sing Vol	lume (1 vol.	/ 3 vol): 2, 0	8/6.2	<u>.5</u>	•		Well Borel	nole	Volume:		· ·
rging Me	ethod:	Centrifugal Pump Grundfos Subme	rsible Pump		- -	Sa	mpling Met	hod:	Peristaltic P		ole Pump
		Centrifugal Pump ES-40/-60 Subme					21		Teflon Baller		
		23-70/-00 adollic	eresure rump	<u> </u>	-				ES Sub. Pur	np @ <	1Umin.
inging Ra	ite: See	e below	Total Disc	charge:	8		Ca	gnia	Volumes Purged	: _	3, <u>85</u>
mments	:		···	· · · · · · · · · · · · · · · · · · ·	•						
ste Wat	ter Disposal:	To drum.									
rting Ti	me: Ś	1:42							-		
1e Pump	оп: <u>8</u>	:47									
Date	оп: <u>8</u>	Gal. Purged	рН	T deg. F	Diluted S.C.	ŀ	Dil. Factor		S.C. (<i>u</i> S/cm)		Color
Date			рн 7.42	T deg. F	Diluted S.C.	x	Dil. Factor	=			Color
Date	Time	Gal. Purged		68.1	Diluted S.C.	\vdash	Dil. Factor		2100		Color
Date	Time 8:51 8:53	Gal. Purged	7.42	68.1 68.2	Diluted S.C.	×	Dil. Factor	=	2100		Color
Date	. Time 8:51 8:53 8:54	6 6.5 7	7.42 7.39 7.37	68.1 68.2 68.3	Diluted S.C.	×	Dil. Factor	11 11	2100 2110 2110		Color
Date	Time 8:51 8:53	Gal. Purged	7.42	68.1 68.2	Diluted S.C.	x x	Dil. Factor	11 11	2100		Color
Date	. Time 8:51 8:53 8:54	6 6.5 7	7.42 7.39 7.37	68.1 68.2 68.3	Diluted S.C.	x x x	Dil. Factor	11 11	2100 2110 2110		Color
Date	. Time 8:51 8:53 8:54	6 6.5 7	7.42 7.39 7.37	68.1 68.2 68.3	Diluted S.C.	x x	Dil. Factor	11 11	2100 2110 2110		Color
Date	. Time 8:51 8:53 8:54	6 6.5 7	7.42 7.39 7.37	68.1 68.2 68.3	Diluted S.C.	x x x	Dil. Factor	1 1 1 1	2100 2110 2110		Color
Date	. Time 8:51 8:53 8:54	6 6.5 7	7.42 7.39 7.37	68.1 68.2 68.3	Diluted S.C.	x x x	Dil. Factor		2100 2110 2110		Color
Date	. Time 8:51 8:53 8:54	6 6.5 7	7.42 7.39 7.37	68.1 68.2 68.3	Diluted S.C.	x x x	Dil. Factor		2100 2110 2110		Color
Date	. Time 8:51 8:53 8:54	6 6.5 7	7.42 7.39 7.37	68.1 68.2 68.3	Diluted S.C.	x x x x	Dil. Factor		2100 2110 2110		Color
Date	. Time 8:51 8:53 8:54	6 6.5 7	7.42 7.39 7.37	68.1 68.2 68.3	Diluted S.C.	x x x x	Dil. Factor		2100 2110 2110		Color
Date / Z-/99	. Time 8:51 8:53 8:54	Gal. Purged 6 6.5 7 7.5	7.42 7.39 7.37 7.35	68.1 68.3 68.4	Diluted S.C.	x x x x x x x x x	Dil. Factor		2100 2110 2110		Color
Date / Z-/99	8:51 8:53 8:54 8:55 :	Gal. Purged 6 6.5 7 7.5	7.42 7.39 7.37 7.35	68.1 68.3 68.4		x x x x x x x x x	3:57		2100 2110 2110		Color