

120460
EVA

hOP case file

UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK) / CONTAMINATION SITE REPORT

EMERGENCY <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		HAS STATE OFFICE OF EMERGENCY SERVICES REPORT BEEN FILED? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		FOR LOCAL AGENCY USE ONLY I HEREBY CERTIFY THAT I HAVE DISTRIBUTED THIS INFORMATION ACCORDING TO THE DISTRIBUTION SHOWN ON THE INSTRUCTION SHEET ON THE BACK PAGE OF THIS FORM. SIGNED: <u>[Signature]</u> DATE: <u>11/25/01</u>	
REPORT DATE 01/22/01		CASE #			
REPORTED BY	NAME OF INDIVIDUAL FILING REPORT JOHN MRAKOVICH		PHONE (570) 5812320		SIGNATURE [Signature]
	REPRESENTING <input type="checkbox"/> LOCAL AGENCY <input checked="" type="checkbox"/> OWNER/OPERATOR <input type="checkbox"/> REGIONAL BOARD <input type="checkbox"/> OTHER		COMPANY OR AGENCY NAME ALLCAL ENVIRONMENTAL		
	ADDRESS 27973 HIGH COUNTRY DRIVE, HAYWARD, CA 94542				
RESPONSIBLE PARTY	NAME STEVE SIMI <input type="checkbox"/> UNKNOWN		CONTACT PERSON STEVE SIMI		PHONE (570) 5882013
	ADDRESS 2735 BROADWAY, OAKLAND, CA 94612				
SITE LOCATION	FACILITY NAME (IF APPLICABLE)		OPERATOR STEVE SIMI		PHONE (570) 5882013
	ADDRESS 1347 PARK STREET ALAMEDA, CA ALAMEDA 94501				
	CROSS STREET ALAMEDA AVENUE				
IMPLEMENTING AGENCIES	LOCAL AGENCY ALAMEDA CO. HEALTH CARE SERVICES AGENCY		CONTACT PERSON EVA CHU		PHONE (570) 5676762
	REGIONAL BOARD SAN FRANCISCO BAY REGION		PHONE ()		
SUBSTANCES INVOLVED	(1) NAME HEATING OIL				QUANTITY LOST (GALLONS) <input checked="" type="checkbox"/> UNKNOWN
	(2)				<input type="checkbox"/> UNKNOWN
DISCOVERY/ABATEMENT	DATE DISCOVERED 1/1/01		HOW DISCOVERED <input type="checkbox"/> INVENTORY CONTROL <input type="checkbox"/> SUBSURFACE MONITORING <input type="checkbox"/> NUISANCE CONDITIONS <input type="checkbox"/> TANK TEST <input checked="" type="checkbox"/> TANK REMOVAL <input type="checkbox"/> OTHER		
	DATE DISCHARGE BEGAN [] [] [] [] [] [] [] [] [] [] <input type="checkbox"/> UNKNOWN		METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY) <input type="checkbox"/> REMOVE CONTENTS <input checked="" type="checkbox"/> CLOSE TANK & REMOVE <input type="checkbox"/> REPAIR PIPING <input type="checkbox"/> REPAIR TANK <input type="checkbox"/> CLOSE TANK & FILL IN PLACE <input type="checkbox"/> CHANGE PROCEDURE <input type="checkbox"/> REPLACE TANK <input type="checkbox"/> OTHER		
	HAS DISCHARGE BEEN STOPPED? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO IF YES, DATE 1/1/01				
SOURCE/ CAUSE	SOURCE OF DISCHARGE <input type="checkbox"/> TANK LEAK <input checked="" type="checkbox"/> UNKNOWN <input type="checkbox"/> PIPING LEAK <input type="checkbox"/> OTHER		CAUSE(S) <input type="checkbox"/> OVERFILL <input type="checkbox"/> RUPTURE/FAILURE <input type="checkbox"/> SPILL <input type="checkbox"/> CORROSION <input checked="" type="checkbox"/> UNKNOWN <input type="checkbox"/> OTHER		
	CASE TYPE <input type="checkbox"/> UNDETERMINED <input type="checkbox"/> SOIL ONLY <input checked="" type="checkbox"/> GROUNDWATER <input type="checkbox"/> DRINKING WATER - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED)				
CURRENT STATUS	CHECK ONE ONLY <input type="checkbox"/> NO ACTION TAKEN <input type="checkbox"/> PRELIMINARY SITE ASSESSMENT WORKPLAN SUBMITTED <input checked="" type="checkbox"/> POLLUTION CHARACTERIZATION <input type="checkbox"/> LEAK BEING CONFIRMED <input type="checkbox"/> PRELIMINARY SITE ASSESSMENT UNDERWAY <input type="checkbox"/> POST CLEANUP MONITORING IN PROGRESS <input type="checkbox"/> REMEDIATION PLAN <input type="checkbox"/> CASE CLOSED (CLEANUP COMPLETED OR UNNECESSARY) <input type="checkbox"/> CLEANUP UNDERWAY				
	REMEDIAL ACTION CHECK APPROPRIATE ACTION(S) (SEE BACK FOR DETAILS) <input type="checkbox"/> CAP SITE (CD) <input type="checkbox"/> EXCAVATE & DISPOSE (ED) <input type="checkbox"/> REMOVE FREE PRODUCT (FP) <input type="checkbox"/> ENHANCED BIO DEGRADATION (IT) <input type="checkbox"/> CONTAINMENT BARRIER (CB) <input type="checkbox"/> EXCAVATE & TREAT (ET) <input type="checkbox"/> PUMP & TREAT GROUNDWATER (GT) <input type="checkbox"/> REPLACE SUPPLY (RS) <input type="checkbox"/> VACUUM EXTRACT (VE) <input type="checkbox"/> NO ACTION REQUIRED (NA) <input type="checkbox"/> TREATMENT AT HOOKUP (HU) <input type="checkbox"/> VENT SOIL (VS) <input type="checkbox"/> OTHER (OT)				
COMMENTS	One groundwater monitoring well installed in parking lane of Park Street.				

#105511

UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK) / CONTAMINATION SITE REPORT

EMERGENCY

☐ YES ☒ NO

HAS STATE OFFICE OF EMERGENCY SERVICES
REPORT BEEN FILED? ☐ YES ☒ NO

FOR LOCAL AGENCY USE ONLY

I HEREBY CERTIFY THAT I HAVE DISTRIBUTED THIS INFORMATION ACCORDING TO THE
DISTRIBUTION SHOWN ON THE INSTRUCTION SHEET ON THE BACK PAGE OF THIS FORM.

REPORT DATE

01/22/01

CASE

SIGNED

1/25/01

DATE

REPORTED BY

NAME OF INDIVIDUAL FILING REPORT

JOHN MRAKOVICH

PHONE

(510) 581-2320

SIGNATURE

J. MRAKOVICH

REPRESENTING

☐ LOCAL AGENCY ☒ OWNER/OPERATOR ☐ REGIONAL BOARD

COMPANY OR AGENCY NAME

ALLCAL ENVIRONMENTAL

ADDRESS

27973 HIGH COUNTRY DRIVE, HAYWARD, CA

94542

RESPONSIBLE PARTY

NAME

STEVE SIMI

☐ UNKNOWN

CONTACT PERSON

STEVE SIMI

PHONE

(510) 588-2013

ADDRESS

2735 BROADWAY, OAKLAND, CA

94612

SITE LOCATION

FACILITY NAME (IF APPLICABLE)

OPERATOR

STEVE SIMI

PHONE

(510) 588-2013

ADDRESS

1347 PARK STREET ALAMEDA, CA

ALAMEDA 94501

CROSS STREET

ALAMEDA AVENUE

IMPLEMENTING AGENCIES

LOCAL AGENCY

AGENCY NAME

ALAMEDA CO. HEALTH CARE
SERVICES AGENCY

CONTACT PERSON

EVA CHU

PHONE

(510) 567-6762

REGIONAL BOARD

SAN FRANCISCO BAY REGION

PHONE

()

SUBSTANCES INVOLVED

(1)

NAME

HEATING OIL

QUANTITY LOST (GALLONS)

☒ UNKNOWN

(2)

☐ UNKNOWN

DISCOVERY/ABATEMENT

DATE DISCOVERED

1/17/01

HOW DISCOVERED

☐ TANK TEST

☐ INVENTORY CONTROL

☒ TANK REMOVAL

☐ SUBSURFACE MONITORING

☐ OTHER

☐ NUISANCE CONDITIONS

DATE DISCHARGE BEGAN

1/17/01

☐ UNKNOWN

METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY)

☐ REMOVE CONTENTS

☒ CLOSE TANK & REMOVE

☐ REPAIR PIPING

☐ REPAIR TANK

☐ CLOSE TANK & FILL IN PLACE

☐ CHANGE PROCEDURE

☐ REPLACE TANK

☐ OTHER

SOURCE OF DISCHARGE

☐ TANK LEAK

☒ UNKNOWN

☐ PIPING LEAK

☐ OTHER

CAUSE(S)

☐ OVERFILL

☐ RUPTURE/FAILURE

☐ SPILL

☐ CORROSION

☒ UNKNOWN

☐ OTHER

CASE TYPE

CHECK ONE ONLY

☐ UNDETERMINED

☐ SOIL ONLY

☒ GROUNDWATER

☐ DRINKING WATER - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED)

CURRENT STATUS

CHECK ONE ONLY

☐ NO ACTION TAKEN

☐ PRELIMINARY SITE ASSESSMENT WORKPLAN SUBMITTED

☒ POLLUTION CHARACTERIZATION

☐ LEAK BEING CONFIRMED

☐ PRELIMINARY SITE ASSESSMENT UNDERWAY

☐ POST CLEANUP MONITORING IN PROGRESS

☐ REMEDIATION PLAN

☐ CASE CLOSED (CLEANUP COMPLETED OR UNNECESSARY)

☐ CLEANUP UNDERWAY

REMEDIAL ACTION

CHECK APPROPRIATE ACTION(S) (SEE BACK FOR DETAILS)

☐ CAP SITE (CD)

☐ EXCAVATE & DISPOSE (ED)

☐ REMOVE FREE PRODUCT (FP)

☐ ENHANCED BIO DEGRADATION (IT)

☐ CONTAINMENT BARRIER (CB)

☐ EXCAVATE & TREAT (ET)

☐ PUMP & TREAT GROUNDWATER (GT)

☐ REPLACE SUPPLY (RS)

☐ VACUUM EXTRACT (VE)

☐ NO ACTION REQUIRED (NA)

☐ TREATMENT AT HOOKUP (HU)

☐ VENT SOIL (VS)

☐ OTHER (OT)

COMMENTS

One groundwater monitoring well installed in parking lane of
Park Street.