April 18, 1995

Jennifer Eberle
Department of Environmental Health
Alameda County Health Care Services Agency
1131 Harbor Bay Pkwy #250
Alameda, CA 94502-6522

SUBJECT: GROUNDWATER SAMPLING REPORT AT THE AMERICAN PRESIDENT LINES

TERMINAL, 1395 MIDDLE HARBOR ROAD, OAKLAND, CALIFORNIA

Dear Jennifer:

Enclosed please find the 1994 fourth quarter groundwater sampling report for the American President Lines Terminal. This site was the location of an underground storage tank removal and is the County's project # STID 3777.

The results of the last 4 quarters of sampling indicate that the level of TPH-G and BETX are ND in MW-2 and TPH-G, TOG and BETX are ND in MW-3. Therefore we would like to change the sample protocol to only analyse the samples at MW-1 for TPH-G, TPH-D, BETX and VOC (EPA Method 8010), MW-2 for TPH-D and VOC (EPA Method 8010), and MW-3 for TPH-D and VOC (EPA Method 8010).

We are also requesting that the frequency of future sampling be either semi-annually or annually given the low levels of the above constituents in the groundwater and the groundwater is not a potential drinking water source.

If you have any questions or need additional information, please contact me at 272-1118.

Sincerely,

Susa Gates

Associate Environmental Scientist

SG\jb

c: Neil Werner

John DeGeorge (Alisto Engineering)

pc\wp51\files\susa\1995\jeberle,ltr

100 Pine Street | 15th Floor Ban Francisco | 0A 941** [415] 464-9400 | FAX [415] 464-1565 PORT OF OAKLAND

NVIRONMENTAL DEPT.

GEOMATRIX

95 APR 18 A9: 51

RECEIVED

6 April 1995 Project No. 2026

Ms. Susa Gates Port of Oakland 530 Water Street Oakland, California 94607

Subject:

Groundwater Sampling

American President Lines Terminal

1395 Middle Harbor Road

Port of Oakland Oakland, California

Dear Ms. Gates:

This letter report presents the results of the fourth quarter groundwater sampling event for 1994 performed by Geomatrix Consultants. Inc. (Geomatrix) on 4 November 1994 at the American President Lines Terminal (APL), 1395 Middle Harbor Road, at the Port of Oakland (Port; Figure 1). The work was conducted in accordance with our October 1992 Work Plan and in response to the 13 November 1992 Alameda County Health Care Services Agency letter to the Port. This sampling event represents the eighth quarter of groundwater sampling.

For the quarterly monitoring program, Geomatrix performed water-level measurements and groundwater sampling. These activities and the results are described below.

WATER-LEVEL MEASUREMENTS

Geomatrix measured water levels in the three shallow groundwater monitoring wells (Figure 2) on 4 November 1994 before groundwater was sampled. Water levels were measured to the nearest 0.01 foot using a steel tape. The measurements were used to calculate water-level elevations at each of the wells; the elevations are shown on Figure 2 and are presented in Table 1.

Water-level elevations measured on 4 November 1994 ranged from 6.33 to 6.85 feet Mean Lower Low Water (MLLW; Port datum). The water-level elevations are 0.19 to 0.20 feet lower than those measured during the previous quarter. The horizontal gradient, as in previous quarters, is very flat; horizontal flow direction was southwesterly, toward the Oakland Inner Harbor.



Ms. Susa Gates Port of Oakland 6 April 1995 Page 2

GROUNDWATER SAMPLING

Geomatrix collected groundwater samples from the three on-site monitoring wells on 4 November 1994 (Figure 2). All equipment used in the wells was washed with a laboratory-grade detergent (Alconox) and rinsed with deionized water. Before being sampled, the wells were purged using a stainless steel bailer. To obtain groundwater representative of the aquifer screened by the well, the wells were purged until the temperature, pH, and specific conductance of the purged groundwater stabilized and at least four casing volumes were removed. Groundwater purged from the site was contained in a labeled 55-gallon drum which is being temporarily stored on site.

After the wells were purged, groundwater samples were collected from the approximate mid-point of the screened interval using a disposable bailer. The samples were decanted from the bailer directly into the appropriate containers. The samples were labeled and placed in an ice-cooled chest for delivery under Geomatrix chain-of-custody to Clayton Environmental Consultants, Inc. (Clayton) of Pleasanton, California, a state-certified analytical laboratory retained by the Port. A copy of the chain-of-custody record is included in Attachment A.

Groundwater samples were analyzed by Clayton for total petroleum hydrocarbons as gasoline (TPHg) by modified U.S. Environmental Protection Agency (EPA) Method 8015; total petroleum hydrocarbons as diesel (TPHd) by EPA Method 8015; total oil and grease by Standard Method 5520 C and F; halogenated volatile organic compounds (VOCs) by EPA Method 8010; and benzene, toluene, ethylbenzene, and total xylenes (BTEX) by EPA Method 8020. A copy of the analytical laboratory report is included in Attachment A.

ANALYTICAL RESULTS

The analytical results for the groundwater samples are summarized in Tables 2 (attached). Benzene, toluene, and total xylenes were reported in the groundwater samples from monitoring well MW-1 at concentrations of 15.0, 2.4, and 11.2 micrograms per liter (μ g/l), respectively. 1,1-dichloroethane (1,1-DCA), 1,2-dichloroethane (1,2-DCA), and 1,2-dichloroethene (1,2-DCE) were also reported in the samples from well MW-1 at concentrations of 2.2 and 0.8 μ g/l respectively. Vinyl chloride was detected in the groundwater samples from well MW-1 at a concentration of 0.7 μ g/l. TPHd and total oil and grease were also detected in the samples from well MW-1 at concentrations of 1,600 and 1 μ g/l respectively. 1,4-dichlorobenzene (1,4-DCB) and 1,2-DCE were reported in the groundwater samples from well MW-2 at concentrations of 0.9 and 2.2 μ g/l respectively.



Ms. Susa Gates Port of Oakland 6 April 1995 Page 3

TPHd was detected in the groundwater samples from well MW-2 at a concentration of 1,400 μ g/l. TPHd was the only compound detected in the samples collected and analyzed from MW-3 at a concentration of 630 μ g/l.

The analytical laboratories have noted that the material reported as diesel does not match the diesel pattern but is more like oil. These data indicate that the material is likely either highly degraded diesel or oil which includes hydrocarbon compounds which fall within the diesel range.

SUMMARY OF RESULTS AND RECOMMENDATIONS

Two years of quarterly water levels and water quality data have been collected in the three wells in the vicinity of the former underground storage tanks. Water-level elevations have been relatively consistent, with two of the three wells (MW-2 and MW-3) having elevation changes of less than 0.9 feet over the last two years and the third well (MW-1) having an elevation change of less than 1.2 feet over the last two years. The horizontal gradient is relatively flat and the flow directions have been southerly toward the Oakland Inner Harbor during six of the last eight quarters; flow was to the north during the last two quarters of 1993.

Groundwater samples were analyzed for TPHd. TPHg, TOG, BTEX, and VOCs during the past eight quarters; total oil and grease was also monitoring in wells MW-1 and MW-2. All monitoring well samples were also analyzed for TDS and total oil and grease during the first four quarters.

TPH as diesel has generally been reported in all three wells, with higher concentrations typically in MW-1, the upgradient well. The analytical laboratories have noted that the material reported as diesel does not match the diesel pattern but is more likely oil Low levels of TPH as gasoline have been reported only in the upgradient well, MW-1. After the first quarter of monitoring, benzene, toluene, ethylbenzene and xylene have been reported only in MW-1; only benzene is present at levels slightly above its California maximum contaminant level (MCL) of 1 μ g/l. Several other volatile organic compounds have been detected sporadically at low concentrations in all three wells. TDS concentrations have varied significantly in all three wells.

The water-level elevations indicate the hydraulic gradient at the site is flat. TDS concentrations have varied; however, generally the TDS results indicate that the water is brackish and not a potential drinking water source. Only benzene has been detected in the



Ms. Susa Gates Port of Oakland 6 April 1995 Page 4

upgradient well at concentrations slightly above its MCL. Based on these results, it appears that groundwater has not been significantly impacted as a result of leakage from the USTs. We recommend that monitoring be performed annually and that the analyses include TPH as diesel and EPA Method 8010 for all wells and TPH as gasoline and BTEX for well MW-1.

Sincerely yours,

GEOMATRIX CONSULTANTS, INC.

James M. Abitz Staff Engineer Sally E. Goodin R.G. Principal Geologist

2026\QTR1-95.LTR JMA/SEG/Jam

Attachments: Tables (3)

Figures (2)

Attachment A - Chain-of-Custody Record and Analytical Laboratory Report

TABLE 1
WATER-LEVEL ELEVATIONS

American President Lines Terminal 1395 Middle Harbor Road Port of Oakland Oakland. California

Water-Level Elevations in Feet (MLLW)

Measuring Date	MW-1	MW-2	MW-3
8 March 1993	7.07	6.58	6.76
11 May 1993	7.08	6.79	6.95
19 August 1993	6.27	6.30	6.34
24 November 1993	5.89	6.02	6.05
24 February 1994	6.86	6.54	6.76
14 June 1994	6.83	6.34	6.43
23 August 1994	7.05	6.52	6.62
4 November 1994	6.85	6.38	6.33

TABLE 2
SUMMARY OF COMPOUNDS DETECTED IN GROUNDWATER SAMPLES

Page 1 of 2

American President Lines Terminal 1395 Middle Harbor Road Port of Oakland Oakland, California

Concentrations in parts per billion (µg/l)

Well No.	Date	TPH as Gasoline	TPH as Diesel	Total Oil and Grease	Веплепе	Toluene	Ethylbenzene	Total Xylenes	EPA Method 8010
MW-I	2/5/93	1800	4700	5000	9.2	1.6	8.9	2.7	1,1-DCA 0.8
	5/11/93	260	4800	7000	3.2	2.3	0.7	0.5	1,1-DCA 0.6
	8/19/93	60	2300	ND	9.0	ND	ND	ND	1,1-DCA 2.0 1,1-DCE 2.0
	11/24/93	50	280	ND	8.8	1.5	ND	3.0	1,1-DCA 0.7
	2/24/94	360	2000	NA II	12	ND	2	ND	1,1-DCA 2.0
	6/14/94	ND	ND	ND	9.4	ND	ND	0.7	1,1-DCA 1.0
	8/23/94	80	3000	ND	13.0	2.4	ND	9.0	1,1-DCA 2.3 1,2-DCA 0.3 1,2-DCE 0.4 VC 1.1
	11/4/94	ND /	1600	and ND	15 1	2.4	ND	11.2	1,1-DCA 2.2 1,2-DCA 0.8 VC 0.7
MW-2	2/5/93	ND	840	2000	ND	ND	ND	ND	ND
	5/11/93	ND	3700	ND	ND	ND	ND	ND	ND
	8/19/93	ND	620	ND	ND	ND	ND	ND	1,4-DCB 3.0 1,2-DCB 1.0
	11/24/93	ND	80	ND	ND	ND	ND	ND	ND
	2/2/94	ND	ND	NA	ND	ND	ND	ND	1,4-DCB 1.0

TABLE 2
SUMMARY OF COMPOUNDS DETECTED IN GROUNDWATER SAMPLES

Page 2 of 2

Well No.	Date	TPH as Gasoline	TPH as Diesel	Total Oil and Grease	Benzene	Toluene	Ethylbenzene	Total Xylenes	EPA Method 8010
MW-2 (con't)	6/14/94	NA	ND	ND	NA	NA	NA	NA	1,4-DCB 0.8
	8/23/94	NA	620	ND	NA	NA	NA	NA	1,4-DCB 1.3 1,2-DCE 0.4
	11/4/94	NA	1400	ND /	NA	(NA)	NA	(NA)	1,4-DCB 0.9 ↓ 1,2-DCE 2.2
MW-3	2/5/93	ND	3400	2000	2.1	0.9	1.7	3.1	Cis-1,2-DCE 0.4
	5/11/93	ND	3300	ND	ND	ND	ND	ND	ND
	8/19/93	ND	840	ND	ND	. ND	ND	ND	1,4-DCB 1.0
	11/24/93	ND	100	ND	ND	ND	ND	ND	ND
	2/2/94	ND	890	NA	ND	ND	ND	ND	ND
	8/23/94	NA	440	ND	ND	ND	ND	ND	1,4-DCB 0.6
	6/14/94	NA	ND	ND	ND	ND	ND	ND	ND
	11/4/94	NA NA	630	ND/	ND /	ND	ND	ND	ND 🧠

Notes:

Samples collected by Geomatrix Consultants, Inc. and analyzed by Curtis & Tomkins, Ltd., of Berkeley, California, Dames & Moore of Novato, California, and Clayton Environmental Consultants, Inc., of Pleasanton, California, for TPH as gasoline by modified EPA Method 8015; TPH as diesel by EPA Method 8015; total oil and grease by Standard Method 5520 C and F; benzene, toluene, ethylbenzene, and total xylenes by EPA Method 8020; and halogenated volatile organic compounds by EPA Method 8010.

@ not typical of diesel

DCA = dichloroethane

DCB = dichlorobenzene


DCE = dichloroethene

VC = vinyl chloride

TPH = total petroleum hydrocarbons

NA not analyzed


ND = not detected at or above detection limit



ZIRTAMOS D

SITE LOCATION MAP American President Lines Terminal 1395 Middle Harbor Road Oakland, California Figure 1 Project No.

Project No. 2026



1252 Quarry Lane P.O. Box 9019 Pleasanton, CA 94566 (510) 426-2600 Fax (510) 426-0106



November 21, 1994

Mr. Jamie Abitz GEOMATRIX CONSULTANTS 100 Pine Street, 10th Floor San Francisco, CA 94111

> Client Ref.: 2026I Clayton Project No.: 94110.74

Dear Mr. Abitz:

Attached is our analytical laboratory report for the samples received on November 4, 1994. A copy of the Chain-of-Custody form acknowledging receipt of these samples is attached.

Please note that any unused portion of the samples will be disposed of after December 21, 1994, unless you have requested otherwise.

We appreciate the opportunity to be of assistance to you. If you have any questions, please contact Suzanne Haus, Client Services Supervisor, at (510) 426-2657.

Sincerely,

Harriotte A. Hurley, CIH Director, Laboratory Services Western Operations

HAH/tjb

Attachments

Analytical Results

for

Geomatrix Consultants Client Reference: 2026I Clayton Project No. 94110.74

Sample Identification: MW-2 11/04/94 Date Sampled: 11/04/94 Lab Number: 9411074-01A Date Received: Sample Matrix/Media: WATER Date Prepared: 11/13/94 11/13/94 Preparation Method: EPA 5030 Date Analyzed: Method Reference: Analyst: NAN EPA 8010

	2111 0010			
Analyte		CAS #	Concentration (ug/L)	Method Detection Limit (ug/L)
Purgeable Halocarbons				
Bromodichloromethane Bromoform Bromomethane Carbon tetrachloride Chlorobenzene Chloroethane 2-Chloroethylvinyl e Chloroform Chloromethane Dibromochloromethane 1,2-Dichlorobenzene 1,3-Dichlorobenzene 1,4-Dichlorobenzene Dichlorodifluorometh 1,1-Dichloroethane 1,2-Dichloroethane 1,2-Dichloroethane 1,2-Dichloroethene cis-1,2-Dichloroet 1,2-Dichloropropane cis-1,3-Dichloroprop trans-1,3-dichloroprop	ther ane ne hene ene opene thane e	75-27-4 75-25-2 74-83-9 56-23-5 108-90-7 75-00-3 110-75-8 67-66-3 74-87-3 124-48-1 95-50-1 541-73-1 106-46-7 75-34-3 107-06-2 75-35-4 156-59-2 156-60-5 78-87-5 10061-01-5 10061-02-6 76-13-1 75-09-2 79-34-5 127-18-4 71-55-6 79-00-5	ND N	0.7 0.7 0.7 0.7 0.7 0.7 0.7 0.7 0.7 0.7
Trichloroethene Trichlorofluorometha		79-01-6 75-69-4	ND ND	0.3

Analytical Results

for

Geomatrix Consultants Client Reference: 2026I

Clayton Project No. 94110.74

Sample Identification: MW-2

Lab Number:

9411074-01A

Sample Matrix/Media:

Preparation Method: Method Reference:

EPA 5030

WATER

EPA 8010

Date Sampled:

11/04/94 11/04/94

Date Received: Date Prepared:

11/13/94

Date Analyzed:

11/13/94

Analyst:

NAN

			Method
			Detection
		Concentration	Limit
Analyte	CAS #	(ug/L)	(\mathtt{ug}/\mathtt{L})

Purgeable Halocarbons (Continued)

Vinyl chloride

75-01-4

ND V

0.5

Surrogates Recovery (%) QC Limits (%)

1-Chloro-2-methylpropene

513-37-1

74

70 - 130

Not detected at or above limit of detection ND: Information not available or not applicable



Analytical Results for

Geomatrix Consultants Client Reference: 2026I Clayton Project No. 94110.74

Sample Identification: MW-3

Lab Number:

9411074-02A

Sample Matrix/Media: Preparation Method:

WATER EPA 5030

Method Reference:

EPA 8010

Date Sampled: 11/04/94

Date Received: 11/04/94 Date Prepared: 11/15/94

11/15/94 Date Analyzed:

Analyst: NAN

Analyte	CAS #	Concentration (ug/L)	Method Detection Limit (ug/L)
Purgeable Halocarbons			
Bromodichloromethane	75-27-4	ND	1
Bromoform	75-25-2	ND	1
Bromomethane	74-83-9	ND	1
Carbon tetrachloride	56- 23-5	ND	1
Chlorobenzene	108-90-7	ND	1 1 2
Chloroethane	75-00-3	ИĎ	1
2-Chloroethylvinyl ether	110-75-8	ND	
Chloroform	67-66 - 3	ND	1
Chloromethane	74-87-3	ND	1
Dibromochloromethane	124-48-1	ND	1
1,2-Dichlorobenzene	95-50-1	ND	1
1,3-Dichlorobenzene	541-73-1	ND	
1,4-Dichlorobenzene	106-46-7	ND	<u>1</u>
Dichlorodifluoromethane	75-71-8	ND	2
1,1-Dichloroethane	75-34-3	ND	0.8
1,2-Dichloroethane	107-06 - 2	ND	0.6
1,1-Dichloroethene	75-35-4	ND	0.4
cis-1,2-Dichloroethene	156-59-2	ND	0.8
trans-1,2-Dichloroethene	156-60-5	ND	0.8
1,2-Dichloropropane	78-87-5	ND	1
cis-1,3-Dichloropropene	10061-01-5	ND	1
trans-1,3-dichloropropene	10061-02-6	ND	1:
Freon 113	76-13-1	ND	4
Methylene chloride	75-09 - 2	ND	4
1,1,2,2-Tetrachloroethane	79-34-5	ND	1
Tetrachloroethene	127-18-4	ND	1
1,1,1-Trichloroethane	71-55-6	ND	1
1,1,2-Trichloroethane	79-00-5	ND	1
Trichloroethene	79-01-6	ND	0.6
Trichlorofluoromethane	75-69-4	ND	0.8



Page 5 of 16

Analytical Results for

Geomatrix Consultants Client Reference: 2026I

Clayton Project No. 94110.74

Sample Identification: MW-3

Lab Number:

9411074-02A

Sample Matrix/Media:

WATER EPA 5030

Preparation Method: Method Reference:

EPA 8010

Date Sampled:

11/04/94

Date Received: Date Prepared: 11/04/94 11/15/94

Date Analyzed:

11/15/94

Analyst:

NAN

			Method
			Detection
		Concentration	Limit
Analyte	CAS #	(ug/L)	(ug/L)

Purgeable Halocarbons (Continued)

Vinyl chloride

75-01-4

ND

1

Surrogates

Recovery (%)

OC Limits (%)

1-Chloro-2-methylpropene

513-37-1

100

70 - 130

ND: Not detected at or above limit of detection --: Information not available or not applicable



Page 6 of 16

Analytical Results for

Geomatrix Consultants Client Reference: 2026I Clayton Project No. 94110.74

Sample Identification: MW-1 Date Sampled: 11/04/94
Lab Number: 9411074-03A Date Received: 11/04/94

Sample Matrix/Media: WATER Date Prepared: 11/15/94 Preparation Method: EPA 5030 Date Analyzed: 11/15/94

Method Reference: EPA 8010 Analyst: NAN

Method Reference: EPA 8010	•	Analyst:	NAN
Analyte	CAS #	Concentration (ug/L)	Method Detection Limit (ug/L)
Purgeable Halocarbons			
Bromodichloromethane Bromoform Bromomethane Carbon tetrachloride Chlorobenzene Chloroethane 2-Chloroethylvinyl ether Chloroform Chloromethane Dibromochloromethane 1,2-Dichlorobenzene 1,3-Dichlorobenzene 1,4-Dichlorobenzene Dichlorodifluoromethane 1,1-Dichloroethane 1,2-Dichloroethane 1,2-Dichloroethene cis-1,2-Dichloroethene trans-1,2-Dichloroethene trans-1,3-Dichloropropene trans-1,3-dichloropropene Freon 113 Methylene chloride 1,1,2-Tetrachloroethane 1,1-Trichloroethane 1,1-Trichloroethane 1,1,2-Trichloroethane	75-27-4 75-25-2 74-83-9 56-23-5 108-90-7 75-00-3 110-75-8 67-66-3 74-87-3 124-48-1 95-50-1 541-73-1 106-46-7 75-71-8 75-34-3 107-06-2 75-35-4 156-59-2 156-60-5 78-87-5 10061-01-5 10061-02-6 76-13-1 75-09-2 79-34-5 127-18-4 71-55-6 79-00-5	ND N	0.7 0.7 0.7 0.7 0.5 0.5 0.5 0.5 0.4 0.4 0.5 0.6 0.5 0.6 0.5 0.6 0.5 0.6 0.6 0.6 0.6 0.6 0.6 0.6 0.6 0.6 0.6
Trichloroethane Trichlorofluoromethane	79-00-5 79-01-6 75-69-4	ND ND ND	0.3 0.4

Page 7 of 16

Analytical Results

for

Geomatrix Consultants Client Reference: 2026I

Clayton Project No. 94110.74

Sample Identification: MW-1

Lab Number:

9411074-03A

Sample Matrix/Media:

WATER

Preparation Method:

EPA 5030

Method Reference:

EPA 8010

Date Sampled:

11/04/94

Date Received:

11/04/94

Date Prepared:

11/15/94

Date Analyzed:

11/15/94

Analyst:

NAN

•			Method
			Detection
		Concentration	Limit
Analyte	CAS #	(ug/L)	(ug/L)

Purgeable Halocarbons (Continued)

Vinyl chloride

75-01-4

<u>Surrogates</u>

Recovery (%)

0.5 OC Limits (%)

1-Chloro-2-methylpropene

513-37-1

101

70 - 130

ND: Not detected at or above limit of detection Information not available or not applicable



Page 8 of 16

11/13/94

Analytical Results for

Geomatrix Consultants Client Reference: 2026I

Clayton Project No. 94110.74

Sample Identification: METHOD BLANK

Lab Number:

9411074-04A

Sample Matrix/Media:

WATER

Preparation Method: Method Reference:

EPA 5030

EPA 8010

Date Sampled:

Date Received:

Date Prepared: Date Analyzed:

11/13/94

Analyst: NAN

Rechod Reference.		maryst.	IALMA
Analyte	CAS #	Concentration (ug/L)	Method Detection Limit (ug/L)
Purgeable Halocarbons			,
Bromodichloromethane	75-27-4	ND	0.7
Bromoform	75-25-2	ND	0.7
Bromomethane	74 - 83-9	ND	0.7
Carbon tetrachloride	56-23-5	ND	0.6
Chlorobenzene	108-90-7	ND	0.7
Chloroethane	75-00-3	ND	0.5
2-Chloroethylvinyl ether	110-75-8	ND	1
Chloroform	67-66-3	ND	0.5
Chloromethane	74-87-3	ND	0.6
Dibromochloromethane	124-48-1	ND	0.6
1,2-Dichlorobenzene	95-50-1	ND	0.5
1,3-Dichlorobenzene	541-73-1	ND	0.5
1,4-Dichlorobenzene	106-46-7	ND	0.5
Dichlorodifluoromethane	75-71-8	ND	1
1,1-Dichloroethane	75 - 34-3	ND	0.4
1,2-Dichloroethane	107-06-2	ND	0.3
1,1-Dichloroethene	75-35-4	ND	0.2
cis-1,2-Dichloroethene	156-59-2	ND	0.4
trans-1,2-Dichloroethene	156-60-5	ND	0.4
1,2-Dichloropropane	78-87-5	ND	0.5
cis-1,3-Dichloropropene	10061-01-5	ND	0.5
trans-1,3-dichloropropene	10061-02-6	ND	0.6
Freon 113	76-13-1	ND	2
Methylene chloride	75-09-2	ND	. 2
1,1,2,2-Tetrachloroethane	79-34-5	ND	0.5
Tetrachloroethene	127-18-4	NĎ	0.5
1,1,1-Trichloroethane	71-55-6	ND	0.5
1,1,2-Trichloroethane	79-00-5	ND	0.6
Trichloroethene	79-01-6	ND	0.3
Trichlorofluoromethane	75-69-4	ND	0.4



Page 9 of 16

Analytical Results for

Geomatrix Consultants Client Reference: 2026I Clayton Project No. 94110.74

Sample Identification: METHOD BLANK

1-Chloro-2-methylpropene

Lab Number:

9411074-04A

Sample Matrix/Media: Preparation Method:

WATER EPA 5030

Method Reference:

EPA 8010

Date Sampled:

Date Received:

Date Prepared:

Date Analyzed:

Analyst:

95

11/13/94 11/13/94

70 - 130

NAN

11001100 110101011001		2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 -	
Analyte	CAS #	Concentration (ug/L)	Method Detection Limit (ug/L)
Purgeable Halocarbons (Continued)			
Vinyl chloride	75-01-4	ND	0.5
Surrogates		Recovery (%)	OC Limits (%)

513-37-1

Not detected at or above limit of detection ND: Information not available or not applicable



Page 10 of 16

11/04/94

11/04/94

Analytical Results for

Geomatrix Consultants Client Reference: 2026I

Clayton Project No. 94110.74

Sample Identification: MW-3 Date Sampled:
Lab Number: 9411074-02C Date Received:

Sample Matrix/Media: WATER Date Prepared: 11/15/94 Preparation Method: EPA 5030 Date Analyzed: 11/15/94

Method Reference: EPA 8020 Analyst: NAN

Method Reference.	EFA 0020		maryse.	141 114
Analyte		CAS #	Concentration (ug/L)	Method Detection Limit (ug/L)
Purgeable Aromatics				
Benzene Chlorobenzene 1,2-Dichlorobenzene 1,3-Dichlorobenzene 1,4-Dichlorobenzene Ethylbenzene Toluene o-Xylene p,m-Xylenes		71-43-2 108-90-7 95-50-1 541-73-7 106-46-7 100-41-4 108-88-3 95-47-6	ND	0.8 0.6 1 0.6 1 0.6 0.6 0.8
Surrogates			Recovery (智)	QC Limits (%)
1,4-Difluorobenzene		540-36-3	101	70 - 130

ND: Not detected at or above limit of detection --: Information not available or not applicable

Note: Detection limits increased due to matrix interference.



Analytical Results for

Geomatrix Consultants Client Reference: 2026I Clayton Project No. 94110.74

Sample Identification: MW-1

Lab Number:

9411074-03C

Sample Matrix/Media: Preparation Method:

WATER

EPA 5030

Date Sampled:

11/04/94 11/04/94

Date Received: Date Prepared:

11/15/94

Date Analyzed:

11/15/94

Method Reference:	EPA 8020		Analyst:	NAN
Analyte		CAS #	Concentration (ug/L)	Method Detection Limit (ug/L)
Purgeable Aromatics				
Benzene Chlorobenzene 1,2-Dichlorobenzene 1,3-Dichlorobenzene 1,4-Dichlorobenzene Ethylbenzene Toluene o-Xylene p,m-Xylenes		71-43-2 108-90-7 95-50-1 541-73-7 106-46-7 100-41-4 108-88-3 95-47-6	15 ND ND ND ND ND 2.4 4.5 6.7	0.4 0.3 0.5 0.3 0.5 0.3 0.3 0.4
Surrogates			Recovery (%)	OC Limits (%)
1,4-Difluorobenzene		540-36-3	119	70 - 130

Not detected at or above limit of detection ND: Information not available or not applicable



Page 12 of 16

Analytical Results for

Geomatrix Consultants Client Reference: 2026I Clayton Project No. 94110.74

Sample Identification: METHOD BLANK

Lab Number:

9411074-04A

Sample Matrix/Media:

Preparation Method: Method Reference:

EPA 5030

WATER

EPA 8020

Date Sampled:

Date Received:

Date Prepared:

11/15/94 Date Analyzed: 11/15/94

Analyst:

NAN

Method Kerefence:	EPA 6020		Anaryse.	111.77
Analyte		CAS #	Concentration (ug/L)	Method Detection Limit (ug/L)
Purgeable Aromatics				
Benzene Chlorobenzene 1,2-Dichlorobenzene 1,3-Dichlorobenzene 1,4-Dichlorobenzene Ethylbenzene Toluene o-Xylene p,m-Xylenes		71-43-2 108-90-7 95-50-1 541-73-7 106-46-7 100-41-4 108-88-3 95-47-6	ND ND ND ND ND ND ND	0.4 0.3 0.5 0.3 0.5 0.3 0.3 0.4
Surrogates			Recovery (名)	OC Limits (%)
1,4-Difluorobenzene	· 3	540-36-3	101	50 - 150

Not detected at or above limit of detection Information not available or not applicable

Date Received: 11/04/94

Page 13 of 16

Analytical Results for

Geomatrix Consultants

Client Reference: 2026I Clayton Project No. 94110.74

Sample Identification: See Below

Lab Number:

Sample Matrix/Media:

Extraction Method:

SM 5520F SM 5520C

Method Reference:

Date Extracted: 11/09/94 9411074 WATER Date Analyzed: 11/17/94

	out grease	Method Detection
Lab Sample Date	Hydrocarbons	Limit
Number Identification Sampled	(mg/L)	(mg/L)
-01 MW-2 11/04/94	ND 🔑 .	1
-02 MW-3 11/04/94	ND 🗸	1
-03 MW-1 11/04/94	ND (1
-04 METHOD BLANK	ND	1

Not detected at or above limit of detection ND: Information not available or not applicable --:

Analytical Results for

Geomatrix Consultants

Client Reference: 2026I Clayton Project No. 94110.74

Sample Identification: See Below

Lab Number:

9411074

Sample Matrix/Media:

WATER

Extraction Method:

EPA 3510

Method Reference:

EPA 8015 (Modified)

Date Received: 11/04/94 Date Extracted: 11/09/94

Date Analyzed: 11/14/94

Lab Number	Sample Identification	Date Sampled	TPH-D (ug/L)	Method Detection Limit (ug/L)
-01 -02 -03	MW-2	11/04/94	1400 a	50
-02	MW - 3	11/04/94	630 .a	50
-03	MW - 1	11/04/94	1600 a	50
-04	METHOD BLANK	- -	ND	50

ND: Not detected at or above limit of detection --: Information not available or not applicable

TPH-D = Extractable petroleum hydrocarbons from C10 to C42 quantitated as diesel.

a Unidentifiable hydrocarbons do not match the typical diesel pattern.



Page 15 of 16

Analytical Results for

Geomatrix Consultants Client Reference: 2026I

Clayton Project No. 94110.74

Sample Identification: See Below

Lab Number:

9411074

Sample Matrix/Media:

WATER

Preparation Method:

EPA 5030

Method Reference:

EPA 8015 (Modified)

11/04/94 Date Received:

Date Prepared: 11/09/94 Date Analyzed: 11/09/94

Lab Number	Sample Identification	Date Sampled	TPH-G (ug/L)	Method Detection Limit (ug/L)
-03	MW-1	11/04/94	ND	50
-04	METHOD BLANK	- -	ND	50

Not detected at or above limit of detection Information not available or not applicable

TPH-G = Volatile petroleum hydrocarbons from C6 to C10 quantitated as gasoline.

Date Received:

Date Analyzed:

Date Extracted: 11/09/94

Page 16 of 16

11/04/94

11/17/94

Analytical Results for

Geomatrix Consultants

Client Reference: 2026I Clayton Project No. 94110.74

Sample Identification: See Below

Lab Number:

9411074

Sample Matrix/Media:

WATER

Extraction Method:

SM 5520B

Method Reference:

SM 5520C

Lab Number	Sample Identification	Date Tot Sampled	cal Oil and Grease (mg/L)	Method Detection Limit (mg/L)
-01	MW-2	11/04/94	ND .	1
-02	MW - 3	11/04/94	ND	1
-03	MW-1	11/04/94	1	1
-04	METHOD BLANK	·	ND	1

Not detected at or above limit of detection Information not available or not applicable

Chain-of-Custoo	ly F	lec	or	d						Νō		4	57	73				Da	te:	П	14	1	94	Page of /
Project No.: 2026 I									AN	ALY	SES	,												REMARKS
Samplers (Signatures): Chili Rema	Method 8010	0d B020	od 8240	EPA Method 8270	30 ine 8015	TPH as diesel \$015	rex	Tak 1 0.1 + gresse													water (W)	-	f containers	Additional comments 1) Analyze Tetal oil and grease by 5520 c & F. OIA-D 2xqlil, 2xqlipml of OZA-F2xqlil, 4xqlipml word O3A-5 2xqlil, 8xqlipml
Date Time Sample Number	EPA Meth	EPA Method 8020	EPA Method 8240	EPA Meth	TPH as ga	TPH as di	TPH as BTEX	Tet. 10.1												Cooled	Soil (S) or	Acidified	Number o	by 5520 CEF.
11/4/94 1210 MW-2	\aleph		igspace			\bigvee		X					<u> </u>		ļ					X	3 3	y	4	OIA-D 2x 811, 2x 81
1340 MW-1	\otimes		_		\times	\Diamond	ļ	\hat{X}							ļ						المنا	<u>,</u> 义	10	OSA = 5 2x81 L, 9x8 40mg
	-	_	-	\vdash	_		<u> </u>	_	_		 	-	-		_					٠				g · a··
	\$								_												-			
	-				<u> </u>	_				=			+	-						<u> </u>		·—·-		
			_	-								-	-											
	1	-	-					_	-	-	-	<u> </u>	1	-			-	_					-	
	** T		und ti	imo:						Pocul	its to:				1						_			
	1011	S	L.	d		t			-					-41	ai t	Z.		Total	No.	of co	ntain	ers:	20	·
Relinquished by:	Date	8			o by.	ムナ	ela	dt			Date	3: /P	î Din	outsh		$\overline{)}$	700	د	W	1	1			od of shipment: Pick Up
Signature Vil Rosel	441						us	RJ.	le	U	11/4	X	Signa				7				ци	PHI	Labor	ratory comments and Log No.:
Signature Pul Rossel Printed name: Charles Lone	44/90	1 P	1)0	re	L,	Ku	Sh	Re	/di				Printe											
Company: Germany		۲	ompa See	Y,	2517	نت	er f	\star			Time	_	Comp	pany:	AE	KO	\mathcal{L}	ξu	VER	<u>'</u>	Tim			
Received by: Signalure:	Time	. (H <u>s</u>	ecerv	ure 1	UC.	} J/	Pi y	(3)	/9	7	֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֟֓֓֓֓		Rece		1	reej	1/2	Bel	lez	4	12	ンフ		
Printed name:	-	_		d nan	ne:							L			יר. me:			n 4	//		V	P		00=====================================
Diana Kushfeldt		c	omp	any:									Prin <u>te</u> Comp	Dany:										Geomatrix Consultants 100 Pine St. 10th Floor San Francisco, CA. 94111
Company: Leornatrix			AE	L) 🧸	DE	7.1	VE	<u>e)</u>				C	L1	47	<u>67</u>	JE	Ñν (Cox	15 .		[(415) 434-9400

Quality Assurance Results Summary

Matrix Spike/Matrix Spike Duplicate Results

for

Clayton Project No. 94110.74

Quality Assurance Results Summary for Clayton Project No. 94110.74

Clayton Lab Number:

9411074-LCS

Ext./Prep. Method:

SM5520B 11/09/94

Date: Analyst: .

HYT

Std. Source:

E940825-01W

Sample Matrix/Media:

WATER

Analytical Method: Instrument ID:

SM5520C 00000

Date: Time: 11/17/94 13:01

Analyst: Units:

CTS MG/L

Analyte	Sample Result	Spike Level	Matrix Spike Result	MS Recovery (%)	Matrix Spike Duplicate Result	MSD Recovery (%)	Average Recovery (% R)	LCL (% R)	UCL (% R)	RPD (%)	UCL (%RPD)
OIL&GREASE(IR)	ND	5.06	4.74	94	4.83	95	95	78	; 121	1.9	20

Quality Assurance Results Summary for Clayton Project No. 94110.74

Clayton Lab Number:

Ext./Prep. Method: Date:

9411076-LCS EPA 5030

Analyst:

Std. Source:

Sample Matrix/Media:

11/13/94 NAN

WATER

V940927-02W

Analytical Method: EPA601 2/801020

Instrument ID:

02857

Date: Time:

11/13/94 05:08

Analyst: Units:

NAN UG/L

Analyte		Sample Result	Spike Level	Matrix Spike Result	MS Recovery (%)	Matrix Spike Duplicate Result	MSD Recovery (%)	Average Recovery (% R)	LCL (% R)	UCL (% R)	RPD	UCL (%RPD)
1,1-DICHLOROETHENE	(HALL)	ND	20.0	18.2	91	18.8	94	93	65	131	3.2	22
BENZENE	(PID)	ND	20.0	19.6	98	20.0	100	99	76	134	2.0	20
CHLOROBENZENE	(PID)	ND	20.0	19.1	96	19.6	98	97	75	127	2.6	20
CHLOROBENZENE	(HALL)	ND	20.0	18.0	90	18.8	94	92	79	132	4.3	20
TOLUENE	(PID)	ND	20.0	20.2	101	20.8	104	103	71	125	2,9	20
TRICHLOROETHENE	(HALL)	ND	20.0	19.0	95	19.7	99	97	6 9	133	3.6	20

Quality Assurance Results Summary for

Clayton Project No. 94110.74

Clayton Lab Number: Ext./Prep. Method:

9411048-LCS EPA3510

Date:

11/09/94

Analyst: Std. Source: HYT G941109-01W

Sample Matrix/Media:

WATER

Analytical Method: Instrument ID: EPA8015 02883 11/13/94 23:42

Date: Time:

1/13/94 23:42 AMN

Analyst: Units:

UG/L

Analyte	Sample Result	Spike Level	Matrix Spike Result	MS Recovery (%)	Matrix Spike Duplicate Result	MSD Recovery (%)	Average Recovery (% R)	LCL (% R)	UCL (% R)	RPD (%)	UCL (%RPD)
DIESEL	ND	1,000	1,260	126	1,290	129	128	40	140	2.4	40

Quality Assurance Results Summary

Clayton Project No. 94110.74

Clayton Lab Number: Ext./Prep. Method:

9411064-07C

Date: Analyst:

Std. Source:

WAS V941024-04W

EPA5039 11/09/94

Analytical Method: Instrument ID: Date: Time: Analyst: Units:

EPA8015 8020 05587 11/09/94 13:56 WAS UG/L

Sample Matrix/Media: WATER

Analyte		Sample Result	Spike Level	Matrix Spike Result	MS Recovery (%)	Matrix Spike Duplicate Result	MSD Recovery (%)	Average Recovery (% R)	LCL (% R)	UCL (% R)	RPD (%)	UCL (%RPD)
BENZENE	(PID)	ND	11.1	12.9	116	12.1	109	113	81	118	6.4	20
ETHYLBENZENE	(PID)	ND	10.2	11.2	110	10.4	102	106	81	114	7.4	20
GASOLINE	(FID)	ND	500	460	92	430	86	89	80	150	6.7	25
TOLUENE	(PID)	ND	51.7	55.6	108	50,1	97	102	84	118	10	20
TOTAL XYLENE	(PID)	ND	62.2	63.9	103 -	59.6	96	99	85	115	7.0	20