

**RECEIVED**

**By dehloptoxic at 9:34 am, Jul 26, 2006**



76 Broadway  
Sacramento, California 95818

July 14, 2006

Mr. Barney Chan  
Alameda County Health Agency  
1131 Harbor Bay Parkway  
Alameda, California 94502

Re: **Report Transmittal  
Quarterly Report  
Second Quarter – 2006  
76 Service Station #7176  
7850 Amador Valley Boulevard  
Dublin, California**

Dear Mr. Chan:

I declare under penalty of perjury that to the best of my knowledge the information and/or recommendations contained in the attached report is/are true and correct.

If you have any questions or need additional information, please contact

Shelby S. Lathrop (Contractor)  
ConocoPhillips  
Risk Management & Remediation  
76 Broadway  
Sacramento, CA 95818  
Phone: 916-558-7609  
Fax: 916-558-7639

Sincerely,

A handwritten signature in black ink that reads "Thomas H. Kosel".

Thomas Kosel  
Risk Management & Remediation

Attachment



Solving environment-related business problems worldwide

www.deltaenv.com

3164 Gold Camp Drive • Suite 200  
Rancho Cordova, California 95670 USA  
916.638.2085 800.477.7411  
Fax 916.638.8385

July 24, 2006

Mr. Barney Chan  
Alameda County Health Agency  
1131 Harbor Bay Parkway, Suite 250  
Alameda, California 94502

**Re: Quarterly Summary Report – Second Quarter 2006**  
Delta Project No. C107176021

Dear Mr. Chan:

On behalf of ConocoPhillips (COP), Delta Environmental Consultants, Inc. (Delta) is submitting this Quarterly Summary Report – Second Quarter 2006 for the following location:

**Service Station**

**Location**

76 Service Station No. 7176


7850 Amador Valley Boulevard  
Dublin, California

No regulatory correspondence was received or sent since the last summary report was submitted on May 16, 2006. TRC will continue conducting semi-annual monitoring and sampling at the site; the next monitoring and sampling event at the site will occur during the third quarter 2006.

Sincerely,  
Delta Environmental Consultants, Inc.

Ben Wright  
Staff Geologist

Daniel J. Davis, R.G.  
Senior Project Manager



cc: Ms. Shelby Lathrop, ConocoPhillips (electronic copy)


Attachment A – Historic Groundwater Flow Directions

A member of:



**Attachment A**  
**Historic Groundwater Flow Directions**

**Historic Groundwater Flow Directions**  
**ConocoPhillips Site No. 7176**  
7850 Amador Valley Boulevard  
Dublin, California



■ Groundwater Flow Direction

Legend

Concentric circles represent  
quarterly monitoring events  
Fourth Quarter 1995 through First  
Quarter 2006  
34 data points shown