

Wickham, Jerry, Env. Health

Subject: RO486_PHONE_LOG_2012-09-25
Entry Type: Phone call

Start: Tue 9/25/2012 2:21 PM
End: Tue 9/25/2012 2:21 PM
Duration: 0 hours

Phone call with Peter Schaefer of CRA. In considering development of one half of the site, would need to evaluate for vapor intrusion. Site has a layer of compacted road base that is difficult to get through for drilling. The tank pit has 1.5 inch drain rock to about 4 feet overlain by compacted road base. Would expect approximately four additional soil vapor probes within southern half of site.

Jerry Wickham