

Broadbent & Associates, Inc.  
1324 Mangrove Ave., Suite 212  
Chico, CA 95926  
Voice (530) 566-1400  
Fax (530) 566-1401

**RECEIVED**

3:42 pm, Jan 30, 2009

Alameda County  
Environmental Health



January 28, 2009

Project No. 06-82-645

Atlantic Richfield Company  
P.O. Box 1257  
San Ramon, CA 94583  
Submitted via ENFOS

Attn.: Mr. Paul Supple

Re: Fourth Quarter, 2008 Status Report, Former BP Station #11107, 18501 Hesperian Boulevard, San Lorenzo, California. ACEH Case No. RO0000489.

Dear Mr. Supple:

Attached is the *Fourth Quarter, 2008 Status Report* for Former BP Station #11107 (herein referred to as Station #11107) located at 18501 Hesperian Boulevard, San Lorenzo, California (Property).

Should you have questions please do not hesitate to contact us at (530) 566-1400.

Sincerely,


BROADBENT & ASSOCIATES, INC.

A handwritten signature in black ink, appearing to read 'Matt Herrick', written over a horizontal line.

Matthew G. Herrick, P.G., C.HG.  
Senior Hydrogeologist

A handwritten signature in black ink, appearing to read 'Robert H. Miller', written over a horizontal line.

Robert H. Miller, P.G., C.HG.  
Principal Hydrogeologist



Enclosures

cc: Mr. Paresh Khatri, Alameda County Environmental Health, 1131 Harbor Bay Parkway, Suite 250, Alameda, CA, 94502 (Submitted via ACEH ftp Site)  
Ms. Shelby Lathrop, ConocoPhillips, 76 Broadway, Sacramento, CA 95818  
Mr. Abdul Noor Mayar, 18501 Hesperian Blvd, San Lorenzo, CA 94580  
GeoTracker

## STATION #11107 QUARTERLY STATUS REPORT

Facility: #11107	Address:	18501 Hesperian Boulevard, San Lorenzo, California
Station #11107 Environmental Business Manager:		Mr. Paul Supple
Consulting Co./Contact Persons:		Broadbent & Associates, Inc. (BAI) / Rob Miller & Matt Herrick
Primary Agency/Regulatory ID No.:		Alameda County Environmental Health (ACEH) / ACEH Case No. RO0000489
Consultant Project No.:		06-82-645
Facility Permits/Permitting Agency.:		NA

### WORK PERFORMED THIS QUARTER (Fourth Quarter, 2008):

1. Submitted Third Quarter, 2008 Semi-Annual Ground-Water Monitoring Report. Report completed by BAI.
2. No environmental work was completed on the Property during the Fourth Quarter, 2008.

### WORK PROPOSED FOR NEXT QUARTER (First Quarter, 2009):

1. Submit Fourth Quarter, 2008 Status Report (contained herein).
2. Conduct ground-water monitoring/sampling for First Quarter, 2009.

### QUARTERLY RESULTS SUMMARY:

Current phase of project:	<u>Ground-water monitoring/sampling</u>
Frequency of ground-water sampling:	<u>MW-4, MW-5, and MW-6 = Semi-annual (1Q and 3Q)</u>
Frequency of ground-water monitoring:	<u>MW-1 through MW-7 Semi-annual (1Q and 3Q)</u>
Is free product (FP) present on-site:	<u>No</u>
Current remediation techniques:	<u>NA</u>
Depth to ground water (below TOC):	<u>NA</u>
General ground-water flow direction:	<u>NA</u>
Approximate hydraulic gradient:	<u>NA</u>


### DISCUSSION:

No environmental activities took place at Station #11107 during the Fourth Quarter, 2008. The attached Drawing 1 depicts the site and monitor well locations. The most recent ground-water monitoring/sampling data is provided in the Third Quarter, 2008 Semi-Annual Ground-Water Monitoring Report.

Case closure was requested on April 23, 2004 by Atlantic Richfield Company. A response from the ACEH regarding the closure request has not been received. Data collected during Third Quarter, 2008 continued to document ground-water concentrations below water quality objectives. It is requested that the ACEH consider case closure at Station #11107.

### ATTACHMENTS:

Drawing 1. Site Map, Station #11107, San Lorenzo, CA



**LEGEND**

- Monitoring well location
- Well — Well designation
- SA — Sampling frequency
- SA(1,3) Sampled semi-annually during 1st and 3rd quarters
- NS Not sampled

NOTE: SITE MAP ADAPTED FROM CAMBRIA ENVIRONMENTAL FIGURES. SITE DIMENSIONS AND FIGURES FACILITY LOCATIONS NOT VERIFIED.

