Working To Restore Nature

3315 Almaden Expressway, Suite 34 San Jose, CA 95118

Phone: (408) 264-7723 FAX: (408) 264-2435

EXXON COMPANY, U.S.A. QUARTERLY STATUS REPORT

April - June 1993 June 30, 1993 (Page 1 of 2)

RAS #7-3006 720 High Street Oakland, California Job No: 130006

exxon0693

Work Performed During This Quarter

April through June 1993

- Performed monthly depth-to-water monitoring on April 5 and May 28, 1993.
- Submitted final report for first quarter 1993 Quarterly Monitoring on May 11, 1993.
- o Performed quarterly monitoring second quarter 1993 on June 10 and 11, 1993.

Groundwater Sampling (sampled March 10 and 11, 1993) Results: (mg/L)

Well MW-1 MW-2 MW-3 MW-4	TPHg < 0.05	< <u>B</u> <0.0005	<u>T</u> <0.0005	E <0.0005 Sheen Sheen hase Hydrocar	<u>X</u> <0.0005	<u>TPHd</u> 0.14	<u>TOG</u> -	<u>VOCs</u>	Trends Decreased Decreased Decreased Unchanged
MW-5			-	lell Destroyed	COHS				Onenangea
MW-6				hase Hydrocar	bons				Increased
MW-7	3.5	0.16	0.0062	0.022	0.019	0.64	< 0.05	••	Decreased
MW-8				Sheen					Unchanged
MW-9	< 0.050	< 0.0005	< 0.0005	< 0.0005	< 0.0005	< 0.050		_	Unchanged
MW-10	< 0.050	< 0.0005	< 0.0005	< 0.0005	< 0.0005	< 0.050			Unchanged
MW-11	< 0.050	< 0.0005	< 0.0005	< 0.0005	< 0.0005	0.24		-	Increased
MW-12				Sheen					Unchanged
MW-13				Sheen					Unchanged
MW-14	0.41	< 0.0005	< 0.0005	0.0009	0.0016	< 0.25			Increased
MW-15			7	Not Accessible					

See Table 3



exxon0693

EXXON COMPANY, U.S.A. QUARTERLY STATUS REPORT

April - June 1993 June 30, 1993 (Page 2 of 2)

RAS #7-3006 720 High Street Oakland, California Job No: 130006

Free Phase Product Recovery

- e Removed approximately 2 cups of water/product mixture from the petrotraps in wells MW-2 and MW-4, and approximately 3 cups of water/product mixture from the petrotrap in well MW-6 on May 28, 1993.
- Removed approximately 2 cups of water/product mixture from the petrotraps in wells MW-2 and MW-4, and approximately 1 cup of water/product mixture from the petrotrap in well MW-6 on June 10, 1993.

Work to be Performed Next Quarter


Estimated Completion Date 09/30/93

- o Submit final report for second quarter 1993 Quarterly Monitoring to Exxon.
- o Submit final report for the Interim Remediation Investigation to Exxon.
- Perform Quarterly Monitoring for the third quarter 1993 on August 9 and 10, 1993.

Work to be Performed Next 12 Months

Estimated Completion Date 06/30/94

 Continue quarterly groundwater monitoring and sampling program to evaluate the trends of gasoline and diesel hydrocarbons and groundwater gradient in first encountered groundwater below the site.







exxon0393

3315 Almaden Expressway, Suite 34

San Jose, CA 95118 Phone: (408) 264-7723 FAX: (408) 264-2435

EXXON COMPANY, U.S.A. QUARTERLY STATUS REPORT

January - March 1993 April 9, 1993

(Page 1 of 2)

ROYAI

RAS #7-3006 720 High Street Oakland, California Job No: 130006

136

Work Performed During This Quarter

January through March 1993

- o Submitted Addendum One to the Interim Groundwater Remediation Work Plan to the Alameda County Health Care Services Agency (ACHCSA) on January 18, 1993.
- Performed monthly depth-to-water monitoring on January 27, and February 18, 1993.
- o Submitted final report for fourth quarter 1992 Quarterly Monitoring on February 2, 1993.
- o Installed three vapor wells on February 11, 1993.
- Conducted a vapor extraction test was on February 18, 1993.
- o Installed a Passive Free Phase Gasoline Hydrocarbon Recovery System was installed in monitoring wells MW-2, MW-4, and MW-6 on February 18, 1993.
- Performed a step-drawdown and a pumping and recovery test on February 25-26, 1993 utilizing monitoring well MW-13.
- Performed quarterly monitoring first quarter 1993 on March 10 and 11, 1993.
- o Submitted Response to the ACHCSA letter dated March 5, 1993 concerning Evaluation of Addendum One to the Interim Groundwater Remediation Work Plan on March 23, 1993.
- Submitted final Limited Records Search on March 24, 1993.

Groundwater Sampling (sampled March 10 and 11, 1993) Results: (mg/L)

Well MW-1 MW-2 MW-3	<u>TPHg</u> <0.05	<u>B</u> <0.0005	_T <0.0005	E <0.0005 Sheen Sheen hase Hydrocan	<u>X</u> <0.000S thoms	<u>TPHd</u> 0.14	<u>TOG</u> -	<u>Voc</u> s	Trends Decreased Decreased Decreased Unchanged
MW-4 MW-5 MW-6 MW-7	35	0.16	Ÿ	Vell Destroyed hase Hydrocar 0.022 Sheen	l	0.64	<0.05	##	Increased Decreased Unchanged



exxon0393

EXXON COMPANY, U.S.A. QUARTERLY STATUS REPORT January - March 1993 April 9, 1993 (Page 2 of 2)

RAS #7-3006 720 High Street Oakland, California Job No: 130006

Groundwater Sampling (sampled March 10 and 11, 1993) Results: (mg/L)

Well	TPHg	<u>B</u>	<u>T</u>	<u>E</u>	<u>x</u>	TPHd	TOG	<u>VOCs</u>	Trends
MW-9 MW-10 MW-11	<0.050 <0.050 <0.050	<0.0005 <0.0005 <0.0005	<0.0005 <0.0005 <0.0005	<0.0005 <0.0005 <0.0005 Sheen	<0.0005 <0.0005 <0.0005	<0.050 <0.050 0.24	- - -	-	Unchanged Unchanged Increased Unchanged
MW-12 MW-13 MW-14 MW-15	0.41	<0.0005	<0.0005	Sheen 0.0009 Not Accessible	0.0016	<0.25	-	-	Unchanged Increased

See Table 3

Free Phase Product Recovery

Removed approximately 1/8 cup of product from well MW-6 on February 18, 1993. Petrotraps were installed in wells MW-2, MW-4, and MW-6 on February 18, 1993.

Work to be Performed Next Quarter

Estimated Completion Date 06/30/93

- Submit final report for first quarter 1993 Quarterly Monitoring.
- o Submit final report for the Interim Remediation Immvestigation.
- e Perform Quarterly Monitoring for the second quarter 1993 on May 11 and 12, 1993.

Work to be Performed Next 12 Months

Estimated Completion Date 03/31/94

c Continue quarterly groundwater monitoring and sampling program to evaluate the trends of gasoline and diesel hydrocarbons and groundwater gradient in first encountered groundwater below the site.



Quarterly Groundwater Sampling Exxon Station 7-3006, Oakland, California April 1, 1993 130006.01

TABLE 3 RESULTS OF ADDITIONAL LABORATORY ANALYSES OF WATER SAMPLES FROM WELL MW-7 on March 11, 1993

Former Exxon Station 7-3006
Oakland, California
Page 1 of 2
(See notes on page 2)

PARAMETER	CONCENTRATION	MCL	EPA METHOD
INORGANIC ANALYSES			
Total Alkalinity, as CaCO ₃	360		
Bicarbonate Alkalinity, as CaCO ₃	360		
Carbonate Alkalinity, as CaCO ₃	<10		
Hydroxide Alkalinity, as CaCO,	<10		
Antimony	<0.06		6010/200.7, ICP
Arsenic	0.016	0.05	7060, Furnace AAS
Beryllium	<0.01		6010/200.7, ICP
Cadmium	<0.005	0.01	6010/200.7, ICP
Calcium	28		6010/200.7, ICP
Chloride	11	250	SM 407A
Chromium	<0.01	0.05	6010/200.7, ICP
Copper	<0.01	1.0	6010/200.7, ICP
Cyanides	<0.005		
Iron	1.6	0.3	6010/200.7, ICP
Lead	<0.1	0.05	6010/200.7, ICP
Magnesium	47		6010/200.7, ICP
Manganese	1.4	0.05	6010/200.7, ICP
Mercury	0.0004	0.002	7470, Cold Vapor AA
Nickel	<0.02		6010/200.7, ICP
Selenium	< 0.005	0.01	7740, Furnace AAS
Silver	<0.01	0.05	6010/200.7, ICP
Sodium	63	***	6010, ICP
Sulfate	<1.0	250	375.4
Thallium	<0.2		6010/200.7, ICP
Zinc	0.02	5.0	6010/200.7, ICP
pH, at 25°C	7.0	· •••	



Quarterly Groundwater Sampling Exxon Station 7-3006, Oakland, California April 1, 1993 130006.01

TABLE 3 RESULTS OF ADDITIONAL LABORATORY ANALYSES OF WATER SAMPLES FROM WELL MW-7 on March 11, 1993

Former Exxon Station 7-3006
Oakland, California
Page 2 of 2
(See notes on page 2)

	(Control of the Contro	
PARAMETER	CONCENTRATION	MCL	EPA METHOD
Specific Conductance, umhos/cm at 25°C	600	900	
Total Dissolved Solids	400	500	160.1
Total Hardness, as CaCO3	260		
ORGANIC ANALYSES*			
Organic Lead, as Pb	<0.1		338
Benzene	0.18	0.001	624
Toluene	0.006	0.100	624
Ethylbenzene	0.016	0.680	624
Total Xylenes	0.010	1.75	624
Napthalene	0.027		625

Results in parts per million (ppm) unless otherwise noted.

MCL: Maximum Contaminant Level for drinking water standards recommended by the California State

Department of Health Services (October 1990).

: Not Applicable

: All other compounds were nondetectable.

