



508 E. Lewelling
Product piping on
east side of
former tank pit

054183331173-2
5794 0138

9/15/94

Tulvet Shinn



508 E. Lewelling
Product piping
leading to former
dispenser on north side of former tank pit.
(Two alongside one another)

054183331173-2
5791 0138

9/15/94

Tulvet Shinn



508 E. Lewelling
Tank pit in background
trench on north of pit
& former dispenser location in foreground.

054183331173-2
5790 0138

9/15/94

Tulvet Shinn



508 E. Lewelling
Product piping trench east
of the former tank pit. (Two
parallel to one another). Some odor noted in darker
clayey material in trench.

054183331173-2
5793 0138

9/15/94

Tulvet Shinn

→ N



508 E Lowelling
Product piping trench on east side of tank pit. Parker (blue/black) clayey soil (appears native). Slight odor in areas of this clay.
054183331173-2 5787 0138
t/15/84
Juliet Shinn



508 E Lowelling
Product piping on east side of tank pit. (Two parallel to one another)
054183331173-2 5792 0138
9/15/84
Juliet Shinn



508 E Lowelling
Sum total of product piping removed from both the east & north side of former gas tank pit.
054183331173-2 5783 0138
9/15/84
Juliet Shinn



508 E. Lawelling, San Lorenzo 4/14/99
 Tank pit where over 4,000 gallons of 2
 3,000-gallon gas USTs used to 09318221467-2
 be. Max excavated some 0547 1730
 material since the pull. Juliet Shinn



508 E. Lawelling, San Lorenzo 4/14/99
 Stacked soil was not 09318221467-2
 covered when I arrived 0547 1730
 out on site. Juliet Shinn



508 E Lawelling, S.L. 4/14/99
 South Sidewall. No longer staining
 where it used to be during 09318221467-2
 tank removal in Aug '98 0547 1730
 Juliet Shinn



508 E. Lowelling Blvd, S.L.

8/26/93

Tank pit in foreground w/ dispenser & island in background. 03317211124-2
Juliet Shur



508 E. Lowelling Blvd, S.L. 8/26/93
Soils stained on East sidewall of one of the 2,000-gallon gas tanks. Some stained soil on bottom. 03317211124-2
Juliet Shur



508 E Lowelling Blvd, S.L.

8/26/93

One of the 2,000-gallon gas USTs, located on north end of tank pit. Corroded, but no apparent holes. 03317211124-2
Juliet Shur



508 E Lowelling Blvd, S.L.

8/26/93

All three tanks, two 2,000-gallon USTs & one 4,000-gallon UST in the pit. 03317211124-2
Juliet Shur



508 E. Lowelling Blvd., San Lorenzo 8/26/93
83317211124-2
Pen-size hole in 4,000-gallon gas UST.
Juliet Sher



508 E. Lowelling, S.L. 8/26/93
83317211124-2
Several pen-size holes in bottom of
4,000-gallon UST. Juliet Sher



508 E. Lowelling Blvd, S.L. 8/26/93
Pen-size hole in bottom of 4,000-gallon UST.
83317211124-2
Juliet Sher



508 E. Lowelling Blvd, S.L. 8/26/93
83317211124-2
Found sand underneath 4,000-gallon gas UST. Juliet Sher



508 E. Leavelle Blvd, S.L. 8/26/73
 2nd 2,000-gallon gas UST. Corrosion but
 no holes noted. 03317211124-2
 Tubert Shure



508 E-Leavelle Blvd., S.L. 8/26/73
 4,000-gallon 03317211124-2
 and 4 pin-size holes. Corrosion, putting
 Tubert Shure



508 E. Leavelle Blvd, S.L. 8/26/73
 Stained soil observed on east wall +
 floor of pit 03317211124-2
 of pit where 2,000-gallon UST was.
 (on the end of pit) Tubert Shure



508 E Leavelle Blvd, S.L. 8/26/73
 03317211124-2
 Stained soil on west end of pit
 Tubert Shure



508 E. Lewelling Blvd, S.L. 8/26/93
Stained soil on east, south, north walls
of pit and bottom for 4,000-gallon gas tank.
83317211124-2
Julius Stein



508 E. Lewelling Blvd, S.L. 8/26/93
Stained soil at bottom & east sidewalk
of tank pit 83317211124-2
for 2nd 2,000-gallon OST.
Julius Stein



Former tank pit



8' deep pit soil
from
east trench