

RECEIVED

By dehloptoxic at 9:37 am, Jul 26, 2006



76 Broadway
Sacramento, California 95818

July 14, 2006

Mr. Don Hwang
Alameda County Health Agency
1131 Harbor Bay Parkway
Alameda, California 94502

Re: **Report Transmittal**
Quarterly Report – Second Quarter 2006
76 Service Station #5367
500 Bancroft Avenue
San Leandro, CA

Dear Mr. Hwang:

I declare under penalty of perjury that to the best of my knowledge the information and/or recommendations contained in the attached report is/are true and correct.

If you have any questions or need additional information, please contact

Shelby S. Lathrop (Contractor)
ConocoPhillips
Risk Management & Remediation
76 Broadway
Sacramento, CA 95818
Phone: 916-558-7609
Fax: 916-558-7639

Sincerely,

A handwritten signature in black ink that reads "Thomas H. Kosel".

Thomas Kosel
Risk Management & Remediation

Attachment



Solving environment-related business problems worldwide

www.deltaenv.com

3164 Gold Camp Drive • Suite 200
Rancho Cordova, California 95670 USA
916.638.2085 800.477.7411
Fax 916.638.8385

July 24, 2006

Mr. Donald Hwang
Alameda County Health Agency
1131 Harbor Bay Parkway, Suite 250
Alameda, California 94502

Re: Quarterly Summary Report – Second Quarter 2006
Delta Project No. C105367081

Dear Mr. Hwang:

On behalf of ConocoPhillips (COP), Delta Environmental Consultants, Inc. (Delta) is submitting this Quarterly Summary Report – Second Quarter 2006 for the following location:

Service Station

Location

76 Service Station No. 5367


500 Bancroft Avenue
San Leandro, California

No regulatory correspondence was received or sent since the last summary report was submitted on May 16, 2006. TRC will continue conducting semi-annual monitoring and sampling at the site; the next monitoring and sampling event at the site will occur during the third quarter 2006. Delta will complete a Sensitive Receptor Survey at the site; it is anticipated that results of the survey will be submitted during the third quarter 2006.

Sincerely,
Delta Environmental Consultants, Inc.

Ben Wright
Staff Geologist

Daniel J. Davis, R.G.
Senior Project Manager




cc: Ms. Shelby Lathrop, ConocoPhillips (electronic copy)

Attachment A – Historic Groundwater Flow Directions

Attachment A
Historic Groundwater Flow Directions

Historic Groundwater Flow Directions
ConocoPhillips Site No. 5367
500 Bancroft Avenue
San Leandro, California



■ Groundwater Flow Direction

Legend
Concentric circles represent
quarterly monitoring events
Third Quarter 1990 through First
Quarter 2006
39 data points shown