

QUARTERLY SUMMARY REPORT  
2ND QTR - 1991  
(April - June)

RECEIVED

2:04 pm, Jun 17, 2009

Alameda County  
Environmental Health

UNOCAL SERVICE STATION #5367  
500 Bancroft Avenue  
San Leandro, California

City/County ID # San Leandro Fire Dept.

County: Alameda

**BACKGROUND**

Installed ground-water monitoring well MW-1 in September 1987, wells MW-2 through MW-4 in September 1988, wells MW-5 and MW-6 in May 1989, and wells MW-7 and MW-8 February 1990. Performed quarterly ground-water monitoring after wells were installed. Ground water has fluctuated between 33 and 38 feet below the ground surface.

**RECENT QUARTER ACTIVITIES**

Submitted first quarter monitoring report on May 20. Performed second quarter monitoring in May.

**NEXT QUARTER ACTIVITIES**

Submit second quarter monitoring report in July and perform quarterly monitoring in August.

**CHARACTERIZATION / REMEDIAL STATUS**

Soil contamination delineated? Yes  
Dissolved ground water delineated? No  
Free product delineated? N/A  
Amount of gw contaminant recovered this quarter? 0 (gal)

Soil remediation in progress? No

- anticipated start? \_\_\_\_\_
- anticipated completion? \_\_\_\_\_

Dissolved/free product remediation in progress? No

- anticipated start? \_\_\_\_\_
- anticipated completion? \_\_\_\_\_

CONSULTANT/CONTRACTOR: Applied GeoSystems