

# QUARTERLY SUMMARY REPORT 4TH QTR - 1991

(October - December)

UNOCAL SERVICE STATION #5367 500 Bancroft Avenue

San Leandro, California

City/County ID # San Leandro Fire Dept.

County: Alameda

#### **BACKGROUND**

Installed groundwater monitoring well MW-1 in September 1987, wells MW-2 through MW-4 in September 1988, wells MW-5 and MW-6 in May 1989, and wells MW-7 and MW-8 February 1990. Performed quarterly groundwater monitoring after wells were installed. Groundwater has fluctuated between 33 and 38 feet below the ground surface.

## RECENT QUARTER ACTIVITIES

Submitted second quarter monitoring report on September 4, 1991. Performed fourth quarter monitoring in December.

### **NEXT QUARTER ACTIVITIES**

Submit third and fourth quarter monitoring reports.

## CHARACTERIZATION / REMEDIAL STATUS

Soil contamination delineated?	<u>Yes</u>
Dissolved ground water delineated?	<u>No</u>
Free product delineated?	<u>N/A</u>
Amount of gw contaminant recovered this quarter?	<u>0</u> (gal)
Soil remediation in progress?	<u>No</u>

CONSULTANT/CONTRACTOR: RESNA

#### **RECEIVED**

2:04 pm, Jun 17, 2009

Alameda County Environmental Health