

QUARTERLY SUMMARY REPORT

1ST QTR - 1992

(January - March)

RECEIVED

2:03 pm, Jun 17, 2009

Alameda County
Environmental HealthUNOCAL SERVICE STATION #5367
500 Bancroft Avenue
San Leandro, California

FILE #	<u>5367</u>	SS	<input checked="" type="checkbox"/>	BP	<input type="checkbox"/>
RPT	<input type="checkbox"/>	QM	<input type="checkbox"/>	TRANSMITTAL	<input type="checkbox"/>
1	<input type="checkbox"/>	2	<input type="checkbox"/>	3	<input checked="" type="checkbox"/>
4	<input type="checkbox"/>	5	<input type="checkbox"/>	6	<input type="checkbox"/>

City/County ID# San Leandro Fire DepartmentCounty: Alameda County**BACKGROUND**

Installed groundwater monitoring well MW-1 in, wells MW-2 through MW-4 in 1988, wells MW-5 and MW-6 in May 1989, and wells MW-7 and MW-8 in 1990. Quarterly groundwater monitoring performed since well installation. Groundwater has fluctuated between 33 and 38 feet below the ground surface.

RECENT QUARTER ACTIVITIES

Submitted fourth quarter 1991 monitoring report in February 1992. Performed first quarter monitoring in March.

NEXT QUARTER ACTIVITIES

Submit first quarter monitoring report. Perform second quarter groundwater monitoring.

CHARACTERIZATION/REMEDIAL STATUS

Soil contamination delineated?	<u>Yes</u>
Dissolved groundwater delineated?	<u>No</u>
Free Product delineated?	<u>NA</u>
Amount of gw contaminant recovered this quarter?	<u>0 gallons</u>
Soil remediation in progress?	<u>No</u>

CONSULTANT:RESNA Industries**MONITORING CONTRACTOR:**GeoStrategies