



**QUARTERLY SUMMARY REPORT**  
3RD QTR - 1992  
(July - September)

Working To Restore Nature

**UNOCAL SERVICE STATION #5367**  
500 Bancroft Avenue  
San Leandro, California

RECEIVED

SEP 10 1992

**RECEIVED**

2:01 pm, Jun 17, 2009

Alameda County  
Environmental Health

City/County ID# San Leandro Fire Department

County: Alameda County

**BACKGROUND**

Eight groundwater monitoring wells present. Groundwater has fluctuated between 33 and 38 feet below the ground surface.

**RECENT QUARTER ACTIVITIES**

Third quarter 1992 monitoring performed in September 1992.

**NEXT QUARTER ACTIVITIES**

Perform fourth quarter 1992 groundwater monitoring.

**CHARACTERIZATION/REMEDIAL STATUS**

Soil contamination delineated?	<u>Yes</u>
Dissolved groundwater delineated?	<u>No</u>
Free Product delineated?	<u>NA</u>
Amount of gw contaminant recovered this quarter?	<u>0 gallons</u>
Soil remediation in progress?	<u>No</u>

**CONSULTANT:**

RESNA Industries