

QUARTERLY SUMMARY REPORT  
Second Quarter 1993  
(April - June)

**RESNA**  
Working To Restore Nature

UNOCAL SERVICE STATION #5367  
500 Bancroft Avenue  
San Leandro, California

City/County ID# San Leandro Fire Department

County: Alameda County

FILE #	<u>5367</u>	SS	<input checked="" type="checkbox"/>	BP	<input type="checkbox"/>
RPT	<input type="checkbox"/>	QM	<input type="checkbox"/>	TRANSMITTAL	<input type="checkbox"/>
1	<input type="checkbox"/>	2	<input type="checkbox"/>	3	<input checked="" type="checkbox"/>
4	<input type="checkbox"/>	5	<input type="checkbox"/>	6	<input type="checkbox"/>

RECEIVED

2:00 pm, Jun 17, 2009

Alameda County  
Environmental Health

**BACKGROUND**

Eight groundwater monitoring wells present. Groundwater has fluctuated between 33 and 38 feet below the ground surface.

**RECENT QUARTER ACTIVITIES**

Second quarter 1993 monitoring performed. Submitted second quarter report.

**NEXT QUARTER ACTIVITIES**

Perform third quarter 1993 groundwater monitoring.

**CHARACTERIZATION/REMEDIAL STATUS**

Soil contamination delineated?	<u>Yes</u>
Dissolved groundwater delineated?	<u>No</u>
Free Product delineated?	<u>NA</u>
Amount of gw contaminant recovered this quarter?	<u>0 gallons</u>
Soil remediation in progress?	<u>No</u>

**CONSULTANT:**

RESNA Industries