



Third Quarter 1993 (July -September)

UNOCAL SERVICE STATION #5367

500 Bancroft Avenue San Leandro, California

City/County ID#

San Leandro Fire Department

County:

Alameda County

FILE#	5367	_ \$\$ _	<u>/</u>	BP	
RPT	QM	_TRA	NSMIT	TAL _	
12	2 3	_ 4_	5_	6.	

BACKGROUND

Eight groundwater monitoring wells present. Groundwater has fluctuated between 33 and 38 feet below the ground surface.

RECENT QUARTER ACTIVITIES

Third quarter 1993 monitoring performed and report submitted.

NEXT QUARTER ACTIVITIES

Perform fourth quarter 1993 groundwater monitoring. Respond to letter from County.

CHARACTERIZATION/REMEDIAL STATUS

Soil contamination delineated?
Dissolved groundwater delineated?
Free Product delineated?
Amount of gw contaminant recovered this quarter?
Soil remediation in progress?

Yes No NA 0 gallons No

CONSULTANT:

RESNA Industries

RECEIVED

2:00 pm, Jun 17, 2009

Alameda County Environmental Health