



PACIFIC
ENVIRONMENTAL
GROUP, INC.

RECEIVED

11:34 am, Jun 17, 2009

Alameda County
Environmental Health

April 18, 1997
Project 311-127.1A

Mr. Richard Hiatt
Regional Water Quality Control Board
San Francisco Bay Region
2101 Webster Street, Suite 500
Oakland, California 94612

Re: 76 Products Company
Quarterly Summary Report
First Quarter 1997

FILE #	5367	SS	<input checked="" type="checkbox"/>	BP	<input type="checkbox"/>
RPT	QM	TRANSMITTAL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
1	2	3	<input checked="" type="checkbox"/>	4	5
				6	

Dear Mr. Hiatt:

As directed by Ms. Tina Berry of Tosco Marketing Company (formerly 76 Products Company), Pacific Environmental Group, Inc. is forwarding the quarterly summary report for the following location:

Service Station

5367

Location

500 Bancroft Avenue, San Leandro

Should you have questions or comments, please do not hesitate to contact our office at (408) 441-7500.

Sincerely,

Pacific Environmental Group, Inc.

Joseph Muzzio
Project Geologist

Enclosure

cc: Ms. Tina Berry, Tosco Marketing Company
Ms. Amy Leech, Alameda County Health Care Services

Quarterly Summary Report First Quarter 1997

76 Products Company Service Station 5367
500 Bancroft Avenue
San Leandro, California

City/County ID #: None
County: Alameda

BACKGROUND

The site is an active 76 Products Company service station. In 1987, limited soil excavation was performed at the site during the replacement of underground storage tanks, product lines and product dispensers. One groundwater monitoring well was installed following these activities. Between 1988 and 1994, eight monitoring wells were installed, aquifer testing was performed and a remedial action plan was prepared. In 1995, one additional monitoring well was installed, and a soil vapor extraction (SVE) and groundwater extraction remediation system was constructed. During the first quarter of 1996, remedial system start up and operation were performed. During the third quarter 1996, Unocal submit revisions to the groundwater monitoring program requesting a sampling reduction from quarterly to semiannually.

RECENT QUARTER ACTIVITIES

Groundwater monitoring and sampling were performed in March. Monthly monitoring of the soil vapor and groundwater extraction and treatment system was performed and appropriate compliance documentation was submitted. During February and March the SVE system was operated in pulsed mode to increase petroleum hydrocarbon vapor recovery. However, influent concentrations remained at non-detectable levels. Therefore, the SVE and dewatering system was shut down on March 13, 1997.

NEXT QUARTER ACTIVITIES

No activities are planned. — *GW m&S will continue*

CHARACTERIZATION/REMEDIAL STATUS

Soil contamination delineated? Yes.

Dissolved groundwater delineated? Yes.

Free product delineated? Not applicable.

Total amount of groundwater contaminant recovered? Approximately 108 pounds.

Soil remediation in progress? No. System shut down in March 1997

Start? March 1996.

Completion date? March 1997.

Dissolved/free product remediation in progress? No. System shut down in March 1997

Start? March 1996.

Completion? March 1997.

CONSULTANT: Pacific Environmental Group, Inc.