

October 12, 1998
Project 311-127.1A

Mr. Richard Hiett Regional Water Quality Control Board San Francisco Bay Region 2101 Webster Street, Suite 500 Oakland, California 94612

Re: 76 Service Station 5367 Quarterly Summary Report Third Quarter 1998

Dear Mr. Hiett:

As directed by Ms. Tina Berry of Tosco Marketing Company, Pacific Environmental Group, Inc. is forwarding the quarterly summary report for the following location:

Service Station

Location

5367

500 Bancroft Avenue, San Leandro

Should you have questions or comments, please do not hesitate to contact our office at (408) 441-7500.

Sincerely,

Pacific Environmental Group, Inc.

Timothy L. Ripp Project Geologist

Enclosure

: Ms. Tina Berry, Tosco Marketing Company

Ms. Amy Leech, Alameda County Health Care Services

RESENTED.

RECEIVED

3:42 pm, Jun 15, 2009

Alameda County
Environmental Health

OCT 1 4 1998

**ENV. COMPLIANCE** 



76 Service Station 5367 500 Bancroft Avenue San Leandro, California

City/County ID #: None

County: Alameda

## BACKGROUND

The underground fuel storage tanks, product dispensers and associated underground piping were replaced in 1987. There are currently five on-site groundwater monitoring wells and five off-site groundwater monitoring wells in use at the site. Soil vapor extraction and groundwater extraction systems were operated at the site from to March 1996 to March 1997, removing an estimated 108 pounds of gasoline hydrocarbons.

## RECENT QUARTER ACTIVITIES

Semiannual groundwater monitoring and sampling activities were performed in September 1998.

## **NEXT QUARTER ACTIVITIES**

No activities are planned.

## CHARACTERIZATION/REMEDIAL STATUS

Soil contamination delineated? Yes.

Dissolved groundwater delineated? Yes.

Free product delineated? Not applicable.

Total amount of groundwater contaminant recovered? Approximately 108 pounds.

Soil remediation in progress? No.

Start? March 1996.

Completion date? March 1997.

Dissolved/free product remediation in progress? No.

Start? March 1996.

Completion? March 1997.

CONSULTANT: Pacific Environmental Group, Inc.