## ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY



ALEX BRISCOE, Agency Director

ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

May 11, 2010

J.W. Silveira J.W. Silveira Realty 499 Embarcadero Oakland, CA 94606

Subject: Fuel Leak Case No. RO0000504 and Geotracker Global ID (T0600101898), William Wurzbach Company, 1200 20<sup>th</sup> Avenue, Oakland, CA 94606 – Case Closure

Dear Mr. Silveira:

This letter transmits the enclosed underground storage tank (UST) case closure letter in accordance with Chapter 6.75 (Article 4, Section 25299.37[h]). The State Water Resources Control Board adopted this letter on February 20, 1997. As of March 1, 1997, the Alameda County Environmental Health (ACEH) is required to use this case closure letter for all UST leak sites. We are also transmitting to you the enclosed case closure summary. These documents confirm the completion of the investigation and cleanup of the reported release at the subject site. The subject fuel leak case is closed. This case closure letter and the case closure summary can also be viewed on the State Water Resources Control Board's Geotracker website (<a href="http://geotracker.swrcb.ca.gov">http://geotracker.swrcb.ca.gov</a>) and the Alameda County Environmental Health website (<a href="http://www.acgov.org/aceh/index.htm">http://www.acgov.org/aceh/index.htm</a>).

#### SITE INVESTIGATION AND CLEANUP SUMMARY

Please be advised that the following conditions exist at the site:

- Total Petroleum Hydrocarbons as gasoline remain in soil at concentrations up to 270 ppm.
- Total Petroleum Hydrocarbons as gasoline remain in groundwater at concentrations up to 9,000 ppb.
- As described in section IV of the attached Case Closure Summary, the case was closed with Site Management Requirements that limit future land use to commercial land use only.

If you have any questions, please call Jerry Wickham at (510) 567-6791. Thank you.

Sincerely

Donna L. Drogos, P.E.

Chief

#### Enclosures:

- 1. Remedial Action Completion Certification
- 2. Case Closure Summary

CC:

Leroy Griffin (w/enc)
Oakland Fire Department
250 Frank H. Ogawa Plaza, Ste. 3341
Oakland, CA 94612-2032
(Sent via E-mail to: lgriffin@oaklandnet.com)

Closure Unit (w/enc)
State Water Resources Control Board
UST Cleanup Fund
P.O. Box 944212
Sacramento, CA 94244-2120

Paul King, P&D Environmental, Inc. 55 Santa Clara Avenue, Suite 240 Oakland, CA 94610 (Sent via E-mail to: PDKing0000@aol.com)

Donna Drogos, ACEH (Sent via E-mail to: <a href="mailto:donna.drogos@acgov.org">donna.drogos@acgov.org</a>)
Jerry Wickham, ACEH (w/o enc)

Geotracker (w/enc) File (w/orig enc)

## ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY



ALEX BRISCOE, Agency Director

ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

#### REMEDIAL ACTION COMPLETION CERTIFICATION

May 11, 2010

J.W. Silveira J.W. Silveira Realty 499 Embarcadero Oakland, CA 94606

Subject: Fuel Leak Case No. RO0000504 and Geotracker Global ID (T0600101898), William Wurzbach Company, 1200 20<sup>th</sup> Avenue, Oakland, CA 94606 – Case Closure

Dear Mr. Silveira:

This letter confirms the completion of a site investigation and remedial action for the underground storage tanks formerly located at the above-described location. Thank you for your cooperation throughout this investigation. Your willingness and promptness in responding to our inquiries concerning the former underground storage tank(s) are greatly appreciated.

Based on information in the above-referenced file and with the provision that the information provided to this agency was accurate and representative of site conditions, this agency finds that the site investigation and corrective action carried out at your underground storage tank(s) site is in compliance with the requirements of subdivisions (a) and (b) of Section 25296.10 of the Health and Safety Code and with corrective action regulations adopted pursuant to Section 25299.3 of the Health and Safety Code and that no further action related to the petroleum release(s) at the site is required.

This notice is issued pursuant to subdivision (h) of Section 25296.10 of the Health and Safety Code. Please contact our office if you have any questions regarding this matter.

Sincerely

Ariu Levi Director

Alameda County Environmental Health

Agency Name: Alameda County Environmental Health

### €ASE CLOSURE SUMMARY LEAKING UNDERGROUND FUEL STORAGE TANK - LOCAL OVERSIGHT PROGRAM

#### I. AGENCY INFORMATION

Address: 1131 Harbor Bay Parkway
Phone: (510) 567-6791

Date: January 29, 2010

City/State/Zip: Alameda, CA 94502-6577	Phone: (510) 567-6791
Responsible Staff Person: Jerry Wickham	Title: Senior Hazardous Materials Specialist

#### **II. CASE INFORMATION**

Site Facility Name: William Wurzbach Company								
Site Facility Address: 1200 20 <sup>th</sup>	Avenue, Oakland, CA 94606							
RB Case No.: 01-2066 StlD: 4868 LOP Case No.: RO0000504								
URF Filing Date: 7/18/1994	Geotracker ID: T0600101898	APN:	20-109-1					
Responsible Parties	Addresses		Phone Numbers					
J.W. Silveira	499 Embarcadero, Oakland, CA 94	4606	510-834-9810					

Tank I.D. No	Size in Gallons	Contents	Closed In Place/Removed?	Date
1	600 gallons	Gasoline	Removed	01/19/1994
2	600 gallons	Gasoline	Removed	01/19/1994
				a ar en
Ma to the		MA ANY NAT	- 64 74 144	
	Piping	Removed	01/19/1994	

#### III. RELEASE AND SITE CHARACTERIZATION INFORMATION

Cause and Type of Release: Both tanks showed evidence of corrosion holes and the western tank had significant corrosion holes and splits along the seam.							
Site characterization complete? Yes Date Approved By Oversight Agency:							
Monitoring wells installed? Yes		Number: 3	Proper screened interval? Yes				
Highest GW Depth Below Ground Surface: 10 feet bgs	0.4	Lowest Depth: 27.5 feet bgs	Flow Direction: Southwest				
Most Sensitive Current Use: Potential drinking	water	source.					

Summary of Production Wells in Vicinity: Two water supply or unknown wells were identified within 2,000 feet of the site. Well T2S/R3W 6P1 1901 Calcot Street is approximately 1,500 feet southeast of the site. Well records indicate the well is 345-feet deep and may be an abandoned well. Based on the cross gradient location, distance from the site, and limited extent of groundwater contamination from the site, the well is not likely to be a receptor for the site. The second well, T2S/R4W 1k, is located approximately 1,500 feet west of the site. Well T2S/R4W 1k is 727 feet deep and is apparently owned by the Port of Oakland. Based on the cross gradient location, distance from the site, and limited extent of groundwater contamination from the site, the well is not likely to be a receptor for the site. Aquifer Name: East Bay Plain Are drinking water wells affected? No Nearest SW Name: The Tidal Canal between Oakland and Is surface water affected? No Alameda is approximately 1,500 feet southwest of the site. Off-Site Beneficial Use Impacts (Addresses/Locations): None Where are reports filed? Alameda County Environmental Health Reports on file? Yes and City of Oakland Fire Department

TREATMENT AND DISPOSAL OF AFFECTED MATERIAL							
Material Amount (Include Units) Action (Treatment or Disposal w/Destination) Date							
Tank	2 - 600 gallon tanks	The tanks were transported to H and H Ship Services in San Francisco, CA for disposal	01/19/1994				
Piping	Not reported	The piping was transported H and H Ship Services in San Francisco, CA for disposal	01/19/1994				
Free Product	, .						
Soil	80 cubic yards	Transported to Keller Canyon Landfill for disposal	07/05/1994				
Groundwater	da sal sa	AUT-					

### MAXIMUM DOCUMENTED CONTAMINANT CONCENTRAT No information available from tank removals IONS BEFORE AND AFTER CLEANUP

(Please see Attachments 1 through 6 for additional information on contaminant locations and concentrations)

O	Soil	(ppm)	Water (ppb)		
Contaminant	Before	After	Before	After	
TPH (Gas)	2,300	270	23,000(1)	9,000(1)	
TPH (Diesel)	Na	NA	1,900	1,900	
TPH (Motor Oil)	NA	NA	NA	NA	
Benzene	2.9	0.28	3,700(1)	1,200(1)	
Toluene	33	0.25	560(1)	63(1)	
Ethylbenzene	28	3.6	1,000(1)	130(1)	
Xylenes	150	14	3,100(1)	74(1)	
Lead	5.7(2)	5.7(2)		ALIO NAS MA	
МТВЕ	<0.005(3)	<0.005(3)	26,000(4)	2.4(4)	
Other (8240/8270)	NA	NA	20(5)	20(5)	

<sup>(1)</sup> The maximum concentration before cleanup is the maximum concentration detected historically in groundwater from MW-1; the maximum concentration after cleanup is from a groundwater sample collected from well MW-1 during the most recent groundwater monitoring event on 06/06/2007.

(2) No metals analyzed other than lead.

<sup>(3)</sup> MTBE <0.005 ppm; 1,2-DCA = 0.019 ppm; EDB <0.004 ppm; TBA, TAME, ETBE, and DIPE not analyzed.

<sup>(4)</sup> MTBE <0.5 ppb; 1,2-DCA = 52 ppb; EDB <5 ppb; TBA, TAME, ETBE, and DIPE not analyzed.

<sup>(5)</sup> Trichloroethene = 20 ppb; cis-1,2-dichloroethene = 72 ppb; napthalene = 570 ppb; other VOCs not detected at various reporting limits.

Site History and Description of Corrective Actions:

The site is a commercial building located at the corner of Solano Way and 20<sup>th</sup> Avenue in Oakland, California. Surrounding land use is commercial and industrial. Two underground storage tanks (USTs) were removed from the sidewalk in front of 1200 20<sup>th</sup> Avenue on January 19, 1994. The tanks were oriented roughly north-south within a common excavation. Both tanks showed evidence of corrosion holes and the western tank had a split along the seam at the south end of the tank. Due to significant soil staining observed beneath the tanks, the excavation was extended to a depth of approximately 15 feet bg. The lateral extent of the excavation was limited by 20<sup>th</sup> Avenue to the north, Solano Way to the west, and a gas line and the building foundation to the south. Following overexcavation, contamination was still observed along the western sidewall of the excavation.

Three soil borings were advanced and completed as monitoring wells in February 1995. The three monitoring wells (MW-1, MW-2, and MW-3) were constructed to depths of 30, 35, and 30 feet bgs, respectively. TPHg and benzene were detected in groundwater from well MW-1, which is located immediately adjacent to the former USTs, at concentrations of 1,900 and 92 ppb, respectively.

Two additional soil borings were advanced south of the former USTs in June 1999. TPHg, BTEX, and MTBE were not detected in soil samples from the two borings. No groundwater samples were collected from the borings because groundwater was reportedly not encountered in the borings.

The three groundwater monitoring wells were monitored sporadically from February 1995 to August 2001. TPHg has been detected in groundwater from well MW-1 at concentrations ranging from 23,000 ppb in July 1998 to 1,900 ppb in June 2007.

An additional investigation consisting of soil gas sampling (SG-1), a geophysical survey, and soil borings (B-3 through B-9), was conducted in March and April 2009. Soil gas sampling was attempted at two depths (5 and 10 feet bgs) at location SG-1, which is located within an office space inside the building adjacent to the former USTs. However, it was not possible to collect soil vapor samples at either depth due to the high vacuum conditions associated with fine-grained soils in the borehole.

A resistivity survey along with continuous coring and conductivity logging in the soil borings was used to identify coarse-grained soils that appear to be within buried stream channels. The stream channels are present beneath portions of the site and appear to intersect some monitoring wells but not others. The distribution of the stream channels in relation to the monitoring wells affects the apparent hydraulic gradient observed from the monitoring wells. Historically, the calculated hydraulic gradient has been north-northeast, which is uphill and highly unlikely. Consistently lower groundwater elevations observed in well MW-2 is more likely the result of vertical gradients associated with movement of groundwater in the buried stream channels. Groundwater flow at the site more likely follows the topography and regional flow to the southwest. Soil and grab groundwater data from the soil borings indicated that the extent of contamination is limited to the vicinity of the former USTs.

In October 2009, one additional soil boring (B-10) was advanced and a subslab soil vapor sample (SG-1) was collected. SG-1 was collected from the subslab space immediately below the floor of an office space adjacent to the former USTs. Benzene was detected at a concentration of 9.5 micrograms per cubic meter. Based on the subslab soil vapor sample, the hazard quotient was less than one and the cumulative excess cancer risk was estimated to be 0.18 per million.

#### **IV. CLOSURE**

Does completed corrective action protect existing beneficial uses per the Regional Board Basin Plan? Yes

Does completed corrective action protect potential beneficial uses per the Regional Board Basin Plan? Yes

Does corrective action protect public health for current land use? Alameda County Environmental Health staff does not make specific determinations concerning public health risk. However, based upon the information available in our files to date, it does not appear that the release would present a risk to human health based upon current land use and conditions.

Site Management Requirements: Case closure for this fuel leak site is granted for the current commercial land use only. If a change in land use to any residential or other conservative land use scenario occurs at this site, Alameda County Environmental Health (ACEH) must be notified as required by Government Code Section 65850.2.2. ACEH will re-evaluate the case upon receipt of approved development/construction plans.

Excavation or construction activities in areas of residual contamination require planning and implementation of appropriate health and safety procedures by the responsible party prior to and during excavation and construction activities.

This site is to be entered into the City of Oakland Permit Tracking System due to the residual contamination on site.

Should corrective action be reviewed if land use changes? Yes.

Was a deed restriction or deed notification filed? No

Date Recorded: --

Monitoring Wells Decommissioned: No

Number Decommissioned: 0

Number Retained: 3

List Enforcement Actions Taken: None

. . .

List Enforcement Actions Rescinded: --

#### V. ADDITIONAL COMMENTS, DATA, ETC.

Considerations and/or Variances:

No soil or groundwater analyses for TBA, TAME, ETBE, or DIPE. Based on absence of MTBE in soil or groundwater samples, analyses for additional fuel oxygenates not warranted.

Conclusion:

Alameda County Environmental Health staff believe that the levels of residual contamination do not pose a significant threat to water resources, public health and safety, and the environment under the current commercial land use based upon the information available in our files to date. No further investigation or cleanup for the fuel leak case is necessary unless a change in land use to any residential or other conservative land use scenario occurs at the site. ACEH staff recommend closure for this site.

#### VI. LOCAL AGENCY REPRESENTATIVE DATA

Prepared by: Jerry Wickham	Title: Senior Hazardous Materials Specialist				
Signature: Jan Widdlam	Date: 02/25/10				
Approved by: Donna L. Drogos, P.E.	Title: Chief				
Signature: Law J	Date: 02/25/10				

This closure approval is based upon the available information and with the provision that the information provided to this agency was accurate and representative of site conditions.

#### VII. REGIONAL BOARD NOTIFICATION

Regional Board Staff Name: Cherie McCaulou	Title: Engineering Geologist
Notification Date: 02/25/2010	


#### **VIII. MONITORING WELL DECOMMISSIONING**

Date Requested by ACEH: 03/02/2010	/oz/2010 Date of Well Decommissioning Report: 05/06/2010					
All Monitoring Wells Decommissioned: (es) No	Number Decommissioned: 3	Number Retained: Ø				
Reason Wells Retained: NA						
Additional requirements for submittal of groundwater data from retained wells: None						
ACEH Concurrence - Signature:	muldre	Date: 05/11/2010				


#### Attachments:

- 1. Site Vicinity Map/Area Well Survey Map (1 page)
- 2. Site Map (3 pp)
- 3. Soil and Groundwater Contour/Chemical Concentration Maps and Cross Sections (11 pp)
- 4. Soil and Soil Vapor Analytical Data (5 pp)
- 5. Groundwater Analytical Data (17 pp)
- 6. Boring Logs (22 pp)

This document and the related CASE CLOSURE LETTER & REMEDIAL ACTION COMPLETION CERTIFICATE shall be retained by the lead agency as part of the official site file.



#### **International Boulevard**



East 12th Street


#### **LEGEND**


Figure 3
Site Vicinity Map Showing Drilling Locations, and Locations of Cross Sections and Resistivity Transect
William Wurzbach Company
1200 20th Avenue
Oakland, California



Base Map from Google Earth

P&D Environmental, Inc. 55 Santa Clara Ave., Suite 240 Oakland, CA 94610





#### **LEGEND**




Figure 4


Aerial Photograph of Site Vicinity Showing Drilling Locations, and Locations of Cross Sections and Resistivity Transect William Wurzbach Company 1200 20th Avenue Oakland, California





Base Map from Google Earth


P&D Environmental, Inc. 55 Santa Clara Ave., Suite 240 Oakland, CA 94610
















Tetra Tech EM Inc.
















Site Vicinity Map Detail Showing TPH-G Concentrations in Groundwater
William Wurzbach Company
1200 20th Avenue
Oakland, California

N

Base Map From: Tetra Tech EM Inc. Site Location Map P&D Environmental, Inc. 55 Santa Clara Avenue, Suite 240 Oakland CA 94610








Figure 6
Dipole Resistivity Investigation Along 20th Avenue
William Wurzbach Company
1200 20th Avenue
Oakland, California

N

Base Map From:
J R Associates
Civil and Engineering Geophysics

P&D Environmental, Inc. 55 Santa Clara Avenue, Suite 240 Oakland CA 94610



	Table 1. Summary of Borchole Soil Laboratory Analytical Results									
Sample ID	Sample Date	TPH-G	MTBE	Benzene	Toluene	Ethylbenzene	Total Xylenes	EDB	1,2-DCA	Total Lead
B3-4.5	4/6/2009	ND<1.0	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND< <u>0.004</u>	ND<0.004	NA
B3-9.5	4/6/2009	21, a,b	ND<0.005	0.017	ND<0.005	0.021	ND<0.005	ND< <u>0.004</u>	ND<0.004	NA
B3-14.5	4/6/2009	ND<1.0	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND< <u>0.004</u>	ND<0.004	5.7
B3-17.5	4/6/2009	ND<1.0	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND< <u>0.004</u>	ND<0.004	NA
B3-19.5	4/6/2009	ND<1.0	ND<0.005	ND<0.005	ND<0.005	ND<0.005	0.0077	ND< <u>0.004</u>	ND<0.004	NA
B3-24.5	4/6/2009	ND<1.0	ND<0.005	0.011	ND<0.005	ND<0.005	0.018	ND<0.004	ND<0.004	NA
B4-2.5	4/6/2009	ND<1.0	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND< <u>0.004</u>	ND<0.004	NA
B4-4.5	4/6/2009	250, c,b	ND< <u>0.10</u>	ND<0.10	ND<0.10	0.74	2.3	ND< <u>0.080</u>	ND<0.080	NA
B4-9.5	4/6/2009	46, c,b	ND<0.10	0.28	0.25	0.76	<u>4.1</u>	ND<0.080	ND< <u>0.080</u>	5.3
B4-14.5	4/6/2009	3.7	ND<0.005	ND<0.005	0.023	0.045	0.15	ND<0.004	0.019	NA
B4-19.5	4/6/2009	36, c,b	ND<0.010	0.018	ND<0.010	0.078	0.40	ND<0.0080	ND< <u>0.0080</u>	NA
B4-24.5	4/6/2009	ND<1.0	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND<0.004	ND<0.004	NA
B5-2.0	4/6/2009	ND<1.0	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND<0.004	ND<0.004	NA
B5-4.5	4/6/2009	180, c,b	ND<0.10	ND<0.10	ND<0.10	1.3	<u>6.1</u>	ND< <u>0.080</u>	ND< <u>0.080</u>	NA
B5-9.5	4/6/2009	270, c,b	ND< <u>0.20</u>	0.22	ND<0.20	<u>3.6</u>	<u>14</u>	ND< <u>0.16</u>	ND< <u>0.16</u>	ND<5.0
B5-14.5	4/6/2009	ND<1.0	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND< <u>0.004</u>	ND<0.004	NA
BS-19.5	4/6/2009	ND<1.0	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND<0.004	ND<0.004	NA
B5-22.0	4/6/2009	ND<1.0	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND< <u>0.004</u>	ND<0.004	NA
B5-24.5	4/6/2009	ND<1.0	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND< <u>0.004</u>	ND<0.004	NA
B6-4.5	4/6/2009	ND<1.0	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND<0.004	ND<0.004	NA
B6-9.5	4/6/2009	ND<1.0	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND<0.004	ND<0.004	5.2
B6-14.5	4/6/2009	ND<1.0	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND<0.004	ND<0.004	NA
B6-19.5	4/6/2009	ND<1.0	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND<0.004	ND<0.004	NA
B6-24.5	4/6/2009	ND<1.0	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND< <u>0.004</u>	ND<0.004	NA
ESL'		83	0.023	0.044	2.9	2.3	2.3	0.00033	0.0045	200
ESL 2		83	0.023	0.044	2.9	3.3	2.3	0.00033	0.0045	750
ESL <sup>3</sup>		83	0.023	0.044	2.9	3.3	2.3	0.00033	0.0045	750
ESL⁴		83	0.023	0.044	2.9	3.3	2.3	0.00033	0.0045	750

TPH-G = Total Petroleum Hydrocarbons as Gasoline

MTBE = Methyl tertiary-butyl ether

EDB = Ethylene Dibromide

1,2-DCA = 1,2-Dichloroethane

ND = Not detected.

NA = Not Analyzed.

- a = Laboratory note: strongly aged gasoline or diesel range compounds are significant in the TPH-G chromatogram.
- b = Laboratory note: no recognizable pattern.
- c = Laboratory note: heavier gasoline range compounds are significant (aged gasoline?)

ESL' = Environmental Screening Level, developed by San Francisco Bay - Regional Water Quality Control Board (SF-RWQCB) updated May 2008, from Table A - Shallow Soil Screening Levels, Groundwater is a current or potential source of drinking water. Residential Land Use.

ESL<sup>2</sup> = Environmental Screening Level, developed by San Francisco Bay - Regional Water Quality Control Board (SF-RWQCB) updated May 2008, from Table A - Shallow Soil Screening Levels, Groundwater is a current or potential source of drinking water. Commercial/Industrial Land Use.

ESL<sup>3</sup> = Environmental Screening Level, developed by San Francisco Bay - Regional Water Quality Control Board (SF-RWQCB) updated May 2008, from Table C - Deep Soil Screening Levels, Groundwater is a current or potential source of drinking water. Residential Land Use.

ESL<sup>4</sup> = Environmental Screening Level, developed by San Francisco Bay - Regional Water Quality Control Board (SF-RWQCB) updated May 2008, from Table C - Deep Soil Screening Levels, Groundwater is a current or potential source of drinking water. Commercial/Industrial Land Use.

Results in bold exceed their respective ESL values for Residential Land Use.

Underlined results exceed their respective ESL values for Commercial/Industrial Land Use.

Results in micrograms per liter (µg/L) unless otherwise specified.

	Table 1. Summary of Soil Analytical Results										
Sample ID	Sample Date TPH-G		МТВЕ	Benzene	Toluene	Ethylbenzene	Total Xylenes				
B10-4.5	10/5/2009	ND<1.0	ND<0.05	ND<0.005	ND<0.005	ND<0.005	ND<0.005				
B10-9.5	10/5/2009	ND<1.0	ND<0.05	ND<0.005	ND<0.005	ND<0.005	ND<0.005				
B10-14.5	10/5/2009	ND<1.0	ND<0.05	ND<0.005	ND<0.005	ND<0.005	ND<0.005				
B10-19.5	10/5/2009	ND<1.0	ND<0.05	ND<0.005	ND<0.005	ND<0.005	ND<0.005				
B10-24.5	10/5/2009	ND<1.0	ND<0.05	ND<0.005	ND<0.005	ND<0.005	ND<0.005				
B10-29.5	10/5/2009	ND<1.0	ND<0.05	ND<0.005	ND<0.005	ND<0.005	ND<0.005				
B10-34.5	10/5/2009	ND<1.0	ND<0.05	ND<0.005	ND<0.005	ND<0.005	ND<0.005				
ESL <sup>I</sup>		83	0.023	0.044	2.9	2.3	2.3				
ESL <sup>2</sup>		83	0.023	0.044	2.9	3.3	2.3				
ESL <sup>3</sup>		83	0.023	0.044	2.9	3.3	2.3				
ESL ⁴		83	0.023	0.044	2.9	3.3	2.3				

TPH-G = Total Petroleum Hydrocarbons as Gasoline

MTBE = Methyl tertiary-butyl ether

ND = Not detected.

ESL<sup>1</sup> = Environmental Screening Level, developed by San Francisco Bay - Regional Water Quality Control Board (SF-RWQCB) updated May 2008, from Table A – Shallow Soil Screening Levels, Groundwater is a current or potential source of drinking water. Residential Land Use.

ESL<sup>2</sup> = Environmental Screening Level, developed by San Francisco Bay - Regional Water Quality Control Board (SF-RWQCB) updated May 2008, from Table A – Shallow Soil Screening Levels, Groundwater is a current or potential source of drinking water. Commercial/Industrial Land Use.

ESL<sup>3</sup> = Environmental Screening Level, developed by San Francisco Bay - Regional Water Quality Control Board (SF-RWQCB) updated May 2008, from Table C – Deep Soil Screening Levels, Groundwater is a current or potential source of drinking water. Residential Land Use.

ESL<sup>4</sup> = Environmental Screening Level, developed by San Francisco Bay - Regional Water Quality Control Board (SF-RWQCB) updated May 2008, from Table C – Deep Soil Screening Levels, Groundwater is a current or potential source of drinking water. Commercial/Industrial Land Use.

Results in micrograms per liter (µg/L) unless otherwise specified.

Table 3. Summary of Soil Gas Sample Analytical Results											
Sample ID	Sample Date	TPH-G	MTBE	Benzene	Toluene	Ethylbenzene	m,p-Xylenes	o-Xylenes	1,2-DCE	Naphthalene	2-Propanol
SG1	10/5/009	1,700	ND<4.8	9.5	42	8.5	33	12	ND<5.3	ND<28	ND<13
SG1-DUP	10/5/009	1,500	ND<4.8	9.2	45	7.5	34	12	ND<5.3	ND<28	16
SG1 Lab Duplicate		1,600	ND<4.8	10	39	8.1	32	12	ND<5.3	ND<28	ND<13
ESL <sup>T</sup>		10,000	9,400	84	63,000	980	m, p, o xylenes I	21,000 combined	94	72	None
ESL <sup>2</sup>		29,000	31,000	280	180,000	3,300	m, p, o xylenes5	58,000 combined	310	240	None

TPH-G = Total Petroleum Hydrocarbons as Gasoline

MTBE = Methyl tertiary-butyl ether

1,2-DCA = 1,2-Dichloroethane

2-Propanol = used as a leak detector during soil gas sample collection.

ND = Not detected.

ESL<sup>1</sup> = Environmental Screening Level, developed by San Francisco Bay - Regional Water Quality Control Board (SF-RWQCB) updated May 2008, from Table E – Indoor Air and Soil Gas (Vapor Intrusion Concerns), residential land use.

ESL<sup>2</sup> = Environmental Screening Level, developed by San Francisco Bay - Regional Water Quality Control Board (SF-RWQCB) updated May 2008, from Table E – Indoor Air and Soil Gas (Vapor Intrusion Concerns), commercial/industrial land use.

Results in micrograms per cubic meter (µg/m³) unless otherwise specified.

Table 1 Summary of Soil Sample Analysis Results in PPM; 1200 20th Ave., Oakland

Boring	Depth	TPH(g)	Ben- zene	Toluene	Ethyl- benzene	Xylenes	Total Lead
MW-1	5 ft	4.8	0.005	0.011	0.012	0.026	5.2
	15 ft	1.3	0.16	0.023	0.044	0.068	ND
MW-2	15 ft	ND.	ND · · · ·	ND · · · ·	ND · · · ·	ND	ND"
	25 ft	ND	ND	ND	ND.	ND	ND
MW-3	10 ft	ND	ND	ND	ND	ND	5.9
	20 ft	ND	ND	ND	ND	ND	8.5



### **Analytical Laboratory Report**

EPA Methods 8015 Modified / 8020

**Date Sampled:** 

1/19/94

Proj Mgr:

John Alt

Date Received:

1/19/94

Client:

**Epigene International** 

TPHg/BTEX Analyzed:

1/24, 25/94

Project:

94-005, 1200-20th Ave.

**TPHd Extracted:** 

NR

Matrix:

Soil 2A005

TPHd Analyzed: Date Reported:

NR 1/31/94

Lab #: Report #:

401030.rpt

Lab ID No.	Field ID No.	TPHG/BTEX DL Factor		Toluene	Ethyl benzene	Xylenes - Total	TPHg	TPHd	TPHd DL Factor
01	S-1	1	ND	ND	ND	ND	ND	NR	
02	S-2	1	ND	ND	ND	ND	ND	NR	
03	S-3	1	ND	ND	ND	ND	ND	NR	
04	S-4	1		0.011	0.020	0.071	8.5	NR	
05	S-5	1		0.13	0.072	0.38	11	NR	
06	S-6	10		3340	28	<b>170</b>		NR	
07	P-1, P-2 COMPOSITE	i	0.045	0.094	0.67	2.1	52	NR	
08	P-3, P-4 COMPOSITE	· · · · · · · · · · · · · · · · · · ·	0.064	0.17	0,60	2.1	37	NR	
7 1 2 1 WWW									

Detection Limits (DL)	D BBS make	0.005 make	0.005 ma/ka	0.005 ma/ka	1.0 mg/kg	l i
Detection Limits (DL)	Groon Higher	0.005 mg/ng	O'OOS GIRAND	0.405	110 015 115	l
· · · · · · · · · · · · · · · · · · ·	}	l l				i

NOTES:

NR - Analysis not requested.

COC - Chain of custody

ND - Analytes not detected at, or above the stated detection limit.

TPHg - Total petroleum hydrocarbons as gasoline.

TPHd - Total petroleum hydrocarbons as diesel #2.

mg/kg - Milligrams per kilogram (PPM). ug/L-Microgram per Litre (PPB).

DL - Detection limit.

DF - Dilution Factor

PQL - Practical Quantitation Limit - Multiply DL by the DF to obtain the PQL for a specific sample.

BTEX - This analysis was performed using EPA Method 8020, and EPA Method 5030.

TPHg - This analysis was performed using EPA Method 8015 Mod., and EPA Method 5030.

TPHd - This analysis was performed using EPA Method 8015 Mod. and LUFT Manual.

**CERTIFICATION:** 

California Department of Health Services ELAP Certificate #1842

Onsite Environmental Laboratories, 5500 Boscell Common, Fremont, CA 94538 (510) 490-8571

Laboratory Director

1-31-94

Printed on recycled paper.

Table 2. Sur	able 2. Summary of Laboratory Analytical Results												
Well Number	Sample Date	TPH-D	TPH-G	MTBE	Benzene	Toluene	Ethylbenzene	Total Xylenes	EDB	1,2-DCA			
MW1	6/6/2007	1,900, a	9,000	ND < 160	1,200	63	130	74.0	ND < 5.0	59.0			
MW2	6/6/2007	ND < 50	ND < 50	ND < 5.0	ND < 0.5	ND < 0.5	ND < 0.5	ND < 0.5	ND < 0.5	ND < 0.5			
MW3	6/6/2007	ND < 50	ND < 50	ND < 5.0	ND < 0.5	ND < 0.5	ND < 0.5	ND < 0.5	ND < 0.5	ND < 0.5			

TPH-D = Total Petroleum Hydrocarbons as Diesel

TPH-G = Total Petroleum Hydrocarbons as Gasoline

MTBE = Methyl tertiary-butyl ether analyzed by EPA Method 8021B.

EDB = Ethylene Dibromide analyzed by EPA Method 8260B.

1,2-DCA = 1,2-Dichloroethane analyzed by EPA Method 8260B.

Benzene, Toluene, Ethylbenzene and Total Xylenes analyzed by EPA Method 8021B.

ND = Not detected.

a = Laboratory Note: gasoline range compounds are significant.

Results in micrograms per liter (µg/L) unless otherwise specified.

	Table 2. Summary of Borehole Groundwater Laboratory Analytical Results									
Sample ID	Sample Date	TPH-G	MTBE	Benzene	Toluene	Ethylbenzene	Total Xylenes	EDB	1,2-DCA	
B3-W	4/8/2009	1,200	ND<2.5	110	ND<2.5	56	92	ND<2.5	11	
B4W-65	4/9/2009	100	ND<0.5	11	1.5	1.3	5.3	ND<0.5	ND< <b>0.5</b>	
B6-W	4/6/2009	ND < 50	ND<0.5	ND<0.5	ND<0.5	ND<0.5	0.55	ND<0.5	ND< <b>0.5</b>	
B7-W	4/7/2009	ND < 50	ND<0.5	ND<0.5	ND<0.5	ND<0.5	0.53	ND< <b>0.5</b>	ND<0.5	
B7W-64	4/9/2009	ND < 50	ND<0.5	1.0	0.99	ND<0.5	1.0	ND<0.5	ND<0.5	
B8-W	4/9/2009	ND < 50	ND<0.5	ND<0.5	ND<0.5	1.3	3.2	ND<0.5	ND< <b>0.5</b>	
B8W-59	4/9/2009	ND < 50	ND<0.5	ND<0.5	ND<0.5	ND<0.5	1.6	ND< <b>0.5</b>	ND< <b>0.5</b>	
B9-W	4/9/2009	ND < 50	ND<0.5	ND<0.5	1.0	1.6	7.1	ND<0.5	ND<0.5	
ESL		100	5.0	1.0	40	30	20	0.05	0.5	

TPH-G = Total Petroleum Hydrocarbons as Gasoline

MTBE = Methyl tertiary-butyl ether

EDB = Ethylene Dibromide

1,2-DCA = 1,2-Dichloroethane

ND = Not detected.

ESL = Environmental Screening Level, developed by San Francisco Bay - Regional Water Quality Control Board (SF-RWQCB) updated May 2008, from Table A – Shallow Soil Screening Levels, Groundwater is a current or potential source of drinking water. Results in micrograms per liter (μg/L) unless otherwise specified.

	Table 2.	Summary of Borehole Groundwater Analytical Results								
Sample ID	Sample Date	TPH-G	MTBE	Benzene	Toluene	Ethylbenzene	Total Xylenes			
B10-W	10/5/009	ND<1.0	ND<0.05	ND<0.005	ND<0.005	ND<0.005	ND<0.005			
ESL		100	5.0	1.0	40	30	20			

TPH-G = Total Petroleum Hydrocarbons as Gasoline

MTBE = Methyl tertiary-butyl ether

ND = Not detected.

ESL = Environmental Screening Level, developed by San Francisco Bay - Regional Water Quality Control Board (SF-RWQCB) updated May 2008, from Table A – Shallow Soil Screening Levels, Results in micrograms per liter (μg/L) unless otherwise specified.

# TABLE 3 FOURTH QUARTER GROUNDWATER RESULTS VOC AND TPH COMPOUNDS IN GROUNDWATER 1200 20TH AVENUE, OAKLAND

		Menitoring (Veil	Managara tenangan Juangan Kanganan dalah dan
			WW-3
Benzene	500	ND	ND
Toluene	7. 1 <b>.26</b> 1.431		ND L
Ethylbenzene	130	ND	ND
m.p-Xylenes	130	The Part of the Art of	i i dai
o-Xylene	38	ND	ND
MTBE	NO. Isidi		ALC THE CASE OF TH
	MW.		
Gasoline	3,200	DN	ND

#### Notes:

ug/L micrograms per Liter

ND not detected

TPH total petroleum hydrocarbons VOC volitile organic compound

MW-1 is water sample JW2-21

MW-2 is water sample JW2-22

MW-3 is water sample JW2-23

# TABLE 4 MONITORING WELL MW-1 VOC AND TPH COMPOUNDS IN GROUNDWATER FEBRUARY 1995 TO DECEMBER 2000 1200 20TH AVENUE, OAKLAND

Date	TPANOPIE			Y0'E (00/12)///		annersonament tans annersonament Tanamaranament Tan
intest to account the control of the	Gasoline	Benzene	Toluêne	Ethylpenzene	Xyienes	MIBE
Feb-95	1,900	92	39	57	260	
Jun-95	4,100	410	32	14	180	
Oct-95	1,300	180	22	32		1210 12 12 12 12 12 12 12 12 12 12 12 12 12
Feb-96	1,700	200	21	41	120	
Jun-96	1,900	160	7	34	31	
Sep-96	4,700	460	66	190	680	100 (100 )
Jan-97	2,200	230	35	100	330	
Jul-98	23,000	3,500	450	1,000	3,100	
Apr-99	14,000	2,600	560	141114340 - Eli	1,600	######################################
Feb-00	3,000	280	17	92	118	ND ND
May-00	18,000	3,700	430	770	2,440	ND
Sep-00	4,300	1,200	<b>59</b>	420	330	<b>//</b> 0.43
Dec-00	3,200	500	26	130	130	ND

#### Notes:

ug/L micrograms per Liter

not analyzedND not detected

TPH total petroleum hydrocarbons VOC volitile organic compound

# TABLE 5 MONITORING WELL MW-2 VOC AND TPH COMPOUNDS IN GROUNDWATER FEBRUARY 1995 TO DECEMBER 2000 1200 20TH AVENUE, OAKLAND

	rizikowa	Paragraphic Committee		dVoe (va/Lijes		
	Gasolile	Benzene	Toluene		XVienes	MIBE
Feb-95	ND	ND	ND	ND	ND	** **
Jun-95	ND	1.8	αN	1.1	0.62	
Oct-95	1111115	22	NO			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Feb-96	ND	3.3	2.7	0.99	2.4	~
Jun-96	ND	ND	0.6	ND	1.2	<b></b>
Sep-96		9.3	0.57	armonical control of the control of		
Jan-97	ND	2.6	ND	ND	0.76	
Jul-98	ND	ND	ND	ND	ND	<b>**</b> **
Apr-99			NO			here again and
Feb-00	ND	ND	ND	ND	ND	ND
May-00	ND	ND	ND	ND	ND	ND
Sep-00		, dan i	ND		ND.	ND
Dec-00	ND	ND	ND	ND	ND	ND

#### Notes:

ug/L micrograms per Liter

not analyzed not detected

TPH total petroleum hydrocarbons VOC volitile organic compound

# TABLE 6 MONITORING WELL MW-3 VOC AND TPH COMPOUNDS IN GROUNDWATER FEBRUARY 1995 TO DECEMBER 2000 1200 20TH AVENUE, OAKLAND

						a Principal and the second and a second
THE RESERVE THE PROPERTY OF TH	Gasoline	Benzene	Toluene	Ethylbenzene	Xylenes .	MTEE
Feb-95	ND	ND	ND	ND	ND	by 10
Jun-95	160	0.6	ΝD	0.6	0.72	<b>-</b> +
Oot-95	180	5.8	NO.			
Feb-96	54	5.6	2.8	2.9	8.1	***
Jun-96	ND	ND	ND	ND	ND	** ** ********************************
Sep-96	<b>96</b> Ų,,	112	7.1	######################################	62	
Jan-97	ND	ND	ND	ND	ND	
Jul-98	ND ND	ND	ND	ND	ND	er observ halle
Apr-99	No.	ΝD	NO THE			
Feb-00	ND	ND	ND	ND	ND	ND
May-00	ND	ND	ND	ND	ND	ND
Sep-00	ide di <b>No</b> ce di III	, in No	NO ILL			
Dec-00	ND	ND	ND	ND	ND	ND


### Notes:

ug/L micrograms per Liter

- not analyzed

ND not detected


TPH total petroleum hydrocarbons VOC volitile organic compound



	Volatile Org		by GC/MS		
		3 77 75 7	<u> </u>		<u> </u>
Client: Tetra Tech EMI	_		Analysis Method: Prep Method:	EPA 8260 EPA 5030	l i
Project#: P110604 Location: JW Silveira Props -	7301812th		rrep mediod:	DIA 3030	1
Bocacion: an priveria propo		<u>.</u>			
Field ID: JW1-04			Sampled:	04/01/99	]
Lab ID: 138737-005			Received:	04/01/99	
Matrix: Water	•		Extracted:	04/02/99 04/02/99	1
Batch#: 47202			Analyzed:	04/02/22	
Units: ug/L					
Diln Fac: 1			20 10 10 10 10 10 10 10 10 10 10 10 10 10	NAME AND DESCRIPTION OF THE PROPERTY OF THE PR	· 90000000
Analyte	Result		Repo	rting Limit	
Freon 12	ND			10	
Chloromethane	ND			1.0	
Vinyl Chloride	ND			1.0	
Bromomethane	ND			1.0	
Chloroethane	ND			1.0 5.0	
Trichlorofluoromethane	ND			10	
Acetone	ND			5.0	·
Freon 113	ND			0.5	
1,1-Dichloroethene	ND ND		3	5.0	
Methylene Chloride   Carbon Disulfide	ND			0.5	
MTBE	ND			0.5	
trans-1,2-Dichloroethene		.3		0.5	
Vinyl Acetate	ND			10	
1,1-Dichloroethane	ND			0.5	
2-Butanone	ND			1.0	
cis-1,2-Dichloroethene	ND			0.5	
2,2-Dichloropropane	ND			5.0	
Chloroform	ND			0.5	
Bromochloromethane	ND			10	
1,1,1-Trichloroethane	ND			0.5	
1,1-Dichloropropene	ND			5.0	
Carbon Tetrachloride	ND .			0.5	
1,2-Dichloroethane	ND			0.5 0.5	
Benzene	,	73 5.7		0.5	
Trichloroethene		). <i>(</i>		0.5	
1,2-Dichloropropane	ND ND			0.5	
Bromodichloromethane   Dibromomethane	ND			5.0	
4-Methyl-2-Pentanone	ND			10.	
cis-1,3-Dichloropropene	ND			0.5	
Toluene		7.0		0.5	
trans-1,3-Dichloropropene	ND			0.5	
1,1,2-Trichloroethane	ND		•	0.5	
2-Hexanone	ND			10	
1,3-Dichloropropane	ND			5.0	
Tetrachloroethene	ND		•	0.5	
Dibromochloromethane	ND			0.5	•

	Volatile	Organics	by GC/MS		
Field ID: JW1-04			Sampled:	04/01/99	
Lab ID: 138737-005			Received:	04/01/99	
Matrix: Water			Extracted:	04/02/99	ļ
Batch#: 47202			Analyzed:	04/02/99	
Units: ug/L					
Diln Fac: 1				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
Analyte	Resul	t	P	eporting Limit	
1,2-Dibromoethane	ND			5.0	
1,2-Dibiomoethane   Chlorobenzene	ND			0.5	ĺ
1,1,1,2-Tetrachloroethane	ND			5.0	İ
Ethylbenzene	1112	29	Name for	0.5	İ
m.p-Xylenes		6.3		0.5	·
m,p-xyrenes   o-Xylene		0.7		0.5	Ì
Styrene	ND	~ * *	•	0.5	
Bromoform	ND			0.5	1
Isopropylbenzene	1.2	41		5.0	
1,1,2,2-Tetrachloroethane	ND			0.5	
1,2,3-Trichloropropane	ND			5:0	
Propylbenzene	W. T	45		5.0	
Bromobenzene	ND			5.0	
1,3,5-Trimethylbenzene	ND			5.0	
2-Chlorotoluene	ND			5.0	
4-Chlorotoluene	ND			5.0	
tert-Butylbenzene	ND			5.0	
1,2,4-Trimethylbenzene	ND			5.0	
sec-Butylbenzene	<del></del>	12		5.0	
para-Isopropyl Toluene		18		5.0	
1,3-Dichlorobenzene	ND			50	
1,4-Dichlorobenzene	ND			5.0	
n-Butylbenzene	•	17		5.0	
1,2-Dichlorobenzene	ND			5.0	
1,2-Dibromo-3-Chloropropane	ND			5.0	
1,2,4-Trichlorobenzene	ND			5.0	,
Hexachlorobutadiene	ND			5.0	
Naphthalene	•	3.4 J		5.0	
1,2,3-Trichlorobenzene	ND			5.0	
Surrogate	\$Red	overy	1	Recovery Limits	
Dibromofluoromethane		94		81-121	
1,2-Dichloroethane-d4		96		76-127	
Toluene-d8		103		90-109	
Bromofluorobenzene		98		82-118	


J: Estimated Value




•			Page T OL Z
	Volatile Organic	s by GC/MS	
Client: Tetra Tech EMI		Analysis Method:	EPA 8260
Project#: Pl10604		Prep Method:	EPA 5030
Location: JW Silveira Props	•		
7.7.7.7.7.00		Sampled:	04/01/99
Field ID: JW1-05		Received:	04/01/99
Lab ID: 138737-006		Extracted:	04/04/99
Matrix: Water Batch#: 47224		Analyzed:	04/04/99
Units: ug/L			<b>.</b>
Diln Fac: 8.333		ì	
	220000000000000000000000000000000000000	1 2 12 12 13 14 15 16 14 16 16 14 16 16 16 16 16 16 16 16 16 16 16 16 16	999-999 ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( )
Analyte	Result	Repo	orting Limit
Freon 12	ND	<u></u> ·	83
Chloromethane	ND		8.3
Vinyl Chloride	ND 		8.3 8.3
Bromomethane	ND		8.3
Chloroethane	ND	·	42
Trichlorofluoromethane	ND ·		83
Acetone	ND		42
Freon 113	ND		4.2
1,1-Dichloroethene	ND ND		42
Methylene Chloride	ND		4.2
Carbon Disulfide MTBE	ND		4.2
trans-1,2-Dichloroethene	ND		4.2
Vinyl Acetate	ND		83
1,1-Dichloroethane	ND		4.2
2-Butanone	ND		83
cis-1,2-Dichloroethene	ND		4.2
2,2-Dichloropropane	ND		42
Chloroform	ND		4.2
Bromochloromethane	, ND		83
1,1,1-Trichloroethane	ND		4.2
1,1-Dichloropropene	ND		42
Carbon Tetrachloride	ND	•	4.2
1,2-Dichloroethane	ND		4.2
Benzene	1300		4.2
Trichloroethene	20		4.2
1,2-Dichloropropane	ND	,	4.2
Bromodichloromethane	ND		4.2
Dibromomethane	ND		42
4-Methyl-2-Pentanone	ND		83
cis-1,3-Dichloropropene	ND		4.2 4.2
Toluene	30		4.2
trans-1,3-Dichloropropene	ND		4.2
1,1,2-Trichloroethane	ND		4.2 83
2-Hexanone	ND .		42
1,3-Dichloropropane	ND		4.2
Tetrachloroethene	ND		4.2
Dibromochloromethane	ND	<u> </u>	




	Volatile Organic	s by GC/MS	
Field ID: JW1-05		Sampled:	04/01/99
Lab ID: 138737-006		Received:	04/01/99
Matrix: Water		Extracted:	04/04/99
Batch#: 47224	•	Analyzed:	04/04/99
Units: ug/L			•
Diln Fac: 8.333			
Analyte	Result	P	eporting Limit
1,2-Dibromoethane	ND		42
Chlorobenzene	ND		4.2
1,1,1,2-Tetrachloroethane	ND		42
Ethylbenzene	93	Nove de	4.2
m,p-Xylenes	36		4.2
o-Xylene	ND		4.2
Styrene	ND		4.2
Bromoform	ND		4.2
Isopropylbenzene	ND		42
1,1,2,2-Tetrachloroethane	ND		4.2
1,2,3-Trichloropropane	ND		42
Propylbenzene	ND		42
Bromobenzene	ND		42 42
1,3,5-Trimethylbenzene	ND		42
2-Chlorotoluene	ND		42
4-Chlorotoluene	ND	v	42
tert-Butylbenzene	ND		42 42
1,2,4-Trimethylbenzene	ND .		42
sec-Butylbenzene	ND		42
para-Isopropyl Toluene	ND		42
1,3-Dichlorobenzene	ND		42
1,4-Dichlorobenzene	ND		42
n-Butylbenzene	ND		42
1,2-Dichlorobenzene	ND		42
1,2-Dibromo-3-Chloropropane	ND	*	42
1,2,4-Trichlorobenzene	ND		42
Hexachlorobutadiene	ND		42
Naphthalene	ND		42
1,2,3-Trichlorobenzene	ND	The second of th	* *** ********************************
Surrogate	%Recovery		Recovery Limits
Dibromofluoromethane	96		81-121
1,2-Dichloroethane-d4	102		76-127
Toluene-d8	106		90-109
Bromofluorobenzene	95		82-118



	Volatile Orç	janic	by GC/MB	
Client: Tetra Tech EMI Project#: P110604 Location: JW Silveira Props			Analysis Method: Prep Method:	EPA 8260 EPA 5030
Field ID: JW1-06 Lab ID: 138737-007 Matrix: Water Batch#: 47224			Sampled: Received: Extracted: Analyzed:	04/01/99 04/01/99 04/05/99 04/05/99
Units: ug/L Diln Fac: 2.5		· · · · · · · · · · · · · · · · · · ·		
Analyte	Result	· . · ·	Repo	rting Limit
Freon 12	ИD		·	25
Chloromethane	ND			2.5
Vinyl Chloride	ND			2.5
Bromomethane	ND			2.5
Chloroethane	ND			2.5
Trichlorofluoromethane	ND			1.3
Acetone	ND			25
Freon 113	ND			13
1,1-Dichloroethene	ND			1.3
Methylene Chloride	ND			13
Carbon Disulfide	ND			1.3
MTBE	ND			1,3
trans-1,2-Dichloroethene		21		1.3
Vinyl Acetate	ND			25
1,1-Dichloroethane	ND			1.3
2-Butanone	ND			25
cis-1,2-Dichloroethene		72		1.3
2,2-Dichloropropane	ND			13
Chloroform	ND			1.3
Bromochloromethane	ND		•	25
1,1,1-Trichloroethane	ND			1.3
1,1-Dichloropropene	ND			13
Carbon Tetrachloride	ND			1.3
1,2-Dichloroethane	ND			1.3
Benzene	2	80		1.3
Trichloroethene		75 .		1.3
1,2-Dichloropropane	ND			1.3
Bromodichloromethane	ND			1.3
Dibromomethane	ND			13
4-Methyl-2-Pentanone	ND			25
cis-1,3-Dichloropropene	ND			1.3
Toluene	4	1.4		1.3
trans-1,3-Dichloropropene	ND			1.3
1,1,2-Trichloroethane	ND			1.3
2-Hexanone	ND			25
1,3-Dichloropropane	ND			13
Tetrachloroethene	ND			1.3
Dibromochloromethane	ND			. 1.3




MARK PARK PARK PARK PARK PARK PARK PARK P			
	Volatile Organio	es by GC/MS	
Field ID: JW1-06		Sampled:	04/01/99
Lab ID: 138737-007		Received:	04/01/99
Matrix: Water		Extracted:	04/05/99
Batch#: 47224		Analyzed:	04/05/99
Units: ug/L			
Diln Fac: 2.5			
Analyte	Result	, P	eporting Limit
1,2-Dibromoethane	ND	•	13
Chlorobenzene	ND		1.3
1,1,1,2-Tetrachloroethane	ND		1.3
Ethylbenzene	. 66	··· ·	1.3
m,p-Xylenes	6.4		1.3
o-Xylene	1.3		1.3
Styrene	ND		1.3
Bromoform	ND		1.3
Isopropylbenzene	17		13
1,1,2,2-Tetrachloroethane	ND		1.3
1,2,3-Trichloropropane	ND		13
Propylbenzene	15		13
Bromobenzene	ND		13
1,3,5-Trimethylbenzene	MD		13
2-Chlorotoluene	ND		13
4-Chlorotoluene	ND		. 13
tert-Butylbenzene	ND	4	13
1,2,4-Trimethylbenzene	ND		13
sec-Butylbenzene	ND		13
para-Isopropyl Toluene	ND	•	13
1,3-Dichlorobenzene	ND		13
1,4-Dichlorobenzene	ND	•	13
n-Butylbenzene	ND		13
1,2-Dichlorobenzene	ND		13
1,2-Dibromo-3-Chloropropane	ND		1.3 ,
1,2,4-Trichlorobenzene	ND		13 13
Hexachlorobutadiene	ND		13
Naphthalene	ND		13
1,2,3-Trichlorobenzene	ND		**************************************
Surrogate	%Recovery		Recovery Limits
Dibromofluoromethane	93	·	81-121
1,2-Dichloroethane-d4	96		76-127
Toluene-d8	104		90-109
Bromofluorobenzene	97		82-118



	Volatile Organi	ca by GC/MS	
Client: Tetra Tech EMI		Analysis Method	d: EPA 8260
Project#: P110604		Prep Method:	EPA 5030
Location: JW Silveira Props	·		
			04/03/00
Field ID: JW1-07		Sampled:	04/01/99 04/01/99
Lab ID: 138737-008		Received: Extracted:	04/01/99
Matrix: Water		Analyzed:	04/05/99
Batch#: 47224		Alialyzeu:	04/03/22
Units: ug/L			
pilm Fac: 8.333			
Analyte	Result	Re	porting Limit
Freon 12	ND	مربعد ر	83
Chloromethane	ND		83
Vinyl Chloride	ND		8.3
Bromomethane	ND		8.3
Chloroethane	ND		8.3
Trichlorofluoromethane	ND		42
Acetone	ND		83
Freon 113	ND		42 4.2
1,1-Dichloroethene	ND		4.2 42
Methylene Chloride	ND		4,2
Carbon Disulfide	ND		4.2
MTBE	ND		4.2
trans-1,2-Dichloroethene	ND .		83
Vinyl Acetate	ND ND		4.2
1,1-Dichloroethane	ND		83
2-Butanone	ND		4.2
cis-1,2-Dichloroethene 2,2-Dichloropropane	ND		42
Chloroform	ND		4.2
Bromochloromethane	ND		83
1,1,1-Trichloroethane	ND	•	4.2
1,1-Dichloropropene	ND	•	42
Carbon Tetrachloride	ND		4.2
1,2-Dichloroethane	ND		4.2
Benzene	1100		4.2
Trichloroethene	ND		4.2
1,2-Dichloropropane	ND		4.2
Bromodichloromethane	ND		4.2
Dibromomethane	ND	4	42
4-Methyl-2-Pentanone	ND		83
cis-1,3-Dichloropropene	ND		4.2
Toluene	100		4.2
trans-1,3-Dichloropropene	ND		4.2
1,1,2-Trichloroethane	ND		4.2
2-Hexanone	ND		83
1,3-Dichloropropane	ND		42
Tetrachloroethene	ND		4.2
Dibromochloromethane	ND		4.2

N. Carlotte and Ca	Volatile	Organics	by GC/MS	
Field ID: JW1-07			Sampled:	04/01/99
Lab ID: 138737-008			Received:	04/01/99
Matrix: Water			Extracted:	04/05/99
Batch#: 47224			Analyzed:	04/05/99
Units: ug/L				
Diln Fac: 8.333				
Analyte	Resul	ŧ .		Reporting Limit
1,2-Dibromoethane	ND			42
Chlorobenzene		5.2		4.2
1,1,1,2-Tetrachloroethane	ND			42
Ethylbenzene		540	was w	4.2
m,p-Xylenes		370 `		4.2
o-Xylene		38		4.2
Styrene	ND			4.2
Bromoform	ND			4.2
Isopropylbenzene		50		42
1,1,2,2-Tetrachloroethane	ND			4.2
1,2,3-Trichloropropane	ND		•	42
Propylbenzene		86		42
Bromobenzene	ND			42
1,3,5-Trimethylbenzene	÷	120		42
2-Chlorotoluene	ND	•		42
4-Chlorotoluene	ND			42
tert-Butylbenzene	ND			42
1,2,4-Trimethylbenzene		200		42
sec-Butylbenzene	ND			42
para-Isopropyl Toluene		22 J		42
1,3-Dichlorobenzene	ND			42
1,4-Dichlorobenzene	ND			42
n-Butylbenzene		39 J		42
1,2-Dichlorobenzene	ND			42
1,2-Dibromo-3-Chloropropane	ND			42
1,2,4-Trichlorobenzene	ND			42
Hexachlorobutadiene	ND			42
Naphthalene		570		42
1,2,3-Trichlorobenzene	ND			42
Surrogate	*Rec	overy		Recovery Limits
Dibromofluoromethane		94		81-121
1,2-Dichloroethane-d4		101		76-127
Toluene-d8		106		90-109
Bromofluorobenzene		97		82-118

J: Estimated Value



	Volacile Organics	by GC/MS	
Client: Tetra Tech EMI		Analysis Method:	
Project#: P110604		Prep Method:	EPA 5030
Location: JW Silveira Props			
Field ID: JW1-08		Sampled:	04/01/99
Lab ID: 138737-009	•	Received:	04/01/99
Matrix: Water		Extracted:	04/02/99
Batch#: 47202		Analyzed:	04/02/99
Units: ug/L			
Diln Fac: 1			
Analyte	Result	Repo	rting Limit
Freon 12	ND	·	10
Chloromethane	ND		1.0
Vinyl Chloride	ND		1.0
Bromomethane	ND		1.0
Chloroethane	ND		1.0
Trichlorofluoromethane	ND		5.0
Acetone	ND		10
Freon 113	ND		5.0 0.5
1,1-Dichloroethene	ND		5.0
Methylene Chloride	ND		0.5
Carbon Disulfide	ND	sart	0.5
MTBE	ND		0.5
trans-1,2-Dichloroethene	ND		10
Vinyl Acetate	ND ND		0.5
1,1-Dichloroethane	ND		10
2-Butanone cis-1,2-Dichloroethene	ND		0.5
2,2-Dichloropropane	ND	•	5.0
Chloroform	ND		0.5
Bromochloromethane	ND		10
1,1,1-Trichloroethane	ND		0.5
1,1-Dichloropropene	ND		5.0
Carbon Tetrachloride	ND		0.5
1,2-Dichloroethane	ND		0.5
Benzene	ND		0.5
Trichloroethene	ND		0.5
1,2-Dichloropropane	ND		0.5
Bromodichloromethane	ND		0.5
Dibromomethane	ND		5.0
4-Methyl-2-Pentanone	ND		10
cis-1,3-Dichloropropene	ND		0.5
Toluene	ND		0 _ 5
trans-1,3-Dichloropropene	ND		0.5
1,1,2-Trichloroethane	ND		. 0.5
2-Hexanone	ND		10
1,3-Dichloropropane	ND		5.0
Tetrachloroethene	ND		0.5
Dibromochloromethane	ND		0.5



Page 2 of 2

	Volatile Organics	by GC/MS		
Field ID: JW1-08		Sampled:	04/01/99	
Lab ID: 138737-009		Received:	04/01/99	
Matrix: Water	•	Extracted:	04/02/99	
Batch#: 47202		Analyzed:	04/02/99	·
Units: ug/L				
Diln Fac: 1				
Analyte	Result	R	eporting Limit	
1,2-Dibromoethane	ND		5.0	
Chlorobenzene	ND		0.5	
1,1,1,2-Tetrachloroethane	ND		5.0	
Ethylbenzene	ND	****	0.5	
m,p-Xylenes	ND		0.5	
o-Xylene	ND		0.5	
Styrene	ND		0.5	
Bromoform	ND		0.5	
Isopropylbenzene	ND		5.0	
1,1,2,2-Tetrachloroethane	ND		0.5	
1,2,3-Trichloropropane	ND		5.0	
Propylbenzene	ND		5.0	
Bromobenzene	ND		5.0	
1,3,5-Trimethylbenzene	ND		5.0	
2-Chlorotoluene	ND		5.0	
4-Chlorotoluene	ND		5.0	
tert-Butylbenzene	ND		5.0	
1,2,4-Trimethylbenzene	ND		5.0	
sec-Butylbenzene	ND		5.0	
para-Isopropyl Toluene	ND		5.0	
1,3-Dichlorobenzene	ND		5.0	
1,4-Dichlorobenzene	ND		5.0	
n-Butylbenzene	ND		5.0	
1,2-Dichlorobenzene	ND		5.0	
1,2-Dibromo-3-Chloropropane	ND		5.0	
1,2,4-Trichlorobenzene	ND		5.0	
Hexachlorobutadiene	ND		5.0	
Naphthalene	ND	•	5.0	
1,2,3-Trichlorobenzene	ND	•	5.0	
Surrogate	%Recovery	P	ecovery Limits	
Dibromofluoromethane	95		81-121	·
1,2-Dichloroethane-d4	99		76-127	
Toluene-d8	106		90-109	
Bromofluorobenzene	99		82-118	

1200 20th Aven	ue.				Well Number	MW-1
1200 20th Ave.	, Oakland, O	ali	forni	a .	Diameter of Boring	8 inches
ect # 94-067					Total Depth of Boring	30 feet
J. Alt, CEG					Date Started	February 13, 1995
pany Soils Explo	ration Servi	.ces			Date Completed	February 13, 1995
ts					······································	
					·	
<u> </u>						
WELL CONSTRUCT	TION DETAIL	Samble #	Blow Counts	Graphic Log		DESCRIPTION
				1076.17		
					•	and gravel FILL.
	¥83698) 2		·			_
2-inch dia						
	grout				Gray silty 6	
with ,	,		g:		tan mottelir	ng, moist. —
walls —		1	9			
			12			
						ngangan dengan d
					Bluish-gray	sandy CLAY,
		2	7 8		-	
		<u> </u>	<u>8</u>			~
	8					· •-
	Bentonite —— seal			1	-	_
<b>数</b> 身	#3					
	Lonestar sand	-	8		1	_
2-inch dia		3	17 25			AND, scattered
PVC tubing	T. C.		1			e gravel.Sänd is medium rained, moist.
0.02" 員員						,
STORS THE						
					•	<del>-</del>
	2-inch dia Sched. 40 PVC tubing with solid walls	94-067  J. Alt, CEG  pany Soils Exploration Servi  ts  WELL CONSTRUCTION DETAIL  2-inch dia Sched. 40 PVC tubing with solid walls  2-inch dia Sched. 40 PVC tubing with solid walls  2-inch dia Sched. 40 PVC tubing with o.02"	1200 20th Ave., Oakland, Caling 94-067  J. Alt, CEG  pany Soils Exploration Services ts  WELL CONSTRUCTION DETAIL  2-inch dia Sched. 40 PVC tubing with solid walls  2-inch dia Sched. 40 PVC tubing with Sched. 40 PVC tubing with Sched. 40 PVC tubing with Sched. 40 PVC tubing with O.02"  3 Bentonite Seal 3 Jonestar Sand 3	2-inch dia Sched. 40 PVC tubing with solid walls   Bentonite seal  2-inch dia Sched. 40 PVC tubing with solid walls   Bentonite seal  #3 Lonestar sand  2-inch dia Sched. 40 PVC tubing with solid walls   Bentonite seal  #3 Lonestar sand  2-inch dia Sched. 40 PVC tubing with solid walls   Bentonite seal	2-inch dia Sched. 40 PVC tubing with solid walls  2-inch dia Sched. 40 PVC tubing with solid walls  2-inch dia Sched. 40 PVC tubing with solid walls  2-inch dia Sched. 40 PVC tubing with solid walls  2-inch dia Sched. 40 PVC tubing with solid walls  2-inch dia Sched. 40 PVC tubing with solid walls  3 17 25 PVC tubing with 0.02"	Diameter of Boring  94-067  J. Alt, CEG  Date Started  Date Completed  Total Depth of Boring  Total Depth of Boring  Date Started  Date Completed  Total Depth of Boring  Date Started  Date Completed  Total Depth of Boring  Total Depth of Boring  Date Started  Date S

## WILLL LUG

Project	Number 94-067				
	· · · · · · · · · · · · · · · · · · ·			<del></del>	Page 2 of 2
Depth In Feet	WELL CONSTRUCTION DETAIL	Sample #	Blow Counts	Graphic Log	DESCRIPTION
in	WELL CONSTRUCTION DETAIL  2-inch dia PVC sched. 40 tubing/ with 0.02" slots  Slip-on end cap  Slip-on end cap	ejdures 4 5	**Moig 14 30 41 5 8 10 6 14 31	Graphic Log	DESCRIPTION  Dark gray SAND (as above), scattered pebble-size gravel. Sand is medium— to coarse-grained, moist.  Grayish-tan silty CLAY with lenses of brown silty sand,  grading  to  brown fine-grained SAND.  Bottom of boring.  Bottom of sampling.
- 41 - 42 - 43 - 44 45					

## WELL LUG

Project	1200 20th	Avenue.				tainti hittanin av	Mt.i 2		
Location		Ave., Oakland, (	 Cali	forni	<b>-</b>	Diameter of Boring	MW-2 8 inches		
Project :	10000000000000000000000000000000000000					Total Depth of Boring	35 feet		
Geologis		CEG				•	February 13, 1995		
	***************************************	Exploration Servi			********		February 13, 1995		
l		aproracion bervi	~~~		***********	Date Completed	reprudry 10, 1775		
Oomin.c.	ills	<del></del>			<del></del>	<u> </u>			
			PARTICULAR PROPERTY.						
Depth In Feet	WELL CONST	RUCTION DETAIL	Sample #	Blow	Graphic Log	I	DESCRIPTION		
- 0									
		T				asphalt Brown sand an	d gravel FILL.		
- 1	0.56.00						-		
- 2	2-inch dia					Light-brown s	ilty CLAY, dry,		
- 3	Sched. 40	grout					• • • • • • • • • • • • • • • • • • •		
- 4	tubing i-						. <b></b>		
- 5	with solid			9	111	Light-brown S	ILT with sand,		
- 6	walls —		1	14 17		scattered peb			
- 7	1				9		<b>-</b>		
- 8					a				
- 9	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\						•••		
<b>-</b> 10		13	2	12 17			note take time this date alone their time them as an annual		
11			Ĺ	17			AND with gravel n size, moist.		
- 12						WO 2,	and the field for y		
]		1 1					-		
- 13		] [-]					<b>b</b>		
- 14		1 [4					••••		
- 15		1 [1]	<u> </u>	15	1.1	_ As above, moi	ist.		
- 16			3	17 21		-			
- 17		Bentonite					,		
- 18		seal			, , ,		•		
- 19		#3			•0•	Brown SAND wi	<del></del> -		
20	<b>1 B</b>	Lonestar	1	1		and scattered	i pebbles, moist.		

# WELL LUG

Project	Name 1200 20th Avenue.				Well Number MW-2
Project I	Number 94-067	.,		*****	Page 2 of 2
		<del></del>			
Depth In Feet	WELL CONSTRUCTION DETAIL	Sample #	Blow Counts	Graphic Log	DESCRIPTION
<b>→ 20</b>	2" dia. #3 Sched. 40, #3 Lonestar sand	4	10 19	ő	Brown SAND (as above) with silt and scattered pebbles, moist.
- 21 - 22			32	-	
- 23	tubing With 0.02"			0	
<b>– 24</b>	slots——		 	ð	
- 25	#3 Lonestar sand		16	.0.	As above.
- 26	7 minum 10 10 10 10 10 10 10 10 10 10 10 10 10 1	5	23 34		
- 27					
- 28				<b>.</b> =.	•• •-
- 29				0	
- 30 - 31	To the state of th	6	6 10	0.	As above, wet. Lenses of brown silt.
- 32		-	9		
- 33				0.0	
- 34	Slip-on Lonestar			•0•	- <b>-</b>
- 35	end cap	7	8		Brown gravelly SAND with silt, gravel to 1 1/2" in size, sub-round
- 36			18		t <b>o su</b> b-angular (chert, shale, SS).
- 37					Bottom of sampling -
- 38					
- 39 - 40					
- 41					
- 42				,	
43					-
- 44			,		
45					

#### YYLLL LUU

*1A	1200 20th Avenue.	-			*** 16 1 4 1	· Mi 3
Project		~ 1:	,	pa-1/4p		
Location		атт.	torna		Diameter of Boring	,
Project #	94-067				Total Depth of Boring	30 feet
Geologis	J. Alt. CEG		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	-		February 14, 1995
Drill Com	pany Soils Exploration Servi	ces	•	, <del></del>	Date Completed	February 14, 1995
Commen						
		······				
	,	•				
Depth		# 0	ষ	je Ji		
In Feet	WELL CONSTRUCTION DETAIL	Sample	Blow Counts	Graphic Log	1	DESCRIPTION
						<u></u>
- 0				3,575	Asphalt	4 1771
- 1		•	1		Sand and gra	vei fill.
- 2	변 변			11/	Light-brown	eilty CLAY
- з	2-inch dia Sched. 40	-		///		ed coarse sand, moist.
	PVC 7			1//		_
- 4	tubing with		-	1//		
- 5	solid walls	1	7	1//	<b>†</b>	
- 6	Walls T(   )	-	8	1//	1	-
- 7	月月			1//	1	ton.
- 8	日日			///	1	makes and the beside beauty legisle beauty street while the same grade and
					Tan sandy GR	(AVEL, moist
- 8		-	12	7		
- 10		2	21			
- 11	] []	-	24			<b>-</b>
- 12	D. Danita					_
- 13	₩ Sentonite ₩ H—— seal			1 ( T		″ •••
- 14	Solid-wall					
1	tubing #3	<b> </b>	4	1//	light-brown	silty CLAY, moist.
15	2-inch dia. Lonestar sand	3	8	1//	7	*****
- 16	2-inch dia. Sched. 40 PVC tubing with 0.02" slots	-	10	1//	1	-
- 17	with			1//	1	,
- 18	0.02" slots	ľ		1//	1	
1					Tan SILT W	ith reddish-brown
19		<del> -</del>	ـ ا	1//	motteling.	1" thick lens of

# WELL LOG

Project I	Name 1200 20th Avenue.				Well Number MW-3
Project I	Number 94-067				Page 2 of 2
				<del>,</del>	
Depth In Feet	WELL CONSTRUCTION DETAIL	Sample #	Blow Counts	Graphic Log	DESCRIPTION
- 20 - 21 - 22	2-inch dia Sched. 40 #3 #3 Lonestar 0.02" slots	4	5". 7 4		- Tan SILT with reddish-brown motteling (as above). l <sup>m</sup> -thick lens of pebbles
- 23 - 24	I [4] 無 8년				Tan SAND, fine-grained, moist.
– 25	No. of the Control of	5	4 11 13		·
- 26 - 27			13		-
- 28			,		_
- 29 - 30	Slip-on end cap				As above, saturated
- 31		6	7   11   15		_
- 32 - 33			-		Bottom of sampling
- 34					
- 35					
- 36 - 37					•••
- 38					-
- 39 - 40					
41					-
- 42 - 43					
44 45					- -

	Tetra I	ech EN	Inc.	BORING ID: SB-1
		STREET, SUI		SITE: 1200 ZO = AVE
		5-543-4880	1 9-4 100	PROJECT: SILVEIRA - CAKLAND
			g I	058-1
		A POTTHE	S DEIVEN S DEIVEN Tiff bgs	PROJECT NO.: PILOG
	SWAPLEID	SAMPLETIME SAMPLEDEFI PID READING	MOHES BEGO MOHES DAW DEPTH (II bas)	
	Š	SAMPIL SAMPIL PID RED	MONES NONES DEPTH	
	######################################			ASPHALT 6"
	COMMISSION OF CO		1	FILL, SANDY- SILT, VIDEY PAE BROWN (10 YR 7/4), MOIST, SOFT.
			3 2	SILTY-CLAY, LIGHT YELLOWISH BEOWN (10 YR 4/4), LOW PLASTICITY, DRY, STIFF
	<u></u>			LOW PLASTICITY, DRY, STIFF
			] " 3	
				CLAYEY-GRAVEL, BROWN (104R4/3), FINE, SUB-POWNED, MEDIUM DEUSE GRAVET, WELL GRADUD, DRY
			5 2	MEDION DESE CHARLE, DELL GRENZELZ, DICE
			7	
			4— a	•
				SANDA-CIAN GERMEN-BROWN (7.54 5/2) LOW RASTICION
			3 s z	SANDY-CLAY, GRAYISH-BROWN (2.54 5/2), LOW PLASTICITY DAMP, VERY STIEF, W/15% COMEST SAD.
	- Andrews - Andr		B 10   1	
	The second secon		1	
	Market many management of the second of the		1 111 6	CLAMEY-SAND, BROWN (10 YR 43), SUB-ANGULAN, COARSE
			12	CLAMEY-SAND, BROWN (10 YR 43), SUB-ANGULAN, COMESE GRAINED SAND, MOIST, DENISE CLAY, DUNE YELLOW (2.5 4 6/6), HIGH PLASTICITY, DAMP,
				V VERY STIFE
			[83] 12	GRAVELY-CLAM MOTTLED BROWN (7.5 YR 5/2) & GRAM (546)
			<u> </u>	LOW PLASTICITY, MOIST, STIFF, W/20% FINE GRAVEL
			14 1	
Sein	- ASS maly discovere construct substitute recommendate		1 15	
	CANTING MANAGEMENT AND AND AND AND AND AND AND AND AND AND		16	No Recovery
				No recovery
			Ø 18	
<b>3</b>			19 1	CLAY, REDDISH BROWN (548 4/4), HIGH REASTICITY, DAME,
			₹ 20 [	VERY STIFE
			(S)	4
		* *		

		Total Control		HED	***************************************		Tetra Tech EM Inc.	BORING ID: SB-1
	Q	IME MANUAL MANUA MANUAL MANUAL MANUAL MANUAL MANUAL MANUAL MANUAL MANUAL MANUAL MANUA MA MANUA MANUA MANUA MANUA MANUA MANUA MANUA MANUA MANUA MANUA MA MANUA MANUA MANUA MANUA MANUA MANUA MANUA MANUA MANUA MANUA MANu	DN.	RECOVE HIVEN	(SEQ	IL TYPE	135 MAIN STREET, SUITE 1800	SITE: 1200 20th AUGNUE
	SAMPLE ID	SAMPLE TIME	PID READING	NOHES BECOVE	OEPTH (fl bgs)	USCS SOIL TYPE	SAN FRANCISCO, CA 94105 415-543-4880	PROJECT: SILVEIRA - OAKLAND
							SME AS ABOVE: CLAM. RE	DDIST BROWN (54R 4/4)
	**************************************				22		SAME AS ABOVE: CLAY, REM HIGH PLASTICITY, DAMP, I	Jerry STIFF.
				24		TVICE PER PER PER PER PER PER PER PER PER PE	government of the second of th	Park Property
				12/	23	H		
					24		<u>aliania de comunicario de comunicación de com</u>	
			- VANAGE	24	26	İ	- The state of the	- 12 75
				2	23			
				_	26		W/15% VERY FINE GRAVE	2-5mm
				124	27			
				23,				
		_		18	28			P. 14
				18/1	29		AS GRAVE PRESSOT	
					34.50			
				57/				
			H	29	31	- Company of the Comp	*	
					90		W/10% MEDIAM SAND	
			-	11/11				
,					33			
				12	34			
	***************************************		$\vdash$	2				
				12	35			0,434
					05			
			H	1		¥	TD=36 H bys SAM	RUR ROTUSAL STREET
			2	]	37			
			Н	-	38			
					39			
			H	1				
	4	1	H	1	40			
					41			
		The same of the sa	$\left\  \cdot \right\ $					
			固		42			
	en en en en en en en en en en en en en e		П		43	**************************************		
		-				United Marketon		
	anna antara antara antara antara di anna di antara di antara di antara di antara di antara di antara di antara		$\Box$		44	decounter		

Taire'	Tech E	W Ta		-			BORING ID: 5B-Z		
135 MAIN	STREET, SI NCISCO, C	UITE 18	300	MM-1		(v)	SITE: 1200 20 H AUE		
	15-549-488		<del>-</del>	4		O	PROJECT: SILVEIRA - OAKLAND		
	走 要 aa 要	SOCVERED IN	1346	黄	9 5B-2	58-i_	PROJECT NO.: PILOLO		
SAMPLE ID	SAMPLE DEPT	DHIVE INTERNITY INCHES RECC INCHES CRIVI DEPTH (II bos)	34A1 108 8981	FELD ORETCH	30-2		LOGGED BY: By GCEUN		
				SILTY-CLAY,		YELONE	A BROWN (10 48 4/4), LAW PLASTICITY		
		3 1	3		The second secon				
		2 2 s					(10 YR 4/3), MEDIUM GRAINED.		
**************************************		3		JUB-POUX		MEIL GR	NOED GRAVEL, MEDIUM DENSE,		
		*	שׁ		SAN SAN SAN SAN SAN SAN SAN SAN SAN SAN				
		\$ \$		<u> </u>					
	5 E E E	1.2 €		S. 154 / / A			WN (75 4 4/3), LOW PLASTICITY.		
		7		DAME, VEI	4.5	ie, u/	20% MEDIUM SAND.		
JW2-05	10550	8							
		13							
		134 23 1				Cale of the second second control of the sec			
Early Comments and		11	يـ ا	GRAVELY-CLA	1. M	MOLST	780WN (7.5 485/2) & GRAY (544) STIFF, W/15% FINE GRAVEL		
				5-Cem					
		46		CLAM. DAVEY	TZ es	(2.5 YK	4/10). High PEASTICITY. DAMPER		
**************************************		\$		Jeey 37	- Armen Sir				
				***************************************	3-				
			1						
					say Fi	HE GRAN	14. Z-4 mm		
BY A TO COMMISSION OF COMMISSI		1 3 1			engaperantamintamintamintamintamintamintamintam				
			#1						
<del>Characteria .</del>	<del>ne namena za karan</del>	3.1.£		3			¥		

SIME AS ABOVE: CLAY, TANK KED (2.5 YR HIGH PLASTICITY, DAMP, VISRY STIFE, W. FINE GRAVER E-HIMM  20  324  325  326  327  327  328  329  320  320  320  321  322  323  324  325  326  327  327  328  329  330  330  330  330  330  330  330	15 AUE 15 AUE 24 - OAKLAND
JUZ-ONO 1200 327 O CLAMEN-SAND, BROWN (7.5 YR 5/2), MEDIUM PROCEN GRADED SAND, JERN DENSE,  SANDY-CLAY, GRANISH BROWN (2.5 Y 5/2)  DAMP, JUSKY STILE, W/15% FINE GRAN 31  W/590 MEDIUM GRAVIEL 8-12mm  1035  DAMP, JERN STILE, W/20% FINE TO M 10-14mm  1035  1035  1037  1038	246) 1/1090 Voray
JUZ-OLO 1200 927 J. CLAYEY- SAD, BROWN (25 YRS/2), MEDIUM PROPEY GRADED SADD, JERY DENSE,  SANDY-CLAY, GRAYISH BROWN (25 Y S/ DAMP, VERY STIFF, W/15% FINE GRAN  10 30  10 31  W/5% MEDIUM GRANICA 8-12 MAY  W/5% MEDIUM GRANICA 8-12 MAY  W/5% MEDIUM GRANICA 8-12 MAY  W/5% MEDIUM GRANICA 8-12 MAY  DAMP, VERY STIFF, W/15% FINE TO M  10 35  10 35  11 36  12 37  13 38  10 = 37.7 ft bgp. EQUIMIENT REFUSA  12 38  12 37  13 38  10 = 37.7 ft bgp. EQUIMIENT REFUSA	
SANDY-CIAM, GRAYISA BROWN (25 4 5)  DAMP, VISEY STIFF, W/154, FINE GRAY  29  W/540 MEDIUM GRAVER 8-12 MAY  31  W/540 MEDIUM GRAVER 8-12 MAY  33  GRAVERY - CLAM, YELOWISH BROWN (104R 5)  DAMP, VERY STIFF, W/204 FINE TO M  10-14 MM  30  TD=37.7 A bys. Equilment Refusal  Day No Gray Country Country  Day No Gray Country  Day N	m GRAINED, DAMP
W/5% MEDIUM GRAVER 8-12mm  W/5% MEDIUM GRAVER 8-12mm  W/5% MEDIUM GRAVER 8-12mm  GRAVERY - CLAY, YELLOWISH BROWN (1048 S  Damp, VERY STIFF, W/20% FINE TO 18  10-14mm	2), LOW PLASTIC MED SAMO
GRANERY - CLAM, YELLOWISH BROWN (104R S  DAMP, NETCH STIFF, W/2012 FILLE TO A  10-14 mm  10-14 m	
36 10 = 377 A bys Equipment Testuses  100 14 mm  100 36  100 37  100 36  100 37  100 38  100 37  100 38  100 3	5/4-), Low KASTIC
TO = 37.7 A bgs. Equipment TREFUSA	UHava Glive
Day No Geowley All Court Tracks	
	<b>&gt;.</b>
40 41	
43 43	4

攤

BO	RING!		B3 PROJECTNO: 0405 PROJECTN	AME:	William Wurzba	ch Co	1200	20th Ave	Oakland	
-			AATION: 20 feet south of eastern corner of 20th Avenue an			011 (00.	·	······································	тим: None	
DR	ILLING	G AG	ENCY: Vironex, Inc.	DRILLE	R: Justin	DATE	& TIME	STARTED:	DATE & TIME FINISHED:	
DR	ILLIN	G E(	QUIPMENT: Geoprobe 6600		:		4/6/0 133		4/6/09 1410	
СО	MPLE	T101	N DEPTH: 25.0 Feet BEDROCK DEPTH: No	t Enco	untered		LOGGI		CHECKED BY:	
FIF	ST WA	TEF	R DEPTH: Not Encountered NO. OF SAMPLES: 6 Se	oil, 1 W			ML	.D		
DEPTH (FT.)			DESCRIPTION	GRAPHIC	WELL CONSTRUCTION LOG	BLOW COUNT PER 6"	BLOW COUNT PER 6" PID		REMARKS	
			0.0 to 0.5 ft. Asphalt and base rock. 0.5 to 2.0 ft. Brown silt (ML); medium stiff, moist, with orangemottling, and roots. No Petroleum Hydrocarbon (PHC) odor.—	ML	No Well Constructed		0	using a 5-f Geoprobe	ontinuously cored oot long 2.0-inch O.D. Macrocore barrel	
_			2.0 to 4.0 ft. Brown sandy clay (CL); medium stiff, — moist, with black mottling. No PHC odor.	CL			0	1.5-inch O sleeves.	ed with 4.8-foot long D. transparent PVC	
	5		4.0 to 5.0 ft. Grayish brown silt (ML); medium stiff, dry.  No PHC odor.  X	ML	B3-4.5		0		6 ft. recovery	
F			5.0 to 6.0 ft. Brown gravelly clayey sand (SC); medium dense, dry, with angular gravel to 0.25-in. diameter. No PHC odor.	SC	_		0	5 to 10 ft.	4.5 ft. recovery	
E		******	6.0 to 10.0 ft. Grayish brown silty clay (CL); stiff, moist. No PHC odor.	-			0	10 to 15 ft.	4.2 ft. recovery	
		_		CL			0	15 to 20 ft.	4.6 ft. recovery	
	10		10.0 to 17.0 ft. Grayish brown clayey sand (SC); —		B3-9.5		U	20 to 25 ft	. 4.6 ft. recovery	
			medium stiff, moist, with angular gravel to 0.5-in.  diameter. No PHC odor.				0			
			12.0 to 15.0 ft. Soil stained bluish green; strong PHC odor.	sc			14	Water not drilling.	encountered during	
_	1.5			<u> </u>	B3-14.5		109		erminated at 25.0 ft. on	
	15			<u> </u>	20 11.0	***************************************	3	4/6/09. Te slotted PV	mporary 1-in. diam. C casing placed in bore-	
E		_	17.0 to 25.0 ft. Orange-brown silty clay (CL); stiff,				0	Latex glov	porary well capped with e and bentonite plug to echarge. Water level	
_			moist, with black mottling. No PHC odor.		B3-17.5		0	measured :	at 15.8 ft. at 1340 on ater sample B3-W col-	
_	20				B3-19.5			sheen on s	345; slight odor but no ample. Collected 5	
	20			CL			0	tainers, ve	1 1-liter amber con- ry slow recharge. well again capped to	
			22.0 to 25.0 ft. Medium stiff.					allow for t	urther recharge. Water ared at 15,1 ft. at 1000	
		_	22.0 to 25.0 ft. Medium stri.	-				on 4/9/09. amber con	One additional 1-liter tainer for sample B3-W	
	25				B3-24.5		0	collected a	et 1005; slight odor but on sample.	
L	20		-						grouted on 4/9/09 using ipe and neat cement	
E								grout.	•	
				1						
	30							***************************************		
L	30			1	<u> </u>		<u> </u>	<u> </u>		

BOI	RING N	Ю.:	B4 PROJECT NO.: 0405 PROJECT	AME:	William Wurzba	ch Co.	, 1200	20th Ave.,	. Oakland
во	RING I	LOC	NTION: 20th Avenue southeast side parking lane, at northe	ast corn	er with Solano V	Vay	ELEVAT	FION AND DA	тим: None
	LLING		,	RILLER:	Justin/Jeremy	DATE	4/6/0		DATE & TIME FINISHED: 4/6/09 1300
			UIPMENT: Geoprobe 6600				LOGGE		CHECKED BY:
CO	MPLET	TION	DEPTH: 25.0 Feet BEDROCK DEPTH: N		ıntered		ML		CHECKED BY:
FIR		TER	DEPTH: 21.0 Feet NO. OF SAMPLES: 6	Soil T	7	ļ		· · · · · · · · · · · · · · · · · · ·	
DEPTH (FT.)			DESCRIPTION	GRAPHIC	WELL CONSTRUCTION LOG	BLOW COUNT PER 6"	B		REMARKS
			0.0 to 0.5 ft. Concrete (3-in.) and base rock.  0.5 to 6.0 ft. Orange-brown gravelly silty sand (SM); medium dense, dry, with angular gravel to 0.5-in. diameter. No Petroleum Hydrocarbon (PHC) odor.  3.5 to 6.0 ft. Bluish green staining and	SM	No Well Constructed B4-2.5	***************************************	0	using a 5-fi Geoprobe I sampler lin 1.5-inch O sleeves.	ontinuously cored oot long 2.0-inch O.D. Macrocore barrel ed with 4.8-foot long .D. transparent PVC
	5		6.0 to 10.5 ft. Bluish green and brown silty clay (CL),		B4-4.5		101	5 to 10 ft. 4	4.4 ft. recovery 4.6 ft. recovery 4.6 ft. recovery 4.2 ft. recovery 6.4.2 ft. recovery
	10		stiff, moist. Strong PHC odor.  9.0 to 10.5 ft. With gravel to 0.25-in. diameter.	CL	B4-9.5		345	20 to 25 ft	
	10		10.5 to 11.0 ft. Bluish green gravelly clayey sand (SC); medium dense, moist. Strong PHC odor.  11.0 to 13.0 ft. Olive-green silty clay (CL); stiff, moist, withbluish green staining, and orange mottling. Slight PHC odor.	SC			3	Borehole t 4/6/09. To well not p	erminated at 25.0 ft. on emporary 1-in. diameter laced in borehole, and no ple collected.
	15		13.0 to 14.0 ft. Brown gravelly clayey sand (SC); medium dense, moist, with gravel to 0.25-in. diameter. Strong PHC odor.  14.0 to 21.0 ft. Brown silty clay (CL); stiff, moist, with bluish green staining, trace angular gravel to 0.25-in. diameter, and black mottling.  Strong PHC odor.	SC SC	B4-14.5		77		grouted on 4/9/09 using ipe and neat cement
			Strong FRC duot.	CL	, .				
	20		21.0 to 25.0 ft. Grayish brown gravelly silty sand (SM):	<u>x</u>	B4-19.5		65		
			loose, wet to saturated, with angular gravel to 0.5-in. diameter. Moderate PHC odor.	SM			3	****	
	25		24.0 to 25.0 ft. No PHC odor.	x	B4-24.5		0		
	30								

вов	RING N	ю.:	B4a PROJECT NO.: 0405 PROJECT N	ame: V	Villiam Wurzba	ch Co.	, 1200	20th Ave.,	Oakland
воі	RING I	LOC	ATION: 3 feet north of borehole B4				ELEVAT	TION AND DA	тим: None
	LLING		ENCY: Vironex, Inc. DI UIPMENT: Geoprobe 6600	RILLER:	Justin/Jeremy	DATE	& TIME 4/7/0 100		DATE & TIME FINISHED: 4/7/09 1430
				+ Engan	mtana d		LOGGE		CHECKED BY:
					nterea		ML		C.12C.12C 2.1.
FIR		TER	DEPTH: 21.0 Feet NO. OF SAMPLES: NO.	FSAMPLES: None					
DEPTH (FT.)			DESCRIPTION	GRAPHIC COLUMN	WELL CONSTRUCTION LOG	BLOW COUNT PER 6" PID			REMARKS
	5		0.0 to 0.5 ft. Concrete (3-in.) and base rock.  0.5 to 5.5 ft. Orange-brown gravelly silty sand (SM); medium dense, dry, with angular gravel to 0.5-in. diameter. No Petroleum Hydrocarbon (PHC) odor.  3.5 to 5.5 ft. Bluish green staining and strong PHC odor.	SM	No Well Constructed		119	using a 5-f Geoprobe sampler lin 1.5-inch O sleeves. 0 to 5 ft. 4	ontinuously cored oot long 2.0-inch O.D. Macrocore barrel led with 4.8-foot long .D. transparent PVC
			5.5 to 10.5 ft. Bluish green and brown silty clay (CL); stiff, moist, with some angular gravel to 0.25-in. diameter. Strong PHC odor.	CL			94	5 to 10 ft.	4.6 ft. recovery
	10		10.5 to 11.0 ft. Bluish green gravelly clayey sand (SC); medium dense, moist. Strong PHC odor.  11.0 to 16.0 ft. Olive-green silty clay (CL); stiff, moist, withbluish green staining. Slight PHC odor.	SC			25	10 to 15 ft	4.6 ft. recovery
	15		16.0 to 16.5 ft. Brown clayey sand (SC); medium dense, moist, with bluish green staining. Strong PHC odor.  16.5 to 19.0 ft. Brown silty sand (SM); medium dense,	SC			77	15 to 20 ft	4.7 ft. recovery
	20		moist, with bluish green staining. Strong PHC odor.  19.0 to 24.5 ft. Reddish brown gravelly clayey sand— (SC); loose, moist, with bluish green staining, and angular gravel to 0.5-in. diameter. Strong PHC odor.  21.0 ft. Wet to saturated.	y SC			251	20 to 25 ft	:. 3.6 ft. recovery
	25		24.5 to 32.5 ft. Brown silty clay (CL); stiff, moist, with orange mottling. No PHC odor.  27.0 to 30.0 ft. With angular gravel to 0.5-in. diameter.	CL	The second secon		0	25 to 30 f	t. 3.8 ft. recovery
E	30							***************************************	

ВОР	RING N	0.:	B4a PROJECT NO.: 0405 PROJECT NA	me: W	/illiam Wurzbac	ch Co.	, 1200	20th Ave.,	Oakland
BO	RING L	.oc/	ATION: 3 feet north of borehole B4				ELEVAT	TON AND DA	тим: None
	LLING		ENCY: Vironex, Inc. BE	BILLER:	Justin/Jeremy	4/7/09 1000			date & time finished: 4/7/09 1430
	***************************************			t Encou	ntered	LOGGED BY:			CHECKED BY:
			DEPTH: 70.0 Feet BEDROCK DEPTH: NO DEPTH: 21.0 Feet NO. OF SAMPLES: NO		IHCICU	MLD			
FIR		TER	DEFIN: 21.0 1 CCt NO. OF SAMPLES: 100	i	<u> </u>	<u> </u>			
	DEPTH (FT.)		DESCRIPTION	GRAPHIC COLUMN	WELL CONSTRUCTION LOG	BLOW COUNT PER 6"	GIA		REMARKS
			24.5 to 32.5 ft. Brown silty clay (CL); stiff, moist, with orange mottling. With blue-green staining and strong PHC odor 30.0 to 32.5 ft.	CL	No Well Constructed	***************************************	268	30 to 35 ft	4.2 ft. recovery
<u>-</u>			32.5 to 33.5 ft. Olive-brown clayey sand (SC); medium dense, moist, with angular gravel to 0.5-in. diameter. Slight PHC odor.  33.5 to 34.5 ft. Brown fine sand (SP); loose, moist. Slight PHC odor.	SC SP			8		
	35		34.5 to 42.0 ft. Brown silty clay (CL); stiff, moist, with black mottling. NoPHC odor.				0	35 to 40 ft	. 2.8 ft. recovery
				CL				***************************************	
	40		·		- Antier and a second			40 to 45 ft	. 3.2 ft. recovery
			42.0 to 44.5 ft. Brown fine sand (SP); loose, saturated.— Slight PHC odor.	SP			30		
	45		44.5 to 49.5 ft. Brown clayey sand (SC); loose, saturated, with interbeds of fine sand (SP).  Slight PHC odor.	SC/ SP	Transmission and the state of t		3	45 to 50 ft	. 4.2 ft. recovery
	50		49.5 to 51.5 ft. Orange-brown gravelly clayey sand					50 to 55 f	t, 3.6 ft. recovery
			diameter. Slight PHC odor.  51.5 to 53.0 ft. Brown fine sand (SP); loose, saturated.—	SC			7		
			Slight PHC odor.  53.0 to 55.0 ft. Orange-brown gravelly clayey sand (SC); dense, moist, with angular gravel to 0.5-in.  diameter. No PHC odor.	sc			0		
	55		55.0 to 59.0 ft. Light grayish brown clayey sand (SC); loose, saturated, with interbeds of fine sand (SP).  No PHC odor.	SC/ SP			0	55 to 60 f	t. 4.2 ft. recovery
	60°		59.0 to 60.0 ft. Light grayish brown sandy clay (CL);_stiff, moist. No PHC odor.	CL			0	-	

BOR	ung n	:.0	B4a project no.: 0405 project n	ame: V	Villiam Wurzba	ch Co.	, 1200	20th Ave.,	Oakland
BOF	RING I	LOC	ATION: 3 feet north of borehole B4				ELEVA	TION AND DA	тим: None
			ENCY: Vironex, Inc. D	RIELER:	Justin/Jeremy	DATE	4/7/ 100		DATE & TIME FINISHED: 4/7/09 1430
				+ Encou	entara d		LOGGI		CHECKED BY:
			N DEPTH: 70.0 Feet BEDROCK DEPTH: NO. OF SAMPLES: NO.	·····	nitered	MLD			
rina		T	perin: 21.01cct No.075Antres: 140		7	 	***************************************		
DEPTH (FT.)			DESCRIPTION	GRAPHIC COLUMN	WELL CONSTRUCTION LOG	BLOW COUNT PER 6"	GIA	REMARKS	
			60.0 to 64.5 ft. Brown fine sand (SP); loose, saturated.  No PHC odor.	SP	No Well Constructed		0	60 to 65 ft	. 4.2 ft. recovery
	65		64.5 to 65.5 ft. Grayish brown clay (CL); stiff, moist No PHC odor.	CL	**************************************		0	65 to 70 ft	. 2.8 ft. recovery
			65.5 to 67.0 ft. Brown clayey sand (SC); loose, saturated, with interbeds of fine sand (SP).  No PHC odor.	sc			0		
			67.0 to 70.0 ft. Olive-green clay (CL); stiff, moist.  No PHC odor.	CL			0	Water enc	ountered during drilling
_	70					<del>                                     </del>			erminated at 70.0 ft. on
_								Borehole p a tremie p grout.	grouted on 4/7/09 using ipe and neat cement
					· ·			east of bou	ion approximately 3 ft. rehole B4, a soil condrobe was pushed to 70 ft. for electrical conducting. Borehole grouted using a tremie pipe and ont grout.
							TO THE PROPERTY OF THE PROPERT	northeast punch wa 4/9/09. H was confi water lev- punch dri level in th rods was 1330, and Water sar 1345; no Water lev in Hydroj 1529. H	ion approximately 4 ft. of borehole B4, a Hydro s pushed to 65.0 ft. on lydropunch seal integrity rmed using electrical el indicator. The Hydrolling rods were then to 61.0 ft. The water ne Hydropunch measured at 64.7 ft. at 1 at 63.5 ft. at 1340. nple B4W-65 collected a odor or sheen on sample el subsequently measure punch rods at 61.8 ft. at /dropunch borehole in 4/9/09 using a tremie

BOR	ING N		B5 PROJECT NO.: 0405 PROJECT	NAN	1E: V	/illiam Wurzbac	h Co.	, 1200	20th Ave.,	Oakland
BOE	UNG L	юса	ATION: 8 feet northeast of borehole B4					ELEVAT	ION AND DA	тим: None
	LLING			D	RILLER	Justin	DATE	& TIME 4/6/0 0955	19	DATE & TIME FINISHED: 4/6/09 1300
				Tat	Empar	mtowed		LOGGE		CHECKED BY:
				Not Encountered 7 Soil				ML		
FIR							T			
DEPTH (FT.)			DESCRIPTION		COLUMN	WELL CONSTRUCTION LOG	BLOW COUNT PER 6" PID			REMARKS
	_		0.0 to 0.5 ft. Concrete (3-in.) and base rock.  0.5 to 5.0 ft. Orange-brown gravelly silty sand (SM); medium dense, dry, with angular gravel to 0.5-in. diameter. No Petroleum Hydrocarbon (PHC) odor.  2.5 to 5.0 ft. Soil stained bluish green; strong PHC odor.	x	SM	No Well Constructed B5-2.0 B5-4.5	***************************************	0 2 47	using a 5-1 Geoprobe sampler lii 1.5-inch C sleeves. 0 to 5 ft. 4	continuously cored foot long 2.0-inch O.D. Macrocore barrel ned with 4.8-foot long O.D. transparent PVC
<u></u>	5		5.0 to 7.0 ft. Bluish green silty clay (CL); medium stiff, moist. Strong PHC odor.		CL			0	5 to 10 ft.	4.6 ft. recovery
			7.0 to 8.0 ft. Bluish green gravelly clayey sand (SC); medium dense, moist. Strong PHC odor.  8.0 to 9.5 ft. Bluish green silty clay (CL); medium stiff, moist. Strong PHC odor.		SC CL					
	10		9.5 to 14.5 ft. Bluish green silty sand (SM); medium dense, moist, with trace angular gravel to 0.25-in. diameter. Strong PHC odor.	<u>×</u>	SM	B5-9.5		113	10 to 15 f	t. 4.6 ft. recovery
	15		14.5 to 16.0 ft. Bluish green to orange-brown gravelly clayey sand (SC); medium dense, moist, with gravel to 0.5-in. diameter. Slight PHC odor.	×	SC	B5-14.5		28	15 to 20 f	t. 4.5 ft. recovery
			16.0 to 23.0 ft. Bluish green fine sand lenses (SP), loose, moist; interbedded with gravelly sand (SW), loose, moist. Slight PHC odor.		<b>an</b> .	n-control manual 4		26		
	20		19.5 to 25.0 ft. Color change to orange-brown, with no PHC odor, and gravel to 0.5-in. diameter. 20.0 ft. Wet.	x	SP/ SW ∑	B5-19.5		0	20 to 25	ft. 4.6 ft. recovery
			23.0 to 25.0 ft. Orange-brown gravelly clayey sand (SC);	x	60	B5-22.5		0		
	25		medium dense, moist, with angular gravel to 0.5-in. diameter. No PHC odor.	x	SC	B5-24.5		0	drilling a	est encountered during at 20.0 ft.
									well not	Temporary 1-in. diameter placed in borehole and no mple collected.
									Borehole a tremie grout.	e grouted on 4/6/09 using pipe and neat cement
	30	*****	-					<u> </u>		

BOF	ING N	ю.:	B6 PROJECT NO.: 0405 PROJECT NA	ME: V	Villiam Wurzbac	h Co.	, 1200	20th Ave.,	. Oakland
воз	RING I	LOC	ATION: 12 feet northeast of borehole B5				ELEVAT	TION AND DA	тим: None
				DRILLER	: Justin	DATE	& TIME 4/6/( 083		
DRI	LLINC	G EQ	uipment: Geoprobe 6600				•		CHECKED BY:
CO	MPLET	rio»	вретн: 25.0 Feet вергоск дертн: No			LOGGED BY: MLD			CHECKED B1.
FIR	ST WA	TER	DEPTH: Not Encountered NO. OF SAMPLES: 5 S	Soil, 1 V					
ОЕРТН (FT.)			DESCRIPTION	GRAPHIC COLUMN	WELL CONSTRUCTION LOG	BLOW COUNT PER 6"	CIIA		REMARKS
			0.0 to 0.5 ft. Concrete (3-in.) and base rock.  0.5 to 4.5 ft. Orange-brown gravelly silty sand (SM); medium dense, dry, with angular gravel to 0.5-in. diameter. No Petroleum Hydrocarbon (PHC) odor.	SM CL/	No Well Constructed	***************************************	0	using a 5-f Geoprobe sampler lir 1.5-inch O sleeves.	continuously cored cort long 2.0-inch O.D. Macrocore barrel ned with 4.8-foot long o.D. transparent PVC
	5		interbeds of gravelly clayey sand (\$C), medium dense, moist, with angular gravel to 0.5-in. diameter. No PHC odor.  5.5 to 7.5 ft. Olive-green silty clay (CL); stiff, moist, with trace angular gravel to 0.25-in. diameter. No PHC odor.	CL	150-4.5	***************************************	0	5 to 10 ft.	4.6 ft. recovery
	10		7.5 to 10.0 ft. Olive-green sandy clayey gravel (GC); moist, with angular gravel to 0.75-in. diameter. No PHC odor.  10.0 to 21.5 ft. Olive-green and brown clay (CL); medium stiff, moist. No PHC odor.	GC	B6-9.5		0	10 to 15 ft	4.5 ft. recovery
	15			CL	B6-14.5			15 to 20 fi	t. 4.6 ft. recovery
	20				B6-19.5		0		t. 4.7 ft. recovery
	-		21.5 to 22.0 ft. Brown gravelly clayey sand (SC); loose, moist, with angular gravel to 0.25-in. diameter. No PHC odor.  22.0 to 25.0 ft. Olive-green and brown clay silty (CL), medium stiff, moist. No PHC odor.	SC V CL			0	Borehole 4/6/09. I slotted P hole. Wa ft. at 094	terminated at 25.0 ft. on femporary 1-in. diam. VC casing placed in bore ater level measured at 23. 0, and at 23.0 ft. at 0950. mple B6-W collected at
	25				B6-24.5			1040: 5 N container odor or s porary w further re 1-liter ar B6-W co no odor	VOA and 1 1-liter amber rs, very slow recharge; no heen on sample. Tem-rell capped to allow for scharge. One additional objected at 1510 on 4/7/05 or sheen on sample.
	30	_	-						pipe and neat cement

	RING N		B7 PROJECT NO.: 0405 PROJECT	ΓNAN	1E; V	Villiam Wurzbac	h Co.,	1200	20th Ave.,	Oakland
BOI	RING I	LOCA	ATION: Approximately 15 ft. west of southeast corner of	20tl	ı Aven	ue and Solano	Way	ELE	VATION AND	datum: None
			ENCY: Vironex, Inc. UIPMENT: Geoprobe 6600	DRII	LLER:	Justin/Jeremy	DATE	& TIME 4/6/( 144		DATE & TIME FINISHED: 4/6/09 1525
	-		0.70	Niot i	Engon	ntarad		LOGGE	<u> </u>	CHECKED BY:
	-					morea	MLD			
rin.		TEN	DET IN NOT EMOCRATED AND ASSESSMENT OF SAME BESS.	SAMPLES: 2 Water			E			*
	DEPTH (FT.)		DESCRIPTION		GRAPHIC	WELL CONSTRUCTION LOG	BLOW COUNT PER 6"	PID		REMARKS
	5		0.0 to 0.5 ft. Asphalt and base rock.  0.5 to 7.0 ft. Grayish brown clayey silt (ML); medium stiff, moist, with orange mottling.  No Petroleum Hydrocarbon (PHC) odor.		ML	No Well Constructed		0	using a 5-fi Geoprobe is sampler lin 1.5-inch O sleeves. 0 to 5 ft. 4 5 to 10 ft.	ontinuously cored out long 2.0-inch O.D. Macrocore barrel ed with 4.8-foot long .D. transparent PVC  5 ft. recovery  4.4 ft. recovery
	10		7.0 to 11.0 ft. Light gray silty clay (CL); medium stiff, moist, with black mottling. No PHC odor.		CL			0	20 to 25 ft Water not drilling.	4.8 ft. recovery 4.8 ft. recovery encountered during
			11.0 to 14.0 ft. Orange-brown gravelly clayey sand (SC); medium dense, moist, with angular gravel to 0.5-in. diameter. No PHC odor.		sc			0	4/6/09. Te slotted PV borehole. Temporary glove and for recharg	erminated at 25.0 ft. on mporary 1-in. diam. C casing placed in Borehole dry at 1530. v well capped with Latex bentonite plug to allow ge. On 4/7/09, water
	15		<ul><li>14.0 to 25.0 ft. Light gray silty clay (CL); stiff, moist, with orange mottling. No PHC odor.</li><li>16.0 to 17.5 ft. With some gravel to 0.25-in. diameter.</li></ul>					0	Water sam	pured at 16.0 ft. at 1335. ple B7W collected at dor or sheen on sample. grouted on 4/7/09 using e and neat cement grout.
	20		21.0 to 21.3 ft. 3-in. thick interbed of gravelly sand with angular gravel to 0.5-in. diamater.		CL	, the same of the	- PARAMETER - PARA	0	north of the continuous soil conductive onductive grouted or	on approximately 3 ft. as borehole that was sly cored to 25.0 ft., a scrivity probe was pushed a 4/6/09 for electrical ity logging. Borehole a 4/6/09 using a tremie leat cement grout.
	25								south of the continuous 4/6/09, and to 64.0 ft.	ion approximately 4 ft. he borehole that was isly cored to 25.0 ft. on Hydropunch was pushed on 4/9/09. Hydropunch rity was confirmed using
	30							0	electrical The Hydr were then water lev rods was 1514, and Water sar 1545; no Borehole	water level indicator. opunch drilling rods i retracted to 60.0 ft. The lin the Hydropunch measured at 59.7 ft. at 1 at 56.3 ft. at 1524. nple B7W-64 collected a odor or sheen on sample grouted on 4/6/09 using pe and neat cement grou

BORING	G NO	).;	B8 PROJECT NO.: 0405 PROJECT NO.	me: V	Villiam Wurzbac	h Co.	, 1200	20th Ave.,	Oakland
BORING	G LC	OCA	TION: 27 feet southwest of Solano Way on southwest side	le of 20	th Avenue		ELEVAT	TON AND DA	тим: None
DRILLI			ENCY: Vironex, Inc. DI	RILLER:	Justin/Jeremy	DATE	4/8/0 083	-	DATE & TIME FINISHED: 4/8/09 0930
			DEPTH: 30.0 Feet BEDROCK DEPTH: No	t Encor	intered		LOGGE	D BY:	CHECKED BY:
				Vater		MLD			
					Z	<u> </u>			
DEPTH (FT.)			DESCRIPTION	GRAPHIC COLUMN	WELL CONSTRUCTION LOG	BLOW COUNT PER 6"	BLOW COUNT PER 6"		REMARKS
5 10			0.0 to 0.5 ft. Asphalt and base rock.  0.5 to 4.0 ft. Light grayish brown silt (ML); medium stiff, moist, with black and orange mottling. No Petroleum Hydrocarbon (PHC) odor.  3.5 to 4.0 ft. With angular gravel to 0.25-in. diamater.  4.0 to 5.5 ft. Orange-brown silty sand (SM); loose, moist, with abundant angular gravel to 0.25-in. diameter. No PHC odor.  5.5 to 8.5 ft. Light grayish brown silt (ML); medium stiff, moist, with black mottling. No PHC odor.  8.5 to 11.0 ft. Orange-brown silty sand (SM); medium dense, moist, with abundant angular gravel to 0.5-in. diameter. No PHC odor.  11.0 to 12.0 ft. Olive-brown clay (CL); medium stiff, moist, with some angular gravel to 0.25-in. diameter. No PHC odor.  12.0 to 14.5 ft. Orange-brown clayey sand (SC); medium dense, moist, with some angular gravel to 0.5-in. diameter, and orange mottling. No PHC odor.  14.5 to 30.0 ft. Orange-brown silty clay (CL); stiff, moist. No PHC odor.	ML SM ML SM CL SC	No Well Constructed		0 0 0 0 0	using a 5-f Geoprobe is sampler lift 1.5-inch O sleeves.  0 to 5 ft. 4 5 to 10 ft.  10 to 15 ft 15 to 20 ft.  20 to 25 ft 25 to 30 ft Water not continuous Borehole t 4/8/09. Te slotted PV borehole. Temporary glove and for recharglevel measund at 28. sample Bi odor or shole grout tremie pip At a locat west of the continuous oil condusoil ontinuously cored oot long 2.0-inch O.D. Macrocore barrel led with 4.8-foot long .D. transparent PVC  5 ft. recovery  4.2 ft. recovery  4.2 ft. recovery  4.5 ft. recovery  4.6 ft. recovery  . 4.6 ft. recovery  . 4.6 ft. recovery  . 4.6 ft. recovery  . 2.6 ft. recovery  . 3.2 ft. recovery  . 4.6 ft. recovery  . 4.6 ft. recovery  . 4.6 ft. recovery  . 4.6 ft. recovery  . 4.6 ft. recovery  . 4.6 ft. recovery  . 2.7 ft. recovery  . 3.2 ft. recovery  . 4.6 ft. recovery  . 4.6 ft. recovery  . 4.6 ft. recovery  . 4.7 ft. on amporary 1-in. diam.  . C casing placed in  Borehole dry at 1150.  y well capped with Later bentonite plug to allow  ge. On 4/9/09, water  sured at 28.8 ft. at 0936,  5 ft. at 1258. Water  sw collected at 1300; no  seen on sample. Bore-  ted on 4/9/09 using a  see and neat cement grout  ion approximately 4 ft.  e borehole that was  sly cored to 30 ft., a  uctivity probe was pushe  n 4/8/09 for electrical	
							0	conductive grouted of pipe and in At a locat south of the borehole,	ity logging. Borehole n 4/8/09 using a tremie neat cement grout. ion approximately 4 ft. he continuously cored a Hydropunch was
	25 30		24.0 to 25.5 ft. With angular gravel to 0.25-in. diameter.  26.0 to 30.0 ft. Brown, with trace gravel to 0.25-in. diameter. No PHC odor.	<b>*</b>			0	pushed to Hydropur firmed us indicator. rods were The wate rods was 1045, and Water sar 1100, no Borehole	59.0 ft. on 4/9/09. nch seal integrity was coing electrical water leve. The Hydropunch drillithen retracted to 55.0 ft. level in the Hydropunmeasured at 55.2 ft. at 1 at 53.1 ft. at 1055. mple B8W-59 collected odor or sheen on sampl grouted on 4/9/09 using the and neat cement ground.

BORING N	Ю.:	B9 project no.: 0405 project na	me: V	illiam Wurzbac	h Co.	, 1200	20th Ave.,	Oakland
BORING I	LOCA	TION: On west side of 20th Avenue 95 feet northeast of	E. 12th	St.		ELEVAT	ION AND DA	тим: None
DRILLING			ILLER:	Justin/Jeremy	DATE	& TIME 4/9/0 0830	-	DATE & TIME FINISHED: 4/9/09 0935
DRILLING	G EQ	лрмент: Geoprobe 6600				LOGGE		CHECKED BY:
COMPLE	TION			ntered		ML		
FIRST WA	TER	DEPTH: Not Encountered NO. OF SAMPLES: 1 V	/ater					<u> </u>
DEPTH (FT.)		DESCRIPTION	GRAPHIC	WELL CONSTRUCTION LOG	BLOW COUNT PER 6"	PID		REMARKS
5 10 15 20 25		0.0 to 1.0 ft. Asphalt and base rock.  1.0 to 5.0 ft. Light gray silt (ML); medium stiff, moist, with trace gravel to 0.25-in. diameter, and blackmottling. No Petroleum Hydrocarbon (PHC) odor.  5.0 to 10.5 ft. Light olive-gray silty clay (CL); stiff, moist, with black and orange mottling. No PHC odor.  6.5 to 8.0 ft. With angular gravel to 0.25-in. diameter.  10.5 to 11.0 ft. Orange-brown clayey sand (SC); medium dense, moist, with gravel to 0.5-in. diameter. No PHC odor.  11.5 to 16.5 ft. Light olive-gray clay (CL); stiff, moist, with trace angular gravel to 0.5-in. diameter, and black mottling. No PHC odor.  16.5 to 17.0 ft. Olive-brown gravelly clayey sand (SC); medium dense, moist, with angular gravel to 0.5-in. diameter. No PHC odor.  17.0 to 22.0 ft. Olive-gray clay (CL); stiff, moist, with minor angular gravel to 0.5-in. diameter. No PHC odor.  22.0 to 23.0 ft. Olive-brown gravelly clayey sand (SC); medium dense, moist, with angular gravel to 0.25-in. diameter. No PHC odor.  23.0 to 26.5 ft. Olive-brown clay (CL); stiff, moist. No PHC odor.	ML  CL  SC  CL  SC  CL	No Well Constructed		0 0 0 0 0 0	using a 5-1 Geoprobe sampler lit. 1,5-inch C sleeves. 0 to 5 ft. 4 5 to 10 ft. 10 to 15 ft 20 to 25 ft 25 to 30 ft Water not drilling. Borehole 4/9/09. T slotted P' borehole. 24.4 ft. a 1415. W ted at 142 but no oc grouted of	continuously cored foot long 2.0-inch O.D. Macrocore barrel ned with 4.8-foot long 0.D. transparent PVC 4.8 ft. recovery 4.8 ft. recovery 4.4 ft. recovery 4.4.6 ft. recovery 4.4.6 ft. recovery 4.4.6 ft. recovery 4.4.6 ft. recovery 4.4.6 ft. recovery 4.4.6 ft. recovery 4.4.6 ft. recovery 4.4.6 ft. recovery 5.4.6 ft. recovery 6.4.6 ft. recovery 6.4.7 ft. recovery 6.4.7 ft. recovery 7.4 ft. 4.5 ft. recovery 6.4.7 ft. recovery 8.4.8 ft. recovery 8.4.8 ft. recovery 8.4.9 ft. recovery 9.4.9
		26.5 to 27.0 ft. Olive-brown gravelly clayey sand (SC); medium dense, moist, with angular gravel to 0.25-in. diameter.  No PHC odor.  27.0 to 30.0 ft. Olive-brown silty clay (CL); stiff, moist. No PHC odor.	SC			0	7.1100	
_ 30	) -	-						

BORING NO.:	B10 PROJECT NO.: 0405.R5 PROJECT N	ame: V	Villiam Wurzba	ch Co.	, 1200	20th Ave.,	Oakland
BORING LOC	ATION: Inside garage, approximately 20 ft. from garage	entrance			ELEVAT	TION AND DA	тим: None
ORILLING AC		RILLER:	Justin	DATE	& TIME 10/5 083		DATE & TIME FINISHED 10/5/09 1000
DRILLING E		t Engay	ntarad	LOGGED BY:			CHECKED BY:
COMPLETIO				MLD			
FIRST WATE	R DEPTH: Not Encountered NO. OF SAMPLES: 7	Soil, 1 V		ļ., ī			<u></u>
DEPTH (FT.)	DESCRIPTION	GRAPHIC COLUMN	WELL CONSTRUCTION LOG	BLOW COUNT PER 6"	ond .		REMARKS
5 -	0.0 to 0.5 ft. Concrete (1-in.) and base rock.  0.5 to 2.0 ft. Olive-brown clay (CL); medium stiff, moist, with black mottling. No Petroleum Hydrocarbon (PHC) odor.  2.0 to 9.0 ft. Olive-brown silt (ML); medium stiff, moist, with minor coarse sand and trace angular gravel to 0.5-in. diameter, and black mottling.  No PHC odor.	CL	No Well Constructed B10-4.5	Callery Control of Con	0	using a 5-1 Geoprobe sampler li 1.5-inch C sleeves. 0 to 5 ft. 4	continuously cored foot long 2.0-inch O.D Macrocore barrel ned with 4.8-foot long 0.D. transparent PVC 4.6 ft. recovery
- 10 -	9.0 to 10.0 ft. Orange-brown silty sand (SM); medium dense, moist, with minor angular gravel to 0.25-in.  diameter. No PHC odor.  10.0 to 16.0 ft. Olive-brown silt (ML); stiff, moist, with some coarse sand, and black mottling.  No PHC odor.	SM	B10-9.5	Linear transfer of the second state of the sec	0	10 to 15 f	t, 4.8 ft. recovery
	-	ML	B10-14.5	A SERVICE TO THE PROPERTY OF T	0	15 to 20 f	t. 4.8 ft. recovery
20	18.5 to 22.5 ft. Olive-brown silty clay (CL); stiff, moist, with some angular gravel to 0.5-in. diameter, and orange and black mottling.  No PHC odor.	CL	B10-19.5		0	20 to 25	ft. 4.6 ft. recovery
25	22.5 to 23.5 ft. Brown clayey fine sand (SC); medium dense, moist. No PHC odor.  23.5 to 35.0 ft. Olive-brown clay (CL); very stiff, moist, with black mottling.  No PHC odor.	SC × CL	B10-24.5	ANTER CONTRACTOR OF THE PROPERTY OF THE PROPER	0	25 to 30	ft. 4.8 ft, recovery
		×	B10-29.5	ATTACATION AND AND AND AND AND AND AND AND AND AN	0	- Military Company	

(Continued on page 2.)

BORING I	NO.:	B10 PROJECT NO.: 0405.R5 PROJEC	T NA	ME: V	/illiam Wurzbac	h Co.	, 1200	20th Ave.,	Oakland
BORING	LOC	ATION: Inside garage, approximately 20 ft. from gara	ge ei	ntrance			ELEVAT	ION AND DA	тим: None
DRILLIN		ency: Vironex, Inc.	DR	ILLER:	Justin	DATE	& TIME 10/5/ 083		date & time finished: 10/5/09 1000
			Not	Encou	ntered		LOGGE		СНЕСКЕЙ ВУ:
				oil, 1 W		MLD			
	ATER	R DEPTH: Not Encountered NO. OF SAMPLES:	73			<u> </u>			1
DEPTH (FT.)		DESCRIPTION	GRAPHIC		WELL CONSTRUCTION LOG	BLOW COUNT PER 6"	DID		REMARKS
35		(Continued from page 1.)  23.5 to 35.0 ft. Olive-brown clay (CL); very stiff, moist, with black mottling.  No PHC odor.	X	CL	No Well Constructed  B10-34.5		0	Water not drilling. Borehole to 10/5/09, To slotted PV borehole. Water leve 1030, and Water sam 1100; 3 V	encountered during erminated at 35.0 ft. on Temporary 1-in. diameter C casing placed in Borehole dry at 1000. el measured at 33.9 ft. at at 33.7 ft. at 1053. uple B10-W collected at OA containers collected. grouted on 10/5/09 emie pipe and neat rout.
							The second secon	especially and the second seco	