FILE OR PER NO. | ENVELOPE No. ____ of ____

☐ OWNER Pacific Cryogenic
Address 2311 Magnolia St.
Oak 607 Phone

☐ Contractor
Address
Phone

☐ OTHER (Specify) Hageman-Aguiar
Address 284-1661 Gary Aguiar
Phone

☒ CONTACT FOR INVESTIGATION

PLAN REVIEW	By	Date
$ Rec'd.		
No. Plans Rec'd.		
Plans Approved		
Layout Made		
Rejected		
Applicant Notified		
Plans Returned		
Permit Issued		
CONSTRUCTION PROGRESS ACCEPTANCE		
FOOD Pre-Plaster/drywall		
Pre-Final		
Final		

	By	Date
ROOL Pre-Concrete/Gunite		
Pre-Plaster		
Final		
EXCAVATION Septic Tank		
Absorption Field		
Absorption Bed		
FINAL House Sewer		
Septic Tank		
Absorption Field		
Absorption Bed		
OTHER		

U.G. TANKS Pre-Covering
Final

LOP 1211 B →

Closed

XR

REMARKS

Date	By	
4-20-93	JE	Rcv'd 3-8-93 QR by H-A. Piping excavation was backfilled. SP still remains onsite. 3 backfill mws (#4-6) were installed for future in-situ treatment. Gw sampled on 1-7-93 flowed SE. Gw has up to 4800 ppb TPHg + 6.4 ppb benz (MW-4). No recommendations. The dissolved [illegible]s seem

REMARKS

Date	By	
		centered around the piping leak.
4-23	JE	Spoke w/Gary Aguiar. No plan for in-situ remed. yet. SE gw flow. They just sampled gw this wk. I should get QR in ~3 wks. SP still onsite.
6-4	JE	Reviewed 5-24-93 QR by HA. Gw sampled on 4-23-93 flowed SE. Gw has up to 21,000 ppb TPH-g + 23 ppb benz (MW-3); both are big↑s, altho water

LOCATION

Vicinity Map

table dropped in MW3

8-23 Reviewed 8-2 QR by H-A. Gw sampled on 7-16-93 flowed E. Up to 16,000 ppb TPHg + 19 ppb benz (MW-3). Spoke w/Gary Aguiar. No same plan. RP needs a letter. SP still onsite. Wrote letter to RP.

2311 Magnolia St
Oakland CA 94607
PACIFIC CRYOGENIC

FILE OR PER NO.] ENVELOPE No.____ of____

☐ OWNER Pacific Cryogenic
Address 2311 Magnolia St.
Oak 607 Phone

☐ Contractor
Address H-A 284-1661
Phone

☐ OTHER (Specify)
Address
Phone

☒ CONTACT FOR INVESTIGATION

PLAN REVIEW	By	Date
$ Rec'd.		
No. Plans Rec'd.		
Plans Approved		
Layout Made		
Rejected		
Applicant Notified		
Plans Returned		
Permit Issued		
CONSTRUCTION PROGRESS ACCEPTANCE		
FOOD: Pre-Plaster/drywall		
FOOD: Pre-Final		
FOOD: Final		

		By	Date
POOL	Pre-Concrete/Gunite		
POOL	Pre-Plaster		
POOL	Final		
EXCAVATION	Septic Tank		
EXCAVATION	Absorption Field		
EXCAVATION	Absorption Bed		
FINAL	House Sewer		
FINAL	Septic Tank		
FINAL	Absorption Field		
FINAL	Absorption Bed		
OTHER			

LOP 1211 C

U.G. TANKS	Pre-Engineering	Date
	Final	

XR

REMARKS

Date	By	
3-23-94	JE	Reviewed 2-3-94 QR by H-A. Gw sampled on 1-28-94. Gw flowed E on 2-2-94. Must follow up on disposal of purge water. DC MW3 has biggest hits (7,500 ppb TPHg, 8.5 ppb benz, 3½ TPHd + 370 TPH-ms).

REMARKS

Date	By	
		See inside notes

LOCATION

Vicinity Map

REMARKS			REMARKS			REMARKS		
Date	By		Date	By		Date	By	
~~11-19-93~~ 12	JE	Reviewed 10-8-93 wp for Hydropunches by H-A. Looks good. Sp w/Gary. Wrote RP acceptance letter.						
2-17-94	JE	reviewed 12-8-93 QR + Report of Subsurf. Invest. by H-A. Gw sampled 11-8-93 flowed SE. MW3 has biggest hits. They defined gw contam. w/ the HPs. (Fig 5).						