

ALAMEDA COUNTY, DEPARTMENT OF ENVIRONMENTAL HEALTH

80 Swan Way, #200
Oakland, CA 94621
(415) 271-4320

Hazardous Materials Division Inspection Form

1:00-

Site ID# _____ Site Name Pacific Cryogenic Today's Date 11/12/97
 Site Address 2311 Magnolia St. EPA ID# _____
 City Oakland Zip 94607 Phone _____

MAX Amt. Stored > 500lbs/55g/200cf? Y N
 Hazardous Waste generated per month? _____

Inspection Categories:

- I. Haz. Mat/Waste GENERATOR/TRANSPORTER
- II. Business Plans, Acute Hazardous Materials
- III. Underground Tanks Piping removal

The marked items represent violations of the Calif. Administration Code (CAC) or the Health & Safety Code (HS&C)

I.A GENERATOR (Title 22)

	1. Waste ID	* 66471
	2. EPA ID	66472
	3. > 90 days	66508
	4. Label dates	66508
	5. Biennial	66493
Manifest	6. Records	66492
	7. Correct	66484
	8. Copy sent	66492
	9. Exception	66484
	10. Copies Rec'd	66492
Misc.	11. Treatment	66371
	12. On-site Disp. (H.S.&C.)	26189.5
	13. Ex Haz. Waste	66570
Prevention	14. Communications	67121
	15. Aisle Space	67124
	16. Local Authority	67126
	17. Maintenance	67120
	18. Training	67105
Confin. Agency	19. Prepared	67140
	20. Name List	67141
	21. Copies	67141
	22. Emg. Coord. Trng.	67144
Containers, Tanks	23. Condition	67241
	24. Compatibility	67242
	25. Maintenance	67243
	26. Inspection	67244
	27. Buffer Zone	67246
	28. Tank Inspection	67259
	29. Containment	67245
	30. Safe Storage	67261
	31. Freeboard	67257

Comments:

Removal of piping + sampling ^{from dispenser}.
 Two lengths of piping. One went to the gas tank, + one was the fill pipe for waste oil tank. Both pipes were rusty. Holes at various lengths were noted in w. oil pipe, which still had waste oil inside. Photo of hole taken. Excavated soil beneath pipe to a depth of 36". Also found a hole in gas pipe at same location of hit in soil below pipe. Soil here is greenish + odor of gas. Continued to excavate trench to ~6' bgs at end on Union St. Trench samples (two) taken at ~3' bgs.

I.B TRANSPORTER (Title 22)

	32. Applic./Insurance	66428
	33. Comp. Cert./CHP Insp.	66448
	34. Containers	66465
Manifest	35. Vehicles	66465
	36. EPA ID #s	66531
	37. Correct	66541
	38. HW Delivery	66543
	39. Records	66544
Cont'rs	40. Name/ Covers	66545
	41. Recyclables	66800

Rev 6/88

Contact: HACEMAN - AQUAR, INC.
 Title: Owner
 Signature: [Signature]

Inspector: Jennifer Eberle
 Signature: [Signature]



11-12-92 Pacific Cryogenic
holes 2811 Magnolia St., Oakland
in piping (in pink) Geberle 94607