



April 1, 1999

Stid 1129

Mr. David B. De Witt Tosco Marketing Company 2000 Crow Canyon Place, Suite 400 San Ramon, CA 94583 ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION (LOP) 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

RE: Waste Oil Underground Storage Tank Removal at Tosco 76 Branded Facility No. 11122, 3101 98th Ave., Oakland, CA.

Dear Mr. De Witt:

This office has assigned me to oversee the above case. I have received and reviewed the "Waste Oil Tank Removal Report" dated March 4, 1999 submitted by Gettler-Ryan Inc. regarding the above referenced site. This report indicates that the concentrations of chemicals in soil are all below ND or at low levels. However, the concentrations of the heavy metals are of concern. I discussed this issue with Mr. David J. Vossler of Gettler-Ryan Inc. as well.

This office suggests the following:

- Perform a leachibility test on W01(10) and Comp WO soil samples, if there are still some remaining soil samples available. If there is no more remaining soil sample available, take couple of samples from the same area at the same height, to maintain consistency with the previous results, and perform a leachibility "WET" test to evaluate the STLC values. If the STLC values are not exceeded, the case may not be reconsidered as a LOP case. However, if the STLC values are exceeded, then this office will reevaluate the situation regarding the above referenced site.
- Please submit a report regarding the above activity to this office within 30 days from the receipt of this letter.

This is a formal request for technical information and hence any delays should be requested in writing.

If you have any questions, please call me at (510) 567-6876.

Sincerely,

Amir K. Gholami, REHS

Hazardous Materials Specialist

C: Mr. David J. Vossler, Project Manager, Gettler-Ryan Inc., 6747 Sierra Court, Suite J, Dublin, CA 94568 Files