

June 20, 1995

QUARTERLY GROUNDWATER MONITORING REPORT JUNE 2, 1995 GROUNDWATER SAMPLING ASE JOB NO. 2750 a t

2425 Central Avenue Alameda, California

Submitted by:
AQUA SCIENCE ENGINEERS, INC.
2411 Old Crow Canyon Road, #4
San Ramon, CA 94583
(510) 820-9391

SO MAIST PARIS: DE

1.0 INTRODUCTION

This report outlines the methods and findings of Aqua Science Engineers, Inc. (ASE)'s quarterly groundwater sampling at the property located at 2425 Central Avenue in Alameda, California (Figures 1 and 2).

2.0 GROUNDWATER SAMPLING

On June 2, 1995, ASE measured the depth to groundwater in the site well The well was then purged of four using an electric water level sounder. well casing volumes of groundwater using a pre-cleaned PVC pump. pH, temperature and conductivity of the purge water were monitored during evacuation, and groundwater samples were not collected until these Groundwater samples were then collected from the parameters stabilized. well with a disposable polyethylene bailer. The samples were decanted from the bailer into four (4) 40-ml volatile organic analysis (VOA) vials, preserved with hydrochloric acid, labeled, placed in protective foam sleeves, and stored on wet ice for transport to American Environmental Network (AEN) of Pleasant Hill, California (CSDHS #1172) under chain of custody. No odors were present in the groundwater at the time of the sampling.

Well sampling purge water was contained in DOT 17H drums and stored on-site for handling by the client at a later date. See Appendix A for a copy of the well sampling field log.

3.0 ANALYTICAL RESULTS FOR GROUNDWATER

The groundwater samples were analyzed by AEN for total petroleum hydrocarbons as gasoline (TPH-G) by modified EPA Method 8015, benzene, toluene, ethylbenzene and total xylenes (BTEX) by EPA Method 8020 and dissolved lead by EPA Method 6010. The analytical results are tabulated below in Table One, and the certified analytical report and chain of custody form are included in Appendix B. No hydrocarbons were detected in the groundwater samples.

TABLE ONE
Summary of Chemical Analysis of GROUNDWATER Samples
All Results are in parts per billion

Well I.D.	Date of Sampling	TPH Gasoline	Benzene	Toluene	Ethyl Benzene	Total Xylenes	Dissolved Lead
MW-1	03-13-95 06-02-95	<50 <50	0.6 <0.5	2 <0.5	<0.5 <0.5	2 <2	<40 <40
EPA METHO)D	5030/ 8015	8020	8020	8020	8020	6010

4.0 CONCLUSIONS AND RECOMMENDATIONS

No hydrocarbons were detected in the groundwater samples collected from monitoring well MW-1 this quarter. ASE recommends continuing the quarterly groundwater monitoring program. If no hydrocarbons are detected above California Department of Toxic Substances Control (DTSC) maximum contaminant levels (MCLs) for drinking water during the next two sampling periods, then ASE will recommend applying for site closure.

5.0 REPORT LIMITATIONS

The results of this assessment represent conditions at the time of the groundwater sampling, at the specific locations at which the samples were collected, and for the specific parameters analyzed for by the laboratory.

It does not fully characterize the site for contamination resulting from unknown sources, or for parameters not analyzed for by the laboratory. All of the laboratory work cited in this report was prepared under the direction of an independent CSDHS certified laboratory. The independent laboratory is solely responsible for the contents and conclusions of the chemical analysis data.

-2-

Aqua Science Engineers appreciates the opportunity to assist you with your environmental needs. Should you have any questions or comments, please feel free to call us at (510) 820-9391.

Respectfully submitted,

AQUA SCIENCE ENGINEERS, INC.

Robert E. Kitay, R.E.A. Project Geologist

Attachments: Figures 1 and 2


Appendices A and B

cc: Ms. Erma Delluchi

Ms. Juliet Shin, ACHCSA

Mr. Kevin Graves, RWQCB, San Francisco Bay Region

-3-




SITE LOCATION MAP

Delluchi Property 2425 Central Avenue Alameda, California

Aqua Science Engineers

Figure 1

BASE: USGS Oakland East 7.5 minute quadrangle topographic map, dated 1980, scale 1:24,000.



 \mathbb{N}

Figure 2

AQUA SCIENCE ENGINEERS

APPENDIX A

Field Logs



WELL SAMPLING FIELD LOG

Project Name and Address: Dellochi, Alamed.
Project Name and Address: Job #: 2750 Well Name: μω-(Well diameter (inches): 2
Job #: 2158 Sampled by: D4
Depth to water before sampling (feet): 6.85
Thickness of floating product if any:
Depth of well casing in water (feet):
at the of college per well casing volume (gailons):
Number of well casing volumes to be removed: A gallons of well casing volumes to be r
Req'd volume of groundwater to be purged before sampling (gallons):
The word to myrge the well. Delicated Dailo
Time Evacuation Began: 11:30 Time Evacuation Finished: 11:45
Time Evacuation Degan
Approximate volume of groundwater purged: Did the well go dry?: No After how many gallons:
Time samples were collected: 11:55
n i di a af complina: la 09
Percent recovery at time of sampling: 99 Samples collected with: Dedicated Boiler Sample color: Ludy brown Odor: None Description of sediment in sample: Small amount of fire brown 5
Semples collected with: Dedicated Bailer
Samples confected with. Description Odor Hare
Description of addiment in sample: suall access of fire brown 5
Description of sediment in sample.
OTTEMOLI DATA
CHEMICAL DATA
Volume Purged Temp pH Conductivity
Volume Purged Temp pH Conductivity 1 1/4 60.4 7.12 585
61.7 7.10 60.0
5 62.8 7.14 604
8 62.8 7.11 6.04
· · · · · · · · · · · · · · · · · · ·
SAMPLES COLLECTED
SAM LES CODECTED
Sample # of containers Volume & type container Pres Iced? Analysis
MV-1 3 40 ml glass VOF V V TOU-6/BIEX
11 1 500 me plastic No V Dissolved Ph

APPENDIX B

CAL-EPA Certified Laboratory Results and Chain-of-Custody Record

American Environmental Network

Certificate of Analysis

DOHS Certification: 1172

AIHA Accreditation: 11134

PAGE 1

AQUA SCIENCE ENGINEERS, INC 2411 OLD CROW CANYON RD. #4 SAN RAMON, CA 94583

ATTN: DAVE ALLEN CLIENT PROJ. ID: 2750

REPORT DATE: 06/16/95

DATE(S) SAMPLED: 06/02/95

DATE RECEIVED: 06/02/95

AEN WORK ORDER: 9506051

PROJECT SUMMARY:

On June 2. 1995, this laboratory received 1 water sample(s).

Client requested sample(s) be analyzed for inorganic and organic parameters. Results of analysis are summarized on the following page(s). Please see quality control report for a summary of QC data pertaining to this project.

Samples will be stored for 30 days after completion of analysis, then disposed of in accordance with State and Federal regulations. Samples may be archived by prior arrangement.

If you have any questions, please contact Client Services at (510) 930-9090.

LarryKlein

Laboratory Director

AQUA SCIENCE ENGINEERS, INC.

AEN JOB NO: 9506051 DATE SAMPLED: 06/02/95 DATE RECEIVED: 06/02/95 CLIENT PROJ. ID: 2750

Client Sample Id.	AEN Lab Id.	Purgeable Hydrocarbons as Gasoline (ug/L)	Benzene (ug/L)	Toluene (ug/L)	Ethyl- benzene (ug/L)	Total Xylenes (ug/L)
MW-1	01	ND	ND	ND	ND	ND
Reporting Limit:		50	0.5	0.5	0.5	2
EPA Method:		5030 GCFID	8020	8020	8020	8020

Instrument: F

Date Analyzed: 06/09/95

ND = Not Detected

AQUA SCIENCE ENGINEERS, INC

SAMPLE ID: MW-1

AEN LAB NO: 9506051-01 AEN WORK ORDER: 9506051 CLIENT PROJ. ID: 2750

DATE SAMPLED: 06/02/95 DATE RECEIVED: 06/02/95 REPORT DATE: 06/16/95

ANALYTE	METHOD/ CAS#	RESULT	REPORTING LIMIT	UNITS	DATE ANALYZED
#Sample Filtration	0.45 um	-		Filtr Date	06/02/95
#Digestion, Metals ICP/AA	EPA 3010	÷		Prep Date	06/07/95
Lead	EPA 6010	ND	0.04	mg/L	06/12/95

ND = Not detected at or above the reporting limit
* = Value at or above reporting limit

AEN (CALIFORNIA) QUALITY CONTROL REPORT

AEN JOB NUMBER: 9506051

CLIENT PROJECT ID: 2750

Quality Control and Project Summary

All laboratory quality control parameters were found to be within established limits.

<u>Definitions</u>

Laboratory Control Sample (LCS)/Method Spike(s): Control samples of known composition. LCS and Method Spike data are used to validate batch analytical results.

Matrix Spike(s): 'Aliquot of a sample (aqueous or solid) with added quantities of specific compounds and subjected to the entire analytical procedure. Matrix spike and matrix spike duplicate QC data are advisory.

Method Blank: An analytical control consisting of all reagents, internal standards, and surrogate standards carried through the entire analytical process. Used to monitor laboratory background and reagent contamination.

Not Detected (ND): Not detected at or above the reporting limit.

Relative Percent Difference (RPD): An indication of method precision based on duplicate analysis.

Reporting Limit (RL): The lowest concentration routinely determined during laboratory operations. The RL is generally 1 to 10 times the Method Detection Limit (MDL). Reporting limits are matrix, method, and analyte dependent and take into account any dilutions performed as part of the analysis.

Surrogates: Organic compounds which are similar to analytes of interest in chemical behavior, but are not found in environmental samples. Surrogates are added to all blanks, calibration and check standards, samples, and spiked samples. Surrogate recovery is monitored as an indication of acceptable sample preparation and instrumental performance.

- D: Surrogates diluted out.
- #: Indicates result outside of established laboratory QC limits.

QUALITY CONTROL DATA

METHOD: EPA 8020, 5030 GCFID

AEN JOB NO: 9506051 INSTRUMENT: F

INSTRUMENT: F MATRIX: WATER

Surrogate Standard Recovery Summary

			Percent Recovery
Date Analyzed	Client Id.	Lab Id.	Fluorobenzene
06/09/95	MW-1	01	96
QC Limits:			92-109

DATE ANALYZED: 06/09/95

SAMPLE SPIKED: 9506040-05

INSTRUMENT: F

Matrix Spike Recovery Summary

	6	A		QC Limits	
Analyte	Spike Added (ug/L)	Average Percent Recovery	RPD	Percent Recovery	RPD
Benzene Toluene	17.8 51.6	99 95	6 5	85-109 87-111	17 16
Hydrocarbons as Gasoline	500	86	<1	66-117	19

Daily method blanks for all associated analytical runs showed no contamination over the reporting limit.

QUALITY CONTROL DATA

AEN JOB NO: 9506051

SAMPLE SPIKED: DI WATER DATE ANALYZED: 06/12/95

MATRIX: WATER

Method Spike Recovery Summary

				QC Limits		
Analyte	Inst./ Method	Spike Added (mg/L)	Average Percent Recovery	RPD	Percent Recovery	RPD
Pb, Lead	ICP/6010	0.5	105	1	94-115	6

Daily method blanks for all associated runs showed no contamination over the reporting limit.

R.35-3

950606098

Aqua Science Engineers, Inc. 2411 Old Crow Canyon Road, #4, San Ramon, CA 94583 (SIO) 820-9391 - FAX (SIO) 837-485

Chain of Custody

DATE 6.2.95 PAGE 1 OF (510) 820-9391 - FAX (510) 837-4853 PROJECT NAME Delluchi SAMPLERS (SIGNATURE) (PHONE NO.) ADDRESS Alameda 820.4391 ANALYSIS REQUEST PURGABLE ARCMATICS (EPA 602/C020) SPECIAL INSTRUCTIONS: ILTERT 1A-DMW-1 6/2 11:55 Water (time) (signature) (time) (signature) (time) TANDARD

(date) (printed name) (date) (printed name) RECEIVED BY LABORATORY: RELINOUISHED BY:

4:35 P RELINQUISHED BY: RECEIVED BY (signature)

(time) 'signature'

(printed name)

(time) 'signature'

(signature)

(time) 'signature'

(signature)

(date) (printed name) Company- AEN Company- AEW Company ASE /2 C. Company-AEU