SITE: 420 13th-9t. Oakland

## ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY

DAVID J. KEARS, Agency Director

R0576

(510) 271-4530

RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

DEPARTMENT OF ENVIRONMENTAL HEALTH
State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program
80 Swan Way, Rm 200
Oakland, CA 94621

January 21, 1993

STID 4142

Paul Lafontaine Zimmerman Investments 1330 Broadway Oakland CA 94612

Dear Mr. Lafontaine,

We are in receipt of the "Technical Report for Site Investigation," prepared by Certified Environmental Consulting Inc. (CEC), dated 1/11/93. This report documents the installation and sampling results from two soil borings and one groundwater monitoring well in 13th St. The soil and groundwater results indicate non-detectable concentrations of contaminants, with the exception of trace amounts of toluene in both soil and groundwater.

This report recommends the re-excavation and off-site disposal of soil from the 550-gallon waste oil and the 4,500-gallon diesel vaults. We are in agreement with this recommendation, and request at least 2 business days notice for site activities.

If you have any questions, please contact me at 510-271-4530.

Sincerely,

Jennifer Eberle

Hazardous Materials Specialist

cc: Tom Gillespie, Certified Environmental Consulting, Inc., 140 West Industrial Way, Benicia CA 94510

Rich Hiett, RWQCB Ed Howell/File

jе

## ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY

DAVID J. KEARS, Agency Director

R0576

RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

DEPARTMENT OF ENVIRONMENTAL HEALTH
State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program
80 Swan Way, Rm 200
Oakland, CA 94621
(510) 271-4530

September 2, 1992

STID 4142

Paul Lafontaine Zimmerman Investments 1330 Broadway Oakland CA 94612

Dear Mr. Lafontaine,

We are in receipt of the Tank Closure Report prepared by Certified Environmental Consulting, Inc., dated June 1992.

Soil collected from beneath the southwest end of the 4,500-gallon diesel tank contained 8,500 ppm TPH-diesel; the stockpile contained 1,900 ppm TPH-diesel. The fill end of this tank was on the northeast end.

Soil collected from beneath the waste oil tank contained 120 ppm Oil & Grease; the stockpile contained 240 ppm Oil & Grease.

Based on these significant levels of contaminants, a soil and groundwater investigation is required in the vicinity of the waste oil tank and 4,500-gallon diesel tank to determine the extent of soil and groundwater contamination. Groundwater monitoring wells are generally installed in a triangular fashion to determine the groundwater flow direction and the levels of contamination. The workplan for this investigation must adhere to the Tri-Regional Board Staff Recommendations for Preliminary Evaluation and Investigation of Underground Tank Sites, 8/10/90, and must include a schedule for implementation. Your workplan must be submitted to J. Eberle of this office within 45 days or by October 17, 1992. Enclosed is a copy of RWQCB's guideline (Appendix A) for your reference.

All reports and proposals must be submitted under seal of a California-Registered Geologist, -Certified Engineering Geologist, or -Registered Civil Engineer. All proposals, reports, and analytical results pertaining to this investigation and remediation must be sent both to our office and to:

Rich Hiett RWQCB, San Francisco Bay Region 2101 Webster St., Suite 500 Oakland CA 94612 Paul LaFontaine STID 4142-A Page 2 of 2 September 2, 1992

Please be advised that this is a formal request for technical reports pursuant to California Water Code Section 13267(b). Any extensions of the stated deadlines or modifications of the required tasks must be confirmed in writing by either this agency or the RWQCB.

If you have any questions, please contact Jennifer Eberle at 510-271-4320.

Sincerely,

Susan Hugo

Server L. Hugo

Senior Hazardous Materials Specialist

cc: Dave Janney, Certified Environmental Consultants, 140 W. Industrial Way, Beniciz CA 94510

Rich Hiett, RWQCB Ed Howell/File

je 4142-A

DAVID J. KEARS, Agency Director

SITE: 420 13th St. Oakland, CA

R0576

RAFAT A. SHAHID, Assistant Agency Director

May 28, 1992

STID #4142

Paul Lafontaine Zimmerman Investments 1330 Broadway Oakland CA 94612 DEPARTMENT OF ENVIRONMENTAL HEALTH Hazardous Materials Division 80 Swan Way, Rm. 200 Oakland, CA 94621 (510) 271-4320

Dear Mr. Lafontaine,

The case file for your site has been reassigned to Jennifer Eberle, Hazardous Materials Specialist. Please forward future correspondence to her attention. This letter is being written as per request by Dave Janney in your behalf.

We are in receipt of a faxed copy of the laboratory results for soluble lead from sampling associated with the 6,000-gallon gasoline tank at your site. The results indicate concentrations of lead below the STLC.

In addition, Jennifer Eberle spoke with Rich Hiett of RWQCB on 5/26/92 regarding the low concentrations of petroleum hydrocarbons in the stockpile from the gasoline tank. Although there was 1.8 ppm TPH-g and 0.012 ppm benzene in the stockpile, the samples from the bottom of the excavation had nondetectable concentrations of hydrocarbons. A groundwater investigation will be needed nevertheless at this site due to the significant hydrocarbon concentrations associated with the 500-gallon waste oil tank and the 4,500-gallon diesel tank. Therefore, Rich Hiett and Jennifer Eberle agreed that the backfilled stockpile soil from the gasoline tank may remain in place.

If you have any questions, please phone J. Eberle at 510-271-4320.

Sincerely,

Susan Hugo

Senior Hazardous Materials Specialist

cc: Dave Janney, Certified Environmental Consultants, 140 W.
Industrial Way, Benicia CA 94510

Rich Hiett, RWQCB

File

DEPARTMENT OF ENVIRONMENTAL HEALTH

Hazardous Materials Program 80 Swan Way, Rm. 200 Oakland, CA 94621

(415)

## ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY DAVID J. KEARS, Agency Director

March 14, 1991

Mr. Jonathan Leo Heller, Ehrman, White & McAuliffe 333 Bush Street San Francisco, CA 94104-2878

Dear Mr. Leo

I am in receipt of your Government Code Section 6250 request to inspect our files for the following addresses:

(RO129) 1721 Webster St.
(RO576) 420 13th Street
1833 Harrison Street (Notin Envision)
1424 Harrison Street (u)

Please contact me at your earliest convenience to arrange a mutually acceptable time for the site search to take place.

Sincerely:

Paul M. Smith

Paul or Drill

Hazardous Materials Specialist

cc:

Mark Borsuk Mark Thomson

AL