

3/24/94

STID 1385
1494 - 67th St Emeryville 94608

Talked to Jenni Alexander re: letter 11/93
of APC, does the site qualify for APC
forward her copy of letter & draft APC

6/1/94

Talked to Jenni Alexander re: modifying
monitoring program

MW-8, MW-5, MW-4 (every quarter)
MW-6 dropped but if MW-4 showed
any levels, then sample MW-6

6/2/94

Call Anita Panbayan 420-3500
request closure report for the tank (gasoline)
no data, disposal records

9/10/93 STP 1385 - Coulter Steel
722 Falger Ave.

Talked to Marian Watada
re: phone not fully defined in the eastern portion
up gradient well showing high hits

re: need soil boring^{per} in the east side of property

re: check volume application for the ugt (gasoline)
still on site.

9/16/93

Talked to Marian Watada (SCD)

re: letter:

- 1) forms A&B
 - 2) Check Contractor's License
 - 3) must use the new
UGT forms
 - 4) note of for T&H BTEX
- Shana: 9/24/93
will send forms A&B

6/29/93

STID

Cantler Steel

- Talked to Jim Alexander re:
- disposal of groundwater stored (4-5,000 gal)
refer to Ric Brazo (RWQCB)
 - requirement, semi annual monitoring

FILE OR] SH] ENVELOPE
 PER NO.] No. of

OWNER COULTER STEEL
 Address 1494 6TH Street
 722 FOLDER ST.
 EMERYVILLE 94608 Phone

Contractor SCOTT CO. & CA
 Address 1919 MARKET ST.
 Oakland 94607 Phone

OTHER (Specify)
 Address
 Phone

CONTACT FOR INVESTIGATION

PLAN REVIEW

\$ 432.⁰⁰ Rec'd. TS 10/15/91

No. 612109 Plans Rec'd.

Plans Approved

Layout Made

Rejected

Applicant Notified

Plans Returned

Permit Issued

CONSTRUCTION PROGRESS ACCEPTANCE

FOOD Pre-Plaster/drywall

Pre-Final

Final

By Date

POOL Pre-Concrete/Gunite

Pre-Plaster

Final

EXCAVATION Septic Tank

Absorption Field

Absorption Bed

House Sewer

FINAL Septic Tank

Absorption Field

Absorption Bed

OTHER

By Date

Pre-Covering

Final

U.G. TANK

LOP 1385

XR BRV

REMARKS	Date	By	REMARKS	LOCATION
---------	------	----	---------	----------

Date	By	REMARKS	Date	By	REMARKS	LOCATION
10/30/91	SH	Review clove plan - 1-10,000 G diesel, approved.	12/18/91	SH	Site visit, overexcavation of the pit.	Vicinity Map Project # 612109 Fee Paid 432. ⁰⁰ Date 10/15/91
11/20/91	SH	1-10,000 G UGT removal. Soil discoloration, diesel tank, groundwater (green) present w/ what appear like floating product. Frank Atkins of Emeryville Fire present at site. 2 soil samples collected (1 from each end of tank) + groundwater sample collected. Black pilled soil characterized (4 diesel, sample comprised	12/19/91	SH	Soil samples (verification) samples collected (3 bottom samples, 4 sidewall samples (1 from each wall). NO ground-water present. 4 sidewalls of pit distinguished green sh color about 4 ft from surface approximately (4 ft wide) UGR must be submitted. Forms left with waste samples of Coulter Steel (UGR, A, B, C) SB 2004 no. 100.	

REMARKS			REMARKS			REMARKS		
Date	By		Date	By		Date	By	
12/20/91	SH	Talked to Jack Sabnis. Rec'd. faxed copy of original soil sample results. BTX&E work not analyzed. Must test for BTX&E, TPH & for phase verification ^{soil} samples (7) collected 12/19/91.						
3/20/92	SH	Review work plan - see note (3/30/92) draft letter.						
4/1/92	SH	Talked to consultant about deficiencies in the Workplan						
4/6/92	SH	Draft letter - letter out re: submitted workplan.						
7/6/92	SH	Transferred to LOP						