

2/1/96 Spoke to Wesley Adams, City, re correction in July 25th ltr from "northeast" to "northwest". He also mentioned that the ltr ^{will be} sent out tomorrow.

3/5/96 Left message for Wesley Adams, City of Alameda, that I would initiate a case closure summary.

3/5/96 Spoke to Wesley Adams re case closure & fact that level of benzene at 0.63 ppm exceed human health protective thresholds given in ASTM RBCA. He said he will have ACC get in touch w/ us re Tier 2.

3/5/96 Spoke to ML re RBCA values & Misty Kaltrider.

5/3/96 Left message for Misty Kaltrider requesting her client to submit a letter stating that they will try to keep the area where 0.63 ppm benzene was identified paved or capped.

5/13/96 Left message for Wesley Adams reminding him of above 5/3/96 request

IMPORTANT MESSAGE

FOR Larry Seto
DATE 7-11-94 TIME 10:55 **AM**
M. David Hoexter
OF _____

PHONE _____
AREA CODE _____ NUMBER _____ EXTENSION _____

TELEPHONED	<input checked="" type="checkbox"/>	PLEASE CALL	<input checked="" type="checkbox"/>
CAME TO SEE YOU	<input type="checkbox"/>	WILL CALL AGAIN	<input type="checkbox"/>
WANTS TO SEE YOU	<input type="checkbox"/>	RUSH	<input type="checkbox"/>
RETURNED YOUR CALL	<input type="checkbox"/>	SPECIAL ATTENTION	<input type="checkbox"/>

MESSAGE re: Alameda City Hall
Tanks. Addition Soil
samples this afternoon

leave message with
Andrew at 748 4695

SIGNED _____
LITHO IN U.S.A.

FILE OR ENVELOPE
 PER NO. **Removal** No. _____ of _____
 OWNER **City of Alameda**
 Address **2263 Santa Clara Ave.**
Alameda 94501 Phone _____
 Contractor **VCI of Calif**
 Address **753 Peralta Ave.**
Sanheandro Phone _____
 OTHER (Specify) _____
 Address _____ Phone _____
 CONTACT FOR INVESTIGATION

PLAN REVIEW
 \$ **951.00** Rec'd. **Ma** 6/8/94
 No. _____ Plans Rec'd. _____
 Plans Approved _____
 Layout Made _____
 Rejected _____
 Applicant Notified _____
 Plans Returned _____
 Permit Issued _____
 CONSTRUCTION PROGRESS ACCEPTANCE
 Pre-Plaster/drywall _____
 Pre-Final _____
 Final _____

By _____ Date _____
 POOL
 Pre-Concrete/Gunit _____
 Pre-Plaster _____
 Final _____
 EXCAVATION
 Septic Tank _____
 Absorption Field _____
 Absorption Bed _____
 House Sewer _____
 FINAL
 Septic Tank _____
 Absorption Field _____
 Absorption Bed _____
 OTHER _____
 U.G. TANKS
 Pre-Covering _____
 Final _____
122220

XR
 REMARKS
 Date By
 6/15/94 C.S. 1,100 gal. tested tank, ^{and 280 gal} saw some holes in bottom/side of 1,100 gal tank
 6/17/94 C.S. Sampled excavation of 280 gal UGT, soil sample taken under tank but a strong gas odor
 Sampled ~~1,100~~ under 1,000 gal. tank - 2 samples from tank, 2 samples on side odor detected during tank removal but not after over excavation of backfill
 6/21/94 W.S. Last tank was removed from underneath sidewalk. There was some sitting on the bottom of ~~side~~ of tank, but no hole. A sewer line in the excavation was busted during excavations, two soil samples from sidewalk were taken close to bottom of tank

REMARKS
 Date By
 CLOSURE

LOCATION
 Vicinity Map
 725630
 \$951.00
 6-8-94
 R0643

12263 Santa Clara Ave
 Alameda, CA 94501
 PUBLIC WORKS DEPARTMENT
 1st ID
 3837