

August 30, 1990 BEI Job No. 89070

Mr. Dennis Byrne Alameda County Health Care Services Agency Division of Hazardous Materials Department of Environmental Health 80 Swan Way, Room 200 Oakland, CA 94621

Subject:

Quarterly Groundwater Sampling

Peterson Properties 1301 - 65th Street Emeryville, California

Dear Mr. Byrne:

This letter and its enclosures constitute the third quarterly groundwater sampling report for the second year for the subject facility.

The existing monitoring well (MW-1) was sampled on August 8, 1990. The well was purged prior to sampling by removal of four well casing volumes of water. A representative sample was collected with a clean, Teflon bailer and placed in two 40-ml volatile organics vials provided by the laboratory. The sample containers were labelled, packed on ice and delivered to Trace Analysis Laboratory, a California-certified laboratory. The sample was analyzed for Total Petroleum Hydrocarbons (TPH) as gasoline using the California Department of Health Services Method and benzene, toluene, xylenes and ethylbenzene using EPA Method 8020. An equipment blank was collected after initial decontamination of the bailer, but it was not analyzed by the laboratory.

TPH as gasoline, benzene, and ethylbenzene were detected in the water sample at concentrations of 620 ug/l (parts per billion), 430 ug/l, and 25 ug/l, respectively. Toluene and xylenes were not detected in the water sample. A copy of the analytical report is attached.

Cordially,

BLYMYER ENGINEERS, INC.

Michael S. Lewis


Manager, UST Services

Mr. Dennis Byrne Alameda County Health Care Services Agency August 30, 1990 Page Two

Enclosures:

Groundwater Monitoring Data form dated 8/8/90 Purge Data form dated 8/8/90 Chain of Custody Record Laboratory Analytical Report dated 8/24/90 Site Plan

cc: Mr. Lester Feldman, San Francisco Bay Regional Water Quality Control Board Mr. Ed Peterson Mr. Robert Coussan Mr. Charles Gensler Mr. Lawrence C. Jones, Jr. Rick Griffith, Esq.



GROUNDWATER MONITORING DATA

Project	Name	_ Peter	rson -	Emeryv	ille, CA	Proj	ect No.	89070_
Date 8	<u> -8-90</u>			Field	Technician	n <u>ML/JM</u>	Sheet 1	of <u>1</u>
Weather	S	unny		<u>,</u>	Temperat	ure <u>80</u>	Wind _	5K
WELL ID	1	TOC ELEV.	DT W	DTP	PΤ	PT x .8		WATER ELEV.
MW-1			3.99'		- AND		=	
			بيجستن سيسمي					
								
	_						- 1111	
				<u></u>				
	. <u>–</u>							
	· –							
								
TOC = T DTW = D DTP = D PT = P	EPTH ' EPTH '	IO WATI IO PROI	ER DUCT					
COMMENT	s:							
<u>Well V</u>	<u>olume</u>	= 3.25	<u>gallo</u>	ns				
Water	is sl	ightly	silty;	sligh	t odor.			<u> </u>
								



PURGE DATA

Project N	Name <u>Peters</u>	on - En	meryville, CA	Proje	ect No. $\frac{8}{100}$	39070	
Date 8	-8-90	Fiel	d Technician	ML/JM	Sheet	_ of	_1
WELL ID	WELL VOLUME NO.	Hq	TEMPERATURE	(F) CON	DUCTIVITY	(uS/	<u>'cm)</u>
<u>MW</u> -1	<u>Initial</u>	6.75	85.2_		980		
	1	<u>6.63</u>	78.0		1270		
	2	6.60	75.4		1530	•	
•	3	6.48	73.6		1635		
	4	6.52	<u>73.3</u>		1612		
	· · · · · · · · · · · · · · · · · · ·						
							
					·		

BEI Field Services

1829 Clement Avenue Alameda, CA 94501

CHAIN OF CUSTODY RECORD

							-HAIN (or Gua		UT	KE	LU	KU							
PROJ NO		CT	NAN	1E									625/8270					\neg	····	
89070 Peterson - Eneryville							NO OF CON- TAINERS	as gasoline + BTXE	esel	ase (SM503E)	VOC (EPA 624/8240)	18		ł	ł	1 1	1			
SAMPLERS (Signature)												23			-		١			
White P. L												(EPA						REMARKS	EMARKS	
DATE	TIME	CONTR.	GRAB	SAMPLE LOCATION				TPH as ga	TPH as diesel	Oil & Gre	VOC (EP A	Semi-YOC	970H							
8-8-90	11:10		×	Bail	20°	Blank	,							\times	\neg				* _ · · · · = -	
8-3-90	11:45		X		-1				×										Stando	and TAT
		_	 					ļ												
		-	-	<u> </u>	·			ļ	 				-		_					
		├-	 	ļ					-		_	-	ļ			\dashv	+-	-		
······································		 	-	<u> </u>		· · · · · · · · · · · · · · · · · · ·			-		 		-		\dashv	+	-			
															\neg	十	+			
															\Box					
		<u> </u>	_	<u> </u>					_	<u> </u>	_	_	 				1_			
		┼	-	ļ				<u> </u>		<u> </u>		 	_		_	-	 			
		╀╌	╁					 	+-	-	-	-	┼-	 			-			·
Relinquishe Michi	d by : (Signa Ruff, A d bu : (Signa	tur	.)	Date/T	ime	Received by	: (Signatur	e) PMZ 8	Relin	quis	hed 2	by:	(Sig	natur	e)	Date	/Time	R	eceived by	: (Signature)
Relinquishe	d by : (Signa	atur	e)	Date/T	ime	Recei√ed by	: (Signatur	· e)	Relin	quis	hed	by:	(Sig	natur	~e)	Date.	Time	R	eceived by	: (Signature)
Relinquishe	d by : (Sign:	atur	e)	Date/1		Received fo (Signature)		ry by:	D	ate/	Tim	ę	Re	eta /	: s	to	Bly	y .n	yer	Engineers,
CCR/REY	0/2-89			······································							L									



LOG NO.: 9009
DATE SAMPLED: 8/08/90
DATE RECEIVED: 8/08/90
DATE ANALYZED: 8/15/90
DATE REPORTED: 8/24/90

CUSTOMER:

Blymyer Engineers, Inc.

REQUESTER:

Mike Lewis

PROJECT:

No. 89070, Peterson-Emeryville

		<u>Sample Type:</u>	<u>Water</u>		
			MW-1		
Method and <u>Constituent</u>	<u>Units</u>	Concen- <u>tration</u>	Detection <u>Limit</u>		
DHS Method:					
Total Petroleum Hydro- carbons as Gasoline	ug/l	620	30		
Modified EPA Method 8020:					
Benzene	ug/l	430	5		
Toluene	ug/l	< 5	5		
Xylenes	ug/l	< 10	10		
Ethylbenzene	ug/l	25	6		

Louis W. DuPuis

Quality Assurance/Quality Control Manager

G5 TH STREET UTILITY POLE (TYP 2 LOCATIONS) TANK EXCAVATION MW-1 BUILDING 1301 65TH STREET BLYMYER & SONS ENGINEERS, INC. HENRY HORN & SONS NO 8897.1