HEALTH CARE SERVICES

AGENCY

DAVID J. KEARS, Agency Director



ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION (LOP) 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700

FAX (510) 337-9335

REMEDIAL ACTION COMPLETION CERTIFICATION Alameda, CA 94502-6577

March 20, 1997

Marla Guensler Exxon Corporation 800 Bell St., Rm 1331 Houston, Texas 77002 Richard Ritchey 3600 Vasco Road Brentwood, CA 94513-4555

Perry K. Pahlmeyer 10234 County Road 250 Durango, CO 81301

Faramarz Khodayari 4868 Calaveras Ave. Oakland, CA 94619

Re: Former Exxon Station, 4868 Calaveras Ave., Oakland, CA 94619 [STID 1114]

Dear Ms. Guensler and Messrs. Pahlmeyer, Ritchey, and Khodayari,

This letter confirms the completion of a site investigation and remedial action for the underground storage tanks formerly located at the above described location. Thank you for your cooperation throughout this investigation. Your willingness and promptness in responding to our inquiries concerning the former underground storage tanks are greatly appreciated.

Based on information in the above-referenced file and with the provision that the information provided to this agency was accurate and representative of site conditions, no further action related to the underground tank release is required.

This notice is issued pursuant to a regulation contained in Section 2721(e) of Title 23 of the California Code of Regulations.

Please contact our office if you have any questions regarding this matter.

Sincerely,

Mee Ling Tung

Director of Environmental Health Services

c: Acting Chief, Hazardous Materials Division - files Juliet Shin, ACDEH Kevin Graves, RWQCB Lori Casias, SWRCB (w/ enclosure)

01-2209*

ENVITOPMENTAL PROTECTION

97 MAR -7 PM 3: 48

CASE CLOSURE SUMMARY Leaking Underground Fuel Storage Tank Program

Date: December 30, 1997

I. AGENCY INFORMATION

Agency name: Alameda County-HazMat Address: 1131 Harbor Bay Pkwy. City/State/Zip: Alameda, CA 94502 Phone: (510) 567-6700

Responsible staff person: Juliet Shin Title: Senior HMS

II. CASE INFORMATION

Site facility name: Former Exxon Station

Site facility address: 4868 Calaveras Ave., Oakland, CA 94619 RB LUSTIS Case No: N/A Local Case No./LOP Case No.: 1114

URF filing date: SWEEPS No: N/A

Responsible Parties:	Addresses:	Phone Numbers:
Exxon Corporation Contacts: Marla Guensler or Tom Michael	800 Bell St., Rm 1331 Houston, Texas 77002 or P.O. Box 4032 Concord, CA 94524-4032	(510)246-8776
Perry K. Pahlmeyer	10234 County Road 250 Durango, CO 81301	(970) 259-7576
Richard Ritchey	3600 Vasco Rd. Brentwood, CA 94513-4555	Unknown
Faramarz Khodayari	4868 Calaveras Ave. Oakland, CA 94619	(510)482-2462

Tank No:	<u>Size in</u> _gal.:	Contents:	<u>Closed in-place</u> <u>or removed?:</u>	<u>Date:</u>		
			<u>-</u>			
1	8,000-gallon	gasoline or diesel	removed	2/81		
2	8,000-gallon	gasoline or diesel	removed	2/81		
3	8,000-gallon	gasoline or diesel	removed	2/81		
4	250-gallon	waste oil	removed	2/81		

III. RELEASE AND SITE CHARACTERIZATION INFORMATION

Cause and type of release: Unknown

Site characterization complete? YES

Date approved by oversight agency: December 30, 1996

Monitoring Wells installed? YES Number: 3

Proper screened interval? YES. MW-1 and MW-2(16'-31'bgs); MW-3(16'-36'bgs)

Highest GW depth below ground surface: 16.68 feet Lowest depth: 20.51 feet However, first encountered groundwater in Borings B-2 and B-8 in September 1995 was at 11-feet below ground surface (bgs). Based on the attached boring logs and cross-section diagram, the groundwater observed in these two borings may have been from the gravelly clay lenses as opposed to the primary sand aquifer.

Flow direction: east-southeast

Most sensitive current use: Commercial/Residential

Are drinking water wells affected? NO Aquifer name: Unknown

Is surface water affected? NO Nearest affected SW name: None

Off-site beneficial use impacts (addresses/locations): None

Report(s) on file? YES Where is report(s) filed? Alameda County
1131 Harbor Bay Pkwy.
Alameda, CA 94502

Treatment and Disposal of Affected Material:

<u>Material</u>	<u>Amount</u> (include units)	Action (Treatment or Disposal w/destination)	<u>Date</u>
Tanks	Four	Unknown	2/81
Soil Cuttings	Three cubic yards	BFI Landfill Livermore, CA	10/1/96
Purge water	130 gallons	Romic Environmental Palo Alto, CA	Unknown

III. RELEASE AND SITE CHARACTERIZATION INFORMATION (Continued) Maximum Documented Contaminant Concentrations - - Before and After Cleanup

Contaminant	Soil (ppm)	Water (pr	ob)
	Before ^{î After}	Before ³	<u> After</u>
TPH (Gas)	110	2,800	ND
TPH (Diesel)	ND	ND	
Total Oil & Grease	ND	NA	
Benzene	0.24	13	ND
Toluene	0.19	6.7	ND
Xylene	0.23	16	ND
Ethylbenzene	0.08	13	ND
Chlorinated Hydrocarbons	ND	NA	
Metals	2	NA	

NA-Not Analyzed

- 1-Soil sample collected from Boring B-8 at 10-feet bgs on 9/5/95
- 2-Metal concentrations were very low and below human health protective thresholds established by U.S. EPA.
- 3-Groundwater sample collected from Boring B-8 in 9/13/95
- 4-Soil concentrations were left in place.

IV. CLOSURE

Does completed corrective action protect existing beneficial uses per the Regional Board Basin Plan? Undetermined

Does completed corrective action protect potential beneficial uses per the Regional Board Basin Plan? Undetermined

Does corrective action protect public health for current land use? YES

Site management requirements: Based on the low levels of residual contaminant concentrations remaining in the soil and groundwater within the gravelly/clay lenses (refer to attached copy of cross-section diagram), the local agency should be notified if this material is ever exposed through construction activities, and the Health & Safety plan, for construction activities, should address potential exposures to these concentrations.

Should corrective action be reviewed if land use changes? NO

Monitoring wells Decommisioned: NO Will be decommissioned upon receipt of case closure.

Number Decommisioned:

Number Retained:

List enforcement actions taken: None

٧. LOCAL AGENCY REPRESENTATIVE DATA

Name: Juliet Shin

Signature:

Title: Senior HMS
Date: 2/12/97

Reviewed by

Name: Eva Chu

Signature:

Title: Hazardous Materials Specialist

Date:

Name: Thomas Peacock

Signature:

Title: Supervising HMS

Date:

VI.

Date Submitted to RB:

RWQCB Staff Name: Kevin G

RB Response:

Title: San. Engineering Asso.

ADDITIONAL COMMENTS! VII.

The site is located in the central-eastern section of Oakland, California, at the intersection of Calaveras Avenue and Buell Street, adjacent to Highway 580. The site is less than 1/2 mile south of the Hayward Fault line and lies at an elevation of approximately 150 feet above mean sea level. The topography slopes gently toward the southwest (refer to attached figure 1).

The site is currently zoned for residential and light commercial/ industrial, and is currently occupied by International Auto Clinic, an auto repair and detailing facility. Exxon operated a gas station at the facility from the early 1970s until 1981, when three 8,000-gallon gasoline/diesel underground storage tanks (USTs) and one 250-gallon waste oil UST was removed from the site.

On September 5, 1995, six exploratory borings (B-1 through B-6) were drilled at the site in the locations of the former USTs and piping, to identify any potential petroleum contamination (refer to attached figure 2 for sample locations). The borings were drilled to depths ranging from 10to 18-feet below ground surface (bgs). On September 13, 1995, two additional borings, B-7 and B-8, were drilled in an attempt to collect additional groundwater samples.

A total of 13 soil samples were collected from Borings B-1 through B-6, and B-8 at depths ranging from 5- to 10-feet bqs. These samples were analyzed for Total Petroleum Hydrocarbons as gasoline (TPHg), TPH as diesel (TPHd), and benzene, toluene, ethylbenzene, and xylenes (BTEX). Additionally, soil samples collected from Boring B-6, located adjacent to the former waste oil UST, was analyzed for Total Oil & Grease, chlorinated hydrocarbons (using Method 8010), and heavy metals. Analysis results identified up to 110 parts per million (ppm) TPHg, 0.24ppm benzene, 0.19ppm toluene, 0.083ppm

ethylbenzene, 0.23ppm total xylenes, and low levels of metals that were below human health protective levels per the U.S. Environmental Protection Agency (refer to attached table 1).


"Grab" groundwater samples were collected from Borings B-2 and B-8. These water samples were analyzed for TPHg and BTEX (refer to attached table 2). The groundwater sample collected from Boring B-8 identified 2,800 parts per billion (ppb) TPHg, 13ppb benzene, 6.7ppb toluene, 13ppb ethylbenzene, and 16ppb total xylenes. No contaminants were identified above detection limits from the sample collected from Boring B-2. It appears that, based on the attached boring logs and the cross-section diagram data, that these water samples were collected from the gravelly clay lenses located above the primary sandy aquifer (refer to attached figures 3 and 4). In fact, both the soil and groundwater contamination at the site appear to be limited to these lenses.


On August 7, 1996, three borings were drilled at the site and converted into monitoring wells (MW-1 through MW-3) (refer to attached figure 2). A total of 11 soil samples were collected from these three borings (refer to attached figures 3 & 4). These soil samples were analyzed for TPHg and BTEX. Soil samples collected from MW-1 identified up to 55ppm TPHg, 1ppm ethylbenzene, and 0.94ppm total xylenes. No contaminants were identified in the soil samples collected from the other two borings above detection limits. Groundwater samples were collected from the three wells after proper well development and purging processes. The groundwater samples were analyzed for TPHg and BTEX. No contaminants were identified above detection limits (refer to attached table 5 and well logs).

In summary, this office is recommending that this case be closed for the following reasons:

Groundwater contamination was only identified in one "grab" groundwater sample collected from the site. The water sample collected from Boring B-8 identified 2,800ppb TPHg and 13ppb benzene, while water samples collected from Boring B-2 and the three monitoring wells did not identify any contaminants above detection limits. Based on the Tier 1 table of the American Society for Testing and Materials' Risk-Based Corrective Action guidelines [E 1739-95] (ASTM RBCA), the levels of benzene identified in this groundwater sample do not exceed human health protective levels for groundwater for a residential property at 10⁻⁵ excess cancer risk. Additionally, the groundwater contaminant plume appears to be stable and limited in extent based on the fact that no groundwater contamination was identified in Well MW-3, located only ~40-feet downgradient from Boring B-8.

- o Analytical results of all the soil samples collected from the site, other than from Boring B-8, identified low concentrations of TPHg and BTEX. Per the ASTM RBCA guidelines, the levels of BTEX in these samples were below the human health protective levels for soil for a residential property at a 10⁻⁵ excess cancer risk. Only one soil sample, out of 24 soil samples identified benzene levels exceeding human health protective levels for a residence at 0.24ppm (from Boring B-8). However, the mean concentration of benzene for all the soil samples on site would be below human health protective levels.
- o Both soil and groundwater contamination identified at the site appear to be limited to the gravelly/clay lenses lying above the primary sandy aquifer, and do not appear to have migrated to the sandy aquifer (refer to attached boring logs and cross-section diagram).
- o There are no water supply wells within 0.25 miles of the site.





EA®

Figure 1. Location and topography, Exxon RS 7-3894, 4868 Calaveras Avenue, Oakland, California.

Drawn ELA	Date 10/23/96
Reviewed	Date
Rev	Date
Final (M	Date 11/21/96
	738941 Stong cd








Figure 2. Site map showing locations of groundwater monitoring wells and soil borings, former Exxon RS 7-3894, 4868 Calaveras Avenue, Oakland, California.

Drawn ELA	Date 10/21/96
Reviewed	Date
Rev	Date
Final (M	Date 11/21/96
	73864\ \site-man fb5




Figure 3. Site map showing geologic cross-section A-A', former Exxon RS 7-3894, 4868 Calaveras Avenue, Oakland, California.

•	
Drawn CTC	Date 10/25/96
Reviewed	Date
Rev	Date /
Final (M)	Date 11/21/96
	73894\\site-map.fh5










TABLE 1 SOIL SAMPLE ANALYTICAL RESULTS (mg/kg), FORMER EXXON RS 7-3894, 4868 CALAVERAS AVENUE, OAKLAND, CALIFORNIA, 5 SEPTEMBER 1995

Sample	Depth			Ethyl-										
Number	(feet)	Benzene	Toluene	benzene	Xylenes	TPH-g	TPH-d	TOG	VOCs	Cd	Cr	Pb	Ni	Zn_
7.1.5	,,,	0.010	0.0006	0.025	0.064	4.5	Mo	NA	NA	NA	NA	NA	NA	NA
B-1-5	5	0.018	0.0086	0.025			ND		NA NA	NA NA	NA.	NA NA	NA	NA
B-1-10	10	ND	ND	ND	ND	ND	ND	NA						
B-2-5	5	. ND	ND	ND	、 ND	ND	ND	NA	NA	NA	NA	NA	NA	NA
B-2-9	9	ND	ND	ND	ND	ND	МД	NA	NA	NA	NА	NA	NA	NA
B-3-5	5	0.027	0.05	0.012	0.061	6.0	ND	NA	NA	NA	NA	NA	NA	NA
B-3-9	9	0.099	0.081	0.031	0.12	21	ND	NA	NA	NA	NA	NA	NA	NA
B-4-5	5	0.048	0.045	0.041	0.063	12	ND	NA	NA	NA	NA	NA	NA	NA
B-4-9	9	0.013	0.013	ND	0.016	2.3	ND	NA	NA	NA	NA	NA	NA	NA
B-5-5	5	ND	ND	ND	ND	ND	ND	NA	NA	NA	NA	NA	NA	NA
B-5-9	9	0.022	0.021	0.023	0.083	3.9	ND	NA	NA	NA	NA	NA	NA	NA
B-6-5	5	ND	ND	ND	ND	ND	ND	NA	NA	NA	NA	NA	NA	NA
B-6-9	9	ND	ND	ND	ND	ND	ND	NA	NA	NA	NA	NA	NA	NA
B-8-10	10	0.24	0.19	0.083	0.23	110	ND	NA	NA	NA	NA	NA	NA	NA
B-6-5	5							ND	ND	0.7	30	1.9	40	260
B-6-9	9							ND	ND	1.8	ND	4.6	36	290

TPH-g	Total Petroleum Hydrocarbons as gasoline.
TPH-d	Total Petroleum Hydrocarbons as diesel.
TOG	Total Oil and Grease.
VOCs	Volatile Organic Compounds.
Cd	Cadmium.
Cr	Chromium.
Pb	Lead.
Ni	Nickel.
Zn	Zinc.
NA	Not analyzed.
ND	Not detected (below laboratory detection limit).

Source: Soil Tech Engineering, Inc.

File No. 8-95-617-SA

TABLE 2 WATER SAMPLES ANALYTICAL RESULTS IN MILLIGRAMS PER LITER (mg/L)

Date	Sample No.	TPHd	TPHg	В	т	B	x	
9/05/95	B-2	ND	ND	ND	ND	ND	ND	
9/13/95	B-8	ND	2.8	0.013	013 0.0067 0.013		0.016	
		(01)-5	2 451	, 7	/ 7	17	11	

(ppb) -> 2,800 13 6.7 13 16

TPHd - Total Petroleum Hydrocarbons as diesel

TPHg - Total Petroleum Hydrocarbons as gasoline

BTEX - Benzene, Toluene, Ethylbenzene, Total Xylenes

ND - Not Detected (Below Laboratory Detection Limit)

TABLE 3 CONSTRUCTION DETAILS OF GROUNDWATER MONITORING WELLS, EXXON 7-3894, 4868 CALAVERAS AVENUE, OAKLAND, CALIFORNIA, 7 AUGUST 1996

Well No.	Elevation Ground (ft msl)	Elevation TOC (ft msl)	Casing Material	Total Depth (ft bgs)	Well Depth (ft bgs)	Borehole Diameter (in.)		Screened Interval (ft bgs)	Slot Size (in.)	Filter Pack Interval (ft bgs)	Filter Pack Material
MW1	151.54	151.33	PVC	31	31	8.25	2	16-31	0.020	14-31	#3 Lonestar Sand
MW2	150.31	149.95	PVC	31	31	8.25	2	16-31	0.020	14-31	#3 Lonestar Sand
MW3	151.44	151.07	PVC	36	36	8.25	2	16-36	0.020	14-36	#3 Lonestar Sand

ft msl feet above mean sea level ft bgs feet below ground surface

TOC top of casing

TABLE 5 SOIL SAMPLE ANALYTICAL RESULTS, FORMER EXXON RS 7-3894, 4868 CALAVERAS AVENUE, OAKLAND, CALIFORNIA, 7 AUGUST 1996

Concentrations (mg/kg) Ethyl-Boring Depth TPH-g **Xylenes** No. Date (ft bgs) Benzene Toluene benzene MW1 0.94 55* 8/7/96 9-10 < 0.05 < 0.05 1.0 < 0.05 < 0.05 0.28 0.39 38* 8/7/96 14 < 0.005 8/7/96 20-21 < 0.005 < 0.005 < 0.005 <1.0 < 0.005 < 0.005 <1.0 8/7/96 29-30 < 0.005 < 0.005 MW2 < 0.005 < 0.005 < 0.005 < 0.005 <1.0 8/7/96 9-11 <1.0 8/7/96 15-17 < 0.005 < 0.005 < 0.005 < 0.005 < 0.005 < 0.005 < 0.005 < 0.005 <1.0 8/7/96 25-27 <1.0 8/7/96 29-31 < 0.005 < 0.005 < 0.005 < 0.005 MW3 8/7/96 10-11.5 < 0.005 < 0.005 < 0.005 < 0.005 <1.0 < 0.005 < 0.005 <1.0 8/7/96 20-21.5 < 0.005 < 0.005 < 0.005 <1.0 8/7/96 30-31.5 < 0.005 < 0.005 < 0.005

ft bgs feet bgs



^{*} Hydrocarbons ranging from C8-C12 were present on the sample chromatogram, indicating weathered gasoline.

mg/kg milligrams per kilogram

TABLE 4 QUARTERLY GROUNDWATER MONITORING AND SAMPLING RESULTS, 4868 CALAVERAS AVENUE, OAKLAND, CALIFORNIA, 1996


		Top of Casing	Depth	Groundwater	LPH			Concentrati	on (μg/L)		
Well		Elevation	to Water	Elevation	Thickness			Ethyl-			
No.	Date	(ft msl)	(ft)	(ft msl)	(ft)	Benzene	Toluene	benzene	Xylenes	TPH-g	MTBE
MW1	08/19/96	151.33	18.11	133.22	0.00	<0.5	<0.5	<0.5	<0.5	<50	<2.5
MW2	08/19/96	149.95	16.68	133.27	0.00	<0.5	<0.5	<0.5	<0.5	<50	<2.5
MW3	08/19/96	151.07	20.51	130.56	0.00	<0.5	<0.5	<0.5	<0.5	<50	<2.5
Rinse Blank	08/19/96					<0.5	<0.5	<0.5	<0.5	<50	<2.5
Trip Blank	08/19/96					<0.5	<0.5	<0.5	<0.5	<50	<2.5

TPH-g Total Petroleum Hydrocarbons as gasoline.

MTBE Methyl t-butyl ether

ft msl Feet relative to mean sea level.

μg/L Micrograms per liter.



' [,	Lopped By Noori Ameli frances Bodonia									
▎├─	Data Dr		/05/95		Exploratory Boring Log Approx, Elevation		Boring No. B-1			
` ├-							Boring Diameter 8-inch			
	_	Mrinos bile dri	ill rig B	-40L		Sampling Method				
Depth, Ft.	Sample No.	Field Test for Total Ionization	Banetration Registance Blows/6"	Unilled Soil Classification	DESC	RIPTION				
1 2 3					Munsell Soil Co Very dark grey Munsell Soil Co	ish-brown silty plor: HUE 10 ker to black sil	OYR 3/3 clay, damp, stiff. OYR 3/2 Lty clay, damp, stiff.			
6 . 7 -	B-1	5		СL	gravelly clay, Munsell Soil Co	hard. plor: HUE 10 nter brown silty	eyish-brown silty pea OYR 4/2 o pea gravelly clay, hard. OYR 4/3			
10. 11. 12. 13.	B1	-10		СL	gravelly clay, h Munsell Soil Col V First groun	nard. or: HUE 10Y adwater encounte brown silty pea or: HUE 10Y	ered at 10 feet. gravelly clay, hard, moist.			
16			·							

Remarks

Loi	gged B	y. Nooi	ri Ameli		Exploratory Boring Log		Boring No. B-2		
Dat	ie Driii	od. 9/05	5/95		Approx, Elevation		Boring Diameter 8-inch		
	u gau MOD.		ll rig B-	40L		Sampling Method			
Depth, Ft,	Sample No.	Field Test for Total Ionization	Penetration Resistance Blower 6"	Unitied Soil Classification	DESC	CRIPTION	·		
1 .					3-inch asphalt, 3-inch dark brown baserock. Munsell Soil Color: HUE 10YR 3/3 Black silty pea gravelly clay, hard. Munsell Soil Color: HUE 5Y 2.5/1				
3 .					Color gets lighter to very dark greyish-brown silty pea gravelly clay, hard. Munsell Soil Color: HUE 10YR 3/2				
5 . 7 .	в-2	-5		с .	Dark greyish-brown silty pea gravelly clay, hard. Munsell Soil Color: HUE 10YR 3/2				
8 9 1 10	3–2–	9		CL.	clay, moist. Munsell Soil Co	olor: HUE 10	ne sandy pea gravelly,		
11				·	Boring terminat	ed at 10 feet.	•		
13 14 15									
16				·····			·		

ا آ.	00000	Rv 37-			<u> </u>					
1 —	te Dell		ori Ameli		Exploratory Boring Log		Boring No. B-3			
"		3/(05/95		Approx Elevation		Boring Diameter 8-inch			
Di		Armod Dile dri	ill rig B	-40L		Sampling Mathod				
Depth, Ft.	Sample No.	Field Test for Total Ionization	Peneirstion Resistance Blows/6"	Unitted Sott Ciessification	DESC	RIPTION				
1					3-inch asphalt, 3-inch dark brown baserock. Munsell Soil Color: HUE 10YR 3/3 Dark olive-grey fine sandy clay, stiff, light petroleum odo Munsell Soil Color: HUE 5Y 3/2					
6	3-3-	5		GT .	petroleum odor. Munsell Soil Col	or: HUE 5y	ight petroleum odor.			
9 E	3-3-9	9		d d	clay, very light Munsell Soil Col Dark greyish-bro petroleum odor. Munsell Soil Col Color changes to	petroleum odd or: HUE 2. wn silty pea g or: HUE dark yellowis	5y 4/2 ravelly clay, very light 2.5y 4/2 h-brown silty clay, hard, damp.			
12					Munsell Soil Cole Boring terminated		YR 4/4			
14 15					·					
Remai	rks									

0-95-017-SA									
10	gged E	y. Noor	i Ameli		Exploratory Boring Log		Boring No. B-4		
Dat	le Drill	°° 9/05	5/95		Approx Elevation		Boring Diameter 8-inch		
Drilling Method						Sampling Mathod			
<u> </u>	Mob	ile dri	ll rig B	-40L	1.				
Depth, Ft.	Sample No.	Field Test for Total Ionization	Penetration Resistance Blowsr 6"	United Sott	DESC	DESCRIPTION			
1					damp, very lig	, dark olive-grey ht petroleum odor olor: HUE 5Y	•		
2					Munsell Soil Color gets dark	er to very dark g	rey silty clay, hard,		
3 •					Munsell Soil Co	oleum odor, damp. lor: HUE 5Y	3/1		
4 5 .	3–4-	5		CT.	Color changes to olive-brown silty gravelly clay, hard. Munsell Soil Color: HUE 2.5Y 4/4				
6 .						.			
7 - 8		-			·				
9 10	B-4-	.9		CT .	petroleum odor. Munsell Soil Co	lor: HUE 2.5	hard, very light		
11					Boring terminat	ed at 10 feet.			
12 13			٠						
14									
15							·		
16							• .		
Ren	nerks						•		

Remarks

Date Dril		ori Ameli 05/95		Exploratory Boring Log Approx. Elevation		Boring Diameter 8-inch
Drilling &	elhod	ill rig E	3-40L	Sampling Method		1 0-11.51
Depth, Fl. Sample No.	Field Test for Total Ionization	Denetration Restatement Blows/6"	Unitied Soll Classification	DESC	RIPTION	
1 2 3 4 5 B-5-6 7 8 9 B-5-10 11 12 13 14 15 16			ст .	4-inch asphalt Munsell Soil Co Black silty cla Munsell Soil Co Color gets ligh gravelly clay, Munsell Soil Co Color gets ligh Munsell Soil Co Color gets ligh Munsell Soil Co Munsell Soil Co	d-inch dark olor: HUE ay, hard. olor: HUE at the dark olor: HUE attented to dark olor: HUE attented to olive to dark olor: HUE at the dark olor: HUE attented to olive to dark olive olor: HUE	brown baserock. 10YR 3/3 5Y 2.5/1 Dlive-grey silty 5Y 3/2 brown silty gravelly clay, hard. 10YR 3/3 Drown silty gravelly 2.5Y 4/4 -grey silty gravelly 5Y 3/2

Remarks

Drilling Method Mobile drill rig B-40L DESCRIPTION 3-inch asphalt, 3-inch dark olive-grey baserock. Munsell Soil Color: HUE 5Y 3/2 Color gets darker to very dark grey silty clay, hard. Munsell Soil Color: HUE 10YR 3/1 Color changes to olive-brown silty clay with minor pea gravel, hard. Munsell Soil Color: HUE 2.5Y 4/4						
Mobile drill rig B-40L						
3-inch asphalt, 3-inch dark olive-grey baserock. Munsell Soil Color: HUE 5Y 3/2 Color gets darker to very dark grey silty clay, hard. Munsell Soil Color: HUE 5Y 3/1 Color gets lighter to very dark grey silty clay, hard. Munsell Soil Color: HUE 10YR 3/1 Color changes to olive-brown silty clay with minor pea gravel, hard. Munsell Soil Color: HUE 2.5Y 4/4						
Munsell Soil Color: HUE 5Y 3/2 Color gets darker to very dark grey silty clay, hard. Munsell Soil Color: HUE 5Y 3/1 Color gets lighter to very dark grey silty clay, hard. Munsell Soil Color: HUE 10YR 3/1 CL Color changes to olive-brown silty clay with minor pea gravel, hard. Munsell Soil Color: HUE 2.5Y 4/4						
Color gets lighter to very dark grey silty clay, hard. Munsell Soil Color: HUE 10YR 3/1 CL Color changes to olive-brown silty clay with minor pea gravel, hard. Munsell Soil Color: HUE 2.5Y 4/4						
pea gravel, hard. Munsell Soil Color: HUE 2.5Y 4/4						
9 B-6-9 CL Olive-brown silty gravelly clay, hard. Munsell Soil Color: HUE 2.5Y 4/4						
Color changes to dark olive-grey fine sandy gravelly clay, moist, very light petroleum odor.						
Munsell Soil Color: HUE 5Y 3/2 Color changes to olive-brown fine sandy clay, stiff. Munsell Soil Color: HUE 2.5Y 4/4	Munsell Soil Color: HUE 5Y 3/2 Color changes to olive-brown fine sandy clay, stiff.					
14	•					
16	;					


8-95-617-SA

Data Dilliad 9/05/95					Exploratory Boring Log		Boring No B-6 Boring Diameter 8-inch		
Dill	Imp Mi Mob	rihođ	ll rig B-	-40L	Eampling Mathod				
Decth, Fr.	Semple No.	Field Test for Total Ionization	Donele ellon Pasiet ence Blower5	Unined Sell Clessification	DES	CRIPTION			
17				CIT	Color changes t Munsell Soil Co	to olive-brown blor: HUE	fine sandy clay, stiff. 2.5y 4/4		
18					Olive-brown fir Munsell Soil Co	ne sandy clay, olor: HUE	stiff. 2.5y 4/4		
19 ·							•		
21.			,						
22. 23.									
24									
25 .					,				
26. 27									
28							•		
29 · 30									
31.									
32									
Remarks									

Log	pod E	y Nooi	ci Ameli		Exploratory Boring Lop		Boring No. B-7			
Det	• Driii	• 9/13	3/95		Approx. Elevation		Boring Diameter 8-inch			
Drift		oile dri	ill rig B	-40L		Sampling Mathod				
Depth, Ft.	Sample No.	Field Test for Total Ionization	Peneltetion Antietence Blows/6"	Unified Soft Clessification	DESC	DESCRIPTION				
1 2				ст	3-inch asphalt, 3-inch dark brown baserock. Munsell Soil Color: HUE 10YR 3/3 Dark Olive-grey fine sandy clay, stiff, light petroleum odd Munsell Soil Color: HUE 5Y 3/2					
3 . 5 . 6 .				CL.	light petroleum Munsell Soil Co Black silty cla	lor: HUE 5Y	2.5/1 ht petroleum odor.			
8 9 10					Color changes t clay, very ligh Munsell Soil Co	t petroleum odor.				
11. 12. 13				· :	Color changes to Munsell Soil Co	o dark yellowish- lor: HUE 10YR	brown silty clay, hard, damp. 4/4			
14 15				CL.	Dark yellowish- Munsell Soil Co Boring terminat					
16 Rem	narks		•				•			

10		V Noor	i Ameli		Exploratory Boring Log		Boring No. B-8			
1		•ø 9/13			Approx. Elevation		Boring Diameter 8-inch			
							0-11611			
Dri	Mob		ll rig B-	-40L		Sampling Method				
Deoth, Ft.	Sample No.	Field Test for Total Ionization	Penetrellon Resistance Blows/6"	Unified Soil	DESC	CRIPTION				
1 2 3 4 5 6 7 7 8 9 10. 11. 12. 13. 14. 15. 16.		_1°O		ਰ ਰ	Very light pet. Munsell Soil Co Color gets dar. hard, very light Munsell Soil Co Color changes to Munsell Soil Co Olive-brown sil petroleum odor. Munsell Soil Co	color: HUE 5Y ker to very dark the petroleum odor color: HUE 5Y co olive-brown sil lor: HUE 2.5Y ty gravelly clay, clor: HUE 2.5Y	3/2 grey silty clay, , damp. 3/1 ty gravelly clay, hard. 4/4 hard, very light			
Rei	Remarks									

WELL COMPLETION DIAGRAM FOR GROUNDWATER MONITORING WELL MW1






EA ENGINEERING, SCIENCE, AND TECHNOLOGY

Client: Exxon Company, U.S.A.

Site: RS 7-3894

Location: 4868 Calaveras Avenue, Oakland, California.

WELL COMPLETION DIAGRAM FOR GROUNDWATER MONITORING WELL MW2






EA ENGINEERING, SCIENCE, AND TECHNOLOGY

Client: Exxon Company, U.S.A.

Site: RS 7-3894

Location: 4868 Calaveras Avenue, Oakland, California.

WELL COMPLETION DIAGRAM FOR GROUNDWATER RECOVERY WELL MW3





EA ENGINEERING, SCIENCE, AND TECHNOLOGY

Client: Exxon Company, U.S.A.

Site: RS 7-3894

Location: 4868 Calaveras Avenue, Oakland, California.