### **HEALTH CARE SERVICES**

#### **AGENCY**



DAVID J. KEARS, Agency Director

September 12, 2000 StID # 1068 ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway. Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

#### REMEDIAL ACTION COMPLETION CERTIFICATION

Exxon-Mobil Co. Mr. Darin Rouse P.O. Box 4032 Concord, CA 94524-4032 Resources for Community Development Ms. Lisa Motoyama 2131 University Ave., Ste. 224 Berkeley, CA 94704

RE: 6600 E. 14th St., Oakland 94621

Dear Mr. Rouse and Ms. Motoyama:

This letter confirms the completion of site investigation and remedial action for the one (1) 550 waste oil and the three (3) 10,000 gallon gasoline tanks formerly located at the above described location. Thank you for your cooperation throughout this investigation. Your willingness and promptness in responding to our inquiries concerning the former underground tank is greatly appreciated.

Based on information in the above-referenced file and with provision that the information provided to this agency was accurate and representative of site conditions, this agency finds that the site investigation and corrective action carried out at your underground storage tank(s) site is in compliance with the requirements of subdivisions (a) and (b) of Section 25299.37 of this Health and Safety Code and with corrective action regulations adopted pursuant to Section 25299.77 of the Health and Safety Code and that no further action related to the petroleum release(s) as the site is required.

This notice is issued pursuant to subdivision (h) of Section 25299.37 of the Health and Safety Code.

Please contact Barney Chan at (510) 567-6765 if you have any questions regarding this matter.

Sincerely,

Mee Ling Tung

Director, Environmental Health

Mr. D. Rouse & Ms. L. Motoyama StID # 1068 6600 E. 14<sup>th</sup> St., Oakland CA 94621 September 12, 2000 · Page 2

c: B. Chan, Hazardous Materials Division-files

Mr. Chuck Headlee, RWQCB Mr. Allan Patton, SWRCB Cleanup Fund

Mr. Leroy Griffin, City of Oakland OES, 1605 Martin Luther King Dr., Oakland CA 94612

RACC6600B14thSt

#### ALAMEDA COUNTY

#### **HEALTH CARE SERVICES**

#### **AGENCY**



DAVID J. KEARS, Agency Director

September 14, 2000 StID# 1068

ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway. Suite 250

Mr. Darin Rouse Exxon-Mobil Co. P.O. Box 4032 Concord CA 94524-4032 Ms. Lisa Motoyama Alameda. CA 94502-6577 Resources for Commin 10 167 6708 evelopment 2131 University Ave., Ste. 224 Berkeley, CA 94704

RE: Fuel Leak Site Case Closure, 6600 E. 14<sup>th</sup> St., Oakland CA 94621

Dear Mr. Rouse and Ms. Motoyama:

This letter transmits the enclosed underground storage tank (UST) case closure letter in accordance with the Health and Safety Code, Chapter 6.75 (Article 4, Section 25299.37 h). The State Water Resources Control Board adopted this letter on February 20, 1997. As of March 1, 1997, the Alameda County Health Services, Local Oversight Program (LOP) is required to use this case closure letter. We are also enclosing the case closure summary. This document confirms the completion of the investigation and cleanup of the reported release at the subject site.

#### Site Investigation and Cleanup Summary:

Please be advised that the following conditions exist at the site:

- \* 13 parts per million (ppm) Total Petroleum Hydrocarbons as gasoline (TPHg), 25 ppm TPH as diesel, and 0.037 and 0.075 ppm toluene and xylenes, respectively remain in the soil at the site.
- 160 parts per billion (ppb) TPH as gasoline, 180 ppb TPH as diesel, 12 ppb benzene and 420 ppb MTBE remain in the groundwater at the site.

This site should be included in the City's permit tracking system. You may contact me at (510) 567-6765 if you have any questions.

Sincerely,

Barney M. Chan

Hazardous Materials Specialist

enclosures: Case Closure Letter, Case Closure Summary

c: Mr. L. Griffin, City of Oakland OES, 1605 MLK Jr. Way,

Oakland CA 94612

/B. Chan, files (letter only)

Trlt6600E14thSt

# CASE CLOSURE SUMMARY Leaking Underground Fuel Storage Tank Program

I. AGENCY INFORMATION Date: June 16,2000

Agency name: Alameda County-HazMat Address: 1131 Harbor Bay Parkway

Rm 250, Alameda CA 94502

City/State/Zip: Alameda Phone: (510) 567-6700

Responsible staff person: Barney Chan Title: Hazardous Materials Spec.

#### II. CASE INFORMATION

Site facility name: Former Exxon Station

Site facility address: 6600 E. 14th St., Oakland CA 94621

RB LUSTIS Case No: N/A Local Case No./LOP Case No.: 1068

ULR filing date: 4/3/91 SWEEPS No: N/A

Responsible Parties:	Addresses:	Phone Numbers:
1. Exxon-Mobil Co. c/o Mr. Darin Rouse	P.O. Box 4032 Concord, CA 94524-4032	925-246-8768
<ol> <li>Resources for Community Development c/o Ms. Lisa Motoyama</li> </ol>	2131 University Ave. Suite224 Berkeley, CA 94704	510-841-2210 x19

Tank No:	Size in gal.:	<u>Contents:</u>	<pre>Closed in-place   or removed?:</pre>	Date:
1	550	waste oil	removed	12/20/96
2	10,000	gasoline	removed	"
3	10,000	gasoline	removed	"
4	10,000	gasoline	removed	"

#### III RELEASE AND SITE CHARACTERIZATION INFORMATION

Cause and type of release: possibly from releases from the dispenser

Site characterization complete? Yes

Date approved by oversight agency:

Monitoring Wells installed? Yes Number: 14: 11 monitoring, 3 VEWs

#### Leaking Underground Fuel Storage Program

#### III RELEASE AND SITE CHARACTERIZATION INFORMATION

Proper screened interval? Yes, generally screened from 3-25' bgs

Highest GW depth: 4.4'bgs Lowest GW depth: 13.0' bgs

Flow direction: from south-45 degrees west

Most sensitive current use: commercial/industrial, however residential

housing is planned on the site

Are drinking water wells affected? No Aquifer name: NA

Is surface water affected? No Nearest affected SW name: NA

Off-site beneficial use impacts (addresses/locations): NA

Report(s) on file? Yes Where is report(s)? Alameda County

1131 Harbor Bay Parkway, Room 250, Alameda CA 94502-6577

and City of Oakland, OES 1605 Martin Luther King Dr. Oakland CA 94612

#### Treatment and Disposal of Affected Material:

Material	Amount (include units)	Action of Dispose	(Treatmental w/desti		Date
Tanks	3- 10,000 1- 550	Disposed @	Erickson,	Richmond	12/20/96
	2- hydraulic lift	W.	· ·	'W	n
Soil	511 tons 18 tons	Disposed @	BFI Landf:	ill	2/6/97 2/25/97
	197 tons	<b>u</b>	n n		12/97
	151 tons	w.	" "		4/98

#### Leaking Underground Fuel Storage Program

Maximum Documented Contaminant Concentrations - - Before and After Cleanup

Contaminant	Soil 1Before	<b>l (ppm)</b> <b>2</b> After	Water (ppb) 3Before After 4
TPH (Gas)	350	13	160
TPH (Diesel)	56	25	180
Benzene	1.4	ND	12
Toluene	0.22	0.037	ND
Ethylbenzene	2.7	ND	ND
Xylenes	18	0.075	ND
TRPH (418.1)	590		
HVOC's	ND		
Semi-volatiles	ND		
MTBE	1.2		420
11 1 7 (0.1 0.	~~1 3T' C . \ 3TT		

Heavy metals (Cd, Cr, Pb, Ni, Zn) ND, 69, 13, 120, 70

Comments (Depth of Remediation, etc.):

- 1 Samples from tank removals on 12/20/96
- 2 Samples from over-excavation of the dispenser area, no over-excavation of the hydraulic lift area was performed
- 3 no groundwater was encountered during the tank removals
- 4 1/27/00 monitoring results for MW2

#### IV. CLOSURE

Does completed corrective action protect existing beneficial uses per the Regional Board Basin Plan? Undetermined

Does corrective action protect public health for current land use? YES

Site management requirements: site should be included in the City of Oakland Permit Tracking System. A site health and safety plan will be required for any subsurface work.

Should corrective action be reviewed if land use changes? Yes

Monitoring wells Decommisioned?: No

Number Decommissioned: 8 Number Retained: 6

List enforcement actions taken: None

List enforcement actions rescinded: NA

#### Leaking Underground Fuel Storage Tank Program

#### v. LOCAL AGENCY REPRESENTATIVE DATA

Name: Barney M. Chan

Title: Hazardous Materials Specialist

Signature:

Barney in Cha-

Date: 6-26-00

Reviewed by

Name: Tom Peacock

Title: Manager

Signature:

Date: 6-76-00

Name: Eva Chu

Title: Hazardous Materials Specialist

Signature: W7

Date: 6/20/00

VI. RWQCB NOTIFICATION

Date Submitted to RB:

RB Response:

RWQCB Staff Name: C. Headlee

Title: AEG Date:

VII. ADDITIONAL COMMENTS, DATA, ETC.

See attached site summary.

Page 4 of 4

Site Summary for 6600 E. 14th St., Oakland CA 94621 StID # 1068

This site is located on the north side of E. 14<sup>th</sup> St. (International Blvd.), between 66<sup>th</sup> Ave. and Havenscourt Blvd. This block consists of two parcels, 6600 E. 14<sup>th</sup> St., the western parcel that was a former Exxon service station and 6630 E. 14<sup>th</sup> St., the eastern parcel, that was a former Texaco station. See Figures 1 and 2. The two parcels are tied because Exxon assumed responsibility for all environmental issues for both parcels.

It addition, because of the presence of former USTs on both parcels, there's a possibilty of commingling of releases from the sites. It is believed that the USTs on 6630 E. 14<sup>th</sup> St. were removed in 1966, when the Texaco station was torn down, however, there are no reports documenting this. There are also no records on the number or locations of USTs on this parcel. A summary of the documented environmental investigations conducted at the two parcels is detailed below.

June 14, 1988- Texaco installed monitoring wells MW-7A through MW-7C, see Plate 6. No monitoring information was obtained from these wells and it appears that these wells were closed by Texaco in September 1988, although no formal closure report was provided. Exxon later assumed site liability and initiated their own investigation.

March 1991- Exxon installed three monitoring wells, MW1 through MW3, to investigate potential releases from the USTs on 6600 E. 14<sup>th</sup> St.. MW1 was located just on the 6630 E. 14<sup>th</sup> St. parcel, MW2 was located down-gradient of the USTs and dispensers and MW3 was located cross-gradient of the USTs on 6600 E. 14<sup>th</sup> St. See Figure 2, Table 1 and accompanying well logs. Soil samples from the borings contained up to 98 ppm TPHg and 0.074, 0.12, 0.24, 0.19 ppm BTEX, respectively. Groundwater exhibited up to 3100 ppb TPHg, 160 ppb TPHd and 190, 2.6, 100, 84 ppb, BTEX, respectively. Since this time to the present, the highest groundwater contamination has been found in MW-2.

May 1992- Exxon installed four additional groundwater monitoring wells, MW4- MW7 both on and off-site, to further delineate the plume. Little to no petroleum contamination was observed in the borings from these wells. Subsurface soils were similar to that encountered in wells MW1 through MW3. Beneath the asphalt cap, one encountered silty clay to about 14' bgs where groundwater was encountered in sandy clay. Groundwater rises to about 8-10'bgs. Groundwater monitoring has consistently detected TPHd, TPHg and BTEX only in MW-2 and MW-3. See Figure 3 for the monitoring well locations, Figure 4 for a cross-section diagram from MW-4 to MW-7, Table 2 for analytical and accompanying well logs. MW-5 was located approximately 160' down-gradient of MW-2, the most impacted well.

November 1993- Exxon installed three soil vapor extraction wells, VE1 through VE3 and two borings, B-1 and B-2. One of the vapor wells (VE-2) and one of the borings (B-2) were advanced below groundwater (about 12' bgs), where a grab water sample was taken. Soil samples were taken from all five borings. Low levels of TPH were detected in the soil samples. The highest groundwater sample was from S-B-2, cross-gradient to the dispensers. See Plate 1 & Table 3.

Site Summary for 6600 E. 14<sup>th</sup> St., Oakland CA 94621 StID # 1068 Page 2.

**December 1993-** Exxon performed a SVE feasibility test and a groundwater extraction feasibility test. The SVE consisted of the three vapor extraction wells and wells MW-1 and MW-2. A step-drawdown test was performed on MW-2 at three rates. SVE and groundwater extraction were determined not to be feasible alternatives.

**February 1996-** Exxon submitted a CAP recommending passive bio-remediation based upon fate and transport estimation for site contaminants. Excavation was not recommended since this was an on-going operating station, but would be considered upon the closure of the station or removal of the tanks. It is noted, however, that Exxon's evaluation was using a model for the migration and attenuation of benzene, not MTBE. To enhance natural attenuation, in September 1996, Exxon installed ORC socks in wells MW1, MW2, MW3 and MW6.

December 1996- The existing service station was destroyed, the three 10, 000 gallon gasoline fuel tanks and one 550 gallon used oil tank were removed along with the product lines and two hydraulic hoists. Soil samples were taken from a depth of 9-9.5'bgs along the sidewalls of UST pit. One soil sample from beneath the waste oil tank pit was taken, as were samples from beneath the two hydraulic hoists and from beneath each of the dispensers. See Plate 2 and Tables 4 & 5 for the results of these samples. Generally, very low levels of TPHg, BTEX and MTBE were found in the samples from the tank pit. The highest TPHg contamination was exhibited in soil samples from beneath the southernmost dispensers, D2 and D3. Up to 350 ppm TPHg and 1.4, 0.13, 2.7 and 18 ppm, BTEX, respectively was found. Based upon these results, over-excavation was later performed.

January 1997- Exxon destroyed two off-site wells (MW1 and MW7) and three on-site SVE wells (VE1 through VE3) and installed one replacement monitoring well, MW8 on 6600 E. 14<sup>th</sup> St., near the northernmost dispenser. The monitoring wells were destroyed to allow Exxon to divest their interest in 6630 E. 14<sup>th</sup> St. See Plate 3, Table 6 and accompanying well log.

**February 1997-** Exxon performed a geophysical survey on 6630 E. 14<sup>th</sup> St., parcel 1, searching for additional USTs. Three areas were discovered with magnetic anomalies. The contractor stated that the anomalies were not large enough to be a group of underground fuel tanks, however, it was possible that one of the anomalies could be a small UST such as a waste oil tank, as was recently confirmed. **See drawing 3 indicating the three areas.** 

May 1997- The two of the three magnetic anomaly areas were excavated and no additional USTs were discovered. The third area was located adjacent to the boundary of the two parcels and was not probed due to its proximity to the sidewalk. Apparently, the probing missed the recently detected UST near the boundary of 6600 and 6630 E. 14<sup>th</sup> St..

December 1997- Exxon excavated approximately 197 tons of soil from the former dispenser areas, D2 and D6, and adjacent to MW8. Soil was excavated to a depth of 10' bgs and confirmation soil samples were taken at the limits of the excavation. See Plate 4 & Table 7.

Site Summary for 6600 E. 14<sup>th</sup> St., Oakland CA 94621 StID # 1068 Page 3.

January 1998- Exxon drilled two soil borings SB1 and SB2 and collected soil samples. The purpose of these borings was to determine the lateral extent of the contamination found in boring S-9-D6 in the easterly direction. The soil samples collected at a depth of 6' exhibited ND for TPHg, BTEX and TPHd.

April 1998- Exxon excavated approximately 151 tons of soil in the area between the former northernmost dispenser and SB1 and SB2. See Plate 4 and Table 7 for the results of both excavations. Both excavation soil piles, approximately 348 cubic yards, were disposed at BFI Landfill in Livermore.

April 1999- Exxon performed a sensitive receptor and underground utility survey to primarily determine the potential migration and impact of the MTBE release. No municipal or private wells were located within a 2,000 feet radius of the site. No domestic water wells were located within 1000 feet of the site. No surface water bodies were identified within a 2500 feet radius of the site and no basements were observed in buildings within a 1000 feet radius of the site.

The utility survey identified electric, gas, sewer, telephone, storm drain, cable TV and water lines lying either on the sidewalk or within E. 14<sup>th</sup> St., however, since the first encountered groundwater lies approximately 16' bgs, only a sewer interceptor lying 22' bgs, might act as a pathway for groundwater.

October 1999- Exxon performed an off-site investigation to determine the extent of the MTBE in soil and groundwater. Borings SB1 through SB3 were drilled immediately down-gradient of MW2: within the property boundary, within the median and within the southern curb on E. 14<sup>th</sup> St., respectively. These borings were hand augered to approximately two feet below first-encountered groundwater and sampled using a disposable bailer. At the same time a water sample from MW2 was also collected for chemical analysis. The groundwater sample from SB1, approximately 15' down-gradient of MW2, exhibited 18,000 ppb TPHg, 46, ND, 1200, 64, 1900 ppb BTEX and MTBE, respectively. The groundwater samples from SB2 and SB3 did not detect any analytes. MW2 exhibited 1800 ppb TPHg, 8.6,ND,ND, ND, 1300 ppb BTEX and MTBE, respectively. The results from SB1 indicate the petroleum release has migrated down-gradient, however, the results from SB2 and SB3 indicate that the plume has not migrated significantly off-site. See Plate 5 and Table 8. A couple of cross-sections on and off-site are also provided.

The MTBE release appears confined to an area near MW-2. An iso-concentration map of MTBE is provided, See Plate 7, as well as a similar map for benzene seen on Plate 8. A rose diagram provided indicates a fairly consistent south-southwest gradient. See Plate 9. Table 10 provides the cumulative groundwater monitoring data.

Site Summary for 6600 E. 14<sup>th</sup> St., Oakland CA 94621 StID # 1068 Page 4.

**December 1999-** Exxon submitted a RBCA and requested site closure. The RBCA used the maximum value for BTEX in soil and groundwater to determine risk. The exposure pathways considered viable were:

- Surface soil direct ingestion and dermal contact (residential receptor)
- Surface soil volatilization to indoor air (inhalation: residential receptor)
- Surface soil volatilization to outdoor air (inhalation: residential receptor)
- Subsurface soil volatilization to outdoor air (inhalation: residential receptor)
- Subsurface soil volatilization to indoor air (inhalation: residential receptor)
- Groundwater volatilization to indoor air (inhalation: residential receptor)
- Groundwater volatilization to outdoor air (inhalation: residential receptor)

All surface soil samples were taken from the February 21, 2000 Clayton Phase II Site Assessment. See Figure 5 and Table 9. The surface soil samples were shallow composite samples from borings B-3, B-11, B-12, B-13 and B-14. Only sample B-12 detected any TEX, while all samples were ND for benzene. The highest subsurface soil, S-9-D6, with a benzene concentration of 0.62 ppm, was used to evaluate subsurface soil risk. The maximum benzene concentration within the past year, 0.1 ppm from MW-2, was used to evaluate risk from groundwater. Neither of these maximum concentration values exceeded their respective SSTL Please refer to the GSI input table, work sheets and summary of data points.

February 18, 2000- Spoke with Ms. L. Motoyama of RCD (Resources for Community Development) the new property owner of both 6600 and 6630 E. 14<sup>th</sup> St., and was notified that their consultant, Clayton Environmental, had discovered an apparent waste oil tank on 6630 E. 14<sup>th</sup> St. property. Clayton also performed a Phase II investigation for RCD who plan a multi-unit housing complex on the combined parcels. This investigation consisted of two elements. One was performing an extensive geophysical survey using vertical magnetic gradient (VMG), terrain conductivity (TC), metal detection (MD) and ground penetrating radar (GPR), all in an attempt to identify the existence of UST, piping or back-filled excavations. See Table 11 and Plates 8 and 9. Table 11 lists the six magnetic anomalies identified by VMG and the results of physical probing in these areas. These six locations are shown on Plate 9. Plate 8 shows the results of the TC survey. It is interesting that two areas labeled A & B are noted as possible zones of backfill. Area a is the area of the former USTs and the over-excavation, while area B is most likely the area of the former Texaco USTs.

The second element consisted of advancing 14 temporary borings and sampling soil and groundwater from these borings. Six select soil samples (based upon PID readings) were analyzed for TPH as motor oil, as diesel and as gasoline, BTEX, MTBE, volatile organics and the five heavy metals analyzed for waste oil tanks. The two-point composite soil samples were taken from 2 and 4 feet bgs. Very little contaminants were found in the shallow soil samples. The only significant contaminants was the presence of TPHmo,d and g in the grab groundwater samples from borings B-2 through B-5. Up to 1600, 1300 and 1700 ppb TPHmo,d,g, respectively was found in these samples. No benzene or toluene was found. Up to 8.7 ppb ethylbenzene, 1.5 ppb xylenes and 18 ppb MTBE were also reported in groundwater. See Tables 9,12 and Figure 5,

Site Summary for 6600 E. 14<sup>th</sup> St., Oakland CA 94621 StID # 1068 Page 5.

The source of the release may be from former USTs on Parcel 1, (6630 E. 14<sup>th</sup> St.) or from both Parcel 1 and Parcel 2, (6600 E. 14<sup>th</sup> St.). The concentrations in these grab groundwater samples are similar to that found in MW-2 on Parcel 2, the well down-gradient of the former USTs and dispensers. Extensive monitoring of MW-2 indicates that the fuel release is limited in extent and no risk to human health or environment is expected. The petroleum release on Parcel 1 is either from the former USTs on Parcel 1, assumed to have been removed in 1966, or from the former USTs on Parcel 2, removed in 1996. Therefore, it is safe to say that the release to groundwater on Parcel 1 is no more a threat as that from Parcel 2, which we know is not a threat. In addition, the City of Oakland has recently issued a no further action for the waste oil tank removal.

In summary, site closure is recommended for 6600 E. 14<sup>th</sup> St. and no further action for 6630 E. 14<sup>th</sup> St. based upon:

- Adequate source removal has occurred. The underground tanks have been removed from both sites and extensive over-excavation of soil has occurred on 6600 and to lesser degree at 6630 E. 14<sup>th</sup> St.
- Both parcels have been adequately characterized. Although less sampling has occurred on 6630 E. 14<sup>th</sup> St., the site has had a thorough geophysical examination. No underground tanks appear to remain and a large area of possible backfill was identified from where the former underground tanks likely were removed. Low levels of dissolved petroleum hydrocarbons were identified down-gradient to this area. Although subsurface sampling was not done in this area, based upon the concentration of petroleum hydrocarbons detected in groundwater on Parcel 1, it is not likely that high concentrations of hydrocarbon remain in soil.
- The groundwater plume is not migrating. The down-gradient well, MW-7, has not been impacted over many years of monitoring. The MTBE found on-site has not been found offsite.
- No sensitive receptors are likely to be impacted.
- The site poses no significant risk to human health or the environment. The proposed residential development will be built on a concrete slab foundation, therefore the lack of subsurface soil data on Parcel 1 is not as critical.

Ss6600E




FIGURE 1: SITE VICINITY MAP

EXXON COMPANY, U.S.A. SERVICE STATION NO. 7 - 0236 6630 EAST 14TH STREET OAKLAND, CALIFORNIA


**PROJECT NO. 30 - 491** 

0 2000 SCALE IN FEET

SOURCE: U.S.G.S. MAP OAKLAND EAST QUADRANGLE CALIFORNIA. 7.5 MINUTE SERIES (TOPOGRAPHIC) PHOTOED 1959. PHOTOREVISED 1980




ALTON GEOSCIENCI 1000 Burnett Ave., Ste. 140 Concord, CA 94520




GROUND WATER MONITORING WELL

- 1. Contour lines are interpretive based on water level reading recorded on
- 3. Average Hydraulic Gradient = 0.03

ALTON GEOSCIENC 1000 Burnett Ave., Ste. 140 Concord, CA 94520





## TABLE? - SUMMARY OF ANALYTICAL RESULTS FOR SOIL SAMPLES

#### Exxon Company, U.S.A. Exxon Service Station No. 7-0236 6630 East 14th Street Oakland, California

Alton Geoscience, Inc. Project No. 30-491

Well No.	Depth (in feet)	TPH-G	В	T	Е	X
Date of	Sampling - M	arch 13,	Concentrations 1991	in Parts Per	Million	
MW-1	6-6.5	ND<1	ND<0.003	ND<0.003	ND<0.003	ND<0.003
MW-1	11-11.5	ND<1	ND<0.003	ND<0.003	ND<0.003	ND<0.003
MW-1	16-16.5	ND<1	ND<0.003	ND<0.003	ND<0.003	ND<0.003
MW-2	6-6.5	2	0.008	0.018	ND<0.003	0.025
MW-2	11-11.5	98	0.074	0.12	0.24	0.19
MW-2	16-16.5	ND<1	0.051	ND<0.003	0.018	0.009
MW-3	6-6.5	ND<1	0.009	ND<0.003	ND<0.003	0.01
MW-3	11-11.5	ND<1	ND<0.003	ND<0.003	ND<0.003	0.018
MW-3	16-16.5	ND<1	ND<0.003	ND<0.003	ND<0.003	0.004

#### Note:

TPH-G = Total petroleum hydrocarbons

B = Benzene T = Toluene

E = Ethylbenzene

X = Xylenes

ND = Not detected above the reported method detection limits

NA = Not analyzed

	ALTON GEOSCIENCE, Inc. LOG OF EXPLORATORY BORING FIELD SKETCH OF BORING LOCATION									CLIENT_ LOCATIO	Exxor N 14	30-491 n Company, U. hth St. & 66th A W. Shipp A	S.A. ve., Oa	akland	-	BORING NO. WELL NO. MW-1
F	IELD S	SKE	FCH	OF E	SORING LO	CATION	į								HO! E D!	AM10"
												HOD <u>CME 75</u> E <u>Modified sp</u>			_	
												4" PVC, 0.02				
١,	70P.0	e Ci	LSIN	IG EI	EVATION_	100.00	) <b>'</b>					st Hazmat Drilli				
'	<u> </u>		<b>1011</b>							<u> </u>		7.44*	<b>—</b>	·	T	
Γ	<u>ن</u> ک	) **.		æ.				<b> </b> -		PTH TO WA	TER	3/15/91				
	50.	Į.	H	프	Alell		ی	#OFILE		ME		0900				
	1 /2 FOOT	CGI(PPM)	SAMPLE	DEPTH (Ft)	S 4ell		33 35 3	Ě	!.	WIL.		E	ESCF	RIPTION		
H		<b>)</b>	H	_	Christy Bo	x			_							
				-0				1111		" Asphalt, 5"	Hoad	ned from	1,	+26		
	20,28, 32	0	I	4 6 8	4" sch. 40 PVC Casing		CL			CLAY: dark o	ray, mo	sist, hard, mediu d, 1% organics.	ım plas		1-2% ang	jular medium-
	12,18, 18	0		12					•	SELTY CLAY	: mediu 1%	m brown, moist, angular gravel t	, hard, r o 1/2".	nedium plast	ic, 5% an	gular sand,
	12,15 18	. 0		10	6 4" sch. 40					SANDY CLA Z	Y: brov sa	vn, wet, hard, k and, 5% angular	ow plas gravel t	ticity, mediur o 1".	n to coars	se grained
	8,16, 21			2	O Slot 2		S			Same, beco	mes s	aturated, grave	ls to 1/	<b>4</b> *.		
	13,16 20 12,16 24 7,14	в,			End Ca			CL		Same as al	and, 1-2 bove.	st, hard, medium % organics. very stiff, 1-2%			3% mediu	am grained
	18		١	t	30	Portla	nd	Ceme	nt	BORING T	TERMIN	ATED AT 29.5	EET B			
				-   -	32			Lone			Drive	n interval	포			ered during drilling
			.	Ţ.	34			e Pell			Sатр	le	Ŧ	Stabilized	water lev	/el


LOX BOI	3 D RIN	F E G	XPL	SCIENCE, In ORATORY				CLIENT_ LOCATIO	Exxo 2N _14	30-491 n Company, U.S tth St. & 66th Av W. Shipp Al	6.A. /e., O	akland	3/13/91	BORING NO. WELL NO. MW-2
FIELD	SKE	TC	(OF	BORING LOCATI	ON									
								1		10D <u>CME 75</u>			HOLE DI	AM_ 10"
										Modified spl				<u>.                                    </u>
1								L		4" PVC, 0.020				
TOP	)FC	ASI	VG El	EVATION _ 98.9	34'	-		DRILLER	We	st Hazmat Drillin	g Con	p		
					Т		D	EPTH TO WA	TER	9.05'				
1 2 2	Ŧ	111	E	₩eii Construction		Lat	-	ATE		3/15/91				
85	E	Æ	PEPTH	s tru	8	PROFILE	7	IME		0900				
BLOWS PER 1/2 FOOT	CGI (PPM)	SAMPLE	Ä	%eil Cons	8	Ě				D	ESCF	RIPTION		
	-	-	-0	Christy Box	上									
1			- 0			1111	نط	3" Asphalt, 5"	Road	Base	//	<u> </u>		
14,24, 26	0		-2 -4 -6 -8	sch. 40 PVC / Casing	CI					ed 5-2°		stic, ~ 10% <b>s</b> i	it, 1-2% (	oorganics.
11,13, 15	. 0		10 12 14					SILTY CLAY:	mottle to c	d(brown with oli parse grained sar	ve pat	ches), moist,	very stiff	, 5% medium
12,18 21			16	sch. 40 PVC .020	S		<u>P</u>	SANDY CLAY	Y: brow su	rn, wet, hard, lov brounded sand,	v plast 1-3% r	ticity, medium coot trace.	-grained	angular tı
18,25 29	i.		22	Fnd Can			XXXX	Same, with 1	10% gr	avei.				
18,21 28			24		C		-		sub	rounded sand.				nedium-grained
			2					BORING TE	RMNA	TED AT 26,5 FE	et be	LOW GRADE	•	
			3	Porti	d #3	Ceme Lone Pelle	star		Driven Sample	interval	<u>추</u> 조	Water level e		red during drilling


LO	ALTON GEOSCIENCE, Inc. LOG OF EXPLORATORY BORING  TIELD SKETCH OF BORING LOCATION							CLIEI LOC <i>I</i>	NT <u>Exx</u>	30-491 on Company, U. 4th St. & 66th A W. Shipp A	S.A. ve., Oakland		BORING NO. WELL NO. MW-3
FIELD	SKE	TCI	IOF	BORING LOCATI	ON		·	200.		•			
								DRILL	HOLE DL	AML 10"			
								SAMP	LER TYP	E Modified sp	it spoon		
							,	CASIN	IG DATA	4" PVC, 0.02	0' slots		
TOPC	)FC	ASII	NG E	LEVATION 99.3	38'	-		DRILL	ER We	est Hazmat Drilliu	ng Corp.		
8.				٤			D	ा भाष	WATER	7.84'			
2.00	E	щ	(F	ACE.		u	D	ATE		3/15/91			
BLOWS PER 1/2 FOOT	CGI[PPM	SAMPLE	DEPTH (Ft)	Weil	90en	PROFILE	T	ME		0900	<u> </u>		
표구	8	Š	8		ă	Æ				D	ESCRIPTION	l	
•			-0	Christy Box	<u> </u>		_	* Asphait,	E* Bood	Page :			
			-				⊢ਃ	Aspnan,	5 hoau	pase			
			2	4* sch. 40				Scre	ened	5-15			
			4	PVC /				<i>y</i> •		3 7 7		-	
10,16,	١,	Н	_	Casing			C	LAY: darl	gray, mo	ist, hard, mediu	n plastic, 5% n	ounded mediu	m grained
19			- 0		CL		~	sar		•	•		-
			-8		]		T	)					
			- 10		1	177	->-	. ۔ ۔ ۔ ۔ ۔ ۔					
10,12, 13	0	Ш	- 10				]	ANDVO	5.V		fire metabook		ff law alasticib
13	l		- 12				ੈ	ANDY C		led(brown with o dium to coarse g			
]			14							-			
18,26,		┢┰	-		sc	1//	١,	b	hn.	bood			
24	ľ		- 16	4° sch. 40	]~~	14		same, bed	omes orc	wn, wet, hard.			
1			18	PVC 1		14	꼳	_	•				
			-	.020									
14,16,	1		- 20				,	Same, no	nravel				•
19			- 22			17	ì	Jante, IIV	A. 61401"				
			- 24	End Cap	<b>†</b> • •								
		-	[~		CL		1	SILTY CL		n, moist, very sti rounded gravel to		stic, 1% round	ed sand, 1%
12,14, 16			- 26	Ĭ.			<u> </u>						
			- 28				1	BORING	TERMINAT	ED AT 25 FEET	BELOW GRAI	Œ	
			30					•					
			F	Portia	nd C	emen	<b>t</b>						
			32	Sand	#3 L	onesi	tar	П	Driven	interval	<b>⊻</b> Water lev	el encountere	d during drilling
			34	Bento					Sample			d water level	•
<u> </u>	<u>.                                    </u>		1 -	1 666			-						


Sec. 1284

...


į







Scale in feet Vertical exaggeration = 4:1



#### **HYDROGEOLOGIC CROSS SECTION A-A'**

Exxon RAS #7-0236 6630 East 14th Street Oakland, California

FIGURE 4

**ALTON GEOSCIENCE** Pleasanton, California

30-0491 4/92

TABLE 2

### Summary of Results of Soil Sampling Exxon RAS #7-0236 6630 East 14th Street, Oakland, California

CONCENTRATIONS IN PARTS PER MILLION (PPM)

ID	DATE OF SAMPLING	DEPTH OF SOIL SAMPLE (FEET)	TPH-G	TPH-D	В	T	E	X	LAB
5.4\AJ .4	00/06/00	5 to 5.5	ND<1	ND<5	ND<0.005	ND<0.005	ND<0.005	ND<0.005	PACE
MW-4 MW-4	03/26/92 03/26/92	14.5 to 15	ND<1	ND <5	ND < 0.005	ND < 0.005	ND<0.005	ND<0,005	PACE
MW-5	03/26/92	5 to 5.5	ND<1	ND<5	ND<0,005	ND<0.005	ND<0.005	ND<0.005	PACE
MW-5	03/26/92	15 to 15.5	ND<1	ND<5	ND<0.005	ND<0.005	ND<0.005	ND<0.005	PACE
MANA/ 6	03/26/92	5 to 5.5	ND<1	ND<5	ND<0.005	ND<0.005	ND<0.005	ND<0.005	PACE
MW-6 MW-6	03/26/92	15 to 15.5	ND<1	ND<5	ND<0.005	ND<0.005	ND<0.005	ND<0.005	PACE
MW-7	03/26/92	5 to 5.5	ND<1	ND<5	ND<0.005	ND<0,005	ND<0,005	ND<0,005	PACE
MW-7	03/26/92	15 to 15.5	18	23	ND<0,005	ND<0.005	ND<0.005	ND<0.005	PACE
EXPLAN	ATION OF ABBF	REVIATIONS:		, , , , , , , , , , , , , , , , , , ,					
TPH-G	total petroleu	m hydrocarbons		(EPA meth	nod 8015 modif	ied)			
TPH-D	as gasoline :total petroleu as diesel	m hydrocarbons		(EPA met	nod 8015 modif	ied)			
В	:benzene			(EPA met					
Ŧ	:toluene			(EPA met					
	ethylbenzene:	)		(EPA met					
E X	:xylenes			· (EPA met	hod 8020)				
PACE	:Pace Labora								
ND	:not detected			<del></del>					

LO	TON G OF RINC	EX			CE FORY					CLIENT Exxon	0 E. 14th Street, Oakland	-	WELL NO. MW-4
	FIELD	SKET			ORING L	OCATI	ON			SAMPLER TYPE CASING DATA 2"	Sch. 40 PVC: 2.5 Blank	, 22.5' Screen	Page 1 of 1
	ТОР		ASIN	1	EVATIO		16'		D	DRILLERWest	Hazmat Drilling Corpora	7.76	3
	(mdd) Qic	ΓΡΗ-G (ppm)	SAMPLE	DEPTH (fbg)	Well	SITUCIIK	Ş	PROFILE		ATE IME	3/26/92 <sub>.</sub> 10:20 AM	4/6/9 12:00	
	PID	ТРН	SAN	DEP	Wel	<u> </u>	nscs	똢			DESCRIPT	ION	
	0			- 18 - 20 - 22 - 24	End Cap		CL			SILTY CLAY: b medium-grained  SILTY CLAY: o medium-grained  SILTY CLAY: b plasticity.  SANDY CLAY: sand, some coaplasticity.  SANDY CLAY: sand, increasing gravel, low plasticity.		y stiff; trace find st, very stiff; tra very fine-graine ; fine- to mediu trace fine grave to medium-grain and increasing	ce fine- to ed sand, low im-grained el, low ined ined
				- 26						Borehole termi	nated at approximately	<i>∠</i> ⇒-1/∠ 1 <del>00</del> 1 001	ow grade

ALTON LOG OF BORING	EXF						CLIENT Exxon	30 E. 14th Street, Oakland,		WELL NO. MW-5
		SEE F	BORING LOCA GURE 2 ELEVATION 15				SAMPLER TYPE CASING DATA 2	OD Hollow Stem Auger Split spoon Sch. 40 PVC: 2.5' Blank, t Hazmat Drilling Corporation	22.5' Screen	Page 1 of 1
PID (ppm)	TPH-G (ppm)	SAMPLE	Well Construction	nscs	PROFILE	D	EPTH TO WATER ATE IME	18' 3/26/92 11:50 AM DESCRIPTIO	10. 4/6/ 12:00	/92
0		1 2 2 2	2" diam. Sch. 40 PVC Casing Ca	CL			SILTY CLAY: b medium-grained SILTY CLAY: b low plasticity.  SANDY CLAY: sand, low plasticity.  CLAYEY SAND sand, trace fine gravel.	: brown, wet, medium de grained and coarse-grain	coarse-graine ne- to coarse nse; medium- nse; medium- ned sand and	-grained 
		- 2	6				Borehole termin	ated at approximately 25	·1/2 feet belov	n grade

LO	FON ( G OF RING	EXI			CE FORY		1	CLIENT Exxon	0 E. 14th Street, Oakland, C		WELL NO. MW-6 Page 1 of 1		
1	FIELD:	SKFT	CHO	OF BO	ORING LOCAT	ION					Fage ( Ut )		
•	ices.	··-·	0.,	J, J,				DRILLING METHO	DD Hollow Stem Auger	HOLE D	АМ. <u>10"</u>		
			SEE	FIG	JRE 2				Split spoon/Continuous Co				
									CASING DATA 4" Sch. 40 PVC: 2.5' Blank , 20' Screen				
	TOP	OF C	ASIN	IG EL	EVATION 18	.79'		DRILLER Wes	t Hazmat Drilling Corporation	on			
	1					Τ-	1	OCCUPATED WATER	18.5'	8.2	9'		
		Ē		ĝ	ii O			DEPTH TO WATER	3/26/92	4/6/			
	m d	9	빌	Į) Į	itruc	[,	븵	DATE TIME	2:00 PM	12:00	PM		
	(mdd) Gle	TPH-G (ppm)	SAMPLE	ЭЕРТН (fbg)	Well Construction	nscs	PROFILE	! tiair-	DESCRIPTION	ON			
			8	-	<u> </u>	╬							
				0	4" diam.	*	<b>777</b>		ne gravel subgrade		<u> </u>		
				2	Sch. 40 🕃			SILTY CLAY: b	black, slightly moist, very I sand, trace fine gravel, i	sum; trace ntermittent co	olor		
				4	PVC Casing			changes to oliv	re-green, low plasticity.				
				[ 4				-					
	0			- 6				/ SANDY CLAY:	brown, slightly moist, ve	ry stiff; mediu	m- to		
				8		CL		coarse-grained	i sand, trace fine gravel,	ow plasticity.			
				-				SILTY CLAY: b	rown, slightly moist, very	stiff; trace me	edium- to		
	0			10					sand, moderate plasticity				
				12				SANDY CLAY	brown, slightly moist, ve I sand, trace fine gravel, I	low plasticity.	·		
				14		<b> </b>	V//	CLAYEY SANI	D. brown, moist, medium	dense; medit	ım- to		
1					4" diam. Sch. 40	SC		coarse-grained	sand, trace fine gravel,	some olive-gr	een mottling.		
				16	PVC E	-	1	CLAY(6" layer	): brown, slightly moist, ve	ery stiff; low p	lasticity.		
1				18	0.020"			/I	: brown, moist, stiff; fine-				
	0			<b>-</b>		CI	-{//	fine gravel, lov	w plasticity.				
				20				1	slightly moist, very stiff; n	noderate to h	igh		
				22	End Cap			plasticity, black	k wavy vertical streaks.				
	0			24	Later			Porehole term	inated at approximately 2	3 feet below	grade		

LO	FON G OF RINC	EX			CE TORY		1		CLIENT Exxon	0 E. 14th Street, Oakland, C		WELL NO. MW-7		
	FIELD	SKET	гсн (	OF B	ORING LOCAT	ION			<u> </u>		:	Page 1 of 1		
	ТОР	OF C			URE 2 LEVATION 19	.23*			SAMPLER TYPE CASING DATA <u>2</u> "	D Hollow Stem Auger Split spoon Sch. 40 PVC: 2.5' Blank, 2 Hazmat Drilling Corporation		АМ. <u>8*</u>		
		Ê		g)	uo			C	EPTH TO WATER	14'	8.3	4'		
	Ē	g g	щ	<b>Q</b>	ucti		Ш	E	ATE	3/26/92	4/6/			
	PID (ppm)	ΓΡΗ-G (ppm)	SAMPLE	DEPTH (fbg)	Well Construction	nscs	PROFILE	1	IME	4:00 PM	12:00	PM		
	<u>-</u>	۴	Š	ä	<u>a</u> ×80				DESCRIPTION					
				- 0		-	<b> </b>		ASPHALT 6"/fin	e oravel suborade	· · · · · · · · · · · · · · · · · · ·	<del></del>		
				-2	2" diam. Sch. 40 33 PVC Casing	CL			SILTY CLAY: bl	ack, slightly moist, very stated and, moderate plasticity		- to		
	0		F2.	- 6 - 8		SM		<u></u>		live-green, slightly moist, sand, fine gravel.	dense; fine-	 to		
	0			- 10 - 12		CL		~-		olive-green, moist, very sti cand, low plasticity.	_ <b></b> ff; medium- t	0		
	0			- 14 - 16	Sch. 40	sc		<del>文</del>	CLAYEY SAND coarse-grained	: olive-green, wet, dense; sand.	medium- to			
	0			20	End Cap	CL				ightly moist, very stiff; mo wavy vertical streaks.	derate to hig	<b></b>		
				- 24 - 26		11	1//	1	Borehole termin	ated at approximately 23	feet below g	rade		




TABLE : 4 SOIL SAMPLE ANALYSIS RESULTS

Former Exxon Service Station 7-0236 6630 East 14th Street Oakland, California (Page 1 of 2)

	Sample Number	ТРНд	Benzene	Toluene	Ethyl- benzene	Total Xylene	ТЕРН	ТРРН	MTBE	Lead
	Soil - Hoists									
(A)	S-10-H1	< 1.0	< 0.0050	< 0.0050	< 0.0050	0.0067	NA	320	NA	< 10
			al Analyses: HVC			mium = <1.0; Chro		= 110; Zinc = 73	*14.*	~10
(B)	S-10-H2	16	< 0.0050	0.037	< 0.0050	0.18	NA	590	NA	< 10
(-)						mium = <1.0; Chro			MM	<10
	Soil - Gasoline UST's							•		
C	S-9.5-T1N	1.1	< 0.0050	< 0.0050	< 0.0050	< 0.0050	1.1	NA	1.2	NA
I	S-9-T1S	3,1	< 0.0050	0.0056	0.027	0.025	2.9	NA NA	0.44	NA NA
Þ	S-9.5-T2N	< 1.0	< 0.0050	< 0.0050	< 0.0050	< 0.0050	<1.0	NA	< 0.025	NA NA
<b>1</b> ∳	S-9-T2S	2,8	0.0072	0.010	0.0088	0.015	2.0	NA	0.46	NA NA
E	S-9-T3N	<1.0	0.0054	< 0.0050	< 0.0050	< 0.0050	1.8	NA NA	0.28	NA NA
G	S-9-T3S	16	0.036	0.030	0.049	0.086	7.8	NA	0.22	NA NA
	Soil-Used-Oil UST						•			
	S-8-T4	<1.0	< 0.0050	< 0.0050	< 0.0050	< 0.0050	52	220	< 0.025	<10
						nium = <1.0; Chro			<b>\0.023</b>	<b>\10</b>
	Soil-Dispensers				•					
M	S-3-D1	9.4	0.043	0.086	0.031	0.075	1.8	NA	NA	NA
N	S-2.5-D2	150		0.13	2.5	10	21	NA NA	NA NA	NA NA
6	S-3-D3	350	(1.4) 0.24	< 0.25	2.7	18	41	NA NA	NA NA	NA NA
_	S-3.5-D4	99	0.58	0.22	0.90	0.31	6.1	NA NA	NA NA	
	\$-3.5-D5	29	0.45	0.082	0.33	0.41	5.7	NA	0.96	13 NA
	S-3-D6	95	< 0.12	< 0.12	0.45	6.4	56 56	NA NA	0.62	NA NA

#### TABLE 5 SAMPLE ANALYSIS RESULTS STOCKPILED SOIL

Former Exxon Service Station 7-0236 6630 East 14th Street Oakland, California

Sample	TDIL	Benzene	Toluene	Ethyl benzene	Xylene	TEPHd	TTLC Lead
Number	TPHg	Belizene	Toldoke				
Gasoline USI	- Soilpile						27.4
SP-1-(1-4)	1.7	< 0.0050	0.012	0.0064	0.046	11	NA
SP-2-(1-4)	31	0.15	0.034	0.18	0.23	38	58 (2.3)
SP-3-(1-4)	3.4	0.0087	< 0.0050	0.0090	0.066	34	NA
SP-4-(1-4)	15	0.094	0.044	0.063	0.44	31	NA
SP-5-(1-4)	13	0.085	0.027	0.032	0.42	160	12
SP-6-(1-4)	00	0.059	0.030	0.025	0.29	17	<10
31-0-(1-1)	Addition	and Amalurees: HVC	C's = ND: SVOC's	= ND; TRPH $=$ 30	0; Antimony =	< 10; Arsenic :	= <10;
	Addition	Rarium =	79: Beryllium = <1	1.0: Cadmium = $<1$	.0; Chromium =	32; Cobalt =	5.5; Copper = 23
		Mercury =	= 0 031 · Molyhdenur	n = <5.0; Nickel =	54; Selenium =	<10; Silver =	= <1.0;
		Thallism :	= 24. Vanadium = 3	1; Zinc = 44; Thalli	um (<0.2); Van	adium = (0.23)	)
CD T (I A)	1.4	0.14	0.052	< 0.025	0.18	25	NA
SP-7-(1-4) SP-8-(1-4)	14 7.9	0.038	0.040	0.027	0.28	12	NA
Hoist - Stock	kmile.						
SP-1-(1-4)	1,100	< 0.5	2.6	7.4	48	NA	<10
51-1-(1-4)	1,100	Additiona	I Analyses: HVOC's n = 68; Nickel = 11	s = ND; SVOC's = 10; Zinc = 62; Chro	ND; TRPH = 2, mium = $(0.17)$ ;	,600; Cadmium Nickel = (2.2)	$_{1} = <1.0;$

Notes:

Results in milligrams per kilograms (ml/kg) unless otherwise noted.

<	=	Less than detection limit established by laboratory.
TPHg	==	Total petroleum hydrocarbons as gasoline
BTEX	=	Benzene, toluene, ethylbenzène, total xylene isomers
MTBE	=	Methyl tert-butyl ether
TEPHd	=	Total petroleum hydrocarbons as diesel
TRPH	=	Total recoverable petroleum hydrocarbons
HVOC's	<u></u>	Halogenated volatile organic compounds
SVOC's	<del>5</del>	Semi-volatile organic compounds
NA	==	Not Analyzed
( )	=	STLC reported in milligrams per liter (mg/L)
NA	=	Not Analyzed



### Table 3 RESULTS OF ANALYSES OF SOIL AND GROUNDWATER SAMPLES Exxon Service Statio 7-0236 6630 East 14th Street Oakland, California

	-			Ethyl-	Total		
Date	ТРНд	TPHd	Benzene	Toluene	benzene	Xylenes	Lead
11/29/93	<1.0	<5.0	< 0.005	< 0.005	< 0.005	< 0.005	NA
11/29/93	<1.0	<5.0	< 0.005	< 0.005	< 0.005	< 0.005	NA
11/23/93	<1.0	<5.0	<0.005	<0.005	-0.00s	-0.005	NTA
11/23/93	4.6	<5.0	< 0.005	< 0.005	< 0.005	<0.005	NA NA
11/20/93	48	8.5	0.024	0.014	0.057	0.000	
11/29/93	200	47					NA NA
				101000	10.005	2.5	1421
11/23/93	<1.0	7.2	< 0.005	< 0.005	< 0.005	< 0.005	NA
11/23/93	<1.0	<5.0	< 0.005	< 0.005	< 0.005	< 0.005	NA
11/23/93	<1.0	<5.0	< 0.005	<0.005	<0.005	~0.005	NA.
11/23/93	1.7	150	< 0.005	< 0.005	< 0.005	< 0.005	NA.
11/29/93	11.0	42.	<0.005	<b>√</b> 0.005	0.19	0.025	.1.0
11/29/93	1.4	<5.0	< 0.005	< 0.005	11	0.033 12	<1.0 <1.0
)							
	6800	1300	35	16	240	26	274
11/23/93	1300	330					NA NA
	11/29/93 11/29/93 11/23/93 11/23/93 11/29/93 11/23/93 11/23/93 11/23/93 11/29/93 11/29/93	11/29/93 <1.0 11/29/93 <1.0 11/23/93 <1.0 11/23/93 4.6 11/29/93 4.8 11/29/93 200 11/23/93 <1.0 11/23/93 <1.0 11/23/93 1.7 11/29/93 11.0 11/29/93 1.4	11/29/93       <1.0	11/29/93         <1.0	11/29/93         <1.0	Date         TPHg         TPHd         Benzene         Toluene         benzene           11/29/93         <1.0	Date         TPHg         TPHd         Benzene         Toluene         benzene         Xylenes           11/29/93         <1.0

Notes:

(1) Soil sample results in parts per million


(2) Water sample results in parts per billion


TPHg: Total petroleum hydrocarbons as gasoline TPHd: Total petroleum hydrocarbons as diesel

NA: Not applicable Sample designation:

S30.3VE-1: S=Soil, 30.3=Sample depth (feet), VE-1=Sample location

\* = Drill Cuttings composite samples





6630 East 14th Street

Oakland California

ERI

ENVIRONMENTAL NO.

PLATE 3

BB/MWB Soil Boring/Groundwater Monitoring Well


# TABLE $oldsymbol{6}$ SOIL AND STOCKPILE SAMPLE ANALYSIS RESULTS


Former Exxon Service Station 7-0236 6630 East 14th Street Oakland, California

Sample Number	ТРНд	В	T	Е	х	TEPHd	мтве тт	LC Lead
S-10-MW8	22	0.26	0.013	0.067	0.19	14	<0.025	NA
SP-1-(1-4)	13	0.28	0.026	0.069	0.11	14	NA	13

Notes:	•	
Soil results in par	rts per million	
TPHg	=	Total petroleum hydrocarbons as gasoline analyzed using EPA method 8015 (modified).
BTEX	<del>==</del>	Toluene, benzene, ethylbenzene and total xylenes using EPA method 8020.
TEPHd	=	Total extractable petroleum hydrocarbons as diesel analyzed using EPA method 8015 (modified).
MTBE	=	Methyl tert-butyl ether analyzed using EPA method 8020.
TTLC Lead	=	Total threshold limit concentrations (TTLC) analyzed using EPA method 6010.
NA	=	Not Analyzed

Project No.: 2009 Boring Boring Plate: 1										
Site: Former Exxon Service Station 7-0236 Date: Drill Contractor: Woodward	01/10/97									
Sample Method: Split Spoon Geologist: STEVE M. ZI	<u>LGAN</u>									
Drill Rig: <u>B57</u> Bore Hole Diameter: <u>8"</u> Signature Location: <u>Between South ends of former dispenser</u> Registration: <u>R.G. 4333</u>										
islands. Logged by: Scott Graha										
GEOLOGIC DESCRIPTION	A SE CO									
Fill, sandy gravel										
CH Clay, black, damp, trace of very fine-grained sand										
-5-30 6.0 Silty clay, olive-gray, moist, some very fine-grained sand, trace of gravel to 1/4" diameter	T. Cemen									
	ies									
	Neat									
	Ne Ne									
10-47 383										
transitioning to sandy clay, olive-gray, moist, orange and black mottling, fine-grained, some	Grout:									
gravels	E J J									
-15- 40 =	17									
light brown, wet, increasing gravels	[7]									
	Size:									
20-13 2.0 transitioning to silty clay, brown, wet	·									
	Sand									
	E-   01									
	0010									
trace of silt, lens of gravels to 3/8" diameter at 25 feet	00									
75-10 0.0 Total depth = 25 feet										
Groundwater encountered at 14.5 feet	Size:									
	Slot									
	N SS									
30-	Î									
	ໍ້ເນ									
	1,1,5									
35	lete									
	Diameter									
	Well									
40										





## **EXPLANATION**

MW8

♦ Groundwater Monitoring Well

Limits of Over Excavation

VES

Destroyed Vapor Well

Soil Sample

SOURCE: Modified from a map provided by



# GENERALIZED SITE PLAN

FORMER EXXON SERVICE STATION 7-0236 6600 East 14th Street Oakland, California PROJECT NO.

2009

PLATE

**8**4


### TABLE T SAMPLE ANALYSES RESULTS OVER EXCAVATION OF SOIL DECEMBER 1997

Former Exxon Service Station 7-0236 6600 East 14th Street Oakland, California

Sample Number			(Page 1 of 2	ornia E)		
\$2/97 \$-5-D6	ТРРНg <1.0	Benzene	Toluene	Ethyl- benzene	Total Xylenes	
F S-8.5-D6-3E E S-8-D6-2N H S-7.5-D6-1W A S-9.5-D2N C S-10-D2S D S-7.0-D2W B S-7.0-D2E Hand Auger	800 1.9 <1.0 1.1 3.5 13 <1.0 <1.0	<0.0050 0.62 <0.0050 <0.0050 <0.0050 <0.0050 <0.0050 <0.0050 <0.0050	<0.0050 <0.50 <0.0050 <0.0050 <0.0050 <0.0050 0.037 <0.0050 <0.0050	<0.0050 <0.50 <0.0050 <0.0050 <0.0050 <0.0050 <0.0050 <0.0050 <0.0050	<0.0050 <0.50 0.021 <0.0050 <0.0050 0.012 0.075 <0.0050 <0.0050	TEPHd  <1.0 620 <1.0 1.0 1.5  5.6 7.5 5.1 25
J S-6-B2 1/98	<1.0	<0.0050 <0.0050	<0.0050 <0.0050	<0.0050 <0.0050	<0.0050 <0.0050	<1.0 1.0

Soil results in milligrams per kilograms (mg/Kg)

	THE PLANTAGE TO A	e leit		
<	-8-4-12 pc	r kilograms (mg/Kg)		
TPPHg BTEX MTBE	==	Less than detection limit est Total purgeable petroleus	stablished by laboratory.  hydrocarbons as gasoline analyzed using EPA method 8015 (modifications) and the stable of the stable	
TEPHd	= ==	Methyl tertiary -butyl ether	hydrocarbons as gasoline analyzed using EPA method 8015 (modification analyzed using EPA method 8020 hydrocarbons are EPA method 8020	ed)
		10tal extractable petroleum	analyzed using EPA method 8020 hydrocarbons as diesel using EPA method 8015 (modified)	



FORMER EXXON SERVICE STATION 7-0236 6600 East 14th Street

# Groundwater Monitoring Well (Destroyed)

Lunation Wall (Dontament)

Soil Boring


PLATE


### TABLE 8 GROUNDWATER SAMPLE RESULTS


Former Exxon Service Station 7-0236 6600 East 14th Street Oakland, California (Page 1 of 1)

				mphi -	MTBE	В	Т	В	Х	DO
Sample	Sampling	DTW	TEPHd	TPPHg	MITEL				*******	<mg l=""></mg>
	Date		<	***************************************		ug/L 46	<25	1,200	32	
W-11-SB1	10/13/99	11	den	18,000	1,900	<1	<1	<1	<1	***
W-13-SB2	10/13/99	13	***	< 50	<5	-	<1	<1	<1	***
W-16-SB3	10/13/99	16		< 50	<5	<1	~,	**		
W-21-MW2	10/13/99	21	590	1,800	1,300	8.6	<5	<5	<5	8.71
Notes:		771	collected from s	oil horing one a	t 11 feet below	grade surface.				
W-11-SB1	=			on porms one		,				
DTW	1222	Depth to wat	er. able petroleum hy	.iambana as d	liacel analyzed II	ising EPA method	d 8015 (modified	i).		
TEPHd	=	Total extract	able petroleum ny	drocarbons as d	isoline analyzed	using EPA meth	od 5030/8015 (r	nodified).		

W-11-SB1	=	Water sample collected from soil borning one at 11 lest bolow grade out in
DTW	122	Depth to water.
TEPHd	==	Total extractable petroleum hydrocarbons as diesel analyzed using EPA method 8015 (i
TPPHg	#	Total purgeable petroleum hydrocarbons as gasoline analyzed using EPA method 5030.
MTBE	==	Methyl tertiary butyl ether analyzed using EPA method 8260.
BTEX	==	Benzene, toluene, ethylbenzene, and total xylenes analyzed using EPA method 8021.
DO	æ	Dissolved oxygen reading collected after well purging using a YSI model 55 meter.
***	=	Not measured/not analyzed.
<	===	Less than the indicated detection limit shown by the laboratory.
ug/L	=	Micrograms per liter.
mg/L	=	Millgrams per liter
-		







EXXON SERVICE STATION 7-0236


gann Fast 14th Street


ERI

TALLES CONTRACTOR OF THE PROPERTY AND ADDRESS OF THE PROPE

Soil Boring

8





FN 20090005

### **EXPLANATION**

N Compass Direction
Thirteen Data Points Shown

Rose diagram developed by evaluating the groundwater gradient direction from the quarterly monitoring data. Each circle on the rose diagram represents the number of monitoring events that the gradient plotted in that 22 1/2 degree sector. For example, five quarterly groundwater gradient directions plotted between due south and south 22 1/2 degrees west. Therefore, the dominant groundwater gradient direction as depicted by the rose diagram is between due south and south 45 degrees west.



# GROUNDWATER FLOW DIRECTION ROSE DIAGRAM

FORMER EXXON SERVICE STATION 7-0236 6600 East 14th Street Oakland, California PROJECT NO. 2009 PLATE

TABLE 1 O

CUMULATIVE GROUNDWATER MONITORING AND SAMPLING DATA
Former Exxon Service Station 7-0236
6500 East 14th Street
Oakland, California
(Page 1 of 8)

Well ID#	Sampling	SUBJ	DTW	Elev.	TEPHd	TPPHg	MTBE	В	Ť	Ë	×	Od	<del></del>			
(TOC)	Date	<	feet	>					-				Ferrous Iron	Alkalinity	Nitrate	Sulfate
MWI	3/15/91	NR	7.44	12.76	***	<50	***	<0.3	0.5	0.3				mg/L		
(20.20)	1/15/92 (H,T)	NR	10.60	9.60	< 300	< 50	***	< 0.5	0.7	< 0.5	1.3	***	***	444	***	
	3/23/92 (H,T)	NR	6.38	13.82	<50	< 50	***	< 0.5	<0.5	< 0.5	0.9	***	***	444	***	***
	4/6/92	NR	7.55	12.65	•••		***	-0.0	~0.0		< 0.5	***	***	•••	•••	
	7/8/92 (H,T)	NR	9.85	10.35	< 50	< 50	,	<0.5	< 0.5	40.4	-0.5	***	***	404	***	***
	10/13/92 (H,T)	NR	12.95	7.25	< 50	<50		< 0.5	< 0.5	< 0.5	< 0.5		*** .	44-	***	***
	3/9/93	NLPH	7.38	12.82	<50	< 50		< 0.5		< 0.5	< 0.5	4,44		***	* ***	
	6/4/93	NLPH	8.55	11.65	< 50	<50			< 0.5	<0.5	<0,5	***	***	444	***	***
	9/2/93	NLPH	10.85	9.35	<50	<50		< 0.5	< 0.5	< 0.5	< 0.5	***		==-		***
	11/16/93	NLPH	12.43	7.77	<50	<50		< 0.5	< 0.5	< 0.5	< 0.5		***		***	***
	2/4/94	NLPH	9.10	11.10	<50		***	< 0.5	<0.5	< 0.5	<0.5	***	707		***	***
	4/29/94	NLPH	8.45	11.75	<50	< 50	***	< 0.5	< 0.5	< 0.5	< 0.5		***			***
	9/20/94	NLPH	10.73	9,47		< 50	***	< 0.5	< 0.5	< 0.5	< 0.5	•	***	P***		408
	12/14/94	NLPH			< 50	< 50	*	<0.5	< 0.5	< 0.5	< 0.5			***		***
	3/27/95	NLPH	7.35	12.85	< 50	< 50		<b>≮</b> 0.5	< 0.5	< 0.5	< 0.5	444	***	***	-84	***
	5/18/95		7.06	13.14	< 50	< 50	***	< 0.5	< 0.5	< 0.5	< 0.5	***		***		
	8/8/95	NLPH	7.32	12.88	< 50	< 50	***	< 0.5	< 0.5	< 0.5	< 0.5				•••	***
	11/7/95	NLPH	9,24	10.96	< 50	< 50	< 2.5	< 0.5	< 0.5	< 0.5	< 0.5	7.4	•••			
	2/29/96	NLPH	10.74	9,46	< 50	< 50	< 2.5	·<0.5	< 0.5	< 0.5	< 0.5		***		***	***
		NLPH	6,80	13.40	53	< 50	< 2.5	<0.5	< 0.5	< 0.5	< 0.5	***	•••	***	***	
	\$/10/96	NLPH	8.13	12.07	150	< 50	< 2.5	< 0.5	< 0.5	< 0.5	< 0.5		****	484	444	
	8/20/96	NLPH	9.58	10.62	< 50	< 50	< 2.5	< 0.5	< 0.5	< 0.5	< 0.5	***		***		***
	10/17/96		***	***		***		***	***		•••	9.50	***	***		
	11/27/96		400	***	***		-45	444	,	<b>244</b>	***	11,54	574		p4.0	***
	12/6/96	NLPH	8,1Q	12,10		444		***	<b></b>		***	10.05	***		***	***
	1/19/97	Abandoned	•••			***	47-	•••	***	***	***	***	444	***	***	***
MW2	3/15/91 (H.T)	NR	9.05	10.10												
19.15)	1/15/92 (H,T)		-	10.10	120	1,700		190	2.6	12	64	***	444	***	***	***
13.13)		NR	11,60	7.55	1,000	6,800		81	< 10	320	170	**-	***	4	,	***
	3/23/92 (H.T)	NR	9.42	9.73	3,000	7,100		740	30	810	490		***	***	***	***
	4/6/92	NR	9.09	10.06	***			***	***	***	***		400	***	•••	
	7/8/92	NR	10,08	9.07	2,100	7,000	***	250	14	300	160		•••	***		***
	10/13/92	NR	12.06	7.09	1,900	3,200	***	97	2.6	97	53	***		***	***	***
	3/9/93	sheen	9.71	9.44	***	447	-44	700		***		•••	***		***	***
	6/4/93	sheen	9.40	9,75	***	4=4	***		4	***	***	***			***	*41
	9/2/93	sheen	10.46	8.69	3,700	000,11	2,500	210	18	260	59	•••		***		-40
	11/16/93 (M*)	NLPH	11.44	7.71	3,300	8,500	***	75	27	51	32		•	•••	***	
	2/4/94	NLPH	10.41	8.74	2,700	4,400	***	120	16	22		•••	***			
	4/29/94	NLPH	9.51	9.64	2,000	380	***	5.9	0.6	1.6	7.7	***	***	***		
	9/20/94	NLPH	10.57	8.58	1,800**	19,000	***	190	29***		< 0.5	***	***	***		***
	12/14/94	sheen	8,90	10.25	***	13,000		120		110	27***		***		•••	•
	3/27/95	NLPH	7.72	11.43	1,700	6,300					V+4	***	444	•••	•••	***
	5/18/95	sheen	8.65	10.50	2,000#	6,000		210	15	250	43	***		***	***	***
	8/8/95	NLPH	9.67	9.48	2,700	•		180	9,9	220	55	***	***	***	***	***
	11/7/95	NLPH	10.49			5,300	36,000	110	< 20	120	<20	400	-10	***		*#h
	*******	114511	10,43	8.66	1,800	6,400	24,000	120	11	95	38	***	447	***	***	
	2/29/96	NLPH	0.46	10.50	,	Additional Anal			operties < *							
	4/47/70	WILL	8.45	10.70	2,500	< 5,000	25,000	120	< 50	120	< 50	***	***	***	•••	***

TABLE 10

#### CUMULATIVE GROUNDWATER MONITORING AND SAMPLING DATA

Former Exxon Service Station 7-0236 6600 East 14th Street Oakland, California (Page 2 of 8)

Well ID #	Sampling	SUBI	DTW	Elev	TEPHd	TPPHg	MTBE	8	T	E	Х	DO	Ferrous Iron	Alkalınıty	Natrate	Sultate
(TOC)	Date	<	feet	, >	<			ug/L,			>	<	··	mg/L		>
MW2 (cont.)	5/10/96	NLPH	9,02	10.13	2,300	11,000	26,000	210	120	210	140		***	•••	***	***
(19.15)	8/20/96	NLPH	10.08	9.07		***		•••		***			*	•••		***
	10/17/96	***		***		*		***				7.75	***		•••	
	11/27/96			***	~~				***			6.28	***	*		***
	12/6/96	NLPH .	10.21	8.94	1,700	5,800	< 125	170	< 25	38	<25	5.21	*	•••	***	
	1/17/97	NLPH	***								***	3.67	*		***	•••
(22.19)	2/25/97	NLPH	8.15	14,04	1,500	5,900	4,400	110	14	310	52	2.71		•••		•••
	3/13/97			***	***		***		***			2.46	***	***		***
	4/16/97			***		***	***	***	***	***		1.00	•••	*	***	***
	5/21/97	NLPH	10.50	11.69	1,600	5,700	1,800	71	11	240	59	0.85	***		***	***
	6/5/97					•		***	***			2.18	***		***	•••
	7/11/97		•••	**-	•••	•••			***			1.87	***			•••
	8/6/97	NLPH	10.80	11.39	1,600	4,100	(1,900)	40	5.2	49	17	1.51	•••	***	•••	•••
	9/23/97	***	***		•••	-++						2.36	***	•••		***
	10/7/97 .	NLPH	11.08	11.11	1,200	280	230	1.2	2.4	< 0.5	1.1	1.56	***	***		***
	12/24/97		4**				***		****			1.23	•••	***	•••	
	1/16/98	NLPH	7.29	14,90	1,200	3,500	3,000	190	14	110	31	1.18		***	•••	
	2/20/98							***	44,			1.30		•••	***	
	3/26/98	***	***	***			4**		•••			1.20	***	***		***
	4/17/98	NLPH	8.61	13.58	970	3,200	2,600	150	6.9	37	5.7	1.38	•••	***	***	
	5/13/98			**-		***		***	•••			0.45		***	***	
	6/22/98		***	4		440		•••	***	•••	***	1.09	•••	•••	•••	
	7/17/98	NLPH	9.38	12.81	1,300	1,700	1,500	63	< 5.0	< 5.0	< 5.0	0.86	***	***		
	10/16/98	NLPH	10.41	11.78	1,500	2,000	1,400	22	< 2.0	< 2.0	2.4		***	***	**-	•••
	1/15/99	NLPH	10.01	12.18	900	2,300	2,200	< 5.0	6.0	< 5.0	6.5	***	***		***	***
	4/23/99	NLPH	7.61	14.58	967	2,140	937	42.3	<1.0	22.3	< 1.0	***		***	•	•••
	7/30/99	NLPH	9.82	12.37	1,620	2,480	1,470/1,360*	100	< 10.0	< 10.0	< 10.0	**-	***	***	•••	•••
	8/12/99	NLPH	10.00	12.19	F3.				***	***	***	***	0.710	750	6.0	7.2
	9/3/99	NLPH	***	***		•••	***	***	***	***	***	1.02	***			
	10/11/99	NLPH	10.46	11.73	1,700	2,900	1,300/1,400*	< 1.0	2.5	<1.0	<1.0	**-	0.200	927	14.8	27.6
	10/14/99	NLPH	***	•••	•••		74=		***	***		19.71	***			
	1/26-27/2000	NLPH	8.95	13.24	150/180**	160	420	12	< 0.5	< 0.5	< 0.5	4.10	0.0200	842	6.97	28.2
MW3	3/15/91 (H,T)	NR	7.84	11.75	160	3,100	***	2.2	1.9	100	84		***		•••	•••
(19.59)	1/15/92 (H,T)	NR	10.30	9.29	< 300	250	***	0.7	6.8	1.5	1.5		***	***		
(22,000)	3/23/92 (H.T)	NR	6.84	12.75	440	640		< 0.5	12	25	6.5		***	***		***
	4/6/92	NR	7.84	11.75	***	***			774				•••			
	7/8/92 (H,T)	NR	8,63	10.96	960	2,900	•••	< 0.5	2.6	12	63.7	***			•••	***
	10/13/92 (H)	NR	12.10	7.49	400	1,100	***	5 5	< 0.5	4.6	1.1	•••	•••	•••	•••	
	3/9/93	sheen	9.05	10.54		***			***	***	***	***		•••		***
	6/4/93	sheen	8.43	11.16			4	***			•••	***	•••	•••	•••	***
	9/2/93	NLPH	10.22	9.37	690	840	***	2.7	3.6	5.4	2.9		•••	•••	***	***
	11/16/93	NLPH	11.44	8.15	310	650	***	< 0.5	11	7.7	2.4	•••	***	•••		•••
	2/4/94	NLPH	9.27	10.32	340	870	***	0.6	14	1.2	0.8	***	***	44-	***	***
	4/29/94	NLPH	8.10	11.49	290	790	***	< 0.5	< 0.5	0.8	1	***	***	•••	•••	***
	9/20/94	NLPH	10.10	9.49	290 91**	1,900	***	<0.5	< 0.5	11	4,4	***	***	•••	4**	•••
	9/20/94 12/14/94	NLPH NLPH	8.00	11.59	190	1,700		17	22	< 0.5	<0.5	***	***	***	•••	•••
								5.0	3.1	6.3	3.6					***
	3/27/95	NLPH	7.23	12.36	1,100	1,500	•••	3.0	J. i	0.5	3.0		***	⊷•		***

## TABLE 1© CUMULATIVE GROUNDWATER MONITORING AND SAMPLING DATA Former Exxon Service Station 7-0236

6600 East 14th Street Oakland, California (Page 3 of 8)

Well ID#	Sampling	SUBJ	DTW	Elev	TEPHd	TPPHg	MTBE	В	T	E	Х	DO	Ferrous Iron	Alkalinity	Nitrate	Suitate
(TOC)	Date	<	feet	>	<		1913 - 8411 - 81	ug/L				-		•	=	
IW3 (cont.)	5/18/95	NLPH	7.73	11.86	470#	1,000	***	< 0.5	< 0.5	4.1	0.94	***		1. 1.mg/L		
(19.59)	8/8/95	NLPH	8.81	10.78	580	1,600	12	12	< 0.5	2.4	0.63	***	***		***	
	11/7/95	NLPH	9.96	9.63	540	1,500	26	<25	2,9	< 2.5	< 2.5		•••	***	***	***
	2/29/96	NLPH	8.47	11.12	680	1,000	<25	<50	< 5.0	< 5.0	< 5.0		***		4-4	
	5/10/96	NLPH	7.93	11.66	560	480	6.8	<10	< 1.0	< 1.0	<1.0			***	***	***
	8/20/96	NLPH	10.13	9.46	•••	***				***	-1.0				***	***
	10/17/96	***			•••	***	***			***	***	7.65			***	***
	11/27/96		*	***	•••		•••			***		8.76				***
	12/6/96	NLPH	9.21	10.38	450	970	19	< 1.0	<1.0	<1.0	1.8	10.14	***	***		***
	1/17/97	***	***	***		***	***	404		***	1.0			***	***	
(22.62)	2/25/97	NLPH	8.34	14.28	410	990	47	10	0.85	0.86		14.02	***		***	***
	3/13/97		***		***	***	***		***		1.5	10.69	-4-		***	*-*
	4/16/97			***			***				•••	8.68	***	***	444	***
	5/21/97	NLPH	9,99	12.63	270	< 50	< 2.5	< 0.5	*** ~0 e		***	18.73	***	•••		
	6/5/97	***	***		210		~ 4.3	***	< 0.5	< 0.5	< 0.5	6.76	***	***		
•	7/11/97	404		***		***					***	6.70	***			***
	8/6/97	NLPH	10.29	12.33	310	650	••• •••			4-4	***	4.10	***		***	***
	9/23/97	***	10.25	****			< 5.0	4,0	<1.0	< 1.0	<1.0	10.59	***			***
	10/7/97	NLPH	10.86		400	1.600		**	440		***	8.62		***	•	
	12/24/97			11.76	500	1,600	12	24	10	< 2.0	3.5	11.81	***	***	**-	***
	1/16/98	***		***	***	***			***	***		***	444	***	***	***
	2/20/98	***	***	***	***	•			***		***		444	***	***	***
	3/26/98	***	***		44*	***	***	***	***	***	***	11.22		***	•••	^**
		AIX DII	***	***	***	***	•••	***	***	***	***	10,55	***	***		~**
	4/17/98	NLPH	7.56	15.06	220	710	21	< 0.5	0.76	< 0.5	< 0.5	9.40			***	
	5/13/98	***		***			***	***	***		***	0.22	•••	-40	•••	4**
	6/22/98	***					***	•••		***		0,96	-4-	***		***
	7/17/98	NLPH	8.23	14.39	180	450	8.9	9.5	<1.0	< 1.0	<1.0	0.94			***	4-2
	10/16/98	NLPH	9.75	12.87	320	520	5.1	< 0.5	11	< 0.5	0.93	***	***	***	***	·
	1/15/99	NLPH	8.83	13.79	600	190	12	< 0.5	0.91	< 0.5	0.7	***	***		***	
	4/23/99	NLPH	7.11	15.51	194	406	2.71	< 0.5	< 0.5	< 0.5	< 0.5		***			***
	7/30/99	NLPH	8.98	13.64	72.5	193	< 2.50	< 0.5	< 0.5	< 0.5	< 0.5		4-6		***	4**
	8/12/99	NLPH	9.40	13.22		***		***	***	***		***	0.0440	330	48.1	47.4
	9/3/99	NLPH	***	•••	***		***		•••			2.56	***	***	***	4717
	10/11/99	NLPH	9.91	12.71	100	130	< 1.0	< 1.0	< 1.0	< 1.0	< 1.0		0.0490	317	50.1	48.2
	10/14/99	NLPH			***	***	***			***		1.41	***	***	***	444
	1/26-27/2000	NLPH	8.56	14.06	150/<50**	210	<2	1.6	< 0.5	< 0.5	< 0.5	2.00	0.0120	329	38.6	61.9
MW4	4/6/92	NR	7.76	11.70	< 50	< 50		< 0.5	< 0.5	< 0.5	< 0.5			***		
(19.46)	7/8/92	NR	9.56	9.90	< 50	< 50	***	< 0.5	< 0.5	<0.5	< 0.5	***		•••	***	***
	10/13/92	NR	12.09	7.37	< 80	< 50		< 0.5	< 0.5	< 0.5	< 0.5	***			***	
	3/9/93	NLPH	7.53	11.93	< 50	< 50	***	< 0.5	< 0.5	<0.5	< 0.5	***			***	***
	6/4/93	NLPH	8.50	10.96	< 50	< 50	***	< 0.5	< 0.5	< 0.5	< 0.5			***		•••
	9/2/93	NLPH	10.30	9.16	< 50	< 50	***	< 0.5	< 0.5	< 0.5			***	***	***	***
	11/16/93*	•••	***	***	***			~0.0	***	C 0.3	< 0.5			***	•••	
	2/4/94	NLPH	8.82	10.64	< 50	<50		< 0.5	< 0.5		···	***	***	•	•••	***
	4/29/94 (D)	NLPH	8.55	10.91	100	<50	***			< 0.5	< 0.5	***		***	***	
	9/20/94	NLPH	10.21	9.25	< 50	<50		< 0.5	< 0.5	< 0.5	< 0.5	***	***	***	***	
	12/14/94	NLPH	7.04	12.42			***	< 0.5	< 0.5	< 0.5	< 0.5	***	•••		***	***
	API 471 77	CHECK	7.04	14.44	< 50	<50	***	< 0.5	<0.5	< 0.5	< 0.5		***		***	-4*



#### TABLE 10 CUMULATIVE GROUNDWATER MONITORING AND SAMPLING DATA

Former Exxon Service Station 7-0236 6600 East 14th Street Oakland, California (Page 4 of 8)

Well ID#	Sampling	SUBJ	DTW	Elev.	TEPHd	ТРРНд	МТВЕ	В	T	Ε	Х	DO	Ferrous Iron	Alkalinity	Nitrate	Sultate
(TOC)	Date	<, ,,	feet	. , , .>	<, ,	., ,		ug/L			>	<		mg/L		
MW4 (cont.)	3/27/95	NLPH	6.38	13.08	140	< 50	***	< 0.5	< 0.5	< 0.5	< 0.5		•••		•	
(19.46)	5/18/95	NLPH	7.56	11.90	< 50	< 50	***	< 0.5	< 0.5	< 0.5	< 0.5	•••	***	***	•••	•
(15110)	8/8/95	NLPH	8.92	10.54	< 50	< 50	< 2.5	< 0.5	< 0.5	< 0.5	< 0.5		•••			***
	11/7/95	NLPH	10.30	9.16	< 50	< 50	< 2.5	< 0.5	< 0.5	< 0.5	< 0.5	***	***			
	2/29/96	NLPH	6.44	13.02	< 50	< 50	< 2.5	< 0.5	< 0.5	< 0.5	< 0.5	***			•••	
	5/10/96	NLPH	8,15	11.31	< 50	< 50	< 2.5	< 0.5	0.84	< 0.5	2.3	•	•••	***	•	
	8/20/96	NLPH	9.27	10.19	< 50	< 50	< 2.5	< 0.5	< 0.5	< 0.5	< 0.5		***		•••	***
	10/17/96	110411	***	***	***							1.63			•	•
	11/27/96	***	400			•••	**-	***	***		***	1.54		•••	•••	***
	12/6/96	NLPH	7.76	11.70		***	***	***				2.33	•••	***		
	1/17/97	112111		***	***	***	***	***		***		0 91		•••	•••	•••
/22 £05	2/25/97	NLPH	7.98	14.60	< 50	< 50	< 2.5	< 0.5	0.89	< 0.5	1.8	1.03	•••		•••	•••
(22.58)	3/13/97	(ATLI	***	400			•••				***	1.06	***	***	**-	
					***	***	***	•••			***	4.03	***		•••	
	4/16/97	618 D12	9.03	13.55	***	***						0.90		•••	***	***
	5/21/97	NLPH	3.03	15.33		***	400	•••	***	•••	•••	1.46	•••	•••	•••	***
	6/5/97					***		•••	***			1,31	•••		•••	•••
	7/11/97	44V	0.74	12.84	< 50	< 50	<2.5	< 0.5	< 0.5	< 0.5	< 0.5	1.46	•••		•••	***
	8/6/97	NLPH	9.74		~30				•••	***		1.50	•••	-+*	•••	
	9/23/97		10.00	10.60			***	***	***	A-4	•••	1.65	***	•••	***	***
	10/7/97	NLPH	10.06	12.52			•••				•••	1.96		***	***	
	12/24/97	***	***	10.60	EO	 60	<2.5	< 0.5	< 0.5	< 0.5	< 0.5	1.68	•••	***	4	
	1/16/98	NLPH	5.01	17,57	< 50	<50				400	***	3.33	***	•••	•••	
	2/20/98		***					•••		***	***	1.65	***			
	3/26/98		***		•••			***		***	***	3.10	***	•••		***
	4/17/98	NLPH	7.21	15.37	***	, ***	***			***	***	0,40	***	***		***
	5/13/98	***	***		•••	***	***	***	444	***	***	1.20	•••	•••	***	***
	6/22/98		***		***			-0.4	< 0.5	< 0.5	< 0.5	1.84	***	***	***	***
	7/17/98	NLPH	8.46	14.12	< 50	< 50	< 2.5	< 0.5			4-4	***				***
	10/16/98	NLPH	9.84	12.74	•••	***	***		-0.6		< 0.5	***		•••		***
	1/15/99	nlph	11.33	11.25	< 50	< 50	< 2.5	< 0.5	< 0.5	< 0.5		***		***	•••	***
	4/23/99	NLPH	7.63	14.95	*	•••	•••				-0.6		***	•••		•
	7/30/99	NLPH	9.17	13.41	< 50	< 50	< 2.5	< 0.5	< 0.5	< 0.5	< 0.5		***		•••	•••
	9/3/99	NLPH		***	*	•••	***		***	-4.0	***	2.94		***	•••	
	10/11/99	NLPH	9.98	12.60	***	***									•••	•••
	10/14/99	NLPH	***	,		***	***	***				1.36		***	***	***
	1/26-27/2000	NLPH	7.60	14.98	110/<50**	< 50	<2	< 0.5	< 0.5	< 0.5	< 0.5	3.00	***	•••		
MW5	4/6/92	NR	10.66	6.29	< 50	< 50	4**	< 0.5	< 0.5	< 0.5	< 0.5		***	***	•••	
(16.95)	7/8/92 *	***				***	***	•••	***		•••		***			***
(19.70)	10/13/92	NR	15.02	1.93	< 50	69	***	< 0.5	< 0.5	< 0.5	< 0.5					•••
	3/9/93	NLPH	10.27	6,68	< 50	<50	***	< 0.5	< 0.5	< 0.5	< 0.5	•	***	***		•••
	6/4/93	NLPH	11.35	5,60	< 50	< 50	***	< 0.5	< 0.5	< 0.5	< 0.5	***	***	•••	•••	•
	9/2/93	NLPH	13.15	3,80	< 50	< 50		< 0.5	< 0.5	< 0.5	< 0.5		•••		•••	***
	11/16/93	NLPH	14.35	2,60	<50	< 50	***	< 0.5	< 0.5	< 0.5	< 0.5		***	***	•••	
	2/4/94	NLPH	11.83	5,12	60	< 50	•••	< 0.5	< 0.5	< 0.5	< 0.5				•••	4
			11.15	5 80	<50	< 50	*	< 0.5	< 0.5	< 0.5	< 0.5	•			***	•••
	4/29/94	NLPH		4.16	<50	< 50		< 0.5	< 0.5	< 0.5	< 0.5	•••	•••	•••		
	9/20/94	NLPH	12.79 9.9 <b>5</b>	7.00	<50	<50		< 0.5	< 0.5	< 0.5	< 0.5	***				***
	12/14/94	NLPH	9.93	7.00	~ 30	~30		~010	1010	10.0						

#### Table 10

#### CUMULATIVE GROUNDWATER MONITORING AND SAMPLING DATA Former Exxon Service Station 7-0236

Former Exxon Service Station 7-0236 6600 East 14th Street Oakland, California (Page 5 of 8)

Well ID#	Sampling	SUBJ	DTW	Elev.	TEPHd	TPPHg	мтве	В	T	E	Х	DO	Ferrous Iron	Alkalinity	Nitrate	Sulfate
(TOC)	Date	<			< ,,			ug/L			>	_ <		mg/L		
MW5 (cont.)	3/27/95	NLPH	9.09	7.86	< 50	< 50		< 0.5	< 0.5	< 0.5	< 0.5	***	-10			
(16.95)	5/18/95	NLPH	10.29	6.66	< 50	< 50		< 0.5	4.6	0.65	2.8				•••	
	8/8/95	NLPH	11.13	5.82	51	< 50	< 2.5	< 0.5	< 0.5	< 0.5	< 0.5			***		***
	11/7/95	NLPH	12.12	4.83	< 50	< 50	< 2.5	< 0.5	< 0.5	< 0.5	< 0.5	***	***	***	•••	***
Ad	iditional Analyses fo	or general miner	als and properti	es <**								•••	***		***	
	2/29/96	NLPH	9.24	7.71	60	< 50	< 2.5	< 0.5	< 0.5	< 0.5	< 0.5			***	***	***
	5/10/96	NLPH	10.71	6.24	< 50	< 50	< 2.5	< 0.5	< 0.5	< 0.5	1.6	***		•••		•••
	8/20/96	NLPH	11.45	5.50		400			***		***	***	-4-		***	4
	10/17/96	***	***	***		***	444	4+1	4**	***	4		***		***	
	11/27/96	445	***		***	***	***	404	ERF		449	4.57	4	***	***	***
	12/6/96	NLPH	10.70	6,25	90	62	< 2.5	1.2	6.5	1.7	11	***			***	
	1/17/97	408		444	***	***		***		4**		***	•••		***	***
	2/25/97	NLPH	10.49	6.46	90	< 50	< 2.5	1.4	2.4	0.95	7.4		***	4==	***	***
(19.98)	3/13/97				•	***	***	***	***		444	-		***	***	***
, ,	4/15/97	***			***	***		744	***	***	***	•••	***	***		
	5/21/97	NLPH	11.31	8.67	< 50	< 50	< 2.5	< 0.5	< 0.5	< 0.5	< 0.5	***				
	6/5/97	***	***	***	***	***		***	~~~	***		•••	***		***	***
	7/11/97							•••	***	•••	•••					***
	8/6/97	NLPH	11 78	8.20	< 50	< 50	<2.5	< 0.5	< 0.5	< 0.5	< 0.5			***	***	***
	9/23/97	772		***	400	100			~0.3	~0.3	<0.3	•••	***	***	***	***
	10/7/97	NLPH	12.26	7.72	< 50	< 50	<2.5	< 0.5	< 0.5	< 0.5	< 0.5			***		
	12/24/97		***					•••	4**	~0.3		***	•••		***	***
	1/16/98	NLPH	8.87	11.11	< 50	< 50	< 2.5	< 0.5	< 0.5		D. 64		*	•••	***	•
	2/20/98		+**		~30	-30		~0.3	< 0.3	< 0.5	0.64	***	***	***	***	***
	3/26/98	***	***	404					•		***		***		***	
	4/17/98	NLPH	9.97	10.01	< 50	< 50	<2.5	0.9	2.2	0.81			***	4	•••	
	5/13/98	***	21,21	10.01	~ > >	~30	~2.5	0.9			3.6	P**			***	
	6/22/98		***				***		***		***	***	***	***	-4.	
	7/17/98	NLPH	11.00	8.98	<50	< 50	<2.5	< 0.5	< 0.5	# O #		***	***	***	***	***
	10/16/98	NLPH	11.92	8.06		< 50				< 0.5	< 0.5	444	***	***	***	4.49
	1/15/99	NLPH	9.01	10.97	51	< 50	< 2.5	< 0.5	< 0.5	< 0.5	< 0.5	***	=44	***	-	•••
	4/23/99	NLPH			< 50		< 2.5	<0.5	< 0.5	< 0.5	< 0.5	***	***	***	***	
	7/30/99	NLPH	6.31 11.16	13.67 8.82	< 50 < 50	< 50 < 50	<2.0	< 0,5	< 0.5	< 0.5	< 0.5	-44	***		*44	***
							<2.5	< 0.5	< 0.5	< 0.5	<0.5		***	***	***	
	8/12/99	NLPH	11.48	8.50	•••	•••	444	•••	***		***	***	0.110	510	< 1.0	17.7
	9/3/99	NLPH			-1-	***	4		***		***	2.11	***	4-4		***
	10/11/99	NLPH	12,01	7.97	< 50	< 50	< 1.0	< 1.0	< 1.0	<1.0	<1.0	***	4.00	457	5.39	27.2
	10/14/99	NLPH		***	444	•••		***	***	***		1.58	14.		***	
	1/26-27/2000	NLPH	10.12	9.86	130 < 50**	< 50	<2	< 0.5	< 0.5	< 0.5	<0.5	2.20	0.0340	503	<1.00	1,95
MW6	4/6/92 (H)	NR	8.29	10.50	< 50	< 50	•••	< 0.5	< 0.5	< 0.5	<0.5	•••				***
(18.79)	7/8/92 (H,T)	NR	9.22	9.57	< 50	< 50		< 0.5	< 0.5	< 0.5	< 0.5		***		***	•••
	10/13/92	NR	11.53	7.28	< 50	< 50	***	< 0.5	< 0.5	< 0.5	< 0.5	•••	***	444	***	***
	3/9/93	NLPH	8.26	10.53	< 50	< 50	444	< 0.5	< 0.5	< 0.5	< 0.5	***	***	***	***	***
	6/4/93	NLPH	8.90	9.89	< 50	< 50	444	< 0.5	< 0.5	< 0.5	< 0.5	***	***	***	,	***
	9/2/93	NLPH	9.92	8.87	60	< 50	***	< 0.5	< 0.5	< 0.5	<0.5	***	***	***	***	
	11/16/93	NLPH	10.65	8.14	< 50	< 50	***	< 0.5	< 0.5	< 0.5	< 0.5	***	44.	***	***	***
	2/4/94	NLPH	9,26	9.53	80	< 50		< 0.5	< 0.5	< 0.5	< 0.5	***			***	***
	4/29/94	NLPH	8.33	10.46	110	< 50	***	< 0.5	<0.5	< 0.5	<0.5	***	***	***	***	***

### TABLE 1f CCUMULATIVE GROUNDWATER MONITORING AND SAMPLING DATA


Former Exxon Service Station 7-0236 6600 East 14th Street Oakland, California (Page 6 of 8)

Vell ID#	Sampling	SUBJ	DTW	Elev.	TEPHd	TPPHg	MTBE	В	T	E	×	D0	Ferrous Iron	Aikalınity me/i	Nitrate	Sulface
(TOC)	Date	<	feet	>	<						< 0.5		****		***	***
W6 (cont.)	9/20/94	NLPH	9.23	9.56	< 50	< 50	•••	< 0.5	< 0.5	< 0.5	~ U.J		***	•••		
(18.79)	12/14/94	sheen	7.87	10.92	•••	•••	***						***	***		٠
	3/27/95	NLPH	7.63	11.16	54	56	*	< 0.5	< 0.5	< 0.5	< 0.5	•	***	***		
	5/18/95	NLPH	8.00	10 79	71	56	***	< 0.5	< 0.5	< 0.5	< 0.5				***	
	8/8/95	NLPH	8.92	9.87	60	< 50	< 2.5	< 0.5	< 0.5	< 0.5	< 0.5	•••	***			
	11/7/95	NLPH	9.77	9.02	< 50	< 50	4.7	< 0.5	< 0.5	< 0.5	< 0.5		***		••-	
	2/29/96	NLPH	7 67	11.12	64	< 50	< 2.5	< 0.5	< 0.5	< 0.5	< 0.5	100	***	***	•••	
	5/10/96	NLPH	8.33	10.46	110	< 50	5.4	< 0.5	< 0.5	< 0.5	< 0.5	***	•••	***	***	***
		NLPH	9.16	9.63	***		***		***	•••			***	***	***	***
	8/20/96			***		***	***		***			10.58	***	***	***	***
	10/17/96					***	***			4		14.17		***	644	
	11/27/96	***					3,9	< 0.5	< 0.5	< 0.5	< 0.5	10.33			***	
	12/6/96	NLPH	8.55	10.24	68	<50						11.71	440			***
	1/17/97			•••		***	***				< 0.5	10.94	***		•••	
(21.84)	2/25/97	NLPH	8.42	13.42	67	< 50	6.8	< 0.5	< 0.5	< 0.5		8.88				
	3/13/97	***	***	***	***	***			***						•••	
	4/16/97	***	***	***	•	,	***	***	***	***		15.20	***	***		
	5/21/97	NLPH	9.16	12.68	82	< 50	3,4	< 0.5	< 0.5	< 0.5	<0.5	12.38				
	6/5/97		***	***	***		***		***	***		10.99		***	***	••
						***	4-4	***	***	***	•••	10.13	***	***		••
	7/11/97	***		12.02	<50	< 50	< 2.5	< 0.5	< 0.5	< 0.5	< 0.5	9.05		***	***	••
	8/6/97	NLPH	9.82			~	***	***		-44		6.22		***		
	9/23/97	***			444	< 50	4.1	< 0.5	< 0.5	< 0.5	< 0.5	9.68	4	***	•••	4-
	10/7/97	NLPH	9.85	11.99	89			<b>~0.5</b>	***	***	***	2.78	•	•••		
	12/24/97	***					***		< 0.5	< 0.5	< 0.5	2.73	•••		•••	•
	1/16/98	NLPH	5,50	16.34	93	< 50	<2.5	< 0.5				3.55		•••		
	2/20/98		447	+		•••	***	•••			4+4	3.90	•••			•
	3/26/98		-4-	=44	***	4***	***	***		-0.5		5.08	•••		•••	_
	4/17/98	NLPH	8.12	13.72	59	< 50	< 2.5	< 0.5	< 0.5	< 0.5	< 0.5			***		
	5/13/98				, ,,,	***			•••	***	***	6.90	•••			
	6/22/98	***			***	***	***	***	***		***	8.96	•••	•••	***	
	7/17/98	NLPH	8,81	13.03	63	<50	3.3	< 0.5	< 0.5	< 0.5	< 0.5	10.69			•••	•
	10/16/98	NLPH	9,84	12.00	60	<50	< 2.5	< 0.5	< 0.5	< 0.5	< 0.5		***			•
			9,55	12.29	< 50	< 50	3.7	< 0.5	< 0.5	< 0.5	< 0.5			•••	•••	
	1/15/99	NLPH		13.12	106	< 50	14.4	< 0.5	< 0.5	< 0.5	< 0.5		•••	***		-
	4/23/99	NLPH	8.72		< 50	<50	<2.50/2.50*	< 0.5	< 0.5	< 0.5	< 0.5		***	***		
	7/30/99	NLPH	9.32	12.52				***	***			6.20	***	•••	***	
	9/3/99	NLPH				***	24/54		<1.0	< 1.0	<1.0	•••		•••	•••	
	10/11/99	NLPH	9.54	12.30	< 50	< 50	3,4/5*	<1.0				9.09	***	•••	•••	
	10/14/99	NLPH	444		***				***	-0-	< 0.5	2.30	***		***	
	1/26-27/2000	NLPH	9,09	12.75	120/<50**	< 50	2.7	< 0.5	< 0.5	< 0.5	<b>~0.3</b>	2.30				
MW7	4/6/92	NR	8.34	10.89	< 50	< 50		< 0.5	< 0.5	< 0.5	< 0.5		***		***	
(19.23)	7/8/92 *	NR	10.30	8.93	< 50	< 50	***	< 0.5	< 0.5	< 0.5	< 0.5			•••	•••	•
(17.42)	10/13/92	NR	12.91	6.32	94	670		0.8	< 0.5	< 0.5	2.5		•••	***	***	-
			12.71	(		•••	•••					***	***	***	***	
	3/9/93	***		10.55	< 50	< 50	•••	< 0.5	< 0.5	< 0.5	< 0.5	***	•••		*	
	6/4/93	NLPH	8,68			<50	•••	< 0.5	< 0.5	< 0.5	< 0.5	•••			***	
	9/2/93	NLPH	10.80	8.43	< 50			< 0.5	< 0.5	< 0.5	< 0.5		•••	***		
	11/16/93	NLPH	12.38	6.85	< 50	< 50					< 0.5			***		
	2/4/94	NLPH	9.28	9.95	< 50	< 50	***	< 0.5	< 0.5	< 0.5				411	***	
	4/29/94	NLPH	9.19	10.04	< 50	< 50	***	< 0.5	< 0.5	< 0.5	< 0.5	444	***			

### TABLE 1D CUMULATIVE GROUNDWATER MONITORING AND SAMPLING DATA Former Exxon Service Station 7-0236

6600 East 14th Street
Oakland, California
(Page 7 of 8)

Well ID #	Sampling	SUBJ	DTW	Elev.	TEPHd	TPPHg	MTBE	В	T		<del></del>				····	
(TOC)	Date	<	teet ,			•			-	E	X	DO	Ferrous (ron	Alkalinity	Nitrate	Sulfate
W7 (cont.)	9/20/94	NLPH	10.85	8.38	< 50	< 50	***	ug/L < 0.5	-0.6					mg/L		
(19.23)	12/14/94	NLPH	8.44	10.79	< 50	< 50			< 0.5	< 0.5	< 0.5	***	***		7=2	
	3/27/95	NLPH	7.54	11.69	280	< 50		< 0.5 < 0.5	<0.5	< 0.5	< 0.5	***	***	***	***	
	5/18/95	NLPH	8.11	11.12	< 50	< 50			< 0.5	< 0.5	< 0.5	***	***	•••		
	8/8/95	NLPH	9.48	9.75	52	<50	 ~2 £	< 0.5	< 0.5	< 0.5	< 0.5	***	***	•••	***	
	11/7/95	NLPH	10.83	8.40	< 50	<50	< 2.5	< 0.5	< 0.5	< 0.5	< 0.5		***	***		***
	2/29/96	NLPH	7.70	11.53	< 50	< 50	<2.5 <2.5	< 0.5	< 0.5	< 0.5	< 0.5	•••		•••		
	5/10/96	NLPH	8,76	10.47	<50	< 50		< 0.5	< 0.5	< 0.5	< 0,5	***	-44	***	***	
	8/20/96	NLPH	9,91	9.32	<50	< 50	< 2.5	< 0.5	< 0.5	< 0.5	2.1		***			***
	10/17/96	***	***	7.52			<2.5	< 0.5	< 0.5	< 0.5	< 0.5	444	***	***	***	
	11/27/96	***	***	***	***		4**	•••	444	***		1.48	***	***	***	***
	12/6/96	NLPH	8,90		1	***		***		***	***	2.71	444	***	***	***
	1/19/97	Abandoned	0,30	10.33	***		***		***	***		8.90	***	•••	***	
	1/12/2/	Vositifolico		***	***		•••		***	***	***		***	***	***	***
MW8	1/17/97	***	***	***												
(22.60)	2/25/97	NLPH	7.93	14.67	< 50	•••	•••		***		•••	1.39		***	***	
	3/13/97		***			69	30	< 0.5	< 0.5	< 0.5	< 0.5	1.82	***	***	en h	***
	4/16/97	***	***	***	***	***	***	•••		***		1.58	***	***		-
	5/21/97	NLPH	9.04	12.57		***	***	•••	***	***		0.81		***	•••	***
	6/5/97			13.56	< 50	< 50	3.5	< 0.5	< 0.5	< 0.5	< 0.5	0.74			***	
	7/11/97	***	400	~44	***	**-	***	***	***	***		0.55	***			***
	8/6/97	*** *// 1971	5.00	***	***	4	***	***	***		***	0.85	***	***	***	***
	9/23/97	NLPH	9.90	12.70	< 50	< 50	<2.5	< 0.5	< 0.5	< 0.5	< 0.5	0,77	•••	***	444	•••
	10/7/97	\(\frac{1}{2}\)	10.44		***	^	***	***	***	***		0,75	***	•••	***	
		NLPH	10.23	12,37	< 50	100	4.9	1.1	< 0.5	< 0.5	< 0.5	0.82		•••		
	12/24/97	***		***	47#	A	***	***	***	***		0.86		***		
	1/16/98	NLPH	4.39	18.21	81	180	9.6	2.8	< 0.5	< 0.5	0.92	0.94	•••	***	***	***
	2/20/98	***	*	***	***	***	***	4	***	444	***	0.61		•••	***	***
	3/26/98		***		•••	***		***		***		0.53	***	4		***
	4/17/98	NLPH	***		74	370	27	< 0.5	0.94	< 0.5	0.79	2.65	494		***	
	5/13/98	• 4.		***		***	***	***		***	400	0.25	***		***	
	6/22/98	744	***	***	,	***	***	745	•	***	***	1,38	***	***	***	
	7/17/98	NLPH	8.02	14.58	< 50	< 50	3.3	< 0.5	< 0.5	< 0.5	< 0.5	2.09	***			
	10/16/98	NLPH	9.78	12.82	< 50	< 50	< 2.5	< 0.5	< 0.5	< 0.5	< 0.5	2.09			***	***
	1/15/99	NLPH	8.40	14.20	<50	< 50	< 2.5	< 0.5	0.97	< 0.5	< 0.5	4+-		***	***	***
	4/23/99	NLPH	7.35	15.25	70.1	111	3,45	< 0.5	< 0.5	< 0.5	<0.5		-+-	***		***
	7/30/99	NLPH	8.86	13.74	< 50	89.4	<2.5	< 0.5	2.7	< 0.5				***		***
	9/3/99	NLPH	***	*44		***	7/4	***			<0.5	0.46	•••	***		***
	10/11/99	NLPH	10.04	12.56	<30	<50	<1.0	< 1.0	*** ***	 10	***	2.45	•••	***		***
	10/14/99	NLPH	414	***	***	***	***		<1.0	< 1.0	<1.0	***	***	***		***
	1/26-27/2000	NLPH	5.52	17.08	90/60**	< 50	<2	 -0.e	446		***	0.69	*	***		***
					> aray	700	~_	< 0.5	< 0.5	< 0.5	< 0.5	2.10	•••	444		***



TABLE?

Summary of Petroleum Products and VOCs in Soil
6600 International Boulevard, Oakland, California

					Petroleu	m Products				VOCs
Sample ID	Depths (feet)	TPH-mo	TPH-d	TPH-g	Benzene	Toluene	Ethylbenzene	Xylenes	MTBE	All Analytes
B-3 (comp)	1 and 3	ND	6.2	ND	ND	ND	ND	ND		
B-7 (comp)	2 and 4	ND	1.7	ND	ND	ND	ND		ND	ND
B-11 (comp)	2 and 4	ND	3.1	ND	ND	ND	ND ND	ND	ND	ND
B-12 (comp)	2 and 4	ND	2.9	ND	ND	0.012		ND	ND	ND ·
B-13 (comp)	2 and 4	ND	- · <del>· ·</del>				0.034	0.11	ND	ND
			1.5				•	• • ••		ND
B-14 (comp)	2 and 4 2 and 4	ND ND	2,8 1.5	ND ND	ND ND	ND ND	ND ND	ND ND	ND ND	

#### Notes:

All results reported in milligrams per kilogram (mg/kg) or parts per million (ppm)

ND = Analyte not present at or above the method detection limit

(comp) = 2-point composite soil sample

TPH-mo = Total petroleum hydrocarbons as motor oil

TPH-d = Total petroleum hydrocarbons as diesel

TPH-g = Total petroleum hydrocarbons as gasoline

MTBE= Methyl tertiary butyl ether

VOCs= Volatile Organic Compounds



Site Name: Former Exxon Station 7-0236 Job Identification: 2009RBCA Output light of the Site Location: 6600 East 14th Street Date Completed: 11/10/99 Software: GSI RBCA Spreadsheet NOTE: values which differ from Tier 1 default values are shown in bold Italics and underlined. Version: 1 0.1 Completed By: Steve M. Zigan Exposure Parameter Definition (Units) Residential Commercial/Industrial Adult ATc Surface Averaging time for carcinogens (yr) (1-6yrs) (1-16 yrs) Chronic Constrctn 70 Parameters Definition (Units) ATn Averaging time for non-carcinogens (yr) Residential 30 Constrctn вW Body Weight (kg) 6 Contaminated soil area (cm^2) 16 25 70 8.0E+05 ED W Exposure Duration (yr) 15 Length of affect, soil parallel to wind (cm) 8.0E+05 35 70 30 W.gw 1,3E+03 Length of affect, soil parallel to groundwater (cm Averaging time for vapor flux (yr) 1.3E+03 25 30 FF Uair Ambient air velocity in mixing zone (cm/s) 6.4E+02 Exposure Frequency (days/yr) 25 EF.Derm 350 2.3E+02 Exposure Frequency for dermal exposure delta Air mixing zone height (cm) 250 180 350 2.0E+02 **IRaw** Ingestion Rate of Water (L/day) Lss Thickness of affected surface soils (cm) 250 IRs. 2 Рe Particulate areal emission rate (g/cm^2/s) 9.1E+01 Ingestion Rate of Soil (mg/day) 1 100 IRadi 6.8E-14 Adjusted soil Ing. rate (mg-yr/kg-d) 200 50 1.1E+02 100 IRa.in Inhalation rate Indoor (m^3/day) 9.4E+01 15 Groundwater Definition (Units) IRa.out Inhalation rate outdoor (m^3/day) 20 20 Value delta.gw Groundwater mixing zone depth (cm) Skin surface area (dermal) (cm^2) 20 SAadj 5.8E+03 10 1.8E+02 Adjusted dermal area (cm\*2-yr/kg) Groundwater Infiltration rate (cm/yr) 2,0E+03 5.8E+03 5.8E+03 2.1E+03 Ugw Groundwater Darcy velocity (cm/yr) Soil to Skin adherence factor 1.7E+03 AAFB 1 Groundwater seepage velocity (cm/yr) Age adjustment on soil ingestion Ugw.tr FALSE AAFd Ks Saturated hydraulic conductivity(cm/s) Age adjustment on skin surface area FALSE FALSE tox Use EPA tox data for air (or PEL based)? grad Groundwater gradient (cm/cm) FALSE TRUE gwMCL2 Use MCL as exposure limit in groundwater? Sw Width of groundwater source zone (cm) FALSE 9.8E+02 Sd Depth of groundwater source zone (cm) 1,8E+02 phi.eff Effective porosity in water-bearing unit 3.8E-01 foc.sat Fraction organic carbon in water-bearing unit 1.0E-03 BIO? Matrix of Exposed Persons to is bloattenuation considered? FALSE Residential BC Complete Exposure Pathways Biodegradation Capacity (mg/L) Commercial/Industrial Outdoor Air Pathways: Constrctn SS.v Volatiles and Particulates from Surface Soils Soil Definition (Units) FALSE Value hc S.v Volatilization from Subsurface Soils Capillary zone thickness (cm) FALSE TRUE 5.0E+00 TRUE hν GW.v Volatilization from Groundwater Vadose zone thickness (cm) FALSE 2.0E+02 -9.2 Indoor Air Pathways: TRUE rho Soil density (g/cm^3) FALSE foc (101) Fraction of organic carbon in vadose zone 8.6 Vapors from Subsurface Soils eles - more conservative TRUE phi GW.b Soil porosity in vadose zone Vapors from Groundwater FALSE TRUE Soil Pathways: Lgw Depth to groundwater (cm) 2.9E+02 - 9.5 FALSE \$\$.d L\$ Depth to top of affected subsurface soil (cm) Direct Ingestion and Dermal Contact FALSE 9.1E+01 Groundwater Pathways: Lsubs Thickness of affected subsurface soils (cm) TRUE TRUE 4.0E+02 GW.i рΗ Groundwater Ingestion Soil/groundwater pH FALSE 6.5 S.I Leaching to Groundwater from all Soils FALSE FALSE capillary phi.w Volumetric water content Vadose foundation FALSE phi.a 0.342 0.12 Volumetric air content 0.12 0.038 0.28 0.26 Building Matrix of Receptor Distance Definition (Units) Residential Lb Commercial and Location On- or Off-Site Residential Bullding volume/area ratio (cm) Commercial/Industrial Distance 2.0E+02 ER On-Site Building air exchange rate (s^-1) 3.0E+02 Groundwater receptor (cm) Distance On-Site 1.4E-04 ls FALSE Lcrk Foundation crack thickness (cm) 2.3E+04 inhalation receptor (cm) FALSE 1.5E+01 eta (.0) TRUE Foundation crack fraction FALSE 0.00001 Matrix of Transport Target Risks Parameters Definition (Units) based on actual data Individual TRab Target Risk (class A&B carcinogens) Cumulative Residential Commercial 1,0E-06 Groundwater TRC Target Risk (class C carcinogens)

© Groundwater Services, Inc. (GSI), 1995-1997. All Rights Reserved.

ax

ау

az

Vapor dcy

Longitudinal dispersivity (cm)

Transverse dispersivity (cm)

Transverse dispersion coefficient (cm) Vertical dispersion coefficient (cm)

Vertical dispersivity (cm)

1.08-05

1.0E+00

2

2

THO

Opt

Tier

Target Hazard Quotient

**RBCA Tier** 

Calculation Option (1, 2, or 3)

	rmer Exxon Station 7-0236 6600 East 14th Street			y: Steve M. Z ted: 11/10/19:	-							105
GROUNDWATER SSTL VALUES			Target Risk (Class A & B) 1.0E-6			☐ MCL exposure limit? ☐ PEL exposure limit?			Ca	Calculation Option: 2		
*		_		531	L Results For Con	piete Exposure	Pathwaya ("x" If C	omplete)				**************************************
		Representative Concentration	Groundwater Ingestion		Ingestion	Groundwater Volatilization X to Indoor Air		Groundwater Volatilization X to Outdoor Air		Applicable SSTL	SSTL Exceeded ?	Required CRF
CAS No.	Name	(mg/L)	Residential: (on-site)	Commercial; (on-site)	Regulatory(MCL): (on-site)	Residential; (on-site)	Commercial: (on-site)	Residential (on-site)	Commercial: (on-site)	(mg/L	1	Only if 'yes' let
71-43-2	Benzene	A OE 1	NA	NA	NA NA	3.0E+1	NA	3.7E+0	NA NA	3.7E+0		<1
100-41-4	<u>Ethylbenzene</u>	2.2E-2	NA	_ NA	NA	>Sol	NA	>Sol	NA NA	>Sol		<1
108-88-3	Toluene	1.0E-2	NA	NA	NA	>Sol	NA NA	>Sol	NA	>Sol		<1
1330-20-7	Xylene (mixed isomers)	1.0E-2	NA	NA	NA	>Sol	NA NA	>Sol	NA NA	>Sol	<del>                                     </del>	<1

© Groundwater Services, Inc. (GSI), 1995-1997. All Rights Reserved.

Software: GSI RBCA Spreadsheet Version: 1.0.1

Serial: G-311-YSX-926

<i></i>		RBCA SITE	ASSESSIV	ENT					T	ler 2 Worksh	et 9.2	
Site Name: Fo	rmer Exxon Station 7-0236		Completed B	y: Steve M. Zi	gan			-				
Site Location:	6600 East 14th Street		Date Comple	ted: 11/10/199	9							1 OF 1
ຣບ	BSURFACE SOIL SSTL (> 3 FT BGS)	VALUES	Target	k (Class A & B) Risk (Class C) lazard Quotlent	1.0E-5	☐ MCL expos		<u> </u>	Ca	Iculation Option	: 2	
				SSTL	Results For Comp	lete Exposure Pa	athways ("x" If C	ompiete)				
CONSTITUEN	ITS OF CONCERN	Representative Concentration	Soi	Leaching to	Groundwater		latilization to	1 .	latilization to tdoor Air	Applicable SSTL	SSTL Exceeded ?	Required CRF
CAS No.	Name	(mg/kg)	Residential: (on-site)	Commercial: (on-site)	Regulatory(MCL)	Residential: (on-site)	Commercial: (on-site)	Residential: (on-site)	Commercial: (on-site)	(mg/kg)	"■" If yes	Only if "yes" left
·····	Benzene	6,2E-1 t	NA	NA	NA	4.2E+0	NA	4.2E+0	NA	4.2E+0		<1
100-41-4	Ethylbenzene	1.3E-1	NA	NA	NA	>Res	NA	>Res	NA	>Res		<1
108-88-3	Toluene	8.7E-2	NA	NA	NA	>Res	NA	>Res	NA	>Res		<1
	Xylene (mixed isomers)	1.3E+0	NA	NA	NA	>Res	NA	>Res	NA	>Res		<1

© Groundwater Services, Inc. (GSI), 1995-1997. All Rights Reserved.

Software: GSI RBCA Spreadsheet Version: 1.0.1

Senal: G-311-YSX-926

**UCL Percentile** 

Analytical Data (Up to 50 Data Points)

Default Calculated Detection Distribution Limit of Data

(mg/kg)

#DIV/0!	0.005
#DIV/01	0.005
#DIV/0!	0.005
#DIV/0!	0.005

(mg/kg) (mg/kg) (mg/kg) (mg/kg) (mg/kg) (mg/kg) (mg/kg) Sample Name Date Sampled

BET

SCREEN 7.1 GROUNDWATER CONCENTRATION -CALCULATOR

## Choose UCL Percentile



Analytical Data (Up to 50 Data Points)

1	2	3	4	5	6	7	8
•	~	•	7	•	v	•	v

Calculated Distribution of Data	Defauit Detection Limit (mg/L)	Well Name Date Sampled	GERMANICATION AND PROPERTY OF	(mg/L) viv.	(mg/L)	(mg/L) ////2	(mg/L)	(mg/L)	(mg/L) /////s ///si/es	(mg/L)
Lognormai	0.002	В	20 004e	38.4	6 0/22	[	F No of the	Na life lote la		
Lognormal	0.002	$\epsilon$	× 0,004	C 95	(6,(8)?)?	0,000	(10,0 <b>(</b> 0/2)	(4) (9) (1)	ci (P) (P) (Mar.	
Lognormal	0.002	T	(0)(0)(0)2/3	0/08/04	1. (6): 6) 0 Es	@p}(e)(g)	School of order	le gelor se	e elejaja,	16-31-[91-7]
Lognormal	0.005	×	0.010	0.01	a for a legis	(0,0 <b>06</b> 0-5)	2 (0.7)	(2) 0 (1)	Me delet	in the

TABLE 12 Summary of Petroleum Products and VOCs in Grab Groundwater 6600 International Boulevard, Oakland, California

Sample ID	Thi			Petroleur	n Product							
B-1		TPH-d	ТРН-д	Benzene	Toluene	Ethylbenzene	Xylenes	MTBE	Acetone		<u>YOCs</u> Naphthalene	IPB
B-2 B-3 B-4 B-5	ND ND ND 1.600	98 200 1,000 180 1,300	ND 1,300 1,700 890 ND	ND ND ND ND ND	ND ND ND ND ND	ND ND 8.7 3.7 ND	ND 1.5 1.2 ND	ND ND 18 8.2 ND	ND 70 290 ND ND	ND ND 54 54	ND ND 2.6 2.6	
Notes:									ND	ND	ND	ND

All results reported in micrograms per liter (ug/L) or parts per billion (ppb)

ND = Analyte not present at or above the method detection limit

TPH-mo = Total petroleum hydrocarbons as motor oil

TPH-d = Total petroleum hydrocarbons as diesel

TPH-g = Total petroleum hydrocarbons as gasoline

MTBE= Methyl tertiary butyl ether

VOCs= Volatile Organic Compounds

MEK = Methyl Ethyl Ketone

IPB = Isopropylbenzene





#### 4.0 <u>FIELD ACTIVITIES</u>

#### 4.1 GEOPHYSICAL INVESTIGATION

On November 11, 1999, Jesse Edmands, Staff Environmental Consultant of Clayton, conducted a geophysical investigation of the subject property. NORCAL Geophysical Consultants performed the fieldwork. The purpose of the investigation was to determine if USTs or other buried material associated with the former onsite gasoline stations remained onsite. Also, the property was surveyed for areas of potential backfill. Geophysical techniques used included vertical magnetic gradient (VMG), terrain conductivity (TC), metal detection (MD), and ground penetrating radar (GPR). The complete geophysical survey report is provided as Appendix C.

Through VMG, six magnetic anomalies or buried metallic objects (Anomaly I through IV) were discovered throughout the subject property. In addition, using MD, two metal objects were located in the vicinity of Anomaly I and V. Clayton further investigated these anomalies through backhoe excavations. One Earth Environmental, Inc. was subcontracted to operate the backhoe equipment. On December 1, 1999, John D. Glover, Supervisor, and Marc R. Mullaney, Project Geologist of Clayton, directed the anomaly excavations. During the excavation work, Anomaly V was actually found to be two objects, which are referred to as V-A and V-B. Details regarding the excavations are summarized as follows:


Salimiarized as follows:	TABLE 1	1


Anomaly ID	<b>Excavation Limits</b>	Description			
I	4' by 4' by 2' deep	An abandoned utility line			
H	4' by 4' by 2' deep	Metallic scrap			
III 4' by 4' by 2' deep		Pipe coupling or valve			
IV	10' by 3' by 4' deep	Power footing/cable tie			
V-A	8' by 5' 6' deep	Waste oil UST			
V-B	4' by 4' by 2' deep	Metallic scrap			
VI	4' by 4' by 2' deep	Metallic scrap			


In addition, two areas of low TC (Areas A and B) were discovered, suggesting possible backfilled areas. GPR analysis conducted on the subject property was inconclusive due the impenetrable nature of the soil to the GPR. The locations of the geophysical anomalies are depicted on Figure 3.

#### 4.2 SUBSURFACE INVESTIGATION

On December 1, 1999, Mr. Mullaney of Clayton conducted a limited subsurface investigation. A total of 14 borings (B-1 through B-14) were advanced on the property in









# TERRAIN CONDUCTIVITY CONTOUR MAP

6600 INTERNATIONAL BOULEVARD

LOCATION: OAKLAND, CALIFORNIA


AL CLIENT: CLAYTON ENVIRONMENTAL CONSULTANTS

JOB #: 99-304.05 NORCAL GEOPHYSICAL CONSULTANTS INC.


DATE: NOV. 1999 DRAWN BY: G.RANDALL. APPROVED BY: DJB



PLATE



	LEGEND
	LIMITS OF VERTICAL MAGNETIC GRADIENT INVESTIGATION
0-0	VERTICAL MAGNETIC GRADIENT CONTOUR (CONTOUR INTERVAL = 50 nT/m)
Δ	SUSPECTED BURIED FERROUS OBJECT
uu	UNDIFFERENTIATED UTILITY
-	MONITORING WELL





VERTICAL MAGNETIC GRADIENT CONTOUR MAP 6600 INTERNATIONAL BOULEVARD

LOCATION: OAKLAND, CALIFORNIA

CLIENT: CLAYTON ENVIRONMENTAL CONSULTANTS

#: 99-304.05 NORCAL GEOPHYSICAL CONSULTANTS INC.
E: NOV 1999 DRAWN BY: G.RANDALL APPROVED BY:

INC. 9

PLATE