


March 7, 1996



AllWest Environmental, Inc.

Specialists in Environmental Due Diligence and Remedial Services

One Sutter Street, Suite 600 San Francisco Ca 94104 Tel 415 391 2510 Fax 415 391 2008

Ms. Juliet Shin Alameda County Environmental Health Department 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577

Subject: Map Showing Excavation Limits and Sampling Locations

1055 Eastshore Highway, Albany, California

AllWest Project No. 95117.25

Dear Ms. Shin:

Pursuant to your request, AllWest re-plotted the soil excavation map showing all previous sampling locations. As shown on the attached map, the limits of soil excavation are well defined by a ring of soil borings and monitoring wells that detected no evidence of soil impact. The impacted soils detected at previous boring SB-2 were successfully removed during the soil excavation. We trust the re-plotted map clarifies the locations of non-detect soil samples and their relation with the limits of soil excavation.

Should you have questions regarding the attached map or need additional information, please call us at (415) 391-2510.

Sincerely,

AllWest Environmental, Inc.

Long Ching, PE

Senior Project Manager

LC/bms

L95117.25G


55/103-0 PH 1162 SLIDING DOORS SB-4 P-2 EX-NWSW-6 0° former UST LOCATION ww-3 [⊕] MW-2 ⊕ **⊕** MW-1 ⊕ EX-ESW-6 0' SOIL EXCAVATION 7' to 8' deep • \$B-1 EX-B-8.0'⊕ P-3 EX-ESW-5.0° SB-2 ◆ • P-5 sB-3 MW-4⊕ ● P-4 20' 10 30' APPROXIMATE SCALE = MONITORING WELL LOCATION MW-1 = VERIFICATION SOIL SAMPLE LOCATION EX-B-8.0° = PREVIOUS SOIL BORING LOCATION \$B-3 **Excavation Limits Project** Figure March & Soil Sample 95117.25 4a 1996 Location Map

1055 Eastshore Highway

Albany, California

Source


AllWest





1055 Eastshore Highway Albany, California

Source AllWest





August 1995

Gradient Map

Project No. 95117.28

Figure 4

1055 East Shore Highway, Albany, California

Source **AllWest**