The dosed.

smn 3800



John P. Caffrey, Chairman



Division of Clean Water Programs

2014 T Street, Suite 130 • Sacramento, California 95814 • (916) 227-4539 FAX (916) 227-4530 Mailing Address: P.O. Box 944212 • Sacramento, California • 94244-2120 Internet Address: http://www.swrcb.ca.gov/-cwphome/ustct/fundhome.htm

DEC 17 1998

Curt Bolton Grand Marina, Inc. 2099 Grand St Alameda, CA 94501

Peter M. Rooney Secretary for

Environmental

Protection

UNDERGROUND STORAGE TANK CLEANUP FUND, CLAIM NO. 12737, FOR SITE ADDRESS: 2041 GRAND ST, ALAMEDA

The State Water Resources Control Board (State Board) is able to issue, pursuant to applicable regulations, the enclosed Letter of Commitment (LOC) in an amount not to exceed \$32,000. This LOC is based upon our review of the corrective action costs you reported to have incurred to date. The LOC may be modified by the State Board.

It is very important that you read the terms and conditions listed in the enclosed LOC. Claims filed with the Underground Storage Tank Cleanup Fund far exceed the funding available and it is very important that you make use of the funding that has been committed to your cleanup in a timely manner.

You are reminded that you must comply with all regulatory agency time schedules and requirements and you must obtain three bids for any required corrective action. Only corrective action costs required by the regulatory agency to protect human health, safety and the environment can be claimed for reimbursement. Unless waived in writing, you are required to obtain preapproval of costs for all future corrective action work (form enclosed). If you have any questions on obtaining preapproval of your costs or the three bid requirement, please call David Hallstrom, our Technical Reviewer assigned to claims in your Region, at (916) 227-4519. Failure to obtain preapproval of your future costs may result in the costs not being reimbursed.

The following documents needed to submit your reimbursement request are enclosed:

- "Reimbursement Request Instructions" package. Retain this package for future
 reimbursement requests. These instructions must be followed when seeking reimbursement for
 corrective action costs incurred after January 1, 1988. Included in the instruction package are
 samples of completed reimbursement request forms and spreadsheets.
- "Bid Summary Sheet" to list information on bids received which must be completed and returned.
- "Reimbursement Request" forms which you must use to request reimbursement of costs incurred
- "Spreadsheet" forms which you must use in conjunction with your reimbursement request

THIS IS IMPORTANT TO YOU, PLEASE NOTE:

You have 90 calendar days from the date of this letter to submit your first reimbursement request for incurred corrective action costs. NO EXTENSIONS CAN BE GRANTED. If you fail to do so, your LOC funds will automatically be reduced to zero (deobligated). Once this occurs, any future funds for this site are subject to availability when you submit your first reimbursement request. We continuously review the status of all active claims. You must continue to remain in compliance and submit a reimbursement request every 6 months. Failure to do so will result in the Fund taking steps to withdraw your LOC.

If you have any questions regarding the enclosed documents, please contact Anna Torres at (916) 227-4388.

Sincerely,

Dave Deaner, Manager / UST Cleanup Fund Program

Enclosures

cc: Mr. Thomas Peacock
Alameda County EHD
1131 Harbor Bay Pkway, 2nd Fl.
Alameda, CA 94502-6577

E** PROTEOFIOH**
98 DEC 29 PM 3:58

ALAMEDA COUNTY

HEALTH CARE SERVICES





DAVID J. KEARS, Agency Director

ENVIRONMENTAL HEALTH SERVICES

1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 (510) 337-9335 (FAX)

StID 3820

June 24, 1998

Mr. Kurt Bolton Harbor Master, Grand Marina 2099 Grand Marina Alameda, CA 94501

RE: Well Decommission at 2099 Grand Street, Alameda, CA

Dear Mr. Bolton:

This office and the San Francisco RWQCB have reviewed the case closure summary for the above referenced site and concur that no further action related to the underground tank release is required at this time. Before a remedial action completion letter is sent, the onsite monitoring wells (MW2 through MW4, MW5a and MW6a) should be decommissioned, if they will no longer be monitored. Please notify this office upon completion of well destruction so a closure letter can be issued.

Well destruction permits may be obtained from Alameda County Public Works. They can be reached at (510) 670-5575.

If you have any questions, I can be reached at (510) 567-6762.

Sincerely,

eva chu

Hazardous Materials Specialist

grandmarına-1

RO# 819 RG-closed \$1D# 3996

	UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK) / CONTAMINATION SITE REPORT						
_	HAS STATE OFFICE OF EMERGENCY SERVICES THE PORT BEEN FILED? THE TOTAL THE PORT BEEN FILED? THE PORT BEEN FILED?	FOR LOCAL AGENCY USE ONLY THEREBY CERTIFY THAT I HAVE DISTRIBUTED THIS INFORMATION ACCORDING TO THE					
	YES NO YES NO RT DATE CASE #	DISTRIBUTION SHOWN ON THE INSTRUCTION SHEET ON THE BACK PAGE OF THIS FORM:					
0.4	411 Da Ga 9181	SIGNED DATE					
λ6	MINEY TOURMANN G	01628. SAOO WHUY BY CHIMANN					
яеровтер ву	REPRESENTING OWNER/OPERATOR REGIONAL BOARD LOCAL AGENCY OTHER	ACC ENVIY DAMENTAL CONSULTING					
H	ADDRESS + Capwall Dr. Suite IN	Oakland CASTATE 94621					
RESPONSIBLE PARTY	NAME OF UT A MAYING UNKNOWN	CONTACT PERSONS TO VICTOR ()					
RESPO	2099 Grandreer AVENUE.	Mamada CA STATE 94506					
ZS	Errand Marina . The	OPERATOR PHONE ()					
SITE LOCATION	ADDRESS ZOS AW.	CITY Alameda COUNTY Hiameda ZIP 94501					
SIT	CROSS STREET FOX MAN WAU						
ENTING	Mampala Chuntu Health are	CONTACT PERSON. PHONE STO. SGT. 6700					
IMPLEMENTING AGENCIES	SF Bay Area Regional Due	HIL CONTYDI BOARD ()					
SUBSTANCES INVOLVED	"JOB-GAILON LET (AOKO)	QUANTITY LOST (GALLONS) UNKNOWN					
SUBST	(2)	UNKNOWN					
EMENT		VENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS NK REMOVAL OTHER					
RY/ABATEMENT	DATE DISCHARGE BEGAN UNKNOWN	METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY) REMOVE CONTENTS CLOSE TANK & REMOVE REPAIR PIPING					
DISCOVE	M M DI DI YI YI HAS DISCHARGE BEEN STOPPED ? YES NO IE YES DATE	REPAIR TANK CLOSE TANK & FILL IN PLACE CHANGE PROCEDURE TREPLACE TANK OTHER					
F	CALISERS	Y					
SOURCE	TANK LEAK UNKNOWN C	OVERFILL RUPTURE/FAILURE SPILL CORROSION UNKNOWN OTHER					
CASE	CHECK ONE ONLY UNDETERMINED SOIL ONLY GROUNDWATER	DRINKING WATER - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED)					
 	CHECK ONE ONLY						
CURRENT STATUS	NO ACTION TAKEN PRELIMINARY SITE ASSESSME						
0 %	REMEDIATION PLAN	PLETED OR UNNECESSARY) CLEANUP UNDERWAY					
DIAL	CHECK APPROPRIATE ACTION(S) (SEE BACK FOR DETAILS) CAP SITE (CD) EXCAVATE & TREAT (ET)						
REMEDIAL	CONTAINMENT BARRIER (CB) NO ACTION REQUIRED (I	VA) TREATMENT AT HOOKUP (HU) VENT SOIL (VS)					
"							
COMMENTS							
SOM	,						



January 23, 1998

Mr. Tom Peacock County of Alameda, Environmental Health Services 1131 Harbor Bay Patkway, Suite No. 250 Alameda, California 94502

Re: Check for Deposit - Project # 483D, Type M at 2099 Grand Street, Alameda

Dear Mr. Peacock:

Enclosed please find a check in the amount of \$3,000.00 to replenish the deposit/refund account for Project #483D (2099 Grand Street, Alameda). In addition, please note our correct mailing address:

SECOR 90 New Montgomery Street, Suite 620 San Francisco, CA 94105-4503

If you require any further information, please feel free to call me at (415) 882-1548. Thanks for your time.

Sincerely,

Laura O'Shea Staff Scientist

SECOR International Incorporated

Laur 40'Shea

H:\CROWLEY\ACEHS.LTR

DAVID J. KEARS, Agency Director



ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, #250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

October 16, 1996

Jim Ritchie
Secor Corporation
90 New Montgomery Street, #620
San Francisco, CA - 94105

Reference: 2099 Grand Avenue, Alameda, CA

Dear Mr. Ritchie:

I am in receipt of the risk assessment prepared by Secor, dated August 13, 1996 for the referenced site. The risk assessment was reviewed by this Department and the following concerens need to be addressed:

- 1. Only results of recent subsurface soil samples collected in October 1994 was used to evaluate the risk although investigations conducted by Zaccor in 1992 and Seacor in 1993 identified significant concentrations of diesel, gasoline, oil and grease and other constituents in soil and groundwater around the above-ground storage tank area. Since the monitoring wells, MW-5 to MW-8 were installed in the perimeter of the plume, soil and groundwater samples collected from these borings/ well are not representative of the site. Hence, data submitted from previous investigations should be included in the evaluation of the risk.
- 2. The risk assessment has proposed using PAH's as indicator compounds to evaluate the risk for diesel by using LUFT Manual's recommended percentage of benzopyrene in diesel as 0.07 ug/gm. Since benzopyrene has been identified in the groundwater samples during the March 1996 quarterly groundwater monitoring conducted on-site, the percentage of benzopyrene in diesel should be calculated from the actual site data.
- 3. Please provide a reference for the site specific value used for the air exchange rate.
- 4. Since the contaminated soil around the above ground tank, (the source) has not been removed, this Department is concerned about continuous release of petroleum hydrocarbon contamination to the Bay. A detailed investigation and ecological risk assessment was conducted for the San Francisco Airport which is approved by the San Francisco Regional Water Quality Control Board (RWQCB) to identify cleanup levels for diesel, jet fuel, gasoline and BTEX. Attached is a summary of the ecological risk assessment and cleanup levels prepared by the State Regional Water Quality Control Board. Since 1995, RWQCB has adopted an order which includes cleanup criteria based on ecological risk assessments (Order No. 95-136) and hence this issue should be evaluated for the

referenced project. Based on the results of this evaluation, a effective cleanup strategy (source removal should be evaluated as one of the cleanup strategies) may need to be implemented to reduce or prevent migration of petroleum compounds to the Bay.

5. Since exposure to surface contaminants is a pathway that needs to be evaluated for landscaped areas, a site map showing areas of the site that will be landscaped (as opposed to areas that will be capped), and locations of the proposed commerical buildings and restaurant that are to developed on site (for the vapor transport pathway) should be submitted to this Department. If a final plan is not available, then the risk assessment should take a conservative perspective in evaluating the risk, i.e. assuming that the building could be built anywhere on the site, and any area on the site could be potentially landscaped. Also, risk management practices can be implemented if applicable (eg. importing clean fill above the contaminated soil in landscaped areas to eliminate exposure, using vapor barriers to reduce indoor air exposure, etc.).

Submit an amended report addressing the above listed concerns. If you have any questions, you may reach me at (510) 567-6764.

Sincerely,

Madhulla Logan

Hazardous Material Specialist

CC:, Joe Gordan, Secor International, Inc, 4900 Pearl East Circle, Suite 200, Boulder, Colorado-80301.



Ms. Madhulla Logan Hazardous Materials Specialist Alameda County Health Care Services Agency 1131 Harbor Bay Parkway, Suite 250 Alameda, California 94502-6577

PROPOSED ADDITIONAL ACTIVITIES, GRAND STREET AND FORTMANN WAY PROPERTY, ALAMEDA, CALIFORNIA

Dear Ms. Logan:

This letter is submitted to describe proposed additional activities by SECOR International Incorporated (SECOR) for the above referenced property (the site). As you know, SECOR has investigated the site subsurface since October 1993. Our investigatory activities have included: an historical records review, soil boring advancement, monitoring well installation and destruction, underground product line precision testing, soil and groundwater sample collection and chemical analysis, and a tidal influence study. The reports summarizing the results of these activities have been submitted to the Alameda County Health Care Services Agency (ACHCSA) for review and approval.

The analyte concentrations and distribution presented in those reports submitted to you by SECOR indicate a lack of significant impact to groundwater, and an apparently limited zone of impacted soils. The primary compounds present in the subsurface are neither mobile nor do they appear to pose a significant risk to human health or the environment. We propose performing a Risk Assessment of the Site and immediate surroundings to more thoroughly evaluate the risks posed by the noted compounds. We believe Risk Assessment is the next logical step toward our goal of closing the site with respect to ACHCSA and other regulatory agency oversight.

We would appreciate your consideration of our proposal as well as a written response to the proposed actions. Should you have any questions, please do not hesitate to contact us at (415) 882-1548.

Sincerely yours,

SECOR International Incorporated

James G. Ritchie, R.G. Principal Geologis

Jam Dethu



Ms. Madhulla Logan Hazardous Materials Specialist Alameda County Health Care Services Agency 1131 Harbor Bay Parkway, Suite 250 Alameda, California 94502-6577

REVISION OF GROUNDWATER MONITORING PROGRAM, GRAND STREET AND FORTMANN WAY PROPERTY, ALAMEDA, CALIFORNIA

Dear Ms. Logan:

This letter is submitted to confirm our telephone conversation of November 8, 1995 regarding your receipt of the October 30, 1995 Quarterly Groundwater Monitoring Report prepared by SECOR International Incorporated (SECOR) for the above referenced property (the site). As you confirmed during our conversation, the subject report replaces the October 27, 1995 SECOR report submitted to the Alameda County Health Care Services Agency (ACHCSA).

Based upon our discussion, we understand that you agree to our modifying the groundwater monitoring program. Specifically, wells which have exhibited four quarters of non-detectable (or non-reportable) analyte concentrations will no longer be sampled for those analytes. Thus, oil and grease will be eliminated as an analyte from each of the six monitored wells. Well MW-1 will be the sole location for analysis of benzene, toluene, ethylbenzene, and xylenes (BTEX) compounds, and wells MW-1, MW-4, and MW-5 will be sampled and analyzed for total petroleum hydrocarbons as gasoline (TPHg).

Should you have any questions, please do not hesitate to contact us at (415) 882-1548.

Sincerely yours,

SECOR International Incorporated


Terri Plunkett-Kalmey

Project Geologist

James G. Ritchie, R.G.

Principal Geologist

May 15, 1995





Ms. Madhulla Logan Hazardous Materials Specialist Alameda County Health Care Services Agency 1131 Harbor Bay Parkway, Suite 250 Alameda, California 94502-6577

SUMMARY REPORT - ADDITIONAL SUBSURFACE INVESTIGATION, 2099 GRAND STREET, ALAMEDA, CALIFORNIA.

Dear Ms. Logan:

SECOR International Incorporated (SECOR) is pleased to submit this Summary Report for your review. The report summarizes the results of our Additional Subsurface Investigation of property located at 2099 Grand Street in Alameda, California (the Site). We performed the investigation in accordance with our Work Plan Addendum dated October 11, 1994.

We look forward to answering any questions you may have regarding our report or other related matters. Please do not hesitate to call us at (415) 882-1548.

Sincerely yours,

SECOR International Incorporated

Terri J. Plunkett-Kalmey

Project Geologist

James G. Ritchie, R.G. Principal Geologist



August 12, 1994

Ms. Madhulla Logan Hazardous Materials Specialist Alameda County Health Care Services Agency 80 Swan Way Alameda, California 94621

LETTER OF COMMENT - FOLLOW-UP LETTER FROM ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY REGARDING INVESTIGATION OF 2099 GRAND AVENUE, ALAMEDA, CALIFORNIA

Dear Ms. Logan:

This letter is submitted to comment upon your August 2, 1994 letter regarding the Additional Investigation performed by Science & Engineering Analysis Corporation (SEACOR) for the above referenced property (the site). As you know, our meeting of June 8, 1994 included discussion of the results of our Additional Investigation. Our discussion and tentative agreements were not completely described in your letter, nor was some significant background information as discussed.

During our meeting, we agreed that SEACOR had adequately and properly responded to the August 16, 1993 request of the ACHSA regarding investigation of the former on-site above ground storage tank (AST) area. In particular, our recently-completed investigation focused on laterally characterizing the extent of hydrocarbon-impacted soils. You agreed during the June 8, 1994 meeting that no further assessment of impacted soils would be required. Thus, it was agreed that quarterly groundwater monitoring could be performed using several existing and several proposed monitoring wells.

The monitoring data could be used to assess the need for and/or type of soil or groundwater remediation. While our investigation did not reveal widespread impacted groundwater, groundwater monitoring and reporting was proposed due to the fact that the investigation used "grab" groundwater samples in lieu of installation and sampling of groundwater monitoring wells. The proposed well "network" would be designed to more completely surround the site.

Your letter mentions that additional soils investigation and/or cleanup could be evaluated and possibly required by the ACHSA in the future. We reiterate that the nature and distribution of the hydrocarbons (i.e. low volatile content, slow-moving hydrocarbons in a covered or capped setting) would typically be addressed by simple remedial actions such as capping, monitoring, and/or excavation. These solutions, when implemented, are generally the most cost-effective.

Per your request, we will submit a Work Plan as an Addendum to the previously-approved Work Plan for the above-described additional work. The Work Plan will be provided to you within 30 working days of the date of this letter. We also request an accounting of the costs incurred by the ACHSA against the \$750 previously submitted for the Additional Site Investigation. Should you have any questions or concerns regarding this letter, please do not hesitate to contact me at (415) 882-1548.

Sincerely yours,

Science & Engineering Analysis Corporation

James G. Ritchie, R.G.

Principal Geologist

RAFAT A. SHAHID, Assistant Agency Director

DEPARTMENT OF ENVIRONMENTAL HEALTH Hazardous Materials Division 80 Swan Way, Rm. 200 Oakland, CA 94621 (510) 271-4320

August 2, 1994

Mr. James Ritchie Seacor Corporation 90 New Montgomery Street #620 San Francisco, CA 94105

Reference: 2099 Grand Avenue, Alameda, California

Dear Mr. Ritchie:

This letter is sent as a follow-up to our meeting on June 8, 1994 regarding additional work to be done on the above mentioned site. As per the decisions made during our meeting, I have listed the following investigations/work that is required on the above mentioned property:


- 1. Groundwater monitoring should be conducted at quarterly intervals for a period of one year at a minimum. The need for additional investigation will be re-evaluated by this Department in conjunction with the Regional Water Quality Control Board.
- 2. The four existing monitoring wells MW-1 to MW-4 and four proposed wells (MW-5 to MW-8) should be used for monitoring to get representative samples. Four additional monitoring wells are needed since the existing monitoring wells are not adequate to characterize the extent of contamination in the downgradient direction. The locations for the four proposed monitoring wells as described in your July 13, 1994 letter is acceptable to this Department.
- 3. The need for additional soil investigation and cleanup work will be evaluated in the near future. Hence, please be aware that additional soil investigation/cleanup may be required on the site.

A workplan should be submitted to this office for approval prior to initiating any field work on the site. Also the deposit submitted to this office for oversight of investigation has been exhausted. The deposit/refund mechanism is authorized in Alameda County Ordinance Code Section 3-140.6. Please submit an additional deposit of \$900 to cover future costs pertaining to this case (the hourly rate is \$90/hour). Any unused portion of these funds will be returned to you at the completion of this project provided no further funds are needed.

If you have any questions please call me at (510) 567-6764

Madhulla Logan
Hazardous Materials Specialist

CC: Files July 13, 1994



Ms. Madhulia Logan Hazardous Materials Specialist Alameda County Health Care Services Agency 80 Swan Way Alameda, California 94621

LETTER OF CONFIRMATION - DISCUSSION OF ADDITIONAL INVESTIGATION OF ABOVE GROUND STORAGE TANKS, 2099 GRAND AVENUE, ALAMEDA, CALIFORNIA

Dear Ms. Logan:

This letter is submitted to confirm our discussions regarding the Additional Investigation performed by Science & Engineering Analysis Corporation (SEACOR) for the above referenced property (the site). As you confirmed during our meeting of June 8, 1994 and subsequent conversations, the work performed to date by SEACOR has adequately and properly responded to the requests of the Alameda County Health Care Services Agency (ACHCSA). The recently-completed Additional Investigation sufficiently characterized the extent of hydrocarbons in subsurface soils in the vicinity of the former on-site above ground tank (AGT) farm.

During our conversations, we agreed that assessment of groundwater quality would be the next step in characterizing site subsurface conditions. The attached Site Plan includes proposed additional monitoring well locations, in addition to specifying those existing monitoring wells proposed for abandonment and those proposed for incorporation into a quarterly groundwater monitoring program. The groundwater monitoring data would be used in conjunction with existing data to assess the need for and/or type of remediation at the site. We agreed that one year of quarterly monitoring and reporting would be conducted; SEACOR additionally proposes to perform a tidal study, consisting of extended water level measurements in on-site wells to assess the influence of tides upon the water table elevation beneath the site.

We would appreciate your verification of these items in writing. Should you have any questions or concerns regarding this letter or our request, please do not hesitate to contact me at (415) 882-1548.

Sincerely yours,

Science & Engineering Analysis Corporation

James G. Ritchie, R.G. Principal Geologist June 4, 1993



Mr. Kevin Tinsley
Hazardous Materials Specialist
Alameda County Health Care Services Agency
Department of Environmental Health
80 Swan Way, Room 200
Oakland, California 94521

WORK PLAN TO CONDUCT ADDITIONAL SITE INVESTIGATION, GRAND MARINA FACILITY, 2099 GRAND STREET, ALAMEDA, CALIFORNIA

Dear Mr. Tinsley:

The attached Work Plan is submitted by Science & Engineering Analysis Corporation (SEACOR) in response to your written request of March 30, 1993. SEACOR is authorized to implement this Work Plan upon approval by the Alameda County Health Care Services Agency (ACHCS).

Please note that the attached Work Plan is submitted in partial fulfillment of the requests made in your March 30, 1993 letter. The information gained from implementation of the Work Plan is necessary to fully address your requests.

We would appreciate your review of and comment on the Work Plan. Please do not hesitate to contact us at (415) 882-1548 with any questions or comments.

Principal-in-Charge

Sincerely yours,

Science & Engineering Analysis Corporation

James G. Ritchie, R.G.

Principal Geologist

attachment

cc: Mr. Edgar Howell - ACHCS, Hazardous Materials Division

No. 4974

Mr. Richard Hiett - RWQCB, San Francisco Bay Region

CROGRMAR WP 50085-001-01 white -env health yellow -facility pink -files

ALAMEDA COUNTY, DEPARTMENT OF ENVIRONMENTAL HEALTH

Call fory shout with with an eligralar, 80 Swan Way, =200 Oaklana, CA 94621 (415) 271-4320

Hazardous Materials Division Inspection Form

	Site ID#	Site Name	itrand	Marina	Todays Date	· 4/3/9
	Site Adaress <u>2</u>	1407 G	rand ST.	· 	EPA ;D#	
	city Aium	neda		Zip <u>94</u>	. Phone	
_	MAX Amt. Stored > 500lb Hazardous Waste generat he marked items represe	ed per month	1? Y N	II. Business Plans, Acute III. Underground Tanks		
ا #	ne markea ilerris represe	TI VIOIGIIOI E	s of the Calif, Adminis	ildiloit Code (CAC) oi i	Tie nediti a salety Code	9 (H3&C)
Manifest	GENERATOR (Title 22) 1. Waste ID 2. EPA ID 3. > 90 days 4. Label dates 5. Blennial 6. Records 7. Correct 8. Copy sent 9. Exception 10. Copies Recid	* 66471 66472 66508 66508 66493 66492 66492 66484 66492	Mr. Zacco Off Samp (gasolnie,	ived on site or took the wr ling points of		warked
Misc.	11. Treatment12. On-site Disp. (H.S.&C.)13. Ex Haz. Waste	66371 26189.5 66570	20 feut.	Samutinus or	us could not	le le
Prevention	14. Communications 15. Alsie Space 16. Local Authority 17. Maintenance 18. Training	67121 67124 67126 67120 67105	Eduplied it bity lie	exactly when we are or walk of the marked	LO fret older warp. Sample off for all	Location Buown
gency	19. Prepared 20. Name List 21. Caples 22. Emg. Coord. Ting.	67140 67141 67141 67144	foirts. The	e valper would	/ /	along
Containers, Tanks	23. Condition 24. Compatibility 25. Maintenance 26. Inspection 27. Buffer Zone 28. Tank Inspection 29. Containment 30. Safe Storage 31. Freeboard	67241 67242 67243 67244 67246 67259 67245 67261 67257	20 feat a run 20 g	shert possible text in longto	, since pipes 4.	generally
l.B	TRANSPORTER (Title 22) 32. Applic./Insurance33. Comp. Cert./CHP Irsp34. Containers	66428 66448 66465				
Manifest	35, Vehicles 36, EPA ID ≠s 37, Correct 38, HW Delivery 39, Records	66465 66531 66541 66543 66544				
Confre	40. Name/ Covers 41. Recyclables	66545 66800				
Rev ó,						ı
	Contact:					
	Title:	· · · · · · · · · · · · · · · · · · ·		Inspector:		
	Signature: _			Signature:	سے میں نے بنت کی سات نے سات کی بہت کی بہت کی بہت کا جہستانہ کی	{

LOP - RECORD CHANGE REQUEST FORM

Mark Out What Needs Changing and Hand to LOP Data Entry (Name/Address changes go to Annual Programs Data Entry)

Insp: ML

AGENCY # : 10000 SOURCE OF FUNDS: F

SUBSTANCE: 8006619

StID : 3820

LOC: -0-

StID : 3820 SITE NAME: Grand Marina

DATE REPORTED : 05/24/88

ADDRESS : 2099 -0 Grand St

DATE CONFIRMED: 05/24/88

CITY/ZIP : Alameda

94501

MULTIPLE RPs : N

SITE STATUS

CASE TYPE: O CONTRACT STATUS: 4 PRIOR CODE:184 EMERGENCY RESP: -0-

RP SEARCH: S

DATE COMPLETED: 03/20/92

PRELIMINARY ASMNT: U DATE UNDERWAY: 11/18/87 DATE COMPLETED: 03/.

REM INVESTIGATION: - DATE UNDERWAY: -0- DATE COMPLETED: -0
REMEDIAL ACTION: - DATE UNDERWAY: -0- DATE COMPLETED: -0
POST REMED ACT MON: - DATE UNDERWAY: -0- DATE COMPLETED: -0-

ENFORCEMENT ACTION TYPE: 1

DATE ENFORCEMENT ACTION TAKEN: 03/20/92

LUFT FIELD MANUAL CONSID: 3HSCAW CASE CLOSED: -

DATE CASE CLOSED: -0-

DATE EXCAVATION STARTED: 11/18/87 REMEDIAL ACTIONS TAKEN: ED-

RESPONSIBLE PARTY INFORMATION _______

RP#1-CONTACT NAME: Manager

COMPANY NAME: Grand Marina ADDRESS: 2099 Grand St.

CITY/STATE: Alameda, Ca 94501

	INSPECTOR VERIFICATION:					
NAME		DATE				
Name/Address	Changes Only	DATA ENTRY INF	UT: Case Progress Changes			
ANNPGMS	LOP	DATE	LOP DATE			

HCSA BI-WEEKLY TIME RECORD

		97-09							_ DEPT	COST CE	nter: _	<u> </u>	
D A T E	D A Y	REGULAR TIME	T	ENTHS O	VACATION	FLTG HOLDAY	COUNTY BOLIDAY	PAID LEAVE	(SIEC	W APPROPE	R TIME: RIATE TIME AT BOTTON		EACH DAY'S TOTAL TIME
	<u> </u>	(01)	(SI)	(55)	(62)	(62)	(4 6)	(76)	()	()	()	()	
4/ 06	SUN	<u> </u>	<u> </u>		<u> </u>								1
07	MON				<u> </u>			<u> </u>					
08	TUE	 	ļ	 	<u> </u>		<u> </u>	ļ	<u> </u>		1		
09	WED		<u> </u>							<u> </u>			
10	THU	 											
11	FRI	<u> </u>					<u> </u>						
12	SAT	<u> </u>		 	<u> </u>								
1ST WEEK	TOTAL		45.54.78							<u>Gara</u>			
4/		7			7								<u> </u>
13	SUN	 	 		ļ		<u> </u>	,		<u> </u>			
14	MON	 		<u> </u>	<u> </u>					<u> </u>			
15 16	TUE	 			<u> </u>		<u> </u>		<u> </u>	<u> </u>	<u> </u>		
	WED	 					<u> </u>			<u> </u>			
17	THU	ļ					<u> </u>		<u> </u>	<u> </u>			
18	FRI								<u> </u>				
19	SAT						<u> </u>	<u> </u>	<u> </u>				
2ND WEEK	TOTAL												
PAVI	PRRIOD		E SAMELLE		1 s			Jahren der eine 20					
	OTALS	38											
		(01)	(51)	(55)	(61)	(©2)	(66)	(76)	()	()	()	()	
			•										
ADDITION	AI TIM	CONFE TABLE	CPP OF THURSDAY										
		R CODES TABLE:		ORPAYROLL	CLERK FOR CO	DES NOT SHOW	YN.			MINUT	ES TAB	L E	
12 = PR $31 = ST$	emium Raight	O/T WORKED * O/T WORKED * COMP TIME WO COMP TIME WO	53 ORKED • 54	= SICK LE	ave: Maternit Ave: Pamily Mi Ave: Dependen Ement	EDICAL EMER	GENCY • • UTINE APPT • •	10 -	3 MIN = 9 MIN = -15 MIN = -21 MIN =	9.1 HR 9.2 HR	40 - 45 46 - 51	MIN = 0.5 F MIN = 0.7 F MIN = 0.8 F MIN = 0.9 F	HER HER
71 = CO	MP TIN	Y/SUBPOENA FB TAKEN * ITHOUT PAY *	••	= REQUIRE - SUBJECT	S PRIOR DEPT A	PPROVAL			-27 MIN = -33 MIN =			MIN = 1.0 E	ir
	FORMULA FOR TIME ALLOCATION TO TO THE BEST OF MY KNOWLEDGE, I HEREBY CERTIFY THAT I HAVE CORRECTLY MULTIPLE COST CENTERS REPORTED ALL TIME FOR THIS PAY FERIOD ON THIS TIME SHEET.												
COST CENTER NUMBER		PERCENT TIME	TOTAL HOUR	1 -	TIME CODE STRIBUTION	EMPLOYEE'S SIGNATURE			··				
						DATE _	· 		80CIAL S	SEC. NO	·		 -
			<u> </u>			EMPLOY	BE'S NAME						
				REVIEWED AND APPROVED:									
	DATB												

LOP - RECORD CHANGE REQUEST FORM

Mark Out What Needs Changing and Hand to LOP Data Entry (Name/Address changes go to Annual Programs Data Entry)

Insp: ML

AGENCY # : 10000 SOURCE OF FUNDS: F SUBSTANCE: 8006619

SITE NAME: Grand Marina ADDRESS: 2099 Grand St CITY/ZIP: Alameda 94501 DATE REPORTED : 05/24/88 DATE CONFIRMED: 05/24/88

MULTIPLE RPs : N

SITE STATUS _____

CASE TYPE: O CONTRACT STATUS: 4 PRIOR CODE:184 EMERGENCY RESP:

DATE COMPLETED: 03/20/92 RP SEARCH: S

PRELIMINARY ASMNT: C DATE UNDERWAY: 11/18/87 DATE COMPLETED: 03/05/98
REM INVESTIGATION: DATE UNDERWAY: DATE COMPLETED:
REMEDIAL ACTION: DATE UNDERWAY: DATE COMPLETED:
POST REMED ACT MON: DATE UNDERWAY: DATE COMPLETED:

ENFORCEMENT ACTION TYPE: 1 DATE ENFORCEMENT ACTION TAKEN: 03/20/92 LUFT FIELD MANUAL CONSID: 3HSCAW

CASE CLOSED: Y DATE CASE CLOSED: 10/21/98

DATE CASE CLOSED

DATE EXCAVATION STARTED: 11/18/87 REMEDIAL ACTIONS TAKEN: ED-

RESPONSIBLE PARTY INFORMATION

RP#1-CONTACT NAME: Manager

COMPANY NAME: Grand Marina ADDRESS: 2099 Grand St.

CITY/STATE: Alameda, Ca 94501

INSPECTOR VERIFICATION:						
NAME	NAME SIGNATURE			DATE		
Name/Address	Changes Only	DATA ENTRY 1	INPUT:	Case	Progress Changes	
ANNPGMS	LOP	DATE		LOP _	DATE	

LOP - RECORD CHANGE REQUEST FORM

Mark Out What Needs Changing and Hand to LOP Data Entry (Name/Address changes go to Annual Programs Data Entry)

Insp: CL

AGENCY # : 10000 SOURCE OF FUNDS: F SUBSTANCE: 8006619

StID : 3820 LOC: 12/17/98

StID : 3820 SITE NAME: Grand Marina DATE REPORTED : 05/24/88 ADDRESS : 2099 Grand St DATE CONFIRMED: 05/24/88

CITY/ZIP: Alameda 94501 MULTIPLE RPs : N

SITE STATUS

CASE TYPE: O CONTRACT STATUS: 4 PRIOR CODE: 1B4 EMERGENCY RESP:

DATE COMPLETED: 03/20/92 RP SEARCH: S

PRELIMINARY ASMNT: C DATE UNDERWAY: 11/18/87 DATE COMPLETED: 03/20/92
REM INVESTIGATION: DATE UNDERWAY: DATE COMPLETED:
REMEDIAL ACTION: DATE UNDERWAY: DATE COMPLETED:
POST REMED ACT MON: DATE UNDERWAY: DATE COMPLETED:

ENFORCEMENT ACTION TYPE: 1 DATE ENFORCEMENT ACTION TAKEN: 03/20/92 LUFT FIELD MANUAL CONSID: 3HSCAW

CASE CLOSED: Y DATE CASE CLOSED: 03/16/99

DATE EXCAVATION STARTED: 11/18/87 REMEDIAL ACTIONS TAKEN: ED-

RESPONSIBLE PARTY INFORMATION _____

RP#1-CONTACT NAME: Manager

COMPANY NAME: Grand Marina ADDRESS: 2099 Grand St.

CITY/STATE: Alameda, Ca 94501

INSPECTOR VERIFICATION:					
NAME		SIGNATURE	DATE		
Name/Address	Changes Only	DATA ENTRY INPUT	T: Case Progress Changes		
ANNPGMS	LOP	DATE	LOP DATE		

DIVISION OF HAZARDOUS MATERIALS
DEPARTMENT OF ENVIRONMENTAL HEALTH
470 - 27th St., Rm. 322, Oakland, CA 94112 • {415} \$74-7237

DEPARTMENT OF ENVIRONMENTAL HEALTH

ACCEPTED

470 - 27th Street, Third Floor

Oakland, CA 94612

Telephone: (415) 874-7237

DA COUNTY HEALTH CARE SEF CES AGENCY DEPARTMENT OF ENVIRONMENTAL HEALTH HAZARDOUS MATERIALS DIVISION

Department are assure compliance with State and Popularies of laws. The project proposed harein is now released for lease of any required building permits for construction.

A one copy of these accopted plans must be on the lob the sevalable to all contractors and croftsmen involved with the removal.

Any charge or efferations of these plans and spacifications of the removal.

Building Inspection Department to determine if such the Contract of the requirements of State and local laws.

Charges meet the requirements of State and local laws.

Charges meet the requirements of state and local laws.

Charges meet the requirements of state and local laws.

Charges meet the requirements of least 48 hours prior to the following required inspections: These plans have been reviewed and found to be accorded able and essentially most the requirements of State (1974).

The state of State (1974) and (1974)

Sampling.

Removal of Tank and Piping

Issuance of a permit to operate is dependent on connpliance with accepted plans and all applicable laws and Final Inspection

THERE IS, A FINANCIAL PENALTY FOR NOT OBTAINING THESE INSPECTIONS. regulations.

James hr,55/W6 125-0 e T CLOSUM8 301104d COMPESTE AND 2008

Carrier 57848

BAR Comp

TANK CLOSURE/MODIFICATION PLANS UNDERGROUND

l.	Business Name <u>Encinal Marina</u>		
	Business Owner		
2.	Site Address 2051 Grand Street		
	CityAlameda	Zip 94501	Phone 865-1200
3.	Mailing Addresssame	·	
	City	Zip	Phone
4.	Land Owner		
	Address	City, State	Zip
5.	EPA I.D. NoCAC 0000 78269		
6.	Contractor Zaccor Companies,	Inc	
	Address 791 Hamilton AVenue		
	City Menlo Park		Phone 363-2181
	License Type A	D # 478799	
7.	Other (Specify)		
	Address		
	City	Phone	
•	ALDINE SS		

٥.	Contact Person for investigation
	Name Gary Zaccor Title President
	Phone 363-2181
9.	Total No. of Tanks at facilityl
10.	Have permit applications for all tanks been submitted to this office? Yes $[x]$ No $[]$
11.	State Registered Hazardous Waste Transporters/Facilities
	a) Product/Waste Tranporter
	Name H & H Ship Service EPA I.D. No. CAD 004771168
_1	Address 220 China Basin
	City San Francisco State CA Zip-94107
	b) Rinsate Transporter
	Name see above EPA I.D. No.
	Address
	City State Zip
	c) Tank Transporter
	Name Zaccor Companies EPA I.D. No.
	Address Hydroblasting & rinsing on site render tank
	Cityunregulated Zip
	d) Contaminated Soil Transporter
	Name EPA I.D. No
	Address
	City State Zip
12.	Sample Collector
	Name Blaine Tech Services
	Company
	Address 1370 Tully Rd. Suite 505
	City San Jose State CA Zip95150 phone408)723-3974

Ė

13. Sampling Information for each tank or area

Tank or Area				Material sampled	Location & Depth
Capa	city	Historic (past 5			
				in the past? Ye	
15.	NFPA me	ethods used	for rende	ring tank inert?	Yes [] No []
	If yes	, describe.	<u> </u>		
16.	Labora				· · · · · · · · · · · · · · · · · · ·
	Name				
	Addres	ā			
					Zip
	State (Certificatio	on No		

17. Chemical Methods to be used for Analyzing Samples

Contaminant Sought	EPA, DHS, or Other Sample Preparation Method Number	EPA, DHS, or Other Analysis Number
		-

18.	Site Safety Plan submitted:	xes []	ио []	
19.	Workman's Compensation: Yes [] No []	•	
	Copy of Certificate enclosed?	Yes []	Мо []	
	Name of Insurer			

- 20. Plot Plan submitted? Yes [] No []
- 21. Deposit enclosed? Yes [] No []
- 22. Please forward to this office the following information within 60 days after receipt of sample results.
 - a) Chain of Custody Sheets
 - b) Original Signed Laboratory Reports
 - c) TSD to Generator copies of wastes shipped and received
 - d) Attachment A summarizing laboratory results

I declare that to the best of my knowledge and belief the statements and information provided above are correct and true. I understand that information in addition to that provided above may be needed in order to obtain an approval from the Department of Environmental Health and that no work is to begin on this project until this plan is approved.

I understand that any changes in design, materials or equipment will void this plan if prior approval is not obtained.

I will notify the Department of Environmental Health at least two (2) working days (48 hours) in advance to schedule any required inspections. I understand that site and worker safety are soley the responsibility of the property owner or his agent and that this responsibility is not shared nor assumed by the County of Alameda.

Signature of Contractor	
Name (please type)	*
Signature	
Date	
Signature of Site Owner or Operator	
Name (please type)	
Signature	
Date	

NOTES:

- 1. Any changes in this document must be approved by this Department.
- 2. Any leaks discovered must be submitted to this office on an underground storage tank unauthorized leak/contamination site report form within 5 days of its discovery.
- 3. Three (3) copies of this plan must be submitted to this Department. One copy must be at the construction site at all times.
- 4. A copy of your approved plan must be sent to the landowner.

UNDERGROUND TANK CLOSURE/MODIFICATION PLANS

ATTACHMENT A SAMPLING RESULTS

Tank or Area	Contaminant	Location & Depth	Results (specify units)
			•

INSTRUCTIONS

- 2. SITE ADDRESS
 Address at which closure or modification is taking place.
- 5. EPA I.D. NO.
 This number may be obtained from the State Department of Health Services, 916/324-1781.
- 6. CONTRACTOR
 Prime contractor for the project.
- 7. OTHER
 List professional consultants here.
- 12. SAMPLE COLLECTOR

 Persons who are collecting samples.
- 13. SAMPLING INFORMATION
 Historic contents the principal product(s) used in the last 5 years.

Material sampled - i.e., water, oil, sludge, soil, etc.

- 16. LABORATORIES
 Laboratories used for chemical and geotechnical analyses.
- 17. CHEMICAL METHODS:
 All sample collection methods and analyses should conform to EPA or DHS methods.

Contaminant - Specify the chemical to be analyzed.

Sample Preparation Method Number - The means used to prepare the sample prior to analyses - i.e., digestion techniques, solvent extraction, etc. Specify number of method and reference if not an EPA or DHS method.

Analysis Method Number - The means used to analyze the sample - i.e., GC, GC-MS, AA, etc. Specify number of method and reference if not a DHS or EPA method.

NOTE: Method Numbers are available from certified laboratories.

A plan outlining protective equipment and additional specialized personnel in the event that significant amount of hazardous materials are found. The plan should consider the availability of respirators, respirator cartridges, self-contained breathing apparatus (SCBA) and industrial hygienists.

19. ATTACH COPY OF WORKMAN'S COMPENSATION

20. PLOT PLAN

The plan should consists of a scaled view of the facility at which the tank(s) are located and should include the following information:

- a) Scale
- b) North Arrow
- c) Property Line
- d) Location of all Structures
- e) Location of all relevant existing equipment including tanks and piping to be removed
- f) Streets
- g) Underground conduits, sewers, water lines, utilities
- h) Existing wells (drinking, monitoring, etc.)
- i) Depth to ground water
- j) All existing tanks in addition to the ones being pulled

1/88

,		PLEASE TYPE OR PRINT	100 UN 35 COMM-988	PERMIT		
•	_	TRACT BLOCK PAGE LOT PARCEL Encinal Marina	NO. HOUSE CODE	NO.		
	OWNER	NAME 2051 Grand Street 865-1200 ADDRESS PHONE	JOB ADDRESS 2051 Grand S	<u>Stree</u>	t	
	ð	Alameda, CA 94501 PHONE CITY STATE ZIP	APPLICATION FOR PLUMBII CITY OF AI Central Peri	AMEDA	HANICAL F	ERMIT
•	ARCHIT./ ENGR.	NAME LICENSE	2263 Santa Cl Alameda, C	ara Avenu	ı e	
		ADDRESS PHONE	(415) 522-410			
		CITY STATE ZIP	removal of under	groun	d tank	5_
-		I hereby affirm that I am licensed under provisions of Chapter 9 commencing with section 7000 of Division 3 of the Business and Professions Code, and my license is	was to the same			
•		in full force and effect. LICENSE No. A 478799 CITY BUSINESS 1776	VALUATION OF WORK \$			
	E H	AND CLASS LICENSE No. Zaccor Companies, Inc	CONTACT NAME:		·	
	CONTRACTOR	CONTRACTOR NAME 791 Hamilton Ave	CONTACT PHONE			
	S	ADDRESS	ITEMS PLUMBING	NO.	FEE	TOTA
	٥	Menlo Park, CA 94025 363-2181	Basins	1	\$ 6.00	ļ
		-	Baths Catch Basin	 	6.00	
		SIGNATURE	Closets	<u> </u>	6.00	
-			Dishwasher Drinking Fountain	┼	6.00	├
		I hereby affirm that I am exempt from the Contractor's License Law for the following reason (Sec. 7031.5, Business and Professions Code: Any city or county	Fire Sprinklers	1	30.00	1
		which requires a permit to construct, alter, improve, demotish, or repair any struc-	Floor Drain	Ţ	6.00	<u> </u>
		ture, prior to its issuance, also requires the applicant for such permit to file a sign- ed statement that he is licensed pursuant to the provisions of the Contractor's	Floor Sinks Garbage Disposal	 	6.00	├
	İ	License Law (Chapter 9 — commencing with Section 7000) of Division 3 of the	Gas Lines/Meters	 	6.00	
	z	Business and Professions Code) or that he is exempt therefrom and the basis for the alleged exemption. Any violation of Section 7031.5 by any applicant for a permit	Gas Outlets	Ţ	2.00 6.00	<u> </u>
	100	subjects the applicant to a civil penalty of not more than five hundred dollars (\$500.):	Gas Range Gas Test		4.00	├
	1 DECLARATION	L as owner of the property, or my employees with wages as their sole compen-	Hot Tub/Spa		60.00	
		sation, will do the work, and the structure is not intended or offered for sale (Sec. 7044, Business and Professions Code: The Contractor's License Law does not app-	Lawn Sprinklers Leaders Rain Water		10.00	├
		ly to an owner of property who builds or improves thereon, and who does such work	Sewer Abandonment	 	14.00	
	DER	himself or through his own employees, provided that such improvements are not in- tended or offered for sale. If, however, the building or improvement is sold within	Sewer Extension/Replacement		20.00	
	OWNER-BUILD	one year of completion, the owner-builder will have the burden of proving that he did not build or improve for the purpose of sale).	Sewer Repair Showers		10.00	├ -
		I. as owner of the property, am exclusively contracting with licensed contracting.	Sinks	+	6.00	<u> </u>
		tors to construct the project (Sec. 7044, Business and Professions Code. The Con-	Solar System		38.00	ļ
	٥	tractor's License Law does not apply to an owner of property who builds or im- proves thereon, and who contracts for such projects with a contractor(s) licensed	Sumps / Storage Tanks	 	30.00 20.00	27-
		pursuant to the Contractor's License Law).	Tollet		6.00	1
		1 am exempt under Sec	Vault Toilet Washing Machine/Dryer	 	20.00 6.00	<u> </u>
		B&P.C. for this reason	Water Heater Res/Comm	 	6.00/10.00	-
ͺ -	_	Owner's SignatureDate	Water Lines/Meters		6.00	
	COMP. INSURANCE DECLARATION	I hereby affirm that I have a certificate of consent to self-insure, or a certificate of Worker's Compensation Insurance, or a certified copy thereof (Sec. 3800, Lab C.).	MECHANICAL	+	 	
W.	ΠĀ	Policy No 0801858	Air Conditioning Equip.		10.00/20.00	
Ó/	됤	Policy No 0801858 CompanState Funk Certified copy is hereby furnished.	Boiler Control Change		8.00	
5	8	Certified copy is filed with the city Central Permit Office	Convectors	+	4.00	
	Š	Applicant Gary Zaccor pate 4/15/88	Dryer Res/Comm.		6.00/10.00	
Ę,	8	(This section need not be completed if the permit is for one hundred dollars (\$100) or less).	Fans and Blowers Fireplace	 	10.00	
1000	ξ	I certify that in the performance of the work for which this permit is issued, I shall	Flues		4.00	
$:\mathcal{U}_{j_{1}}$	ğ.	not employ any person in any manner so as to become subject to the Workers' Compensation Laws of California.	Furnace Heaters	1	10.00	 -
9		Applicant Date	Hoods Res./Comm	+	4.00/30.00	
1 .	WORKERS	NOTICE TO APPLICANT: If, after making this Certificate of Exemption, you	Panels and Coils		4.00	
•	Ě	should become subject to the Worker's Compensation provisions of the Labor Code, you must forthwith comply with such provisions or this permit shall be	Registers Vents Bath/Kitchen		2.00 4.00	
	₹	deemed revoked.				
	-	I hereby affirm that there is a construction lending agency for the performance of the work for which this permit is issued (Sec. 3097, Civ. C.)	ISSUANCE FEE		6.00	6.0
	LENDER	Lender's Name	Sub Total Fees	\$	26-	
_	-	Lender's Address	AB 941 Fee		5 90	
	-	I certify that I have read this application and state that the information given is true and sorrect. Lagree to comply with all local ordinance and state laws relating to building construction and I make this statement under penalty of law. I hereby authorize representatives of the city/county to enter upon the above mentioned properly to inspection purposes. NOTICE: This permit was expire by limitation if work	Tota' Fees	s <u>3</u>	(.00	
	PLICAN	is not started in 180 days or if work is abandoned for more than 180 days. Do not conceat of cover any construction until the work is inspected and the inspection is recorded on the Building Inspection Card. All inspection requests are required 24.	APPLICATION RECEIVED DATE SIGNED		_	
	4	hours in advance of the inspection 522-4100 X279, 8 30AM to 10AM	APEROVAL 7			
	* }	Contractor Owner	HTE-25 BOTONET / mula	140	Vinda	- great

APPLICATION RECEIVED DATE SIGNED APPROVAL **ISSUED** DATE SIGNED Yellow

TOTAL

6.00

L Owner
L Ager

Agen X

0

Signature of Contractor Owner or Agent

		SOO ACCUME OOD	NO.			
	BLOCK PAGE LOT PARCEL	(0.50				
•	Marina	. ,				
	and Street 865-1200	JOB ADDRESS 2051 Grand S	tree	<u>t</u>		
	PHONE	APPLICATION FOR PLUMBING/MECHANICAL PERMIT				
	a, CA 94501	CITY OF AL	AMEDA			
	STATE ZIP	Central Permi		_		
	LICENSE	. 2263 Santa Cla Alameda, CA		•		
	· · · · · · · · · · · · · · · · · · ·	(415) 522-4100		•		
	ESS PHONE	DESCRIPTION OF WORK				
	STATE ZIP	removal of underg	ימנוסמי	d tank	~	
			10011	<u>a carrit</u>	<u> </u>	
	areby affirm that I am licensed under provisions of Chapter 9 commencing with					
	action 7000 of Division 3 of the Business and Professions Code, and my license is a full force and effect.	VALUATION OF WORK\$				
	LICENSE NO. A 478799 CITY BUSINESS 1776	••				
1	AND CLASS	CONTACT NAME:			- , -	
.:4	Zaccor Companies, Inc	CONTACT PHONE			<u>.</u>	
CONTRACI	contractor NAME 791 Hamilton Ave		1 110	FEE	TOTAL	
됳		ITEMS PLUMBING	NO.	FEE _	TOTAL	
8	Menlo Park, CA 94025 363-2181 CITY STATEZIP PHONE	Basins		\$ 6.00		
- 1	CITY STATE/ZIP PHONE	Baths		6.00		
- 1	DIOMATURE	Catch Basin	 	8.00		
	SIGNATURE	Closets Dishwasher		6.00		
		Drinking Fountain		6.00		
1	I hereby affirm that I am exempt from the Contractor's License Law for the following reason (Sec. 7031.5, Business and Professions Code: Any city or county	Fire Sprinklers	 	30.00 6.00		
_	which requires a permit to construct alter improve demolish of fedalf any struc-	Floor Drain Floor Sinks	 	6.00	 	
	which requires a permit to file a sign- ture, prior to its issuance, also requires the applicant for such permit to file a sign- ed statement that he is licensed pursuant to the provisions of the Contractor's	Garbage Disposal	 	6.00	<u> </u>	
	ticense taw (Chanter 9 commencing with Section 7000) of Division 3 of the	Gas Lines/Meters		6.00	ļ	
z	Business and Professions Code) or that he is exempt therefrom and the basis for the alleged exemption. Any violation of Section 7031.5 by any applicant for a permit	Gas Outlets	ļ	2.00 6.00	 	
ᅙ	subjects the applicant to a civil penalty of not more than tive hundred collars	Gas Pange		4.00		
DECLARATION	(\$500.).	Hot Tub/Spa		60.00		
×	1, as owner of the property, or my employees with wages as their sole compensation, will do the work, and the structure is not intended or offered for sale (Sec.).	Lawn Sprinklers		6.00		
96	7044, Business and Professions Code: The Contractor's License Law coes not app-	Leaders Rain Water Sewer Abandonment	 	14.00	 	
띮	i blissest as there are bits own amployage introduced in at such improvements are not in-	Sewer Extension/Replacement		20.00		
글	tended or offered for sale. If, however, the building or improvement is sold within one year of completion, the owner-builder will have the burden of proving that he	Sewer Repair		10.00		
OWNER-BUILDER	did not build or improve for the purpose of sale).	Showers Sinks	 	6.00	 	
	I, as owner of the property, am exclusively contracting with licensed contractors to construct the project (Sec. 7044, Business and Professions Code; The Con-	Solar System	 	38.00		
	terretor's tissees taw does not sooly to so owner of property who puties of mit	Sumpe		30.00		
_	proves thereon, and who contracts for such projects with a contractor(s) licensed pursuant to the Contractor's License Law).	Storage Tanks Tollet	 	20,00 8,00		
	☐ I am exempt under Sec.	Vault Tollet	 	20.00		
	B&P.C. for this reason	Washing Machine/Dryer		6.00		
	Owner's SignatureDate	Water Heater Res/Comm	 	6.00/10.00		
		Water Lines/Meters	 	0.00	f	
Š	I hereby affirm that I have a certificate of consent to self-insure, or a certificate of Worker's Compensation insurance, or a certified copy thereof (Sec. 3800, Lab C.).	MECHANICAL				
¥	Policy No 0801858 companState Fur	Air Conditioning Equip.		10.00/20.00	 	
3	Certified copy is hereby furnished.	Boiler Control Change	 	6.00	 	
, Ħ	Six Cartified convis filed with the city Central Permit Office	Convectors		4.00		
<u>8</u>	Applicant Gary Zaccor Date 4/15/88	Dryer Res/Comm.	ļ	6.00/10.00 10.00	 	
WORKERS' COMP, INSURANCE DECLARATIO	(This section need not be completed if the permit is for one hundred dollars	Fans and Blowers Fireplace	 	4.00	 	
	(\$100) or less). i certify that in the performance of the work for which this permit is issued, I shall	Flues	<u> </u>	4.00		
	not employ any person in any manner so as to become subject to the Workers.	Furnace		10.00	 	
	Compensation Laws of California.	Heaters Hoods Res./Comm	-	4.00/30.00	 	
	Applicant Date	Panels and Colls		4.00		
畜	NOTICE TO APPLICANT: If, after making this Certificate of Exemption, you should become subject to the Worker's Compensation provisions of the Labor	Registers	ļ	4.00	 	
ğ	Code, you must forthwith comply with such provisions or this permit shall be	Vents Bath/Kitchen	 	1 7.00	 	
	deemed revoked.	ISSUANCE FEE	17	6.00	6.00	
83	I hereby affirm that there is a construction lending agency for the performance of the work for which this permit is issued (Sec. 3097, Civ. Ci).			26 -		
LENDI	Lender's Name	Sub-Total Fees	\$	20-		
ij.	Lender's Address	AB 941 Fee		5 00		
	I deriry that I have read this application and state that the information given is	Total Fees	, 3	1.00		
	I selle and cherect I agree to comply with all local ordinance and state laws relating	(DIM) rees	*			
APPLICANT	to building construction and I make this statement under penalty of law. I hereby	1				
	norty for inspection number. NOTICE: This permit will expire by imitation I' work	APPLICATION RECEIVED				
	is not started in 180 days or if work is abandoned for more than 180 days. Do not conceal or cover any construction until the work is inspected and the inspection is	DATE SIGNED		_	,	
	recorded on the Building Inspection Card. All inspection reques's are required 24		/7/	7	/	
	hours in advance of the Inspection, 522-4100 X279, 8 30AM to 10AM	APPROVAL PARE 25 SWED		Karal .	لعصيب	
	Contactor Strain	The contract	77	من سر سرمر	-U	
	Agent X	ISSUED	~ (
	Signature of Contractor, Owner or Agent	DATE SIGNED				

ELEMBING & MECHANICAL PLANS

APPROVED

Donald I Rodrigues, Sr Plbg & Mech Insp.

2000 GAL GAS TON TOTAL PEMOUAL/40 PIP cae off. GRAND 35041 G 0000 L WAM TS BY PLUMBING & MECHANICAL PLANS APPROVED

Donald I. Rodrigues Sr Plbg & Mech Insp

FORTMANJ 3000 of 7 754 GRAZO ST. EXISTING

EXISTING TOTAL REMOVAL / NO PIPING

م الرار

2000 GAL GAS TANK