RAFAT A. SHAHID, Director





DEPARTMENT OF ENVIRONMENTAL HEALTH Environmental Protection Division 1131 Harbor Bay Parkway, #250 Alameda, CA 94502-6577 (510) 567-6700

# REMEDIAL ACTION COMPLETION CERTIFICATION

August 9, 1995

Mrs. J.C. Delanoy 21 Duke Rancho Mirage, CA 92270

UNDERGROUND STORAGE TANK (UST) CASE
Re: Former Camisa Bros. Roofing, 1901 Broadway, Alameda, CA 94501
Site No. 310

Dear Mrs. Delanoy,

This letter confirms the completion of site investigation and remedial action for the 550-gallon gasoline underground storage tank formerly located at the above described location. Enclosed is the Case Closure Summary for the referenced site for your records.

Based upon the available information, including the current land use, and with the provision that the information provided to this agency was accurate and representative of site conditions, no further action related to the underground storage tank release is required.

This notice is issued pursuant to a regulation contained in Title 23, California Code of Regulations, Division 3, Chapter 16, Section 2721(e). If a change in land use is proposed, the owner must promptly notify this agency.

Please telephone Juliet Shin at (510) 567-6700 if you have any questions regarding this matter.

Sincerely,

Refet a. Shahid (by Jan)
Rafat A. Shahid, Director

c: Acting Chief, Hazardous Materials Division - files Juliet Shin, ACDEH Kevin Graves, RWQCB Mike Harper, SWRCB

LOP\Completion

01-2001

## CASE CLOSURE SUMMARY Leaking Underground Fuel Storage Tank Program

#### AGENCY INFORMATION I.

Date: April 5, 1995

Alameda County-HazMat Address: 1131 Harbor Bay Pkwy Agency name:

City/State/Zip: Alameda, CA 94502 Phone: (510) 567-6700 Responsible staff person: Juliet Shin Title: Senior HMS

#### CASE INFORMATION II.

Site facility name: Former Camisa Bros. Roofing

Site facility address: 1901 Broadway, Alameda, CA 94501

Local Case No./LOP Case No.: 310 RB LUSTIS Case No: N/A

SWEEPS No: N/A URF filing date: 12/13/94

## Responsible Parties:

### Addresses:

### Phone Numbers:

Mrs. J.C. Delanoy

21 Duke

(510) 834-3311

Rancho Mirage, CA 92270

Tank No:	Size in gal.:	Contents:	<u>Closed in-place</u> <u>or removed?:</u>	Date:
1	550	gasoline (leaded and unleaded)	removed	4/28/94

### RELEASE AND SITE CHARACTERIZATION INFORMATION III.

Cause and type of release: Unknown

Site characterization complete? YES

Date approved by oversight agency: 2/15/95

Monitoring Wells installed? No

Proper screened interval? NA

Highest GW depth below ground surface: Lowest depth: Depth to water in tank pit was observed to be at approximately 6.5-feet below ground surface

Flow direction: Unknown

Most sensitive current use: Unknown

## Leaking Underground Fuel Storage Tank Program

Are drinking water wells affected? NO Aquifer name: Unknown

Is surface water affected? NO Nearest affected SW name: None

Off-site beneficial use impacts (addresses/locations): None

Report(s) on file? YES Where is report(s) filed? Alameda County

1131 Harbor Bay Pkwy Alameda, CA 94502

Treatment and Disposal of Affected Material:

<u>Material</u>	Amount (include units)	Action (Treatment of Disposal w/destination)	<u>Date</u>
Tank	550-gallon	Erickson, Inc. 255 Parr Blvd. Richmond, CA 94801	4/28/94
Purge water	225 gallons	American Valley Environ. Services, Inc. 2930 Geer Road, Ste 156 Turlock, CA 95382	6/9/94

III. RELEASE AND SITE CHARACTERIZATION INFORMATION (Continued)
Maximum Documented Contaminant Concentrations - - Before and After Cleanup

Contaminant	Soil (ppm) Before After	Water (ppm) Before After Purging
TPH (Gas) TPH (Diesel)	3.7 NA	4.8 ND NA
Benzene	0.015	0.64 ND
Toluene	0.078	0.70 ND
Xylene	0.36	0.55 ND
Ethylbenzene	0.042	0.076 ND
Lead	ND	

## IV. CLOSURE

Does completed corrective action protect existing beneficial uses per the Regional Board Basin Plan? **Undetermined** 

Does completed corrective action protect potential beneficial uses per the Regional Board Basin Plan? **Undetermined** 

## Leaking Underground Fuel Storage Tank Program

Does corrective action protect public health for current land use? YES

Site management requirements: NA

Should corrective action be reviewed if land use changes? NO

Monitoring wells Decommisioned:

Number Decommisioned:

Number Retained:

List enforcement actions taken: None

List enforcement actions rescinded:

LOCAL AGENCY REPRESENTATIVE DATA ٧.

Name: Juliet Shin

Signature:

Title: Senior HMS Date: 4/6/95

Reviewed by

Name: Eva Chu

Signature:

Name: Madhulla Logar Signature:

RWQCB NOTIFICATION VI.

Date Submitted to RB:

RWOCB Staff Name: Kevin Graves

Title: Hazardous Materials Specialist

Date:

Title: Hazardous Materials Specialist

Date:

Title: San. Engineering Asso. Date:

ADDITIONAL COMMENTS, DATA, ETC. VII.

One 550-gallon underground storage tank was removed from the site on April 28, 1994. Although the soil sample collected from the fill end of the tank pit did not identify contaminants above detection limits, and the soil sample collected from the stockpiled soil identified only low levels of contaminants, TPHg at 3.7 ppm and benzene at 0.015 ppm, the initial "grab" ground water sample collected from the tank pit identified elevated levels of TPHg at 4,800 ppb and benzene at 640 ppb. This water sample was collected without first purging the tank pit.

On June 13, 1994, the tank pit was purged of 225 gallons of water and the ground water recharged in the tank pit to approximately 5.5 feet below ground surface. Another "grab" ground water sample was collected from the pit and analyzed for TPHg and BTEX. No contaminants were identified above the detection limits.

Based on the low levels of soil and ground water contamination, this site should be considered for closure.

Page 3 of 3