

ING

ARCO TANKS/LINE MONITORING SYSTEM CERTIFICATION FOR POSITIVE SHUTDOWN



<u>Location</u>	<u>Service Company</u>	<u>Date</u>
<u>ARCO # 2152</u>	<u>API / RONAN</u>	<u>12-6-91</u>
<u>22141 Center</u>	<u>3031 Tischway</u>	
<u>Castro Valley, CA</u>	<u>San Jose, CA</u>	

Technician Performing Test B. THORNTON

TECH # 180

MANUFACTURER RONAN

PRODUCT LINE
TYPE DWF

TANK
TYPE DWF

WASTE OIL TANK
TYPE _____

MONITOR
 Non Existing

MONITOR
 Non Existing

MONITOR
 Non Existing

API/PSD Operational

PSD Operational

Operational

Non Operational

Non Operational

Non Operational


DEAR SIR.

THIS IS TO CERTIFY THAT THE ANNUAL MONITORING SYSTEM TEST WERE PERFORMED AT THE ABOVE REFERENCED FACILITY, THE METHOD USED TO TEST THE MONITORING SYSTEM IS APPROVED BY, AND EXCEEDS THE SPECIFICATION ACCORDING TO THE MANUFACTURER.

SINCERELY

B. Thornton

Please leave one copy at the facility and send one copy to ARCO.



A.P.I./RONAN LEAK DETECTION SYSTEMS
 2300 EAST ARTESIA BOULEVARD • LONG BEACH, CA 90805
 (213) 984-5380 • FAX (213) 984-5390

SERVICE ORDER NUMBER 00107	
DATE OF SERVICE 12-6-91	
TECHNICIAN B. THORNTON	
ARRIVED 3:00 pm	DEPARTED 5:15 p

1107

BILL TO		SITE ID NUMBER ARCO # 2152	
ADDRESS		ADDRESS AND CROSS STREET 22141 Center St. @ Grove	
CITY, STATE AND ZIP CODE		CITY, STATE AND ZIP CODE Castro Valley, CA 94546	
P.O. NUMBER 280587	MODEL NUMBER X765-A3-3x-3s	SERIAL NUMBER 8-1117	SITE PHONE # (415) 581-1268
SERVICE REQUESTED BY/C.O. ARCO			
SERVICE REQUESTED Install KV-700			

DESCRIPTION OF WORK PERFORMED: Install 3rd KV-700 interposing relays - RUN conduit & pull wire - Terminate wires for failsafe Positive shutdown. Test all 3 lines for shutdown - all pass - label system & relays. cert & seal

SYSTEM CERTIFIED YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> PSD	SYSTEM PSD YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	SYSTEM RUNNING YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	WASTE OIL YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	SYSTEM SEALED YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
---	---	---	--	--

DEMONSTRATED FOR:

QTY	MATERIALS USED MODEL #	DESCRIPTION	UNIT PRICE	TOTAL
3 rd	KV-700	24VDC - N.O.		
1	1/2" X 90°	LIT. FLEX CONN	3.90	} 14.90
1	1/2" X 90°	LIT. FLEX CONN	2.35	
2	1/2" LIT. FLEX		1.96	
15	FOUR LUGS		.20	
40'	18g TFFU wire		.10	
1	1/2" chase nipple		.05	
3	wire nuts		.05	
HOURS-MILEAGE		RATE	AMOUNT	
LABOR	2.25			
TRAVEL	1			
MILES	44			

SUB-TOTAL	
TAX	
TOTAL	

CUSTOMER SIGNATURE: *[Signature]* DATE: 12-6-91 TIME: 5:15



Receipt for Certified Mail

No Insurance Coverage Provided
Do not use for International Mail
(See Reverse)

90701-1488
5300

x 6411
3702-6411



Sent to # 2152 Alameda Co	
Street and No	
P.O., State and ZIP Code	
Postage	\$
Certified Fee	
Special Delivery Fee	
Restricted Delivery Fee	
Return Receipt Showing to Whom & Date Delivered	
Return Receipt Showing to Whom, Date and Addressee's Address	
TOTAL Postage & Fees	\$
Postmark or Date 5-7-92	

PS Form 3800, June 1991

m

Detector Test Results

NR
L. 94546

Dear Sirs:

This letter is to notify you that the monitoring system and leak detectors at the above facility passed the intergity system test, as noted in the attached test results for the underground storage tank and line system on 12-6-91 and 7-3-91. Neither the tanks nor product lines require annual precision tests, to my knowledge.

ARCO is committed to the compliance of all environmental laws that govern the safe operation of underground storage tanks. Feel free to call me at 310-407-2610.

Sincerely,

ARCO Products Company
a division of Atlantic Richfield Company

C. A. Holman
Env. Compl. Engineer

out of this rece
3811
the address
in a
CERT

ARCO Products Company
17315 Studebaker Rd.
Cerritos, California 90701-1488
Telephone 310 404 5300



Mailing Address: Box 6411
Artesia, California 90702-6411

5-8-92

Alameda County Health
Dept. of Env. Health
80 Swan Way Room 200
Oakland, Ca 94621

Attn: Ravi Arulanantham

Re: Monitor and Leak Detector Test Results
ARCO #2152
22141 Center
Oakland, Ca. 94546

Dear Sirs:

This letter is to notify you that the monitoring system and leak detectors at the above facility passed the intergity system test, as noted in the attached test results for the underground storage tank and line system on 12-6-91 and 7-3-91. Neither the tanks nor product lines require annual precision tests, to my knowledge.

ARCO is committed to the compliance of all environmental laws that govern the safe operation of underground storage tanks. Feel free to call me at 310-407-2610.

Sincerely,

ARCO Products Company
a division of Atlantic Richfield Company

C. A. Holman
Env. Compl. Engineer

ARCO Products Compa
2000 Alameda de las Pulgas
Mailing Address: Box 5811
San Mateo, California 94402
Telephone 415 571 2400



**MONITOR CERTIFICATION
INSPECTION**

This letter certifies that the monitor is in place, the probes are in the correct positions and the operation of the system.

FACILITY # 02152

DATE 7-3-91

DEALER 22141 Center St

ADDRESS Castro Valley

TYPE OF MONITOR Ronan

SYSTEM FUNCTION

TANKS PASS FAIL N/A

LINES PASS FAIL N/A

IS CONSOLE LABELED CORRECTLY? YES NO CORRECTED

COMMENTS: _____

INSPECTED BY:

CONTRACTOR Scott Co.

TECHNICHIAN P. Ferreira

SIGNATURE [Signature]

ARCO Products Company
2000 Alameda de las Pulgas
Mailing Address: Box 5011
San Mateo, California 94402
Telephone 415 571 2400



MONITOR CERTIFICATION
INSPECTION

This letter certifies that the monitor is in place, the probes are in the correct positions and the operation of the system.

DATE 8-29-90

FACILITY # 2152

DEALER _____

ADDRESS 22141 CENTER ST
CASTRO VALLEY

TYPE OF MONITOR RDWAR-3

SYSTEM FUNCTION

TANKS PASS FAIL _____ N/A _____

LINES PASS FAIL _____ N/A _____

IS CONSOLE LABELED CORRECTLY? YES _____ NO _____ CORRECTED _____

COMMENTS: _____

INSPECTED BY: CONTRACTOR AFC

TECHNICIAN LINSTEADT

SIGNATURE [Signature]