

August 16, 1993

QUARTERLY GROUNDWATER MONITORING REPORT ASE JOB NO. 2596

at
The Goodman Property
2501 Santa Clara Avenue
Alameda, California 94501

Prepared for:
Ms. Helen Goodman
3239 Thompson Avenue
Alameda, California 94501

Prepared by:
AQUA SCIENCE ENGINEERS, INC.
2411 Old Crow Canyon Road, #4
San Ramon, CA 94583
(510) 820-9391

1.0 INTRODUCTION

Site Location (Site), See Figure 1
The Goodman Property
2501 Santa Clara Avenue
Alameda, CA 94501

Property Owner

Ms. Helen Goodman

3239 Thompson Avenue

Alameda, CA 94501

Environmental Consulting Firm Aqua Science Engineers, Inc. (ASE) 2411 Old Crow Canyon Road, #4 San Ramon, CA 94583 Contact: David Allen, Project Manager (510) 820-9391

Agency Review
Alameda County Health Care Services Agency (ACHCSA)
80 Swan Way, Room 350
Oakland, CA 94621
Contact: Ms. Juliet Shin
(510) 271-4530

California Regional Water Quality Control Board (RWQCB), San Francisco Bay Region 2101 Webster Street, Suite 500 Oakland, CA 94612 Contact: Mr. Richard Hiett (510) 286-4359

The following is a report detailing the results of the July 27, 1993, quarterly groundwater sampling at the above referenced site. This sampling was conducted as required by the RWQCB and the ACHCSA. ASE has prepared this report on behalf of the property owner, Ms. Helen Goodman. This report is intended to supplement to the following ASE report: "Final Report of Environmental Activities Detailing the Source Removal and Assessment Operations" dated June 8, 1993.

2.0 GROUNDWATER FLOW DIRECTION AND GRADIENT

On July 27, 1993, ASE resurveyed the top of casing elevations relative to a project datum. The top of casing elevations are presented below in Table One.

Prior to purging water from the three monitoring wells, ASE measured the depth to water in each site well using a water level sounder. The surface of the groundwater was also checked for the presence of free-floating hydrocarbons or sheen. No free-floating hydrocarbons or sheen were detected in any of the wells. Depths to groundwater are presented below in Table One.

TABLE ONE
Summary of Groundwater Well Survey Data

Well I.D.	Date of Measurement	Top of Casing Elevation (relative to project datum)	Depth to Water (feet)	Groundwater Elevation (project data)
MW-1	4-26-93	23.96	5.68	18.28
	5-26-93		6.08	17.88
	6-29-93		6.22	17.74
	7-27-93		6.51	17.45
MW-2A	4-26-93	23.87	4.90	18.97
VI W - 2.A	5-26-93	23.67	p. 5.56	18.31
	6-29-93		5.80	18.07
	7-27-93		6.18	17.69
MW-3	4-26-93	25.00	6.65	18.35
172 71 0	5-26-93		7.20	17.80
	6-29-93		7.42	17.58
	7-27-93		7.76	17.24

Groundwater elevation contours for the July 27, 1993 measurements are presented on Figure 2. Groundwater is currently flowing to the northeast beneath the site at a gradient of 0.006 feet/feet.

3.0 GROUNDWATER SAMPLE COLLECTION AND ANALYSIS

Prior to sampling, each monitoring well was purged of five well casing volumes of water using an electric PVC pump. Groundwater samples were then collected from each well using a new polyethylene bailer. The samples were decanted from the bailer into three 40-ml volatile organic analysis (VOA) vials. In addition to the VOA vial samples, groundwater

Goodman Property Quarterly Groundwater Monitoring Report - July 27, 1993

from well MW-1 was also decanted into two brown 1-liter bottles. The samples were then preserved with hydrochloric acid (except for the sample to be analyzed for pH), capped, labeled and placed on wet ice for transport to Priority Environmental Labs of Milpitas, California under chain-of-custody.

The analytical results for this and previous quarters are presented below as Tables Two and Three, and the certified laboratory report and chain-of-custody form are included as Appendix A.

The well purge water was placed in 55-gallon steel 17H drums, labeled, and left on site for temporary storage.

The groundwater samples were analyzed for total petroleum hydrocarbons as gasoline (TPH-G) by modified EPA Method 5030/8015, benzene, toluene, ethylbenzene and xylenes (BTEX) by EPA Method 602, pH by EPA Method 9045 and electrical conductivity by EPA Method 120.1. In addition, the samples from well MW-1 were also analyzed for total petroleum hydrocarbons as diesel (TPH-D) by modified EPA Method 3510/8015 and oil and grease by EPA Method 5520 C&F.

TABLE TWO
Summary of Analytical Results of WATER Samples
TPH as Gasoline and Diesel, BTEX, and Oil & Grease
All results are in parts per billion

Well ID & Dates Sampled	TPH Gasoline	TPH Diesel	Benzene	Toluene	Ethyl Benzene	Total Xylenes	Oil & Grease
<u>MW-1</u>							
10-26-92	<50	<50	<0.5	<0.5	<0.5	<0.5	<500
04-26-93	<50	<50	<0.5	<0.5	< 0.5	<0.5	<500
07-27-93	<50	<50	<0.5	<0.5	<0.5	<0.5	<500
<u>MW-2*</u> 10-26-93	32,000		76	100	77	220	
<u>MW-2A</u> 04-26-93	<50		<0.5	<0.5	<0.5	<0.5	
07-27-93	<50		<0.5	< 0.5	<0.5	<0.5	
MW-3 10-26-93	320		2.2	1,7	1.3	9.5	
04-26-93	2200		3.5	4.6	8.0	28	
07-27-93	7200		3.9	4.7	6.2	19	
01-21-93	1200		3.7	7./	0.2	17	
EPA METHOD	5030/ 8015	3510/ 8015	602	602	602	602	5520 C&F

^{--- =} Not Analyzed

TABLE THREE
Summary of Chemical Analysis of WATER Samples
pH and Electrical Conductivity
July 27, 1993 Sampling

	pН	Conductivity (uS)
Sample I.D.		
MW-1	6.6	530
MW-2A	6.7	580
MW-3	6.7	630
EPA METHOD	9045	120.1

^{* =} Monitoring well MW-2 was destroyed during overexcavation activities.

4.0 CONCLUSIONS

Groundwater flowed to the northeast beneath the site at a gradient of 0.006 feet/feet on July 27, 1993. The benzene concentration in groundwater from well MW-3 exceeded the California EPA Department of Toxic Substance Control maximum contaminant level for drinking water of 1 part per billion. No hydrocarbons were detected in groundwater samples from monitoring wells MW-1 and MW-2A.

5.0 RECOMMENDATIONS

ASE recommends continuing the quarterly groundwater sampling program. After the first year, a review of the quarterly reports will dictate if any further action will be required.

Monthly groundwater elevation readings will continue to be collected during the next quarter.

6.0 REPORT LIMITATIONS

The results of this report represent the conditions at the time of the groundwater sampling at the specific locations where the groundwater samples were collected, and for the specific parameters analyzed for by the laboratory. It does not fully characterize the site for contamination resulting from sources other than the former underground storage tanks and associated plumbing at the site, or for parameters not analyzed for by the laboratory. All of the laboratory work cited in this report was prepared under the direction of independent CSDHS certified laboratory. The independent laboratory is solely responsible for the contents and conclusions of the chemical analysis data.

Aqua Science Engineers appreciates the opportunity to provide environmental consulting services to you, and trust that this report meets your needs. Please feel free to call us at (510) 820-9391 if you have any questions or comments.

Respectfully submitted,

AQUA SCIENCE ENGINEERS, INC.

Kalrt C. Kitay Robert E. Kitay

Project Geologist

Attachments: Figures 1 & 2

Appendices A and B

cc: Ms. Juliet Shin, Alameda County Health Care Services Agency

Mr. Richard Hiett, RWQCB, San Francisco Bay Region




SITE LOCATION MAP

Goodman Property 2501 Santa Clara Avenue Alameda, California

Aqua Science Engineers

Figure 1

BASE-USGS Oakland East 7.5 minute quadrangle topographic map, dated 1980, scale 1:24,000.



APPENDIX A

California EPA Certified Laboratory Report of Groundwater Samples



PRIORITY ENVIRONMENTAL LABS

Precision Environmental Analytical Laboratory

July 29, 1993

PEL # 9307075

AQUA SCIENCE ENGINEERS, INC.

Attn: David Allen

Re: Three water samples for pH, Gasoline/BTEX, Diesel, Oil & Grease, and

Conductivity analyses.

Project name: Goodman

Project location: 2501 Santa Clara. - Alameda, CA.

Project number: 2596

Date sampled: Jul 27, 1993
Date extracted: Jul 28, 1993

Date submitted: Jul 28, 1993 Date analyzed: Jul 28, 1993

RESULTS:

SAMPLE	рН Ga	soline	Diesel	Benzene					Conductivity
I.D.	(ug/L)	(ug/L)	(ug/L)			Xylenes (ug/L)	(mg/L)	(us)
							<u> </u>	,	
MW-1	6.6	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	530
MW-2A	6.7	N.D.		N.D.	N.D.	N.D.	N.D.		580
MW-3	6.7	7200		3.9	4.7	6.2	19		630
Blank	7.0	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	0
Spiked Recover	у	82.4%	97.6%	80.5	83.9%	92.19	\$ 95.6%		
Duplica Recove	_	ked							
110000		89.8%	91.2%	87.8	8 93.2%	96.58	104.1%		
Detecti	on								
limit		50	50	0.5	0.5	0.5	0.5	0.5	10
Method	of	5030	/ 3510	/				552	0
Analysi			•	•	602	602	602	C &	F 120.1

David Duong Laboratory Director

1764 Houret Court Milpitas, CA. 95035

Tel: 408-946-9636 Fax: 408-946-9663

Aqua Science Engineers, Inc. 2411 Old Crow Canyon Road, #4, San Ramon, CA 94583 (510) 820-9391 - FAX (510) 837-4853

Chai

INV # 23832

ody

DATE 7/27/13 PAGE 1 OF 1

			رجمي سات																		_	
SAMPLERS (S					HONE		PRO.	JECT N	NAME	<u> </u>	Obre	ب.					1	4O·	<u> 25</u>	16		
(1).al		•	ı	82	0-939	,											, 4					
ANA	LYS	IS R	EQUE	EST					29		52	(E)			•							
SPECIAL INS	**				1	80 20		8	100 E	8	ACT DB	M J		5	ł			خ ا				ł
				:	55 (015)	78/B7	015)	20)	3 3	40)	10)	38 34.50	(2)	- (OO	310)	310	,	COND				
			,		30/8	30/8	33EL 10/8	2/80	J/80	8 4 8 2	75/82	REAS	TAL 8	2 (C	17/11	AM W	E E E	+				
SAMPLE ID.	DATE	TIME	MATRIX	NO. OF	TPH-GASOLINE (EPA S030/8015)	TPH-GASOLINE/BIEX (EPA 5030/8015-8020)	TPH- DIESEL (EPA 3510/8015)	PURGABI	PURGABLE HALOCARBONS (EPA 601/8010)	VOLATE	BASE/NUETRALS, (EPA 625/8270)	OIL & GREASE (EPA 5520 E&F OF B&F)	LUFT ME	TITLE 22 (CAM 17) (EPA 6010+7000)	TCLP (EPA 1311/1310)	STLC- C	REACTIVITY CORROSIVITY I CHI TABILLITY	₩d				
MW-1	7/27	B:00	H, O	5		X	X					X						Х				
MW-24		15:20		3		X												Х				
nw-3	V	15:45	V	3		X												X				
·	ļ					<u> </u>		<u> </u>														_
	<u> </u>			<u> </u>		<u> </u>	ļ <u>.</u>	ļ						ļ	<u> </u>	ļ		ļ			igsquare	_
		<u> </u>]	 	<u> </u>	<u> </u>	<u> </u>		<u> </u>	ļ		<u> </u>	<u> </u>	-	<u> </u>	ļ			 		_
			ļ <u></u>	<u> </u>			<u> </u>	 		<u> </u>			ļ	 		 			 			Ė
	 		ļ	 		 -		 -		 				 	 	-			 	 		_
! 			<u> </u>	<u> </u>		 		-							 	 	 		 			<u> </u>
		<u> </u>				 		 		-				-		<u> </u>				\vdash	├─┥	-
RELINQUISHE		8:05	RECE	VED BY:	<u>. </u>	<u> </u>	REI	LINQUI	ISHED I	BY:	<u> </u>			BYLA				MENTS	L }:		<u>1</u>	
	ignature) (time) (signature)		ure)	re) (time)		(sig	nature)			(time) (216 1	(signature) (time			(time	6)						
DALLER	<u></u> _ر	7/28/	47								_	DA	ViD :	DUGN	t_ 7	128/9	3					
(printed name)		(dat	e) (printe	d name)		(date)	(pri	nted na	me)		(date) (prir				(date						
Company- 🛕	SE, l	ıc.	Comp	any-			Company-				Company- PEC											

APPENDIX B

Well Sampling Field Logs



WELL SAMPLING FIELD LOG

Aqua Science Engineers, Inc. San Ramon, CA 94583

Project Name: <u>Goodner Place II</u>
Project Address: 25-1 Santa Clara Ave. Manche
Job # 1592 Date of sampling: 7-27. 93 Completed by: bA/RK
Completed by: bA/RK
Well Number / Designation:
Top of casing elevation: 23.96'
Total depth of well casing: 23.69 Well diameter: 2"
Depth to water (before sampling): 6.51'
Thickness of floating product if any:
Depth of well casing in water:
Reg'd volume of groundwater to be purged before sampling:
Approximate volume of groundwater purged: 15 5al.
Type of seal at grade: Postland
Type of cap on the casing: Lecking, expandable
Is the seal water tight? Yes Is the cap water tight? Yes
Number of samples (containers) collected
Did 40 ml VOA vials have headspace:
Were sample containers chilled after sampling & for delivery? 423
Are Chain of Custody documents accompanying the samples: 425
Sample temperature: 18.8°C
Sample pH: 6.6 Test method: 1045 Conductivity: 530 Test method: 120.1
Conductivity: 532 lest method: (Lo.)
Physical description of water during initial bailing period:
Physical description of water sample:
Type of analysis requested: TPH - 6
1pH - p
BTEX
0+G-
8010 pH cond.
Type of bailer/sampling equipment used: Electric PUC Pump +
Equipment decontamination procedures: TSP + How was H, How Revsie (24)
Equipment decontainmation procedures. 111 4 1150 With 1 170 EN 12 C
Disposition of bailed water volume:
Drymmed en site.



WELL SAMPLING FIELD LOG

Aqua Science Engineers, Inc. San Ramon, CA 94583

Project Name: Goodman PHASE TT
Project Address: 2501 Santa Clara Are. Mameda
Job # 2596 Date of sampling: 7.27.43
Completed by: DA /RA
Well Number / Designation: MW-2-A
Top of casing elevation: $73.87'$
Total depth of well casing: 21.96' Well diameter: 2"
Depth to water (before sampling): 6.18'
Thickness of floating product if any:
Depth of well casing in water: 15.78
Req'd volume of groundwater to be purged before sampling: 13.5 5.6
Approximate volume of groundwater purged: 15 5cl.
Type of seal at grade: Portland
Type of cap on the casing: Locking, expandable
Is the seal water tight? Yes Is the cap water tight? Yes
Number of samples (containers) collected
Did 40 ml VOA vials have headspace:
Were sample containers chilled after sampling & for delivery?
Are Chain of Custody documents accompanying the samples:
Sample temperature: 18.9°C
Sample pH: 6:1 Test method: 7043
Conductivity: 580 Test method: 1201
Physical description of water during initial bailing period:
Clear
Physical description of water sample:
Type of analysis requested: TPH-C
Type of analysis requested: TPH-C BIE
- H
2 H Enduksity
Type of bailer/sampling equipment used: <u>Puc electric Pump</u> and
Equipment decontamination procedures: TSf +H20 World, 1420 121-5 (22)
Disposition of bailed water volume:
Drummed in sik-



WELL SAMPLING FIELD LOG

Aqua Science Engineers, Inc. San Ramon, CA 94583

Project Name: Goodman PHATE E
Project Address: 2501 SANTA CLARA AVE. ALANKOA
Job # 2596 Date of sampling: 7.27.93
Completed by: DA/RK
Well Number / Designation:
Top of casing elevation: 25.00'
Total depth of well casing: 23.3e' Well diameter: 2"
Depth to water (before sampling): 7.76
Thickness of floating product if any:
Depth of well casing in water:
Req'd volume of groundwater to be purged before sampling: (3.2 9.4)
Approximate volume of groundwater purged: 15 god.
Type of seal at grade: Postiand
Type of cap on the casing: <u>uching</u> expandable
Is the seal water tight? <u>Yes</u> Is the cap water tight? <u>Yes</u>
Number of samples (containers) collected
Did 40 ml VOA vials have headspace: No
Were sample containers chilled after sampling & for delivery? Yes
Are Chain of Custody documents accompanying the samples:
Sample temperature: 18.8°C
Sample pH: 6.7 Test method: 9043
Sample pH: 6.7 Test method: 9093 Conductivity: 430 Test method: 12011
Physical description of water during initial bailing period:
Physical description of water sample: Clear
Type of analysis requested: TPH-G
B True
B True
B True
ptt co-lech vity
Type of hailer/sampling equipment used: Cleetie Puc Pump and
p H co-lack vity
Type of hailer/sampling equipment used: Cleetie Puc Pump and