AGENCY

DAVID J. KEARS, Agency Director



ARNOLD PERKINS, DIRECTOR RAFAT A. SHAHID, DEPUTY DIRECTOR

Alameda County CC4580 Environmental Health Services 1131 Harbor Bay Pkwy., #250 Alameda CA 94502-6577 (510)567-6700 FAX(510)337-9335

REMEDIAL ACTION COMPLETION CERTIFICATION

StID 1939 - 11976 Dublin Blvd, Dublin, CA 94568

February 1, 1996

Mr. Adadu Yemane Unocal P.O. Box 5155 San Ramon, CA 94583 Mr. Steve Thomas Main Street Associates 3100 Oak Road, #360 Walnut Creek, CA 94596

Dear Messrs. Yemane and Thomas:

This letter confirms the completion of site investigation and remedial action for the six former underground storage tanks (2-10K, 2-12K gasoline and 1-280, and 1-510 gallon waste oil tanks) removed from the above site on June 13, 1990 and May 21, 1992. Enclosed is the Case Closure Summary for the referenced site for your records.

Based upon the available information, including the current land use, and with the provision that the information provided to this agency was accurate and representative of site conditions, no further action related to the underground tank release is required.

This notice is issued pursuant to a regulation contained in Title 23, Division 3, Chapter 16, Section 2721(e) of the California Code of Regulations. Please contact Ms. Eva Chu at (510) 567-6700 if you have any questions regarding this matter.

Very truly yours,


Jun Makishima, Interim Director

cc: Chief, Division of Environmental Protection

Kevin Graves, RWQCB

Mike Harper, SWRCB (with attachment)

files (unocald2.5)



CASE CLOSURE SUMMARY Leaking Underground Fuel Storage Tank Program

I. AGENCY INFORMATION Date: November 17, 1995

Agency name: Alameda County-HazMat Address: 1131 Harbor Bay Pkwy

City/State/Zip: Alameda, CA 94502 Phone: (510) 567-6700

Responsible staff person: Eva Chu Title: Hazardous Materials Spec.

II. CASE INFORMATION

Site facility name: Unocal SS #5901

Site facility address: 11976 Dublin Blvd, Dublin 94568

Local Case No./LOP Case No.: 1939 RB LUSTIS Case No: N/A

URF filing date: 6/21/90 SWEEPS No: N/A

Responsible Parties: Addresses: Phone Numbers:

P.O Box 5115, San Ramon 94583 Unocal

Attn. Adadu Yemane

Tank No:	Size in gal.:	Contents:	<pre>Closed in-place or removed?:</pre>	<u>Date:</u>
1	10,000	Gasoline	Removed	6/13/90
2	10,000	Gasoline	Removed	6/13/90
3	280	Waste Oil	Removed	6/13/90
4	12,000	Gasoline	Removed	5/21/92
5	12,000	Gasoline	Removed	5/21/92
6	520	Waste Oil	Removed	5/21/92

RELEASE AND SITE CHARACTERIZATION INFORMATION III.

Cause and type of release: Leaking USTs and product lines

Site characterization complete? YES

Date approved by oversight agency: 3/8/95

Monitoring Wells installed? Yes Number: 6

Proper screened interval? Yes

Highest GW depth below ground surface: 19.21' Lowest depth: 22.35' (MW-6)

Flow direction: N, NE

Most sensitive current use: Commercial

Are drinking water wells affected? No Aquifer name: Dublin Sub-basin Is surface water affected? No Nearest affected SW name: NA Off-site beneficial use impacts (addresses/locations): None

Report(s) on file? YES Where is report(s) filed? Alameda County 1131 Harbor Bay Pkwy Alameda, CA 94502

Treatment and Disposal of Affected Material:

<u>Material</u>	Amount (include units)	Action (Treatment or Disposal w/destination)	<u>Date</u> L
Tank & Piping	3 USTs Cleaned,	Erickson, in Richmond recertified by Erickson	6/13/90 5/21/92
Soil	60 cy	aidlaw, in Buttonwillow " asco Rd L.F. in Livermore	6-7/1990 8-9/1992 8/1992
Groundwater	30,000 gallon Gi	bson Oil, in Bakersfield	6-7/1990

Maximum Documented Contam	inant Cor	ncentrations	- -	Before a	nd After	Cleanup
Contaminant	Soil	(ppm)		Water	(ppb)	
	<u>Before</u>	<u> After</u>		<u>Before</u> 1	<u>After</u>	
TPH (Gas)	5,700	120		2,300	24 0	
TPH (Diesel)	120	120		MD	ND	
Benzene	3.1	.74		3.1	5.1	
Toluene	41	.14		.88	2.6	
Ethylbenzene	110	.13		.39	ND	
Xylenes	640	.17		250	1.8	
, 20		•		_		
Oil & Grease	3,500	ND		ND	ND	
OII & OICABC	5,500	3.12		5.2	-1-	
Heavy metals Cd, Cr, Pb,	Ni Zna	10% ያቸኒሮ		NA	NA	
neavy metals cu, cl, fb,	MI, ZII <	TON DIDO		2422	1411	
Other 8010 constituents	note2	note4		ND	ND	
Other Solo Constituents	notez	noces		ИД	±417	
0070	2			ND	NA	
8270 constituents	note3	note4		MTA	TAY	

NOTE:

- "Grab" groundwater from fuel tank pit.
- 210 ppb 1,2 dichlorobenzene
- 19 ppb PCE
- 670 ppb bis(2-ethylhexyl)phthalate
 - 5,800 ppb 2-methylnaphthalene 4,100 ppb naphthalene
 - 240 ppb phenanthrene
 - 120 ppb pyrene
- All 8010 and 8270 constituents ND after overexcavation, except 19 ppb PCE.

IV. CLOSURE

Does completed corrective action protect existing beneficial uses per the Regional Board Basin Plan? Undetermine Does completed corrective action protect potential beneficial uses per the Regional Board Basin Plan? Undetermine Does corrective action protect public health for current land use? YES

Site management requirements: None

Should corrective action be reviewed if land use changes? YES

Monitoring wells Decommissioned: Yes

Number Decommissioned: 5 Number Retained: 1

List enforcement actions taken: None
List enforcement actions rescinded: NA

V. LOCAL AGENCY REPRESENTATIVE DATA

Name: Eva Chu

Title: Haz Mat Specialist

Signature: 000

Date: 1/20/95

Reviewed by

Name: Juliet Shin

Title: Sr. Haz Mat Specialist

Signature: Julia Sen

Date: ///0/95

Name: Scott Seery

Title: Sr. Haz Mat Specialist

Signature:

Date: 11-20-95

VI. RWQCB NOTIFICATION

Date Submitted to RB: 11/22/95

RB Response: Affirmed

RWQCB Staff Name / /Kevin Graves

Title: AWRCE

Signature:

Date: /1/2 >/95

VII. ADDITIONAL COMMENTS, DATA, ETC.

Two generations of underground storage tanks were removed: one set in June 1990, the other, May 1992. The site is currently a Petco pet food store.

Fuel, waste oil USTs, and product lines removed in June 1990

On June 12, 1990 two 10,000 gallon gasoline (in a common pit) and one 280 gallon waste oil tanks (in another pit) were removed. Holes were noted in all three tanks. Groundwater was present at a depth of 7' in the UST excavations, necessitating the collection of both sidewall and water samples. (See Table 9)

Soil collected from the fuel UST pit sidewalls (SW1 thru SW6) exhibited up to 5,700 ppm TPH-G, and 2.1, 41, 110, and 640 ppm BTEX, respectively. Soil samples were also collected from the product pipe trenches (P1 thru P4) at 6' bgs, exhibiting insignificant concentrations of TPH-G and BTEX. The former fuel pit and product line trenches were subsequently overexcavated.

Confirmatory soil samples (SW1(6.5) and SW2(6.5), SW5(2.5), and SW6(3)) exhibited up to 32 ppm TPH-G, and 0.027, 0.14, 0.13, 0.17 ppm BTEX, respectively. This pit was backfilled with clean soil. A soil sample (WO1) from the bottom of the waste oil pit exhibited up to 1,500 ppm TOG, 120 ppm TPH-D, and unremarkable levels of TPH-G and BTEX. All EPA 8010 constituents were below the detection limit except for 0.21 ppm 1,2-dichlorobenzene. A soil sample (SWA) from the south wall of the waste oil pit exhibited up to 3,500 ppm TOG, the only analysis performed on this sample. (See Fig 2, 3, and Table 8.)

After removing 25,000 gallons of groundwater from the former fuel tank pit, a "grab" water sample (W1) was collected and analyzed, exhibiting 2,300 ppb TPH-G, and 3.1, 0.88, 0.39, and 250 ppb BTEX, respectively. (See Table 9.)

On June 26, 1990 four sidewall soil samples (SW11 thru SW14) were collected from the new UST pit, located to the west of the former pump islands. Approximately 10,000 gallons of groundwater were pumped from this pit and a water sample (W2) collected. No significant levels of TPH-G or BTEX were detected in the soil or water samples. Two 12,000 gallon double-walled fuel USTs were installed in this pit. (See Fig 4, 6, and Table 8, 9.)

The former waste oil pit was also overexcavated laterally and to an approximate depth of 8'. Confirmatory soil samples (SW-B thru SW-H) were collected from three walls at 6 to 6.3' bgs. The south wall could not be excavated at this time due to the proximity of the service station building. Approximately 5,000 gallons of water was pumped from the waste oil pit. A water sample (W3) was collected. Soil and water samples did not exhibit any remarkable levels of petroleum hydrocarbons. A new double-walled waste oil tank was installed in this pit. (See Fig 5, Table 10, 11.)

In November 1990 four groundwater monitoring wells (MW-1 thru MW-4) were installed. Groundwater was encountered at depths ranging from 5.4 to 9.5 feet below grade, except MW-3, which did not encounter groundwater until 15.2' bgs. The four wells were sampled on six consecutive quarters (Nov 90 thru Apr 92) without detecting petroleum hydrocarbons, or EPA method 8100 and 8010 constituents (except for periodic TPH-G in well MW-3). (See Table 4.)

Fuel, Waste Oil USTs, New and Abandoned Piping Removed in May 1992

In May 1992 the three newly-installed fuel and waste oil USTs were removed. Two hydraulic lifts and an oil/water separator, located within the former building were also removed, and the entire site leveled. Contaminated soil beneath the building (including the release associated with the former waste oil tank, hydraulic lifts, and oil/water separator) was overexcavated. Verification soil samples did not reveal any petroleum hydrocarbon constituents or semi-volatile compounds. (See Fig 6, Table 12, 13, 14.)

During the final round of UST removals and site demolition, several generations of abandoned product piping were discovered, east of the former building. All product piping was removed and soil samples collected (PT-1 thru PT-5). Up to 940 ppm TPH-G, and 0.81, 12, and 100 ppm TEX were detected at PT-2 at 5' depth. The product line trenches were overexcavated (over an area of approximately 19 X 15 X 16.5' bgs). Four confirmatory sidewalls soil samples (PT(SW1) thru PT(SW4)) at 12' depth, and a pit bottom sample (PT(16.5)) at 16.5' depth were collected. Petroleum hydrocarbons were not detected in the soil samples. (See Fig 6, Table 14.)

In August 1992, for site divestment purposes, 11 exploratory borings (EB1 thru EB11) were drilled at the site to collect soil and "grab" groundwater samples. Groundwater was encountered at depths ranging from 10.5 to 35.5' bgs. Low to non-detectable levels of TPH-G, TPH-D, BTEX, TOG, TPH-MO, and VOCs were identified in soil and groundwater samples. (See Fig 1, and Table 6, 7.)

A total of six monitoring wells were eventually installed at the site between 1990 and 1994. Well MW-2 was damaged and subsequently destroyed during overexcavation of the abandoned piping lines. Wells MW-1, MW-3, -4, and -5 were destroyed in April 1995. Calculated groundwater flow on the western portion of the site has been to the north-northeast, with a flat gradient (.004). The site is also reportedly near an alleged mapped trace of the Calaveras Fault. Such has been suggested by the consultant by the presence of comparative changes in the color and texture of encountered soil materials, and reported difference in groundwater elevation observed between the eastern and western portions of the site. It has been theorized that movement along the perceived fault trace appears to have created "gouge" zones, apparent barriers to ground water flow. Clearly, groundwater elevations, both those at which water was first observed during boring advancement and stabilized levels in completed wells (MW-2, 3, 5, and 6), are erratic near the eastern margins of the site. The presence of such a fault splay could account for these phenomena. (See Fig 8-12.)


In September 1995, three additional exploratory borings (EB11A, EB12, and EB13) were emplaced just north, east, and south of well MW-6 (which continues to exhibit low levels of TPH-G and benzene). Groundwater was encountered at depths ranging from 24 to 27' bgs. Soil samples were collected at 5' intervals and analyzed for TPH-G and BTEX. A maximum of 4.9 ppm TPH-G and only trace levels of TEX were detected. Benzene was not detected. "Grab" groundwater from EB11A exhibited up to 110 ppb TPH-G, and 4.0 and 1.2 ppb benzene and toluene, respectively. (See Fig 1, Table 1, 2.)


The wells have been sampled quarterly from November 1990 to December 1994. TPH-G and BTEX have not been detected in wells MW-1, 2, 3, 4, or 5, except for trace concentrations of TPH-G on two occasions. The maximum concentrations detected in well MW-6, located east of the perceived fault splay and adjacent to a fairly deep pocket of soil contamination associated with a long-abandoned dispenser island and associated piping, are 790 ppb TPH-G and 8.1 ppb benzene. The most recent (12/94) concentrations of TPH-G and benzene in sampled groundwater are 240 and 5.1 ppb, respectively.


The majority of the hydrocarbon-impacted soil was removed during overexcavation activities. Approximately 30,000 gallons of water was pumped from the original fuel and the waste oil tank pits. The extent of soil and groundwater contamination have been delineated. Groundwater does not appear to be significantly impacted by the fuel release at this site. Continued groundwater sampling is not warranted.


unocald2.3


. . . .





























TABLE 1
SUMMARY OF LABORATORY ANALYSES
SOIL

	Sample	TPH as			Ethyl-	
<u>Date</u>	Number G	asoline	<u>Benzene</u>	<u>Toluene</u>	benzene	<u>Xylenes</u>
9/25/95		1.9*	ND	· ND	ND	ND
		1.7*	ND	` ND	ND	ND
	EB11A(15)	2.5*	ND	ND	ND	ND
	EB11A(20)	4.4	ND	ND	0.0083	0.031
	EB11A(22.5)	4.9	ND	ND	0.0087	0.043
	EB11A(25.5)	1.7*	ND	ND	ND	ND
	EB12(5)	2.2*	ND	ND	ND	ND
	EB12(10)	1.2*	ND	ND	ND	ND
	EB12(15)	ND	ND	ND	ND	ND
	EB12(20)	ND	ND	ND	ND	ND
	EB12(22.5)	ND	ND	ND	ND	ND
	EB13(5)	ND	ND	ND	ND	ND
	EB13(10)	1.4*	ND	ND	ND	0.024
	EB13(15)	1.6*	ND	ND	ND	0.023
	EB13(20)	1.4*	ND	0.0051	ND	0.027
	EB13(21)	1.9*	ND	ND	ИD	0.025

NOTE: The soil samples were collected at the depths below grade indicated in the () of the respective sample number.

ND = Non-detectable.

^{*} Sequoia Analytical Laboratory reported that the hydrocarbons detected did not appear to be gasoline.

TABLE 2
SUMMARY OF LABORATORY ANALYSES
WATER

<u>Date</u>	Sample <u>Number</u>	TPH as <u>Gasoline</u>	Benzene	<u>Toluene</u>	Ethyl- <u>benzene</u>	Xylenes
9/25/95	EB11A	110*	4.0	1.2	ND	ND
	EB12	ND	ND	ND	ND	ND
	EB13	ND	ND	ИД	ND	ND

* Sequoia Analytical Laboratory reported that the hydrocarbons detected did not appear to be gasoline.

ND = Non-detectable.

Results are in micrograms per liter ($\mu g/L$), unless otherwise indicated.

TABLE 3
SUMMARY OF MONITORING DATA

Well #	Ground Water Elevation(feet)	Depth to Water (feet) •	Total Well Depth (feet)♦	Product Thickness (feet)	<u>Sheen</u>	Water Purged (gallons)
	(Mon	itored and s	sampled on Dec	cember 1, 199	4)	
MW1*	362.13	4.67	19.75	0		0
* EWM	352.13	14.73	19.67	0		0
MW4*	362.48	5.10	19.70	0		0
MW5	351.55	14.00	24.97	0	ИО	7.5
MW6	345.04	20.64	25.13	0	No	3.5
	(Moni	tored and S	ampled on Sep	tember 1, 19	94)	
MW1*	361.80	5.00	19.73	0		0
* EWM	351.83	15.03	19.66	0		0
MW4*	362.10	5.48	19.72	0		0
MW5	350.73	14.82	24.97	0	No	7
MW6	343.33	22.35	25.12	0	No	2
		•. •				
	(M	onitored and	l Sampled on	June 3, 1994)		
MW1*	362.01	4.79	N M	0		0
MW3*	351.94	14.92	NM	0		0
MW4 *	362.35	5.23	NM	0		0
MW5	351.25	14.30	25.02	0	No	5.5
MM6	344.34	21.34	25.12	0	No	2
			v			
	(Mo	nitored and	Sampled on M	March 3, 1994)	
MW1*	362.05	4.75	19.81	and any	0	
* EWM	352.05	14.81	19.71		0	
MW4*	362.42	5.16	19.74		0	
MW5	351.64	13.91	25.03	No	8	
MW6	346.47	19.21	25.11	ИО	4.5	

TABLE 3 (Continued)

SUMMARY OF MONITORING DATA

1	Well Casing Elevation
Well #	(feet)**
MW1	366.80
MW3	366.86
MW4	367.58
MW5	365.55
MW6	365.68

- ♦ The depth to water level and total well depth measurements were taken from the top of the well casings.
- * Monitored only.
- ** The elevations of the top of the well casings have been surveyed relative to Mean Sea Level (MSL), per the National Geodetic Survey disk stamped "I-1257, reset 1975" (elevation = 439.93 feet MSL).
- -- Sheen determination was not performed.

NM = Not measured.

- NOTE: 1. Wells MW1 and MW4, wells MW3 and MW5, and well MW6 are considered to be located in three separate hydrologic regimes.
 - Monitoring and sampling data are supplied by MPDS Services, Inc. of Concord, California

TABLE 4
SUMMARY OF LABORATORY ANALYSES
WATER

<u>Date</u>	Well_#	TPH as <u>Gasoline</u>	<u>Benzene</u>	<u>Toluene</u>	<u>Ethylbenzene</u>	Xylenes
12/01/94	MW5 MW6	ND 240	ND 5.1	ND 2.6	ND ND	1.3 1.8
9/01/94	MW5 MW6	ND 490	ND 8.1	1.6 2.9	ND ND	2.1 1.9
6/03/94	MW5 MW6	ND ND	ND ND	ND ND	ND ND	ND ND
3/03/94	MW5 MW6	ND 150	ND 2.4	0.84 2.8	ND ND	0.60
12/09/93	MW1 + MW3 MW5 MW6	 ND ND 790	 ND ND 0.64	ND ND 1.0	ND ND ND	ND ND ND
10/09/93	MW5 MW6	ND 480	ND 1.8	ND 0.63	ND 0.81	ND ND
9/16/93	MW1↓ MW3	ND	ND	nd	ND	ND
6/18/93	MW1♦ MW3	ND	ND	ND	ND	ND
4/03/92	MW1* MW2 MW3 MW4	ND ND ND ND	ND ND ND	ND ND ND ND	ND ND ND ND	ND ND ND
1/02/92	MW1.* MW2 MW3.** MW4	ND ND 38 ND	ND ND ND ND	ND ND ND ND	ND ND ND ND	ND ND ND
10/03/91	MW1* MW2 MW3 MW4	ND ND 32 ND	ND ND ND ND	ND ND ND ND	ND ND ND ND	ND ND ND ND

TABLE 4 (Continued)

SUMMARY OF LABORATORY ANALYSES WATER

<u>Date</u>	Well #	TPH as <u>Gasoline</u>	<u>Benzene</u>	<u>Toluene</u>	<u>Ethylbenzene</u>	Xylenes
7/02/91	MW1*	ND	ND	ND	ND	ND
	MW2	ND	ND	ND	ND	ND
	MW3	ND	ND	ND	ND	ND
	MW4	ND	ND	ND	ND	ND
4/01/91	MW1*	ND	ND	ND	ND	ND
	MW2	ND	ND	ND	ND	ND
	KWM3	ND	ND	ND	ND	ND
	MW4	ND	ND	ND	ND	ND
11/16/90	MW1*	ND	ND	ND	ND	ND
	MW2	ND	ND	ND	ND	ND
	МWЗ	ND	ND	ND	ND	ND
	MW4	ND	ИD	ND	ND	ND

- ♦ All EPA method 8100 constituents (polynuclear aromatic hydrocarbons) were non-detectable.
- * TPH as diesel, TOG, and EPA method 8010 constituents were all non-detectable for MW1.
- ** All EPA method 8010 constituents were non-detectable.

ND = Non-detectable.

-- Indicates analysis was not performed.

Results are in micrograms per liter ($\mu g/L$), unless otherwise indicated.

NOTE: Laboratory analyses data subsequent to October 9, 1993, were provided by MPDS Services, Inc., of Concord, California.

TABLE 5
SUMMARY OF LABORATORY ANALYSES
SOIL

<u>Date</u>	Sample <u>Number</u>	Depth (feet)	TPH as <u>Diesel</u>	TPH as <u>Gasoline</u>	<u>Benzene</u>	<u>Toluene</u>	Ethyl- <u>benzene</u>	Xylenes
11/06/90 & 11/07/90	MW1(5)* MW1(8)	5.0 8.0	ND 	ИD	ND ND	ND ND	ND ND	ND ND
11/01/30	MW2(5)	5.0		ND	ИD	ND	ND	ND
	MW2 (7.5)	7.5		ИD	ИD	ИD	ИD	ND
	MW2 (9)	9.0		ND	ND	ND	ИD	ND
	MW3(5)	5.0	<u></u>	ND	ND	ND	ND	ND
	MW3 (10)	10.0		ND	ND	ND	ND	ИД
	MW3 (15)	15.0		ND	ИD	ИD	ND	ND
	MW3 (5)	5.0	<u></u>	ND	ND	ND	ND	ND
	MW3(10)	10.0		ND	ND	ND	ND	ND
	MW3 (15)	15.0		ND	ИD	ИD	ИD	ND
	MW4 (5)	5.0		ND	ND	ND	ND	ND
10/04/93	MW5 (5)	5.0		ИД	ИО	ИD	ND	ND
	MW5(9.5)	9.5		ND	ND	ND	ND	ND
	MW5(14.5)	14.5		ND	ИD	ND	ИD	ND
	MW6(5)	5.0		ND	ND	ND	ND	ND
	MW6(9.5)	9.5		ND	ND	ND	ND	ND
	MW6 (15)	15.0		ND	ND	ND	ND	ND
	MW6(19.5)	19.5		ND	ND	ND	ND	ND
	MW6(24)	24.0		120	0.74	0.072	0.036	0.15

^{*} TOG and EPA method 8010 constituents were non-detectable.

ND = Non-detectable.

⁻⁻ Indicates analysis was not performed.

TABLE 6
SUMMARY OF LABORATORY ANALYSES
SOIL

(Collected on August 24 & 25, 1992)

Sample <u>Number</u>	Depth <u>(feet)</u>	TPH as <u>Diesel</u>	TPH as <u>Gasoline</u>	<u>Benzene</u>	Toluene	Ethyl- <u>benzene</u>	Xylenes	TOG
EB1(5)	5.0		ND	ND	ND	ND	ND	
EB1(8)	8.0		ND	ND	ND	ND	ND	
EB1(10)	10.0		2.3	ND	ND	0.0057	0.11	
EB1(12.5)	12.5		ND	ND	ND	ND	ND	
	,				-			
EB2(5)	5.0		ND	ND	ND	ND	ND	
EB2(10.5)	10.5		ND	ND	ND	ND	ND	
,				<u>-</u>		, -		
EB3(5)*	5.0	ND	ND	ND	ND	ND	ND	ND
EB3(10)*	10.0	ND	ИД	ИD	ND	ИD	ND	ND
EB3(13)*	13.0	ND	ND	ND	ND	ND	ND	ND
EB4(5)*+	5.0	****	ND	ND	ND	ND	ND	ND
EB4(10)*+	10.0		ND	ND	ND	ND	ND	ND
, ,								
EB5(5)*+	5.0		ND	ND	ND	ND	ND	ND
EB5(10.5)*-	+ 10.5		ND	ND	ND	ИD	ИD	ИD
•								
EB6(5.5)*	5.5	ND	ND	ND	ND	ND	ND	ND
EB6(10)*	10.0	ND	ND	ND	ND	ND	ND	ND
EB7(5)	5.0		ND	ND	ND	ND	ND	
EB7(10)	10.0		ND	ND	ND	ND	ND	
,								
EB8(5)	5.0		ND `	ND	ND	ND	ND	
EB8(10)	10.0		ND	ND	ND	ND	ND	
EB8 (13)	13.0		ND	ND	ND	ND	ND	
EB8 (15.5)	15.5		ND	ND	ND	ND	ND	
EB8(17.0)	17.0		ND	ND	ND	ND	ND	
, ,								
EB9(5)	5.0		ND	ND	ND	ND	ND	
EB9 (10)	10.0		ND	ИД	ND	ИD	ND	
EB9 (15)	15.0		ND	ND	ND	ND	0.010	
EB9(17.5)	17.5		2.6	ND	0.010	0.015	0.018	
EB9 (20)	20.0		ND	ND	ND	ND	ND	
EB9 (25)	25.0		10	0.028	0.032	0.41	2.1	
EB9 (30)	30.0		ND	ND	ND	ND	ND	
EB9 (35)	35.0		ND	ND	ND	ND	ND	

TABLE 6 (Continued)

SUMMARY OF LABORATORY ANALYSES SOIL

(Collected on August 24 & 25, 1992)

Sample <u>Number</u>	Depth (feet)	TPH as <u>Diesel</u>	TPH as <u>Gasoline</u>	<u>Benzene</u>	<u>Toluene</u>	Ethyl- <u>benzene</u>	Xylenes	TOG
EB10(5)	5.0		ND	ND	ND	ND	ND	
EB10(10)	10.0		ND	ND	ND	ND	ND	
EB10(15.5)	15.5		ND	ИD	ND	ND	ND	
EB11(5.5)	5.5		ND	ND	ND	ND	ND	
EB11(10)	10.0		ND	ND	ND	ND	ND	
EB11(15.5)	15.5		ND	ND	ND	ND	ND	

- * All EPA method 8010 constituents were non-detectable, except in samples EB3(13), EB5(10.5), and EB6(10), where tetrachloroethene was detected at a concentration of 11 μ g/kg in each case. Tetrachloroethene was also detected in sample EB6(5.5) at a concentration of 19 μ g/kg.
- + TPH as Hydraulic Fluid was non-detectable.
- ND = Non-detectable.
- -- Indicates analysis was not performed.

KEI-P90-0606.R15 October 24, 1995

TABLE 7
SUMMARY OF LABORATORY ANALYSES
WATER

(Collected on August 24 & 25, 1992)

Sample Number	TPH as Hydraulic Fluid	TPH as Diesel	TPH as Gasoline	Benzene	Toluene	Ethyl- benzene	Xvlenes	TOG
EB1			ND	ND	ND	ND	ND	
EB2			ND	ND	ND	ND	ND	
EB3*		ND	ND	ND	ND	ND	ND	ND
EB4*	510		ND	ND	ND	ИД	ND	ND
EB5*	ND		ND	ND	ND	ND	ND	ND
EB6*		500**	ND	ND	ND	ND	ND	ND
EB7	**· -		ND	ND	ND	ND	ND	
EB8			ИD	ND	ND	ND	ND	
EB9			840***	0.70	ND	ND	98	
EB10			ND	ND	ND	ND	ND	
EB11			ND	ND	ND	ИD	ND	

-- Indicates analysis was not performed.

ND = Non-detectable.

- * All EPA method 8010 constituents were non-detectable.
- ** Sequoia Analytical Laboratory reported that the hydrocarbons detected appeared to be a diesel and non-diesel mixture.
- *** Sequoia Analytical Laboratory reported that the hydrocarbons detected did not appear to be gasoline.

NOTE: Water samples were collected during drilling. The results of the analyses may not be representative of formation water, and should be used for comparative informational purposes only.

Results are in micrograms per liter ($\mu g/L$), unless otherwise indicated.

TABLE 8
SUMMARY OF LABORATORY ANALYSES
SOIL

(Collected on June 13, 15, 20 & 26, 1990)

			Depth	TPH as	TPH as			Ethyl-	
		<u>Sample</u>	(feet)	<u>Diesel</u>	<u>Gasoline</u>	<u>Benzene</u>	<u>Toluene</u>	<u>benzene</u>	<u>Xylenes</u>
н	/	SW1	6.0		5,700	2.1	41	110	640
.18.	(SW1(3)	6.0		2,200	1.8	6.3	30	76
.5	-)	SW1 (6.5)	6.0		32	0.020	0.14	0.13	0.17
المالية المالية	- 2	SW2	6.0		1,500	0.35	0.57	8.0	56
1	_ /	SW2(3)	6.0		360	ND	1.0	3.0	2.0
)	SW2 (6.5)	6.5		6.8	0.020	0.052	0.029	0.063
		SW3	6.0		ND	ND	ND	ND	ND
	/	SW4	6.0		8.0	0.019	0.088	0.0071	0.16
/	/	SW5	6.5		340	0.80	0.26	2.5	3.6
1		SW5 (2.5)	6.0		11	0.027	0.054	0.070	0.12
1		SW6	6.5		120	ND	0.21	0.19	0.14
		SW6 (3)	6.0		1.2	0.0084	0.012	0.012	0.021
	1	P1 P2 P3 P4	6.0		2.5	0.099	0.079	ND	0.034
b, bonc	, 5	P2	6.0		37	0.78	0.14	0.43	3.8
, ,) P3	6.0		8.5	0.028	0.016	0.35	0.080
	(P4	6.0		16	0.091	ИD	0.52	1.3
ų	(SW11*	6.0		ND	ИД	ИД	ИD	0.0079
'reus)	SW12	6.0		ND	ND	ND	ND	ND
1205		SW13	6.0		ND	ND	0.022	ND	ИD
,	Ć	SW14	6.0		ND	ND	ND	ND	0.020
مل .	اکنے. نا	(WO1**	6.5	120	36	0.091	0.17	0.38	1.8
mas	Os,	(WO1** SWA***	6.0		'				

⁻⁻ Indicates analysis was not performed.

ND = Non-detectable.

^{*} TOG was 78 mg/kg.

^{**} TOG was 1,500 mg/kg, and all EPA method 8010 constituents were non-detectable, except 1,2-dichlorobenzene at 210 μ g/kg.

^{***} TOG was 3,500 mg/kg.

TABLE 9

SUMMARY OF LABORATORY ANALYSES WATER

(Collected on June 20 & July 3, 1990)

Sample #	TOG (mg/L)	TPH as <u>Gasoline</u>	<u>Benzene</u>	<u>Toluene</u>	Ethyl- <u>benzene</u>	Xylenes
W1*		2,300	3.1	0.88	0.39	250
W2**	ND	ND	ND	0.96	ND	ND

- * Collected from the former fuel storage tank pit.
- ** Collected from the new fuel storage tank pit.
- -- Indicates analysis was not performed.

ND = Non-detectable.

Results are in micrograms per liter ($\mu g/L$), unless otherwise indicated.

TABLE 10
SUMMARY OF LABORATORY ANALYSES
SOIL

(Collected on July 16 & 20, 1990)

Sample	Depth (feet)	TPH as <u>Diesel</u>	TPH as <u>Gasoline</u>	<u>Benzene</u>	<u>Toluene</u>	Ethyl- <u>benzene</u>	Xylenes
SWB(13)	* 6.0	ИD	ND	ND	0.0095	ND	ND
SWC(10)	* 6.0	ND	1.1	0.0061	0.0330	0.024	0.044
SWD(14)	* 6.0	ИД	ND	0.0052	0.015	ИД	ИД
SWE*	6.3	ND	ND	ND	0.031	ND	ND
SWF*	6.3	ND	ND	ND	0.029	0.0059	0.013
SWG*	6.3	ИD	ND	ND	0.028	ИD	ND
swh*	6.3	ND	ND	ND	0.015	ИD	ND

^{*} TOG and all EPA method 8010 constituents were non-detectable.

ND = Non-detectable.

TABLE 11

SUMMARY OF LABORATORY ANALYSES WATER

(Collected on July 19, 1990)

Sample #	TPH as <u>Diesel</u>	TPH as <u>Gasoline</u>	<u>Benzene</u>	<u>Toluene</u>	Ethyl- <u>benzene</u>	Xylenes
W3*	ND	ND	ND	ND	ND	ND

ND = Non-detectable.

* TOG and all EPA method 8010 constituents were non-detectable.

Results are in micrograms per liter ($\mu g/L$), unless otherwise indicated.

TABLE 12
SUMMARY OF LABORATORY ANALYSES
SOIL

Date	Sample <u>Number</u>	Depth (feet)	TPH as <u>Diesel</u>	TPH as <u>Gasoline</u>	<u>Benzene</u>	<u>Toluene</u>	Ethyl- <u>benzene</u>	Xylenes	Total <u>Lead</u>
5/21/92	F-SW1	6.5		ND	ND	ND	ND	ND	7.4
	F-SW2	6.5	40	ND	ND`	ND	ИD	ИD	4.1
•	F-SW3	6.5		ИD	ИD	ИD	ND	ND	4.9
	F-SW4	6.5		ND	ND	ИD	ND	ND	3.8
	PT-1	11.5		6.2	0.0072	0.072	0.054	0.33	4.0
	PT-2	5.0		940	ND	0.81	12	100	
	PT-3	1.75		ND	0.0078	0.061	0.026	0.14	5.1
	PT-4	1.75		ND	ND	ND	ND	ND	6.5
	PT-5	1.75		ND	ИD	ИD	ND	ИD	4.8
	WO-1*	6.0	ND	ND	ND	ND	ND	ND	4.9
	WO-2*	6.0	ND	ND	ND	ND	ΝD	ИD	5.2
	WO-3*	6.0	ND	ND	ND	ND	ND	ND	5.0
	₩O-4*	6.0	ND	ND	ND	ND	ND	ND	5.3
	H1**	5.0		ND	ND	ND	ND	ND	
	H2***	5.5		230	ND	ND	1.3	0.66	4.4

ND = Non-detectable.

⁻⁻ Indicates analysis was not performed.

^{*} TOG and EPA method 8010 and 8270 constituents were all non-detectable.

^{**} TPH as hydraulic fluid was 1.3 mg/kg.

^{***} TOG was non-detectable. TPH as hydraulic fluid was detected at a concentration of 120 mg/kg. EPA method 8010 and 8270 constituents were non-detectable, except for bis(2-ethylhexyl)phthalate at 670 μ g/kg, 2-methylnaphthalene at 5,800 μ g/kg, naphthalene at 4,100 μ g/kg, phenanthrene at 240 μ g/kg, and pyrene at 120 μ g/kg.

TABLE 13
SUMMARY OF LABORATORY ANALYSES
SOIL

<u>Date</u>	Sample <u>Number</u>	Cadmium	Chromium	Nickel	Zinc
5/21/92	WO-1	ND	29	35	44
	WO-2	ND	24	27	37
	WO-3	ND	24	26	39
	WO-4	ND	32	39	49
	H2	ND	33	43	55

ND = Non-detectable.

KEI-P90-0606.R15 October 24, 1995

TABLE 14
SUMMARY OF LABORATORY ANALYSES
SOIL

<u>Date</u>	Sample D Number (TPH as Hydraulic Fluid		Benzene	Toluene	Ethyl- benzene	Xylenes	TOG
6/15/92	PT(16.5)	16.5		ND	ND	ND	ND	ND	
	PT(SW1)	12.0		ND	ND	ND	ND	ND	
	PT(SW2)	12.0		ND	ND	ND	ND	ND	
	PT(SW3)	12.0		ND	ИD	ND	ND	ND	
	PT(SW4)	12.0		ND	ND	ND	ИD	ND	
	H2(6.5)* H2(SW1)* H2(SW2)* H2(SW3)* H2(SW4)*	5.5 5.5 5.5	ND ND ND ND	ND ND ND ND	ND ND ND 0.069 ND	ND ND 0.0098 0.068 ND	ND ND ND 0.064 ND	ND ND 0.022 0.21 ND	ND ND ND ND

ND = Non-detectable.

⁻⁻ Indicates analysis was not performed.

^{*} EPA method 8270 constituents were all non-detectable

KEI-P90-0606.R15 October 24, 1995

TABLE 15 SUMMARY OF LABORATORY ANALYSES WATER

<u>Date</u>	<u>Sample</u>	TPH as <u>Diesel</u>	TPH as <u>Gasoline</u>	<u>Benzene</u>	<u>Toluene</u>	Ethyl- <u>benzene</u>	<u>Xylenes</u>	Organic <u>Lead</u>
5/21/92	Water-1 Water-2	 86	ND ND	ND ND	ND ND	ND ND	2.7 ND	ND
6/17/92	Water-3	**	ND	ND	ND	ND	ND	

-- Indicates analysis was not performed.

ND = Non-detectable.

- * TOG, cadmium, chromium, lead, nickel, EPA method 8010 and 8270 constituents were all non-detectable. Zinc was detected at 0.037 ppb.
- ** TPH as hydraulic fluid, TOG, EPA method 8270 constituents, and the metals cadmium, chromium, lead, nickel, and zinc were all non-detectable.

Results are in micrograms per liter ($\mu q/L$), unless otherwise indicated.